SCDOT

# US 21 over Harbor River Bridge Replacement

**Design-Build Project - P026862 - Beaufort County, SC**


# PRELIMINARY ROADWAY GEOTECHNICAL REPORT











**October 2, 2017**

UNITED INFRASTRUCTURE GROUP

INFRASTRUCTURE CONSULTING & ENGINEERING

# Preliminary Roadway Geotechnical Services

US 21 Over Harbor River Bridge Replacement Project
Beaufort County, South Carolina

*for*

**Infrastructure Consulting and Engineering**

October 2, 2017

GeoEngineers

8410 154th Avenue NE
Redmond, Washington 98052
425.861.6000

# Preliminary Roadway Geotechnical Services

# US 21 Over Harbor River Bridge Replacement Project
# Beaufort County, South Carolina

**File No. 18461-007-01**

**October 2, 2017**

Prepared for:


Infrastructure Consulting and Engineering
1021 Briargate Circle
Columbia, South Carolina 29210

Attention: Andy Gillis, PE

Prepared by:

GeoEngineers, Inc.
8410 154th Avenue NE
Redmond, Washington 98052
425.861.6000




Zachary A. Simpson, PE
Geotechnical Engineer

Ivy A. Harmon, PE (LA)
Geotechnical Engineer

Heidi P. Cashman, PE (WA)
Senior Geotechnical Engineer

King H. Chin, PE
Principal

ZAS:IAH:HPC:KHC:nld

Disclaimer: Any electronic form, facsimile or hard copy of the original document (email, text, table, and/or figure), if provided, and any attachments are only a copy of the original document. The original document is stored by GeoEngineers, Inc. and will serve as the official document of record.

# Table of Contents


**1.0 INTRODUCTION ..... 1**

**2.0 GEOTECHNICAL EMBANKMENT DESIGN AND CONSTRUCTION ISSUES ..... 1**

**3.0 EMBANKMENT PERFORMANCE LIMITS ..... 1**

**4.0 SUBSURFACE SOIL CONDITIONS ..... 3**

4.1. Geologic Setting ..... 3
4.2. Preliminary Field Exploration Program ..... 3
4.3. Subsurface Conditions ..... 3
4.4. Groundwater Conditions ..... 4

**5.0 PRELIMINARY LABORATORY TESTING PROGRAM ..... 4**

**6.0 SOIL DESIGN PARAMETERS ..... 4**

6.1. Consolidation Parameters ..... 4
6.2. Shear Strength Parameters ..... 5
6.2.1. Holocene Silts and Clays ..... 5
6.2.2. Sands ..... 5
6.2.3. Hawthorn Marl ..... 6
6.2.4. Cooper Formation ..... 6
6.2.5. Embankment Fill ..... 6

**7.0 SEISMIC INPUT PARAMETERS FOR BRIDGE EMBANKMENT DESIGN ..... 7**

**8.0 GEOTECHNICAL EMBANKMENT DESIGN ANALYSES ..... 7**

8.1. West Embankment 1 ..... 9
8.2. West Embankment 2 ..... 9
8.3. West Embankment 3 ..... 9
8.4. West Bridge Embankment 4 ..... 10
8.5. East Bridge Embankment 1 ..... 11
8.6. East Embankment 2 ..... 12
8.7. East Embankment 3 ..... 13

**9.0 PRELIMINARY GEOTECHNICAL EMBANKMENT DESIGN RECOMMENDATIONS ..... 13**

**10.0 FIELD EXPLORATION AND LABORATORY TESTING PROGRAM ..... 14**

**11.0 LIMITATIONS ..... 16**

**12.0 REFERENCES ..... 16**

## LIST OF FIGURES

Figure 1. Vicinity Map
Figures 2A through 2C. Exploration Location Plans
Figure 3A through 3C. US 21 Profile
Figure 4. Over-Consolidation Ratio (OCR) with Depth
Figure 5. Moisture Content vs. Compression Index
Figure 6. Moisture Content vs. Cre/Cce Ratio
Figures 7 and 8. Ground Surface ADRS Curves
Figures 9 through 24. Global Stability Results

## APPENDICES

Appendix A. Field Explorations
Appendix B. Laboratory Testing
Appendix C. Soil Parameter Determination
Appendix D. Consolidation Analyses
Appendix E. Soil Liquefaction Analyses
Appendix F. Slope-W Analyses
Appendix G. Ground Improvement Analyses
Appendix H. Report Limitations And Guidelines For Use

## 1.0 INTRODUCTION

This report presents the results of GeoEngineers' preliminary embankment design analyses and recommendations for the US 21 over Harbor River Bridge replacement project in Beaufort County, South Carolina. The project site is shown relative to surrounding physical features on the Vicinity Map in Figure 1 and on the preliminary site exploration plans shown in Figures 2A through 2C. We understand that the project consists of two earthen roadway embankments and a new bridge that is about 3,400 feet in length.

## 2.0 GEOTECHNICAL EMBANKMENT DESIGN AND CONSTRUCTION ISSUES

Construction of the roadway and bridge embankments requires placing fill up to about 18 feet high at the bridge end bents. The weight of the fill and the traffic loading will cause the compressible soils to consolidate and settle. For most of the roadway embankments, a preload program with vertical wick drains will be implemented to induce the soil consolidation settlement during the preload period to keep the post-construction roadway settlement lower than the specified long-term roadway embankment settlement performance limits per South Carolina Department of Transportation (SCDOT) Geotechnical Design Manual (GDM). The roadway embankments are classified as ROC III for the project.

The total height of the roadway embankments and preload fill required to induce soil consolidation settlement will be on the order of more than 20 feet near the bridge end bents. As the underlying soils settle, they also deform laterally, which can apply lateral stress onto the existing structures that are located within proximity of the preload fill. The use of wick drains will reduce the lateral undrained soil deformation induced by soil consolidation settlement. However, if existing structures are located adjacent to the new embankment fill, ground improvement may be required to reduce the amount of consolidation settlement and help mitigate the effects of the lateral undrained soil deformation that can adversely impact the adjacent structures.

The bridge embankments for this project are classified as ROC I, and therefore will be designed to meet the performance limits at the Extreme Event I (EE I) Limit State per SCDOT GDM. In order to meet the performance limits at the EE I limit state, ground improvement and reinforced soil slopes will be implemented within the bridge embankment footprint, which extends about 75 feet from the toe of the fore slope at the bridge end bents. Per the project Request for Proposal (RFP), The roadway embankments for this project are not required to be designed to meet the performance limits at the EE I Limit State.

Key geotechnical embankment construction issues include management of fill placement and careful instrumentation and monitoring during construction to ensure that the objectives of the preload program are achieved and to prevent subsurface soil failure from occurring during construction.

## 3.0 EMBANKMENT PERFORMANCE LIMITS

The embankment design is completed to confirm that the embankment settlement and global instability performance limits specified in the project RFP and in Chapter 10 of the SCDOT GDM are met. Tables 1 through 5 below presents the embankment performance limits at both the Service Limit State (SLS) and EE I Limit State that are specified for this project.

**TABLE 1. EMBANKMENT SETTLEMENT PERFORMANCE LIMITS AT SLS**

| Deformation ID No. | | Performance Limit Description | ROC | |
|---|---|---|---|---|
| | | | I | III |
| | | Minimum Design Life (Years) | 100 | 100 |
| Settlement (Longitudinal) | EV-01 | Max. settlement along the profile grade | 8.00” | 8.00” |
| | EV-02 | Max. settlement rate per year after roadway has been paved | 0.10” | 0.20” |
| | EV-03 | Max. differential settlement over 50 feet of embankment longitudinally after roadway has been paved | 1.00” | 2.00” |

**TABLE 2. BRIDGE/EMBANKMENT TRANSITION SETTLEMENT PERFORMANCE LIMITS AT SLS**

| Deformation ID No. | | Performance Limit Description | ROC |
|---|---|---|---|
| | | | I |
| Settlement (Longitudinal) | EV-05 | Max. differential settlement between end bent and end of approach slab (inches), $L_{slab}$ measured in feet | 0.075 x $L_{slab}$ |

**TABLE 3. EMBANKMENT SETTLEMENT PERFORMANCE LIMITS AT EE I LIMIT STATE**

| Deformation ID No. | | Performance Limit Description | Design Earthquake | ROC |
|---|---|---|---|---|
| | | | | I |
| Settlement (Longitudinal) | EV-03 | Max. differential settlement over 50 feet of embankment longitudinally after roadway has been paved | FEE | 1.00” |
| | | | SEE | 2.00” |

**TABLE 4. BRIDGE/EMBANKMENT TRANSITION SETTLEMENT PERFORMANCE LIMITS AT EE I LIMIT STATE**

| Deformation ID No. | | Performance Limit Description | Design Earthquake | ROC |
|---|---|---|---|---|
| | | | | I |
| Settlement (Longitudinal) | EV-05 | Max. differential settlement between end bent and end of approach slab (inches), $L_{slab}$ measured in feet | FEE | 0.075 x $L_{slab}$ |
| | | | SEE | 0.100 x $L_{slab}$ |

**TABLE 5. EMBANKMENT GLOBAL INSTABILITY PERFORMANCE LIMITS AT EE I LIMIT STATE**

| Deformation ID No. | | Performance Limit Description | ROC |
|---|---|---|---|
| | | | I |
| Vertical Displacement | GI-01 | Max. at top of the slope failure surface | FEE: 1.00”<br>SEE: 2.00” |
| | GI-02 | Max. at bottom of the slope failure surface | FEE: 1.00”<br>SEE: 2.00” |

| Deformation ID No. | | Performance Limit Description | ROC |
|---|---|---|---|
| | | | I |
| Lateral Displacement | GI-03 | Max. at top of the slope failure surface | FEE: 3.00”<br>SEE: 4.00” |
| | GI-04 | Max. at bottom of the slope failure surface | FEE: 3.00”<br>SEE: 4.00” |

## 4.0 SUBSURFACE SOIL CONDITIONS

### 4.1. Geologic Setting

The geology of the site was described in more details in the geotechnical baseline report prepared by F&ME Consultants, Inc. (F&ME 2017). Generally, the site soils are anticipated to be Holocene deposits consisting of silt, clay and sand, underlain by tertiary deposits consisting of a relatively thin layer of Hawthorn Marl of Miocene age (~23 MYA). The marl thickness at this site is expected to vary from 10 to 30 feet, which is underlain by the tertiary deposits consisting of calcareous, sandy limestone. The upper limestone is considered part of the Cooper Group, and consists of Oligocene (~36 MYA) and late Eocene (~40-50 MYA) age deposits.

The site is located within seismically active region. According to the geologic map titled “Structural Features of South Carolina” produced by South Carolina Department of Natural Resources, Geologic Survey, the major sources identified in the site vicinity are the Garner-Edisto fault, an east-to-west trending, normal fault traversing Beaufort and Jasper Counties in South Carolina. Published geologic maps generally show that this area has a high potential for liquefaction during substantial seismic events.

### 4.2. Preliminary Field Exploration Program

A preliminary field exploration program was completed by F&ME for this project. The field exploration program included 27 borings and 11 cone penetration tests (CPTs). Figures 2A through 2C show the locations of these borings and CPTs completed along the project alignment. Boring and CPT logs of the preliminary field exploration program are presented in Appendix A, Field Explorations.

### 4.3. Subsurface Conditions

Subsurface conditions at the site were evaluated by reviewing the exploration logs and laboratory test results completed by F&ME for this project. In general, the soils observed in the explorations completed at the project site consist of Holocene Deposits, Hawthorn Marl and Cooper Limestone Formation. A generalized soil profile along the project alignment is presented in Figures 3A through 3C, US 21 Profile.

Holocene deposits were encountered in all the explorations, and generally consist of interbedded soft to stiff silt, clay and very loose to very dense sand, generally consistent with the geologic map published for the region. The thickness of the Holocene deposits generally ranges from 50 to 65 feet within the embankment areas. The thickness of silt and clay soils encountered in the explorations range between 5 and 35 feet.

Hawthorn Marl was also encountered in all the explorations that were terminated below Elevation -40 feet mean sea level (MSL). The Hawthorn Marl was encountered to approximately Elevation -79 to -90 feet below ground surface or mudline and consists of stiff to hard clay of variable plasticity.

The Cooper Limestone Formation was encountered below the Hawthorn Marl and generally consists of very stiff to hard clay.

### 4.4. Groundwater Conditions

Groundwater level measurements were completed by F&ME as part of their preliminary geotechnical study. Based on the geotechnical baseline report, groundwater was encountered between Elevation 0 to +3 feet MSL. Groundwater was anticipated to fluctuate with tidal level in Harbor River and is expected to vary by location and season. For the preliminary design analyses, we assumed the design groundwater level at Elevation 0 feet MSL.

## 5.0 PRELIMINARY LABORATORY TESTING PROGRAM

A preliminary laboratory testing program was completed by F&ME for this project. The laboratory testing program included moisture content, Atterberg Limits, grain size distribution, consolidated undrained (CU) triaxial, consolidation, unconfined compression, electro-chemical, and resonant column tests. Data sheets presenting the results of the preliminary laboratory testing program are included in Appendix B, Laboratory Testing.

## 6.0 SOIL DESIGN PARAMETERS

Soil design parameters were developed for the general soil units encountered at the project site. The four general soil units include:

- Holocene silts and clays;
- Holocene sands;
- Hawthorn Marl; and
- Cooper Formation.

The soil design parameters developed for use in the engineering analyses include the consolidation properties of compressible silts and clays and shear strength parameters of each soil unit.

### 6.1. Consolidation Parameters

Seven consolidation tests that were previously performed by F&ME were also reviewed and used to develop the consolidation parameters for the silts and clays used in our preliminary consolidation analyses. Figure 4 presents the stress history of the underlying silts and clays expressed in over-consolidation ratio (OCR) profile, computed using the pre-consolidation pressures determined using the preliminary consolidation test results.

The other two consolidation parameters that we need for our preliminary consolidation analyses are the compression index ($C_{c\varepsilon}$) and recompression index ($C_{r\varepsilon}$). Table 6 presents the range of $C_{c\varepsilon}$ and $C_{r\varepsilon}$

computed for the compressible soils at the west and east embankment areas using the preliminary consolidation test results.

**TABLE 6. COMPRESSION AND RECOMPRESSION RATIOS (PRELIMINARY CONSOLIDATION TEST RESULTS).**

| Embankment | Ccε | Crε |
|---|---|---|
| West | 0.24 to 0.48 | 0.027 to 0.053 |
| East | 0.36 | 0.052 |

Our assessment of the Ccε and Crε values indicates that the compressible soils encountered within the west embankment area are consistent with the values determined for the east embankment. In addition, we also developed a correlation between soil moisture content and compression index that was used in our preliminary consolidation analyses, presented in Figure 5. Our assessment also shows that the ratios of recompression index and compression index generally range from 0.11 to 0.14, as presented in Figure 6, therefore a ratio of 0.13 was selected for use in our analyses.

In order to evaluate the rate of soil consolidation during the preload period and design service life, the coefficient of consolidation, Cv, is estimated and used in the consolidation analyses. The Cv values determined using the preliminary consolidation tests results at the various loading pressures were evaluated and reviewed. Based on our evaluation and review of the preliminary consolidation test results, we used a Cv value of 0.035 $ft^2$/day in our preliminary consolidation analyses.

## 6.2. Shear Strength Parameters

The subsurface soil shear strength properties were characterized based on standard penetration test (SPT) in-situ testing for sand, and laboratory testing results for clay. The following section presents the methods and preliminary soil shear strength parameters determined for this project.

### 6.2.1. Holocene Silts and Clays

The Holocene deposits encountered along the west and east embankment generally consist of 5 to 35 feet thick of soft to medium stiff silts and clays. The shear strength of the cohesive silts and clays is dependent on the stress history of the soil itself. The stress history of the silts and clays was evaluated and the results are presented in Figure 4.

The Stress History and Normalized Soil Engineering Parameters (SHANSEP) approach was used to define soil shear strength as a function of vertical effective stress and the OCR of the soil. Shear strength ($S_u$) of the silts and clays was determined using the following SHANSEP equation:

$$s_u = 0.22\sigma_v' OCR^{0.8}$$

### 6.2.2. Sands

The shear strength parameters of the Holocene sand unit encountered at the project site will be expressed as internal friction angle (ϕ') for the static conditions and residual strength (Sr) for the earthquake conditions, if the sand is determined to be potentially liquefiable under the design earthquake events. The internal friction angle was derived using the correlation developed by Terzaghi et al, (1996) between SPT blow counts (corrected for depth and hammer efficiency) and relative density. Residual effective friction angle was also derived per SCDOT GDM recommendations using the Idriss and Boulanger (2008)

correlations between SPT blow counts (corrected for depth and hammer efficiency as well as fines content). The Meyerhof's and Idriss & Boulanger (2008) correlations used are presented below:

Terzaghi et al, 1996 correlation:

$$\phi' = -0.0027(N_{1\text{-}60})^2 + 0.4333(N_{1\text{-}60}) + 27.184$$

Idriss and Boulanger (2008) Correlation:

$$Sr/\sigma'_v = \exp\left(N_{1\text{-}60cs\text{-}Sr}/16 + ((N_{1\text{-}60cs\text{-}Sr} - 16) / 21.2)^3 - 3\right)$$

Sand shear strength parameters relevant to the proposed design were evaluated using area specific data. Specific layers were delineated using recorded blow count information. Area specific blow counts, friction angles, and residual strength parameters were determined using the information presented in Appendix C, Soil Parameter Determination.

#### 6.2.3. Hawthorn Marl

The F&ME geotechnical baseline report does not present any laboratory testing for the Hawthorn Marl. Based on our assessment of the in-situ SPT and CPT data, it is our opinion that the Hawthorn Marl has similar shear strength characteristics to the Cooper Marl, which is a well-studied soil formation. For the preliminary analyses, we estimated that the Hawthorn Marl has an undrained shear strength of 4 kips per square foot (ksf), which is the average published shear strength for the Cooper Marl. The undrained shear strength was reduced by 15 percent under the seismic loading conditions. For final design analyses, laboratory tests will be completed to refine the shear strength parameters for the Hawthorn Marl soil unit.

#### 6.2.4. Cooper Formation

The F&ME geotechnical baseline report does not include any laboratory shear strength tests for the Cooper Formation for depths of interest. We estimated the shear strength characteristics by comparing the shear wave velocities of the Hawthorn Marl and the Cooper Formation. Our comparison shows that the shear wave velocity of the Cooper Formation is at least 1.5 times higher than the shear wave velocity measured in the Hawthorn Marl. Since the shear strength and shear wave velocity (indicative of shear modulus) is directly related, we estimated a shear strength of 6 ksf for the Cooper Formation in our preliminary analyses. We will complete laboratory shear strength tests to refine the shear strength of the Cooper Formation for use in the final design analyses.

#### 6.2.5. Embankment Fill

Since the embankment fill will meet the SCDOT material specification for structural fill and will be compacted to at least 95 percent of the maximum dry density (MDD) per ASTM D1557, we estimated an internal friction angle of 38 degrees to calculate the shear strength of the embankment fill. We will complete laboratory shear strength tests to refine the friction angle of the embankment fill for use in the final design analyses.

## 7.0 SEISMIC INPUT PARAMETERS FOR BRIDGE EMBANKMENT DESIGN

The seismic input parameters used in the bridge embankment design analyses were provided in the RFP based on the site-specific response analyses completed by F&ME for the project. Table 7 below presents the seismic input parameters for bridge embankment design. Figures 7 and 8 presents the ground surface ADRS curves for the west and east bridge embankment, respectively.

**TABLE 7. SEISMIC INPUT PARAMETERS FOR BRIDGE EMBANKMENT DESIGN**

| ADRS Design Parameters | West Bridge Embankment | | East Bridge Embankment | |
|---|---|---|---|---|
| | FEE | SEE | FEE | SEE |
| $M_w$ | 7.3 | 7.3 | 7.3 | 7.3 |
| PGA (g) | 0.14 | 0.26 | 0.12 | 0.29 |

## 8.0 GEOTECHNICAL EMBANKMENT DESIGN ANALYSES

The roadway embankments were delineated into seven representative zones for use in the geotechnical design analyses. These seven zones are delineated based on ROC categories, subsurface soil conditions and embankment height, as summarized in Table 8 below.

**TABLE 8. EMBANKMENT ZONES**

| Embankment Zone | ROC | Station Range | Embankment Height Range (feet) |
|---|---|---|---|
| West Embankment 1 | III | 59+00 and lower | Less than 4 |
| West Embankment 2 | III | 59+00 to 69+00 | 4 to 13 |
| West Embankment 3 | III | 69+00 to 69+65 | 13 to 14 |
| West Bridge Embankment 4 | I | 69+65 to 70+40 (Begin Bridge) | 14 to 18 |
| East Bridge Embankment 1 | I | 103+80 (End Bridge) to 104+55 | 15 to 17 |
| East Embankment 2 | III | 104+55 to 112+00 | 7 to 15 |
| East Embankment 3 | III | 112+00 and higher | 0 to 7 |

Preliminary consolidation analyses were completed to evaluate the preliminary estimated preload fill required in each of the embankment zones that will meet the SLS settlement performance limits summarized in Tables 1 and 2 presented above. Two sets of one-dimensional (1D) consolidation analyses were completed. The first set of analysis was completed to estimate the amount of settlement that needs to be induced during the preload period. The required preload fill is then estimated by adding 3.2 feet of fill (equivalent to about 400 pounds per square foot (psf), which includes traffic loading and future pavement overlay) to the settlement computed. The second set of analysis was completed to estimate the post-construction roadway consolidation settlement under the 400 psf traffic and pavement overlay loading assuming that the underlying soils will be in the recompression state after the preload program is completed. The preliminary consolidation analyses were completed using an in-house spreadsheet and the

calculations are provided in Appendix D, Consolidation Analyses. For final design, the computer program Settle3D will be used to complete the consolidation analyses using the refined consolidation parameters.

Preliminary global stability analyses were also completed for two static conditions (staged construction and end of construction) to check that the demand/capacity (D/C) ratios for slope stability are acceptable. The preliminary global stability analyses were completed using the computer program SlopeW with Morgenstein-Price analysis method. We included geotextile reinforcement in the SlopeW analyses. A reinforcement equivalent to a Mirafi 1000/100 was used underneath all of the roadway embankments and reinforcement equivalent to Mirafi HP570 was used in the West and East Bridge Embankments. The SlopeW global stability calculations are presented in Appendix E, Soil Liquefaction Analyses.

For both the West and East Bridge Embankments, we also completed soil liquefaction analyses under both FEE and SEE events to confirm that the bridge embankment settlement performance at EE I Limit State as presented in Tables 3 and 4 above are met. Soil liquefaction potential was evaluated by comparing the cyclic shear stress ratio (CSR), and the Demand (D) induced by the design earthquake with the cyclic resistance ratio (CRR), the Capacity (C) of the soil to resist liquefaction. The ratio of CSR (Demand, D) to CRR (Capacity, C) results in the liquefaction triggering resistance ratio for Sand-Like soils $(D/C)_{SL\text{-}Sand}$, and is equivalent to the inverse of the Factor of Safety (1/FS) traditionally used for evaluating liquefaction potential. Full liquefaction occurs when $(D/C)_{SL\text{-}Sand} > \varphi_{SL\text{-}Sand}$, where $\varphi_{SL\text{-}Sand}$ is the triggering resistance factor for the onset of liquefaction required by the GDM. The GDM defines the onset of "Full Liquefaction" for the SEE design earthquake when $(D/C)_{SL\text{-}Sand} > 0.90$ and for the FEE design earthquake when $(D/C)_{SL\ Sand} > 0.85$. Soil liquefaction analyses were completed using the semi-empirical method developed by Idriss and Boulanger (2008) using an in-house spreadsheet. The liquefaction induced settlements of the saturated sands were estimated based on Idriss and Boulanger (2008). Appendix F presents the preliminary liquefaction analysis calculations completed for this project.

In addition to soil liquefaction analysis, preliminary pseudo-static global stability and Newmark analyses were also completed to check that the west and east bridge embankments meet the embankment global instability performance limits at EE I limit state as presented in Table 5 above. Pseudo-static global stability analyses were completed using the computer program SlopeW to determine the yield acceleration for each design section. The bridge embankment seismic deformations were estimated using the simplified Newmark Method described in Section 13.17.2 and Equation 13-106 of the SCDOT GDM. For ROC I bridge embankment, the calculated Newmark displacement will be multiplied by 2.

For the ROC 1 West and East Bridge Embankment, timber piles will be implemented to meet the performance limits at EE I limit state. Timber piles are also planned within the West Roadway Embankment 3 located adjacent to the existing Harbor River Bridge pile foundations to minimize the impacts of the roadway embankment construction. The ground improvement design was completed using the British Standard Method (BS 8006) of the Catenary Design Approach as outlined in Section 19.9.3.1 of the SCDOT GDM to estimate the embankment settlement. Ground improvement calculations for the West and East Bridge Embankment, as well as for the West Roadway Embankment 3 are presented in Appendix G, Ground Improvement Analyses.

The following sections present a summary of the results of the consolidation, global stability, Newmark and soil liquefaction analyses completed for the design sections selected for each of the embankment zones delineated for this project.

### 8.1. West Embankment 1

Consolidation analyses were completed based on the soil profile encountered in boring B-7. Table 9 below summarizes the results of our preliminary consolidation analyses completed for West Embankment 1.

**TABLE 9. WEST EMBANKMENT 1 – SUMMARY OF CONSOLIDATION ANALYSES RESULTS**

| Exploration | Preload Induced Settlement (feet) | Preload Fill Thickness (feet) | Estimated Long Term Roadway Settlement (inches) |
|---|---|---|---|
| B-7 | 0.1 | 3.3 | 1.1 |

The preliminary slope stability cross section was developed at Station 59+00, which we identified as the worst-case soil condition within West Embankment 1. Appendix E presents the soil layers and input parameters used in the preliminary slope stability analyses. Figures 9 and 10 present the results of the slope stability analyses for both staged construction and end of construction conditions. The results indicate that the D/C is less than 0.67 (i.e. FS > 1.5), therefore, is satisfactory.

### 8.2. West Embankment 2

Consolidation analyses were completed based on soil profiles encountered in CPT-5, and borings B-8 and B-9. Table 10 below summarizes the results of our preliminary consolidation analyses completed for West Embankment 1.

**TABLE 10. WEST EMBANKMENT 2 – SUMMARY OF CONSOLIDATION ANALYSES RESULTS**

| Exploration | Preload Induced Settlement (feet) | Preload Fill Thickness (feet) | Estimated Long Term Roadway Settlement (inches) |
|---|---|---|---|
| CPT-5 | 0.2 | 3.4 | 1.9 |
| B-8 | 0.4 | 3.6 | 2.3 |
| B-9 | 1.8 | 5.0 | 6.4 |

The preliminary global stability cross section was developed at Station 69+00, which we identified as the worst-case soil condition within West Embankment 2. Appendix E presents the soil layers and input parameters used in the preliminary global stability analyses. Figures 11 and 12 present the results of the global stability analyses for both staged construction and end of construction conditions. The results indicate that the D/C is less than 0.67 (i.e. FS > 1.5), therefore, is satisfactory.

### 8.3. West Embankment 3

Consolidation analyses were completed based on soil profiles encountered in CPT-6. Table 11 below summarizes the results of our preliminary consolidation analyses completed for West Embankment 3.

**TABLE 11. WEST EMBANKMENT 3 – SUMMARY OF CONSOLIDATION ANALYSES RESULTS**

| Exploration | Preload Induced Settlement (feet) | Preload Fill Thickness (feet) | Estimated Long Term Roadway Settlement (inches) |
|---|---|---|---|
| CPT-6 | 1.2[1] | 4.4 | 1.1[1] |

Notes:

Preload induced settlement and long-term roadway settlement are controlled by the timber pile ground improvement program as presented in Appendix G. The long-term embankment settlement is estimated as the vertical settlement induced by difference of 1 percent strain in the high strength geotextile.

The preliminary global stability cross section was developed at Station 69+65, which we identified as the worst-case soil condition within West Embankment 3. Appendix E presents the soil layers and input parameters used in the preliminary global stability analyses. Figures 13 and 14 present the results of the global stability analyses for both staged construction and end of construction conditions. The results indicate that the D/C is less than 0.67 (i.e. FS > 1.5), therefore, is satisfactory.

### 8.4. West Bridge Embankment 4

Consolidation analyses were completed based on interpreted soil profile at Station 70+40. Table 12 below summarizes the results of our preliminary consolidation analyses completed for West Bridge Embankment 4.

**TABLE 12. WEST BRIDGE EMBANKMENT 4 – SUMMARY OF CONSOLIDATION ANALYSES RESULTS**

| Exploration | Preload Induced Settlement (feet) | Preload Fill Thickness (feet) | Estimated Long Term Roadway Settlement (inches) |
|---|---|---|---|
| Interpreted Soil Profile | 0.5[1] | 3.7 | 1.2[1] |

Notes:

Preload induced settlement and long-term embankment settlement are controlled by the timber pile ground improvement program as presented in Appendix G. The long-term embankment settlement is estimated as the vertical settlement induced by difference of 1 percent strain in the high strength geotextile. Timber pile settlement reduction ratio is estimated to be 85 percent.

Tables 13, 14 and 15 present the results of the soil liquefaction analyses completed using the soil profiles encountered in boring B-9.

**TABLE 13. WEST BRIDGE EMBANKMENT 4 – SUMMARY OF LIQUEFACTION ANALYSES RESULTS FOR SEE**

| Boring No. | Boring Elevation (feet) | Potentially Liquefiable Soil Layers $(D/C)_{SL\text{-}Sand} = 1/FS > 0.90$ | | | | |
|---|---|---|---|---|---|---|
| | | Depth Intervals and Thickness Shown in Parenthesis (feet) | | | | Total Thickness (feet) |
| | | Layer 1 | Layer 2 | Layer 3 | Layer 4 | |
| B-9 | 2.6 | 1 – 16 (15) | 41 – 51 (10) | - | - | 25 |

**TABLE 14. WEST BRIDGE EMBANKMENT 4 – SUMMARY OF LIQUEFACTION ANALYSES RESULTS FOR FEE**

| Boring No. | Boring Elevation (feet) | Potentially Liquefiable Soil Layers $(D/C)_{SL\text{-}Sand} = 1/FS > 0.85$ | | | | |
|---|---|---|---|---|---|---|
| | | Depth Intervals and Thickness Shown in Parenthesis (feet) | | | | Total Thickness (feet) |
| | | Layer 1 | Layer 2 | Layer 3 | Layer 4 | |
| B-9 | 2.6 | 1 – 16 (15) | 41 – 51 (10) | - | - | 25 |

**TABLE 15. WEST BRIDGE EMBANKMENT 4 – LIQUEFACTION INDUCED SETTLEMENT**

| Boring | Settlement under SEE, inches | Settlement under FEE, inches |
|---|---|---|
| B-9 | 16.4 | 16.4 |

By implementing the timber pile ground improvement system, we estimated that the settlement reduction at the West Bridge Embankment 4 is about 85 percent, therefore, the effective liquefaction induced settlement for both the SEE and FEE is about 2.5 inches.

The preliminary global stability cross section was developed at Station 70+40, which we identified as the worst-case soil condition within West Bridge Embankment 4. Appendix E presents the soil layers and input parameters used in the preliminary global stability analyses. Figures 15 and 16 present the results of the global stability analyses for both staged construction and end of construction conditions. The results indicate that the D/C is less than 0.67 (i.e. FS > 1.5), therefore, is satisfactory.

Figure 17 shows the results of the pseudo-static slope stability analysis with a yield acceleration of 0.29g. Using the Simplified Newmark Method, the estimated seismic lateral deformations under the FEE and SEE are negligible as the yield acceleration is higher than the design peak ground acceleration.

### 8.5. East Bridge Embankment 1

Consolidation analyses were completed based on soil profiles encountered in CPT-8. Table 16 below summarizes the results of our preliminary consolidation analyses completed for East Bridge Embankment 1.

**TABLE 16. EAST BRIDGE EMBANKMENT 1 – SUMMARY OF CONSOLIDATION ANALYSIS RESULTS.**

| Exploration | Preload Induced Settlement | Preload Fill Thickness | Estimated Long Term Roadway Settlement (inches) |
|---|---|---|---|
| CPT-8 | 0.5[1] | 3.7 | 1.2[1] |

Note:

1) Preload induced settlement and long-term embankment settlement are controlled by the timber pile ground improvement program as presented in Appendix G. The long-term embankment settlement is estimated as the vertical settlement induced by difference of 1 percent strain in the high strength geotextile. Timber pile ground improvement settlement reduction ratio is estimated to be 75 percent.

Tables 17, 18 and 19 present the results of the soil liquefaction analyses completed using the soil profiles encountered in borings B-16.

**TABLE 17. EAST BRIDGE EMBANKMENT 1 – SUMMARY OF LIQUEFACTION ANALYSES RESULTS FOR SEE**

| Boring No. | Boring Elevation (feet) | Potentially Liquefiable Soil Layers $(D/C)_{SL\text{-}Sand} = 1/FS > 0.90$ | | | | |
|---|---|---|---|---|---|---|
| | | Depth Intervals and Thickness Shown in Parenthesis (feet) | | | | Total Thickness (feet) |
| | | Layer 1 | Layer 2 | Layer 3 | Layer 4 | |
| B-16 | 2.4 | 0 – 3 (3) | 16 – 46 (30) | 56 – 66 (10) | - | 43 |

**TABLE 18. EAST BRIDGE EMBANKMENT 1 – SUMMARY OF LIQUEFACTION ANALYSES RESULTS FOR FEE**

| Boring No. | Boring Elevation (feet) | Potentially Liquefiable Soil Layers $(D/C)_{SL\text{-}Sand} = 1/FS > 0.85$ | | | | |
|---|---|---|---|---|---|---|
| | | Depth Intervals and Thickness Shown in Parenthesis (feet) | | | | Total Thickness (feet) |
| | | Layer 1 | Layer 2 | Layer 3 | Layer 4 | |
| B-16 | 2.4 | 0 – 3 (3) | 21 – 26 (5) | 31 – 46 (15) | 56 – 66 (10) | 33 |

**TABLE 19. EAST BRIDGE EMBANKMENT 1 – LIQUEFACTION INDUCED SETTLEMENT**

| Boring | Settlement under SEE, inches | Settlement under FEE, inches |
|---|---|---|
| B-16 | 18.2 | 14.6 |

By implementing the timber pile ground improvement system, we estimated that the settlement reduction at the West Bridge Embankment 4 is about 75 percent, therefore, the effective liquefaction induced settlements for both the SEE and FEE are about 4.6 and 3.6 inches, respectively.

The preliminary global stability cross section was developed at Station 103+80, which we identified as the worst-case soil condition within East Bridge Embankment 1. Appendix E presents the soil layers and input parameters used in the preliminary global stability analyses. Figures 18 and 19 present the results of the global stability analyses for both staged construction and end of construction conditions. The results indicate that the D/C is less than 0.67 (i.e. FS > 1.5), therefore, is satisfactory.

Figure 20 shows the results of the pseudo-static slope stability analysis with a yield acceleration of 0.46g. Using the Simplified Newmark Method, the estimated seismic lateral deformations under the FEE and SEE are negligible as the yield acceleration is higher than the design peak ground acceleration.

### 8.6. East Embankment 2

Consolidation analyses were completed based on soil profiles encountered in borings B-16 and B-2. Table 20 below summarizes the results of our preliminary consolidation analyses completed for East Embankment 2.

**TABLE 20. EAST EMBANKMENT 2 – SUMMARY OF CONSOLIDATION ANALYSIS RESULTS.**

| Exploration | Preload Induced Settlement (feet) | Preload Fill Thickness (feet) | Estimated Long Term Roadway Settlement (inches) |
|---|---|---|---|
| B-16 | 0.6 | 3.8 | 0.9 |
| B-2 | 0.5 | 3.7 | 0.8 |

The preliminary global stability cross section was developed at Station 104+55, which we identified as the worst-case soil condition within East Embankment 2. Appendix E presents the soil layers and input parameters used in the preliminary global stability analyses. Figures 21 and 22 present the results of the global stability analyses for both staged construction and end of construction conditions. The results indicate that the D/C is less than 0.67 (i.e. FS > 1.5), therefore, is satisfactory.

### 8.7. East Embankment 3

Consolidation analyses were completed based on soil profiles encountered in boring B-5. Table 21 below summarizes the results of our preliminary consolidation analyses completed for East Embankment 3.

**TABLE 21. EAST EMBANKMENT 3 – SUMMARY OF CONSOLIDATION ANALYSIS RESULTS.**

| Exploration | Preload Induced Settlement (feet) | Preload Fill Thickness (feet) | Estimated Long Term Roadway Settlement (inches) |
|---|---|---|---|
| B-5 | 0.1 | 3.3 | 1.0 |

The preliminary global stability cross section was developed at Station 112+00, which we identified as the worst-case soil condition within East Embankment 3. Appendix E presents the soil layers and input parameters used in the preliminary global stability analyses. Figures 23 and 24 present the results of the global stability analyses for both staged construction and end of construction conditions. The results indicate that the D/C is less than 0.67 (i.e. FS > 1.5), therefore, is satisfactory.

## 9.0 PRELIMINARY GEOTECHNICAL EMBANKMENT DESIGN RECOMMENDATIONS

Based on the results of our preliminary analyses, the following are our preliminary geotechnical embankment design recommendations for this project:

- Prior to constructing the roadway embankments and walls, the site will need to be cleared, stripped, grubbed, and all obstructions such as pavements or other structures removed from the footprint of the embankments.
- Based on the subsurface soil conditions encountered within the footprint of the embankments, we anticipate that the site does not require mucking except at a few localized areas where thick, very soft and highly organic soils are encountered. Prior to fill placement, subgrade evaluation should be completed by probing with a ½-inch-diameter steel probe rod to identify areas that require mucking.
- Preload fill will be required within the roadway embankments to pre-induce consolidation soil settlement during the preload period. The feasible preload duration is determined to be 18 months, and wick drains will be installed to help expedite the preload program to ensure that it is completed

within the 18-month period. Table 22 below summarizes the range of preload fill thickness identified within four of the seven delineated embankment zones and the wick drain spacing, if needed.

**TABLE 22. PRELIMINARY RECOMMENDED PRELOAD FILL THICKNESS AND WICK DRAIN SPACING**

| Embankment Zone | Station Range | Preload Fill Thickness above Design Grade (feet) | Wick Drain Spacing (feet) |
|---|---|---|---|
| West Roadway Embankment 1 | 59+00 and lower | < 3.5 | N/A |
| West Roadway Embankment 2 | 59+00 to 69+00 | 3.5 to 5.0 | 6.0-foot Square Pattern |
| East Roadway Embankment 2 | 104+55 to 112+00 | 3.5 to 4.0 | 6.0-foot Square Pattern |
| East Roadway Embankment 3 | 112+00 and higher | < 3.5 | N/A |

- West Roadway Embankment Section 3 that extends from Station 69+00 to 69+65, is located adjacent to the existing Harbor River Bridge pile foundations. Therefore, ground improvement consisting of timber piles will be installed at spacing ranging between 6 to 7 feet in square grids to reduce the undrained lateral soil deformation to prevent additional lateral soil stress that can adversely impact the existing Harbor River Bridge pile foundations.
- To meet the performance limits at EE I limit state, ground improvement consisting of timber piles installed at spacing ranging from 5 to 6 feet in square grids will be required within the West and East Bridge Embankments, extending from Station 69+65 to 70+40 and from Station 103+80 to 104+55, respectively.
- The embankment fill placement should be completed by staged construction using normal weight fill that meets the SCDOT material specifications as structural fill. The rate of fill placement should be managed such that subsurface soil failure does not occur throughout construction.
- Geotechnical instrumentation should be implemented to monitor soil settlement and deformation during construction to ensure that the objectives of the preload program are achieved and to prevent subsurface soil failure from occurring during construction. We recommend that the geotechnical instrumentation program include Settlement Plates, Piezometers and Inclinometers. The quantity and location of the instrumentation will be developed as part of the final embankment design package.

## 10.0 FIELD EXPLORATION AND LABORATORY TESTING PROGRAM

A field exploration and laboratory testing program has been developed to supplement the preliminary exploration and laboratory testing program completed and to refine the soil input parameters used in the preliminary geotechnical design analyses for this project. Soil test borings (SPT) will be performed at each proposed bent location, except at bent 17 where existing boring information is sufficient. Four borings, four CPTs and two dilatometer tests (DMT) are also planned within the new roadway embankment footprint. Borings will be terminated a minimum of 20 feet below the planned foundation tip elevations for the bridge borings, and a minimum of two times the proposed embankment height. All borings will conform to the

guidelines in the SCDOT GDM (2010). Table 23 below presents a summary of the borings, CPTs and DMT planned along the project alignment.

**TABLE 23. SUMMARY OF FIELD INVESTIGATION PLAN**

| Exploration ID | Exploration Type | Station | Proposed Termination Elevation (feet, below MSL) | Drilling Equipment and Access |
|---|---|---|---|---|
| EB1 | Boring | 70+40.50 | -133 | Marsh Buggy |
| B2 | Boring | 72+03 | -131 | Marsh Buggy |
| B3 | Boring | 73+70.50 | -132 | Marsh Buggy |
| B4 | Boring | 75+38 | -132 | Marsh Buggy |
| B5 | Boring | 77+05.50 | -133 | Marsh Buggy |
| B6 | Boring | 78+73 | -155 | Barge |
| B7 | Boring | 80+40.50 | -155 | Barge |
| B8 | Boring | 82+08 | -155 | Barge |
| B9 | Boring | 83+75.50 | -155 | Barge |
| B10 | Boring | 85+43 | -155 | Barge |
| B11 | Boring | 87+10.50 | -155 | Barge |
| B12 | Boring | 88+78 | -155 | Barge |
| B13 | Boring | 90+45.50 | -155 | Barge |
| B14 | Boring | 92+13 | -155 | Barge |
| B15 | Boring | 93+80.50 | -155 | Barge |
| B16 | Boring | 95+48 | -155 | Barge |
| B17 | Boring | 97+15.50 | -135 | NA |
| B18 | Boring | 98+83 | -133 | Marsh Buggy |
| B19 | Boring | 100+50.50 | -133 | Marsh Buggy |
| B20 | Boring | 102+18 | -133 | Marsh Buggy |
| EB21 | Boring | 103+80.50 | -133 | Marsh Buggy |
| 101 | Boring | 66+00 | -49 | Marsh Buggy |
| 102 | Boring | 68+00 | -49 | Marsh Buggy |
| 103 | Boring | 105+00 | -74 | Marsh Buggy |
| 104 | Boring | 107+00 | -74 | Marsh Buggy |
| CPT-1 | Cone Penetration Test | 63+00 | -79 | Marsh Buggy |
| CPT-2 | Cone Penetration Test | 67+00 | -79 | Marsh Buggy |
| CPT-3 | Cone Penetration Test | 109+00 | -79 | Marsh Buggy |
| CPT-4 | Cone Penetration Test | 112+00 | -79 | Marsh Buggy |
| DMT-1 | Dilatometer Test | 70+40.50 | -64 | Marsh Buggy |
| DMT-2 | Dilatometer Test | 103+80.50 | -62 | Marsh Buggy |

We also developed a laboratory testing program consisting of performing laboratory tests using the soil samples obtained from the borings. The objective of the laboratory testing program is to evaluate pertinent physical and engineering characteristics of the soils encountered along the project alignment. Results of the laboratory tests will be used to characterize soil conditions at the site and refine representative design soil profiles and parameters for use in the engineering analyses. Table 24 below presents a summary of the laboratory tests planned for this project.

**TABLE 24. SUMMARY OF LABORATORY TESTING PROGRAM**

| Laboratory Tests | Soil Samples | Quantity |
|---|---|---|
| Moisture Content | Near Surface Soils, Holocene Silts/Clays, Hawthorn Marl | 38 |
| Proctor | Embankment Fill | 4 |
| Atterberg Limits | Near Surface Soils, Holocene Silts/Clays, Hawthorn Marl | 40 |
| Grain Size with No. 200 Wash | Near Surface Soils, Holocene Sand | 30 |
| Consolidation Test | Near Surface Soils, Holocene Silts/Clays, Hawthorn Marl | 20 |
| CU Triaxial Test with pore pressure measurement | Embankment Fill, Near Surface Soils, Holocene Silts/Clays, Hawthorn Marl, Cooper Formation | 40 |
| Organic content | Near Surface Soils (top 5 feet) | 5 |

## 11.0 LIMITATIONS

We have prepared this Preliminary Roadway Geotechnical Report for use by UIG-ICE Design Build Team and the SCDOT for design and construction of the US 21 over Harbor River Bridge Replacement project in Beaufort County, South Carolina.

Within the limitations of scope, schedule and budget, our services have been executed in accordance with generally accepted practices in the field of geotechnical engineering in this area at the time this report was prepared. No warranty or other conditions, express or implied, should be understood.

Any electronic form or hard copy of this document (email, text, table, and/or figure), if provided, and any attachments are only a copy of a master document. The master hard copy is stored by GeoEngineers, Inc. and will serve as the official document of record.

Please refer to Appendix H titled "Report Limitations and Guidelines for Use" for additional information pertaining to use of this report.

## 12.0 REFERENCES

F&ME Consultants, Inc, (2017) "Geotechnical Base Line Report – US 21 (Sea Islands Parkway) Bridge over Harbor River, Beaufort County, South Carolina," February 24, 2017.

F&ME Consultants, Inc, (2017) "Site-Specific Seismic Reponses Analysis Report – US 21 (Sea Islands Parkway) Bridge over Harbor River, Beaufort County, South Carolina," March 10, 2017.

Idriss, I.M. and Boulanger, R.W., (2008) “Soil Liquefaction During Earthquakes,” Earthquake Engineering Research Institute (EERI), EERI Monograph MNO-12.


South Carolina Department of Transportation Geotechnical Manual, SCDOT GDM, (2008).

Terzaghi, K., Peck, R.B., and Mesri, G. (1996). “Soil Mechanics in Engineering Practice,” 3rd Ed., Wiley, New York, pg 549.

Willoughby, Howard, and Nystrom, (2005). “Generalized Geologic Map of South Carolina,” South Carolina Department of Natural Resources Geological Survey.

FIGURES

GeoEngineers




## Vicinity Map

US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 1**

Notes:

1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: F&ME Consultants. Geotechnical Base Line Report, dated 2/24/2017.

18461-007-01




Legend

Cone Penetration Test Location

N
W
E
S

Notes:

1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: F&ME Consultants. Geotechnical Base Line Report, dated 2/24/2017.


18461-007-01

**Exploration Location Plan**

US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 2A**




Legend

- Soil Test Boring Location
- Bulk Sample Location
- Cone Penetration Test Location

Notes:

1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: F&ME Consultants. Geotechnical Base Line Report, dated 2/24/2017.

N W E S

**Exploration Location Plan**

US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 2B**

18461-007-01




Legend

- Soil Test Boring Location
- Bulk Sample Location
- Cone Penetration Test Location

N
W E
S

Notes:

1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: F&ME Consultants. Geotechnical Base Line Report, dated 2/24/2017.


**Exploration Location Plan**

US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 2C**

18461-007-01




Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Legend

- Surficial Holocene - Soft to Med. Stiff Silts and Clays
- Surficial Holocene - Loose to V. Dense Sands
- Hawthorn Marl
- Cooper Group Limestone

Horizontal Scale: 1"=200'
Vertical Scale: 1"=40'
Vertical Exaggeration: 5X

200 0 200
Feet

# US-21 Generalized Subsurface Profile


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

Figure 3A

P:\18\18461007\CAD\00\GeoTech Report\R00\018461007700_F03_Soil Profile.dgn
syl Figure 3A 17x11 (In.) 200.0000 ft / In 12:24:30 PM 10/2/2017

P:\18\18461007\CAD\00\GeoTech Report\R00\018461007700_F03_Soil Profile.dgn
syl Figure 3B 17x11 (In.) 200.0000 ft / in. 12:30:48 PM 10/2/2017




Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Legend

- Surficial Holocene - Soft to Med. Stiff Silts and Clays
- Surficial Holocene - Loose to V. Dense Sands
- Hawthorn Marl
- Cooper Group Limestone

Horizontal Scale: 1"=200'
Vertical Scale: 1"=40'
Vertical Exaggeration: 5X

200 0 200
Feet


# US-21 Generalized Subsurface Profile

US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

Figure 3B

P:\18_18461007\CAD\00\GeoTech Report\R00\018461007700_F03_Soil Profile.dgn 10/2/2017 12:31:20 PM 200.0000 ft / in. 17x11 (In.) Figure 3C syl




Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Legend

- Surficial Holocene - Soft to Med. Stiff Silts and Clays
- Surficial Holocene - Loose to V. Dense Sands
- Hawthorn Marl
- Cooper Group Limestone

Horizontal Scale: 1"=200'
Vertical Scale: 1"=40'
Vertical Exaggeration: 5X


200 0 200
Feet

# US-21 Generalized Subsurface Profile

US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

Figure 3C




Note:
1. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.


**Over-Consolidation Ratio (OCR) with Depth**

US-21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 4**

18461-007-01 Date Exported: 09/29/17




● Consolidation Test Result
Equation of Trendline, y = 0.0041x + 0.0387

Compression Index, Cce

Note:
1. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.


**Moisture Content vs. Compression Index**

US-21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 5**

18461-007-01 Date Exported: 09/29/17




● Consolidation Test Result
Equation of Trendline y = 0.0002x + 0.1067

Recompression Index, Cre
Compression Index, Cce

Note:
1. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

**Moisture Content vs. Cre/Cce Ratio**

US-21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina


GeoEngineers

**Figure 6**


18461-007-01 Date Exported: 09/29/17

## WEST GROUND SURFACE ADRS CURVES w/o GROUND MODIFICATION

(for beginning of bridge embankment)




| T | Sa |
|---|---|
| sec | g |
| 0.00 | 0.14 |
| 0.05 | 0.26 |
| 0.10 | 0.38 |
| 0.15 | 0.38 |
| 0.20 | 0.38 |
| 0.25 | 0.38 |
| 0.30 | 0.38 |
| 0.40 | 0.38 |
| 0.50 | 0.38 |
| 0.55 | 0.38 |
| 0.60 | 0.33 |
| 0.65 | 0.29 |
| 0.70 | 0.26 |
| 0.80 | 0.21 |
| 0.90 | 0.17 |
| 1.00 | 0.14 |
| 1.10 | 0.12 |
| 1.20 | 0.10 |
| 1.30 | 0.09 |
| 1.40 | 0.08 |
| 1.50 | 0.07 |
| 1.60 | 0.07 |
| 1.70 | 0.06 |
| 1.80 | 0.06 |
| 1.90 | 0.06 |
| 2.00 | 0.05 |
| 2.10 | 0.05 |
| 2.20 | 0.05 |
| 2.30 | 0.05 |
| 2.40 | 0.04 |
| 2.50 | 0.04 |
| 2.60 | 0.04 |
| 2.70 | 0.04 |
| 2.80 | 0.04 |
| 2.90 | 0.04 |
| 3.00 | 0.04 |




| T | Sa |
|---|---|
| sec | g |
| 0.00 | 0.26 |
| 0.03 | 0.36 |
| 0.05 | 0.47 |
| 0.12 | 0.74 |
| 0.15 | 0.74 |
| 0.20 | 0.74 |
| 0.25 | 0.74 |
| 0.30 | 0.74 |
| 0.35 | 0.74 |
| 0.40 | 0.74 |
| 0.50 | 0.74 |
| 0.60 | 0.74 |
| 0.70 | 0.74 |
| 0.80 | 0.74 |
| 0.90 | 0.74 |
| 1.00 | 0.74 |
| 1.10 | 0.74 |
| 1.20 | 0.74 |
| 1.30 | 0.74 |
| 1.40 | 0.64 |
| 1.50 | 0.57 |
| 1.60 | 0.51 |
| 1.70 | 0.46 |
| 1.80 | 0.41 |
| 1.90 | 0.36 |
| 2.00 | 0.32 |
| 2.10 | 0.29 |
| 2.20 | 0.26 |
| 2.30 | 0.24 |
| 2.40 | 0.22 |
| 2.50 | 0.20 |
| 2.60 | 0.19 |
| 2.70 | 0.18 |
| 2.80 | 0.17 |
| 2.90 | 0.16 |
| 3.00 | 0.15 |

Reference: Site-Specific Seismic Response Analysis Report prepared by F&ME Consultants, Inc dated March 10, 2017

**West Ground Surface ADRS Curves**

US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina


GeoEngineers

**Figure 7**


18461-007-01 9/29/17

## EAST GROUND SURFACE ADRS CURVES w/o GROUND MODIFICATION

(for end of bridge embankment)




| T | Sa |
|---|---|
| sec | g |
| 0.00 | 0.12 |
| 0.09 | 0.26 |
| 0.20 | 0.26 |
| 0.30 | 0.26 |
| 0.40 | 0.26 |
| 0.50 | 0.26 |
| 0.60 | 0.26 |
| 0.70 | 0.26 |
| 0.80 | 0.26 |
| 0.90 | 0.21 |
| 0.95 | 0.19 |
| 1.00 | 0.17 |
| 1.05 | 0.15 |
| 1.10 | 0.14 |
| 1.15 | 0.13 |
| 1.20 | 0.12 |
| 1.25 | 0.11 |
| 1.30 | 0.10 |
| 1.35 | 0.09 |
| 1.40 | 0.08 |
| 1.50 | 0.07 |
| 1.60 | 0.07 |
| 1.70 | 0.06 |
| 1.80 | 0.06 |
| 1.90 | 0.06 |
| 2.00 | 0.05 |
| 2.10 | 0.05 |
| 2.20 | 0.05 |
| 2.30 | 0.05 |
| 2.40 | 0.04 |
| 2.50 | 0.04 |
| 2.60 | 0.04 |
| 2.70 | 0.04 |
| 2.80 | 0.04 |
| 2.90 | 0.04 |
| 3.00 | 0.04 |




| T | Sa |
|---|---|
| sec | g |
| 0.00 | 0.29 |
| 0.07 | 0.58 |
| 0.10 | 0.58 |
| 0.15 | 0.58 |
| 0.20 | 0.58 |
| 0.25 | 0.58 |
| 0.30 | 0.58 |
| 0.35 | 0.58 |
| 0.40 | 0.58 |
| 0.45 | 0.58 |
| 0.50 | 0.58 |
| 0.60 | 0.58 |
| 0.70 | 0.58 |
| 0.80 | 0.58 |
| 0.90 | 0.58 |
| 1.00 | 0.58 |
| 1.10 | 0.58 |
| 1.20 | 0.58 |
| 1.30 | 0.58 |
| 1.40 | 0.58 |
| 1.50 | 0.58 |
| 1.60 | 0.48 |
| 1.70 | 0.42 |
| 1.80 | 0.37 |
| 1.90 | 0.33 |
| 2.00 | 0.30 |
| 2.10 | 0.28 |
| 2.20 | 0.25 |
| 2.30 | 0.24 |
| 2.40 | 0.21 |
| 2.50 | 0.19 |
| 2.60 | 0.18 |
| 2.70 | 0.17 |
| 2.80 | 0.16 |
| 2.90 | 0.15 |
| 3.00 | 0.15 |

Description of symbols will go here in lower case text.

Description of symbols will go here in lower case text.

Reference: Site-Specific Seismic Response Analysis Report prepared by F&ME Consultants, Inc dated March 10, 2017

# East Ground Surface ADRS Curves


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 8**

18461-007-01 9/29/17

| Color | Name | Model | Unit Weight (pcf) | Phi' (°) | Tau/Sigma Ratio | Cohesion (psf) |
|---|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 38 | | |
| | 1) Silt/Clays | S=f(overburden) | 95 | | 0.46 | |
| | 2) Sands | Mohr-Coulomb | 100 | 29 | | |
| | 3) Hawthorn Marl | Undrained (Phi=0) | 120 | | | 4,000 |
| | 4) Cooper Group Limestone | Undrained (Phi=0) | 120 | | | 6,000 |




Legend

Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - Staged Construction**
**West Embankment 1 (Station 59+00)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 9**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Phi' (°) | Tau/Sigma Ratio | Cohesion (psf) |
|---|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 38 | | |
| | 1) Silt/Clays | S=f(overburden) | 95 | | 0.46 | |
| | 2) Sands | Mohr-Coulomb | 100 | 29 | | |
| | 3) Hawthorn Marl | Undrained (Phi=0) | 120 | | | 4,000 |
| | 4) Cooper Group Limestone | Undrained (Phi=0) | 120 | | | 6,000 |




Legend

Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis


**Global Stability - End of Construction**
**West Embankment 1 (Station 59+00)**

US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 10**

18461-007-01 Date Exported: 09/28/17




| Color | Name | Model | Unit Weight (pcf) | Phi' (°) | Tau/Sigma Ratio | Cohesion (psf) |
|---|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 30 | | |
| | Sands (1) | Mohr-Coulomb | 100 | 30 | | |
| | Silts/Clays | Sef(overburden) | 95 | | 0.38 | |
| | Sands (2) | Mohr-Coulomb | 100 | 30 | | |
| | Hawthorn Marl | Undrained (Phi=0) | 120 | | | 4,000 |
| | Cooper Group Limestone | Undrained (Phi=0) | 120 | | | 6,000 |

Legend

Notes:

1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - Staged Construction**
**West Embankment 2 (Station 69+00)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 11**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Phi' (°) | Tau/Sigma Ratio | Cohesion (psf) |
|---|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 38 | | |
| | Sands (1) | Mohr-Coulomb | 100 | 30 | | |
| | Silts/Clays | S=f(overburden) | 95 | | 0.38 | |
| | Sands (2) | Mohr-Coulomb | 100 | 30 | | |
| | Hawthorn Marl | Undrained (Phi=0) | 120 | | | 4,000 |
| | Cooper Group Limestone | Undrained (Phi=0) | 120 | | | 6,000 |




Legend

Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - End of Construction**
**West Embankment 2 (Station 69+00)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 12**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Phi' (°) | Tau/Sigma Ratio | Cohesion (psf) |
|---|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 38 | | |
| | Sands (1) | Mohr-Coulomb | 100 | 30 | | |
| | Silts/Clays | S=f(overburden) | 95 | | 0.37 | |
| | Sands (2) | Mohr-Coulomb | 100 | 30 | | |
| | Hawthorn Marl | Undrained (Phi=0) | 100 | | | 4,000 |
| | Cooper Group Limestone | Undrained (Phi=0) | 120 | | | 6,000 |




Legend

Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis


**Global Stability - Staged Construction**
**West Embankment 3 (Station 69+65)**

US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 13**

18461-007-01 Date Exported: 09/28/17




Legend

Notes:

1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - End of Construction**
**West Embankment 3 (Station 69+65)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 14**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Cohesion' (psf) | Phi' (°) | Tau/Sigma Ratio | Cohesion (psf) |
|---|---|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 0 | 38 | | |
| | Sands (1) | Mohr-Coulomb | 100 | 0 | 30 | | |
| | Silts/Clays | S=f(overburden) | 95 | | | 0.36 | |
| | Sands (2) | Mohr-Coulomb | 100 | 0 | 30 | | |
| | Hawthorn Marl | Undrained (Phi=0) | 120 | | | | 4,000 |
| | Cooper Group Limestone | Undrained (Phi=0) | 120 | | | | 6,000 |
| | Sands (1) - Improved | Mohr-Coulomb | 100 | 348 | 30 | | |
| | Silts/Clays - Improved | Mohr-Coulomb | 95 | 348 | 19.8 | | |
| | Sands (2) - Improved | Mohr-Coulomb | 100 | 348 | 30 | | |




Legend

Notes:

1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - Staged Construction (Improved)**
**West Embankment 4 (Station 70+40)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 15**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Cohesion' (psf) | Phi' (°) | Tau/Sigma Ratio | Cohesion (psf) |
|---|---|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 0 | 38 | | |
| | Sands (1) | Mohr-Coulomb | 100 | 0 | 30 | | |
| | Silts/Clays | S=f(overburden) | 95 | | | 0.36 | |
| | Sands (2) | Mohr-Coulomb | 100 | 0 | 30 | | |
| | Hawthorn Marl | Undrained (Phi=0) | 120 | | | | 4,000 |
| | Cooper Group Limestone | Undrained (Phi=0) | 120 | | | | 8,000 |
| | Sands (1) - Improved | Mohr-Coulomb | 100 | 348 | 30 | | |
| | Silts/Clays - Improved | Mohr-Coulomb | 95 | 348 | 19.8 | | |
| | Sands (2) - Improved | Mohr-Coulomb | 100 | 348 | 30 | | |




Legend

Notes:

1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - End of Construction (Improved)**
**West Embankment 4 (Station 70+40)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 16**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Cohesion' (psf) | Phi' (°) | Tau/Sigma Ratio | Cohesion (psf) |
|---|---|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 0 | 38 | | |
| | Sands (1) | Mohr-Coulomb | 100 | 0 | 30 | | |
| | Silts/Clays | S=f(overburden) | 95 | | | 0.36 | |
| | Cooper Group Limestone | Undrained (Phi=0) | 120 | | | | 6,000 |
| | Sands (1) - Improved | Mohr-Coulomb | 100 | 348 | 30 | | |
| | Silts/Clays - Improved | Mohr-Coulomb | 95 | 348 | 19.6 | | |
| | Sands (1) - Residual | S=f(overburden) | 100 | | | 0.09 | |
| | Sands (2) - Readual | S=f(overburden) | 100 | | | 0.09 | |
| | Hawthorn Marl - Seismic | Undrained (Phi=0) | 120 | | | | 3,400 |
| | Sands (1) - Residual Improved | Mohr-Coulomb | 100 | 348 | 4.6 | | |
| | Sands (2) - Residual Improved | Mohr-Coulomb | 100 | 348 | 4.6 | | |




Legend

Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - Earthquake (Improved)**
**West Embankment 4 (Station 70+40)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 17**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Cohesion' (psf) | Phi' (°) | Tau/Sigma Ratio |
|---|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 0 | 38 | |
| | Sands (1) | Mohr-Coulomb | 100 | 0 | 30 | |
| | Sands (2) | Mohr-Coulomb | 120 | 0 | 41 | |
| | Sands (3) | Mohr-Coulomb | 100 | 0 | 30 | |
| | Silts/Clays | S=f(overburden) | 95 | | | 0.23 |
| | Sands (4) | Mohr-Coulomb | 100 | 0 | 30 | |
| | Hawthorn Marl | Mohr-Coulomb | 120 | 4,000 | 0 | |
| | Cooper Group Limestone | Mohr-Coulomb | 120 | 6,000 | 0 | |
| | Sands (1) - Improved | Mohr-Coulomb | 100 | 348 | 30 | |
| | Sands (2) - Improved | Mohr-Coulomb | 120 | 348 | 41 | |
| | Sands (3) - Improved | Mohr-Coulomb | 100 | 348 | 30 | |
| | Sands (4) - Improved | Mohr-Coulomb | 100 | 348 | 30 | |
| | Silts/Clays - Improved | Mohr-Coulomb | 95 | 348 | 13 | |




Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - Staged Construction (Improved)**
**East Embankment 1 (Station 103+80)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 18**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Cohesion' (psf) | Phi' (°) | Tau/Sigma Ratio |
|---|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 0 | 38 | |
| | Sands (1) | Mohr-Coulomb | 100 | 0 | 30 | |
| | Sands (2) | Mohr-Coulomb | 120 | 0 | 41 | |
| | Sands (3) | Mohr-Coulomb | 100 | 0 | 30 | |
| | Silts/Clays | S=f(overburden) | 95 | | | 0.23 |
| | Sands (4) | Mohr-Coulomb | 100 | 0 | 30 | |
| | Hawthorn Marl | Mohr-Coulomb | 120 | 4,000 | 0 | |
| | Cooper Group Limestone | Mohr-Coulomb | 130 | 8,000 | 0 | |
| | Sands (1) - Improved | Mohr-Coulomb | 100 | 348 | 30 | |
| | Sands (2) - Improved | Mohr-Coulomb | 120 | 348 | 41 | |
| | Sands (3) - Improved | Mohr-Coulomb | 100 | 348 | 30 | |
| | Sands (4) - Improved | Mohr-Coulomb | 100 | 348 | 30 | |
| | Silts/Clays - Improved | Mohr-Coulomb | 95 | 348 | 13 | |




Legend

Notes:

1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - End of Construction (Improved)**
**East Embankment 1 (Station 103+80)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 19**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Cohesion' (psf) | Phi' (°) | Tau/Sigma Ratio |
|---|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 0 | 38 | |
| | Sands (1) | Mohr-Coulomb | 100 | 0 | 30 | |
| | Sands (2) | Mohr-Coulomb | 120 | 0 | 41 | |
| | Silts/Clays | S=f(overburden) | 95 | | | 0.23 |
| | Cooper Group Limestone | Mohr-Coulomb | 120 | 6,000 | 0 | |
| | Sands (3) - Residual | S=f(overburden) | 100 | | | 0.09 |
| | Sands (4) - Residual | S=f(overburden) | 100 | | | 0.09 |
| | Hawthorn Marl - Seismic | Mohr-Coulomb | 120 | 3,400 | 0 | |
| | Sands (1) - Improved | Mohr-Coulomb | 100 | 348 | 30 | |
| | Sands (2) - Improved | Mohr-Coulomb | 120 | 348 | 41 | |
| | Silts/Clays - Improved | Mohr-Coulomb | 95 | 348 | 13 | |
| | Sands (3) - Residual Improved | Mohr-Coulomb | 100 | 348 | 5.1 | |
| | Sands (4) - Residual Improved | Mohr-Coulomb | 100 | 348 | 5.1 | |




Legend

Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - Earthquake (Improved)**
**East Embankment 1 (Station 103+80)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 20**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Phi' (°) | Tau/Sigma Ratio |
|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 38 | |
| | Sands (1) | Mohr-Coulomb | 100 | 30 | |
| | Sands (2) | Mohr-Coulomb | 120 | 41 | |
| | Sands (3) | Mohr-Coulomb | 100 | 30 | |
| | Silts/Clays | S=f(overburden) | 95 | | 0.22 |
| | Sands (4) | Mohr-Coulomb | 100 | 30 | |
| | Hawthorn Marl | Mohr-Coulomb | 120 | 0 | |
| | Cooper Group Limestone | Mohr-Coulomb | 120 | 0 | |




Legend

Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - Staged Construction**
**East Embankment 2 (Station 104+55)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 21**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Phi' (°) | Tau/Sigma Ratio |
|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 38 | |
| | Sands (1) | Mohr-Coulomb | 100 | 30 | |
| | Sands (2) | Mohr-Coulomb | 120 | 41 | |
| | Sands (3) | Mohr-Coulomb | 100 | 30 | |
| | Silts/Clays | S=f(overburden) | 95 | | 0.22 |
| | Sands (4) | Mohr-Coulomb | 100 | 30 | |
| | Hawthorn Marl | Mohr-Coulomb | 120 | 0 | |
| | Cooper Group Limestone | Mohr-Coulomb | 120 | 0 | |




Legend

Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis


**Global Stability - End of Construction**
**East Embankment 2 (Station 104+55)**

US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 22**

18461-007-01 Date Exported: 09/28/17




| Color | Name | Model | Unit Weight (pcf) | Phi' (°) | Tau/Sigma Ratio |
|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 38 | |
| | Sands (1) | Mohr-Coulomb | 100 | 32 | |
| | Sands (2) | Mohr-Coulomb | 120 | 40 | |
| | Sands (3) | Mohr-Coulomb | 120 | 42 | |
| | Silts/Clays | S=f(overburden) | 95 | | 0.22 |
| | Sands (4) | Mohr-Coulomb | 100 | 31 | |
| | Hawthorn Marl | Mohr-Coulomb | 120 | 0 | |
| | Cooper Group Limestone | Mohr-Coulomb | 120 | 0 | |

Legend

Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - Staged Construction**
**East Embankment 3 (Station 112+00)**


US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 23**

18461-007-01 Date Exported: 09/28/17

| Color | Name | Model | Unit Weight (pcf) | Phi' (°) | Tau/Sigma Ratio |
|---|---|---|---|---|---|
| | Compacted Fill | Mohr-Coulomb | 125 | 38 | |
| | Sands (1) | Mohr-Coulomb | 100 | 32 | |
| | Sands (2) | Mohr-Coulomb | 120 | 40 | |
| | Sands (3) | Mohr-Coulomb | 120 | 42 | |
| | Silts/Clays | S=f(overburden) | 95 | | 0.22 |
| | Sands (4) | Mohr-Coulomb | 100 | 31 | |
| | Hawthorn Marl | Mohr-Coulomb | 120 | 0 | |
| | Cooper Group Limestone | Mohr-Coulomb | 120 | 0 | |




Legend

Notes:
1. The locations of all features shown are approximate.
2. This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Data Source: GeoStudio 2016 v. 8.16.1.13452 – Slope/W Analysis

**Global Stability - End of Construction**
**East Embankment 3 (Station 112+00)**

US 21 Over Harbor River Bridge Replacement
Beaufort County, South Carolina

GeoEngineers

**Figure 24**

18461-007-01 Date Exported: 09/28/17

APPENDICES

GeoEngineers

# APPENDIX A
## Field Explorations

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-1 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 45+50 | **Offset:** | 7.4'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 10.9 ft | **Latitude:** | 32.408695 | **Longitude:** | -80.465492 | **Date Started:** | 8/26/2014 |
| **Total Depth:** | 125 ft | **Soil Depth:** | 125 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/28/2014 |
| **Bore Hole Diameter (in):** | 6 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 550X | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 82% |
| **Core Size:** | N/A | **Driller:** | Independence | **Groundwater:** | **TOB** NR | **24HR** | 8.3 ft |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | Road | | | | | | | | |
| | 0.8 | Asphalt (9.5") | | 1.0 | | | | | | |
| | | **EMBANKMENT FILL** | | 2.0 | SS-1 | 12 | 14 | | | |
| | | Loose to Very Loose, Moist, Dark Yellowish Brown, Non-Plastic, Strongly Reactive, Poorly Graded Fine to Coarse SAND (SP-SM/A-1-b) with Silt and Gravel and Trace of Organics, Munsell=10YR 4/4 | | 4.0 | SS-2 | 6 | 4 | 4 | 4 | 8 |
| 5.9 | | | | 6.0 | SS-3 | 5 | 3 | 4 | 4 | 7 |
| | | @SS-3: Organics=1.15% | | 8.0 | SS-4 | 5 | 2 | 4 | 4 | 6 |
| | | @SS-4: Organics=1.07% | | 10.0 | SS-5 | 4 | 2 | 4 | 2 | 6 |
| 0.9 | | @SS-5: Dark Gray, Munsell=5Y 4/1, LL=NP, PL=NP, PI=NP, NMC=19.3%, %#200=7.3 | | 12.0 | SS-6 | 1 | 1 | 2 | 2 | 3 |
| | | @SS-6: Wet, Weakly Reactive | | 14.0 | SS-7 | 3 | 2 | 2 | 4 | 4 |
| | | @SS-7: Fine Sand, (A-3), LL=NP, PL=NP, PI=NP, NMC=19.2%, %#200=8.0 | | 16.0 | SS-8 | 4 | 4 | 4 | 4 | 8 |
| -4.1 | | @SS-8: Organics=0.31% | | 18.0 | SS-9 | 1 | 1 | 1 | 2 | 2 |
| | 18.0 | **ENGINEERED FILL** | | | SS-10 | 1 | 1 | 1 | WOH | 2 |
| -9.1 | | Very Loose, Wet, Dark Gray, Non-Plastic, Weakly Reactive, Poorly Graded Fine SAND (SP/A-3), Munsell=5Y 4/1 | | 23.5 | SS-11 | 1 | 1 | 1 | | 2 |
| | | @SS-10: LL=NP, PL=NP, PI=NP, NMC=27.4%, %#200=3.3 | | | | | | | | |
| -14.1 | | | | 28.5 | SS-12 | 1 | 2 | 2 | | 4 |
| | 28.0 | **HOLOCENE** | | | | | | | | |
| -19.1 | | Very Loose, Wet, Very Dark Greenish Gray, Non-Plastic, Weakly Reactive, Poorly Graded Fine SAND (SP-SM/A-3) with Silt and Trace of Shell Fragments, Munsell=5GY 3/1 | | 33.5 | SS-13 | 2 | 2 | 2 | | 4 |
| | | @SS-12: LL=NP, PL=NP, PI=NP, NMC=34.7%, %#200=7.4 | | | | | | | | |
| -24.1 | | | | 38.5 | SS-14 | 2 | 1 | 2 | | 3 |
| -29.1 | | | | | | | | | | |
| | | @SS-15: (A-2-4), LL=NP, PL=NP, PI=NP, NMC=33.8%, %#200=11.0 | | 43.5 | SS-15 | | 1/12" | 1 | | 1 |
| -34.1 | 46.5 | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-1 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 45+50 | **Offset:** | 7.4'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 10.9 ft | **Latitude:** | 32.408695 | **Longitude:** | -80.465492 | **Date Started:** | 8/26/2014 |
| **Total Depth:** | 125 ft | **Soil Depth:** | 125 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/28/2014 |
| **Bore Hole Diameter (in):** | 6 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 550X | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 82% |
| **Core Size:** | N/A | **Driller:** | Independence | **Groundwater:** | **TOB** NR | **24HR** | 8.3 ft |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| | | Very Loose, Wet, Very Dark Greenish Gray, Non-Plastic, Weakly Reactive, Silty Fine SAND (SM/A-2-4), Munsell=5GY 3/1 | 48.5 | SS-16 | WOH/12" | | | | 1 |
| -39.1 | 51.0 | @SS-16: LL=NP, PL=NP, PI=NP, NMC=59.0%, %#200=33.2 | | | | | | | |
| | | **HAWTHORN MARL** | 53.5 | | | | | | |
| | | Stiff, Moist, Very Dark Greenish Olive, Low to Medium Plasticity, Weakly Reactive, SILT (ML/A-4) with Phosphate Nodules/Lenses, Munsell=5GY 3/2 | 55.0 | SS-17 | 2 | 4 | 10 | | 14 |
| -44.1 | | | | SS-18 | 4 | 26 | 8 | | 34 |
| | | @SS-18: Hard | 58.5 | | | | | | |
| | | @SS-19: Firm to Stiff | | SS-19 | 3 | 3 | 4 | | 7 |
| -49.1 | | | 63.5 | | | | | | |
| | | | | SS-20 | 3 | 3 | 3 | | 6 |
| -54.1 | | | 65.0 | | | | | | |
| | | | 66.5 | SS-21 | 3 | 3 | 4 | | 7 |
| | | | | SS-22 | 3 | 5 | 5 | | 10 |
| | | | 68.5 | | | | | | |
| | | | | SS-23 | 5 | 5 | 7 | | 12 |
| -59.1 | | | 73.5 | | | | | | |
| | | | | SS-24 | 2 | 4 | 7 | | 11 |
| -64.1 | | | 78.5 | | | | | | |
| | 79.5 | @SS-25: Very Stiff | | SS-25 | 5 | 5 | 18 | | 23 |
| -69.1 | | **COOPER GROUP LIMESTONE** | 83.5 | | | | | | |
| | | Medium Dense, Moist, Light Greenish Gray, Non-Plastic to Low Plasticity, Strongly Reactive, Silty Fine to Coarse SAND (SM/A-2-4) with Phosphate Nodules and Trace of Shell Fragments, Munsell=5GY 7/1 | | SS-26 | 4 | 1 | 2 | | 3 |
| -74.1 | | @SS-26: Very Loose to Loose | 88.5 | | | | | | |
| | | | | SS-27 | 3 | 3 | 7 | | 10 |
| -79.1 | | | | | | | | | |

SPT N VALUE ● PL MC LL ▲ FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90

*For Hammer Calibration* (SS-18, SS-21, SS-22)

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-1 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 45+50 | **Offset:** | 7.4'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 10.9 ft | **Latitude:** | 32.408695 | **Longitude:** | -80.465492 | **Date Started:** | 8/26/2014 |
| **Total Depth:** | 125 ft | **Soil Depth:** | 125 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/28/2014 |
| **Bore Hole Diameter (in):** | 6 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 550X | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 82% |
| **Core Size:** | N/A | **Driller:** | Independence | **Groundwater:** | **TOB** NR | **24HR** | 8.3 ft |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Medium Dense to Loose, Moist, Light Greenish Gray, Non-Plastic to Low Plasticity, Strongly Reactive, Silty Fine to Coarse SAND (SM/A-2-4) with Phosphate Nodules and Trace of Shell Fragments, Munsell=5GY 7/1 | | 93.5 | SS-28 | 2 | 4 | 7 | | 11 |
| -84.1 | | | | | | | | | | |
| -89.1 | | | | 100.0 | SS-29 | 6 | 12 | 13 | | 25 |
| | | | | 103.5 | SS-30 | 2 | 5 | 5 | | 10 |
| -94.1 | | | | | | | | | | |
| | | | | 108.5 | SS-31 | 2 | 4 | 5 | | 9 |
| -99.1 | | | | | | | | | | |
| | | @SS-32: No Phosphate Nodules or Shell Fragments | | 113.5 | SS-32 | 3 | 4 | 8 | | 12 |
| -104.1 | | | | | | | | | | |
| | | | | 118.5 | SS-33 | 4 | 5 | 7 | | 12 |
| -109.1 | | | | | | | | | | |
| | | | | 123.5 | SS-34 | 6 | 8 | 8 | | 16 |
| -114.1 | 125.0 | Boring Terminated at 125.0 Feet | | | | | | | | |
| -119.1 | | | | | | | | | | |
| -124.1 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-2 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 109+84 | **Offset:** | 28.4'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 8.6 ft | **Latitude:** | 32.401896 | **Longitude:** | -80.446292 | **Date Started:** | 9/2/2014 |
| **Total Depth:** | 125 ft | **Soil Depth:** | 125 ft | **Core Depth:** | N/A ft | **Date Completed:** | 9/3/2014 |
| **Bore Hole Diameter (in):** | 6 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 550X | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 82% |
| **Core Size:** | N/A | **Driller:** | Independence | **Groundwater:** | **TOB** NR | **24HR** | 5.9 ft |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | Road | | | | | | | | |
| | 1.0 | Asphalt (11.5") | | 1.0 | | | | | | |
| | | **EMBANKMENT FILL** | | 2.0 | SS-1 | 11 | 15 | | | |
| | | Medium Dense to Loose, Dry to Moist, Very Pale Brown, Non-Plastic, Weakly Reactive, Poorly Graded Fine SAND (SP/A-3) with Trace of Organics, Munsell=10YR 7/3 | | 4.0 | SS-2 | 9 | 10 | 10 | 10 | 20 |
| 3.6 | | | | 6.0 | SS-3 | 3 | 4 | 2 | 2 | 6 |
| | | @SS-3: Dark Olive Brown, Munsell=2.5Y 3/3, Organics=0.56% | | 8.0 | SS-4 | 1/12" | 1 | 1 | | 1 |
| | | @SS-4: Very Loose, Wet, Very Dark Grayish Brown, Munsell=2.5Y 3/2, LL=NP, PL=NP, PI=NP, NMC=28.7%, %#200=4.9 | | 10.0 | SS-5 | 7 | 6 | 5 | 4 | 11 |
| -1.4 | | | | 12.0 | SS-6 | 3 | 4 | 14 | 16 | 18 |
| | | @SS-5: Medium Dense to Dense, LL=NP, PL=NP, PI=NP, NMC=27.9%, %#200=2.5 | | 14.0 | SS-7 | 4 | 10 | 20 | 23 | 30 |
| -6.4 | | @SS-6: Organics=0.45% | | 16.0 | SS-8 | 8 | 18 | 20 | 17 | 38 |
| | | | | 18.0 | SS-9 | 6 | 11 | 10 | 8 | 21 |
| | 18.0 | **ENGINEERED FILL** | | | SS-10 | 3 | 3 | 4 | 8 | 7 |
| -11.4 | | Loose to Very Loose, Wet, Gray, Non-Plastic, Weakly Reactive, Fine SAND (SP-SM/A-3) with Silt and Trace of Organics, Munsell=5Y 5/1 | | 23.5 | SS-11 | WOH/18" | | | | WOH |
| | | @SS-10: LL=NP, PL=NP, PI=NP, NMC=26.5%, %#200=6.3 | | | | | | | | |
| -16.4 | | | | 28.5 | SS-12 | 1/12" | 1 | | | 1 |
| | 27.0 | @SS-11: Very Dark Greenish Gray, Munsell=5GY 3/1, Organics=1.25% | | | | | | | | |
| | | **HOLOCENE** | | 33.5 | SS-13 | 1 | 2 | 2 | | 4 |
| -21.4 | | Very Loose, Wet, Very Dark Greenish Gray, Non-Plastic, Weakly Reactive, Silty Fine SAND (SM/A-2-4), Munsell=5GY 3/1 | | | | | | | | |
| | | @SS-12: LL=NP, PL=NP, PI=NP, NMC=30.3%, %#200=14.0 | | 38.5 | SS-14 | 1 | 3 | 1 | | 4 |
| -26.4 | | | | | | | | | | |
| | 37.0 | | | 43.5 | SS-15 | 3 | 9 | 10 | | 19 |
| | | Very Loose, Wet, Dark Gray, Non-Plastic, Weakly Reactive, Poorly Graded Fine SAND (SP-SM/A-3) with Silt and Trace of Shell Fragments, Munsell=10Y 4/1 | | | | | | | | |
| -31.4 | | @SS-14: LL=NP, PL=NP, PI=NP, NMC=29.3%, %#200=8.8 | | 48.5 | SS-16 | 2 | 3 | 4 | | 7 |
| | | @SS-15: Medium Dense to Loose | | | | | | | | |
| -36.4 | | | | | | | | | | |
| -41.4 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-2 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 109+84 | **Offset:** | 28.4'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 8.6 ft | **Latitude:** | 32.401896 | **Longitude:** | -80.446292 | **Date Started:** | 9/2/2014 |
| **Total Depth:** | 125 ft | **Soil Depth:** | 125 ft | **Core Depth:** | N/A ft | **Date Completed:** | 9/3/2014 |
| **Bore Hole Diameter (in):** | 6 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 550X | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 82% |
| **Core Size:** | N/A | **Driller:** | Independence | **Groundwater:** | **TOB** NR | **24HR** | 5.9 ft |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| | | Medium Dense, Wet, Dark Gray, Non-Plastic, Weakly Reactive, Poorly Graded Fine SAND (SP-SM/A-3) with Silt and Trace of Shell Fragments, Munsell=10Y 4/1 | 53.5 | SS-17 | 2 | 4 | 7 | | 11 |
| -46.4 | | @SS-17: Very Dark Grayish Green, Munsell=5Y 3/2, LL=NP, PL=NP, PI=NP, NMC=28.4%, %#200=10.0 | | | | | | | |
| | | @SS-18: Very Loose | 58.5 | SS-18 | 1 | 1 | 1 | | 2 |
| -51.4 | 62.0 | | | | | | | | |
| | | Very Soft, Wet, Very Dark Gray, Low to Medium Plasticity, Weakly Reactive, CLAY (CL/A-6), Munsell=5Y 3/1 | 63.5 | SS-19 | WOH/12" | | 1 | | 1 |
| -56.4 | 67.0 | | | | | | | | |
| | | Loose, Wet, Dark Gray, Non-Plastic, Weakly Reactive, Fine SAND (SP-SM/A-3) with Silt, Munsell=5Y 4/1 | 68.5 | SS-20 | 1 | 3 | 4 | | 7 |
| -61.4 | | | | | | | | | |
| | 74.0 | | 73.5 | SS-21 | 1 | 2 | 3 | | 5 |
| -66.4 | | **HAWTHORN MARL** | | | | | | | |
| | | Firm to Soft, Moist, Dark Olive Gray, Non-Plastic to Low Plasticity, Weakly Reactive, SILT (ML/A-4), Munsell=5Y 3/2 | 78.5 | SS-22 | 1 | 1 | 4 | | 5 |
| -71.4 | | | | | | | | | |
| | | @SS-23: Strongly Reactive | 83.5 | SS-23 | 2 | 2 | 2 | | 4 |
| -76.4 | 87.0 | | | | | | | | |
| | | **COOPER GROUP LIMESTONE** | 88.5 | SS-24 | 20 | 26 | 6 | | 32 |
| | | Dense, Moist, Olive, Non-Plastic, Strongly Reactive, Silty Fine to Coarse SAND (SM/A-2-4) with Phosphate Nodules/Lenses, Munsell=5Y 4/3 | | | | | | | |
| -81.4 | | | | | | | | | |
| | | @SS-25: Loose to Very Loose, Light Olive Gray, Munsell=5Y 6/2 | 93.5 | SS-25 | 1 | 1 | 4 | | 5 |
| -86.4 | | | | | | | | | |
| | | @SS-26: Greenish Gray, Munsell=10Y 6/1 | 98.5 | SS-26 | 2 | 2 | 4 | | 6 |
| -91.4 | | | | | | | | | |

● SPT N VALUE ●

PL MC LL

▲ FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-2 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 109+84 | **Offset:** | 28.4'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 8.6 ft | **Latitude:** | 32.401896 | **Longitude:** | -80.446292 | **Date Started:** | 9/2/2014 |
| **Total Depth:** | 125 ft | **Soil Depth:** | 125 ft | **Core Depth:** | N/A ft | **Date Completed:** | 9/3/2014 |
| **Bore Hole Diameter (in):** | 6 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 550X | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 82% |
| **Core Size:** | N/A | **Driller:** | Independence | **Groundwater:** | **TOB** NR | **24HR** | 5.9 ft |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Very Loose to Loose, Moist, Olive, Non-Plastic, Strongly Reactive, Silty Fine to Coarse SAND (SM/A-2-4) with Phosphate Nodules/Lenses, Munsell=5Y 4/3 | | 103.5 | SS-27 | 1 | 2 | 2 | | 4 |
| -96.4 | | | | 108.5 | SS-28 | 1 | 2 | 5 | | 7 |
| -101.4 | | | | 113.5 | SS-29 | 1 | 4 | 6 | | 10 |
| -106.4 | | | | 118.5 | SS-30 | 2 | 2 | 5 | | 7 |
| -111.4 | | | | 123.5 | SS-31 | 2 | 3 | 4 | | 7 |
| -116.4 | 125.0 | Boring Terminated at 125.0 Feet | | | | | | | | |
| -121.4 | | | | | | | | | | |
| -126.4 | | | | | | | | | | |
| -131.4 | | | | | | | | | | |
| -136.4 | | | | | | | | | | |
| -141.4 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-3 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | J. Stewart | **Boring Location:** | 39+79 | **Offset:** | 81.5'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.5 ft | **Latitude:** | 32.409483 | **Longitude:** | -80.467111 | **Date Started:** | 9/15/2015 |
| **Total Depth:** | 80 ft | **Soil Depth:** | 80 ft | **Core Depth:** | N/A ft | **Date Completed:** | 9/15/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Deidrich D-25 | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 80% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0.5 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | Marsh | | | | | | | | |
| | | **HOLOCENE** | | 0.0 | SS-1 | WOR/12" | WOH/12" | | | WOH |
| | | Very Loose, Wet, Black, Non-Plastic, Silty Fine SAND (SM/A-4(0)), Munsell=GLEY1 2.5/N | | 2.0 | SS-2 | WOR/24" | | | | WOH |
| | 4.0 | @SS-1: LL=NP, PL=NP, PI=NP, NMC=36.9%, %#200=37.5 | | 4.0 | SS-3 | WOR/24" | | | | WOH |
| -2.5 | | @SS-2: No Recovery | | 6.0 | SS-4 | WOR/24" | | | | WOH |
| | | Very Soft, Wet, Black, High Plasticity, Elastic SILT (MH/A-7-5(36)) with Trace of Organics, Munsell=GLEY1 2.5/N | | 8.0 | SS-5 | WOR/18" | 1 | | | WOH |
| | 9.8 | @SS-3: Organics=3.55% | | | | | | | | |
| -7.5 | | @SS-4: LL=74, PL=49, PI=25, NMC=151.6%, %#200=98.5 | | 13.5 | SS-6 | 12 | 8 | 8 | | 16 |
| | | Very Loose, Wet, Dark Greenish Gray, Non-Plastic, Poorly Graded Fine SAND (SP-SM/A-3) with Silt, Munsell=GLEY1 4/10Y | | | | | | | | |
| -12.5 | | @SS-6: Medium Dense, Greenish Gray, Moist, Munsell=GLEY1 5/N, LL=NP, PL=NP, PI=NP, NMC=26.1%, %#200=7.7 | | 18.5 | SS-7 | 1 | 1/12" | | | 1 |
| | 19.5 | @SS-7: Very Loose, Moist to Wet | | | | | | | | |
| -17.5 | | Very Loose, Moist to Wet, Black, Non-Plastic, Silty Fine to Coarse SAND (SM/A-2-4) with Gravel and Shells, Munsell=GLEY1 2.5N | | 23.5 | SS-8 | 1/12" | | 1 | | 1 |
| -22.5 | | @SS-8: Very Dark Greenish Gray, Munsell=GLEY1 3/10Y, LL=NP, PL=NP, PI=NP, NMC=29.3%, %#200=24.5 | | | | | | | | |
| | 28.5 | | | 28.5 | SS-9 | WOH/18" | | | | WOH |
| -27.5 | | Very Soft, Moist to Wet, Very Dark Greenish Gray, High Plasticity, Elastic SILT (MH/A-7-5(32)) with Trace of Shells, Munsell=GLEY1 3/10Y | | | | | | | | |
| | | @SS-9: LL=58, PL=31, PI=27, NMC=101.1%, %#200=96.6 | | 33.5 | SS-10 | WOH/18" | | | | WOH |
| | 33.5 | | | | | | | | | |
| -32.5 | | Very Loose, Moist to Wet, Very Dark Greenish Gray, Non-Plastic, Poorly Graded Fine SAND (SP-SM/A-3) with Silt and Trace of Shells, Munsell=GLEY1 3/10Y | | 38.5 | SS-11 | WOH | 1 | 2 | | 3 |
| | | @SS-11: LL=NP, PL=NP, PI=NP, NMC=30.2%, %#200=10.4 | | | | | | | | |
| -37.5 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-3 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | J. Stewart | **Boring Location:** | 39+79 | **Offset:** | 81.5'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.5 ft | **Latitude:** | 32.409483 | **Longitude:** | -80.467111 | **Date Started:** | 9/15/2015 |
| **Total Depth:** | 80 ft | **Soil Depth:** | 80 ft | **Core Depth:** | N/A ft | **Date Completed:** | 9/15/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Deidrich D-25 | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 80% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0.5 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| | | Very Loose, Moist to Wet, Dark Gray, Non-Plastic, Poorly Graded Fine SAND (SP-SM/A-3) with Silt and Trace of Shells, Munsell=GLEY1 4/N | 43.5 | SS-12 | 4 | 3 | 1 | | 4 |
| -42.5 | 46.0 | **HAWTHORN MARL** | | | | | | | |
| | | Firm to Soft, Moist, Dark Grayish Olive, Non-Plastic to Low Plasticity, SILT (ML/A-4), Munsell=10Y 4/2 | 48.5 | SS-13 | 2 | 3 | 4 | | 7 |
| -47.5 | | | | | | | | | |
| | | @SS-14: Very Dark Grayish Brown, Munsell=10YR 3/2 | 53.5 | SS-14 | 1 | 2 | 2 | | 4 |
| -52.5 | | | | | | | | | |
| | | | 58.5 | SS-15 | 2 | 3 | 4 | | 7 |
| -57.5 | | | | | | | | | |
| | | | 63.5 | SS-16 | 2 | 2 | 3 | | 5 |
| -62.5 | | | | | | | | | |
| | | @SS-17: Stiff, Olive Brown, Munsell=2.5Y 4/4 | 68.5 | SS-17 | 4 | 4 | 6 | | 10 |
| -67.5 | 71.0 | **COOPER GROUP LIMESTONE** | | | | | | | |
| | | Stiff to Firm, Moist, Light Greenish Gray, Non-Plastic, Strongly Reactive, SILT (ML/A-4) with Sand, Munsell=GLEY1 7/5GY | 73.5 | SS-18 | 4 | 5 | 3 | | 8 |
| -72.5 | 75.0 | Loose, Moist, Light Gray/Black, Non-Plastic, Strongly Reactive, Silty Fine to Medium SAND (SM/A-2-4) with Trace of Shells, Munsell=GLEY1 7/N and 2.5/N | 78.5 | SS-19 | 4 | 2 | 4 | | 6 |
| -77.5 | 80.0 | @SS-19: Light Greenish Gray, Munsell=GLEY1 7/5GY | | | | | | | |
| | | Boring Terminated at 80.0 feet | | | | | | | |

● SPT N VALUE ●

PL MC LL

▲ FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-4 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 53+45 | **Offset:** | 92.6'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.4 ft | **Latitude:** | 32.408077 | **Longitude:** | -80.463008 | **Date Started:** | 9/16/2015 |
| **Total Depth:** | 80 ft | **Soil Depth:** | 80 ft | **Core Depth:** | N/A ft | **Date Completed:** | 9/16/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Deidrich D-25 | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 80% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 2 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | Marsh | | 0.0 | SS-1 | WOH/12" | | | | 1 |
| | | **HOLOCENE** | | 2.0 | | | | | | |
| | | ▽Very Loose, Wet, Dark Grayish Brown, Non-Plastic, Silty Fine SAND (SM/A-2-4) with Trace of Organics, Munsell=2.5Y 4/2 | | | SS-2 | WOH/12" | | | 1 | 1 |
| | | @SS-2: LL=NP, PL=NP, PI=NP, NMC=52.5%, %#200=31.9 | | 4.0 | SS-3 | WOH/24" | | | | WOH |
| -2.6 | 5.0 | @SS-3: Organics=2.68% | | 6.0 | SS-4 | WOH/24" | | | | WOH |
| | 7.5 | Very Soft, Wet, Dark Olive Gray, Medium to High Plasticity, CLAY (CL/A-7) with Trace of Shells, Munsell=5Y 3/2 | | 8.0 | SS-5 | WOH | 1/12" | | 1 | 1 |
| -7.6 | | Very Loose to Loose, Wet, Dark Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4), Munsell=5Y 4/1 | | | | | | | | |
| | | @SS-5: LL=NP, PL=NP, PI=NP, NMC=32.9%, %#200=26.0 | | 13.5 | SS-6 | 1 | 1 | 1 | | 2 |
| -12.6 | | @SS-6: LL=NP, PL=NP, PI=NP, NMC=31.8%, %#200=15.1 | | | | | | | | |
| | | @SS-7: Olive Gray, Munsell=5Y 5/2 | | 18.5 | SS-7 | 2 | 3 | 2 | | 5 |
| -17.6 | | | | | | | | | | |
| | | @SS-8: Dark Olive Gray, with Trace of Shells, Munsell=5Y 3/2, LL=NP, PL=NP, PI=NP, NMC=27.8%, %#200=22.0 | | 23.5 | SS-8 | 2 | 2 | 1 | | 3 |
| -22.6 | | | | | | | | | | |
| | | @SS-9: Greenish Gray, Munsell=GLEY1 5/1 | | 28.5 | SS-9 | 1 | 2 | 1 | | 3 |
| -27.6 | | | | | | | | | | |
| | | @SS-10: LL=NP, PL=NP, PI=NP, NMC=35.8%, %#200=21.6 | | 33.5 | SS-10 | WOH | 1 | 1 | | 2 |
| -32.6 | | | | | | | | | | |
| | | | | 38.5 | SS-11 | WOH/18" | | | | WOH |
| -37.6 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-4 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 53+45 | **Offset:** | 92.6'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.4 ft | **Latitude:** | 32.408077 | **Longitude:** | -80.463008 | **Date Started:** | 9/16/2015 |
| **Total Depth:** | 80 ft | **Soil Depth:** | 80 ft | **Core Depth:** | N/A ft | **Date Completed:** | 9/16/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Deidrich D-25 | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 80% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 2 ft | **24HR** | TIDAL |


| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Very Loose, Wet, Greenish Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4), Munsell=GLEY1 5/1 | 43.5 | SS-12 | 1 | 2 | 2 | | 4 | |
| -42.6 | | | 48.5 | SS-13 | 2 | 1 | 1 | | 2 | |
| -47.6 | | @SS-13: LL=NP, PL=NP, PI=NP, NMC=31.8%, %#200=17.0 | | | | | | | | |
| | 51.0 | **HAWTHORN MARL** | | | | | | | | |
| | | Very Soft to Soft, Wet, Olive Gray, Non-Plastic, SILT (ML/A-4) with Sand, Calcaceous, Munsell=5Y 4/2 | 53.5 | SS-14 | 2 | 2 | 2 | | 4 | |
| -52.6 | | | 58.5 | SS-15 | 1 | 3 | 4 | | 7 | |
| | 58.5 | Firm, Moist, Dark Olive Gray, High Plasticity, Sandy Elastic SILT (MH/A-7-5(16)), Calcaceous, Munsell=5Y 3/2 | | | | | | | | |
| -57.6 | | | 63.5 | SS-16 | 3 | 3 | 4 | | 7 | |
| -62.6 | | @SS-16: Very Dark Grayish Brown, Munsell=2.5Y 3/2, LL=71, PL=35, PI=26, NMC=64.5%, %#200=53.1 | | | | | | | | |
| | | | 68.5 | SS-17 | 2 | 2 | 4 | | 6 | *Lost Casing Shoe, Switched to* |
| -67.6 | | @SS-17: Olive Gray, Munsell=5Y 4/2 | | | | | | | | |
| | 72.5 | **COOPER GROUP LIMESTONE** | 73.5 | SS-18 | 50/5" | | | | 100+ | *Roller Cone* |
| -72.6 | | @SS-18: No Recovery | | | | | | | | |
| | 78.5 | | 78.5 | SS-19 | 3 | 4 | 5 | | 9 | |
| -77.6 | 80.0 | Loose, Wet, Light Olive Gray, Non-Plastic, Strongly Reactive, Silty Fine SAND (SM/A-2-4) with Phosphate Nodules, Calcaceous, Munsell=5Y 6/2 | | | | | | | | |
| | | Boring Terminated at 80.0 feet | | | | | | | | |

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-5 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 116+48 | **Offset:** | 81.7'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.7 ft | **Latitude:** | 32.400844 | **Longitude:** | -80.444475 | **Date Started:** | 9/17/2015 |
| **Total Depth:** | 80 ft | **Soil Depth:** | 80 ft | **Core Depth:** | N/A ft | **Date Completed:** | 9/17/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Deidrich D-25 | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 80% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |




LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-5 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 116+48 | **Offset:** | 81.7'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.7 ft | **Latitude:** | 32.400844 | **Longitude:** | -80.444475 | **Date Started:** | 9/17/2015 |
| **Total Depth:** | 80 ft | **Soil Depth:** | 80 ft | **Core Depth:** | N/A ft | **Date Completed:** | 9/17/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Deidrich D-25 | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 80% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| | | Loose, Wet, Dark Greenish Gray, Non-Plastic, Silty Fine to Medium SAND (SM/A-2-4), Munsell=GLEY1 4/5GY | 43.5 | | | | | | |
| -42.3 | | @SS-12: LL=NP, PL=NP, PI=NP, NMC=33.4%, %#200=20.9 | | SS-12 | 2 | 3 | 4 | | 7 |
| | | | 48.5 | | | | | | |
| | | @SS-13: Greenish Gray, with Trace of Shells, Munsell=GLEY1 5/10Y | | SS-13 | 2 | 4 | 6 | | 10 |
| -47.3 | | | | | | | | | |
| | | | 53.5 | | | | | | |
| | | @SS-14: LL=NP, PL=NP, PI=NP, NMC=38.9%, %#200=26.0 | | SS-14 | 1 | 2 | 4 | | 6 |
| -52.3 | | | | | | | | | |
| | 58.5 | **HAWTHORN MARL** | 58.5 | | | | | | |
| | | Firm to Soft, Moist, Olive, Medium to High Plasticity, Elastic SILT (MH/A-7), Munsell=5Y 4/4 | | SS-15 | 2 | 2 | 3 | | 5 |
| -57.3 | | | | | | | | | |
| | | @SS-16: Non-Reactive | 63.5 | | | | | | |
| | | | | SS-16 | 1 | 2 | 2 | | 4 |
| -62.3 | | | | | | | | | |
| | | | 68.5 | | | | | | |
| | | | | SS-17 | 2 | 2 | 3 | | 5 |
| -67.3 | | | | | | | | | |
| | | | 73.5 | | | | | | |
| | | | | SS-18 | 2 | 2 | 3 | | 5 |
| -72.3 | | | | | | | | | |
| | | | 78.5 | | | | | | |
| | 79.5 | | | SS-19 | 3 | 10 | 33 | | 43 |
| -77.3 | 80.0 | **COOPER GROUP LIMESTONE** | | | | | | | |
| | | Dense, Wet, Dark Gray, Clayey GRAVEL (GC), Munsell=5Y 4/1 | | | | | | | |
| | | Boring Terminated at 80.0 feet | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-6 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 119+93 | **Offset:** | 41.7'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.3 ft | **Latitude:** | 32.39997 | **Longitude:** | -80.443953 | **Date Started:** | 9/18/2015 |
| **Total Depth:** | 80 ft | **Soil Depth:** | 80 ft | **Core Depth:** | N/A ft | **Date Completed:** | 9/18/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Deidrich D-25 | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 80% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | Marsh | | 0.0 | SS-1 | WOH/24" | | | | WOH |
| | 2.0 | **HOLOCENE** Very Soft, Wet, Dark Olive, Non-Plastic to Low Plasticity, Sandy SILT (ML/A-4), Munsell=5Y 3/2 | | 2.0 | SS-2 | WOH | 6 | 6 | 6 | 12 |
| -2.7 | | Medium Dense to Loose, Wet, Dark Olive, Non-Plastic, Silty Fine SAND (SM/A-2-4) with Trace of Organics, Munsell=5Y 3/2 | | 4.0 | SS-3 | 2 | 2 | 7 | 7 | 9 |
| | | @SS-2: Organics=0.53% | | 6.0 | SS-4 | 9 | 7 | 9 | 14 | 16 |
| | | @SS-3: Dark Grayish Brown, Munsell=2.5Y 4/2, LL=NP, PL=NP, PI=NP, NMC=28.4, %#200=17.2 | | 8.0 | SS-5 | 6 | 10 | 16 | 20 | 26 |
| -7.7 | | @SS-4: Grayish Olive/Greenish Gray, Munsell=10Y 5/2 & GLEY1 10Y 5/1 | | | | | | | | |
| | | @SS-5=> LL=NP, PL=NP, PI=NP, NMC=24.6%, %#200=15.7 | | 13.5 | SS-6 | WOH/18" | | | | WOH |
| -12.7 | | @SS-6: Very Loose, Dark Greenish Gray, Munsell=GLEY1 4/10Y, LL=NP, PL=NP, PI=NP, NMC=34.8%, %#200=26.1 | | | | | | | | |
| | | @SS-7: Medium Dense to Dense | | 18.5 | SS-7 | 6 | 9 | 11 | | 20 |
| -17.7 | | | | | | | | | | |
| | | @SS-8: LL=NP, PL=NP, PI=NP, NMC=24.8%, %#200=13.7 | | 23.5 | SS-8 | 11 | 14 | 19 | | 33 |
| -22.7 | | | | | | | | | | |
| | 28.5 | | | 28.5 | SS-9 | WOH/18" | | | | WOH |
| -27.7 | | Very Loose, Wet, Greenish Gray, Non-Plastic, Poorly Graded Fine SAND (SP-SM/A-2-4) with Silt, Munsell=GLEY1 5/5GY | | | | | | | | |
| | | @SS-9: LL=NP, PL=NP, PI=NP, NMC=28.8%, %#200=11.0 | | | | | | | | |
| | 33.5 | | | 33.5 | SS-10 | WOH | 2 | 2 | | 4 |
| -32.7 | | Very Loose, Wet, Greenish Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4), Munsell=GLEY1 5/5GY | | | | | | | | |
| | | @SS-11: Medium Dense, LL=NP, PL=NP, PI=NP, NMC=27.5%, %#200=18.3 | | 38.5 | SS-11 | 3 | 3 | 10 | | 13 |
| -37.7 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-6 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 119+93 | **Offset:** | 41.7'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.3 ft | **Latitude:** | 32.39997 | **Longitude:** | -80.443953 | **Date Started:** | 9/18/2015 |
| **Total Depth:** | 80 ft | **Soil Depth:** | 80 ft | **Core Depth:** | N/A ft | **Date Completed:** | 9/18/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Deidrich D-25 | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 80% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| | | Medium Dense to Dense, Wet, Greenish Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4), Munsell=GLEY1 5/5GY | 43.5 | SS-12 | 9 | 10 | 15 | | 25 |
| -42.7 | | | 48.5 | SS-13 | 8 | 17 | 16 | | 33 |
| -47.7 | | @SS-13: with Trace of Shell Fragments | 53.5 | SS-14 | 6 | 5 | 3 | | 8 |
| -52.7 | | @SS-14: Loose | 58.5 | SS-15 | 1 | 2 | 3 | | 5 |
| | 56.0 | **HAWTHORN MARL** | 63.5 | SS-16 | 1 | 2 | 3 | | 5 |
| -57.7 | | Firm, Wet to Moist, Dark Olive Gray, Medium to High Plasticity, Sandy Elastic SILT (MH/A-7) with Phosphate Nodules, Calcaceous, Munsell=5Y 3/2 | 68.5 | SS-17 | 2 | 3 | 4 | | 7 |
| -62.7 | | | 73.5 | SS-18 | 1 | 2 | 4 | | 6 |
| -67.7 | | | 78.5 | SS-19 | 4 | 50/5" | | | 100+ |
| -72.7 | | | | | | | | | |
| | 79.0 | | | | | | | | |
| -77.7 | 80.0 | **COOPER GROUP LIMESTONE** Hard, Moist, Dark Olive Brown, Low Plasticity, Sandy SILT (ML/A-4) with Trace of Gravel, Calcaceous, Munsell=2.5Y 3/3 | | | | | | | |
| | | Boring Terminated at 80.0 feet | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-7 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 57+99 | **Offset:** | 45.9'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.7 ft | **Latitude:** | 32.407501 | **Longitude:** | -80.461704 | **Date Started:** | 7/19/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/20/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | ▽Marsh | | 0.0 | | | | | | |
| | | **HOLOCENE** | | | | | | | | |
| | 2.0 | Very Soft, Wet, Dark Olive Gray, Low Plasticity, Weakly Reactive, SILT (ML) with Trace of Organics (Wood), Munsell=5Y 3/2 | | 2.0 | SS-1 | WOR/24" | | | | WOR |
| | | | | 4.0 | SS-2 | 2 | 4 | 5 | 4 | 9 |
| -2.3 | | Loose to Very Loose, Wet, Gray, Non-Plastic, Strongly Reactive, Silty Fine to Medium SAND (SM/A-2-4) with Trace of Shell Fragments, Munsell=5Y 5/1 | | 6.0 | SS-3 | 2 | 3 | 1 | 1 | 4 |
| | | | | 8.0 | SS-4 | WOR/12" | WOH/12" | | | WOH |
| | | @SS-3: LL=NP, PL=NP, PI=NP, NMC=24.2%, %#200=12.8 | | | SS-5 | WOH | 1/12" | | 2 | 1 |
| -7.3 | | @SS-4: No Recovery | | | | | | | | |
| | | @SS-5: Very Dark Gray, Weakly Reactive, Munsell=5Y 3/1, LL=NP, PL=NP, PI=NP, NMC=33.1%, %#200=18.2 | | 13.5 | SS-6 | WOH | 1 | 1 | | 2 |
| -12.3 | | @SS-6: Weakly Reactive, Fine to Coarse Sand, LL=NP, PL=NP, PI=NP, NMC=31.3%, %#200=18.9 | | | | | | | | |
| | 18.0 | | | 18.5 | SS-7 | 2 | 2 | 2 | | 4 |
| -17.3 | | Very Loose, Wet, Very Dark Gray, Non-Plastic, Weakly Reactive, Poorly Graded Fine to Coarse SAND (SP-SM/A-2-4) with Silt, Munsell=5Y 3/1 | | | | | | | | |
| | | @SS-7: LL=NP, PL=NP, PI=NP, NMC=24.2%, %#200=10.8 | | 23.5 | SS-8 | 7 | 8 | 9 | | 17 |
| -22.3 | | @SS-8: Medium Dense, Strongly Reactive | | | | | | | | |
| | | @SS-9: Very Loose, Dark Greenish Gray, Weakly Reactive, Munsell=GLEY1 4/10GY | | 28.5 | SS-9 | 3 | 2 | 2 | | 4 |
| -27.3 | | | | | | | | | | |
| | 32.0 | | | 33.5 | SS-10 | 2 | 1 | 1 | | 2 |
| | | Very Soft, Wet, Dark Greenish Gray, Low to Medium Plasticity, Weakly Reactive, Fine Sandy CLAY (CL), Munsell=GLEY1 4/5G | | | | | | | | |
| -32.3 | | | | | | | | | | |
| | 37.0 | | | 38.5 | SS-11 | 1/12" | | | 1 | 1 |
| | | Very Loose to Loose, Wet, Dark Greenish Gray, Non-Plastic, Weakly Reactive, Silty Fine to Medium SAND (SM/A-2-4), Munsell=GLEY1 4/10GY | | | | | | | | |
| -37.3 | | | | | | | | | | |
| | | @SS-12: LL=NP, PL=NP, PI=NP, NMC=38.0, %#200=17.9 | | 43.5 | SS-12 | 2 | 2 | 2 | | 4 |
| -42.3 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-7 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 57+99 | **Offset:** | 45.9'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.7 ft | **Latitude:** | 32.407501 | **Longitude:** | -80.461704 | **Date Started:** | 7/19/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/20/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Loose, Wet, Dark Greenish Gray, Non-Plastic, Weakly Reactive, Silty Fine to Medium SAND (SM/A-2-4), Munsell=GLEY1 4/10GY | 48.5 | | | | | | | |
| -47.3 | | @SS-13: Dark Gray, Munsell=GLEY1 4/N | | SS-13 | 1 | 2 | 3 | | 5 | Hard Lense from 52.5 to 53.0 feet |
| | 53.5 | **HAWTHORN MARL** | 53.5 | SS-14 | 4 | 5 | 5 | | 10 | |
| -52.3 | | Stiff, Wet, Olive Gray, Non-Plastic to Low Plasticity, Weakly Reactive, Sandy SILT (ML/A-4) with Phosphate Nodules, Munsell=5Y 4/2 | | | | | | | | |
| | | @SS-15: Soft to Firm | 58.5 | SS-15 | 2 | 2 | 2 | | 4 | Hard Lense from 58.0 to 58.5 feet |
| -57.3 | | | | | | | | | | |
| | | | 63.5 | SS-16 | 3 | 4 | 4 | | 8 | |
| -62.3 | | | | | | | | | | |
| | 68.5 | Loose, Wet, Olive Gray, Non-Plastic to Low Plasticity, Non-Reactive, Silty Fine SAND (SM/A-2-4), Munsell=5Y 4/2 | 68.5 | SS-17 | 3 | 4 | 4 | | 8 | |
| -67.3 | | | | | | | | | | |
| | 74.0 | **COOPER GROUP LIMESTONE** | 73.5 | SS-18 | 750/5.5" | | | | 100+ | |
| -72.3 | | Very Dense, Wet, Dark Greenish Gray, Non-Plastic to Low Plasticity, Non-Reactive, Silty Fine SAND (SM/A-2-4) with Phosphate Nodules, Calcaceous, Munsell=GLEY1 4/5GY | 78.5 | SS-19 | 30 | 6 | 6 | | 12 | |
| -77.3 | | @SS-19: Medium Dense to Loose, Light Greenish Gray, Strongly Reactive, Munsell=GLEY1 7/5GY | | | | | | | | |
| | | @SS-20: Greenish Gray, Fine to Medium Sand, Munsell=GLEY1 6/10Y | 83.5 | SS-20 | 3 | 2 | 4 | | 6 | |
| -82.3 | | | | | | | | | | |
| | | @SS-21: No Recovery | 88.5 | SS-21 | 2 | 3 | 3 | | 6 | |
| -87.3 | | | | | | | | | | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-7 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 57+99 | **Offset:** | 45.9'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.7 ft | **Latitude:** | 32.407501 | **Longitude:** | -80.461704 | **Date Started:** | 7/19/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/20/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 93.5 | | | | | | | |
| | | @SS-22: No Recovery | | | SS-22 | 3 | 5 | 7 | | 12 | |
| -92.3 | | | | | | | | | | | |
| | | | | 98.5 | | | | | | | |
| | | Medium Dense to Loose, Wet, Greenish Gray, Non-Plastic to Low Plasticity, Non-Reactive, Silty Fine to Medium SAND (SM/A-2-4) with Phosphate Nodules, Calcaceous, Munsell=GLEY1 6/10Y | | | SS-23 | 4 | 6 | 7 | | 13 | |
| -97.3 | | | | | | | | | | | |
| | | | | 103.5 | | | | | | | |
| | | @SS-24: Light Greenish Gray, Munsell=GLEY1 7/10Y | | | SS-24 | 4 | 5 | 6 | | 11 | |
| -102.3 | | | | | | | | | | | |
| | | | | 108.5 | | | | | | | |
| | | | | | SS-25 | 3 | 3 | 3 | | 6 | |
| -107.3 | | | | | | | | | | | |
| | | | | 113.5 | | | | | | | |
| | | | | | SS-26 | 4 | 5 | 6 | | 11 | |
| -112.3 | | | | | | | | | | | |
| | | | | 118.5 | | | | | | | |
| | | | | | SS-27 | 3 | 3 | 6 | | 9 | |
| -117.3 | | | | | | | | | | | |
| | | | | 123.5 | | | | | | | |
| | | @SS-28: Fine Sand | | | SS-28 | 3 | 3 | 4 | | 7 | |
| -122.3 | | | | | | | | | | | |
| | | | | 128.5 | | | | | | | |
| | | | | | SS-29 | 4 | 7 | 6 | | 13 | |
| -127.3 | | | | | | | | | | | |
| | | | | 133.5 | | | | | | | |
| | | | | | SS-30 | 4 | 5 | 7 | | 12 | |
| -132.3 | | | | | | | | | | | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-7 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 57+99 | **Offset:** | 45.9'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.7 ft | **Latitude:** | 32.407501 | **Longitude:** | -80.461704 | **Date Started:** | 7/19/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/20/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Medium Dense to Loose, Wet, Light Greenish Gray, Non-Plastic to Low Plasticity, Non-Reactive, Silty Fine SAND (SM/A-2-4) with Phosphate Nodules, Calcaceous, Munsell=GLEY1 7/10Y | | 138.5 | SS-31 | 4 | 5 | 6 | | 11 | ● |
| -137.3 | | | | | | | | | | | |
| | | @SS-32: Greenish Gray, Munsell=GLEY 1 6/5GY | | 143.5 | SS-32 | 4 | 4 | 5 | | 9 | ● *Rod Slipped and Blow Counts* |
| -142.3 | | | | | | | | | | | |
| | | | | 148.5 | SS-33 | | | 6 | | | *Not Recorded for Top Foot* |
| -147.3 | 150.0 | Boring Terminated at 150.0 feet | | | | | | | | | |
| -152.3 | | | | | | | | | | | |
| -157.3 | | | | | | | | | | | |
| -162.3 | | | | | | | | | | | |
| -167.3 | | | | | | | | | | | |
| -172.3 | | | | | | | | | | | |
| -177.3 | | | | | | | | | | | |

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-8 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 65+00 | **Offset:** | 0.1'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 3.0 ft | **Latitude:** | 32.406749 | **Longitude:** | -80.459611 | **Date Started:** | 7/25/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/26/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | ▽Marsh | | | | | | | | |
| | | **HOLOCENE** | | 0.0 | SS-1 | WOH/24" | | | | WOH |
| | | Very Loose to Loose, Wet, Dark Gray, Non-Plastic, Weakly Reactive, Poorly Graded Fine SAND (SP-SM/A-2-4) with Silt and Trace of Shell Fragments, Munsell=2.5Y 4/1 | | 2.0 | | | | | | |
| | | | | 4.0 | SS-2 | 1 | 1 | 2 | 2 | 3 |
| -2.0 | | @SS-2: Gray, Strongly Reactive, Munsell=5Y 5/1 | | 6.0 | SS-3 | 2 | 2 | 3 | 3 | 5 |
| | | @SS-3: LL=NP, PL=NP, PI=NP, NMC=24.0%, %#200=11.9 | | 8.0 | SS-4 | 2 | 3 | 1 | 1 | 4 |
| -7.0 | | | | 10.0 | SS-5 | 2 | 1 | 1 | 2 | 2 |
| | 12.0 | | | | SS-6 | 2 | 1 | 1 | | 2 |
| | | Very Soft, Wet, Very Dark Gray, Medium Plasticity, Weakly Reactive, Sandy Lean CLAY (CL/A-6(8)), Munsell=5Y 3/1 | | 13.5 | SS-7 | WOH/18" | | | | WOH |
| -12.0 | | | | | | | | | | |
| | | | | 18.5 | SS-8 | WOH/18" | | | | WOH |
| | | @SS-8: LL=34, PL=20, PI=14, NMC=73.8%, %#200=67.5 | | | | | | | | |
| -17.0 | 21.0 | | | | | | | | | |
| | | Very Loose, Wet, Very Dark Gray, Medium Plasticity, Weakly Reactive, Clayey Fine to Medium SAND (SC/A-2-6(0)), Munsell=5Y 3/1 | | 23.5 | SS-9 | WOH/18" | | | | WOH |
| -22.0 | | @SS-9: LL=30, PL=19, PI=11, NMC=54.5%, %#200=34.9 | | | | | | | | |
| | 27.0 | | | 28.5 | SS-10 | 1 | 1 | 1 | | 2 |
| | | Very Loose, Wet, Dark Gray, Non-Plastic, Weakly Reactive, Silty Fine to Medium SAND (SM/A-2-4) with Trace of Shell Fragments, Munsell=5Y 4/1 | | | | | | | | |
| -27.0 | | @SS-10: LL=NP, PL=NP, PI=NP, NMC=38.8%, %#200=22.0 | | 33.5 | SS-11 | 1 | 2 | 2 | | 4 |
| | | | | | | | | | | |
| -32.0 | 37.0 | | | 38.5 | SS-12 | 1 | 1 | 1 | | 2 |
| | | Very Soft, Wet, Dark Greenish Gray, Medium Plasticity, Weakly Reactive, Fine Sandy CLAY (CL), Munsell=GLEY1 4/10GY | | | | | | | | |
| -37.0 | | | | | | | | | | |
| | 42.0 | | | 43.5 | SS-13 | 5 | 3 | 5 | | 8 |
| | | Loose, Wet, Gray, Non-Plastic, Weakly Reactive, Poorly Graded Fine SAND (SP-SM/A-3) with Silt, Munsell=GLEY1 5/N | | | | | | | | |
| -42.0 | | @SS-13: LL=NP, PL=NP, PI=NP, NMC=27.3%, %#200=6.5 | | | | | | | | |
| | | | | 48.5 | SS-14 | 3 | 3 | 4 | | 7 |
| | | @SS-14: LL=NP, PL=NP, PI=NP, NMC=37.1%, %#200=8.2 | | | | | | | | |
| -47.0 | | | | | | | | | | |
| | 52.5 | | | | | | | | | |

SPT N VALUE ● PL MC LL ▲ FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90

*Hard Lense from 51.5 to 52.5 feet*

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-8 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 65+00 | **Offset:** | 0.1'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 3.0 ft | **Latitude:** | 32.406749 | **Longitude:** | -80.459611 | **Date Started:** | 7/25/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/26/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | **HAWTHORN MARL** | | 53.5 | | | | | | | |
| -52.0 | | Loose, Wet, Olive Gray, Medium Plasticity, Non-Reactive, Silty Fine to Medium SAND (SM/A-2-6) with Phosphate Nodules, Munsell=5Y 4/2 | | | SS-15 | 3 | 3 | 2 | | 5 | |
| | 58.5 | | | 58.5 | | | | | | | |
| -57.0 | | Firm, Wet, Olive Gray, Low to Medium Plasticity, Non-Reactive, Fine Sandy SILT (ML/A-4), Munsell=5Y 4/2 | | | SS-16 | 3 | 3 | 3 | | 6 | |
| | | | | 63.5 | | | | | | | |
| -62.0 | | | | | SS-17 | 3 | 2 | 4 | | 6 | |
| | | | | 68.5 | | | | | | | |
| -67.0 | | | | | SS-18 | 2 | 2 | 3 | | 5 | |
| | | | | 73.5 | | | | | | | |
| | | @SS-19: Very Stiff | | | SS-19 | 3 | 4 | 14 | | 18 | *Hard Dense from 75.0 to 75.5 feet* |
| -72.0 | 75.0 | **COOPER GROUP LIMESTONE** | | | | | | | | | |
| | | Medium Dense to Loose, Wet, Light Greenish Gray, Low Plasticity, Strongly Reactive, Silty Fine to Medium SAND (SM/A-2-4), Calcaceous, Munsell=GLEY1 7/5GY | | 78.5 | SS-20 | 21 | 8 | 5 | | 13 | |
| -77.0 | | | | | | | | | | | |
| | | | | 83.5 | | | | | | | |
| -82.0 | | | | | SS-21 | 3 | 2 | 3 | | 5 | |
| | | | | 88.5 | | | | | | | |
| | | @SS-22: No Recovery | | | SS-22 | 2 | 3 | 5 | | 8 | |
| -87.0 | | | | | | | | | | | |
| | | | | 93.5 | | | | | | | |
| | | @SS-23: No Recovery | | | SS-23 | 2 | 4 | 5 | | 9 | |
| -92.0 | | | | | | | | | | | |
| | | | | 98.5 | | | | | | | |
| | | | | | SS-24 | 3 | 3 | 5 | | 8 | |
| -97.0 | | | | | | | | | | | |
| | | @SS-25: Greenish Gray, Munsell=GLEY1 6/5GY | | 103.5 | | | | | | | |
| | | | | | SS-25 | 4 | 4 | 5 | | 9 | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-8 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 65+00 | **Offset:** | 0.1'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 3.0 ft | **Latitude:** | 32.406749 | **Longitude:** | -80.459611 | **Date Started:** | 7/25/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/26/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Loose to Medium Dense, Wet, Greenish Gray, Low Plasticity, Strongly Reactive, Silty Fine to Medium SAND (SM/A-2-4), Calcaceous, Munsell=GLEY1 6/5GY | | 108.5 | SS-26 | 3 | 3 | 3 | | 6 | |
| -107.0 | | | | 113.5 | SS-27 | 3 | 4 | 8 | | 12 | |
| -112.0 | | | | 118.5 | SS-28 | 3 | 3 | 6 | | 9 | |
| -117.0 | | | | 123.5 | SS-29 | 3 | 3 | 4 | | 7 | |
| -122.0 | | | | 128.5 | SS-30 | 7 | 8 | 11 | | 19 | |
| -127.0 | | | | 133.5 | SS-31 | 4 | 5 | 6 | | 11 | |
| -132.0 | | | | 138.5 | SS-32 | | | 10 | | | *Rod Slipped and Blow Counts* |
| -137.0 | | | | 143.5 | SS-33 | 3 | 4 | 6 | | 10 | *Not Recorded for Top Foot* |
| -142.0 | | | | 148.5 | SS-34 | 3 | 4 | 7 | | 11 | |
| -147.0 | 150.0 | Boring Terminated at 150.0 feet | | | | | | | | | |
| -152.0 | | | | | | | | | | | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-9 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 67+04 | **Offset:** | 9.3'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.6 ft | **Latitude:** | 32.406583 | **Longitude:** | -80.458978 | **Date Started:** | 7/27/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/28/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | Marsh | 0.0 | SS-1 | WOH/24" | | | | WOH |
| | 2.0 | **HOLOCENE** Very Soft, Wet, Dark Gray, Medium Plasticity, Weakly Reactive, SILT (ML/A-4) with Fine Sand and Trace of Organics (Wood), Munsell=10YR 4/1 | 2.0 | SS-2 | WOH | 2 | 3 | 2 | 5 |
| -2.4 | 5.0 | Loose to Very Loose, Wet, Dark Gray, Non-Plastic, Strongly Reactive, Poorly Graded Fine to Coarse SAND (SP-SM/A-3) with Silt, Munsell=5Y 4/1 | 4.0 | SS-3 | 4 | 3 | 3 | 3 | 6 |
| | | | 6.0 | SS-4 | WOH/24" | | | | WOH |
| | | | 8.0 | SS-5 | 1 | 1 | 1 | 2 | 2 |
| -7.4 | 10.0 | @SS-2: LL-NP, PL=NP, PI=NP, NMC=22.6%, %#200=7.7 | | | | | | | |
| | | @SS-3: LL=NP, PL=NP, PI=NP, NMC=21.9%, %#200=7.2 | 13.5 | SS-6 | WOH/18" | | | | WOH |
| -12.4 | 15.0 | @SS-4: No Recovery | | | | | | | |
| | 17.0 | @SS-5: Weakly Reactive, Fine Sand, LL=NP, PL=NP, PI=NP, NMC=25.6%, %#200=10.3 | 18.5 | SS-7 | WOH/18" | | | | WOH |
| -17.4 | | @SS-6: Very Dark Gray, Munsell=5Y 3/1 | | | | | | | |
| | | Very Soft, Wet, Very Dark Gray, High Plasticity, Weakly Reactive, Fat CLAY (CH/A-7-5(24)) with Fine Sand, Munsell=5Y 3/1 | 23.5 | SS-8 | WOH/18" | | | | WOH |
| -22.4 | | | | | | | | | |
| | | | 28.5 | SS-9 | WOH/18" | | | | WOH |
| -27.4 | | @SS-9: LL=58, PL=30, PI=28, NMC=88.5%, %#200=79.1 | | | | | | | |
| | | | 33.5 | SS-10 | WOH/12" | | 1 | | 1 |
| -32.4 | | | | | | | | | |
| | | | 38.5 | SS-11 | 1 | 1 | 1 | | 2 |
| -37.4 | | @SS-11: Dark Gray, Munsell=5Y 4/1 | | | | | | | |
| | 42.0 | Loose to Very Loose, Wet, Gray, Non-Plastic, Weakly Reactive, Poorly Graded Fine SAND (SP-SM/A-3) with Silt, Munsell=GLEY1 5/N | 43.5 | SS-12 | 2 | 3 | 4 | | 7 |
| -42.4 | | @SS-12: LL=NP, PL=NP, PI=NP, NMC=25.6%, %#200=7.5 | | | | | | | |
| | | | 48.5 | SS-13 | 2 | 2 | 2 | | 4 |
| -47.4 | 51.0 | | | | | | | | |

SPT N VALUE ● PL × MC ○ LL × ▲ FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-9 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 67+04 | **Offset:** | 9.3'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.6 ft | **Latitude:** | 32.406583 | **Longitude:** | -80.458978 | **Date Started:** | 7/27/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/28/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|---|---|
| | | **HAWTHORN MARL** | | | | | | | | |
| | | Soft to Firm, Wet, Olive, Low to Medium Plasticity, Non-Reactive, Fine to Medium Sandy SILT (ML/A-4), Munsell=5Y 5/3 | 53.5 | SS-14 | 2 | 2 | 2 | | 4 | Hard Lense from 51.5 to 52.0 feet |
| -52.4 | | | | | | | | | | |
| | | @SS-15: Olive Gray, Munsell=5Y 4/2 | 58.5 | SS-15 | 1 | 2 | 3 | | 5 | |
| -57.4 | | | | | | | | | | |
| | | | 63.5 | SS-16 | 2 | 3 | 4 | | 7 | |
| -62.4 | | | | | | | | | | |
| | | | 68.5 | SS-17 | 2 | 2 | 3 | | 5 | |
| -67.4 | | | | | | | | | | |
| | | | 73.5 | SS-18 | 5 | 4 | 9 | | 13 | Hard Lense from 75.0 to 78.0 feet |
| | | @SS-18: Stiff, Weakly Reactive | | | | | | | | |
| -72.4 | 75.0 | **COOPER GROUP LIMESTONE** | | | | | | | | |
| | | Very Dense, Wet, Light Greenish Gray, Low Plasticity, Strongly Reactive, Silty Fine to Medium SAND (SM/A-2-4), Calcaceous, Munsell=GLEY1 7/5GY | 78.5 | SS-19 | 750/5.5" | | | | 100+ | |
| -77.4 | | | | | | | | | | |
| | | @SS-20: Loose to Medium Dense, Greenish Gray, Munsell=GLEY1 6/10Y | 83.5 | SS-20 | 2 | 2 | 3 | | 5 | |
| -82.4 | | | | | | | | | | |
| | | @SS-21: Light Greenish Gray, Munsell=GLEY1 7/5GY | 88.5 | SS-21 | 2 | 3 | 5 | | 8 | |
| -87.4 | | | | | | | | | | |
| | | @SS-22: No Recovery | 93.5 | SS-22 | 2 | 3 | 5 | | 8 | |
| -92.4 | | | | | | | | | | |
| | | | 98.5 | SS-23 | 3 | 3 | 5 | | 8 | |
| -97.4 | | | | | | | | | | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-9 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 67+04 | **Offset:** | 9.3'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.6 ft | **Latitude:** | 32.406583 | **Longitude:** | -80.458978 | **Date Started:** | 7/27/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/28/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| -102.4 | | Medium Dense to Loose, Wet, Light Greenish Gray, Low Plasticity, Strongly Reactive, Silty Fine to Medium SAND (SM/A-2-4), Calcaceous, Munsell=GLEY1 7/5GY | | 103.5 | SS-24 | 4 | 5 | 9 | | 14 |
| -107.4 | | | | 108.5 | SS-25 | 3 | 3 | 5 | | 8 |
| -112.4 | | | | 113.5 | SS-26 | 3 | 3 | 4 | | 7 |
| -117.4 | | | | 118.5 | SS-27 | 4 | 3 | 4 | | 7 |
| -122.4 | | | | 123.5 | SS-28 | 3 | 2 | 4 | | 6 |
| -127.4 | | | | 128.5 | SS-29 | 2 | 2 | 4 | | 6 |
| -132.4 | 132.0 | Stiff, Wet, Greenish Gray, Low Plasticity, Strongly Reactive, Fine Sandy SILT (ML/A-4), Calcaceous, Munsell=GLEY1 6/5GY | | 133.5 | SS-30 | 4 | 5 | 8 | | 13 |
| -137.4 | | | | 138.5 | SS-31 | 5 | 5 | 6 | | 11 |
| -142.4 | 142.0 | Medium Dense to Loose, Wet, Non-Plastic to Low Plasticity, Greenish Gray, Strongly Reactive, Silty Fine SAND (SM/A-2-4), Calcaceous, Munsell=GLEY1 6/5GY | | 143.5 | SS-32 | 3 | 4 | 7 | | 11 |
| -147.4 | 150.0 | Boring Terminated at 150.0 feet | | 148.5 | SS-33 | 3 | 4 | 6 | | 10 |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-10 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 78+24 | **Offset:** | 21.4'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.405352 | **Longitude:** | -80.455652 | **Date Started:** | 6/23/2016 |
| **Total Depth:** | 193 ft | **Soil Depth:** | 191.5 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/27/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | ▽River | | | | | | | |
| | 1.5 | WATER | 1.5 | | | | | | |
| | | **HOLOCENE** | | | | | | | |
| -5.0 | | Very Loose to Loose, Wet, Black, Low Plasticity, Clayey Fine SAND (SC/A-4(1)) with Trace of Shell Fragments/Organics, Munsell=5Y 2.5/1 | 3.5 | SS-1 | WOR/24" | | | | WOR |
| | 7.5 | @SS-2: LL=26, PL=17, PI=9, NMC=50.0%, %#200=41.1 | 5.5 | SS-2 | WOH/24" | | | | WOR |
| | | @SS-3: Dark Greenish Gray, Munsell=GLEY1 4/10Y | 7.5 | SS-3 | 2 | 4 | 2 | 2 | 6 |
| -10.0 | | | 9.5 | SS-4 | 2 | 1 | 1 | 1 | 2 |
| | | | | SS-5 | 1 | 1 | 1 | 1 | 2 |
| | 14.0 | Very Loose, Wet, Dark Greenish Gray, Non-Plastic, Fine SAND (SP-SM/A-3) with Silt and Trace of Shell Fragments, Munsell=GLEY1 4/10Y | 15.0 | SS-6 | 1 | 1 | 1 | | 2 |
| -15.0 | | @SS-4: LL=NP, PL=NP, PI=NP, NMC=24.1%, %#200=7.9 | | | | | | | |
| -20.0 | | Very Soft, Wet, Greenish Gray, Low Plasticity, Sandy SILT (ML/A-4(2)) with Trace of Organics, Munsell=10GY 5/1 | 20.0 | SS-7 | WOH/18" | | | | WOH |
| -25.0 | | @SS-8: LL=33, PL=26, PI=7, NMC=58.3%, %#200=57.2 | 25.0 | SS-8 | WOH/18" | | | | WOH |
| -30.0 | | @SS-9: Dark Greenish Gray, Munsell=5GY 4/1 | 30.5 | SS-9 | WOH/18" | | | | WOH |
| -35.0 | | | 35.5 | SS-10 | WOH/18" | | | | WOH |
| -40.0 | | | 40.5 | SS-11 | WOH/12" | | 1 | | 1 |
| -45.0 | 45.0 | Loose to Medium Dense, Wet, Greenish Gray, Non-Plastic, Fine to Coarse SAND (SP-SM/A-3) with Silt and Trace of Shell Fragments, Munsell=GLEY1 5/10Y | 46.0 | SS-12 | 2 | 3 | 3 | | 6 |
| -50.0 | | @SS-12: LL=NP, PL=NP, PI=NP, NMC=21.9%, %#200=6.0 | 51.0 | SS-13 | 4 | 7 | 10 | | 17 |
| | 52.5 | | | | | | | | |

SPT N VALUE

PL MC LL

▲ FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-10 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 78+24 | **Offset:** | 21.4'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.405352 | **Longitude:** | -80.455652 | **Date Started:** | 6/23/2016 |
| **Total Depth:** | 193 ft | **Soil Depth:** | 191.5 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/27/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| -55.0 | | **HAWTHORN MARL**<br>Very Loose to Loose, Wet, Dark Gray, Medium Plasticity, Strongly Reactive, Silty Fine to Medium SAND (SM/A-2-6(0)), Munsell=5Y 4/1<br>@SS-14: LL=39, PL=27, PI=12, NMC=58.1%, %#200=31.0<br>@SS-15: Weakly Reactive | | 56.5 | SS-14 | 1 | 1 | 2 | | 3 |
| -60.0 | | | | 61.5 | SS-15 | 3 | 2 | 4 | | 6 |
| -65.0 | | | | 66.5 | SS-16 | 2 | 2 | 3 | | 5 |
| -70.0 | | | | 71.5 | SS-17 | 3 | 4 | 4 | | 8 |
| -75.0 | 74.5 | **COOPER GROUP LIMESTONE**<br>Loose to Medium Dense, Wet, Light Greenish Gray, Medium Plasticity, Strongly Reactive, Silty Fine to Medium SAND (SM/A-3), Calcaceous, Munsell=GLEY1 7/10Y | | 76.5 | SS-18 | 1 | 1 | 6 | | 7 |
| -80.0 | | | | 81.5 | SS-19 | 3 | 6 | 5 | | 11 |
| -85.0 | | | | 86.5 | SS-20 | 34 | 7 | 6 | | 13 |
| -90.0 | | | | 91.5 | SS-21 | 2 | 4 | 12 | | 16 |
| -95.0 | | | | 96.5 | SS-22 | 2 | 3 | 4 | | 7 |
| -100.0 | | | | 101.5 | SS-23 | 5 | 5 | 6 | | 11 |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-10 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 78+24 | **Offset:** | 21.4'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.405352 | **Longitude:** | -80.455652 | **Date Started:** | 6/23/2016 |
| **Total Depth:** | 193 ft | **Soil Depth:** | 191.5 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/27/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Loose to Very Loose, Wet, Light Greenish Gray, Medium Plasticity, Strongly Reactive, Silty Fine to Medium SAND (SM/A-3), Calcaceous, Munsell=GLEY1 7/10Y | | 106.5 | SS-24 | 4 | 4 | 3 | | 7 |
| -110.0 | | | | 111.5 | SS-25 | 3 | 3 | 4 | | 7 |
| -115.0 | | | | 116.5 | SS-26 | 4 | 4 | 5 | | 9 |
| -120.0 | | | | 121.5 | SS-27 | 3 | 3 | 3 | | 6 |
| -125.0 | | @SS-28: Olive Gray, Munsell=5Y 4/2 | | 126.5 | SS-28 | 3 | 2 | 1 | | 3 |
| -130.0 | | @SS-29: Greenish Gray, Munsell=GLEY1 6/10Y | | 130.0 | SS-29 | 3 | 3 | 3 | | 6 |
| -135.0 | | | | 135.0 | SS-30 | 2 | 2 | 3 | | 5 |
| -140.0 | | | | 142.0 | SS-31 | 3 | 4 | 4 | | 8 |
| -145.0 | | @SS-32: Medium Dense to Loose | | 147.0 | SS-32 | 4 | 7 | 6 | | 13 |
| -150.0 | | | | 152.0 | SS-33 | 3 | 4 | 6 | | 10 |
| -155.0 | | | | 157.5 | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-10 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 78+24 | **Offset:** | 21.4'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.405352 | **Longitude:** | -80.455652 | **Date Started:** | 6/23/2016 |
| **Total Depth:** | 193 ft | **Soil Depth:** | 191.5 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/27/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| -160.0 | | Loose to Medium Dense, Wet, Greenish Gray, Medium Plasticity, Strongly Reactive, Silty Fine to Medium SAND (SM/A-3), Calcaceous, Munsell=GLEY1 6/10Y | | 162.0 | SS-34 | 3 | 3 | 4 | | 7 |
| | | | | | SS-35 | 3 | 3 | 4 | | 7 |
| -165.0 | | | | 167.0 | SS-36 | 4 | 7 | 9 | | 16 |
| -170.0 | | | | 172.0 | SS-37 | 4 | 4 | 5 | | 9 |
| -175.0 | | | | 177.0 | SS-38 | 4 | 5 | 5 | | 10 |
| -180.0 | | | | 182.0 | SS-39 | 5 | 9 | 9 | | 18 |
| -185.0 | | @SS-40: Dense | | 187.0 | SS-40 | 12 | 8 | 29 | | 37 |
| -190.0 | | | | 191.5 | | | | | | |
| | 193.0 | @SS-41: Loose | | | SS-41 | 4 | 5 | 5 | | 10 |
| -195.0 | | Boring Terminated at 193.0 feet | | | | | | | | |
| -200.0 | | | | | | | | | | |
| -205.0 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-11 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 82+65 | **Offset:** | 4.4'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.404954 | **Longitude:** | -80.454298 | **Date Started:** | 6/29/2016 |
| **Total Depth:** | 192 ft | **Soil Depth:** | 170 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/30/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | ▽River | | | | | | | | |
| | | WATER | | | | | | | | |
| -5.0 | | | | | | | | | | |
| -10.0 | | | | | | | | | | |
| -15.0 | | | | | | | | | | |
| -20.0 | | | | | | | | | | |
| | 22.0 | **HOLOCENE** | | 22.0 | | | | | | |
| -25.0 | 26.0 | Very Soft, Wet, Dark Greenish Gray, Low Plasticity, Sandy SILT (ML/A-4) with Trace of Shell Fragments/Organics, Munsell=GLEY1 4/10Y | | 24.0 | SS-1 | WOR/24" | | | | WOH |
| | 28.0 | | | 26.0 | SS-2 | 4 | 1/18" | | | 1 |
| | 30.0 | | | 28.0 | SS-3 | WOH/24" | | | | WOH |
| -30.0 | | Very Loose, Wet, Dark Greenish Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4) with Trace of Shell Fragments, Munsell=GLEY 1 4/10Y, LL=22, PL=NP, PI=NP, NMC=33.7%, %#200=18.1 | | 30.0 | SS-4 | WOH/24" | | | | WOH |
| | 35.0 | | | | SS-5 | WOH/24" | | | | WOH |
| -35.0 | | | | 36.5 | SS-6 | WOH/18" | | | | WOH |
| -40.0 | | Very Soft, Wet, Dark Greenish Gray, Low Plasticity, Sandy CLAY (CL/A-4(2)) with Trace of Organics, Munsell=GLEY1 4/5GY, LL=26, PL=17, PI=9, NMC=57.6%, %#200=52.1 | | 42.0 | SS-7 | WOH/18" | | | | WOH |
| -45.0 | 46.0 | Very Loose, Wet, Dark Greenish Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4) with Trace of Shell Fragments, Munell=GLEY1 4/5GY, LL=NP, PL=NP, PI=NP, NMC=30.5%, %#200=15.3 | | 47.5 | SS-8 | 1 | 1 | 1 | | 2 |
| -50.0 | | Very Soft, Wet, Dark Greenish Gray, High Plasticity, Elastic SILT (MH/A-7-5(25)), Munsell=GLEY1 4/5GY | | 53.5 | SS-9 | 4 | 3 | 4 | | 7 |
| -55.0 | 57.0 | @SS-6: LL=58, PL=35, PI=23, NMC=93.7%, %#200=87.9 | | 58.0 | SS-10 | 2 | 3 | 3 | | 6 |
| -60.0 | | Very Loose to Loose, Wet, Gray, Low Plasticity, Silty Fine to Medium SAND (SM/A-2-4) with Trace of Shell Fragments, Munsell=GLEY1 5/N | | 63.5 | SS-11 | 2 | 2 | 3 | | 5 |
| -65.0 | | **HAWTHORN MARL** | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Hard Lense from 55.0 to 55.5 feet*

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-11 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 82+65 | **Offset:** | 4.4'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.404954 | **Longitude:** | -80.454298 | **Date Started:** | 6/29/2016 |
| **Total Depth:** | 192 ft | **Soil Depth:** | 170 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/30/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| -70.0 | | **HAWTHORNE MARL**<br>Firm, Wet, Olive Gray, Low Plasticity, Strongly Reactive, Sandy SILT (ML/A-4), Munsell=5Y 4/2 | | 68.5 | SS-12 | 2 | 3 | 4 | | 7 |
| -75.0 | | | | 73.5 | SS-13 | 2 | 3 | 4 | | 7 |
| | 78.5 | | | 78.5 | SS-14 | 3 | 10 | 13 | | 23 |
| -80.0 | | **COOPER GROUP LIMESTONE**<br>Loose to Medium Dense, Wet, Very Dark Gray, Non-Plastic, Weakly to Strongly Reactive, Silty Fine SAND (SM/A-4(0)) with Phosphate Nodules, Calcaceous, Munsell=5Y 3/1 | | 83.0 | SS-15 | 2 | 2 | 4 | | 6 |
| -85.0 | | @SS-15: Light Brownish Gray, Munsell=2.5Y 6/2, LL=31, PL=NP, PI=NP, NMC=45.3%, %#200=46.0 | | 87.5 | SS-16 | 2 | 2 | 3 | | 5 |
| -90.0 | | @SS-16: No Recovery | | 92.5 | SS-17 | 3 | 2 | 3 | | 5 |
| | | @SS-17: Greenish Gray, Munsell=GLEY1 6/10Y | | 97.0 | SS-18 | 7 | 3 | 3 | | 6 |
| -95.0 | | | | | | | | | | |
| -100.0 | | | | 100.0 | SS-19 | 3 | 2 | 3 | | 5 |
| -105.0 | | | | 104.5 | SS-20 | 3 | 7 | 20 | | 27 |
| | | @SS-21: No Recovery | | 107.0 | SS-21 | 1/18" | | | | 1 |
| -110.0 | | | | 112.0 | SS-22 | 2 | 3 | 5 | | 8 |
| -115.0 | | @SS-22: Light Greenish Gray, Munsell=GLEY1 7/5GY | | | | | | | | |
| -120.0 | | | | 120.5 | SS-23 | 3 | 4 | 5 | | 9 |
| -125.0 | | | | 126.0 | SS-24 | 4 | 5 | 6 | | 11 |
| -130.0 | | | | 132.0 | SS-25 | 3 | 3 | 5 | | 8 |

SPT N VALUE ●

PL ✕ MC ○ LL ✕

▲ FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-11 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 82+65 | **Offset:** | 4.4'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.404954 | **Longitude:** | -80.454298 | **Date Started:** | 6/29/2016 |
| **Total Depth:** | 192 ft | **Soil Depth:** | 170 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/30/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| -135.0 | | Loose to Medium Dense, Wet, Light Greenish Gray, Non-Plastic, Weakly to Strongly Reactive, Silty Fine SAND (SM/A-4(0)) with Phosphate Nodules, Calcaceous, Munsell=GLEY1 7/5GY | | 137.5 | SS-26 | 4 | 4 | 6 | | 10 |
| -140.0 | | | | 143.5 | SS-27 | 3 | 3 | 5 | | 8 |
| -145.0 | | @SS-27: Greenish Gray, Munsell=GLEY1 5/10Y | | 147.5 | SS-28 | 3 | 4 | 6 | | 10 |
| -150.0 | | | | 154.0 | SS-29 | 4 | 4 | 5 | | 9 |
| -155.0 | | | | 159.0 | SS-30 | 2 | 4 | 6 | | 10 |
| -160.0 | | | | 163.5 | SS-31 | 3 | 5 | 7 | | 12 |
| -165.0 | | | | 168.0 | SS-32 | 3 | 4 | 6 | | 10 |
| -170.0 | | | | 172.5 | SS-33 | 3 | 3 | 5 | | 8 |
| -175.0 | | @SS-34: Light Greenish Gray, Munsell=GLEY1 7/10Y | | 177.0 | SS-34 | 4 | 8 | 11 | | 19 |
| -180.0 | | | | 181.5 | SS-35 | 3 | 4 | 6 | | 10 |
| -185.0 | | | | 186.0 | SS-36 | 1 | 4 | 5 | | 9 |
| -190.0 | | @SS-37: Munsell=GLEY1 7/5GY | | 190.5 | SS-37 | 2 | 4 | 5 | | 9 |
| | 192.0 | Boring Terminated at 192.0 feet | | | | | | | | |
| -195.0 | | | | | | | | | | |
| -200.0 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-12 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 87+88 | **Offset:** | 79.3'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.404595 | **Longitude:** | -80.45264 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 192 ft | **Soil Depth:** | 159 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/11/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | ▽River | | | | | | | | |
| | | WATER | | | | | | | | |
| -5.0 | | | | | | | | | | |
| -10.0 | | | | | | | | | | |
| -15.0 | | | | | | | | | | |
| -20.0 | | | | | | | | | | |
| -25.0 | | | | | | | | | | |
| -30.0 | | | | | | | | | | |
| | 33.0 | Very Soft to Soft, Wet, Dark Gray, Low to Medium Plasticity, Sandy CLAY (CL/A-6), with Trace of Shell Fragments/Organics, Munsell=GLEY 1 4/N | | 33.0 | SS-1 | 3 | 1/18" | | | 1 |
| -35.0 | 36.5 | | | 35.0 | SS-2 | 1 | 2 | 2 | 2 | 4 |
| | 39.0 | Very Loose, Wet, Dark Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4), Munsell=GLEY1 4/N, LL=NP, PL=NP, PI=NP, NMC=32.9%, %#200=23.8 | | 37.0 | SS-3 | 2 | 2 | 1 | 1 | 3 |
| -40.0 | 41.0 | | | 39.0 | SS-4 | 2 | 6 | 3 | 3 | 9 |
| | | Loose, Wet, Dark Gray, Low Plasticity, Clayey Fine SAND (SC/A-2-4), Munsell=GLEY1 4/N | | 41.0 | SS-5 | 4 | 2 | 2 | 1 | 4 |
| -45.0 | 45.5 | | | 45.5 | SS-6 | 1 | 4 | 1 | | 5 |
| | | Very Loose, Wet, Gray, Non-Plastic, Fine SAND (SP/A-1), Munsell=GLEY1 5/N | | | | | | | | |
| -50.0 | 50.5 | Loose, Wet, Dark Gray, Non-Plastic, Fine to Coarse SAND (SP-SM/A-3) with Silt and Trace of Shell Fragments, Munsell=GLEY1 4/N, LL=NP, PL=NP, PI=NP, NMC=24.6%, %#200=10.4 | | 50.5 | SS-7 | 4 | 3 | 4 | | 7 |
| -55.0 | | **HAWTHORN MARL** | | 56.0 | SS-8 | 4 | 2 | 6 | | 8 |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-12 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 87+88 | **Offset:** | 79.3'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.404595 | **Longitude:** | -80.45264 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 192 ft | **Soil Depth:** | 159 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/11/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| -60.0 | | **HAWTHORN MARL**<br>Loose to Very Loose, Wet, Olive Gray, Non-Plastic, Weakly Reactive, Silty Fine to Medium SAND (SM/A-5(0)) with Trace of Shell Fragments, Munsell=5Y 4/2 | 61.0 | SS-9 | 2 | 2 | 2 | | 4 |
| -65.0 | | @SS-9: No Shell Fragments, LL=51, PL=NP, PI=NP, NMC=81.2%, %#200=48.0 | | | | | | | |
| -70.0 | | @SS-10: Very Dark Greenish Gray, Munsell=GLEY1 3/10Y | 69.5 | SS-10 | 1 | 3 | 3 | | 6 |
| -75.0 | | | 75.0 | SS-11 | 2 | 4 | 5 | | 9 |
| -80.0 | | @SS-12: Medium Plasticity, A-7-5(4), LL=44, PL=31, PI=13, NMC=61.8%, %#200=46.6 | 80.0 | SS-12 | 2 | 3 | 3 | | 6 |
| -85.0 | | | 86.0 | SS-13 | WOH | 3 | 5 | | 8 |
| -90.0 | 91.0 | **COOPER GROUP LIMESTONE**<br>Medium Dense to Loose, Wet, Very Dark Greenish Gray, Non-Plastic, Non-Reactive to Strongly Reactive, Silty Fine to Coarse SAND (SM/A-4(0)) with Phosphate Nodules, Calcaceous, Munsell=GLEY1 3/10Y | 91.0 | SS-14 | 26 | 5 | 7 | | 12 |
| -95.0 | | @SS-15: Light Greenish Gray, Munsell=GLEY1 7/10Y, LL=30, PL=NP, PI=NP, NMC=33.7%, %#200=49.7 | 96.5 | SS-15 | 4 | 6 | 5 | | 11 |
| -100.0 | | | 102.0 | SS-16 | 2 | 4 | 5 | | 9 |
| -105.0 | | @SS-17: Greenish Gray, Munsell=5GY 6/1 | 106.5 | SS-17 | 2 | 4 | 8 | | 12 |
| -110.0 | | | 110.5 | SS-18 | 4 | 6 | 2 | | 8 |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-12 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 87+88 | **Offset:** | 79.3'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.404595 | **Longitude:** | -80.45264 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 192 ft | **Soil Depth:** | 159 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/11/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Loose to Medium Dense, Wet, Greenish Gray, Non-Plastic, Non-Reactive to Strongly Reactive, Silty Fine to Coarse SAND (SM/A-4(0)) with Phosphate Nodules, Calcaceous, Munsell=5GY 6/1 | | 115.5 | SS-19 | | 2 | 3 | | 5 | *Not Recorded for Top 6"* |
| -120.0 | | @SS-20: Greenish Gray, Munsell=GLEY1 6/10Y | | 120.5 | SS-20 | | | | | | *Rod Slipped and Blow Counts* |
| -125.0 | | | | 125.5 | SS-21 | 4 | 6 | 8 | | 14 | *Rod Slipped and Blow Counts* |
| -130.0 | | | | 130.5 | SS-22 | 5 | 4 | 8 | | 12 | *Not Recorded* |
| | 134.0 | | | | | | | | | | |
| -135.0 | | Firm to Stiff, Greenish Gray, Medium to High Plasticity, Strongly Reactive, Fine Sandy SILT (ML/A-6), Munsell=GLEY1 6/10Y | | 135.5 | SS-23 | 3 | 2 | 5 | | 7 | |
| -140.0 | | | | 141.0 | SS-24 | 3 | 4 | 8 | | 12 | |
| -145.0 | | | | | | | | | | | |
| | | | | 148.5 | SS-25 | 3 | 4 | 4 | | 8 | |
| -150.0 | | | | 151.5 | SS-26 | 4 | 5 | 6 | | 11 | |
| -155.0 | | | | 155.5 | SS-27 | 4 | 4 | 5 | | 9 | |
| | 158.0 | | | | | | | | | | |
| -160.0 | | Medium Dense to Loose, Wet, Greenish Gray, Low Plasticity, Strongly Reactive, Silty Fine SAND (SM/A-2-4), Munsell=GLEY1 6/10Y | | 160.0 | SS-28 | 5 | 7 | 12 | | 19 | |
| | 165.0 | | | | | | | | | | |
| -165.0 | | Stiff to Firm, Wet, Light Greenish Gray, Low to Medium Plasticity, Strongly Reactive, Fine Sandy SILT (ML/A-4), Munsell=GLEY1 7/10Y | | 165.0 | SS-29 | 4 | 4 | 6 | | 10 | |
| -170.0 | | | | 170.0 | SS-30 | 3 | 4 | 4 | | 8 | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-12 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | R. Wessinger | **Boring Location:** | 87+88 | **Offset:** | 79.3'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.404595 | **Longitude:** | -80.45264 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 192 ft | **Soil Depth:** | 159 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/11/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| -175.0 | | Very Stiff, Wet, Light Greenish Gray, Low to Medium Plasticity, Strongly Reactive, Fine Sandy SILT (ML/A-4), Munsell=GLEY1 7/10Y | | 174.5 | SS-31 | 4 | 7 | 13 | | 20 |
| -180.0 | 180.0 | Medium Dense, Wet, Greenish Gray, Low to Medium Plasticity, Strongly Reactive, Silty Fine SAND (SM/A-3), Munsell=GLEY1 6/10Y | | 180.0 | SS-32 | | | | | |
| -185.0 | | | | 185.5 | SS-33 | 4 | 5 | 7 | | 12 |
| -190.0 | | @SS-34: Loose | | 190.5 | SS-34 | 4 | 4 | 4 | | 8 |
| | 192.0 | Boring Terminated at 192.0 feet | | | | | | | | |
| -195.0 | | | | | | | | | | |
| -200.0 | | | | | | | | | | |
| -205.0 | | | | | | | | | | |
| -210.0 | | | | | | | | | | |
| -215.0 | | | | | | | | | | |
| -220.0 | | | | | | | | | | |
| -225.0 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Pushed Spoon for Sample, but*

*Blo Counts Not Recorded*


LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-13 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 92+79 | **Offset:** | 16.2'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.403837 | **Longitude:** | -80.451288 | **Date Started:** | 6/16/2016 |
| **Total Depth:** | 190.5 ft | **Soil Depth:** | 162.5 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/21/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |




LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-13 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 92+79 | **Offset:** | 16.2'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.403837 | **Longitude:** | -80.451288 | **Date Started:** | 6/16/2016 |
| **Total Depth:** | 190.5 ft | **Soil Depth:** | 162.5 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/21/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | **HAWTHORN MARL** | | 58.0 | | | | | | | |
| -60.0 | | Very Loose to Loose, Moist, Dark Greenish Gray, High Plasticity, Weakly Reactive, Clayey Fine to Medium SAND (SC/A-7-6(11)), Munsell=10Y 4/1 | | | SS-9 | 7 | 3 | 3 | | 6 | |
| | | | | 63.5 | | | | | | | |
| -65.0 | | @SS-10: LL=67, PL=29, PI=38, NMC=73.8%, %#200=43.9 | | | SS-10 | 2 | 2 | 2 | | 4 | |
| | | | | 69.0 | | | | | | | |
| -70.0 | | @SS-11: No Recovery | | | SS-11 | 3 | 2 | 4 | | 6 | |
| -75.0 | 75.0 | **COOPER GROUP LIMESTONE** | | 76.5 | | | | | | | |
| | | Firm, Moist, Greenish Gray, Low Plasticity, Strongly Reactive, Sandy SILT (ML/A-4(1)) with Phosphate Nodules, Calcaceous, Munsell=GLEY1 6/1 | | | SS-12 | 1 | 3 | 3 | | 6 | |
| -80.0 | | @SS-13: Olive Gray, Munsell=5Y 5/2 | | 81.5 | SS-13 | 3 | 3 | 4 | | 7 | |
| -85.0 | | | | 86.5 | | | | | | | |
| | | @SS-14: No Recovery | | | SS-14 | 2 | 2 | 2 | | 4 | |
| -90.0 | | | | 90.5 | | | | | | | |
| | | @SS-15: Very Stiff | | | SS-15 | | 11 | 12 | | 23 | *Rod Slipped and Blow Counts Not Recorded for Top 6"* |
| -95.0 | | @SS-16: Firm to Stiff, Light Greenish Gray, Munsell=GLEY1 7/10Y | | 94.5 | SS-16 | 3 | 3 | 4 | | 7 | |
| | | | | 99.5 | | | | | | | |
| -100.0 | | @SS-17: LL=30, PL=24, PI=6, NMC=37.3%, %#200=50.2 | | | SS-17 | 3 | 4 | 3 | | 7 | |
| | | | | 104.0 | | | | | | | |
| -105.0 | | | | | SS-18 | 3 | 3 | 7 | | 10 | |
| | | | | 109.0 | | | | | | | |
| -110.0 | | @SS-19: No Recovery | | | SS-19 | 3 | 3 | 3 | | 6 | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-13 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 92+79 | **Offset:** | 16.2'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.403837 | **Longitude:** | -80.451288 | **Date Started:** | 6/16/2016 |
| **Total Depth:** | 190.5 ft | **Soil Depth:** | 162.5 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/21/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| -115.0 | | Firm to Stiff, Moist, Greenish Gray, Low Plasticity, Strongly Reactive, Sandy SILT (ML/A-4(1)) with Phosphate Nodules, Calcaceous, Munsell=5GY 6/1 | | 116.5 | SS-20 | 3 | 3 | 3 | | 6 |
| -120.0 | | | | 121.5 | SS-21 | 5 | 5 | 7 | | 12 |
| -125.0 | | | | 127.0 | SS-22 | 3 | 4 | 7 | | 11 |
| -130.0 | | | | 132.5 | SS-23 | 2 | 3 | 4 | | 7 |
| -135.0 | | | | 138.0 | SS-24 | 3 | 4 | 5 | | 9 |
| -140.0 | | | | | | | | | | |
| -145.0 | | @SS-25: Olive Gray, Munsell=5Y 5/2 | | 146.0 | SS-25 | 4 | 4 | 4 | | 8 |
| | | @SS-26: No Recovery | | 148.0 | SS-26 | 3 | 3 | 5 | | 8 |
| -150.0 | | @SS-27: Light Greenish Gray, Munsell=GLEY1 7/5Y | | 152.5 | SS-27 | 3 | 3 | 4 | | 7 |
| -155.0 | | | | 157.0 | SS-28 | 4 | 4 | 4 | | 8 |
| -160.0 | | | | 162.0 | SS-29 | 3 | 5 | 5 | | 10 |
| -165.0 | | @SS-30: Greenish Gray, Munsell=GLEY1 6/10Y | | 166.5 | SS-30 | 2 | 4 | 5 | | 9 |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-13 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 92+79 | **Offset:** | 16.2'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.0 ft | **Latitude:** | 32.403837 | **Longitude:** | -80.451288 | **Date Started:** | 6/16/2016 |
| **Total Depth:** | 190.5 ft | **Soil Depth:** | 162.5 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/21/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| -170.0 | | Stiff to Firm, Moist, Greenish Gray, Low Plasticity, Strongly Reactive, Sandy SILT (ML/A-4(1)) with Phosphate Nodules, Calcaceous, Munsell=GLEY1 6/10Y | | 172.0 | | | | | | |
| | | | | | SS-31 | 4 | 5 | 7 | | 12 |
| -175.0 | | | | 177.5 | | | | | | |
| | | | | | SS-32 | 2 | 2 | 5 | | 7 |
| -180.0 | | | | 183.5 | | | | | | |
| | | | | | SS-33 | 6 | 5 | 8 | | 13 |
| -185.0 | | | | 189.0 | | | | | | |
| | | @SS-34: Very Stiff | | | | | | | | |
| -190.0 | 190.5 | | | | SS-34 | 7 | 9 | 8 | | 17 |
| | | Boring Terminated at 190.5 feet | | | | | | | | |
| -195.0 | | | | | | | | | | |
| -200.0 | | | | | | | | | | |
| -205.0 | | | | | | | | | | |
| -210.0 | | | | | | | | | | |
| -215.0 | | | | | | | | | | |
| -220.0 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-14 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 97+18 | **Offset:** | 5.6'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.1 ft | **Latitude:** | 32.403431 | **Longitude:** | -80.449948 | **Date Started:** | 6/13/2016 |
| **Total Depth:** | 190 ft | **Soil Depth:** | 190 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/15/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0.1 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | Marsh | | 0.0 | | | | | | |
| | | **HOLOCENE** | | 2.0 | SS-1 | WOH | /12" | 1 | 2 | 1 |
| | | Very Loose, Wet, Dark Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4) with Trace of Shell Fragments, Munsell=GLEY1 4/N | | 4.0 | SS-2 | 2 | 1 | 1 | 1 | 2 |
| -4.9 | | | | 6.0 | SS-3 | 1/12" | | 4 | 7 | 4 |
| | | @SS-4: Medium Dense, Light Gray, Munsell=GLEY1 7/N | | 8.0 | SS-4 | 6 | 10 | 15 | 10 | 25 |
| | | @SS-5: Very Loose, LL=NP, PL=NP, PI=NP, NMC=32.4%, %#200=13.8 | | | SS-5 | 1 | 2 | 1 | 2 | 3 |
| -9.9 | | | | 13.5 | | | | | | |
| | | @SS-6: Medium Dense | | | SS-6 | 4 | 8 | 8 | | 16 |
| -14.9 | | | | 18.5 | | | | | | |
| | 17.0 | Loose, Wet, Greenish Gray, Low Plasticity, Fine SAND (SP-SM/A-3) with Silt, Munsell=GLEY1 6/5GY | | | SS-7 | 3 | 1 | 4 | | 5 |
| -19.9 | | | | 23.5 | | | | | | |
| | 22.0 | Loose to Very Loose, Wet, Dark Gray, Non-Plastic to Low Plasticity, Silty Fine SAND (SM/A-2-4) with Trace of Shell Fragments, Munsell=GLEY1 9/N | | | SS-8 | 2 | 2 | 7 | | 9 |
| -24.9 | | @SS-8: LL=NP, PL=NP, PI=NP, NMC=38.6%, %#200=17.6 | | 28.5 | | | | | | |
| | | @SS-9: Fine to Medium Sand, (A-4(1)), LL=31, PL=24, PI=7, NMC=50.9%, %#200=43.7 | | | SS-9 | 1 | 1 | 1 | | 2 |
| -29.9 | 32.0 | | | 33.5 | | | | | | |
| | | Soft to Very Soft, Wet, Dark Gray, Medium Plasticity, Sandy SILT (ML/A-7-5(4)), Munsell=GLEY1 4/N | | | SS-10 | 2 | 2 | 2 | | 4 |
| -34.9 | | | | 38.5 | | | | | | |
| | | @SS-11: LL=47, PL=36, PI=11, NMC=56.1%, %#200=52.0 | | | SS-11 | WOH | /12" | 2 | | 2 |
| -39.9 | | | | 43.5 | | | | | | |
| | | | | | SS-12 | 1 | 1 | 1 | | 2 |
| -44.9 | 47.0 | | | 48.5 | | | | | | |
| | | Very Loose, Wet, Greenish Black, Non-Plastic, Silty Fine SAND (SM/A-2-4), Munsell=GLEY1 2.5/10Y | | | SS-13 | WOH | 2 | 2 | | 4 |
| -49.9 | | @SS-13: LL=NP, PL=NP, PI=NP, NMC=46.2%, %#200=30.1 | | | | | | | | |
| | 53.5 | | | 53.5 | | | | | | |

SPT N VALUE ●

PL ✕ MC ○ LL ✕

▲ FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-14 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 97+18 | **Offset:** | 5.6'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.1 ft | **Latitude:** | 32.403431 | **Longitude:** | -80.449948 | **Date Started:** | 6/13/2016 |
| **Total Depth:** | 190 ft | **Soil Depth:** | 190 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/15/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0.1 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| -54.9 | | **HAWTHORN MARL**<br>Stiff to Firm, Moist, Dark Olive Gray, Low Plasticity, Non Reactive, SILT (ML/A-4), Calcaceous, Munsell=5Y 3/2<br>@SS-15: Soft to Firm | | | SS-14 | 2 | 5 | 4 | | 9 | |
| | | | | 58.5 | SS-15 | WOH | 2 | 2 | | 4 | |
| -59.9 | | | | | | | | | | | |
| | | | | 63.0 | SS-16 | 3 | 3 | 4 | | 7 | |
| -64.9 | | | | | | | | | | | |
| | | | | 68.0 | SS-17 | 3 | 3 | 4 | | 7 | |
| -69.9 | | | | | | | | | | | |
| | | | | 72.5 | SS-18 | 3 | 3 | 4 | | 7 | |
| -74.9 | | | | | | | | | | | |
| | 77.0 | **COOPER GROUP LIMESTONE**<br>Medium Dense to Loose, Wet, Gray/Black, Low Plasticity, Weakly Reactive, Clayey Fine to Coarse SAND (SC/A-2-4) with Phosphate Nodules, Calcaceous, Munsell=5Y 6/1 & 2.5/1<br>@SS-20: Light Olive Gray, Strongly Reactive, Munsell=5Y 6/2 | | 77.5 | SS-19 | 16 | 4 | 9 | | 13 | |
| -79.9 | | | | | | | | | | | |
| | | | | 83.5 | SS-20 | 2 | 2 | 7 | | 9 | |
| -84.9 | | | | | | | | | | | |
| | | | | 88.5 | SS-21 | 2 | 2 | 3 | | 5 | *Hard Lense from 87.0 to 88.0 feet* |
| -89.9 | | | | | | | | | | | |
| | | | | 93.5 | SS-22 | 7 | 16 | 10 | | 26 | |
| -94.9 | | | | | | | | | | | |
| | 98.5 | Firm to Soft, Wet, Greenish Gray, Non-Plastic to Low Plasticity, Strongly Reactive, Sandy SILT (ML/A-4), Calcaceous, Munsell=GLEY1 5/10Y | | 98.5 | SS-23 | 2 | 3 | 5 | | 8 | |
| -99.9 | | | | | | | | | | | |
| | | | | 104.0 | SS-24 | 2 | 2 | 2 | | 4 | |
| -104.9 | | | | | | | | | | | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-14 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 97+18 | **Offset:** | 5.6'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.1 ft | **Latitude:** | 32.403431 | **Longitude:** | -80.449948 | **Date Started:** | 6/13/2016 |
| **Total Depth:** | 190 ft | **Soil Depth:** | 190 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/15/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0.1 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Firm, Wet, Greenish Gray, Non-Plastic to Low Plasticity, Strongly Reactive, Sandy SILT (ML/A-4), Calcaceous, Munsell=GLEY1 5/10Y | | 108.5 | SS-25 | 3 | 2 | 3 | | 5 | |
| -109.9 | | | | | | | | | | | |
| | | | | 113.5 | SS-26 | 2 | 3 | 3 | | 6 | |
| -114.9 | | | | | | | | | | | |
| | | @SS-27: Stiff | | 118.5 | SS-27 | 4 | 4 | 5 | | 9 | |
| -119.9 | | | | | | | | | | | |
| | 123.5 | | | 123.5 | SS-28 | 3 | 3 | 5 | | 8 | |
| | | Loose, Moist, Gray, Strongly Reactive, Non-Plastic to Low Plasticity, Silty Fine SAND (SM/A-2-4), Calcaceous, Munsell=5Y 6/1 | | | | | | | | | |
| -124.9 | | | | 128.5 | SS-29 | 3 | 2 | 4 | | 6 | |
| -129.9 | | | | | | | | | | | |
| | | @SS-30: No Recovery | | 133.0 | SS-30 | 3 | 2 | 3 | | 5 | |
| -134.9 | | | | | | | | | | | |
| | | @SS-31: Medium Dense, Greenish Gray, Munsell=GLEY1 7/10Y | | 138.0 | SS-31 | | 5 | 6 | | 11 | *Rod Slipped and Blow Count* |
| -139.9 | | | | | | | | | | | |
| | | @SS-32: No Recovery | | 142.5 | SS-32 | 4 | 4 | 5 | | 9 | *N Recorded for Top 6"* |
| -144.9 | | | | | | | | | | | |
| | | @SS-33: Loose, Fine to Coarse Sand | | 148.5 | SS-33 | 3 | 4 | 4 | | 8 | |
| -149.9 | | | | | | | | | | | |
| | | @SS-34: No Recovery | | 153.5 | SS-34 | 4 | 4 | 5 | | 9 | |
| -154.9 | | | | | | | | | | | |
| | | | | 158.5 | SS-35 | 3 | 4 | 5 | | 9 | |
| -159.9 | | | | | | | | | | | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-14 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | J. Wessinger | **Boring Location:** | 97+18 | **Offset:** | 5.6'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 0.1 ft | **Latitude:** | 32.403431 | **Longitude:** | -80.449948 | **Date Started:** | 6/13/2016 |
| **Total Depth:** | 190 ft | **Soil Depth:** | 190 ft | **Core Depth:** | N/A ft | **Date Completed:** | 6/15/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0.1 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Loose, Moist, Greenish Gray, Strongly Reactive, Non-Plastic to Low Plasticity, Silty Fine SAND (SM/A-2-4), Calcaceous, Munsell=GLEY1 7/10Y | | 163.5 | SS-36 | 3 | 3 | 4 | | 7 |
| -164.9 | | | | 168.5 | SS-37 | 4 | 3 | 5 | | 8 |
| -169.9 | | | | 173.5 | SS-38 | 2 | 3 | 5 | | 8 |
| -174.9 | | | | 178.5 | SS-39 | 3 | 3 | 3 | | 6 |
| -179.9 | | | | 183.5 | SS-40 | 3 | 4 | 4 | | 8 |
| -184.9 | | @SS-40: No Recovery | | 188.5 | SS-41 | 3 | 2 | 4 | | 6 |
| -189.9 | 190.0 | Boring Terminated at 190.0 feet | | | | | | | | |
| -194.9 | | | | | | | | | | |
| -199.9 | | | | | | | | | | |
| -204.9 | | | | | | | | | | |
| -209.9 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-15 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 100+78 | **Offset:** | 9.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 1.6 ft | **Latitude:** | 32.403014 | **Longitude:** | -80.448888 | **Date Started:** | 8/3/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/3/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | Marsh | | 0.0 | SS-1 | WOH/24" | | | | WOH |
| | | **HOLOCENE** | | 2.0 | SS-2 | 1 | 1 | 1 | 5 | 2 |
| | | Very Loose, Wet, Very Dark Gray, Non-Plastic, Non-Reactive, Poorly Graded Fine SAND (SP-SM/A-3) with Silt, Munsell=5Y 3/1 | | 4.0 | SS-3 | 7 | 7 | 9 | 4 | 16 |
| -3.4 | | @SS-2: Dark Gray, Munsell=5Y 4/1 | | 6.0 | SS-4 | 6 | 8 | 9 | 12 | 17 |
| | | @SS-3: Medium Dense, Gray, Weakly Reactive, Munsell=5Y 5/1, LL=NP, PL=NP, PI=NP, NMC=26.2%, %#200=8.2 | | 8.0 | SS-5 | 5 | 6 | 8 | 11 | 14 |
| -8.4 | | @SS-4: LL=NP, PL=NP, PI=NP, NMC=23.5%, %#200=5.1 | | 13.5 | SS-6 | 5 | 11 | 14 | | 25 |
| | | @SS-6: LL=NP, PL=NP, PI=NP, NMC=23.8%, %#200=5.5 | | 18.5 | SS-7 | 3 | 2 | 5 | | 7 |
| -13.4 | 17.0 | Loose to Very Loose, Wet, Gray, Non-Plastic, Weakly Reactive, Silty Fine to Medium SAND (SM/A-2-4) with Trace of Shell Fragments, Munsell=5Y 5/1 | | 23.5 | SS-8 | 3 | 3 | 4 | | 7 |
| -18.4 | | @SS-7: LL=NP, PL=NP, PI=NP, NMC=33.2%, %#200=17.5 | | 28.5 | SS-9 | 3 | 2 | 2 | | 4 |
| -23.4 | | | | 33.5 | SS-10 | WOH | 1 | 3 | | 4 |
| -28.4 | | | | 38.5 | SS-11 | WOH/18" | | | | WOH |
| -33.4 | | @SS-10: Dark Gray, Munsell=5Y 4/1 | | 43.5 | SS-12 | WOH/18" | | | | WOH |
| -38.4 | 37.0 | Very Soft, Wet, Dark Gray, Medium Plasticity, Weakly Reactive, Fine Sandy CLAY (CL/A-4) with Trace of Organics, Munsell=GLEY1 4/N | | 48.5 | SS-13 | 3 | 3 | 6 | | 9 |
| -43.4 | 42.0 | @SS-11: Organics=4.15% | | 53.5 | SS-14 | 5 | 6 | 8 | | 14 |
| -48.4 | | Very Loose to Loose, Wet, Dark Gray, Non-Plastic, Weakly Reactive, Silty Fine to Medium SAND (SM/A-2-4) with Trace of Shell Fragments, Munsell=5Y 4/1 | | | | | | | | |
| | | @SS-12: LL=NP, PL=NP, PI=NP, NMC=31.6%, %#200=20.7 | | | | | | | | |
| | | @SS-14: Medium Dense | | | | | | | | |

SPT N VALUE ●

PL × MC ○ LL ×

▲ FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-15 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 100+78 | **Offset:** | 9.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 1.6 ft | **Latitude:** | 32.403014 | **Longitude:** | -80.448888 | **Date Started:** | 8/3/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/3/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Very Loose to Loose, Wet, Dark Gray, Non-Plastic, Weakly Reactive, Silty Fine to Medium SAND (SM/A-2-4) with Trace of Shell Fragments, Munsell=5Y 4/1 | 58.5 | SS-15 | 1 | 1 | 1 | | 2 | |
| -58.4 | | | 63.5 | SS-16 | 3 | 3 | 3 | | 6 | |
| -63.4 | 67.0 | | | | | | | | | |
| | | **HAWTHORN MARL** Loose to Medium Dense, Wet, Olive Gray, Low Plasticity, Weakly Reactive, Silty Fine SAND (SM/A-2-4), Munsell=5Y 4/2 | 68.5 | SS-17 | 3 | 3 | 5 | | 8 | |
| -68.4 | | @SS-18: Olive, Munsell=5Y 4/3 | 73.5 | SS-18 | 4 | 5 | 5 | | 10 | |
| -73.4 | | | 78.5 | SS-19 | 3 | 7 | 16 | | 23 | *Hard Layer from 79.5 to 81.5 feet* |
| -78.4 | 79.5 | **COOPER GROUP LIMESTONE** Medium Dense to Loose, Dark Olive Gray, Low Plasticity, Weakly to Highly Reactive, Silty Fine to Medium SAND (SM/A-2-4) with Phosphate Nodules, Calcaceous, Munsell=5Y 3/2 | 83.5 | SS-20 | 4 | 4 | 5 | | 9 | |
| -83.4 | | @SS-20: Greenish Gray, Munsell=GLEY1 6/10Y | 88.5 | SS-21 | 2 | 14 | 13 | | 27 | |
| -88.4 | | @SS-21: Light Grayish Olive, Munsell=10Y 6/2 | 93.5 | SS-22 | 3 | 5 | 12 | | 17 | |
| -93.4 | | @SS-22: Light Greenish Gray, Munsell=GLEY1 7/10Y | 98.5 | SS-23 | 4 | 4 | 4 | | 8 | |
| -98.4 | | | 103.5 | SS-24 | 3 | 4 | 12 | | 16 | |
| -103.4 | | @SS-25: Greenish Gray, Munsell=GLEY1 6/5GY | 108.5 | SS-25 | 3 | 4 | 6 | | 10 | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-15 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 100+78 | **Offset:** | 9.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 1.6 ft | **Latitude:** | 32.403014 | **Longitude:** | -80.448888 | **Date Started:** | 8/3/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/3/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| | | Loose, Dark Greenish Gray, Low Plasticity, Weakly to Highly Reactive, Silty Fine to Medium SAND (SM/A-2-4) with Phosphate Nodules, Calcaceous, Munsell=GLEY1 6/5GY | 113.5 | SS-26 | 3 | 2 | 3 | | 5 |
| -113.4 | | | 118.5 | SS-27 | 3 | 2 | 4 | | 6 |
| -118.4 | | | 123.5 | SS-28 | 3 | 1 | 4 | | 5 |
| -123.4 | | | 128.5 | SS-29 | 3 | 3 | 4 | | 7 |
| -128.4 | | | 133.5 | SS-30 | 4 | 5 | 3 | | 8 |
| -133.4 | | | 138.5 | SS-31 | 4 | 3 | 5 | | 8 |
| -138.4 | | | | | | | | | |
| | 143.5 | Stiff, Wet, Greenish Gray, Low Plasticity, Strongly Reactive, Fine Sandy SILT (ML/A-4), Calcaceous, Munsell=GLEY1 6/10Y | 143.5 | SS-32 | 4 | 3 | 6 | | 9 |
| -143.4 | | | | | | | | | |
| | 148.5 | | 148.5 | SS-33 | 4 | 4 | 8 | | 12 |
| -148.4 | 150.0 | Medium Dense, Wet, Greenish Gray, Low Plasticity, Strongly Reactive, Silty Fine SAND (SM/A-2-4), Calcaceous, Munsell=GLEY1 6/10Y | | | | | | | |
| | | Boring Terminated at 150.0 feet | | | | | | | |
| -153.4 | | | | | | | | | |
| -158.4 | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-16 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 105+97 | **Offset:** | 25.2'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.4 ft | **Latitude:** | 32.402552 | **Longitude:** | -80.447291 | **Date Started:** | 8/1/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/2/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | Marsh | | 0.0 | SS-1 | WOH/24" | | | | WOH |
| | | **HOLOCENE** | | 2.0 | | | | | | |
| | | Very Loose to Loose, Wet, Gray, Low Plasticity, Weakly Reactive, Silty Fine to Medium SAND (SM/A-2-4) with Trace of Organics (Wood), Munsell=5Y 5/1 | | 4.0 | SS-2 | 2 | 2 | 3 | 3 | 5 |
| -2.6 | 4.0 | @SS-2: Dark Grayish Brown, Munsell=2.5Y 4/2 | | 6.0 | SS-3 | 5 | 12 | 16 | 21 | 28 |
| | | | | 8.0 | SS-4 | 6 | 11 | 11 | 17 | 22 |
| | | | | | SS-5 | 4 | 5 | 10 | 14 | 15 |
| -7.6 | | Medium Dense, Wet, Gray, Non-Plastic, Weakly Reactive, Poorly Graded Fine SAND (SP/A-3) with Trace of Shell Fragments, Munsell=5Y 6/1 | | 13.5 | SS-6 | 7 | 13 | 16 | | 29 |
| -12.6 | | @SS-4: Non-Reactive, LL=NP, PL=NP, PI=NP, NMC=24.5%, %#200=2.1 | | | | | | | | |
| | 17.0 | @SS-6: LL=NP, PL=NP, PI=NP, NMC=24.3%, %#200=2.1 | | 18.5 | SS-7 | 1 | 2 | 6 | | 8 |
| -17.6 | | Loose to Very Loose, Wet, Dark Gray, Non-Plastic, Weakly Reactive, Silty Fine SAND (SM/A-2-4) with Trace of Shell Fragments, Munsell=5Y 4/1 | | 23.5 | SS-8 | 2 | 2 | 3 | | 5 |
| -22.6 | | @SS-8: Gray, Munsell=5Y 5/1, LL=NP, PL=NP, PI=NP, NMC=37.4%, %#200=13.9 | | | | | | | | |
| | | | | 28.5 | SS-9 | 3 | 4 | 6 | | 10 |
| -27.6 | | | | | | | | | | |
| | | | | 33.5 | SS-10 | 2 | 2 | 2 | | 4 |
| -32.6 | | | | | | | | | | |
| | 37.0 | Very Loose, Wet, Dark Gray, Medium Plasticity, Weakly Reactive, Clayey Fine SAND (SC/A-6(4)), Munsell=5Y 4/1 | | 38.5 | SS-11 | 1 | 1 | 1 | | 2 |
| -37.6 | 42.0 | @SS-11: LL=36, PL=21, PI=15, NMC=56.7%, %#200=46.6 | | 43.5 | SS-12 | 2 | 1 | 2 | | 3 |
| -42.6 | 47.0 | Very Loose, Wet, Dark Gray, Non-Plastic, Weakly Reactive, Silty Fine SAND (SM/A-2-4), Munsell=5Y 4/1 | | 48.5 | SS-13 | WOH/12" | | | | 1 |
| | | Very Soft, Wet, Dark Gray, High Plasticity, Weakly Reactive, Elastic SILT (MH/A-7-5(25)) with Few Organics, Munsell=GLEY1 4/N, LL=75 | | | | | | | | |
| -47.6 | | @SS-13: LL=75, PL=35, PI=40, NMC=84.8%, %#200=91.0 | | 53.5 | SS-14 | 1 | 1 | 1 | | 2 |
| -52.6 | | @SS-14: Organics=7.22% | | | | | | | | |
| | 57.5 | | | | | | | | | |

SPT N VALUE ● PL × MC ○ LL × ▲ FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | B-16 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 105+97 | **Offset:** | 25.2'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.4 ft | **Latitude:** | 32.402552 | **Longitude:** | -80.447291 | **Date Started:** | 8/1/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/2/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| | | Loose, Wet, Dark Gray, Non-Plastic, Weakly Reactive, Silty Fine SAND (SM/A-2-4), Munsell=5Y 4/1 | 58.5 | SS-15 | WOH | 2 | 3 | | 5 |
| -57.6 | | | 63.5 | SS-16 | 3 | 3 | 5 | | 8 |
| -62.6 | 67.0 | | | | | | | | |
| | | Soft, Wet, Dark Gray, Medium Plasticity, Weakly Reactive, Fine Sandy CLAY (CL/A-4), Munsell=5Y 4/1 | 68.5 | SS-17 | 2 | 1 | 2 | | 3 |
| -67.6 | 70.0 | **HAWTHORN MARL** | | | | | | | |
| | | Very Loose to Loose, Wet, Olive Gray, Low Plasticity, Weakly Reactive, Silty Fine SAND (SM/A-2-4), Munsell=5Y 4/2 | 73.5 | SS-18 | 3 | 2 | 4 | | 6 |
| -72.6 | | | 78.5 | SS-19 | 3 | 4 | 23 | | 27 |
| -77.6 | 80.0 | @SS-19: Medium Dense, Dark Olive Gray, Munsell=5Y 3/2 | | | | | | | |
| | | **COOPER GROUP LIMESTONE** | | | | | | | |
| | | Medium Dense to Loose, Wet, Light Greenish Gray, Low Plasticity, Strongly Reactive, Silty Fine to Medium SAND (SM/A-2-4), Calcaceous, Munsell=GLEY1 7/5GY | 83.5 | SS-20 | 4 | 6 | 5 | | 11 |
| -82.6 | | | 88.5 | SS-21 | 3 | 2 | 3 | | 5 |
| -87.6 | | @SS-21: Greenish Gray, Munsell=GLEY1 6/10Y | | | | | | | |
| | | | 93.5 | SS-22 | 24 | 20 | 8 | | 28 |
| -92.6 | | @SS-22: Light Greenish Gray, Munsell=GLEY1 7/10Y | | | | | | | |
| | | | 98.5 | SS-23 | 8 | 10 | 5 | | 15 |
| -97.6 | | | | | | | | | |
| | | | 103.5 | SS-24 | 3 | 4 | 6 | | 10 |
| -102.6 | | @SS-24: Greenish Gray, Munsell=GLEY1 6/5GY | | | | | | | |
| | | | 108.5 | SS-25 | 3 | 2 | 4 | | 6 |
| -107.6 | | | | | | | | | |
| | | | 113.5 | SS-26 | 4 | 4 | 5 | | 9 |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Hard Layer from 81.0 to 81.5 feet*

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | B-16 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 105+97 | **Offset:** | 25.2'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.4 ft | **Latitude:** | 32.402552 | **Longitude:** | -80.447291 | **Date Started:** | 8/1/2016 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/2/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Loose to Medium Dense, Wet, Greenish Gray, Low Plasticity, Strongly Reactive, Silty Fine to Medium SAND (SM/A-2-4), Calcaceous, Munsell=GLEY1 6/5GY | | 118.5 | SS-27 | 3 | 3 | 5 | | 8 |
| -117.6 | | | | 123.5 | SS-28 | 5 | 3 | 6 | | 9 |
| -122.6 | | | | 128.5 | SS-29 | 3 | 3 | 4 | | 7 |
| -127.6 | | @SS-29: No Recovery | | 133.5 | SS-30 | 4 | 3 | 3 | | 6 |
| -132.6 | | @SS-30: No Recovery | | 138.5 | SS-31 | 3 | 4 | 3 | | 7 |
| -137.6 | | | | 143.5 | SS-32 | 5 | 6 | 6 | | 12 |
| -142.6 | | | | 148.5 | SS-33 | 3 | 4 | 7 | | 11 |
| -147.6 | 150.0 | Boring Terminated at 150.0 feet | | | | | | | | |
| -152.6 | | | | | | | | | | |
| -157.6 | | | | | | | | | | |
| -162.6 | | | | | | | | | | |
| -167.6 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | TS-1 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | M. Touchberry | **Boring Location:** | 40+78 | **Offset:** | 305.9'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.4 ft | **Latitude:** | 32.408395 | **Longitude:** | -80.467293 | **Date Started:** | 11/16/2015 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | 0 ft | **Date Completed:** | 11/17/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 550X | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 74% |
| **Core Size:** | N/A | **Driller:** | Ameridrill | **Groundwater:** | **TOB** 4 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | Grassed Parking Area | | | | | | | | |
| | | **EMBANKMENT FILL** | | 0.0 | | | | | | |
| | | Medium Dense, Dry to Moist, Dark Reddish Brown, Non-Plastic, Fine to Medium SAND (SP-SM/A-1) with Silt, Munsell= 5YR 2.5/2 | | 2.0 | SS-1 | 3 | 5 | 6 | 6 | 11 |
| | 3.0 | Loose to Very Loose, Wet, Very Dark Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4) with Trace of Shell Fragments, Munsell=GLEY1 3/N | | 4.0 | SS-2 | 5 | 6 | 3 | 5 | 9 |
| 1.4 | | | | 6.0 | SS-3 | 2 | 2 | 1 | 1 | 3 |
| | | @SS-4: Medium Dense to Dense, Dark Greenish Gray, Munsell=GLEY1 4/10Y, LL=NP, PL=NP, PI=NP, NMC=25.9%, %#200=13.9 | | 8.0 | SS-4 | 2 | 5 | 9 | 13 | 14 |
| | | @SS-5: Greenish Gray, Munsell= GLEY1 5/10Y | | 10.0 | SS-5 | 15 | 22 | 15 | 8 | 37 |
| -3.6 | | @SS-6: Very Loose, Very Dark Greenish Gray, Munsell=GLEY1 3/10Y | | 12.0 | SS-6 | 1 | 1 | 1 | 2 | 2 |
| | 12.0 | **ENGINEERED FILL** | | 12.0 | | | | | | |
| | | Medium Dense, Wet, Greenish Gray, Non-Plastic, Fine SAND (SP-SM/A-1) with Silt, Munsell=GLEY1 5/10Y | | 14.0 | SS-7 | 3 | 7 | 7 | 11 | 14 |
| -8.6 | 15.5 | @SS-8: Very Loose, Light Greenish Gray, Munsell=GLEY1 7/10Y | | 16.0 | SS-8 | 2 | 2 | 2 | 2 | 4 |
| | | **HOLOCENE** | | 18.0 | SS-9 | WOH/24" | | | | WOH |
| | | Very Loose to Loose, Wet, Very Dark Greenish Gray, Low Plasticity, Silty, Clayey Fine SAND (SC-SM/A-4(0)), Munsell=GLEY1 3/10Y | | 20.0 | SS-10 | WOH | 1 | 3 | 4 | 4 |
| -13.6 | | @SS-9: LL=25, PL=21, PI=4, NMC=52.2%, %#200=49.7 | | 22.0 | SS-11 | WOH | 3 | 6 | 4 | 9 |
| | 21.0 | Loose to Medium Dense, Wet, Greenish Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4), Munsell=GLEY1 5/10Y | | 24.0 | SS-12 | 5 | 7 | 8 | 6 | 15 |
| -18.6 | | @SS-12: LL=NP, PL=NP, PI=NP, NMC=26.7%, %#200=16.3 | | 26.0 | SS-13 | 2 | 2 | 4 | 4 | 6 |
| | 26.0 | @SS-13: with Trace of Shell Fragments | | | | | | | | |
| | | Very Soft, Wet, Very Dark Greenish Gray, Medium Plasticity, Sandy SILT (ML/A-7-6(9)) with Trace of Shell Fragments, Munsell=GLEY1 3/10Y | | 28.0 | SS-14 | WOH | 1 | 1 | 1 | 2 |
| -23.6 | | @SS-14: LL=42, PL=27, PI=15, NMC=65.5%, %#200=65.6 | | 30.0 | SS-15 | WOH/18" | | | 1 | WOH |
| | 32.0 | | | 32.0 | SS-16 | WOH/24" | | | | WOH |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | TS-1 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | M. Touchberry | **Boring Location:** | 40+78 | **Offset:** | 305.9'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.4 ft | **Latitude:** | 32.408395 | **Longitude:** | -80.467293 | **Date Started:** | 11/16/2015 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | 0 ft | **Date Completed:** | 11/17/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 550X | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 74% |
| **Core Size:** | N/A | **Driller:** | Ameridrill | **Groundwater:** | **TOB** 4 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| | | Very Loose, Wet, Very Dark Greenish Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4) with Shell Fragments, Munsell=GLEY1 3/10Y | 34.0 | SS-17 | 3 | 1/12" | | 1 | 1 |
| -28.6 | | @SS-17: LL=NP, PL=NP, PI=NP, NMC=40.2%, %#200=28.3 | 36.0 | SS-18 | 1 | 1 | 2 | 2 | 3 |
| | | | 38.0 | SS-19 | 1 | 1 | 1 | 1 | 2 |
| | | | 40.0 | SS-20 | 2 | 2 | 1 | 1 | 3 |
| -33.6 | 41.0 | | 42.0 | SS-21 | 2 | 1 | 2 | 1 | 3 |
| | | Soft to Very Soft, Wet, Very Dark Greenish Gray, Non-Plastic to Low Plasticity, SILT (ML/A-4), Munsell=GLEY1 3/10Y | 44.0 | SS-22 | 1 | 1 | 1 | WOH | 2 |
| | 44.0 | @SS-22: with Fine Sand and Trace of Shell Fragments | 44.0 | SS-23 | WOH | 2 | 1 | 3 | 3 |
| -38.6 | | Very Loose, Wet, Very Dark Greenish Gray, Non-Plastic, Silty Fine to Coarse SAND (SM/A-2-4), Munsell=GLEY1 3/10Y, LL=NP, PL=NP, PI=NP, NMC=24.0%, %#200=12.2 | 46.0 | SS-24 | 7 | 10 | 11 | 5 | 21 |
| | 46.0 | | 48.0 | SS-25 | 2 | 6 | 11 | 8 | 17 |
| | 48.0 | Medium Dense, Wet, Gray, Non-Plastic, Poorly Graded Fine to Coarse SAND (SP-SM/A-1-b) with Silt and Trace of Shell Fragments, Munsell=GLEY1 5/N, LL=NP, PL=NP, PI=NP, NMC=20.1%, %#200=9.8 | 50.0 | SS-26 | 2 | 3 | 3 | 5 | 6 |
| -43.6 | | **HAWTHORN MARL** | 52.0 | SS-27 | 3 | 3 | 3 | 4 | 6 |
| | | Very Stiff, Moist, Olive/Dark Greenish Gray, Low Plasticity, Sandy SILT (ML/A-5(4)), Munsell=10Y 4/4 & 4/2 | 54.0 | SS-28 | 4 | 5 | 5 | 5 | 10 |
| | | @SS-26: Firm | 56.0 | SS-29 | WOH | 2 | 2 | 3 | 4 |
| -48.6 | | @SS-27: with Trace of Shell Fragments | 58.0 | SS-30 | 4 | 4 | 4 | 5 | 8 |
| | | @SS-28: Very Stiff, Dark Grayish Olive, Munsell=10Y 4/2 | 60.0 | SS-31 | 2 | 2 | 4 | 5 | 6 |
| | | @SS-29: Soft to Firm, LL=44, PL=39, PI=5, NMC=62.4%, %#200=64.2 | 62.0 | SS-32 | 3 | 4 | 6 | 8 | 10 |
| -53.6 | | | 64.0 | | | | | | |
| | | @SS-32: Stiff | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | TS-1 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | M. Touchberry | **Boring Location:** | 40+78 | **Offset:** | 305.9'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.4 ft | **Latitude:** | 32.408395 | **Longitude:** | -80.467293 | **Date Started:** | 11/16/2015 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | 0 ft | **Date Completed:** | 11/17/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 550X | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 74% |
| **Core Size:** | N/A | **Driller:** | Ameridrill | **Groundwater:** | **TOB** 4 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| -58.6 | | Very Stiff to Stiff, Moist, Dark Grayish Olive, Low Plasticity, Sandy SILT (ML/A-5(4)), Munsell=10Y 4/2 | 66.0 | SS-33 | 7 | 7 | 9 | 10 | 16 |
| | | | 68.0 | SS-34 | 2 | 4 | 5 | 6 | 9 |
| | | | | SS-35 | 3 | 5 | 6 | 6 | 11 |
| -63.6 | | | 70.0 | SS-36 | 3 | 4 | 6 | 9 | 10 |
| | 72.0 | Stiff, Moist, Dark Grayish Olive, High Plasticity, Sandy Elastic SILT (MH/A-7-5(16)), Munsell=10Y 4/2 | 72.0 | SS-37 | 4 | 4 | 6 | 15 | 10 |
| -68.6 | 75.0 | @SS-37: LL=55, PL=32, PI=23, NMC=61.7%, %#200=67.4 | 74.0 | SS-38 | 15 | 19 | 23 | 26 | 42 |
| | | => Hard | 76.0 | SS-39 | 4 | 5 | 8 | 10 | 13 |
| | | **COOPER GROUP LIMESTONE** | 78.0 | SS-40 | 8 | 10 | 18 | 24 | 28 |
| | | Hard, Moist, White, Low Plasticity, Sandy SILT (ML/A-4(4)) with Phosphate Nodules, Munsell=GLEY1 8/N | | | | | | | |
| -73.6 | | @SS-39: Stiff to Very Stiff, LL=31, PL=23, PI=8, NMC=44.5%, %#200=64.7 | 80.0 | SS-41 | 4 | 4 | 5 | 6 | 9 |
| | 81.0 | Loose to Medium Dense, Moist, Gray, Non-Plastic, Silty Fine SAND (SM/A-4(0)), Munsell=5Y 6/1 | 82.0 | SS-42 | 3 | 3 | 3 | 11 | 6 |
| | | @SS-41: LL=NP, PL=NP, PI=NP, NMC=42.6%, %#200=49.1 | 84.0 | SS-43 | 3 | 8 | 18 | 24 | 26 |
| -78.6 | | | 86.0 | SS-44 | 3 | 4 | 6 | 12 | 10 |
| | | | 88.0 | SS-45 | 5 | 6 | 7 | 10 | 13 |
| -83.6 | | @SS-46: Light Olive Gray, Munsell=5Y 6/2 | 90.0 | SS-46 | 2 | 2 | 4 | 5 | 6 |
| | | | 92.0 | SS-47 | 5 | 6 | 6 | 9 | 12 |
| | | | 94.0 | SS-48 | 6 | 7 | 14 | 18 | 21 |
| -88.6 | 96.0 | | 96.0 | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | TS-1 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | M. Touchberry | **Boring Location:** | 40+78 | **Offset:** | 305.9'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.4 ft | **Latitude:** | 32.408395 | **Longitude:** | -80.467293 | **Date Started:** | 11/16/2015 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | 0 ft | **Date Completed:** | 11/17/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 550X | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 74% |
| **Core Size:** | N/A | **Driller:** | Ameridrill | **Groundwater:** | **TOB** 4 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Stiff to Very Stiff, Moist, Light Greenish Gray, Non-Plastic, Sandy SILT (ML/A-4(0)), Munsell=GLEY1 5GY 7/1 | | 98.0 | SS-49 | 2 | 4 | 8 | 12 | 12 |
| | | | | | SS-50 | 9 | 11 | 19 | 29 | 30 |
| -93.6 | | | | 100.0 | SS-51 | 11 | 6 | 8 | 25 | 14 |
| | | | | 102.0 | SS-52 | 4 | 5 | 6 | 17 | 11 |
| | | @SS-53: LL=NP, PL=NP, PI=NP, NMC=33.4%, %#200=56.8 | | 104.0 | SS-53 | 5 | 6 | 15 | 24 | 21 |
| -98.6 | | | | 106.0 | SS-54 | 4 | 6 | 12 | 22 | 18 |
| | | | | 108.0 | SS-55 | 5 | 5 | 7 | 16 | 12 |
| -103.6 | | @SS-56: Firm to Stiff | | 110.0 | SS-56 | 1 | 4 | 4 | 13 | 8 |
| | | | | 112.0 | SS-57 | 4 | 4 | 6 | 10 | 10 |
| | | @SS-58: Hard | | 114.0 | SS-58 | 7 | 13 | 19 | 29 | 32 |
| -108.6 | | @SS-59: Stiff to Very Stiff | | 116.0 | SS-59 | 4 | 5 | 7 | 17 | 12 |
| | | | | 118.0 | SS-60 | 4 | 9 | 13 | 20 | 22 |
| -113.6 | | @SS-61: Firm to Stiff, LL=NP, PL=NP, PI=NP, NMC=35.4%, %#200=55.3 | | 120.0 | SS-61 | 3 | 3 | 4 | 13 | 7 |
| | | | | 122.0 | SS-62 | 3 | 4 | 5 | 8 | 9 |
| | | @SS-63: Hard | | 124.0 | SS-63 | 7 | 14 | 21 | 30 | 35 |
| -118.6 | | @SS-64: Stiff to Very Stiff | | 126.0 | SS-64 | WOH | 5 | 9 | 25 | 14 |
| | | | | 128.0 | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | TS-1 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | M. Touchberry | **Boring Location:** | 40+78 | **Offset:** | 305.9'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.4 ft | **Latitude:** | 32.408395 | **Longitude:** | -80.467293 | **Date Started:** | 11/16/2015 |
| **Total Depth:** | 150 ft | **Soil Depth:** | 150 ft | **Core Depth:** | 0 ft | **Date Completed:** | 11/17/2015 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 550X | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 74% |
| **Core Size:** | N/A | **Driller:** | Ameridrill | **Groundwater:** | **TOB** 4 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| -123.6 | | Very Stiff to Hard, Moist, Light Greenish Gray, Non-Plastic, Sandy SILT (ML/A-4(0)), Munsell=GLEY1 5GY 7/1 | | 130.0 | SS-65 | 3 | 4 | 13 | 46 | 17 |
| | | | | 132.0 | SS-66 | 8 | 14 | 31 | 32 | 45 |
| | | @SS-67: Stiff to Very Stiff | | | SS-67 | 3 | 5 | 5 | 12 | 10 |
| -128.6 | | | | 134.0 | SS-68 | 9 | 13 | 15 | 18 | 28 |
| | | | | 136.0 | SS-69 | 4 | 6 | 8 | 22 | 14 |
| | | | | 138.0 | SS-70 | 5 | 5 | 7 | 16 | 12 |
| -133.6 | | | | 140.0 | SS-71 | 5 | 9 | 12 | 16 | 21 |
| | | | | 142.0 | SS-72 | 5 | 4 | 5 | 16 | 9 |
| | | | | 144.0 | SS-73 | 5 | 11 | 17 | 25 | 28 |
| -138.6 | | | | 146.0 | SS-74 | 4 | 5 | 6 | 13 | 11 |
| | | | | 148.0 | SS-75 | 7 | 9 | 15 | 35 | 24 |
| -143.6 | 150.0 | Boring Terminated at 150.0 feet | | | | | | | | |
| -148.6 | | | | | | | | | | |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

## LEGEND


| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | SB-1 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | M. Miller | **Boring Location:** | 40+85 | **Offset:** | 293.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.8 ft | **Latitude:** | 32.408419 | **Longitude:** | -80.467258 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 520 ft | **Soil Depth:** | 520 ft | **Core Depth:** | 250 ft | **Date Completed:** | 7/14/2016 |
| **Bore Hole Diameter (in):** | 5 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Failing 1500 | **Drill Method:** | RW/RC | **Hammer Type:** | Automatic | **Energy Ratio:** | 75.4% |
| **Core Size:** | NQ | **Driller:** | Huss | **Groundwater:** | **TOB** 6 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | 0.0 | Gravel/Grassed Parking Area | | | | | | | | |
| | | **EMBANKMENT FILL** | | 0.0 | | | | | | |
| | | Medium Dense to Dense, Dry, Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4) with Gravel, Munsell=7.5YR 3/2 | | 2.0 | SS-1 | 8 | 12 | 13 | 13 | 25 |
| | | | | 4.0 | SS-2 | 11 | 14 | 17 | 18 | 31 |
| 1.8 | | ▽@SS-2: Brown, Munsell=10YR 5/3 | | 6.0 | SS-3 | 1 | 2 | 2 | 2 | 4 |
| | | @SS-3: No Recovery, Very Loose | | 8.0 | SS-4 | 1 | 3 | 7 | 13 | 10 |
| | | | | 10.0 | SS-5 | 6 | 9 | 12 | 11 | 21 |
| -3.2 | 10.0 | **ENGINEERED FILL** | | 12.0 | SS-6 | 3 | 3 | 2 | 2 | 5 |
| | | Loose, Wet, Gray, Non-Plastic, Silty Fine to Medium SAND (SM/A-2-4) with Trace of Shells, Munsell=5Y 5/1 | | 14.0 | SS-7 | 1 | 2 | 4 | 7 | 6 |
| -8.2 | 16.0 | | | 16.0 | SS-8 | 7 | 5 | 2 | 3 | 7 |
| | | **HOLOCENE** | | 18.0 | SS-9 | 1 | WOH/18" | | | WOH |
| | | Very Loose to Loose, Wet, Dark Gray, Non-Plastic, Silty Fine SAND (SM/A-2-4) with Trace of Shells, Munsell=5Y 4/1 | | 20.0 | SS-10 | 4 | 5 | 3 | 4 | 8 |
| -13.2 | | @SS-10: Organics=1.92% | | 22.0 | SS-11 | 8 | 5 | 5 | 7 | 10 |
| | | @SS-11: Gray, Fine to Medium Sand, Munsell=5Y 5/1 | | 24.0 | SS-12 | 2 | 2 | 8 | 5 | 10 |
| -18.2 | | | | 26.0 | SS-13 | 3 | 2 | 6 | 6 | 8 |
| | | @SS-14: Dark Olive Gray, Fine Sand, Munsell=5Y 3/2 | | 28.0 | SS-14 | 2 | WOH | 1 | 1 | 1 |
| | | @SS-15: Gray, Munsell=5Y 6/1 | | 30.0 | SS-15 | 1 | 1 | 7 | 15 | 8 |
| -23.2 | | @SS-16: Dense | | 32.0 | SS-16 | 7 | 18 | 21 | | 39 |
| | | @SS-17: Loose to Very Loose, Dark Gray, Fine to Coarse Sand, Munsell=5Y 4/1 | | 34.0 | SS-17 | 3 | 4 | 2 | 1 | 6 |
| -28.2 | | | | 36.0 | SS-18 | 1 | 2 | 1 | 2 | 3 |
| | | @SS-19: Organics =1.42% | | 38.0 | SS-19 | 2 | 2 | 2 | 1 | 4 |
| | | | | 40.0 | SS-20 | 2 | 2 | 2 | 4 | 4 |
| -33.2 | 40.0 | **HAWTHORN MARL** | | 42.0 | SS-21 | 1 | 1/12" | | 2 | 1 |
| | | Very Loose, Wet, Dark Gray, Non-Reactive to Weakly Reactive, High Plasticity, Clayey Fine SAND (SC/A-2-7(2)) with Trace of Shell Fragments, Munsell=GLEY1 4/N | | 44.0 | SS-22 | 1 | 1/12" | | 1 | 1 |
| -38.2 | | @SS-23: LL=42, PL=20, PI=22, NMC=55.4%, %#200=31.9 | | 46.0 | SS-23 | 1/12" | | 1 | 1 | 2 |
| | | | | 48.0 | SS-24 | WOH | 1 | 1 | 6 | 2 |
| | | @SS-25: Medium Dense, Gray, Strongly Reactive, Munsell=5Y 4/1 | | 50.0 | SS-25 | 7 | 7 | 6 | 2 | 13 |




*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | SB-1 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | M. Miller | **Boring Location:** | 40+85 | **Offset:** | 293.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.8 ft | **Latitude:** | 32.408419 | **Longitude:** | -80.467258 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 520 ft | **Soil Depth:** | 520 ft | **Core Depth:** | 250 ft | **Date Completed:** | 7/14/2016 |
| **Bore Hole Diameter (in):** | 5 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Failing 1500 | **Drill Method:** | RW/RC | **Hammer Type:** | Automatic | **Energy Ratio:** | 75.4% |
| **Core Size:** | NQ | **Driller:** | Huss | **Groundwater:** | **TOB** 6 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|
| | | Medium Dense to Loose, Wet, Olive, Non-Reactive, High Plasticity, Clayey Fine SAND (SC/A-2-7(2)) with Trace of Shell Fragments, Munsell=5Y 5/3 | 52.0 | SS-26 | 6 | 13 | 13 | 12 | 26 |
| | | | 54.0 | SS-27 | 2 | 4 | 4 | 5 | 8 |
| -48.2 | | @SS-27: Olive Gray, Munsell=5Y 4/2 | 56.0 | SS-28 | 3 | 4 | 4 | 6 | 8 |
| | | | 58.0 | SS-29 | 3 | 3 | 3 | 5 | 6 |
| | | | 60.0 | SS-30 | 2 | 2 | 3 | 4 | 5 |
| -53.2 | | @SS-31: Dark Olive Gray, Munsell=5Y 3/2 | 62.0 | SS-31 | 2 | 2 | 4 | 4 | 6 |
| | | | 64.0 | SS-32 | 2 | 3 | 5 | 5 | 8 |
| -58.2 | | @SS-33: Olive Gray, Munsell=5Y 4/2 | 66.0 | SS-33 | 3 | 4 | 6 | 6 | 10 |
| | | | 68.0 | SS-34 | 4 | 5 | 7 | 8 | 12 |
| | | | 70.0 | SS-35 | 4 | 4 | 5 | 7 | 9 |
| -63.2 | | | 72.0 | SS-36 | 4 | 5 | 6 | 7 | 11 |
| | | | 74.0 | SS-37 | 3 | 6 | 9 | 9 | 15 |
| -68.2 | | @SS-39: Dense | 76.0 | SS-38 | 5 | 8 | 19 | 50/1.5" | 27 |
| | 77.0 | **COOPER GROUP LIMESTONE** | 78.0 | SS-39 | 33 | 21 | 28 | 20 | 49 |
| | | Dense to Medium Dense, Wet, Light Greenish Gray, Non-Plastic, Non-Reactive, Silty Fine SAND (SM/A-4(0)), Munsell=GLEY1 7/10Y | | SS-40 | 2 | 6 | 11 | 13 | 17 |
| -73.2 | | | 83.5 | | | | | | |
| | | @SS-41: Loose | | SS-41 | 3 | 3 | 4 | | 7 |
| -78.2 | | | 88.5 | | | | | | |
| | | @SS-42: No Recovery | | SS-42 | 2 | 2 | 3 | | 5 |
| -83.2 | | | 93.5 | | | | | | |
| | | @SS-43: Weakly Reactive, LL=NP, PL=NP, PI=NP, NMC=44.7%, %#200=41.3 | | SS-43 | 6 | 4 | 2 | | 6 |
| -88.2 | | | 98.5 | | | | | | |
| | | @SS-44: Non-Reactive | | SS-44 | 4 | 4 | 5 | | 9 |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | SB-1 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | M. Miller | **Boring Location:** | 40+85 | **Offset:** | 293.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.8 ft | **Latitude:** | 32.408419 | **Longitude:** | -80.467258 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 520 ft | **Soil Depth:** | 520 ft | **Core Depth:** | 250 ft | **Date Completed:** | 7/14/2016 |
| **Bore Hole Diameter (in):** | 5 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Failing 1500 | **Drill Method:** | RW/RC | **Hammer Type:** | Automatic | **Energy Ratio:** | 75.4% |
| **Core Size:** | NQ | **Driller:** | Huss | **Groundwater:** | **TOB** 6 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | | @SS-45: Medium Dense to Loose | | 103.5 | SS-45 | 4 | 5 | 6 | | 11 |
| -98.2 | | | | 108.5 | SS-46 | 3 | 4 | 4 | | 8 |
| -103.2 | | | | 113.5 | SS-47 | 5 | 3 | 11 | | 17 |
| -108.2 | | | | 118.5 | SS-48 | 2 | 1 | 2 | | 3 |
| -113.2 | | @SS-48: Very Loose | | | | | | | | |
| | 122.0 | Firm, Wet, Light Greenish Gray, Medium Plasticity, Non-Reactive to Strongly Reactive, Fine Sandy SILT (ML/A-7-5(8)), Munsell=GLEY1 7/10Y | | 123.5 | SS-49 | 4 | 4 | 4 | | 8 |
| -118.2 | | @SS-50: Hard | | 128.5 | SS-50 | 15 | 33 | 50/3.5" | | 83+ |
| -123.2 | | @UD-1: LL=42, PL=30, PI=12, NMC=38.0%, %#200=66.3 | | 130.0 | UD-1 | %REC=100 | | | | |
| | | @SS-51: Stiff | | 133.5 | SS-51 | 5 | 6 | 7 | | 13 |
| -128.2 | | | | | | | | | | |
| | 138.5 | Very Stiff to Stiff, Wet, Light Greenish Gray, High Plasticity, Strongly Reactive, Fat CLAY (CH/A-7-6(33)), Munsell=GLEY1 7/10Y | | 138.5 | SS-52 | 12 | 12 | 8 | | 20 |
| -133.2 | | @SS-52: LL=63, PL=29, PI=34, NMC=68.0%, %#200=86.3 | | 143.5 | SS-53 | 4 | 5 | 5 | | 10 |
| -138.2 | 145.0 | Stiff, Wet, Light Greenish Gray, Medium Plasticity, Strongly Reactive, Sandy SILT (ML/A-6(6)), Munsell=GLEY1 7/10Y | | 145.0 | UD-2 | %REC=100 | | | | |
| | | @UD-2: LL=38, PI=25, PI=13, NMC=33.1%, | | 148.5 | SS-54 | 5 | 7 | 7 | | 14 |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | SB-1 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | M. Miller | **Boring Location:** | 40+85 | **Offset:** | 293.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.8 ft | **Latitude:** | 32.408419 | **Longitude:** | -80.467258 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 520 ft | **Soil Depth:** | 520 ft | **Core Depth:** | 250 ft | **Date Completed:** | 7/14/2016 |
| **Bore Hole Diameter (in):** | 5 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Failing 1500 | **Drill Method:** | RW/RC | **Hammer Type:** | Automatic | **Energy Ratio:** | 75.4% |
| **Core Size:** | NQ | **Driller:** | Huss | **Groundwater:** | **TOB** 6 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" | 2nd 6" | 3rd 6" | 4th 6" | N Value |
|---|---|---|---|---|---|---|---|---|---|---|
| | | %#200=57.3 | | | | | | | | |
| -148.2 | | Stiff, Wet, Light Greenish Gray, Medium Plasticity, Strongly Reactive, Sandy SILT (ML/A-6(6)), Munsell=GLEY1 7/10Y | | 158.5 | SS-55 | 4 | 4 | 5 | | 9 |
| -153.2 | | | | | | | | | | |
| -158.2 | 166.0 | | | | | | | | | |
| | | Loose to Medium Dense, Wet, Light Greenish Gray, Non-Plastic, Strongly Reactive, Silty Fine SAND (SM/A-4(0)), Munsell=GLEY1 7/10Y | | 168.5 | SS-56 | 6 | 8 | 10 | | 18 |
| -163.2 | | | | 170.0 | UD-3 | %REC=0 | | | | |
| -168.2 | | | | | | | | | | |
| | | @SS-57: LL=NP, PL=NP, PI=NP, NMC=32.9%, %#200=43.5 | | 178.5 | SS-57 | 8 | 12 | 15 | | 27 |
| -173.2 | | | | | | | | | | |
| -178.2 | | | | | | | | | | |
| | 188.5 | | | 188.5 | | | | | | |
| | | Firm to Stiff, Wet, Greenish Gray, Medium Plasticity, Strongly Reactive, Fine Sandy SILT (ML/A-7-6(6)), Munsell=GLEY1 6/10Y | | | SS-58 | 4 | 3 | 5 | | 8 |
| -183.2 | | | | | | | | | | |
| -188.2 | | | | 198.5 | | | | | | |
| | | | | 200.0 | SS-59 | 5 | 5 | 7 | | 12 |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | SB-1 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | M. Miller | **Boring Location:** | 40+85 | **Offset:** | 293.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.8 ft | **Latitude:** | 32.408419 | **Longitude:** | -80.467258 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 520 ft | **Soil Depth:** | 520 ft | **Core Depth:** | 250 ft | **Date Completed:** | 7/14/2016 |
| **Bore Hole Diameter (in):** | 5 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Failing 1500 | **Drill Method:** | RW/RC | **Hammer Type:** | Automatic | **Energy Ratio:** | 75.4% |
| **Core Size:** | NQ | **Driller:** | Huss | **Groundwater:** | **TOB** 6 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" 2nd 6" 3rd 6" 4th 6" | N Value |
|---|---|---|---|---|---|---|
| -198.2 | | Stiff to Very Stiff, Wet, Greenish Gray, Medium Plasticity, Strongly Reactive, Fine Sandy SILT (ML/A-7-6(6)), Munsell=GLEY1 6/10 | | UD-4 | %REC=95 | |
| | | @UD-4: LL=43, PL=27, PI=16, NMC=32.0%, %#200=52.1 | 208.5 | | | |
| -203.2 | | | | SS-60 | 5 7 9 | 16 |
| -208.2 | | | 218.5 | | | |
| -213.2 | | | | SS-61 | 5 6 6 | 12 |
| | 221.0 | Very Stiff to Hard, Wet, Greenish Gray, Medium Plasticity, Strongly Reactive, SILT (ML/A-7-5(15)) with Sand, Munsell=GLEY1 6/10Y | | | | |
| -218.2 | | | 228.5 | | | |
| | | | 230.0 | SS-62 | 11 12 21 | 33 |
| -223.2 | | @UD-5: LL=48, PL=30, PI=18, NMC=32.6%, %#200=77.7 | | UD-5 | %REC=99 | |
| -228.2 | | | | | | |
| | 238.5 | Very Stiff to Hard, Wet, Greenish Gray, Medium Plasticity, Strongly Reactive, Lean CLAY (CL/A-6(16)), Munsell=GLEY1 6/10Y | 238.5 | | | |
| | | | | SS-63 | 8 9 12 | 21 |
| -233.2 | | @SS-63: LL=40, PL=23, PI=17, NMC=34.4%, %#200=87.8 | | | | |
| -238.2 | | | 248.5 | | | |
| | 250.0 | | 250.0 | SS-64 | 26 39 34 | 73 |

SPT N VALUE

PL MC LL

FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | SB-1 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | M. Miller | **Boring Location:** | 40+85 | **Offset:** | 293.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.8 ft | **Latitude:** | 32.408419 | **Longitude:** | -80.467258 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 520 ft | **Soil Depth:** | 520 ft | **Core Depth:** | 250 ft | **Date Completed:** | 7/14/2016 |
| **Bore Hole Diameter (in):** | 5 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Failing 1500 | **Drill Method:** | RW/RC | **Hammer Type:** | Automatic | **Energy Ratio:** | 75.4% |
| **Core Size:** | NQ | **Driller:** | Huss | **Groundwater:** | **TOB** 6 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|
| | | **END ROTARY WASH BORING. START NQ CORING** | | | | | | |
| | | **COOPER GROUP LIMESTONE** | | | | | | |
| | | Greenish Gray, Very Plastic, Weakly to Strongly Reactive, Sandy Fat CLAY (CH/A-7-6(34)), Munsell=GLEY1 5/5GY | | | | | | |
| -248.2 | | @252.6': UC Strength=143.5 psi | | 255.0 | NQ-1 | | | |
| | | | | 257.0 | NQ-2 | | | |
| | | @UD-6: LL=76, PL=21, PI=55, NMC=31.6%, %#200=65.1 | | | UD-6 | %REC=100 | | |
| -253.2 | | | | 260.0 | NQ-3 | | | |
| -258.2 | | | | 265.0 | NQ-4 | | | |
| -263.2 | | | | 270.0 | NQ-5 | | | |
| -268.2 | 275.0 | Wet to Moist, Greenish Gray, Low Plasticity, Strongly Reactive, SILT (ML/A-4(1)) with Fine Sand, Munsell=GLEY1 5/5GY | | 275.0 | NQ-6 | | | |
| | | @NQ-6: LL=32, PL=30, PI=2, NMC=30.1%, %#200=71.3 | | 277.0 | UD-7 | %REC=100 | | *Pitcher Barrel Crimped, Damaged* |
| -273.2 | | | | 280.0 | NQ-7 | | | *Sample* |
| -278.2 | | | | 285.0 | NQ-8 | | | |
| -283.2 | | | | 290.0 | NQ-9 | | | |
| -288.2 | | | | 295.0 | NQ-10 | | | |
| | | | | 297.0 | | | | |
| | | | | 298.0 | UD-8 | %REC=100 | | *Encountered Refusal at 12"* |
| | | @299.2': UC Strength=166.5 psi | | | | | | |

LEGEND

*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | SB-1 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | M. Miller | **Boring Location:** | 40+85 | **Offset:** | 293.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.8 ft | **Latitude:** | 32.408419 | **Longitude:** | -80.467258 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 520 ft | **Soil Depth:** | 520 ft | **Core Depth:** | 250 ft | **Date Completed:** | 7/14/2016 |
| **Bore Hole Diameter (in):** | 5 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Failing 1500 | **Drill Method:** | RW/RC | **Hammer Type:** | Automatic | **Energy Ratio:** | 75.4% |
| **Core Size:** | NQ | **Driller:** | Huss | **Groundwater:** | **TOB** 6 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value |
|---|---|---|---|---|---|---|
| | 303.0 | Wet to Moist, Greenish Gray, Low Plasticity, Strongly Reactive, SILT (ML/A-4(1)) with Fine Sand, Munsell=GLEY1 5/5GY | 303.0 | NQ-11 | | |
| -298.2 | | Wet to Moist, Greenish Gray, Low Plasticity, Strongly Reactive, Gravelly SILT (ML/A-4(1)) with Sand, Munsell=GLEY1 5/5GY<br>@NQ-12: LL=37, PL=34, PI=3, NMC=30.3%, %#200=53.3 | 308.0 | NQ-12 | | |
| -303.2 | | | | NQ-13 | | |
| -308.2 | | | 313.0 | NQ-14 | | |
| -313.2 | | | 318.0 | NQ-15 | | |
| -318.2 | | @324.3': UC Strength=85.9 psi | 323.0 | NQ-16 | | |
| -323.2 | | @NQ-17: Moderately Reactive | 328.0 | NQ-17 | | |
| -328.2 | | | 333.0 | NQ-18 | | |
| -333.2 | | @NQ-19: Medium Plasticity, Strongly Reactive, A-6(12)), LL=40, PL=26, PI=14, NMC=25.9%, %#200=82.9 | 338.0 | NQ-19 | | |
| -338.2 | | | 343.0 | NQ-20 | | |
| | | | 348.0 | | | |

SPT N VALUE: PL, MC, LL

FINES CONTENT (%): 0 10 20 30 40 50 60 70 80 90

*Continued Next Page*


LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | SB-1 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | M. Miller | **Boring Location:** | 40+85 | **Offset:** | 293.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.8 ft | **Latitude:** | 32.408419 | **Longitude:** | -80.467258 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 520 ft | **Soil Depth:** | 520 ft | **Core Depth:** | 250 ft | **Date Completed:** | 7/14/2016 |
| **Bore Hole Diameter (in):** | 5 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Failing 1500 | **Drill Method:** | RW/RC | **Hammer Type:** | Automatic | **Energy Ratio:** | 75.4% |
| **Core Size:** | NQ | **Driller:** | Huss | **Groundwater:** | **TOB** 6 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value |
|---|---|---|---|---|---|---|---|
| | | Wet to Moist, Greenish Gray, Low Plasticity, Strongly Reactive, Gravelly SILT (ML/A-4(1)) with Sand, Munsell=GLEY1 5/5GY | | 353.0 | NQ-21 | | |
| -348.2 | | | | | NQ-22 | | |
| | 358.0 | Wet to Moist, Greenish Gray, Low Plasticity, Strongly Reactive, Sandy SILT (ML/A-4(4)), Munsell=GLEY1 5/5GY | | 358.0 | | | |
| -353.2 | | @NQ-23: LL=33, PL=24, PI=9, NMC=17.4%, %#200=64.6 | | | NQ-23 | | |
| | | @359.0': UC Strength=236.4 psi | | 363.0 | | | |
| -358.2 | | | | | NQ-24 | | |
| | | | | 368.0 | | | |
| -363.2 | | | | | NQ-25 | | |
| | 373.0 | Wet to Moist, Greenish Gray, Very Plastic, Strongly Reactive, Fat CLAY (CH/A-7-6(104)), Munsell=GLEY1 5/5GY | | 373.0 | | | |
| -368.2 | | | | | NQ-26 | | |
| | | @UD-9: LL=133, PL=29, PI=104, NMC=39.3%, %#200=87.8 | | 378.0 | | | |
| -373.2 | | | | | UD-9 | %REC=100 | |
| | 381.0 | **OCALA LIMESTONE** | | 381.0 | | | |
| | | Wet to Moist, Greenish Gray, High Plasticity, Strongly Reactive, Elastic SILT (MH/A-7-5(31)), Munsell=GLEY1 5/5GY | | | NQ-27 | | |
| -378.2 | | @NQ-27: LL=63, PL=38, PI=25, NMC=38.3%, %#200=94.7 | | 385.0 | | | |
| | | @381.3': UC Strength=233.5 psi | | | NQ-28 | | |
| -383.2 | | | | 390.0 | | | |
| | | | | | NQ-29 | | |
| -388.2 | | | | 395.0 | | | |
| | | | | | NQ-30 | | |
| | | | | 400.0 | | | |




*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | **County:** | Beaufort | **Boring No.:** | SB-1 | | |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | **Route:** | US 21 | | |
| **Eng./Geo.:** | M. Miller | **Boring Location:** | 40+85 | **Offset:** | 293.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.8 ft | **Latitude:** | 32.408419 | **Longitude:** | -80.467258 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 520 ft | **Soil Depth:** | 520 ft | **Core Depth:** | 250 ft | **Date Completed:** | 7/14/2016 |
| **Bore Hole Diameter (in):** | 5 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Failing 1500 | **Drill Method:** | RW/RC | **Hammer Type:** | Automatic | **Energy Ratio:** | 75.4% |
| **Core Size:** | NQ | **Driller:** | Huss | **Groundwater:** | **TOB** 6 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value | ● SPT N VALUE ● PL MC LL ▲ FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|
| | | Wet to Moist, Greenish Gray, High Plasticity, Strongly Reactive, Elastic SILT (MH/A-7-5(31)), Munsell=GLEY1 5/5GY | | 405.0 | NQ-31 | | | |
| -398.2 | | | | | | | | |
| | | | | 410.0 | NQ-32 | | | |
| -403.2 | | | | | | | | |
| | | | | 415.0 | NQ-33 | | | |
| -408.2 | | | | | | | | |
| | | | | 420.0 | NQ-34 | | | |
| -413.2 | | | | | | | | |
| | | | | 425.0 | NQ-35 | | | |
| -418.2 | | | | | | | | |
| | | | | 430.0 | NQ-36 | | | |
| -423.2 | | | | | | | | |
| | | | | 435.0 | NQ-37 | | | |
| -428.2 | | | | | | | | |
| | 440.0 | | | 440.0 | NQ-38 | | | |
| -433.2 | | Wet to Moist, Greenish Gray, Low Plasticity, Strongly Reactive, Fine Sandy SILT (ML/A-4) | | | | | | |
| | | | | 445.0 | NQ-39 | | | |
| -438.2 | | | | | | | | |
| | | | | 450.0 | NQ-40 | | | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | SB-1 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | M. Miller | **Boring Location:** | 40+85 | **Offset:** | 293.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.8 ft | **Latitude:** | 32.408419 | **Longitude:** | -80.467258 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 520 ft | **Soil Depth:** | 520 ft | **Core Depth:** | 250 ft | **Date Completed:** | 7/14/2016 |
| **Bore Hole Diameter (in):** | 5 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Failing 1500 | **Drill Method:** | RW/RC | **Hammer Type:** | Automatic | **Energy Ratio:** | 75.4% |
| **Core Size:** | NQ | **Driller:** | Huss | **Groundwater:** | **TOB** 6 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|
| | | Wet to Moist, Greenish Gray, Low Plasticity, Strongly Reactive, Fine Sandy SILT (ML/A-4) | | 455.0 | NQ-41 | | | |
| -448.2 | | | | | | | | |
| | | | | 460.0 | NQ-42 | | | |
| -453.2 | | | | | | | | |
| | | | | 465.0 | NQ-43 | | | |
| -458.2 | | | | | | | | |
| | | | | 470.0 | NQ-44 | | | |
| -463.2 | | | | | | | | |
| | | | | 475.0 | NQ-45 | | | |
| -468.2 | | | | | | | | |
| | | | | 480.0 | NQ-46 | | | |
| -473.2 | | | | | | | | |
| | | | | 485.0 | NQ-47 | | | |
| -478.2 | | | | | | | | |
| | | | | 490.0 | NQ-48 | | | |
| -483.2 | 490.0 | **SANTEE LIMESTONE** | | | | | | |
| | | Wet to Moist, Greenish Gray, Low Plasticity, Strongly Reactive, Fine Sandy SILT (ML/A-4) | | | NQ-49 | | | |
| -488.2 | | | | 495.0 | | | | |
| | | | | | NQ-50 | | | |
| | 500.0 | | | | | | | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | SB-1 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | M. Miller | **Boring Location:** | 40+85 | **Offset:** | 293.6'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 6.8 ft | **Latitude:** | 32.408419 | **Longitude:** | -80.467258 | **Date Started:** | 7/6/2016 |
| **Total Depth:** | 520 ft | **Soil Depth:** | 520 ft | **Core Depth:** | 250 ft | **Date Completed:** | 7/14/2016 |
| **Bore Hole Diameter (in):** | 5 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | Failing 1500 | **Drill Method:** | RW/RC | **Hammer Type:** | Automatic | **Energy Ratio:** | 75.4% |
| **Core Size:** | NQ | **Driller:** | Huss | **Groundwater:** | **TOB** 6 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|
| | | Core Sampling Terminated at 500 feet. Borehole advanced to 520 feet using roller cone to facilitate geophysical testing. | | | | | | |
| -498.2 | | | | | | | | |
| -503.2 | | | | | | | | |
| -508.2 | | | | | | | | |
| -513.2 | 520.0 | Boring Terminated at 520.0 feet | | | | | | |
| -518.2 | | | | | | | | |
| -523.2 | | | | | | | | |
| -528.2 | | | | | | | | |
| -533.2 | | | | | | | | |
| -538.2 | | | | | | | | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | AP-1 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 65+07 | **Offset:** | 7.2'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.5 ft | **Latitude:** | 32.406761 | **Longitude:** | -80.459581 | **Date Started:** | 7/27/2016 |
| **Total Depth:** | 20 ft | **Soil Depth:** | 20 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/27/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value |
|---|---|---|---|---|---|---|---|
| | 0.0 | ▽Marsh | | | | | |
| | | DRILL TO 16.0 FEET | | | | | |
| -2.5 | | | | | | | |
| -7.5 | | | | | | | |
| -12.5 | | | | | | | |
| | 16.0 | Wet, Very Dark Gray, Very Plastic, Sandy Fat CLAY (CH/A-7-6(24)), Munsell=5Y 3/1, LL=65, PL=21, PI=44, NMC=63.0%, %#200=61.0 | | 16.0 | UD-1 | %REC=100 | |
| | 18.0 | Wet, Very Dark Gray, Very Plastic, Fat CLAY (CH/A-7-5(60)) with Sand, Munsell=5Y 3/1, LL=111, PL=34, PI=77, NMC=86.3%, %#200=73.3 | | 18.0 | UD-2 | %REC=100 | |
| -17.5 | 20.0 | Boring Terminated at 20.0 Feet | | | | | |

● SPT N VALUE ●

PL MC LL

▲ FINES CONTENT (%)

0 10 20 30 40 50 60 70 80 90

11

## LEGEND


| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | AP-2 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 67+03 | **Offset:** | 15.9'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.6 ft | **Latitude:** | 32.406601 | **Longitude:** | -80.458973 | **Date Started:** | 7/28/2016 |
| **Total Depth:** | 20 ft | **Soil Depth:** | 20 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/28/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value |
|---|---|---|---|---|---|---|---|
| | 0.0 | ▽Marsh | | | | | |
| | | DRILL TO 16.0 FEET | | | | | |
| -2.4 | | | | | | | |
| -7.4 | | | | | | | |
| -12.4 | | | | | | | |
| | 16.0 | Wet, Very Dark Gray, Very Plastic, Clayey SAND (SC/A-7-6(17)), Munsell=5Y 3/1, LL=66, PL=22, PI=44, NMC=56.0%, %#200=49.9 | | 16.0 | UD-1 | %REC=100 | |
| | 18.0 | Wet, Very Dark Gray, Very Plastic, Sandy Fat CLAY (CH/A-7-6(33)), Munsell=5Y 3/1, LL=81, PL=27, PI=54, NMC=69.3%, %#200=63.5 | | 18.0 | UD-2 | %REC=100 | |
| -17.4 | 20.0 | Boring Terminated at 20.0 Feet | | | | | |




## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | AP-3 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 69+09 | **Offset:** | 39.8'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.0 ft | **Latitude:** | 32.406462 | **Longitude:** | -80.458322 | **Date Started:** | 7/28/2016 |
| **Total Depth:** | 29 ft | **Soil Depth:** | 29 ft | **Core Depth:** | N/A ft | **Date Completed:** | 7/28/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) |
|---|---|---|---|---|---|---|---|---|
| | 0.0 | ▽Marsh<br>DRILL TO 25.0 FEET | | | | | | |
| -3.0 | | | | | | | | |
| -8.0 | | | | | | | | |
| -13.0 | | | | | | | | |
| -18.0 | | | | | | | | |
| -23.0 | 25.0 | Wet, Very Dark Gray, Very Plastic, Fat CLAY (CH/A-7-6(50)) with Sand, Munsell=5Y 3/1, LL=85, PL=27, PI=58, NMC=83.0%, %#200=79.5 | | 25.0 | UD-1 | %REC=100 | | |
| | 27.0 | Wet, Very Dark Gray, Very Plastic, Fat CLAY (CH/A-7-6(43)) with Sand, Munsell=5Y 3/1, LL=74, PL=25, PI=49, NMC=78.8%, %#200=81.4 | | 27.0 | UD-2 | %REC=100 | | |
| -28.0 | 29.0 | Boring Terminated at 29.0 Feet | | | | | | |

FINES CONTENT (%): 0 10 20 30 40 50 60 70 80 90

## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | AP-4 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 100+73 | **Offset:** | 8.7'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 1.6 ft | **Latitude:** | 32.403021 | **Longitude:** | -80.448901 | **Date Started:** | 8/4/2016 |
| **Total Depth:** | 74 ft | **Soil Depth:** | 74 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/4/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value | ● SPT N VALUE ● PL MC LL ▲ FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|
| | 0.0 | ▽Marsh<br>DRILL TO 38.0 FEET | | | | | | |
| -3.4 | | | | | | | | |
| -8.4 | | | | | | | | |
| -13.4 | | | | | | | | |
| -18.4 | | | | | | | | |
| -23.4 | | | | | | | | |
| -28.4 | | | | | | | | |
| -33.4 | | | | | | | | |
| | 38.0 | | | 38.0 | | | | |
| -38.4 | 40.0 | Wet, Dark Gray, Very Plastic, Fat CLAY (CH/A-7-6(34)) with Sand, Munsell=GLEY1 4/N, LL=71, PL=24, PI=47, NMC=69.0%, %#200=71.3 | | 40.0 | UD-1 | %REC=60 | | |
| | 42.0 | | | | UD-2 | %REC=100 | | |
| -43.4 | | Wet, Dark Gray, Non-Plastic, Silty Fine to Medium SAND (SM/A-2-4), Munsell=GLEY1 4/N, LL=NP, PL=NP, PI=NP, NMC=33.8%, %#200=21.5<br>DRILL TO 70.0 FEET | | | | | | |

*Continued Next Page*

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | AP-4 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 100+73 | **Offset:** | 8.7'-RT | **Alignment:** | ALT 1B |
| **Elev.:** | 1.6 ft | **Latitude:** | 32.403021 | **Longitude:** | -80.448901 | **Date Started:** | 8/4/2016 |
| **Total Depth:** | 74 ft | **Soil Depth:** | 74 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/4/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value | ● SPT N VALUE ● PL MC LL ▲ FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|
| | | DRILL TO 70.0 FEET | | | | | | |
| -53.4 | | | | | | | | |
| -58.4 | | | | | | | | |
| -63.4 | | | | | | | | |
| -68.4 | 70.0 | | | 70.0 | | | | |
| | 72.0 | Wet, Olive Gray, Non-Plastic, Sandy Fine SILT (ML/A-4(0)), Munsell=5Y 4/2, LL=NP, PL=NP, PI=NP, NMC=58.8%, %#200=52.0 | | 72.0 | UD-3 | %REC=100 | × | ▲ ○ |
| | 74.0 | | | | UD-4 | %REC=100 | | |
| -73.4 | | Wet, Olive Gray, Non-Plastic, Sandy Fine SILT (ML/A-4(0)), Munsell=5Y 4/2 | | | | | | |
| | | Boring Terminated at 74.0 feet | | | | | | |
| -78.4 | | | | | | | | |
| -83.4 | | | | | | | | |
| -88.4 | | | | | | | | |
| -93.4 | | | | | | | | |

LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

SC_DOT G5396 - HARBOR RIVER SPT AND CPT.GPJ FME2017.GDT 2/14/17

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | AP-5 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 106+03 | **Offset:** | 26.3'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.3 ft | **Latitude:** | 32.402547 | **Longitude:** | -80.44727 | **Date Started:** | 8/2/2016 |
| **Total Depth:** | 32 ft | **Soil Depth:** | 32 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/2/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" 2nd 6" 3rd 6" 4th 6" | N Value | SPT N VALUE / PL MC LL / FINES CONTENT (%) 0 10 20 30 40 50 60 70 80 90 |
|---|---|---|---|---|---|---|---|---|
| | 0.0 | ▽Marsh<br>DRILL TO 6.0 FEET | | | | | | |
| -2.7 | 6.0 | Wet, Gray, Non-Plastic, Poorly Graded Fine SAND (SP/A-3), Munsell=5Y 6/1, LL=NP, PL=NP, PI=NP, NMC=21.6%, %#200=3.0 | | 6.0 | UD-1 | %REC=80 | | |
| | 8.0 | Wet, Gray, Non-Plastic, Poorly Graded Fine SAND (SP/A-3), Munsell=5Y 6/1 | | 8.0 | UD-2 | %REC=60 | | |
| -7.7 | 10.0 | DRILL TO 28.0 FEET | | | | | | |
| -12.7 | | | | | | | | |

LEGEND


*Continued Next Page*

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

# SCDOT Soil Test Log

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Project ID:** | P026862 | | | **County:** | Beaufort | **Boring No.:** | AP-5 |
| **Site Description:** | US 21 Bridge Replacement over Harbor River | | | | | **Route:** | US 21 |
| **Eng./Geo.:** | C. Piercy | **Boring Location:** | 106+03 | **Offset:** | 26.3'-LT | **Alignment:** | ALT 1B |
| **Elev.:** | 2.3 ft | **Latitude:** | 32.402547 | **Longitude:** | -80.44727 | **Date Started:** | 8/2/2016 |
| **Total Depth:** | 32 ft | **Soil Depth:** | 32 ft | **Core Depth:** | N/A ft | **Date Completed:** | 8/2/2016 |
| **Bore Hole Diameter (in):** | 4 | **Sampler Configuration** | | **Liner Required:** | Y (N) | **Liner Used:** | Y (N) |
| **Drill Machine:** | CME 45B | **Drill Method:** | RW | **Hammer Type:** | Automatic | **Energy Ratio:** | 83.1% |
| **Core Size:** | N/A | **Driller:** | M.A.D. | **Groundwater:** | **TOB** 0 ft | **24HR** | TIDAL |

| Elevation (ft) | Depth (ft) | MATERIAL DESCRIPTION | Graphic Log | Sample Depth (ft) | Sample No./Type | 1st 6" / 2nd 6" / 3rd 6" / 4th 6" | N Value |
|---|---|---|---|---|---|---|---|
| | | DRILL TO 28.0 FEET | | | | | |
| -17.7 | | | | | | | |
| -22.7 | | | | | | | |
| | 28.0 | Wet, Gray, Non-Plastic, Poorly Graded Fine SAND (SP/A-3), Munsell=5Y 5/1 | | 28.0 | UD-3 | %REC=100 | |
| -27.7 | 30.0 | Wet, Gray, Non-Plastic, Poorly Graded Fine SAND (SP/A-3), Munsell=5Y 5/1, LL=NP, PL=NP, PI=NP, NMC=26.6%, %#200=2.9 | | 30.0 | UD-4 | %REC=100 | |
| | 32.0 | Boring Terminated at 32.0 feet | | | | | |
| -32.7 | | | | | | | |




## LEGEND

| SAMPLER TYPE | | DRILLING METHOD | |
|---|---|---|---|
| SS - Split Spoon | NQ - Rock Core, 1-7/8" | HSA - Hollow Stem Auger | RW - Rotary Wash |
| UD - Undisturbed Sample | CU - Cuttings | CFA - Continuous Flight Augers | RC - Rock Core |
| AWG - Rock Core, 1-1/8" | CT - Continuous Tube | DC - Driving Casing | |

F&ME CONSULTANTS

**US 21 Bridge Replacement over Harbor River**
**Beaufort County, South Carolina**
Project Number :P026862


# Cone Penetration Test

**CPT-1**

**Date:** Aug. 26, 2014
**Estimated Water Depth:** 6 ft
**Rig/Operator:** Conetec

**Station:** 13+72
**Offset:** 7.0'-LT
**Elevation:** 8.5

**Total Depth:** 127.5 ft
**Termination Criteria:** Target Depth
**Cone Size:**




CPT REPORT - DYNAMIC G5396 - HARBOR RIVER SPT AND CPT.GPJ CPT TEST.GPJ 11/1/16

**CPT-1**



*Electronic File Name: 14-54074_CP01.cor*

F&ME CONSULTANTS

US 21 Bridge Replacement over Harbor River
Beaufort County, South Carolina
Project Number :P026862


# Cone Penetration Test

# SCPT-2

**Date:** Aug. 25, 2014
**Estimated Water Depth:** 8 ft
**Rig/Operator:** Conetec

**Station:** 62+99
**Offset:** 27.1'-RT
**Elevation:** 10.7

**Total Depth:** 88.9 ft
**Termination Criteria:** Maximum Reaction Force
**Cone Size:**




CPT REPORT - STANDARD G5396 - HARBOR RIVER SPT AND CPT.GPJ CPT TEST.GPJ 11/3/16



SCPT-2

Electronic File Name: 14-54074_SP02.cor

F&ME CONSULTANTS

US 21 Bridge Replacement over Harbor River
Beaufort County, South Carolina
Project Number :P026862


# Cone Penetration Test

**CPT-3**

**Date:** Sep. 23, 2015
**Estimated Water Depth:** 0 ft
**Rig/Operator:** M.A.D.

**Station:** 42+42
**Offset:** 96.4'-LT
**Elevation:** 2.4

**Total Depth:** 70.5 ft
**Termination Criteria:** Maximum Reaction Force
**Cone Size:**




CPT REPORT - STANDARD G5396 - HARBOR RIVER SPT AND CPT.GPJ CPT TEST.GPJ 10/6/16

**CPT-3**



*Electronic File Name: Habor River Hwy 21 CPT-03.cpt*


F&ME CONSULTANTS

US 21 Bridge Replacement over Harbor River
Beaufort County, South Carolina
Project Number :P026862

# Cone Penetration Test

**CPT-4**

| | | | | | |
|---|---|---|---|---|---|
| **Date:** | Sep. 23, 2015 | **Station:** | 49+36 | **Total Depth:** | 75.5 ft |
| **Estimated Water Depth:** | 0 ft | **Offset:** | 76.2'-LT | **Termination Criteria:** | Maximum Reaction Force |
| **Rig/Operator:** | M.A.D. | **Elevation:** | 1.6 | **Cone Size:** | |




CPT REPORT - STANDARD G5396 - HARBOR RIVER SPT AND CPT.GPJ CPT TEST.GPJ 10/6/16



**CPT-4**

Electronic File Name: Habor River Hwy 21 CPT-04.cpt

F&ME CONSULTANTS

US 21 Bridge Replacement over Harbor River
Beaufort County, South Carolina
Project Number :P026862


# Cone Penetration Test

**CPT-5**

**Date:** Sep. 24, 2015
**Estimated Water Depth:** 0 ft
**Rig/Operator:** M.A.D.

**Station:** 60+88
**Offset:** 78.7'-LT
**Elevation:** 2.5

**Total Depth:** 75.0 ft
**Termination Criteria:** Maximum Reaction Force
**Cone Size:**




**CPT-5**



*Electronic File Name: Habor River Hwy 21 CPT-05.cpt*

CPT REPORT - STANDARD G5396 - HARBOR RIVER SPT AND CPT.GPJ CPT TEST.GPJ 10/6/16


F&ME CONSULTANTS

US 21 Bridge Replacement over Harbor River
Beaufort County, South Carolina
Project Number :P026862

# Cone Penetration Test

**CPT-6**

| | | | | | |
|---|---|---|---|---|---|
| **Date:** | Sep. 24, 2015 | **Station:** | 69+12 | **Total Depth:** | 82.0 ft |
| **Estimated Water Depth:** | 0 ft | **Offset:** | 41.6'-LT | **Termination Criteria:** | Maximum Reaction Force |
| **Rig/Operator:** | M.A.D. | **Elevation:** | 2.0 | **Cone Size:** | |




**CPT-6**



*Electronic File Name: Habor River Hwy 21 CPT-06.cpt*

CPT REPORT - STANDARD G5396 - HARBOR RIVER SPT AND CPT.GPJ CPT TEST.GPJ 10/6/16


F&ME CONSULTANTS

US 21 Bridge Replacement over Harbor River
Beaufort County, South Carolina
Project Number :P026862

# Cone Penetration Test

**CPT-7**

| | | | | | |
|---|---|---|---|---|---|
| **Date:** | Sep. 22, 2015 | **Station:** | 100+84 | **Total Depth:** | 79.9 ft |
| **Estimated Water Depth:** | 0 ft | **Offset:** | 1.9'-LT | **Termination Criteria:** | Maximum Reaction Force |
| **Rig/Operator:** | M.A.D. | **Elevation:** | 1.7 | **Cone Size:** | |




**CPT-7**



*Electronic File Name: Habor River Hwy 21 CPT-07.cpt*

CPT REPORT - STANDARD G5396 - HARBOR RIVER SPT AND CPT.GPJ CPT TEST.GPJ 10/6/16


F&ME CONSULTANTS

US 21 Bridge Replacement over Harbor River
Beaufort County, South Carolina
Project Number :P026862

# Cone Penetration Test

**CPT-8**

| | | | | | |
|---|---|---|---|---|---|
| **Date:** | Sep. 22, 2015 | **Station:** | 103+87 | **Total Depth:** | 66.6 ft |
| **Estimated Water Depth:** | 0 ft | **Offset:** | 15.3'-RT | **Termination Criteria:** | Maximum Reaction Force |
| **Rig/Operator:** | M.A.D. | **Elevation:** | 2.2 | **Cone Size:** | |




CPT REPORT - STANDARD G5396 - HARBOR RIVER SPT AND CPT.GPJ CPT TEST.GPJ 10/6/16



**CPT-8**

*Electronic File Name: Habor River Hwy 21 CPT-08.cpt*


F&ME CONSULTANTS

US 21 Bridge Replacement over Harbor River
Beaufort County, South Carolina
Project Number :P026862

# Cone Penetration Test

**CPT-9**

| | | | | | |
|---|---|---|---|---|---|
| **Date:** | Sep. 22, 2015 | **Station:** | 116+53 | **Total Depth:** | 79.6 ft |
| **Estimated Water Depth:** | 0 ft | **Offset:** | 42.4'-LT | **Termination Criteria:** | Maximum Reaction Force |
| **Rig/Operator:** | M.A.D. | **Elevation:** | 2.4 | **Cone Size:** | |




CPT REPORT - STANDARD G5396 - HARBOR RIVER SPT AND CPT.GPJ CPT TEST.GPJ 10/6/16

**CPT-9**



*Electronic File Name: Habor River Hwy 21 CPT-09.cpt*

F&ME CONSULTANTS

US 21 Bridge Replacement over Harbor River
Beaufort County, South Carolina
Project Number :P026862


# Cone Penetration Test

# CPT-10

**Date:** Sep. 23, 2015
**Estimated Water Depth:** 0 ft
**Rig/Operator:** M.A.D.

**Station:** 120+07
**Offset:** 49.3'-LT
**Elevation:** 2.4

**Total Depth:** 80.2 ft
**Termination Criteria:** Maximum Reaction Force
**Cone Size:**




CPT REPORT - STANDARD G5396 - HARBOR RIVER SPT AND CPT.GPJ CPT TEST.GPJ 10/6/16



CPT-10

Electronic File Name: Habor River Hwy 21 CPT-10.cpt

F&ME CONSULTANTS

**US 21 Bridge Replacement over Harbor River**
**Beaufort County, South Carolina**
Project Number :P026862


# Cone Penetration Test

# SCPT-11

**Date:** Nov. 18, 2015
**Estimated Water Depth:** 4 ft
**Rig/Operator:** Conetec

**Station:** 40+89
**Offset:** 292.5'-RT
**Elevation:** 6.4

**Total Depth:** 101.1 ft
**Termination Criteria:** Maximum Reaction Force
**Cone Size:**




CPT REPORT - STANDARD G5396 - HARBOR RIVER SPT AND CPT.GPJ CPT TEST.GPJ 11/3/16



SCPT-11

*Electronic File Name: 15-54107_SP SCPT-11.cor*

GEOVision
geophysical services

# HARBOR RIVER

# BOREHOLE GEOPHYSICS

# BEAUFORT, SOUTH CAROLINA

# BOREHOLE SB-1

**August 24, 2016**
**Report 16248-01 rev 0**

# HARBOR RIVER

# BOREHOLE GEOPHYSICS

# BEAUFORT, SOUTH CAROLINA

# BOREHOLE SB-1

**Prepared for**

**F&ME Consultants, Inc.**
**3112 Devine St., #B**
**Columbia, South Carolina 29205**
**(803) 254-4540**

**Prepared by**

**GEO*Vision* Geophysical Services**
**1124 Olympic Drive**
**Corona, California 92881**
**(951) 549-1234**
**Project 16248**

**August 24, 2016**
**Report 16248-01 rev 0**

# TABLE OF CONTENTS

**TABLE OF CONTENTS** ..... **3**

**TABLE OF FIGURES** ..... **4**

**TABLE OF TABLES** ..... **4**

**APPENDICES** ..... **5**

**INTRODUCTION** ..... **6**

**SCOPE OF WORK** ..... **6**

**INSTRUMENTATION** ..... **7**

Suspension Velocity Instrumentation ..... 7
Caliper / Natural Gamma Instrumentation ..... 10
Elog / Natural Gamma Instrumentation ..... 11

**MEASUREMENT PROCEDURES** ..... **13**

Suspension Velocity Measurement Procedures ..... 13
Caliper / Natural Gamma Measurement Procedures ..... 13
Elog / Natural Gamma Measurement Procedures ..... 15

**DATA ANALYSIS** ..... **18**

Suspension Velocity Analysis ..... 18
Caliper / Natural Gamma ..... 20
Elog / Natural Gamma Analysis ..... 20

**RESULTS** ..... **21**

Suspension Velocity Results ..... 21
Caliper / Natural Gamma Results ..... 21
Elog / Natural Gamma Results ..... 22

**SUMMARY** ..... **23**

Discussion of Suspension Velocity Results ..... 23
Discussion of Caliper / Natural Gamma Results ..... 23
Discussion of Elog / Natural Gamma Results ..... 24
Suspension Velocity Data Reliability ..... 25
Quality Assurance ..... 25

## Table of Figures

Figure 1: Concept illustration of P-S logging system ..... 27
Figure 2: Example of filtered (1400 Hz lowpass) suspension record ..... 28
Figure 3. Example of unfiltered suspension record ..... 29
Figure 4: Boring SB-1, Suspension R1-R2 P- and $S_H$-wave velocities ..... 30

## Table of Tables

Table 1. Boring locations and logging dates ..... 26
Table 2. Logging dates and depth ranges ..... 26
Table 3. Boring SB-1, Suspension R1-R2 depths and P- and $S_H$-wave velocities ..... 31

# APPENDICES

**APPENDIX A** **SUSPENSION VELOCITY MEASUREMENT QUALITY ASSURANCE SUSPENSION SOURCE TO RECEIVER ANALYSIS RESULTS**

**APPENDIX B** **ELOG, MECHANICAL CALIPER, AND NATURAL GAMMA LOGS**

**APPENDIX C** **GEOPHYSICAL LOGGING SYSTEMS - NIST TRACEABLE CALIBRATION RECORDS**

## INTRODUCTION

Borehole geophysical measurements were collected in one (1) boring at Harbor River in Beaufort, South Carolina. Data acquisition was performed on July 18th, 2016 by Jonathan Jordan of **GEO***Vision*. Data analysis and report preparation were performed by Emily Feldman and Victor Gonzalez and reviewed by John Diehl of **GEO***Vision*. The work was performed for F&ME Consultants, Inc. with Mike Miller serving as the point of contact.

This report describes the field measurements, data analysis, and results of this work.

## SCOPE OF WORK

This report presents the results of borehole geophysical measurements collected on July 18th, 2016 as detailed in Table 1.

Robertson Geologging (RG) ELOG and 3-Arm Mechanical Caliper (CAL) probes were used to collect long and short normal resistivity, single point resistance, self-potential, and borehole diameter, respectively. Both probes also acquired natural gamma (NG). The probes acquire data at up to 0.05 foot sample rate.

Measurement procedures followed these ASTM standards:

- ASTM D5753-05 (Re-approved 2010), “Planning and Conducting Boring Geophysical Logging”
- ASTM D6274-98 (Re-approved 2004), “Conducting Boring Geophysical Logging – Gamma”

Data were combined and plotted as profiles of the preceding parameters versus depth.

# INSTRUMENTATION

## Suspension Velocity Instrumentation

Suspension velocity measurements were performed using the suspension PS logging system, manufactured by OYO Corporation, and their subsidiary, Robertson Geologging. This system directly determines the average velocity of a 3.3-foot high segment of the soil column surrounding the boring of interest by measuring the elapsed time between arrivals of a wave propagating upward through the soil column. The receivers that detect the wave, and the source that generates the wave, are moved as a unit in the boring producing relatively constant amplitude signals at all depths.

The suspension system probe consists of a combined reversible polarity solenoid horizontal shear-wave source ($S_H$) and compressional-wave source (P), joined to two biaxial receivers by a flexible isolation cylinder, as shown in Figure 1. The separation of the two receivers is 3.3 feet, allowing average wave velocity in the region between the receivers to be determined by inversion of the wave travel time between the two receivers. The total length of the probe as used in these surveys is approximately 22 feet, with the center point of the receiver pair 12.5 feet above the bottom end of the probe.

The probe receives control signals from, and sends the digitized receiver signals to, instrumentation on the surface via an armored conductor cable. The cable is wound onto the drum of a winch and is used to support the probe. Cable travel is measured to provide probe depth data using a sheave of known circumference fitted with a digital rotary encoder.

The entire probe is suspended in the boring by the cable, therefore, source motion is not coupled directly to the boring walls; rather, the source motion creates a horizontally propagating impulsive pressure wave in the fluid filling the boring and surrounding the source. This pressure wave is converted to P and $S_H$-waves in the surrounding soil and rock as it passes through the casing and grout annulus and impinges upon the wall of the boring. These waves propagate through the soil and rock surrounding the boring, in turn causing a pressure wave to be generated in the fluid

surrounding the receivers as the soil waves pass their location. Separation of the P and $S_H$-waves at the receivers is performed using the following steps:

1. Orientation of the horizontal receivers is maintained parallel to the axis of the source, maximizing the amplitude of the recorded $S_H$ -wave signals.
2. At each depth, $S_H$-wave signals are recorded with the source actuated in opposite directions, producing $S_H$-wave signals of opposite polarity, providing a characteristic $S_H$-wave signature distinct from the P-wave signal.
3. The 6.3 foot separation of source and receiver 1 permits the P-wave signal to pass and damp significantly before the slower $S_H$-wave signal arrives at the receiver.
4. In saturated soils, the received P-wave signal is typically of much higher frequency than the received $S_H$-wave signal, permitting additional separation of the two signals by low pass filtering.
5. Direct arrival of the original pressure pulse in the fluid is not detected at the receivers because the wavelength of the pressure pulse in fluid is significantly greater than the dimension of the fluid annulus surrounding the probe (feet versus inches scale), preventing significant energy transmission through the fluid medium.

In operation, a distinct, repeatable pattern of impulses is generated at each depth as follows:

1. The source is fired in one direction producing dominantly horizontal shear with some vertical compression, and the signals from the horizontal receivers situated parallel to the axis of motion of the source are recorded.
2. The source is fired again in the opposite direction and the horizontal receiver signals are recorded.
3. The source is fired again and the vertical receiver signals are recorded. The repeated source pattern facilitates the picking of the P and $S_H$-wave arrivals; reversal of the source changes the polarity of the $S_H$-wave pattern but not the P-wave pattern.

The data from each receiver during each source activation is recorded as a different channel on the recording system. The Suspension PS system has six channels (two simultaneous recording channels), each with a 1024 sample record. The recorded data are displayed as six channels with a common time scale. Data are stored on disk for further processing.

Review of the displayed data on the recorder or computer screen allows the operator to set the gains, filters, delay time, pulse length (energy), and sample rate to optimize the quality of the data before recording. Verification of the calibration of the Suspension PS digital recorder is performed every twelve months using a NIST traceable frequency source and counter, as presented in Appendix C.

## Caliper / Natural Gamma Instrumentation

Caliper and natural gamma data were collected using a mechanical 3-arm caliper probe (CAL) manufactured by Robertson Geologging, Ltd. The probe is 6.82 feet long, and 1.5 inches in diameter. As configured, the probe can measure boring diameters between 1.6 and 12 inches.

This probe is useful in the following studies:

- Measurement of boring diameter and volume
- Location of hard and soft formations
- Location of fissures, caving, pinching and casing damage
- Bed boundary identification
- Strata correlation between borings

The probe receives control signals from, and sends the digitized measurement values to, a Robertson Micrologger II (MLII) on the surface via an armored cable. The cable is wound onto the drum of a winch and is used to support the probe. Cable travel is measured to provide probe depth using a sheave of known circumference fitted with a digital rotary encoder. Probe and depth data are transmitted by USB link from the MLII unit to a laptop computer where it is displayed and stored.

The caliper consists of three arms, each with a toothed quadrant at their base, pivoted in the lower probe body. A toothed rack engages with each quadrant, constraining the arms to move together. Linear movement of the rack is coupled to opening and closing of the arms. Springs hold the arms open in the operating position. A motor drive retracts the arms, allowing the probe to be lowered into the boring. The rack is coupled to a potentiometer which converts movement into a voltage sensed by the probe's microprocessor.

Natural gamma measurements rely on small quantities of radioactive material contained in soil and rocks to emit gamma radiation as they decay. Trace amounts of uranium and thorium are present

in a few minerals. Feldspar, mica and clays will include traces of a radioactive isotope of potassium. The radiation is detected by scintillation - the production of a tiny flash of light when gamma rays strike a crystal of sodium iodide. The light is converted into an electrical pulse by a photomultiplier tube. Pulses above a threshold value of 60 KeV are counted by the probe's microprocessor. The measurement is useful because the radioactive elements are concentrated in certain soil and rock types, e.g., clay or shale, and depleted in others, e.g., sandstone or coal.

## Elog / Natural Gamma Instrumentation

Elog and natural gamma data were collected using an electric log probe (ELOG), manufactured by Robertson Geologging, Ltd. This probe measures Single Point Resistance (SPR), short normal (16 inch) resistivity, long normal (64 inch) resistivity, Spontaneous Potential (SP) and natural gamma. The ELGX probe is 8.20 feet long, and 1.73 inches in diameter. The addition of an insulated bridle cable makes the functional length of the tool 41 feet.

This probe is useful in the following studies:

- Bed boundary identification
- Strata correlation between borings
- Strata geometry and type (shale indication)

The probe receives control signals from, and sends the digitized measurement values to, a Robertson Micrologger II (MLII) on the surface via an armored cable. The cable is wound onto the drum of a winch and is used to support the probe. Cable travel is measured to provide probe depth using a sheave of known circumference fitted with a digital rotary encoder. The probe and depth data are transmitted by USB link from the MLII unit to a laptop computer where it is displayed and stored.

The resistivity section of the probe operates by driving an alternating current into the formation from the central SPR/DRIVE electrode. The current returns via the logging cable armor. However, to ensure adequate penetration of the formation, a 10 meter (32.8 feet) insulated bridle cable is

attached between the probe and cablehead, making the functional length of the probe 41 feet. The bridle is comprised of 10 meters of insulated cable with a remote, or reference, electrode located at the top. Voltages are measured between the 16 inch and 64 inch electrodes and the remote earth connection at surface, as noted below:

- Single Point Resistance (SPR): The current flowing to the cable armor is measured along with the voltage at the SPR electrode. The voltage divided by current gives resistance.

- Spontaneous Potential (SP): This is the DC bias of the 16 inch electrode with respect to the voltage return at the surface (ground stake).

Data quality depends on good grounding at the surface. This is achieved with a metal stake driven into the ground near the borehole.

Natural gamma measurements rely on small quantities of radioactive material contained in soil and rocks to emit gamma radiation as they decay. Trace amounts of uranium and thorium are present in a few minerals. Feldspar, mica and clays will include traces of a radioactive isotope of potassium. The radiation is detected by scintillation - the production of a tiny flash of light when gamma rays strike a crystal of sodium iodide. The light is converted into an electrical pulse by a photomultiplier tube. Pulses above a threshold value of 60 KeV are counted by the probe's microprocessor. The measurement is useful because the radioactive elements are concentrated in certain soil and rock types, e.g., clay or shale, and depleted in others, e.g., sandstone or coal.

# MEASUREMENT PROCEDURES

## Suspension Velocity Measurement Procedures

Boring SB-1 was logged uncased from 80 feet below ground surface, and filled with water. Measurements followed the **GEO***Vision* Procedure for P-S Suspension Seismic Velocity Logging, revision 1.5. Prior to each logging run, the probe was positioned with the top of the probe even with a stationary reference point. The electronic depth counter was set to the distance between the mid-point of the receiver and the top of the probe, minus the height of the stationary reference point, if any, verified with a tape measure, and recorded on the field logs. The probe was lowered to the bottom of the boring, stopping at 1.6 foot intervals to collect data, as summarized in Table 2.

At each measurement depth the measurement sequence of two opposite horizontal records and one vertical record was performed, and the gains were adjusted as required. The data from each depth were viewed on the computer display, checked, and recorded on disk before moving to the next depth.

Upon completion of the measurements, the probe zero depth indication at the depth reference point was verified prior to removal from the boring.

## Caliper / Natural Gamma Measurement Procedures

Measurement procedures followed these ASTM standards:

- ASTM D5753-05 (Reapproved 2010), “Planning and Conducting Borehole Geophysical Logging”
- ASTM D6167-11, “Conducting Borehole Geophysical Logging – Mechanical - Caliper”
- ASTM D6274-10, “Conducting Borehole Geophysical Logging – Gamma”

The CAL probe does not require a fluid filled boring for proper operation. Prior to logging, measurement depths were referenced to ground level. This was done by placing the top of the probe even with a fixed reference point, such as top of casing or drill mud bucket. Then the electronic depth counter was set to the probe length minus the height of the reference point. Once verified with a tape measure, these calculations were recorded on a field log. Offset distances between probe tip and measurement points are corrected by the acquisition software. The probe was then lowered to the bottom of the boring, the caliper arms opened via software control, the software recorder turned on and data were acquired on ascent. The probe was returned to the surface at approximately 10-15 feet/minute, collecting data continuously at 0.05-foot spacing, as summarized in Table 2.

Prior to use, caliper tool operation was verified using **GEO***Vision* verification plate S/N 203. Plate S/N 203 is a circular aluminum plate with a series of four machined annular slots in the top surface for fitting the tips of the caliper arms. The slots have outside diameters from 2.1 to 8.0 inches. Methodically, the nose of the probe is centered through the central hole of the verification plate. The caliper probe arms are opened under program control, and a log recorded as the tips of the arms are sequentially placed in the four slots on the plate. The measured dimensions, as displayed on the computer screen, are recorded and compared to the verification plate know diameters.

If the verification records do not fall within +/- 0.05 inches of the verification plate values, the caliper tool is re-adjusted using the four point verification plate and the verification log repeated. As with the verification, the tips of the caliper arms are placed in the holes marked with the known diameter. During re-adjustment, the value of the current point, as stamped on the jig, is entered via the control computer. The system counts for 15 seconds to make an average of the response. The procedure is repeated for the remaining openings. The computation and generation of the adjustment file is entirely automatic. The adjustment file is simply the set of coefficients of a quadratic curve which fits the four data points.

Natural gamma was not calibrated in the field, as it is a qualitative measurement, not a quantitative value, and is used only to assist in picking transitions between stratigraphic units, as described in ASTM D6274-10, “Conducting Borehole Geophysical Logging – Gamma”.

Upon completion of the measurements, the probe zero depth indication at the depth reference point was verified prior to removal from the boring.

Natural gamma was not calibrated in the field, as it is a qualitative measurement, not a quantitative value, and is used only to assist in picking transitions between stratigraphic units, as described in ASTM D6274-10, “Conducting Borehole Geophysical Logging – Gamma”.

Upon completion of the measurements, the probe zero depth indication at the depth reference point was verified prior to removal from the boring.

## Elog / Natural Gamma Measurement Procedures

Measurement procedures followed these ASTM standards:

- ASTM D5753-05 (Re-approved 2010), “Planning and Conducting Boring Geophysical Logging”
- ASTM D6274-10, “Conducting Boring Geophysical Logging – Gamma”

The ELOG probe requires a fluid filled boring for proper operation. Prior to logging, measurement depths were referenced to ground level. This was done by placing the top of the probe even with a fixed reference point, such as top of casing or drill mud bucket. Then the electronic depth counter was set to the probe length minus the height of the reference point. Once verified with a tape measure, these calculations were recorded on a field log. Offset distances between probe tip and measurement points are corrected by the acquisition software.

The probe is connected to the logging cable using a 32.8 foot long insulating cable section or “bridle”. The probe head was insulated by wrapping all exposed metal of the cable head and probe

with self-amalgamating insulation tape. The 32.8 foot insulating yoke was checked for any damage, and repaired with self-amalgamating insulation tape as needed. The functional length of the probe with the bridle cable is 41 feet.

Prior to logging, measurement depths were referenced to ground level. This was done by positioning the probe with the top of the yoke even with a fixed reference point, such as top of casing or drill mud bucket. Then the electronic depth counter was set to the probe and bridle length (41 feet) minus the height of the reference point. Once verified with a tape measure, these calculations were recorded on a field log. Offset distances between probe tip and measurement points are corrected by the acquisition software. The probe was then lowered to the bottom of the boring, the software recorder turned on and data were acquired on ascent.. The probe was then returned to the surface at approximately 10 feet/minute, collecting data continuously at 0.05 foot spacing, until the yoke electrode cleared the surface of the borehole fluid or the probe entered the surface casing, as summarized in Table 2.

The reference ground stake was driven firmly into the ground near the borehole and connected to the ground socket on the winch junction box.

This probe was not calibrated in the field, as it is used to provide qualitative measurements, not quantitative values, and is used only to assist in picking transitions between stratigraphic units, as described in ASTM D5753-05 (Reapproved 2010), Planning and Conducting Boring Geophysical Surveys. A functional test was performed prior to use by applying fixed resistance values across the probe electrodes, as well as a 100 millivolt signal across the SP electrodes, and recording the resultant output of the system.

Natural gamma was not calibrated in the field, as it is a qualitative measurement, not a quantitative value, and is used only to assist in picking transitions between stratigraphic units, as described in ASTM D6274-10, Conducting Boring Geophysical Logging - Gamma.

Upon completion of the measurements, the probe zero depth indication at the depth reference point was verified prior to removal from the boring.

# DATA ANALYSIS

## Suspension Velocity Analysis

Using the proprietary OYO program PSLOG.EXE version 1.0, the recorded digital waveforms were analyzed to locate the most prominent first minima, first maxima, or first break on the vertical axis records, indicating the arrival of P-wave energy. The difference in travel time between receiver 1 and receiver 2 (R1-R2) arrivals was used to calculate the P-wave velocity for that 1.0 meter segment of the soil column. When observable, P-wave arrivals on the horizontal axis records were used to verify the velocities determined from the vertical axis data. The time picks were then transferred into a Microsoft Excel® template (version 2003 SP2) to complete the velocity calculations based upon the arrival time picks made in PSLOG. The Microsoft Excel® analysis files are included on the data disk that accompanies this report.

The P-wave velocity over the 6.3-foot interval from source to receiver 1 (S-R1) was also picked using PSLOG, and calculated and plotted in Microsoft Excel®, for quality assurance of the velocity derived from the travel time between receivers. In this analysis, the depth values as recorded were increased by 4.8 feet to correspond to the mid-point of the 6.3-foot S-R1 interval. Travel times were obtained by picking the first break of the P-wave signal at receiver 1 and subtracting 4 milliseconds, the calculated and experimentally verified delay from source trigger pulse (beginning of record) to source impact. This delay corresponds to the duration of acceleration of the solenoid before impact.

As with the P-wave records, the recorded digital waveforms were analyzed to locate clear $S_H$-wave pulses, as indicated by the presence of opposite polarity pulses on each pair of horizontal records. Ideally, the $S_H$-wave signals from the 'normal' and 'reverse' source pulses are very nearly inverted images of each other. Digital Fast Fourier Transform – Inverse Fast Fourier Transform (FFT – IFFT) lowpass filtering was used to remove the higher frequency P-wave signal from the $S_H$-wave signal. Different filter cutoffs were used to separate P- and $S_H$-waves at different depths, ranging from 600 Hz in the slowest zones to 4000 Hz in the regions of highest velocity. At each depth, the

filter frequency was selected to be at least twice the fundamental frequency of the $S_H$-wave signal being filtered.

Generally, the first maxima were picked for the 'normal' signals and the first minima for the 'reverse' signals, although other points on the waveform were used if the first pulse was distorted. The absolute arrival time of the 'normal' and 'reverse' signals may vary by +/- 0.2 milliseconds, due to differences in the actuation time of the solenoid source caused by constant mechanical bias in the source or by boring inclination. This variation does not affect the R1-R2 velocity determinations, as the differential time is measured between arrivals of waves created by the same source actuation. The final velocity value is the average of the values obtained from the 'normal' and 'reverse' source actuations.

As with the P-wave data, $S_H$-wave velocity calculated from the travel time over the 6.3-foot interval from source to receiver 1 was calculated and plotted for verification of the velocity derived from the travel time between receivers. In this analysis, the depth values were increased by 4.8 feet to correspond to the mid-point of the 6.3-foot S-R1 interval. Travel times were obtained by picking the first break of the $S_H$-wave signal at the near receiver and subtracting 4 milliseconds, the calculated and experimentally verified delay from the beginning of the record at the source trigger pulse to source impact.

These data and analysis were reviewed by John Diehl as a component of **GEO***Vision*'s in-house data validation program.

Figure 2 shows an example of R1 - R2 measurements on a sample filtered suspension record. In Figure 2, the time difference over the 3.3 foot interval of 1.88 milliseconds for the horizontal signals is equivalent to an $S_H$-wave velocity of 1745 feet/second. Whenever possible, time differences were determined from several phase points on the $S_H$-waveform records to verify the data obtained from the first arrival of the $S_H$-wave pulse. Figure 3 displays the same record before filtering of the $S_H$-waveform record with a 1400 Hz FFT - IFFT digital lowpass filter, illustrating

the presence of higher frequency P-wave energy at the beginning of the record, and distortion of the lower frequency $S_H$-wave by residual P-wave signal.

## Caliper / Natural Gamma

CAL and NG data do not require analysis; however depths to identifiable boring log features, such as distinct natural gamma transitions, were compared to verify consistent depth readings on all logs. Using WellCAD software version 5.1, CAL and NG data were combined with other line log data and converted to LAS 2.0 and PDF formats.

## Elog / Natural Gamma Analysis

ELOG and NG data do not require analysis; however depths to identifiable boring log features, such as distinct natural gamma transitions, were compared to verify consistent depth readings on all logs. Using WellCAD software version 5.1, ELOG and NG data were combined with other line log data and converted to LAS 2.0 and PDF formats.

# RESULTS

## Suspension Velocity Results

Suspension R1-R2 P- and $S_H$-wave velocities for Boring SB-1 are plotted in Figure 5. The suspension velocity data presented in this figure are also presented in Table 3. The Microsoft Excel® analysis file is included in the electronic data that accompanies this report.

P- and $S_H$-wave velocity data from R1-R2 analysis and quality assurance analysis of S-R1 data are plotted together in Figure A-1 to aid in visual comparison. It should be noted that R1-R2 data are an average velocity over a 3.3-foot segment of the soil column; S-R1 data are an average over 6.3 feet, creating a significant smoothing relative to the R1-R2 plots. The S-R1 velocity data displayed in this figure are also presented in Table A-1 and included in the Microsoft Excel® analysis file that accompanies this report. The Microsoft Excel® analysis file includes Poisson's Ratio calculations, tabulated data and plots.

## Caliper / Natural Gamma Results

Caliper (CAL) data are presented on combination line log plots with ELOG and NG data (Appendix B). All logs are scaled to the API 5-inch (1 inch = 20 feet) standard. Depths on all figures and tables are referenced to ground surface. LAS 2.0 data and Acrobat files of the plots are included in the boring specific sub-directories in the data directory that accompanies this report.

## Elog / Natural Gamma Results

ELOG data are presented on combination line log plots with CAL and NG data (Appendix B). All logs are scaled to the API 5-inch (1 inch = 20 feet) standard. Depths on all figures and tables are referenced to ground surface. LAS 2.0 data and Acrobat files of the plots are included in the boring specific sub-directories in the data directory that accompanies this report.

# SUMMARY

## Discussion of Suspension Velocity Results

Suspension PS velocity data are ideally collected in an uncased fluid filled boring, drilled with rotary mud (rotary wash) methods, as found in the case of this boring.

Suspension PS velocity data quality is judged based upon 5 criteria.

- Consistent data between receiver to receiver (R1 – R2) and source to receiver (S – R1) data.
- Consistency between data from adjacent depth intervals.
- Consistent relationship between P-wave and $S_H$ -wave (excluding transition to saturated soils)
- Clarity of P-wave and $S_H$-wave onset, as well as damping of later oscillations.
- Consistency of profile between adjacent borings, if available.

Good correspondence between the shapes of the P- and $S_H$-wave velocity curves are observed for this data set. The raw data was of excellent quality, obviating the need for any filtering or other post processing. The velocities derived from S-R1 and R1-R2 data are in good agreement for this borehole, providing verification of the higher resolution R1-R2 data.

There is an interesting drop in both P- and S-wave velocities at about 294 feet below ground surface (bgs). The P-wave velocity drops below water velocity, indicating possibly a thin unsaturated zone. Low Vs velocities continue down to about 400 feet bgs.

## Discussion of Caliper / Natural Gamma Results

The caliper log for boring SB-1 shows fairly consistent 6” gauge below the casing to about 248’, where the gauge narrows to 5”, likely due to a change in bit size. The gauge narrows again to 4” at about 452’ bgs. The caliper log terminated at 475’ due to collapse of the hole. This was the final log to be run.

There were no significant variations in the Natural Gamma log, but notable correspondence between minor features, particularly the events at about 285’ and 400’.

## Discussion of Elog / Natural Gamma Results

Elog data were acquired in this borehole to full depth, including long- and short-normal resistance, single-point resistance (SPR), and self-potential (SP). ELog data correlate well with other line logs, further assisting identification of lithologic variability with depth.

Natural Gamma data collected with this probe is not presented, as it is of lower vertical resolution than that collected with the CAL probe. However, the data correlates very well with the Caliper NG, and confirms the accuracy of the results.

## Suspension Velocity Data Reliability

P- and $S_H$-wave velocity measurement using the Suspension Method gives average velocities over a 3.3-foot interval of depth. This high resolution results in the scatter of values shown in the graphs. Individual measurements are very reliable with estimated precision of +/- 5%. Standardized field procedures and quality assurance checks contribute to the reliability of these data.

## Quality Assurance

These borehole geophysical measurements were performed using industry-standard or better methods for measurements and analyses. All work was performed under **GEO***Vision* quality assurance procedures, which include:

- Use of NIST-traceable calibrations, where applicable, for field and laboratory instrumentation
- Use of standard field data logs
- Independent review of calculations and results by a registered professional engineer, geologist, or geophysicist.

Table 1. Boring locations and logging dates

| BORING DESIGNATION | DATES LOGGED | LOCATION[1] | | ELEVATION (FEET) |
|---|---|---|---|---|
| | | NORTHING | EASTING | |
| SB-1 | 7/18/2016 | 209678.36 | 2164427.494 | 6.4 |

(1) Coordinates provided by F&ME

Table 2. Logging dates and depth ranges

| BORING NUMBER | TOOL AND RUN NUMBER | DEPTH RANGE (FEET)* | CASED OR UNCASED | SAMPLE INTERVAL (FEET) | DATE LOGGED |
|---|---|---|---|---|---|
| SB-1 | SUSPENSION DOWN01 | 78.85 – 501.75 | UNCASED | 1.6 | 7/18/2016 |
| SB-1 | ELOG UP01 | 515.19 – 77.29 | UNCASED | 0.05 | 7/18/2016 |
| SB-1 | CALIPER UP01 | 474.69 – 46.69 | UNCASED | 0.05 | 7/18/2016 |





Figure 1: Concept illustration of P-S logging system





Figure 2: Example of filtered (1400 Hz lowpass) suspension record





Figure 3. Example of unfiltered suspension record





Figure 4: Boring SB-1, Suspension R1-R2 P- and $S_H$-wave velocities

Table 3. Boring SB-1, Suspension R1-R2 depths and P- and $S_H$-wave velocities

**Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio Based on Receiver-to-Receiver Travel Time Data - Borehole SB-1**

| American Units | | | | Metric Units | | | |
|---|---|---|---|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio | Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | | | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | | (m) | (m/s) | (m/s) | |
| 78.9 | 1830 | 5560 | 0.44 | 24.0 | 560 | 1690 | 0.44 |
| 80.5 | 2140 | 6120 | 0.43 | 24.5 | 650 | 1860 | 0.43 |
| 82.1 | 2190 | 6600 | 0.44 | 25.0 | 670 | 2010 | 0.44 |
| 83.7 | 2290 | 6230 | 0.42 | 25.5 | 700 | 1900 | 0.42 |
| 85.3 | 2270 | 5850 | 0.41 | 26.0 | 690 | 1780 | 0.41 |
| 86.9 | 2000 | 5950 | 0.44 | 26.5 | 610 | 1810 | 0.44 |
| 88.5 | 2360 | 6540 | 0.43 | 27.0 | 720 | 1990 | 0.43 |
| 90.1 | 2730 | 6540 | 0.39 | 27.5 | 830 | 1990 | 0.39 |
| 91.7 | 2400 | 6120 | 0.41 | 27.9 | 730 | 1860 | 0.41 |
| 93.3 | 1980 | 5900 | 0.44 | 28.4 | 600 | 1800 | 0.44 |
| 94.9 | 1870 | 5850 | 0.44 | 28.9 | 570 | 1780 | 0.44 |
| 96.5 | 2000 | 6010 | 0.44 | 29.4 | 610 | 1830 | 0.44 |
| 98.1 | 2230 | 6230 | 0.43 | 29.9 | 680 | 1900 | 0.43 |
| 99.7 | 2290 | 6290 | 0.42 | 30.4 | 700 | 1920 | 0.42 |
| 101.3 | 2110 | 6060 | 0.43 | 30.9 | 640 | 1850 | 0.43 |
| 102.9 | 2060 | 6120 | 0.44 | 31.4 | 630 | 1860 | 0.44 |
| 104.5 | 2080 | 5950 | 0.43 | 31.8 | 640 | 1810 | 0.43 |
| 106.1 | 1980 | 6120 | 0.44 | 32.3 | 600 | 1860 | 0.44 |
| 107.7 | 1940 | 6010 | 0.44 | 32.8 | 590 | 1830 | 0.44 |
| 109.3 | 2100 | 5900 | 0.43 | 33.3 | 640 | 1800 | 0.43 |
| 110.9 | 2080 | 5900 | 0.43 | 33.8 | 630 | 1800 | 0.43 |
| 112.5 | 2000 | 6010 | 0.44 | 34.3 | 610 | 1830 | 0.44 |
| 114.1 | 2040 | 6060 | 0.44 | 34.8 | 620 | 1850 | 0.44 |
| 115.7 | 2140 | 6230 | 0.43 | 35.3 | 650 | 1900 | 0.43 |
| 117.3 | 2210 | 6010 | 0.42 | 35.8 | 670 | 1830 | 0.42 |
| 118.9 | 2010 | 5900 | 0.43 | 36.2 | 610 | 1800 | 0.43 |
| 120.5 | 2130 | 5950 | 0.43 | 36.7 | 650 | 1810 | 0.43 |
| 122.1 | 2130 | 6120 | 0.43 | 37.2 | 650 | 1860 | 0.43 |
| 123.7 | 2230 | 6120 | 0.42 | 37.7 | 680 | 1860 | 0.42 |
| 125.3 | 2280 | 6290 | 0.42 | 38.2 | 700 | 1920 | 0.42 |
| 126.9 | 2130 | 6060 | 0.43 | 38.7 | 650 | 1850 | 0.43 |
| 128.5 | 1940 | 5650 | 0.43 | 39.2 | 590 | 1720 | 0.43 |
| 130.1 | 1620 | 5290 | 0.45 | 39.7 | 490 | 1610 | 0.45 |
| 131.7 | 1470 | 5560 | 0.46 | 40.1 | 450 | 1690 | 0.46 |
| 133.3 | 1610 | 5750 | 0.46 | 40.6 | 490 | 1750 | 0.46 |
| 134.9 | 1960 | 5800 | 0.44 | 41.1 | 600 | 1770 | 0.44 |
| 136.5 | 1500 | 5650 | 0.46 | 41.6 | 460 | 1720 | 0.46 |

## Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio Based on Receiver-to-Receiver Travel Time Data - Borehole SB-1

| American Units | | | | Metric Units | | | |
|---|---|---|---|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio | Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | | | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | | (m) | (m/s) | (m/s) | |
| 138.1 | 1340 | 5560 | 0.47 | 42.1 | 410 | 1690 | 0.47 |
| 139.7 | 1850 | 6060 | 0.45 | 42.6 | 560 | 1850 | 0.45 |
| 141.3 | 2170 | 6120 | 0.43 | 43.1 | 660 | 1860 | 0.43 |
| 142.9 | 2020 | 6230 | 0.44 | 43.6 | 620 | 1900 | 0.44 |
| 144.5 | 2010 | 6170 | 0.44 | 44.1 | 610 | 1880 | 0.44 |
| 146.1 | 2190 | 6170 | 0.43 | 44.5 | 670 | 1880 | 0.43 |
| 147.7 | 2210 | 6170 | 0.43 | 45.0 | 680 | 1880 | 0.43 |
| 149.3 | 2180 | 6060 | 0.43 | 45.5 | 660 | 1850 | 0.43 |
| 150.9 | 2260 | 6120 | 0.42 | 46.0 | 690 | 1860 | 0.42 |
| 152.5 | 2120 | 5950 | 0.43 | 46.5 | 650 | 1810 | 0.43 |
| 154.1 | 2300 | 6350 | 0.42 | 47.0 | 700 | 1940 | 0.42 |
| 155.7 | 2420 | 6290 | 0.41 | 47.5 | 740 | 1920 | 0.41 |
| 157.3 | 2240 | 6060 | 0.42 | 48.0 | 680 | 1850 | 0.42 |
| 158.9 | 2110 | 5850 | 0.43 | 48.4 | 640 | 1780 | 0.43 |
| 160.5 | 2110 | 6060 | 0.43 | 48.9 | 640 | 1850 | 0.43 |
| 162.1 | 2120 | 6060 | 0.43 | 49.4 | 650 | 1850 | 0.43 |
| 163.8 | 2130 | 6170 | 0.43 | 49.9 | 650 | 1880 | 0.43 |
| 165.4 | 2250 | 6170 | 0.42 | 50.4 | 690 | 1880 | 0.42 |
| 167.0 | 2280 | 6060 | 0.42 | 50.9 | 690 | 1850 | 0.42 |
| 168.6 | 2160 | 6010 | 0.43 | 51.4 | 660 | 1830 | 0.43 |
| 170.2 | 2220 | 6060 | 0.42 | 51.9 | 680 | 1850 | 0.42 |
| 171.8 | 2310 | 6230 | 0.42 | 52.4 | 700 | 1900 | 0.42 |
| 173.4 | 2340 | 6120 | 0.41 | 52.8 | 710 | 1860 | 0.41 |
| 175.0 | 2330 | 6120 | 0.42 | 53.3 | 710 | 1860 | 0.42 |
| 176.6 | 2390 | 6670 | 0.43 | 53.8 | 730 | 2030 | 0.43 |
| 178.2 | 2570 | 6670 | 0.41 | 54.3 | 780 | 2030 | 0.41 |
| 179.8 | 2700 | 6730 | 0.40 | 54.8 | 820 | 2050 | 0.40 |
| 181.4 | 2470 | 6470 | 0.41 | 55.3 | 750 | 1970 | 0.41 |
| 183.0 | 2310 | 6350 | 0.42 | 55.8 | 710 | 1940 | 0.42 |
| 184.6 | 2350 | 6350 | 0.42 | 56.3 | 720 | 1940 | 0.42 |
| 186.2 | 2310 | 6290 | 0.42 | 56.7 | 710 | 1920 | 0.42 |
| 187.8 | 2210 | 6350 | 0.43 | 57.2 | 680 | 1940 | 0.43 |
| 189.4 | 2280 | 6410 | 0.43 | 57.7 | 700 | 1950 | 0.43 |
| 191.0 | 2400 | 6350 | 0.42 | 58.2 | 730 | 1940 | 0.42 |
| 192.6 | 2340 | 6290 | 0.42 | 58.7 | 710 | 1920 | 0.42 |
| 194.2 | 2250 | 6350 | 0.43 | 59.2 | 690 | 1940 | 0.43 |
| 195.8 | 2170 | 6060 | 0.43 | 59.7 | 660 | 1850 | 0.43 |
| 197.4 | 2200 | 6290 | 0.43 | 60.2 | 670 | 1920 | 0.43 |
| 199.0 | 2230 | 6350 | 0.43 | 60.7 | 680 | 1940 | 0.43 |
| 200.6 | 2210 | 6120 | 0.42 | 61.1 | 680 | 1860 | 0.42 |

**Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio**
**Based on Receiver-to-Receiver Travel Time Data - Borehole SB-1**

| American Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | |
| 202.2 | 2210 | 6290 | 0.43 |
| 203.8 | 2240 | 6120 | 0.42 |
| 205.4 | 2300 | 6290 | 0.42 |
| 207.0 | 2420 | 6470 | 0.42 |
| 208.6 | 2530 | 6600 | 0.41 |
| 210.2 | 2370 | 6540 | 0.42 |
| 211.8 | 2280 | 6470 | 0.43 |
| 213.4 | 2400 | 6670 | 0.43 |
| 215.0 | 2470 | 6600 | 0.42 |
| 216.6 | 2530 | 6470 | 0.41 |
| 218.2 | 2370 | 6670 | 0.43 |
| 219.8 | 2410 | 6470 | 0.42 |
| 221.4 | 2430 | 6600 | 0.42 |
| 223.0 | 2350 | 6470 | 0.42 |
| 224.6 | 2360 | 6350 | 0.42 |
| 226.2 | 2340 | 6350 | 0.42 |
| 227.8 | 2240 | 6410 | 0.43 |
| 229.4 | 2200 | 6290 | 0.43 |
| 231.0 | 2090 | 6170 | 0.44 |
| 232.6 | 2160 | 6410 | 0.44 |
| 234.2 | 2250 | 6230 | 0.42 |
| 235.8 | 2180 | 6170 | 0.43 |
| 237.4 | 1960 | 6120 | 0.44 |
| 239.0 | 1790 | 5900 | 0.45 |
| 240.6 | 1810 | 5950 | 0.45 |
| 242.2 | 1960 | 6120 | 0.44 |
| 243.8 | 2160 | 6410 | 0.44 |
| 245.4 | 2460 | 6410 | 0.41 |
| 247.0 | 2480 | 6290 | 0.41 |
| 248.7 | 2350 | 6600 | 0.43 |
| 250.3 | 2420 | 6670 | 0.42 |
| 251.9 | 2530 | 6470 | 0.41 |
| 253.5 | 2430 | 6540 | 0.42 |
| 255.1 | 2070 | 6060 | 0.43 |
| 256.7 | 1840 | 6060 | 0.45 |
| 258.3 | 1980 | 6010 | 0.44 |
| 259.9 | 2010 | 6060 | 0.44 |
| 261.5 | 1970 | 6060 | 0.44 |
| 263.1 | 2120 | 6290 | 0.44 |
| 264.7 | 2310 | 6350 | 0.42 |

| Metric Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (m) | (m/s) | (m/s) | |
| 61.6 | 670 | 1920 | 0.43 |
| 62.1 | 680 | 1860 | 0.42 |
| 62.6 | 700 | 1920 | 0.42 |
| 63.1 | 740 | 1970 | 0.42 |
| 63.6 | 770 | 2010 | 0.41 |
| 64.1 | 720 | 1990 | 0.42 |
| 64.6 | 700 | 1970 | 0.43 |
| 65.0 | 730 | 2030 | 0.43 |
| 65.5 | 750 | 2010 | 0.42 |
| 66.0 | 770 | 1970 | 0.41 |
| 66.5 | 720 | 2030 | 0.43 |
| 67.0 | 730 | 1970 | 0.42 |
| 67.5 | 740 | 2010 | 0.42 |
| 68.0 | 720 | 1970 | 0.42 |
| 68.5 | 720 | 1940 | 0.42 |
| 69.0 | 710 | 1940 | 0.42 |
| 69.4 | 680 | 1950 | 0.43 |
| 69.9 | 670 | 1920 | 0.43 |
| 70.4 | 640 | 1880 | 0.44 |
| 70.9 | 660 | 1950 | 0.44 |
| 71.4 | 690 | 1900 | 0.42 |
| 71.9 | 660 | 1880 | 0.43 |
| 72.4 | 600 | 1860 | 0.44 |
| 72.9 | 540 | 1800 | 0.45 |
| 73.3 | 550 | 1810 | 0.45 |
| 73.8 | 600 | 1860 | 0.44 |
| 74.3 | 660 | 1950 | 0.44 |
| 74.8 | 750 | 1950 | 0.41 |
| 75.3 | 760 | 1920 | 0.41 |
| 75.8 | 720 | 2010 | 0.43 |
| 76.3 | 740 | 2030 | 0.42 |
| 76.8 | 770 | 1970 | 0.41 |
| 77.3 | 740 | 1990 | 0.42 |
| 77.7 | 630 | 1850 | 0.43 |
| 78.2 | 560 | 1850 | 0.45 |
| 78.7 | 600 | 1830 | 0.44 |
| 79.2 | 610 | 1850 | 0.44 |
| 79.7 | 600 | 1850 | 0.44 |
| 80.2 | 650 | 1920 | 0.44 |
| 80.7 | 710 | 1940 | 0.42 |

**Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio**
**Based on Receiver-to-Receiver Travel Time Data - Borehole SB-1**

| American Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | |
| 266.3 | 2410 | 6800 | 0.43 |
| 267.9 | 2620 | 6800 | 0.41 |
| 269.5 | 3140 | 7090 | 0.38 |
| 271.1 | 3530 | 7330 | 0.35 |
| 272.7 | 3140 | 7090 | 0.38 |
| 274.3 | 2890 | 7020 | 0.40 |
| 275.9 | 2430 | 6600 | 0.42 |
| 277.5 | 2450 | 6670 | 0.42 |
| 279.1 | 3000 | 7170 | 0.39 |
| 280.7 | 3000 | 7170 | 0.39 |
| 282.3 | 2000 | 6350 | 0.45 |
| 283.9 | 1890 | 5380 | 0.43 |
| 285.5 | 1960 | 4870 | 0.40 |
| 287.1 | 1480 | 5560 | 0.46 |
| 288.7 | 2000 | 6120 | 0.44 |
| 290.3 | 2440 | 7490 | 0.44 |
| 291.9 | 2610 | 6670 | 0.41 |
| 293.5 | 2070 | 6350 | 0.44 |
| 295.1 | 2420 | 6470 | 0.42 |
| 296.7 | 2420 | 6670 | 0.42 |
| 298.3 | 1980 | 6230 | 0.44 |
| 299.9 | 2250 | 6600 | 0.43 |
| 301.5 | 2520 | 6670 | 0.42 |
| 303.1 | 2490 | 6600 | 0.42 |
| 304.7 | 2440 | 6410 | 0.42 |
| 306.3 | 2350 | 6290 | 0.42 |
| 307.9 | 2430 | 6350 | 0.41 |
| 309.5 | 2660 | 6870 | 0.41 |
| 311.1 | 2430 | 6540 | 0.42 |
| 312.7 | 1930 | 6230 | 0.45 |
| 314.3 | 1700 | 5750 | 0.45 |
| 315.9 | 1610 | 6060 | 0.46 |
| 317.5 | 1630 | 6060 | 0.46 |
| 319.1 | 1680 | 5950 | 0.46 |
| 320.7 | 1720 | 6170 | 0.46 |
| 322.3 | 1820 | 5900 | 0.45 |
| 323.9 | 1800 | 6410 | 0.46 |
| 325.5 | 1830 | 6060 | 0.45 |
| 327.1 | 1820 | 5850 | 0.45 |
| 328.7 | 1590 | 5800 | 0.46 |

| Metric Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (m) | (m/s) | (m/s) | |
| 81.2 | 730 | 2070 | 0.43 |
| 81.6 | 800 | 2070 | 0.41 |
| 82.1 | 960 | 2160 | 0.38 |
| 82.6 | 1080 | 2230 | 0.35 |
| 83.1 | 960 | 2160 | 0.38 |
| 83.6 | 880 | 2140 | 0.40 |
| 84.1 | 740 | 2010 | 0.42 |
| 84.6 | 750 | 2030 | 0.42 |
| 85.1 | 920 | 2180 | 0.39 |
| 85.6 | 920 | 2180 | 0.39 |
| 86.0 | 610 | 1940 | 0.45 |
| 86.5 | 580 | 1640 | 0.43 |
| 87.0 | 600 | 1480 | 0.40 |
| 87.5 | 450 | 1690 | 0.46 |
| 88.0 | 610 | 1860 | 0.44 |
| 88.5 | 740 | 2280 | 0.44 |
| 89.0 | 800 | 2030 | 0.41 |
| 89.5 | 630 | 1940 | 0.44 |
| 89.9 | 740 | 1970 | 0.42 |
| 90.4 | 740 | 2030 | 0.42 |
| 90.9 | 600 | 1900 | 0.44 |
| 91.4 | 690 | 2010 | 0.43 |
| 91.9 | 770 | 2030 | 0.42 |
| 92.4 | 760 | 2010 | 0.42 |
| 92.9 | 740 | 1950 | 0.42 |
| 93.4 | 720 | 1920 | 0.42 |
| 93.9 | 740 | 1940 | 0.41 |
| 94.3 | 810 | 2090 | 0.41 |
| 94.8 | 740 | 1990 | 0.42 |
| 95.3 | 590 | 1900 | 0.45 |
| 95.8 | 520 | 1750 | 0.45 |
| 96.3 | 490 | 1850 | 0.46 |
| 96.8 | 500 | 1850 | 0.46 |
| 97.3 | 510 | 1810 | 0.46 |
| 97.8 | 520 | 1880 | 0.46 |
| 98.2 | 550 | 1800 | 0.45 |
| 98.7 | 550 | 1950 | 0.46 |
| 99.2 | 560 | 1850 | 0.45 |
| 99.7 | 560 | 1780 | 0.45 |
| 100.2 | 480 | 1770 | 0.46 |

## Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio Based on Receiver-to-Receiver Travel Time Data - Borehole SB-1

| American Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | |
| 330.3 | 1510 | 5900 | 0.47 |
| 331.9 | 1560 | 5600 | 0.46 |
| 333.6 | 1470 | 5650 | 0.46 |
| 335.2 | 1390 | 5600 | 0.47 |
| 336.8 | 1540 | 6470 | 0.47 |
| 338.4 | 1660 | 6170 | 0.46 |
| 340.0 | 1830 | 5950 | 0.45 |
| 341.6 | 2010 | 6290 | 0.44 |
| 343.2 | 2170 | 6670 | 0.44 |
| 344.8 | 1820 | 6170 | 0.45 |
| 346.4 | 1680 | 6230 | 0.46 |
| 348.0 | 1660 | 5950 | 0.46 |
| 349.6 | 1460 | 5750 | 0.47 |
| 351.2 | 1550 | 5950 | 0.46 |
| 352.8 | 2040 | 6410 | 0.44 |
| 354.4 | 2200 | 6670 | 0.44 |
| 356.0 | 2350 | 6730 | 0.43 |
| 357.6 | 2420 | 6540 | 0.42 |
| 359.2 | 2120 | 6410 | 0.44 |
| 360.8 | 2140 | 6540 | 0.44 |
| 362.4 | 2080 | 6350 | 0.44 |
| 364.0 | 1930 | 5950 | 0.44 |
| 365.6 | 1980 | 6230 | 0.44 |
| 367.2 | 2230 | 6800 | 0.44 |
| 368.8 | 2150 | 6350 | 0.44 |
| 370.4 | 1880 | 6170 | 0.45 |
| 372.0 | 1750 | 6010 | 0.45 |
| 373.6 | 1590 | 5900 | 0.46 |
| 375.2 | 1450 | 5650 | 0.46 |
| 376.8 | 1410 | 5800 | 0.47 |
| 378.4 | 1490 | 5800 | 0.46 |
| 380.0 | 1570 | 5900 | 0.46 |
| 381.6 | 1560 | 6120 | 0.47 |
| 383.2 | 1610 | 5950 | 0.46 |
| 384.8 | 1550 | 5600 | 0.46 |
| 386.4 | 1520 | 5850 | 0.46 |
| 388.0 | 1520 | 5900 | 0.46 |
| 389.6 | 1530 | 5650 | 0.46 |
| 391.2 | 1650 | 6170 | 0.46 |
| 392.8 | 1920 | 6290 | 0.45 |

| Metric Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (m) | (m/s) | (m/s) | |
| 100.7 | 460 | 1800 | 0.47 |
| 101.2 | 470 | 1710 | 0.46 |
| 101.7 | 450 | 1720 | 0.46 |
| 102.2 | 430 | 1710 | 0.47 |
| 102.6 | 470 | 1970 | 0.47 |
| 103.1 | 510 | 1880 | 0.46 |
| 103.6 | 560 | 1810 | 0.45 |
| 104.1 | 610 | 1920 | 0.44 |
| 104.6 | 660 | 2030 | 0.44 |
| 105.1 | 560 | 1880 | 0.45 |
| 105.6 | 510 | 1900 | 0.46 |
| 106.1 | 510 | 1810 | 0.46 |
| 106.5 | 440 | 1750 | 0.47 |
| 107.0 | 470 | 1810 | 0.46 |
| 107.5 | 620 | 1950 | 0.44 |
| 108.0 | 670 | 2030 | 0.44 |
| 108.5 | 720 | 2050 | 0.43 |
| 109.0 | 740 | 1990 | 0.42 |
| 109.5 | 650 | 1950 | 0.44 |
| 110.0 | 650 | 1990 | 0.44 |
| 110.5 | 640 | 1940 | 0.44 |
| 110.9 | 590 | 1810 | 0.44 |
| 111.4 | 600 | 1900 | 0.44 |
| 111.9 | 680 | 2070 | 0.44 |
| 112.4 | 660 | 1940 | 0.44 |
| 112.9 | 570 | 1880 | 0.45 |
| 113.4 | 530 | 1830 | 0.45 |
| 113.9 | 480 | 1800 | 0.46 |
| 114.4 | 440 | 1720 | 0.46 |
| 114.8 | 430 | 1770 | 0.47 |
| 115.3 | 460 | 1770 | 0.46 |
| 115.8 | 480 | 1800 | 0.46 |
| 116.3 | 480 | 1860 | 0.47 |
| 116.8 | 490 | 1810 | 0.46 |
| 117.3 | 470 | 1710 | 0.46 |
| 117.8 | 460 | 1780 | 0.46 |
| 118.3 | 460 | 1800 | 0.46 |
| 118.8 | 470 | 1720 | 0.46 |
| 119.2 | 500 | 1880 | 0.46 |
| 119.7 | 590 | 1920 | 0.45 |

**Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio**
**Based on Receiver-to-Receiver Travel Time Data - Borehole SB-1**

| American Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | |
| 394.4 | 2180 | 6670 | 0.44 |
| 396.0 | 2300 | 6350 | 0.42 |
| 397.6 | 2510 | 6870 | 0.42 |
| 399.2 | 2610 | 6940 | 0.42 |
| 400.8 | 3210 | 7090 | 0.37 |
| 402.4 | 3550 | 6940 | 0.32 |
| 404.0 | 3040 | 7090 | 0.39 |
| 405.6 | 2870 | 7020 | 0.40 |
| 407.2 | 2900 | 7090 | 0.40 |
| 408.8 | 2960 | 6940 | 0.39 |
| 410.4 | 2920 | 7020 | 0.39 |
| 412.0 | 2960 | 7090 | 0.39 |
| 413.6 | 2900 | 6940 | 0.39 |
| 415.2 | 2730 | 6800 | 0.40 |
| 416.8 | 2650 | 6600 | 0.40 |
| 418.5 | 2570 | 6670 | 0.41 |
| 420.1 | 2660 | 6730 | 0.41 |
| 421.7 | 2610 | 6800 | 0.41 |
| 423.3 | 2590 | 6800 | 0.41 |
| 424.9 | 2700 | 6800 | 0.41 |
| 426.5 | 2810 | 7020 | 0.40 |
| 428.1 | 2800 | 7170 | 0.41 |
| 429.7 | 2860 | 7170 | 0.41 |
| 431.3 | 2950 | 7200 | 0.40 |
| 432.9 | 2800 | 6970 | 0.40 |
| 434.5 | 2690 | 6690 | 0.40 |
| 436.1 | 2780 | 6900 | 0.40 |
| 437.7 | 2840 | 6690 | 0.39 |
| 439.3 | 2870 | 6630 | 0.38 |
| 440.9 | 2990 | 7120 | 0.39 |
| 442.5 | 2980 | 6830 | 0.38 |
| 444.1 | 2780 | 7090 | 0.41 |
| 445.7 | 2800 | 6970 | 0.40 |
| 447.3 | 2740 | 7050 | 0.41 |
| 448.9 | 2730 | 6690 | 0.40 |
| 450.5 | 2750 | 6960 | 0.41 |
| 452.1 | 2800 | 6960 | 0.40 |
| 453.7 | 2940 | 6960 | 0.39 |
| 455.3 | 3020 | 7140 | 0.39 |
| 456.9 | 3160 | 7120 | 0.38 |

| Metric Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (m) | (m/s) | (m/s) | |
| 120.2 | 660 | 2030 | 0.44 |
| 120.7 | 700 | 1940 | 0.42 |
| 121.2 | 760 | 2090 | 0.42 |
| 121.7 | 800 | 2120 | 0.42 |
| 122.2 | 980 | 2160 | 0.37 |
| 122.7 | 1080 | 2120 | 0.32 |
| 123.1 | 930 | 2160 | 0.39 |
| 123.6 | 880 | 2140 | 0.40 |
| 124.1 | 880 | 2160 | 0.40 |
| 124.6 | 900 | 2120 | 0.39 |
| 125.1 | 890 | 2140 | 0.39 |
| 125.6 | 900 | 2160 | 0.39 |
| 126.1 | 880 | 2120 | 0.39 |
| 126.6 | 830 | 2070 | 0.40 |
| 127.1 | 810 | 2010 | 0.40 |
| 127.5 | 780 | 2030 | 0.41 |
| 128.0 | 810 | 2050 | 0.41 |
| 128.5 | 800 | 2070 | 0.41 |
| 129.0 | 790 | 2070 | 0.41 |
| 129.5 | 820 | 2070 | 0.41 |
| 130.0 | 860 | 2140 | 0.40 |
| 130.5 | 850 | 2180 | 0.41 |
| 131.0 | 870 | 2180 | 0.41 |
| 131.5 | 900 | 2190 | 0.40 |
| 131.9 | 850 | 2130 | 0.40 |
| 132.4 | 820 | 2040 | 0.40 |
| 132.9 | 850 | 2100 | 0.40 |
| 133.4 | 860 | 2040 | 0.39 |
| 133.9 | 880 | 2020 | 0.38 |
| 134.4 | 910 | 2170 | 0.39 |
| 134.9 | 910 | 2080 | 0.38 |
| 135.4 | 850 | 2160 | 0.41 |
| 135.8 | 850 | 2130 | 0.40 |
| 136.3 | 840 | 2150 | 0.41 |
| 136.8 | 830 | 2040 | 0.40 |
| 137.3 | 840 | 2120 | 0.41 |
| 137.8 | 850 | 2120 | 0.40 |
| 138.3 | 900 | 2120 | 0.39 |
| 138.8 | 920 | 2180 | 0.39 |
| 139.3 | 960 | 2170 | 0.38 |

**Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio**
**Based on Receiver-to-Receiver Travel Time Data - Borehole SB-1**

| American Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | |
| 458.5 | 3300 | 7370 | 0.37 |
| 460.1 | 3200 | 7310 | 0.38 |
| 461.7 | 3010 | 7060 | 0.39 |
| 463.3 | 2880 | 6860 | 0.39 |
| 464.9 | 2930 | 7000 | 0.39 |
| 466.5 | 2990 | 7150 | 0.39 |
| 468.1 | 2990 | 7000 | 0.39 |
| 469.7 | 2990 | 7030 | 0.39 |
| 471.3 | 3020 | 7250 | 0.40 |
| 472.9 | 2950 | 7220 | 0.40 |
| 474.5 | 2860 | 6970 | 0.40 |
| 476.1 | 2860 | 7250 | 0.41 |
| 477.7 | 2880 | 7180 | 0.40 |
| 479.3 | 2890 | 6920 | 0.39 |
| 480.9 | 2920 | 7180 | 0.40 |
| 482.5 | 2980 | 7180 | 0.40 |
| 484.1 | 2980 | 7370 | 0.40 |
| 485.7 | 3000 | 7220 | 0.40 |
| 487.3 | 3050 | 7180 | 0.39 |
| 488.9 | 3120 | 7580 | 0.40 |
| 490.5 | 3210 | 6970 | 0.37 |
| 492.1 | 3110 | 7340 | 0.39 |
| 493.7 | 2910 | 7540 | 0.41 |
| 495.3 | 3060 | 7340 | 0.40 |
| 496.9 | 3270 | 7150 | 0.37 |
| 498.5 | 3230 | 7220 | 0.37 |
| 500.1 | 3020 | 7060 | 0.39 |
| 501.8 | 2940 | 7030 | 0.39 |

| Metric Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Receivers | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (m) | (m/s) | (m/s) | |
| 139.8 | 1010 | 2250 | 0.37 |
| 140.2 | 970 | 2230 | 0.38 |
| 140.7 | 920 | 2150 | 0.39 |
| 141.2 | 880 | 2090 | 0.39 |
| 141.7 | 890 | 2130 | 0.39 |
| 142.2 | 910 | 2180 | 0.39 |
| 142.7 | 910 | 2130 | 0.39 |
| 143.2 | 910 | 2140 | 0.39 |
| 143.7 | 920 | 2210 | 0.40 |
| 144.1 | 900 | 2200 | 0.40 |
| 144.6 | 870 | 2130 | 0.40 |
| 145.1 | 870 | 2210 | 0.41 |
| 145.6 | 880 | 2190 | 0.40 |
| 146.1 | 880 | 2110 | 0.39 |
| 146.6 | 890 | 2190 | 0.40 |
| 147.1 | 910 | 2190 | 0.40 |
| 147.6 | 910 | 2250 | 0.40 |
| 148.1 | 910 | 2200 | 0.40 |
| 148.5 | 930 | 2190 | 0.39 |
| 149.0 | 950 | 2310 | 0.40 |
| 149.5 | 980 | 2130 | 0.37 |
| 150.0 | 950 | 2240 | 0.39 |
| 150.5 | 890 | 2300 | 0.41 |
| 151.0 | 930 | 2240 | 0.40 |
| 151.5 | 1000 | 2180 | 0.37 |
| 152.0 | 980 | 2200 | 0.37 |
| 152.4 | 920 | 2150 | 0.39 |
| 152.9 | 900 | 2140 | 0.39 |

# APPENDIX A

# SUSPENSION VELOCITY MEASUREMENT QUALITY ASSURANCE SUSPENSION SOURCE TO RECEIVER ANALYSIS RESULTS





Figure A-1: Boring SB-1, Suspension S-R1 P- and $S_H$-wave velocities

Table A-1. Boring SB-1, S - R1 quality assurance analysis P- and $S_H$-wave data

**Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio Based on Source-to-Receiver Travel Time Data - Borehole SB-1**

| American Units | | | | Metric Units | | | |
|---|---|---|---|---|---|---|---|
| Depth at Midpoint Between Source and Near Receiver | Velocity $V_s$ | Velocity $V_p$ | Poisson's Ratio | Depth at Midpoint Between Source and Near Receiver | Velocity $V_s$ | Velocity $V_p$ | Poisson's Ratio |
| (ft) | (ft/s) | (ft/s) | | (m) | (m/s) | (m/s) | |
| 83.7 | 2250 | 5920 | 0.42 | 25.5 | 690 | 1800 | 0.42 |
| 85.3 | 2270 | 6090 | 0.42 | 26.0 | 690 | 1860 | 0.42 |
| 86.9 | 2340 | 6180 | 0.42 | 26.5 | 710 | 1880 | 0.42 |
| 88.5 | 2180 | 6030 | 0.42 | 27.0 | 670 | 1840 | 0.42 |
| 90.1 | 2210 | 5970 | 0.42 | 27.5 | 670 | 1820 | 0.42 |
| 91.7 | 2200 | 6120 | 0.43 | 27.9 | 670 | 1860 | 0.43 |
| 93.3 | 2170 | 6210 | 0.43 | 28.4 | 660 | 1890 | 0.43 |
| 94.9 | 2130 | 6360 | 0.44 | 28.9 | 650 | 1940 | 0.44 |
| 96.5 | 2150 | 6270 | 0.43 | 29.4 | 660 | 1910 | 0.43 |
| 98.1 | 2120 | 6270 | 0.44 | 29.9 | 650 | 1910 | 0.44 |
| 99.7 | 2150 | 6210 | 0.43 | 30.4 | 650 | 1890 | 0.43 |
| 101.3 | 2160 | 6180 | 0.43 | 30.9 | 660 | 1880 | 0.43 |
| 102.9 | 1980 | 6060 | 0.44 | 31.4 | 600 | 1850 | 0.44 |
| 104.5 | 1970 | 6000 | 0.44 | 31.9 | 600 | 1830 | 0.44 |
| 106.1 | 2000 | 5940 | 0.44 | 32.3 | 610 | 1810 | 0.44 |
| 107.7 | 2000 | 5940 | 0.44 | 32.8 | 610 | 1810 | 0.44 |
| 109.3 | 1980 | 5970 | 0.44 | 33.3 | 600 | 1820 | 0.44 |
| 110.9 | 2000 | 6120 | 0.44 | 33.8 | 610 | 1860 | 0.44 |
| 112.5 | 2060 | 6000 | 0.43 | 34.3 | 630 | 1830 | 0.43 |
| 114.1 | 2020 | 5940 | 0.43 | 34.8 | 620 | 1810 | 0.43 |
| 115.7 | 2060 | 6060 | 0.43 | 35.3 | 630 | 1850 | 0.43 |
| 117.3 | 2060 | 6030 | 0.43 | 35.8 | 630 | 1840 | 0.43 |
| 118.9 | 2060 | 6180 | 0.44 | 36.2 | 630 | 1880 | 0.44 |
| 120.5 | 2030 | 6060 | 0.44 | 36.7 | 620 | 1850 | 0.44 |
| 122.1 | 2020 | 6000 | 0.44 | 37.2 | 620 | 1830 | 0.44 |
| 123.7 | 1970 | 6030 | 0.44 | 37.7 | 600 | 1840 | 0.44 |
| 125.3 | 1970 | 5970 | 0.44 | 38.2 | 600 | 1820 | 0.44 |
| 126.9 | 1880 | 5890 | 0.44 | 38.7 | 570 | 1790 | 0.44 |
| 128.5 | 1780 | 5810 | 0.45 | 39.2 | 540 | 1770 | 0.45 |
| 130.1 | 1720 | 5750 | 0.45 | 39.7 | 520 | 1750 | 0.45 |
| 131.7 | 1730 | 5630 | 0.45 | 40.2 | 530 | 1720 | 0.45 |
| 133.3 | 1690 | 5580 | 0.45 | 40.6 | 520 | 1700 | 0.45 |
| 134.9 | 1660 | 5550 | 0.45 | 41.1 | 510 | 1690 | 0.45 |
| 136.5 | 1680 | 5650 | 0.45 | 41.6 | 510 | 1720 | 0.45 |
| 138.1 | 1700 | 5650 | 0.45 | 42.1 | 520 | 1720 | 0.45 |
| 139.7 | 1830 | 5730 | 0.44 | 42.6 | 560 | 1750 | 0.44 |
| 141.3 | 2010 | 5860 | 0.43 | 43.1 | 610 | 1790 | 0.43 |
| 143.0 | 2100 | 6030 | 0.43 | 43.6 | 640 | 1840 | 0.43 |
| 144.6 | 2050 | 6000 | 0.43 | 44.1 | 620 | 1830 | 0.43 |

**Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio**
**Based on Source-to-Receiver Travel Time Data - Borehole SB-1**

| American Units | | | | Metric Units | | | |
|---|---|---|---|---|---|---|---|
| Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio | Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | | | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | | (m) | (m/s) | (m/s) | |
| 146.2 | 2040 | 6000 | 0.43 | 44.5 | 620 | 1830 | 0.43 |
| 147.8 | 2060 | 5890 | 0.43 | 45.0 | 630 | 1790 | 0.43 |
| 149.4 | 2120 | 6000 | 0.43 | 45.5 | 650 | 1830 | 0.43 |
| 151.0 | 2180 | 6000 | 0.42 | 46.0 | 670 | 1830 | 0.42 |
| 152.6 | 2280 | 6120 | 0.42 | 46.5 | 690 | 1860 | 0.42 |
| 154.2 | 2330 | 6030 | 0.41 | 47.0 | 710 | 1840 | 0.41 |
| 155.8 | 2260 | 6150 | 0.42 | 47.5 | 690 | 1870 | 0.42 |
| 157.4 | 2330 | 6030 | 0.41 | 48.0 | 710 | 1840 | 0.41 |
| 159.0 | 2190 | 5940 | 0.42 | 48.5 | 670 | 1810 | 0.42 |
| 160.6 | 2170 | 5860 | 0.42 | 48.9 | 660 | 1790 | 0.42 |
| 162.2 | 2140 | 5940 | 0.43 | 49.4 | 650 | 1810 | 0.43 |
| 163.8 | 2160 | 5940 | 0.42 | 49.9 | 660 | 1810 | 0.42 |
| 165.4 | 2190 | 5970 | 0.42 | 50.4 | 670 | 1820 | 0.42 |
| 167.0 | 2300 | 6090 | 0.42 | 50.9 | 700 | 1860 | 0.42 |
| 168.6 | 2340 | 6000 | 0.41 | 51.4 | 710 | 1830 | 0.41 |
| 170.2 | 2230 | 6000 | 0.42 | 51.9 | 680 | 1830 | 0.42 |
| 171.8 | 2260 | 6090 | 0.42 | 52.4 | 690 | 1860 | 0.42 |
| 173.4 | 2330 | 6000 | 0.41 | 52.8 | 710 | 1830 | 0.41 |
| 175.0 | 2390 | 6210 | 0.41 | 53.3 | 730 | 1890 | 0.41 |
| 176.6 | 2450 | 6330 | 0.41 | 53.8 | 750 | 1930 | 0.41 |
| 178.2 | 2480 | 6330 | 0.41 | 54.3 | 760 | 1930 | 0.41 |
| 179.8 | 2470 | 6300 | 0.41 | 54.8 | 750 | 1920 | 0.41 |
| 181.4 | 2500 | 6300 | 0.41 | 55.3 | 760 | 1920 | 0.41 |
| 183.0 | 2360 | 6210 | 0.42 | 55.8 | 720 | 1890 | 0.42 |
| 184.6 | 2270 | 6180 | 0.42 | 56.3 | 690 | 1880 | 0.42 |
| 186.2 | 2290 | 6210 | 0.42 | 56.8 | 700 | 1890 | 0.42 |
| 187.8 | 2320 | 6240 | 0.42 | 57.2 | 710 | 1900 | 0.42 |
| 189.4 | 2300 | 6150 | 0.42 | 57.7 | 700 | 1870 | 0.42 |
| 191.0 | 2210 | 6150 | 0.43 | 58.2 | 670 | 1870 | 0.43 |
| 192.6 | 2270 | 6210 | 0.42 | 58.7 | 690 | 1890 | 0.42 |
| 194.2 | 2250 | 6270 | 0.43 | 59.2 | 690 | 1910 | 0.43 |
| 195.8 | 2180 | 6150 | 0.43 | 59.7 | 660 | 1870 | 0.43 |
| 197.4 | 2130 | 6120 | 0.43 | 60.2 | 650 | 1860 | 0.43 |
| 199.0 | 2170 | 6180 | 0.43 | 60.7 | 660 | 1880 | 0.43 |
| 200.6 | 2180 | 6210 | 0.43 | 61.1 | 670 | 1890 | 0.43 |
| 202.2 | 2200 | 6240 | 0.43 | 61.6 | 670 | 1900 | 0.43 |
| 203.8 | 2240 | 6210 | 0.43 | 62.1 | 680 | 1890 | 0.43 |
| 205.4 | 2320 | 6360 | 0.42 | 62.6 | 710 | 1940 | 0.42 |
| 207.0 | 2360 | 6360 | 0.42 | 63.1 | 720 | 1940 | 0.42 |
| 208.6 | 2390 | 6360 | 0.42 | 63.6 | 730 | 1940 | 0.42 |

## Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio
## Based on Source-to-Receiver Travel Time Data - Borehole SB-1

| American Units | | | | Metric Units | | | |
|---|---|---|---|---|---|---|---|
| Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio | Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | | | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | | (m) | (m/s) | (m/s) | |
| 210.2 | 2370 | 6360 | 0.42 | 64.1 | 720 | 1940 | 0.42 |
| 211.8 | 2380 | 6360 | 0.42 | 64.6 | 730 | 1940 | 0.42 |
| 213.4 | 2410 | 6460 | 0.42 | 65.1 | 730 | 1970 | 0.42 |
| 215.0 | 2420 | 6490 | 0.42 | 65.5 | 740 | 1980 | 0.42 |
| 216.6 | 2430 | 6530 | 0.42 | 66.0 | 740 | 1990 | 0.42 |
| 218.2 | 2470 | 6460 | 0.41 | 66.5 | 750 | 1970 | 0.41 |
| 219.8 | 2430 | 6390 | 0.42 | 67.0 | 740 | 1950 | 0.42 |
| 221.4 | 2340 | 6360 | 0.42 | 67.5 | 710 | 1940 | 0.42 |
| 223.0 | 2290 | 6360 | 0.43 | 68.0 | 700 | 1940 | 0.43 |
| 224.6 | 2240 | 6240 | 0.43 | 68.5 | 680 | 1900 | 0.43 |
| 226.3 | 2260 | 6360 | 0.43 | 69.0 | 690 | 1940 | 0.43 |
| 227.9 | 2220 | 6300 | 0.43 | 69.4 | 680 | 1920 | 0.43 |
| 229.5 | 2160 | 6300 | 0.43 | 69.9 | 660 | 1920 | 0.43 |
| 231.1 | 2160 | 6150 | 0.43 | 70.4 | 660 | 1870 | 0.43 |
| 232.7 | 2140 | 6180 | 0.43 | 70.9 | 650 | 1880 | 0.43 |
| 234.3 | 2120 | 6150 | 0.43 | 71.4 | 650 | 1870 | 0.43 |
| 235.9 | 2070 | 6090 | 0.43 | 71.9 | 630 | 1860 | 0.43 |
| 237.5 | 1920 | 5940 | 0.44 | 72.4 | 590 | 1810 | 0.44 |
| 239.1 | 1930 | 5970 | 0.44 | 72.9 | 590 | 1820 | 0.44 |
| 240.7 | 1950 | 5860 | 0.44 | 73.4 | 590 | 1790 | 0.44 |
| 242.3 | 2040 | 5940 | 0.43 | 73.8 | 620 | 1810 | 0.43 |
| 243.9 | 2170 | 6090 | 0.43 | 74.3 | 660 | 1860 | 0.43 |
| 245.5 | 2270 | 6270 | 0.42 | 74.8 | 690 | 1910 | 0.42 |
| 247.1 | 2410 | 6360 | 0.42 | 75.3 | 730 | 1940 | 0.42 |
| 248.7 | 2490 | 6360 | 0.41 | 75.8 | 760 | 1940 | 0.41 |
| 250.3 | 2420 | 6430 | 0.42 | 76.3 | 740 | 1960 | 0.42 |
| 251.9 | 2390 | 6460 | 0.42 | 76.8 | 730 | 1970 | 0.42 |
| 253.5 | 2210 | 6300 | 0.43 | 77.3 | 670 | 1920 | 0.43 |
| 255.1 | 2100 | 6180 | 0.43 | 77.7 | 640 | 1880 | 0.43 |
| 256.7 | 2040 | 6330 | 0.44 | 78.2 | 620 | 1930 | 0.44 |
| 258.3 | 1920 | 6030 | 0.44 | 78.7 | 580 | 1840 | 0.44 |
| 259.9 | 2020 | 6120 | 0.44 | 79.2 | 610 | 1860 | 0.44 |
| 261.5 | 2100 | 6240 | 0.44 | 79.7 | 640 | 1900 | 0.44 |
| 263.1 | 2210 | 6360 | 0.43 | 80.2 | 670 | 1940 | 0.43 |
| 264.7 | 2310 | 6430 | 0.43 | 80.7 | 700 | 1960 | 0.43 |
| 266.3 | 2660 | 6630 | 0.40 | 81.2 | 810 | 2020 | 0.40 |
| 267.9 | 2840 | 7030 | 0.40 | 81.7 | 870 | 2140 | 0.40 |
| 269.5 | 3100 | 7230 | 0.39 | 82.1 | 950 | 2210 | 0.39 |
| 271.1 | 3150 | 7230 | 0.38 | 82.6 | 960 | 2210 | 0.38 |
| 272.7 | 3030 | 7030 | 0.39 | 83.1 | 920 | 2140 | 0.39 |

**Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio**
**Based on Source-to-Receiver Travel Time Data - Borehole SB-1**

| American Units | | | | Metric Units | | | |
|---|---|---|---|---|---|---|---|
| Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio | Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | | | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | | (m) | (m/s) | (m/s) | |
| 274.3 | 2840 | 6880 | 0.40 | 83.6 | 870 | 2100 | 0.40 |
| 275.9 | 2840 | 6770 | 0.39 | 84.1 | 870 | 2060 | 0.39 |
| 277.5 | 2840 | 6840 | 0.40 | 84.6 | 870 | 2090 | 0.40 |
| 279.1 | 2750 | 6770 | 0.40 | 85.1 | 840 | 2060 | 0.40 |
| 280.7 | 2540 | 6590 | 0.41 | 85.6 | 770 | 2010 | 0.41 |
| 282.3 | 2060 | 6120 | 0.44 | 86.1 | 630 | 1860 | 0.44 |
| 283.9 | 1650 | 5580 | 0.45 | 86.5 | 500 | 1700 | 0.45 |
| 285.5 | 1630 | 5650 | 0.45 | 87.0 | 500 | 1720 | 0.45 |
| 287.1 | 1770 | 5300 | 0.44 | 87.5 | 540 | 1610 | 0.44 |
| 288.7 | 1980 | 5830 | 0.43 | 88.0 | 600 | 1780 | 0.43 |
| 290.3 | 2450 | 6060 | 0.40 | 88.5 | 750 | 1850 | 0.40 |
| 291.9 | 2420 | 6530 | 0.42 | 89.0 | 740 | 1990 | 0.42 |
| 293.5 | 2450 | 6460 | 0.42 | 89.5 | 750 | 1970 | 0.42 |
| 295.1 | 2240 | 6150 | 0.42 | 90.0 | 680 | 1870 | 0.42 |
| 296.7 | 2320 | 6210 | 0.42 | 90.4 | 710 | 1890 | 0.42 |
| 298.3 | 2380 | 6490 | 0.42 | 90.9 | 730 | 1980 | 0.42 |
| 299.9 | 2300 | 6270 | 0.42 | 91.4 | 700 | 1910 | 0.42 |
| 301.5 | 2390 | 6300 | 0.42 | 91.9 | 730 | 1920 | 0.42 |
| 303.1 | 2490 | 6490 | 0.41 | 92.4 | 760 | 1980 | 0.41 |
| 304.7 | 2460 | 6360 | 0.41 | 92.9 | 750 | 1940 | 0.41 |
| 306.3 | 2530 | 6300 | 0.40 | 93.4 | 770 | 1920 | 0.40 |
| 307.9 | 2510 | 6300 | 0.41 | 93.9 | 770 | 1920 | 0.41 |
| 309.5 | 2430 | 6210 | 0.41 | 94.4 | 740 | 1890 | 0.41 |
| 311.2 | 2180 | 6240 | 0.43 | 94.8 | 660 | 1900 | 0.43 |
| 312.8 | 1990 | 6430 | 0.45 | 95.3 | 610 | 1960 | 0.45 |
| 314.4 | 1730 | 6030 | 0.45 | 95.8 | 530 | 1840 | 0.45 |
| 316.0 | 1700 | 5890 | 0.45 | 96.3 | 520 | 1790 | 0.45 |
| 317.6 | 1690 | 5630 | 0.45 | 96.8 | 520 | 1720 | 0.45 |
| 319.2 | 1670 | 5750 | 0.45 | 97.3 | 510 | 1750 | 0.45 |
| 320.8 | 1720 | 5600 | 0.45 | 97.8 | 530 | 1710 | 0.45 |
| 322.4 | 1820 | 5920 | 0.45 | 98.3 | 560 | 1800 | 0.45 |
| 324.0 | 1830 | 5750 | 0.44 | 98.7 | 560 | 1750 | 0.44 |
| 325.6 | 1780 | 6000 | 0.45 | 99.2 | 540 | 1830 | 0.45 |
| 327.2 | 1730 | 5970 | 0.45 | 99.7 | 530 | 1820 | 0.45 |
| 328.8 | 1630 | 5920 | 0.46 | 100.2 | 500 | 1800 | 0.46 |
| 330.4 | 1540 | 5780 | 0.46 | 100.7 | 470 | 1760 | 0.46 |
| 332.0 | 1440 | 5390 | 0.46 | 101.2 | 440 | 1640 | 0.46 |
| 333.6 | 1600 | 5530 | 0.45 | 101.7 | 490 | 1690 | 0.45 |
| 335.2 | 1630 | 5580 | 0.45 | 102.2 | 500 | 1700 | 0.45 |
| 336.8 | 1740 | 5650 | 0.45 | 102.7 | 530 | 1720 | 0.45 |

## Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio
## Based on Source-to-Receiver Travel Time Data - Borehole SB-1

| American Units | | | | Metric Units | | | |
|---|---|---|---|---|---|---|---|
| Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio | Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | | | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | | (m) | (m/s) | (m/s) | |
| 338.4 | 1960 | 5890 | 0.44 | 103.1 | 600 | 1790 | 0.44 |
| 340.0 | 2080 | 6240 | 0.44 | 103.6 | 630 | 1900 | 0.44 |
| 341.6 | 2100 | 6730 | 0.45 | 104.1 | 640 | 2050 | 0.45 |
| 343.2 | 2040 | 6430 | 0.44 | 104.6 | 620 | 1960 | 0.44 |
| 344.8 | 1970 | 6360 | 0.45 | 105.1 | 600 | 1940 | 0.45 |
| 346.4 | 1980 | 6210 | 0.44 | 105.6 | 600 | 1890 | 0.44 |
| 348.0 | 1780 | 5940 | 0.45 | 106.1 | 540 | 1810 | 0.45 |
| 349.6 | 1790 | 5890 | 0.45 | 106.6 | 550 | 1790 | 0.45 |
| 351.2 | 1870 | 6240 | 0.45 | 107.0 | 570 | 1900 | 0.45 |
| 352.8 | 2080 | 6360 | 0.44 | 107.5 | 630 | 1940 | 0.44 |
| 354.4 | 2270 | 6560 | 0.43 | 108.0 | 690 | 2000 | 0.43 |
| 356.0 | 2520 | 6300 | 0.40 | 108.5 | 770 | 1920 | 0.40 |
| 357.6 | 2560 | 6530 | 0.41 | 109.0 | 780 | 1990 | 0.41 |
| 359.2 | 2630 | 6360 | 0.40 | 109.5 | 800 | 1940 | 0.40 |
| 360.8 | 2430 | 6210 | 0.41 | 110.0 | 740 | 1890 | 0.41 |
| 362.4 | 2340 | 6300 | 0.42 | 110.5 | 710 | 1920 | 0.42 |
| 364.0 | 2390 | 6120 | 0.41 | 111.0 | 730 | 1860 | 0.41 |
| 365.6 | 2360 | 6180 | 0.41 | 111.4 | 720 | 1880 | 0.41 |
| 367.2 | 2330 | 5970 | 0.41 | 111.9 | 710 | 1820 | 0.41 |
| 368.8 | 2160 | 6210 | 0.43 | 112.4 | 660 | 1890 | 0.43 |
| 370.4 | 1930 | 6150 | 0.45 | 112.9 | 590 | 1870 | 0.45 |
| 372.0 | 1720 | 5970 | 0.45 | 113.4 | 520 | 1820 | 0.45 |
| 373.6 | 1600 | 5780 | 0.46 | 113.9 | 490 | 1760 | 0.46 |
| 375.2 | 1550 | 5600 | 0.46 | 114.4 | 470 | 1710 | 0.46 |
| 376.8 | 1560 | 5750 | 0.46 | 114.9 | 480 | 1750 | 0.46 |
| 378.4 | 1540 | 5860 | 0.46 | 115.3 | 470 | 1790 | 0.46 |
| 380.0 | 1550 | 5700 | 0.46 | 115.8 | 470 | 1740 | 0.46 |
| 381.6 | 1570 | 5810 | 0.46 | 116.3 | 480 | 1770 | 0.46 |
| 383.2 | 1510 | 5860 | 0.46 | 116.8 | 460 | 1790 | 0.46 |
| 384.8 | 1470 | 5750 | 0.46 | 117.3 | 450 | 1750 | 0.46 |
| 386.4 | 1470 | 5630 | 0.46 | 117.8 | 450 | 1720 | 0.46 |
| 388.0 | 1470 | 5680 | 0.46 | 118.3 | 450 | 1730 | 0.46 |
| 389.6 | 1570 | 5650 | 0.46 | 118.8 | 480 | 1720 | 0.46 |
| 391.2 | 1750 | 5920 | 0.45 | 119.3 | 530 | 1800 | 0.45 |
| 392.8 | 1860 | 6000 | 0.45 | 119.7 | 570 | 1830 | 0.45 |
| 394.4 | 1990 | 6120 | 0.44 | 120.2 | 610 | 1860 | 0.44 |
| 396.1 | 2220 | 6430 | 0.43 | 120.7 | 680 | 1960 | 0.43 |
| 397.7 | 2440 | 6630 | 0.42 | 121.2 | 740 | 2020 | 0.42 |
| 399.3 | 2800 | 6770 | 0.40 | 121.7 | 850 | 2060 | 0.40 |
| 400.9 | 2920 | 6960 | 0.39 | 122.2 | 890 | 2120 | 0.39 |

## Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio
## Based on Source-to-Receiver Travel Time Data - Borehole SB-1

| American Units | | | | Metric Units | | | |
|---|---|---|---|---|---|---|---|
| Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio | Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | | | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | | (m) | (m/s) | (m/s) | |
| 402.5 | 3170 | 6960 | 0.37 | 122.7 | 960 | 2120 | 0.37 |
| 404.1 | 3270 | 7030 | 0.36 | 123.2 | 1000 | 2140 | 0.36 |
| 405.7 | 2850 | 6880 | 0.40 | 123.6 | 870 | 2100 | 0.40 |
| 407.3 | 2810 | 7230 | 0.41 | 124.1 | 860 | 2210 | 0.41 |
| 408.9 | 2850 | 7150 | 0.41 | 124.6 | 870 | 2180 | 0.41 |
| 410.5 | 2810 | 7110 | 0.41 | 125.1 | 860 | 2170 | 0.41 |
| 412.1 | 2800 | 7110 | 0.41 | 125.6 | 850 | 2170 | 0.41 |
| 413.7 | 2730 | 7070 | 0.41 | 126.1 | 830 | 2160 | 0.41 |
| 415.3 | 2650 | 6960 | 0.42 | 126.6 | 810 | 2120 | 0.42 |
| 416.9 | 2640 | 6960 | 0.42 | 127.1 | 800 | 2120 | 0.42 |
| 418.5 | 2580 | 6960 | 0.42 | 127.6 | 790 | 2120 | 0.42 |
| 420.1 | 2560 | 6960 | 0.42 | 128.0 | 780 | 2120 | 0.42 |
| 421.7 | 2620 | 6960 | 0.42 | 128.5 | 800 | 2120 | 0.42 |
| 423.3 | 2670 | 6960 | 0.41 | 129.0 | 810 | 2120 | 0.41 |
| 424.9 | 2640 | 6960 | 0.42 | 129.5 | 800 | 2120 | 0.42 |
| 426.5 | 2710 | 6960 | 0.41 | 130.0 | 820 | 2120 | 0.41 |
| 428.1 | 2740 | 7030 | 0.41 | 130.5 | 840 | 2140 | 0.41 |
| 429.7 | 2750 | 6960 | 0.41 | 131.0 | 840 | 2120 | 0.41 |
| 431.3 | 2730 | 6840 | 0.41 | 131.5 | 830 | 2090 | 0.41 |
| 432.9 | 2730 | 6770 | 0.40 | 131.9 | 830 | 2060 | 0.40 |
| 434.5 | 2690 | 6840 | 0.41 | 132.4 | 820 | 2090 | 0.41 |
| 436.1 | 2660 | 6770 | 0.41 | 132.9 | 810 | 2060 | 0.41 |
| 437.7 | 2860 | 6880 | 0.40 | 133.4 | 870 | 2100 | 0.40 |
| 439.3 | 2940 | 6990 | 0.39 | 133.9 | 900 | 2130 | 0.39 |
| 440.9 | 2880 | 6960 | 0.40 | 134.4 | 880 | 2120 | 0.40 |
| 442.5 | 2890 | 7280 | 0.41 | 134.9 | 880 | 2220 | 0.41 |
| 444.1 | 2830 | 7150 | 0.41 | 135.4 | 860 | 2180 | 0.41 |
| 445.7 | 2790 | 7110 | 0.41 | 135.9 | 850 | 2170 | 0.41 |
| 447.3 | 2740 | 7070 | 0.41 | 136.3 | 840 | 2160 | 0.41 |
| 448.9 | 2750 | 6990 | 0.41 | 136.8 | 840 | 2130 | 0.41 |
| 450.5 | 2760 | 7030 | 0.41 | 137.3 | 840 | 2140 | 0.41 |
| 452.1 | 2830 | 6960 | 0.40 | 137.8 | 860 | 2120 | 0.40 |
| 453.7 | 2930 | 7110 | 0.40 | 138.3 | 890 | 2170 | 0.40 |
| 455.3 | 3070 | 7080 | 0.38 | 138.8 | 930 | 2160 | 0.38 |
| 456.9 | 3110 | 7210 | 0.39 | 139.3 | 950 | 2200 | 0.39 |
| 458.5 | 3110 | 7280 | 0.39 | 139.8 | 950 | 2220 | 0.39 |
| 460.1 | 3110 | 7130 | 0.38 | 140.2 | 950 | 2170 | 0.38 |
| 461.7 | 3010 | 7050 | 0.39 | 140.7 | 920 | 2150 | 0.39 |
| 463.3 | 2950 | 7020 | 0.39 | 141.2 | 900 | 2140 | 0.39 |
| 464.9 | 2910 | 7050 | 0.40 | 141.7 | 890 | 2150 | 0.40 |

**Summary of Compressional Wave Velocity, Shear Wave Velocity, and Poisson's Ratio**
**Based on Source-to-Receiver Travel Time Data - Borehole SB-1**

| American Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (ft) | (ft/s) | (ft/s) | |
| 466.5 | 2960 | 7050 | 0.39 |
| 468.1 | 2950 | 6970 | 0.39 |
| 469.7 | 2910 | 7100 | 0.40 |
| 471.3 | 2920 | 7100 | 0.40 |
| 472.9 | 2900 | 7020 | 0.40 |
| 474.5 | 2850 | 6910 | 0.40 |
| 476.1 | 2840 | 6880 | 0.40 |
| 477.7 | 2810 | 6970 | 0.40 |
| 479.3 | 2860 | 6910 | 0.40 |
| 481.0 | 2910 | 7080 | 0.40 |
| 482.6 | 2960 | 7130 | 0.40 |
| 484.2 | 2960 | 7190 | 0.40 |
| 485.8 | 3050 | 7210 | 0.39 |
| 487.4 | 3050 | 7130 | 0.39 |
| 489.0 | 3090 | 7430 | 0.40 |
| 490.6 | 2990 | 7210 | 0.40 |
| 492.2 | 3020 | 6990 | 0.38 |
| 493.8 | 3110 | 7180 | 0.38 |
| 495.4 | 3050 | 7310 | 0.39 |
| 497.0 | 3220 | 7760 | 0.40 |
| 498.6 | 3000 | 7390 | 0.40 |
| 500.2 | 2850 | 7240 | 0.41 |
| 501.8 | 2790 | 7190 | 0.41 |
| 503.4 | 2670 | 7080 | 0.42 |
| 505.0 | 2580 | 6970 | 0.42 |
| 506.6 | 2540 | 6870 | 0.42 |

| Metric Units | | | |
|---|---|---|---|
| Depth at Midpoint Between Source and Near Receiver | Velocity | | Poisson's Ratio |
| | $V_s$ | $V_p$ | |
| (m) | (m/s) | (m/s) | |
| 142.2 | 900 | 2150 | 0.39 |
| 142.7 | 900 | 2120 | 0.39 |
| 143.2 | 890 | 2160 | 0.40 |
| 143.7 | 890 | 2160 | 0.40 |
| 144.2 | 880 | 2140 | 0.40 |
| 144.6 | 870 | 2110 | 0.40 |
| 145.1 | 870 | 2100 | 0.40 |
| 145.6 | 860 | 2120 | 0.40 |
| 146.1 | 870 | 2110 | 0.40 |
| 146.6 | 890 | 2160 | 0.40 |
| 147.1 | 900 | 2170 | 0.40 |
| 147.6 | 900 | 2190 | 0.40 |
| 148.1 | 930 | 2200 | 0.39 |
| 148.5 | 930 | 2170 | 0.39 |
| 149.0 | 940 | 2260 | 0.40 |
| 149.5 | 910 | 2200 | 0.40 |
| 150.0 | 920 | 2130 | 0.38 |
| 150.5 | 950 | 2190 | 0.38 |
| 151.0 | 930 | 2230 | 0.39 |
| 151.5 | 980 | 2360 | 0.40 |
| 152.0 | 910 | 2250 | 0.40 |
| 152.5 | 870 | 2210 | 0.41 |
| 152.9 | 850 | 2190 | 0.41 |
| 153.4 | 810 | 2160 | 0.42 |
| 153.9 | 790 | 2120 | 0.42 |
| 154.4 | 770 | 2090 | 0.42 |

# APPENDIX B

# ELOG, MECHANICAL CALIPER, AND NATURAL GAMMA LOGS

GEOVision
geophysical services

CO F&ME
WELL SB-1
FLD
CTY
STE SC
API No

COMPANY F&ME
WELL ID SB-1
FIELD
COUNTRY USA STATE SC


LOCATION
LAT LONG

OTHER SERVICES
ELOG
CAL
NG
PSL

| | | | |
|---|---|---|---|
| PERMANENT DATUM | NA | ELEVATION NA | K.B. |
| LOG MEAS. FROM | TOC | | D.F. |
| DRILLING MEAS. FROM | NA | | G.L. |

| | | | | | |
|---|---|---|---|---|---|
| DATE | July 18, 2016 | July 18, 2016 | July 20, 2016 | FLUID IN HOLE | MUD |
| RUN No | 1 | 1 | 1 | SALINITY | |
| TYPE LOG | ELOG NG | PSL | CAL NG | DENSITY | |
| DEPTH-DRILLER | 518 | 518 | 518 | LEVEL | |
| DEPTH-LOGGER | 516 | 515 | 476 | | |
| LOG DEEPEST | 516 | 503 | 476 | | |
| LOG SHALLOW | 79 | 79 | 50 | | |
| OPERATING RIG TIME | | | | | |
| RECORDED BY | JJ | JJ | JJ | | |
| WITNESSED BY | | | | | |

| RUN | BOREHOLE RECORD | | | CASING RECORD | | | |
|---|---|---|---|---|---|---|---|
| NO. | BIT | FROM | TO | SIZE | WGT. | FROM | TO |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |



# APPENDIX C

# BORING GEOPHYSICAL LOGGING SYSTEMS - NIST TRACEABLE CALIBRATION RECORDS

MICRO PRECISION CALIBRATION, INC
2165 N. Glassell St.,
Orange, CA 92865
714-901-5659

# Certificate of Calibration

**Date:** Jul 14, 2016 **Cert No.** 222200812421163

**Customer:**
GEOVISION
1124 OLYMPIC DRIVE
CORONA CA 92881

Work Order #: N/A

| | | | |
|---|---|---|---|
| MPC Control #: | BG9698 | Serial Number: | 15014 |
| Asset ID: | 15014 | Department: | N/A |
| Gage Type: | LOGGER | Performed By: | TYLER MCKEEN |
| Manufacturer: | OYO | Received Condition: | IN TOLERANCE |
| Model Number: | 03331-0000 | Returned Condition: | IN TOLERANCE |
| Size: | N/A | Cal. Date: | July 14, 2016 |
| Temp/RH: | 72.0°F / 54.0% | Cal. Interval: | 12 MONTHS |
| | | Cal. Due Date: | July 14, 2017 |

**Calibration Notes:**
See attached data sheet for calculations. ( 1 Page )

Calibrated IAW customer supplied data form Rev 2.1
Frequency measurement uncertainty = 0.0005 Hz
Unit calibrated with Laptop Panasonic Model CF-29,s/n: 4FKSA41798
Calibrated To 4:1 Accuracy Ratio

**Standards Used to Calibrate Equipment**

| I.D. | Description. | Model | Serial | Manufacturer | Cal. Due Date | Traceability # |
|---|---|---|---|---|---|---|
| BD7715 | UNIVERSAL COUNTER | 53131A | 3416A05377 | HEWLETT PACKARD | Aug 26, 2016 | 222008122635161 |
| T1100 | UNIVERSAL COUNTER | 53131A | 3546A09912 | HEWLETT PACKARD | Feb 2, 2017 | 222008122827657 |
| AM4000 | WAVEFORM GENERATOR | 33250A | MY40000703 | AGILENT | Jul 8, 2017 | 222200812420653 |

**Procedures Used in this Event**

| Procedure Name | Description |
|---|---|
| GEOVISION SEISMIC | Suspension PS Seismic Logger/Recorder Calibration Procedure |

Calibrating Technician: TYLER MCKEEN

QC Approval: JIM WILLIAMS

The reported expanded uncertainty of measurement is stated as the standard uncertainty of measurement multiplied by the coverage factor k=2, which for normal distribution corresponds to a coverage probability of approximately 95%. The standard uncertainty of measurement has been determined in accordance with EA's Publication and NIST Technical Note 1297, 1994 Edition. Services rendered comply with ISO 17025:2005, ANSI/NCSL Z540-1, MPC Quality Manual, MPC CSD and with customer purchase order instructions.

Calibration cycles and resulting due dates were submitted/approved by the customer. Any number of factors may cause an instrument to drift out of tolerance before the next scheduled calibration. Recalibration cycles should be based on frequency of use, environmental conditions and customer's established systematic accuracy. The information on this report, pertains only to the instrument identified.

All standards are traceable to SI through the National Institute of Standards and Technology (NIST) and/or recognized national or international standards laboratories. Services rendered include proper manufacturer's service instruction and are warranted for no less than thirty (30) days. This report may not be reproduced in part or in a whole without the prior written approval of the issuing MPC lab.

BG 9698 15014

GEOVision geophysical services

## SUSPENSION PS SEISMIC LOGGER/RECORDER CALIBRATION DATA FORM

**INSTRUMENT DATA**

| | | | |
|---|---|---|---|
| System mfg.: | O/O | Model no.: | 3331 |
| Serial no.: | 15014 | Calibration date: | 07/14/2016 |
| By: | Emily Feldman | Due date: | 07/14/2017 |
| Counter mfg.: | Hewlett Packard | Model no.: | 5313A |
| Serial no.: | 3546A09912 | Calibration date: | 02/02/16 |
| By: | Micro Precision | Due date: | 02/02/17 |
| Signal generator mfg.: | Agilent | Model no.: | ~~07~~ 33250A |
| Serial no.: | MY40000703 | Calibration date: | 07/08/16 |
| By: | Micro Precision | Due date: | 07/08/17 |
| Laptop controller mfg.: | Panasonic RG3 | Model no.: | CF-29 Toughbook |
| Serial no.: | 4FKSA41798 | Calibration date: | N/A |

**SYSTEM SETTINGS:**

| | |
|---|---|
| Gain: | x10 |
| Filter | open |
| Range: | 200 - 5 µs |
| Delay: | 4 msec |
| Stack (1 std) | 1 |
| System date = correct date and time | Yes, 12:25, 7/14/16 |

**PROCEDURE:**

Set sine wave frequency to target frequency with amplitude of approximately 0.25 volt peak
Note actual frequency on data form.
Set sample period and record data file to disk. Note file name on data form.
Pick duration of 9 cycles using PSLOG.EXE program, note duration on data form, and save as .sps file. Calculate average frequency for each channel pair and note on data form.

Average frequency must be within +/- 1% of actual frequency at all data points.

Maximum error ((AVG-ACT)/ACT*100)% As found 0.22% As left 0.22%


| Target Frequency (Hz) | Actual Frequency (Hz) | Sample Period (microS) | File Name Cal2- | Time for 9 cycles Hn (msec) | Average Frequency Hn (Hz) | Time for 9 cycles Hr (msec) | Average Frequency Hr (Hz) | Time for 9 cycles V (msec) | Average Frequency V (Hz) |
|---|---|---|---|---|---|---|---|---|---|
| 50.00 | 50.00 | 200 | 001 | 180 | 50.00 | 180 | 50.00 | 179.8 | 50.05 |
| 100.0 | 100.0 | 100 | 002 | 89.9 | 99.9 | 89.9 | 99.9 | 90.1 | 99.9 |
| 200.0 | 200.0 | 50 | 003 | 44.95 | 200.2 | 45 | 200.0 | 45 | 200.0 |
| 500.0 | 500.0 | 20 | 004 | 18.02 | 499.5 | K:0 | ~~48.0~~ 500.0 | 17.98 | 500.6 |
| 1000 | 1,000 | 10 | 005 | 9.01 | 998.9 | 8.98 | 1002.2 | 9 | 1000 |
| 2000 | 2,000 | 5 | 006 | 4.505 | 1998 | 4.50 | 2000 | 4.495 | 2002 |

Calibrated by: Tyler McKean 7/14/16
Name Date Signature

Witnessed by: Emily Feldman 7/14/16
Name Date Signature

Suspension PS Seismic Recorder/Logger Calibration Data Form Rev 2.1 February 7, 2012

**Shear Wave Velocity- SCPT-2**
**US 21 Replacement Bridge Over Harbor River**
**14-54074**
**August 25th , 2014**




# ConeTec Shear Wave Velocity Data Reduction Sheet

Hole: SCPT-2
Location: US 21 Replacement Bridge Over Harbor River
Cone: AD184
Date: 25-Aug-14
Source: Beam

| | |
|---|---|
| Source Depth | 0.00 m |
| Source Offset | 2.15 m |

| Tip Depth (m) | Geophone Depth(m) | Travel Path (m) | Interval time (ms) | Velocity (m/s) | Velocity (ft/s) | Interval Depth (m) | Interval Depth (ft) |
|---|---|---|---|---|---|---|---|
| 0.00 | | | | | | | |
| 1.85 | 1.65 | 2.71 | | | | | |
| 2.85 | 2.65 | 3.41 | 5.07 | 138.5 | 454.4 | 2.15 | 7.05 |
| 3.85 | 3.65 | 4.24 | 7.86 | 104.8 | 343.7 | 3.15 | 10.33 |
| 4.85 | 4.65 | 5.12 | 7.74 | 114.6 | 375.9 | 4.15 | 13.61 |
| 5.85 | 5.65 | 6.05 | 7.61 | 121.3 | 397.9 | 5.15 | 16.90 |
| 6.85 | 6.65 | 6.99 | 8.78 | 107.5 | 352.5 | 6.15 | 20.18 |
| 7.85 | 7.65 | 7.95 | 10.69 | 89.5 | 293.8 | 7.15 | 23.46 |
| 8.85 | 8.65 | 8.91 | 6.50 | 148.8 | 488.2 | 8.15 | 26.74 |
| 9.85 | 9.65 | 9.89 | 6.24 | 156.1 | 512.0 | 9.15 | 30.02 |
| 10.85 | 10.65 | 10.86 | 4.31 | 226.9 | 744.3 | 10.15 | 33.30 |
| 11.85 | 11.65 | 11.85 | 5.17 | 189.9 | 623.0 | 11.15 | 36.58 |
| 12.85 | 12.65 | 12.83 | 4.89 | 201.5 | 661.2 | 12.15 | 39.86 |
| 13.85 | 13.65 | 13.82 | 6.36 | 155.1 | 509.0 | 13.15 | 43.14 |
| 14.85 | 14.65 | 14.81 | 5.29 | 186.9 | 613.1 | 14.15 | 46.42 |
| 15.85 | 15.65 | 15.80 | 4.59 | 215.6 | 707.2 | 15.15 | 49.70 |
| 16.85 | 16.65 | 16.79 | 4.89 | 202.8 | 665.4 | 16.15 | 52.98 |
| 17.85 | 17.65 | 17.78 | 4.90 | 202.6 | 664.7 | 17.15 | 56.27 |
| 18.85 | 18.65 | 18.77 | 4.92 | 202.0 | 662.7 | 18.15 | 59.55 |
| 19.85 | 19.65 | 19.77 | 4.46 | 223.0 | 731.6 | 19.15 | 62.83 |
| 20.85 | 20.65 | 20.76 | 3.22 | 308.6 | 1012.3 | 20.15 | 66.11 |
| 21.85 | 21.65 | 21.76 | 3.73 | 266.7 | 875.1 | 21.15 | 69.39 |
| 22.85 | 22.65 | 22.75 | 3.39 | 293.2 | 962.0 | 22.15 | 72.67 |
| 23.85 | 23.65 | 23.75 | 3.13 | 318.1 | 1043.5 | 23.15 | 75.95 |
| 24.85 | 24.65 | 24.74 | 3.01 | 330.4 | 1084.0 | 24.15 | 79.23 |
| 25.85 | 25.65 | 25.74 | 2.35 | 423.4 | 1389.2 | 25.15 | 82.51 |
| 26.85 | 26.65 | 26.74 | 2.74 | 363.8 | 1193.5 | 26.15 | 85.79 |
| 27.10 | 26.90 | 26.99 | 0.96 | 258.5 | 848.0 | 26.78 | 87.84 |

**Shear Wave Velocity- SCPT-11**
**US 21 Replacement Bridge Over Harbor River**
**15-54107**
**November 18th , 2015**



| | |
|---|---|
| Job No: | 15-54107 |
| Client: | F&ME |
| Project: | Harbor River |
| Sounding ID: | SCPT-11 |
| Date: | 11/18/2015 |

| | |
|---|---|
| Seismic Source: | Beam |
| Source Offset (ft): | 4.75 |
| Source Depth (ft): | 0.00 |
| Geophone Offset (ft): | 0.66 |

## *SCPTu SHEAR WAVE VELOCITY TEST RESULTS - Vs*

| Tip Depth (ft) | Geophone Depth (ft) | Ray Path (ft) | Ray Path Difference (ft) | Travel Time Interval (ms) | Interval Velocity (ft/s) |
|---|---|---|---|---|---|
| 2.95 | 2.30 | 5.28 | | | |
| 6.23 | 5.58 | 7.33 | 2.05 | 3.59 | 571 |
| 9.51 | 8.86 | 10.05 | 2.73 | 5.23 | 521 |
| 12.80 | 12.14 | 13.04 | 2.98 | 6.32 | 472 |
| 16.08 | 15.42 | 16.13 | 3.10 | 6.52 | 475 |
| 19.36 | 18.70 | 19.29 | 3.16 | 10.35 | 305 |
| 22.64 | 21.98 | 22.49 | 3.19 | 5.71 | 559 |
| 25.92 | 25.26 | 25.71 | 3.22 | 6.34 | 507 |
| 29.20 | 28.54 | 28.94 | 3.23 | 8.38 | 386 |
| 32.48 | 31.82 | 32.18 | 3.24 | 5.36 | 605 |
| 35.76 | 35.10 | 35.42 | 3.25 | 3.94 | 825 |
| 39.04 | 38.39 | 38.68 | 3.25 | 3.97 | 820 |
| 42.32 | 41.67 | 41.94 | 3.26 | 6.00 | 543 |
| 45.60 | 44.95 | 45.20 | 3.26 | 6.55 | 498 |
| 48.88 | 48.23 | 48.46 | 3.26 | 3.32 | 982 |
| 52.17 | 51.51 | 51.73 | 3.27 | 3.20 | 1020 |
| 55.45 | 54.79 | 55.00 | 3.27 | 3.72 | 879 |
| 58.73 | 58.07 | 58.26 | 3.27 | 3.12 | 1049 |
| 62.01 | 61.35 | 61.53 | 3.27 | 3.79 | 862 |
| 65.29 | 64.63 | 64.81 | 3.27 | 3.67 | 892 |
| 68.57 | 67.91 | 68.08 | 3.27 | 3.12 | 1047 |
| 72.01 | 71.36 | 71.52 | 3.44 | 2.69 | 1280 |
| 81.36 | 80.71 | 80.85 | 9.33 | 5.89 | 1585 |
| 84.65 | 83.99 | 84.12 | 3.28 | 1.79 | 1834 |
| 87.93 | 87.27 | 87.40 | 3.28 | 1.65 | 1987 |
| 91.21 | 90.55 | 90.68 | 3.28 | 1.84 | 1783 |
| 94.49 | 93.83 | 93.95 | 3.28 | 1.30 | 2520 |
| 97.77 | 97.11 | 97.23 | 3.28 | 1.45 | 2260 |
| 101.05 | 100.39 | 100.51 | 3.28 | 1.82 | 1804 |

# APPENDIX B
## Laboratory Testing

**US-21 BRIDGE REPLACEMENT OVER HARBOR RIVER**
**BEAUFORT COUNTY, SOUTH CAROLINA**
**F&ME PROJECT NO.: G5396.00**

**FINAL LABORATORY ANALYSIS SUMMARY**

| BORING NUMBER | SAMPLE DEPTH (ft) | % MOISTURE | % GRAVEL | % SAND | % FINES (SILT/CLAY) | LL | PL | PI | USCS | AASHTO Class | % ORGANICS | pH | Resistivity (Ohm-cm) | Sulfate (mg/kg) | Chloride (mg/kg) | Carbonate (% Calcite Equivalent) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| B-1 | 4.0-6.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 1.15 | -- | -- | -- | -- | -- |
| | 6.0-8.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 1.07 | -- | -- | -- | -- | -- |
| | 8.0-10.0 | 19.3 | 16.7 | 76.0 | 7.3 | NP | NP | NP | SP-SM | A-1-b | -- | -- | -- | -- | -- | -- |
| | 12.0-14.0 | 19.2 | 8.4 | 83.7 | 8.0 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 14.0-16.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 0.31 | -- | -- | -- | -- | -- |
| | 18.0-20.0 | 27.4 | 0.0 | 96.7 | 3.3 | NP | NP | NP | SP | A-3 | -- | -- | -- | -- | -- | -- |
| | 28.5-30.0 | 34.7 | 0.2 | 92.4 | 7.4 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 43.5-45.0 | 33.8 | 0.4 | 88.6 | 11.0 | NP | NP | NP | SP-SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 48.5-50.0 | 59.0 | 0.0 | 66.8 | 33.2 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| B-2 | 4.0-6.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 0.56 | -- | -- | -- | -- | -- |
| | 6.0-8.0 | 28.7 | 0.0 | 95.1 | 4.9 | NP | NP | NP | SP | A-3 | -- | -- | -- | -- | -- | -- |
| | 8.0-10.0 | 27.9 | 0.0 | 97.5 | 2.5 | NP | NP | NP | SP | A-3 | -- | -- | -- | -- | -- | -- |
| | 10.0-12.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 0.45 | -- | -- | -- | -- | -- |
| | 18.0-20.0 | 26.5 | 0.0 | 93.7 | 6.3 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 23.5-25.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 1.25 | -- | -- | -- | -- | -- |
| | 28.5-30.0 | 30.3 | 0.3 | 85.7 | 14.0 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 38.5-40.0 | 29.3 | 0.1 | 91.1 | 8.8 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 53.5-55.0 | 28.4 | 0.3 | 89.7 | 10.0 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| B-3 | 0.0-2.0 | 36.9 | 0.2 | 62.3 | 37.5 | NP | NP | NP | SM | A-4(0) | -- | -- | -- | -- | -- | -- |
| | 4.0-6.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 3.55 | -- | -- | -- | -- | -- |
| | 6.0-8.0 | 151.6 | 0.0 | 1.5 | 98.5 | 74 | 49 | 25 | MH | A-7-5(36) | -- | -- | -- | -- | -- | -- |
| | 13.5-15.0 | 26.1 | 0.0 | 92.3 | 7.7 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 18.5-20.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 7.9 | 200 | 126 | 5080 | -- |
| | 23.5-25.0 | 29.3 | 15.8 | 59.7 | 24.5 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 28.5-30.0 | 101.1 | 0.0 | 3.4 | 96.6 | 58 | 31 | 27 | MH | A-7-5(32) | -- | -- | -- | -- | -- | -- |
| | 38.5-40.0 | 30.2 | 3.7 | 85.8 | 10.4 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| B-4 | 2.0-4.0 | 52.5 | 4.9 | 63.2 | 31.9 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 4.0-6.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 2.68 | -- | -- | -- | -- | -- |
| | 8.0-10.0 | 32.9 | 1.2 | 72.9 | 26.0 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 13.5-15.0 | 31.8 | 0.0 | 84.9 | 15.1 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 23.5-25.0 | 27.8 | 1.1 | 76.9 | 22.0 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 33.5-35.0 | 35.8 | 1.6 | 76.8 | 21.6 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 38.5-40.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 8.0 | 180 | 559 | 8350 | -- |
| | 48.5-50.0 | 31.8 | 0.6 | 82.4 | 17.0 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 63.5-65.0 | 64.5 | 0.0 | 46.9 | 53.1 | 71 | 35 | 36 | MH | A-7-5(16) | -- | -- | -- | -- | -- | -- |
| B-5 | 2.0-4.0 | 27.9 | 0.0 | 93.4 | 6.6 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 6.0-8.0 | 24.1 | 0.0 | 85.3 | 14.6 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 8.0-10.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 0.27 | -- | -- | -- | -- | -- |
| | 13.5-15.0 | 36.1 | 0.3 | 79.9 | 19.7 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 23.5-25.0 | 26.8 | 0.1 | 89.4 | 10.5 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 28.5-30.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 8.2 | 9.5 | 488 | 8360 | -- |
| | 33.5-35.0 | 39.0 | 0.0 | 67.2 | 32.8 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 43.5-45.0 | 33.4 | 0.0 | 79.1 | 20.9 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 53.5-55.0 | 38.9 | 0.8 | 73.2 | 26.0 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| B-6 | 2.0-4.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 0.53 | -- | -- | -- | -- | -- |
| | 4.0-6.0 | 28.4 | 0.0 | 82.8 | 17.2 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 8.0-10.0 | 24.6 | 0.0 | 84.3 | 15.7 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 13.5-15.0 | 34.8 | 0.3 | 73.6 | 26.1 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 23.5-25.0 | 24.8 | 0.0 | 86.3 | 13.7 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 28.5-30.0 | 28.8 | 0.0 | 89.0 | 11.0 | NP | NP | NP | SP-SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 38.5-40.0 | 27.5 | 0.0 | 81.7 | 18.3 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 58.5-60.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 7.7 | 85 | 763 | 16000 | -- |

**US-21 BRIDGE REPLACEMENT OVER HARBOR RIVER**
**BEAUFORT COUNTY, SOUTH CAROLINA**
**F&ME PROJECT NO.: G5396.00**

**FINAL LABORATORY ANALYSIS SUMMARY**

| BORING NUMBER | SAMPLE DEPTH (ft) | % MOISTURE | % GRAVEL | % SAND | % FINES (SILT/CLAY) | LL | PL | PI | USCS | AASHTO Class | % ORGANICS | pH | Resistivity (Ohm-cm) | Sulfate (mg/kg) | Chloride (mg/kg) | Carbonate (% Calcite Equivalent) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| B-7 | 4.0-6.0 | 24.2 | 4.0 | 83.2 | 12.8 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 8.0-10.0 | 33.1 | 3.0 | 78.8 | 18.2 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 13.5-15.0 | 31.3 | 0.3 | 80.9 | 18.9 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 18.5-20.0 | 24.2 | 4.0 | 85.1 | 10.8 | NP | NP | NP | SP-SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 28.5-30.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 8 |
| | 43.5-45.0 | 38.0 | 0.0 | 82.1 | 17.9 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| B-8 | 4.0-6.0 | 24.0 | 1.0 | 87.2 | 11.9 | NP | NP | NP | SP-SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 18.5-20.0 | 73.8 | 0.0 | 32.5 | 67.5 | 34 | 20 | 14 | CL | A-6(8) | -- | -- | -- | -- | -- | -- |
| | 23.5-25.0 | 54.5 | 0.2 | 64.8 | 34.9 | 30 | 19 | 11 | SC | A-2-6(0) | -- | -- | -- | -- | -- | -- |
| | 28.5-30.0 | 38.8 | 1.0 | 77.0 | 22.0 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 33.5-35.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 16 |
| | 43.5-45.0 | 27.3 | 0.0 | 93.5 | 6.5 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 48.5-50.0 | 37.1 | 0.0 | 91.8 | 8.2 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| B-9 | 2.0-4.0 | 22.6 | 8.4 | 83.8 | 7.7 | NP | NP | NP | SP-SM | A-1-b | -- | -- | -- | -- | -- | -- |
| | 4.0-6.0 | 21.9 | 2.2 | 90.7 | 7.2 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 8.0-10.0 | 25.6 | 0.1 | 89.6 | 10.3 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 13.5-15.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 5 |
| | 28.5-30.0 | 88.5 | 0.2 | 20.7 | 79.1 | 58 | 30 | 28 | CH | A-7-5(24) | -- | -- | -- | -- | -- | -- |
| | 43.5-45.0 | 25.6 | 1.2 | 91.4 | 7.5 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| B-10 | 3.5-5.5 | 50.0 | 0.0 | 58.9 | 41.1 | 26 | 17 | 9 | SC | A-4(1) | -- | -- | -- | -- | -- | -- |
| | 7.5-9.5 | 24.1 | 0.0 | 92.1 | 7.9 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 25.0-26.5 | 58.3 | 0.0 | 42.8 | 57.2 | 33 | 26 | 7 | ML | A-4(2) | -- | -- | -- | -- | -- | -- |
| | 30.5-32.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 7.1 | 62 | 2400 | 8400 | -- |
| | 46.0-47.5 | 21.9 | 7.0 | 87.0 | 6.0 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 56.5-58.0 | 58.1 | 2.8 | 66.2 | 31.0 | 39 | 27 | 12 | SM | A-2-6(0) | -- | -- | -- | -- | -- | -- |
| | 86.5-88.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 460 |
| B-11 | 26.0-28.0 | 33.7 | 0.0 | 81.8 | 18.1 | 22 | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 28.0-30.0 | 57.6 | 0.5 | 47.4 | 52.1 | 26 | 17 | 9 | CL | A-4(2) | -- | -- | -- | -- | -- | -- |
| | 30.0-32.0 | 30.5 | 0.2 | 84.5 | 15.3 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 36.5-38.0 | 93.7 | 0.0 | 12.1 | 87.9 | 58 | 35 | 23 | MH | A-7-5(25) | -- | -- | -- | -- | -- | -- |
| | 68.5-70.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 451 |
| | 83.0-84.5 | 45.3 | 0.3 | 53.7 | 46.0 | 31 | NP | NP | SM | A-4(0) | -- | -- | -- | -- | -- | -- |
| | 92.5-94.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 7.0 | 101 | 2000 | 5700 | -- |
| B-12 | 37.0-39.0 | 32.9 | 1.3 | 74.9 | 23.8 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 45.5-47.0 | 24.6 | 6.4 | 83.2 | 10.4 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 61.0-62.5 | 81.2 | 0.0 | 52.0 | 48.0 | 51 | NP | NP | SM | A-5(0) | -- | -- | -- | -- | -- | -- |
| | 80.0-81.5 | 61.8 | 0.0 | 53.4 | 46.6 | 44 | 31 | 13 | SM | A-7-5(4) | -- | -- | -- | -- | -- | -- |
| | 96.5-98.0 | 33.7 | 0.9 | 49.3 | 49.7 | 30 | NP | NP | SM | A-4(0) | -- | -- | -- | -- | -- | -- |
| | 115.5-117.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 493 |
| B-13 | 32.0-34.0 | 34.6 | 4.4 | 72.8 | 22.8 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 42.5-44.0 | 63.6 | 0.0 | 35.8 | 64.2 | 41 | 20 | 21 | CL | A-7-6(11) | -- | -- | -- | -- | -- | -- |
| | 52.5-54.0 | 78.3 | 2.1 | 32.6 | 65.3 | 23 | NP | NP | ML | A-4(0) | -- | -- | -- | -- | -- | -- |
| | 58.0-59.5 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 7.2 | 76 | 1700 | 7600 | -- |
| | 63.5-65.0 | 73.8 | 0.2 | 55.9 | 43.9 | 67 | 29 | 38 | SC | A-7-6(11) | -- | -- | -- | -- | -- | -- |
| | 94.5-96.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 460 |
| | 99.5-101.0 | 37.3 | 4.2 | 45.6 | 50.2 | 30 | 24 | 6 | ML | A-4(1) | -- | -- | -- | -- | -- | -- |
| B-14 | 8.0-10.0 | 32.4 | 0.0 | 86.2 | 13.8 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 23.5-25.0 | 38.6 | 0.0 | 82.4 | 17.6 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 28.5-30.0 | 50.9 | 0.3 | 56.0 | 43.7 | 31 | 24 | 7 | SM | A-4(1) | -- | -- | -- | -- | -- | -- |
| | 33.5-35.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 7.4 | 71 | 1600 | 6900 | -- |
| | 38.5-40.0 | 56.1 | 0.0 | 48.0 | 52.0 | 47 | 36 | 11 | ML | A-7-5(4) | -- | -- | -- | -- | -- | -- |
| | 48.5-50.0 | 46.2 | 0.0 | 69.8 | 30.1 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 72.5-74.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 40 |

**US-21 BRIDGE REPLACEMENT OVER HARBOR RIVER**
**BEAUFORT COUNTY, SOUTH CAROLINA**
**F&ME PROJECT NO.: G5396.00**

**FINAL LABORATORY ANALYSIS SUMMARY**

| BORING NUMBER | SAMPLE DEPTH (ft) | % MOISTURE | % GRAVEL | % SAND | % FINES (SILT/CLAY) | LL | PL | PI | USCS | AASHTO Class | % ORGANICS | pH | Resistivity (Ohm-cm) | Sulfate (mg/kg) | Chloride (mg/kg) | Carbonate (% Calcite Equivalent) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| B-15 | 4.0-6.0 | 26.2 | 0.0 | 91.8 | 8.2 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 6.0-8.0 | 23.5 | 0.0 | 94.9 | 5.1 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 13.5-15.0 | 23.8 | 0.0 | 94.5 | 5.5 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | -- |
| | 18.5-20.0 | 33.2 | 0.2 | 82.3 | 17.5 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 38.5-40.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 4.15 | -- | -- | -- | -- | -- |
| | 43.5-45.0 | 31.6 | 0.6 | 78.7 | 20.7 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 58.5-60.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 8 |
| B-16 | 6.0-8.0 | 24.5 | 0.0 | 97.9 | 2.1 | NP | NP | NP | SP | A-3 | -- | -- | -- | -- | -- | -- |
| | 13.5-15.0 | 24.3 | 0.0 | 97.9 | 2.1 | NP | NP | NP | SP | A-3 | -- | -- | -- | -- | -- | -- |
| | 23.5-25.0 | 37.4 | 0.0 | 86.1 | 13.9 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 38.5-40.0 | 56.7 | 0.0 | 53.4 | 46.6 | 36 | 21 | 15 | SC | A-6(4) | -- | -- | -- | -- | -- | -- |
| | 48.5-50.0 | 84.8 | 0.0 | 9.0 | 91.0 | 75 | 35 | 40 | MH | A-7-5(25) | -- | -- | -- | -- | -- | -- |
| | 53.5-55.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 7.22 | -- | -- | -- | -- | -- |
| | 78.5-80.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 15 |
| TS-1 | 6.0-8.0 | 25.9 | 0.3 | 85.8 | 13.9 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 16.0-18.0 | 52.2 | 0.0 | 50.3 | 49.7 | 25 | 21 | 4 | SC-SM | A-4(0) | -- | -- | -- | -- | -- | -- |
| | 22.0-24.0 | 26.7 | 0.0 | 83.7 | 16.3 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 26.0-28.0 | 65.5 | 0.0 | 34.4 | 65.6 | 42 | 27 | 15 | ML | A-7-6(9) | -- | -- | -- | -- | -- | -- |
| | 32.0-34.0 | 40.2 | 1.0 | 70.7 | 28.3 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 44.0-46.0 | 24.0 | 3.7 | 84.1 | 12.2 | NP | NP | NP | SM | A-2-4 | -- | -- | -- | -- | -- | -- |
| | 46.0-48.0 | 20.1 | 10.1 | 80.1 | 9.8 | NP | NP | NP | SP-SM | A-1-b | -- | -- | -- | -- | -- | -- |
| | 56.0-58.0 | 62.4 | 0.0 | 35.8 | 64.2 | 44 | 39 | 5 | ML | A-5(4) | -- | -- | -- | -- | -- | -- |
| | 72.0-74.0 | 61.7 | 0.6 | 32.1 | 67.4 | 55 | 32 | 23 | MH | A-7-5(16) | -- | -- | -- | -- | -- | -- |
| | 76.0-78.0 | 44.5 | 2.0 | 33.3 | 64.7 | 31 | 23 | 8 | ML | A-4(4) | -- | -- | -- | -- | -- | -- |
| | 80.0-82.0 | 42.6 | 0.0 | 50.9 | 49.1 | NP | NP | NP | SM | A-4(0) | -- | -- | -- | -- | -- | -- |
| | 104.0-106.0 | 33.4 | 0.0 | 43.2 | 56.8 | NP | NP | NP | ML | A-4(0) | -- | -- | -- | -- | -- | -- |
| | 120.0-122.0 | 35.4 | 0.2 | 44.5 | 55.3 | NP | NP | NP | ML | A-4(0) | -- | -- | -- | -- | -- | -- |
| SB-1 | 18.0-20.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 1.92 | -- | -- | -- | -- | -- |
| | 36.0-38.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 1.42 | -- | -- | -- | -- | -- |
| | 44.0-46.0 | 55.4 | 0.6 | 67.5 | 31.9 | 42 | 20 | 22 | SC | A-2-7(2) | -- | -- | -- | -- | -- | -- |
| | 93.5-95.0 | 44.7 | 2.2 | 56.5 | 41.3 | NP | NP | NP | SM | A-4(0) | -- | -- | -- | -- | -- | -- |
| | 138.5-140.0 | 68.0 | 0.0 | 13.7 | 86.3 | 63 | 29 | 34 | CH | A-7-6(33) | -- | -- | -- | -- | -- | -- |
| | 168.5-170.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 509 |
| | 178.5-180.0 | 32.9 | 0.2 | 56.3 | 43.5 | NP | NP | NP | SM | A-4(0) | -- | -- | -- | -- | -- | -- |
| | 198.5-200.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 443 |
| | 238.5-240.0 | 34.4 | 0.0 | 12.2 | 87.8 | 40 | 23 | 17 | CL | A-6(16) | -- | -- | -- | -- | -- | -- |
| | 255.0-257.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 361 |
| | 275.0-277.0 | 30.1 | 0.0 | 28.7 | 71.3 | 32 | 30 | 2 | ML | A-4(1) | -- | -- | -- | -- | -- | -- |
| | 303.0-308.0 | 30.3 | 23.6 | 23.2 | 53.3 | 37 | 34 | 3 | ML | A-4(1) | -- | -- | -- | -- | -- | -- |
| | 308.0-313.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 320 |
| | 338.0-343.0 | 25.9 | 0.6 | 16.5 | 82.9 | 40 | 26 | 14 | ML | A-6(12) | -- | -- | -- | -- | -- | -- |
| | 358.0-363.0 | 17.4 | 8.6 | 26.8 | 64.6 | 33 | 24 | 9 | ML | A-4(4) | -- | -- | -- | -- | -- | -- |
| | 373.0-378.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 222 |
| | 381.0-385.0 | 38.3 | 0.0 | 5.3 | 94.7 | 63 | 38 | 25 | MH | A-7-5(31) | -- | -- | -- | -- | -- | -- |
| $H_20$ - River West | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 6.8 | 27 | 22,715 mg/L | 16,596 mg/L | -- |
| $H_20$ - River East | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 6.9 | 26 | 23,227 mg/L | 16,396 mg/L | -- |

**US-21 Bridge Replacement over Harbor River**
**BEAUFORT COUNTY, SOUTH CAROLINA**
**F&ME PROJECT NO.: G5396.00**

**FINAL LABORATORY ANALYSIS SUMMARY**

| BORING NUMBER | SAMPLE DEPTH (ft) | % MOISTURE | % GRAVEL | % SAND | % FINES (SILT/CLAY) | LL | PL | PI | USCS | AASHTO Class | CU Triaxial Shear | | | | UC Strength (psi) | Standard Proctor | | Direct Shear (φ) | Consolidation | Resonant Column |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | φ | C (psf) | φ' | C' (psi) | | Optimum Moisture Content (%) | Maximum Dry Density (pcf) | | | |
| AP-1 | 16.0-18.0 | 63.0 | 0.0 | 39.0 | 61.0 | 65 | 21 | 44 | CH | A-7-6(24) | -- | -- | 29.0 | 0.878 | -- | -- | -- | -- | See Results | -- |
| | 18.0-20.0 | 86.3 | 0.2 | 26.5 | 73.3 | 111 | 34 | 77 | CH | A-7-5(60) | -- | -- | 38.0 | 0.5 | -- | -- | -- | -- | See Results | -- |
| AP-2 | 16.0-18.0 | 56.0 | 2.1 | 48.0 | 49.9 | 66 | 22 | 44 | SC | A-7-6(17) | -- | -- | 31.5 | 0.435 | -- | -- | -- | -- | See Results | -- |
| | 18.0-20.0 | 69.3 | 0.0 | 36.5 | 63.5 | 81 | 27 | 54 | CH | A-7-6(33) | -- | -- | 18.5 | 1.85 | -- | -- | -- | -- | See Results | -- |
| AP-3 | 25.0-27.0 | 83.0 | 0.1 | 20.4 | 79.5 | 85 | 27 | 58 | CH | A-7-6(50) | -- | -- | 26.0 | 1.5 | -- | -- | -- | -- | See Results | -- |
| | 27.0-29.0 | 78.8 | 0.1 | 18.5 | 81.4 | 74 | 25 | 49 | CH | A-7-6(43) | -- | -- | 7.2 | 2.95 | -- | -- | -- | -- | See Results | -- |
| AP-4 | 38.0-40.0 | 69.0 | 0.0 | 28.7 | 71.3 | 71 | 24 | 47 | CH | A-7-6(34) | -- | -- | -- | -- | -- | -- | -- | -- | See Results | -- |
| | 40.0-42.0 | 33.8 | 0.2 | 78.4 | 21.5 | NP | NP | NP | SM | A-2-4 | 13.0 | 4.1 | 24.0 | 4.1 | -- | -- | -- | -- | -- | -- |
| | 70.0-72.0 | 58.8 | 0.0 | 48.0 | 52.0 | NP | NP | NP | ML | A-4(0) | 34.0 | 0.0 | -- | -- | -- | -- | -- | -- | -- | -- |
| AP-5 | 6.0-10.0 | 21.6 | 0.0 | 97.0 | 3.0 | NP | NP | NP | SP | A-3 | -- | -- | -- | -- | -- | -- | -- | 32.1 | -- | -- |
| | 30.0-32.0 | 26.6 | 0.0 | 97.1 | 2.9 | NP | NP | NP | SP | A-3 | -- | -- | -- | -- | -- | -- | -- | 27.9 | -- | -- |
| SB-1 | 130.0-133.0 | 38.0 | 0.0 | 33.7 | 66.3 | 42 | 30 | 12 | ML | A-7-5(8) | -- | -- | -- | -- | -- | -- | -- | -- | -- | See Results |
| | 145.0-148.0 | 33.1 | 0.2 | 42.5 | 57.3 | 38 | 25 | 13 | ML | A-6(6) | -- | -- | 40.7 | 1.05 | -- | -- | -- | -- | -- | -- |
| | 200.0-203.0 | 32.0 | 0.1 | 47.8 | 52.1 | 43 | 27 | 16 | ML | A-7-6(6) | -- | -- | -- | -- | -- | -- | -- | -- | -- | See Results |
| | 230.0-233.0 | 32.6 | 1.0 | 21.3 | 77.7 | 48 | 30 | 18 | ML | A-7-5(15) | | | 29.2 | 16.5 | -- | -- | -- | -- | -- | -- |
| | 250.0-255.0 | 29.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 143.5 | -- | -- | -- | -- | -- |
| | 257.0-260.0 | 31.6 | 0.0 | 34.9 | 65.1 | 76 | 21 | 55 | CH | A-7-6(34) | -- | -- | -- | -- | -- | -- | -- | -- | -- | See Results |
| | 298.0-303.0 | 31.7 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 166.5 | -- | -- | -- | -- | -- |
| | 323.0-328.0 | 22.3 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 85.9 | -- | -- | -- | -- | -- |
| | 358.0-363.0 | 26.8 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 236.4 | -- | -- | -- | -- | -- |
| | 378.0-381.0 | 39.3 | 0.0 | 12.2 | 87.8 | 133 | 29 | 104 | CH | A-7-6(104) | -- | -- | -- | -- | -- | -- | -- | -- | -- | See Results |
| | 381.0-385.0 | 32.3 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 233.5 | -- | -- | -- | -- | -- |
| BS-1 | 0.0-5.0 | 5.3 | 11.4 | 81.0 | 7.6 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | 17.3 | 100.3 | 34.4 | -- | -- |
| BS-2 | 0.0-5.0 | 5.6 | 5.4 | 86.2 | 8.3 | NP | NP | NP | SP-SM | A-3 | -- | -- | -- | -- | -- | 16.6 | 100.8 | 32.6 | -- | -- |
| BS-3 | 0.0-5.0 | 1.3 | 0.1 | 98.2 | 1.7 | NP | NP | NP | SP | A-3 | -- | -- | -- | -- | -- | 18.1 | 97.8 | 33.5 | -- | -- |
| BS-4 | 0.0-5.0 | 2.6 | 0.6 | 96.6 | 2.9 | NP | NP | NP | SP | A-3 | -- | -- | -- | -- | -- | 15.8 | 94.6 | 31.0 | -- | -- |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 14-1273 | **DATE SAMPLE RECEIVED:** | 9/3/2014 |
| **DESCRIPTION OF SOIL:** | Various | | |
| **TESTED BY:** | KB | **DATE OF TESTING:** | 9/3/2014 |
| | | **DATE OF WEIGHING:** | 9/4/2014 |

| **BORING NO.** | B-1 | B-1 | B-1 | B-1 | B-1 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 14-1273C | 14-1273F | 14-1273I | 14-1273L | 14-1273O |
| **SAMPLE DEPTH** | 8.0'--10.0' | 12.0'-14.0' | 18.0'-20.0' | 28.5'-30.0' | 43.5'-45.0' |
| **WATER CONTENT, W%** | 19.3 | 19.2 | 27.4 | 34.7 | 33.8 |

| **BORING NO.** | B-1 | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 14-1273R | | | | |
| **SAMPLE DEPTH** | 48.5'-50.0' | | | | |
| **WATER CONTENT, W%** | 59.0 | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-1** | **10.0** | **Poorly Graded F/C SAND (SP-SM) with Silt and Gravel A-1-b** | **NP** | **NP** | **NP** | **0.46** | **13.35** |
| ⊠ | **B-1** | **14.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **0.70** | **5.84** |
| ▲ | **B-1** | **20.0** | **Poorly Graded Fine SAND (SP) A-3** | **NP** | **NP** | **NP** | **1.22** | **1.99** |
| ★ | **B-1** | **30.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **0.91** | **1.99** |
| ⊙ | **B-1** | **45.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-2-4** | **NP** | **NP** | **NP** | **1.22** | **2.32** |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-1** | **10.0** | **19.1** | **8.741** | **0.675** | **0.089** | **16.7** | **76.0** | **7.3** | |
| ⊠ | **B-1** | **14.0** | **19.1** | **8.544** | **0.321** | **0.083** | **8.4** | **83.7** | **8.0** | |
| ▲ | **B-1** | **20.0** | **2** | **0.373** | **0.163** | **0.087** | **0.0** | **96.7** | **3.3** | |
| ★ | **B-1** | **30.0** | **9.52** | **0.69** | **0.141** | **0.078** | **0.2** | **92.4** | **7.4** | |
| ⊙ | **B-1** | **45.0** | **9.52** | **0.418** | **0.16** | | **0.4** | **88.6** | **11.0** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-1** | **50.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-1** | **50.0** | **4.76** | **0.322** | **0.108** | | **0.0** | **66.8** | **33.2** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-1** | **10.0** | **NP** | **NP** | **NP** | **7** | **Poorly Graded F/C SAND (SP-SM) with Silt and Gravel A-1-b** |
| ⊠ | **B-1** | **14.0** | **NP** | **NP** | **NP** | **8** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ▲ | **B-1** | **20.0** | **NP** | **NP** | **NP** | **3** | **Poorly Graded Fine SAND (SP) A-3** |
| ★ | **B-1** | **30.0** | **NP** | **NP** | **NP** | **7** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ⊙ | **B-1** | **45.0** | **NP** | **NP** | **NP** | **11** | **Poorly Graded Fine SAND (SP-SM) with Silt A-2-4** |
| ✿ | **B-1** | **50.0** | **NP** | **NP** | **NP** | **33** | **Silty Fine SAND (SM) A-2-4** |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## ORGANIC IMPURITIES DETERMINATION
## (AASHTO T267)

**PROJECT:** US 21 Bridge Replacement over Harbor River

**PROJECT NO.:** G5396

**SAMPLE NUMBER:** 14-1273

**DATE SAMPLE RECEIVED:** 9/4/2014

**DESCRIPTION OF SOIL:** Various

**TESTED BY:** JH

**DATE OF TESTING:** 9/8/2014

**DATE OF WEIGHING:** 9/8/2014

| **BORING NO.** | B-1 | B-1 | B-1 | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 14-1273S | 14-1273T | 14-1273U | | |
| **SAMPLE DEPTH** | 4.0'-6.0' | 6.0'-8.0' | 14.0'-16.0' | | |
| **WT. OF CRUCIBLE + DRY SOIL (BEFORE IGNITION) (GRAMS)** | 171.13 | 173.78 | 149.23 | | |
| **WT. OF CRUCIBLE + DRY SOIL (AFTER IGNITION) (GRAMS)** | 170.71 | 173.37 | 149.11 | | |
| **WT. OF CRUCIBLE (GRAMS)** | 134.66 | 135.55 | 110.79 | | |
| **WT. OF DRY SOIL (BEFORE IGNITION) (GRAMS)** | 36.47 | 38.23 | 38.44 | | |
| **WT. OF DRY SOIL (AFTER IGNITION) (GRAMS)** | 36.05 | 37.82 | 38.32 | | |
| **IGNITION LOSS (GRAMS)** | 0.42 | 0.41 | 0.12 | | |
| **ORGANIC IMPURITIES %** | 1.15 | 1.07 | 0.31 | | |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 14-1328 | **DATE SAMPLE RECEIVED:** | 9/4/2014 |
| **DESCRIPTION OF SOIL:** | Various | | |
| **TESTED BY:** | KB | **DATE OF TESTING:** | 9/5/2014 |
| | | **DATE OF WEIGHING:** | 9/8/2014 |

| **BORING NO.** | B-2 | B-2 | B-2 | B-2 | B-2 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 14-1328F | 14-1328I | 14-1328L | 14-1328O | 14-1328R |
| **SAMPLE DEPTH** | 6.0'-8.0' | 8.0'-10.0' | 18.0'-20.0' | 28.5'-30.0' | 38.5'-40.0' |
| **WATER CONTENT, W%** | 28.7 | 27.9 | 26.5 | 30.3 | 29.3 |

| **BORING NO.** | B-2 | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 14-1328U | | | | |
| **SAMPLE DEPTH** | 53.5'-55.0' | | | | |
| **WATER CONTENT, W%** | 28.4 | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | B-2 | 8.0 | Poorly Graded Fine SAND (SP) A-3 | NP | NP | NP | 1.42 | 2.03 |
| ⊠ | B-2 | 10.0 | Poorly Graded Fine SAND (SP) A-3 | NP | NP | NP | 1.22 | 2.02 |
| ▲ | B-2 | 20.0 | Poorly Graded Fine SAND (SP-SM) with Silt A-3 | NP | NP | NP | 1.09 | 2.06 |
| ★ | B-2 | 30.0 | Silty Fine SAND (SM) A-2-4 | NP | NP | NP | | |
| ⊙ | B-2 | 40.0 | Poorly Graded Fine SAND (SP-SM) with Silt A-3 | NP | NP | NP | 1.29 | 2.27 |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | B-2 | 8.0 | 2 | 0.385 | 0.172 | 0.091 | 0.0 | 95.1 | 4.9 | |
| ⊠ | B-2 | 10.0 | 2 | 0.394 | 0.176 | 0.1 | 0.0 | 97.5 | 2.5 | |
| ▲ | B-2 | 20.0 | 4.76 | 0.362 | 0.157 | 0.081 | 0.0 | 93.7 | 6.3 | |
| ★ | B-2 | 30.0 | 9.52 | 0.393 | 0.153 | | 0.3 | 85.7 | 14.0 | |
| ⊙ | B-2 | 40.0 | 9.52 | 0.39 | 0.165 | 0.077 | 0.1 | 91.1 | 8.8 | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |


| BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|
| ● **B-2** | **55.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **1.54** | **2.83** |

| BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|
| ● **B-2** | **55.0** | **9.52** | **0.405** | **0.179** | | **0.3** | **89.7** | **10.0** | |

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-2** | **8.0** | **NP** | **NP** | **NP** | **5** | **Poorly Graded Fine SAND (SP) A-3** |
| ⊠ | **B-2** | **10.0** | **NP** | **NP** | **NP** | **3** | **Poorly Graded Fine SAND (SP) A-3** |
| ▲ | **B-2** | **20.0** | **NP** | **NP** | **NP** | **6** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ★ | **B-2** | **30.0** | **NP** | **NP** | **NP** | **14** | **Silty Fine SAND (SM) A-2-4** |
| ⊙ | **B-2** | **40.0** | **NP** | **NP** | **NP** | **9** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ✿ | **B-2** | **55.0** | **NP** | **NP** | **NP** | **10** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |

ATTERBERG LIMITS G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## ORGANIC IMPURITIES DETERMINATION
## (AASHTO T267)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 14-1328 | **DATE SAMPLE RECEIVED:** | 9/4/2014 |
| **DESCRIPTION OF SOIL:** | Various | | |
| **TESTED BY:** | JH | **DATE OF TESTING:** | 9/8/2014 |
| | | **DATE OF WEIGHING:** | 9/8/2014 |

| **BORING NO.** | B-2 | B-2 | B-2 | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 14-1328A | 14-1328B | 14-1328C | | |
| **SAMPLE DEPTH** | 4.0'-6.0' | 10.0'-12.0' | 23.5'-25.0' | | |
| **WT. OF CRUCIBLE + DRY SOIL (BEFORE IGNITION) (GRAMS)** | 171.92 | 171.93 | 172.55 | | |
| **WT. OF CRUCIBLE + DRY SOIL (AFTER IGNITION) (GRAMS)** | 171.71 | 171.75 | 172.09 | | |
| **WT. OF CRUCIBLE (GRAMS)** | 134.66 | 132.08 | 135.70 | | |
| **WT. OF DRY SOIL (BEFORE IGNITION) (GRAMS)** | 37.26 | 39.85 | 36.85 | | |
| **WT. OF DRY SOIL (AFTER IGNITION) (GRAMS)** | 37.05 | 39.67 | 36.39 | | |
| **IGNITION LOSS (GRAMS)** | 0.21 | 0.18 | 0.46 | | |
| **ORGANIC IMPURITIES %** | 0.56 | 0.45 | 1.25 | | |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396.00 |
| **SAMPLE NUMBER:** | 15-1436 | **DATE SAMPLE RECEIVED:** | 10/1/2015 |
| **DESCRIPTION OF SOIL:** | Various | | |
| **TESTED BY:** | MM | **DATE OF TESTING:** | 10/1/2015 |
| | | **DATE OF WEIGHING:** | 10/2/2015 |

| **BORING NO.** | B-3 | B-3 | B-3 | B-3 | B-3 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 15-1436C | 15-1436G | 15-1436J | 15-1436Q | 15-1436T |
| **SAMPLE DEPTH** | 0.0-2.0' | 6.0-8.0' | 13.5-15.0' | 23.5-25.0' | 28.5-30.0' |
| **WATER CONTENT, W%** | 36.9 | 151.6 | 26.1 | 29.3 | 101.1 |

| **BORING NO.** | B-3 | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 15-1436W | | | | |
| **SAMPLE DEPTH** | 38.5-40.0' | | | | |
| **WATER CONTENT, W%** | 30.2 | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |


| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | B-3 | 2.0 | Silty Fine SAND (SM) A-4(0) | NP | NP | NP | | |
| ⊠ | B-3 | 8.0 | Elastic SILT (MH) A-7-5(36) | 74 | 49 | 25 | | |
| ▲ | B-3 | 15.0 | Poorly Graded Fine SAND (SP-SM) with Silt A-3 | NP | NP | NP | 1.16 | 2.10 |
| ★ | B-3 | 25.0 | Silty Fine SAND (SM) with Gravel A-2-4 | NP | NP | NP | | |
| ⊙ | B-3 | 30.0 | Elastic SILT (MH) A-7-5(32) | 58 | 31 | 27 | | |

| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | B-3 | 2.0 | 9.52 | 0.401 | 0.155 | | 0.2 | 62.3 | 37.5 | |
| ⊠ | B-3 | 8.0 | 4.76 | | | | 0.0 | 1.5 | 98.5 | |
| ▲ | B-3 | 15.0 | 0.84 | 0.35 | 0.158 | 0.079 | 0.0 | 92.3 | 7.7 | |
| ★ | B-3 | 25.0 | 19.1 | 10.692 | 0.168 | | 15.8 | 59.7 | 24.5 | |
| ⊙ | B-3 | 30.0 | 4.76 | | | | 0.0 | 3.4 | 96.6 | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-3** | **40.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **1.46** | **2.72** |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-3** | **40.0** | **19.1** | **3.709** | **0.172** | | **3.7** | **85.8** | **10.4** | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-3** | **2.0** | **NP** | **NP** | **NP** | **38** | **Silty Fine SAND (SM) A-4(0)** |
| ⊠ | **B-3** | **8.0** | **74** | **49** | **25** | **98** | **Elastic SILT (MH) A-7-5(36)** |
| ▲ | **B-3** | **15.0** | **NP** | **NP** | **NP** | **8** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ★ | **B-3** | **25.0** | **NP** | **NP** | **NP** | **25** | **Silty Fine SAND (SM) with Gravel A-2-4** |
| ⊙ | **B-3** | **30.0** | **58** | **31** | **27** | **97** | **Elastic SILT (MH) A-7-5(32)** |
| ✿ | **B-3** | **40.0** | **NP** | **NP** | **NP** | **10** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## ORGANIC IMPURITIES DETERMINATION
## (AASHTO T267)

**PROJECT:** US 21 Bridge Replacement over Harbor River **PROJECT NO.:** G5396.00

**SAMPLE NUMBER:** 15-1436D **DATE SAMPLE RECEIVED:**

**DESCRIPTION OF SOIL:**

**TESTED BY:** JH **DATE OF TESTING:** 10/13/2015

**DATE OF WEIGHING:** 10/14/2015

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | B-3 | | | | |
| **SAMPLE NO.** | 15-1436D | | | | |
| **SAMPLE DEPTH** | 4.0'-6.0' | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (BEFORE IGNITION) (GRAMS)** | 174.66 | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (AFTER IGNITION) (GRAMS)** | 173.24 | | | | |
| **WT. OF CRUCIBLE (GRAMS)** | 134.66 | | | | |
| **WT. OF DRY SOIL (BEFORE IGNITION) (GRAMS)** | 40.00 | | | | |
| **WT. OF DRY SOIL (AFTER IGNITION) (GRAMS)** | 38.58 | | | | |
| **IGNITION LOSS (GRAMS)** | 1.42 | | | | |
| **ORGANIC IMPURITIES %** | 3.55 | | | | |

# Determining pH of Soil for Use in Corrosion Testing
## AASHTO T 289

| | | | |
|---|---|---|---|
| PROJECT TITLE | F&ME/HARBOR RIVER/SC | SAMPLE ID | B-3 15-1436M |
| PROJECT NO. | 1524908.09 | SAMPLE TYPE | Bag |
| REMARKS | F&ME Project No. G5396 | SAMPLE DEPTH | 18.5 - 20.0' |

**SAMPLE PREPARATION**

| | |
|---|---|
| Sieved through the #10 Sieve | YES |
| Air Dry | YES |
| Type of Water | DISTILLED |

| Trial | pH | Temperature |
|---|---|---|
| 1 | 7.90 | 20.0 |
| 2 | 7.88 | 20.1 |
| 3 | 7.89 | 20.2 |
| **AVERAGE** | 7.89 | 20.1 |

**Description** SILTY SAND; dark gray, sea shells.

**USCS** (SM)

| | |
|---|---|
| TECH | TJ |
| DATE | 10/13/15 |
| CHECK | |
| REVIEW | |
| APPROVE | |

# Determining Minimum Laboratory Soil Resistivity
## AASHTO T 288

| | | | | |
|---|---|---|---|---|
| PROJECT TITLE | F&ME/HARBOR RIVER/SC | SAMPLE ID | B-3 | 15-1436N |
| PROJECT NO. | 1524908.09 | SAMPLE TYPE | Bag | |
| REMARKS | F&ME Project No. G5396 | SAMPLE DEPTH | 18.5 - 20.0' | |


| | | |
|---|---|---|
| SAMPLE PREPARATION | Sieved through the #10 Sieve | Yes |
| TEST APPARATUS | Miller Soilbox and Nilsson 400 Soil Resistance Meter. | |

Identification: Lowest resistivity

| SPECIMEN (Point) | 1 | 2 | 3 | 4 |
|---|---|---|---|---|
| RESISTIVITY (ohms-cm) | 800 | 300 | 200 | 250 |

MOISTURE CONTENT

| | | | | |
|---|---|---|---|---|
| WET WEIGHT & TARE | 89.43 | 106.77 | 116.52 | 195.83 |
| DRY WEIGHT & TARE | 84.60 | 95.73 | 98.93 | 135.24 |
| TARE WEIGHT | 51.00 | 52.02 | 52.10 | 52.15 |
| WEIGHT OF MOISTURE (gm) | 4.83 | 11.04 | 17.59 | 60.59 |
| WEIGHT OF DRY SOIL (gm) | 33.60 | 43.71 | 46.83 | 83.09 |
| MOISTURE CONTENT (%) | 14.38 | 25.26 | 37.56 | 72.92 |




Description: SILTY SAND; dark gray, sea shells.

USCS: (SM)

| | |
|---|---|
| TECH | TJ |
| DATE | 10/13/15 |
| CHECK | |
| REVIEW | |
| APPROVE | |

ACL

ADVANCED CHEMISTRY LABS, INC.

Phone: (770) 409-1444
Fax: (770) 409-1844
e-mail: acl@acl-labs.net

3039 Amwiler Road • Suite 100 • Atlanta, GA 30360
P.O. Box 88610 • Atlanta, GA 30356
www.acl-labs.com

**Client:** Golder Associates, Inc.
3730 Chamblee Tucker Road
Atlanta, GA 30341-0000

**Client Proj #:** 1524908
**ACL Project #:** 68442
**Date Received:** 10/13/2015
**Date Reported:** 10/30/2015

**Contact:** Mr. Henry Mock

**Sample ID:** B-3 18.5-20'

**Matrix:** Soil

**ACL #:** 307835

**Date/Time Sampled:** 10/13/2015 11:15

| Analyte (Method) | Result | PQL | Units | DF | Prep Date/Time | Analysis Date/Time | Analyst |
|---|---|---|---|---|---|---|---|
| Sol. Chloride (9252A)* | 5080 | 500 | mg/kg | 50 | 10/16/2015 8:30 | 10/16/2015 8:30 | MM |
| Sol. Sulfate (9038)* | 126 | 50 | mg/kg | 5 | 10/19/2015 10:20 | 10/19/2015 10:20 | MM |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396.00 |
| **SAMPLE NUMBER:** | 15-1437 | **DATE SAMPLE RECEIVED:** | 10/1/2015 |
| **DESCRIPTION OF SOIL:** | Various | | |
| **TESTED BY:** | MM | **DATE OF TESTING:** | 10/1/2015 |
| | | **DATE OF WEIGHING:** | 10/2/2015 |

| **BORING NO.** | B-4 | B-4 | B-4 | B-4 | B-4 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 15-1437C | 15-1437G | 15-1437J | 15-1437M | 15-1437P |
| **SAMPLE DEPTH** | 2.0-4.0' | 8.0-10.0' | 13.5-15.0' | 23.5-25.0' | 33.5-35.0' |
| **WATER CONTENT, W%** | 52.5 | 32.9 | 31.8 | 27.8 | 35.8 |

| **BORING NO.** | B-4 | B-4 | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 15-1437W | 15-1437Z | | | |
| **SAMPLE DEPTH** | 48.5-50.0' | 63.5-65.0' | | | |
| **WATER CONTENT, W%** | 31.8 | 64.5 | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|
| ● B-4 | 4.0 | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ⊠ B-4 | 10.0 | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ▲ B-4 | 15.0 | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ★ B-4 | 25.0 | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ⊙ B-4 | 35.0 | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |


| BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|
| ● B-4 | 4.0 | **25.4** | **3.699** | **0.158** | | **4.9** | **63.2** | **31.9** | |
| ⊠ B-4 | 10.0 | **19.1** | **0.411** | **0.153** | | **1.2** | **72.9** | **26.0** | |
| ▲ B-4 | 15.0 | **2** | **0.384** | **0.175** | | **0.0** | **84.9** | **15.1** | |
| ★ B-4 | 25.0 | **9.52** | **2.034** | **0.162** | | **1.1** | **76.9** | **22.0** | |
| ⊙ B-4 | 35.0 | **9.52** | **1.13** | **0.16** | | **1.6** | **76.8** | **21.6** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-4** | **50.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ⊠ | **B-4** | **65.0** | **Sandy Elastic SILT (MH) A-7-5(16)** | **71** | **35** | **36** | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-4** | **50.0** | **19.1** | **0.4** | **0.166** | | **0.6** | **82.4** | **17.0** | |
| ⊠ | **B-4** | **65.0** | **4.76** | **0.176** | | | **0.0** | **46.9** | **53.1** | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-4** | **4.0** | **NP** | **NP** | **NP** | **32** | **Silty Fine SAND (SM) A-2-4** |
| ⊠ | **B-4** | **10.0** | **NP** | **NP** | **NP** | **26** | **Silty Fine SAND (SM) A-2-4** |
| ▲ | **B-4** | **15.0** | **NP** | **NP** | **NP** | **15** | **Silty Fine SAND (SM) A-2-4** |
| ★ | **B-4** | **25.0** | **NP** | **NP** | **NP** | **22** | **Silty Fine SAND (SM) A-2-4** |
| ⊙ | **B-4** | **35.0** | **NP** | **NP** | **NP** | **22** | **Silty Fine SAND (SM) A-2-4** |
| ✿ | **B-4** | **50.0** | **NP** | **NP** | **NP** | **17** | **Silty Fine SAND (SM) A-2-4** |
| ○ | **B-4** | **65.0** | **71** | **35** | **36** | **53** | **Sandy Elastic SILT (MH) A-7-5(16)** |

ATTERBERG LIMITS G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## ORGANIC IMPURITIES DETERMINATION
## (AASHTO T267)

**PROJECT:** US 21 Bridge Replacement over Harbor River **PROJECT NO.:** G5396.00

**SAMPLE NUMBER:** 15-1437D **DATE SAMPLE RECEIVED:**

**DESCRIPTION OF SOIL:**

**TESTED BY:** JH **DATE OF TESTING:** 10/13/2015

**DATE OF WEIGHING:** 10/14/2015

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | B-4 | | | | |
| **SAMPLE NO.** | 15-1437D | | | | |
| **SAMPLE DEPTH** | 4.0'-6.0' | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (BEFORE IGNITION) (GRAMS)** | 172.08 | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (AFTER IGNITION) (GRAMS)** | 171.01 | | | | |
| **WT. OF CRUCIBLE (GRAMS)** | 132.08 | | | | |
| **WT. OF DRY SOIL (BEFORE IGNITION) (GRAMS)** | 40.00 | | | | |
| **WT. OF DRY SOIL (AFTER IGNITION) (GRAMS)** | 38.93 | | | | |
| **IGNITION LOSS (GRAMS)** | 1.07 | | | | |
| **ORGANIC IMPURITIES %** | 2.68 | | | | |

# Determining pH of Soil for Use in Corrosion Testing
## AASHTO T 289

| | | | |
|---|---|---|---|
| PROJECT TITLE | F&ME/HARBOR RIVER/SC | SAMPLE ID | B-4 15-1437S |
| PROJECT NO. | 1524908.09 | SAMPLE TYPE | Bag |
| REMARKS | F&ME Project No. G5396 | SAMPLE DEPTH | 38.5 - 40.0' |

**SAMPLE PREPARATION**

| | |
|---|---|
| Sieved through the #10 Sieve | YES |
| Air Dry | YES |
| Type of Water | DISTILLED |

| Trial | pH | Temperature |
|---|---|---|
| 1 | 8.03 | 20.1 |
| 2 | 8.04 | 20.2 |
| 3 | 8.04 | 20.2 |
| **AVERAGE** | 8.04 | 20.2 |

**Description** CLAYEY SAND; olive brown.

**USCS** (SC)

| | |
|---|---|
| TECH | TJ |
| DATE | 10/13/15 |
| CHECK | |
| REVIEW | |
| APPROVE | |

# Determining Minimum Laboratory Soil Resistivity
## AASHTO T 288

| | | | |
|---|---|---|---|
| PROJECT TITLE | F&ME/HARBOR RIVER/SC | SAMPLE ID | B-4 15-1437T |
| PROJECT NO. | 1524908.09 | SAMPLE TYPE | Bag |
| REMARKS | F&ME Project No. G5396 | SAMPLE DEPTH | 38.5 - 40.0' |


SAMPLE PREPARATION — Sieved through the #10 Sieve: Yes
TEST APPARATUS — Miller Soilbox and Nilsson 400 Soil Resistance Meter.

Identification: Lowest resistivity

| SPECIMEN (Point) | 1 | 2 | 3 | 4 |
|---|---|---|---|---|
| RESISTIVITY (ohms-cm) | 780 | 320 | 180 | 230 |

MOISTURE CONTENT

| | | | | |
|---|---|---|---|---|
| WET WEIGHT & TARE | 89.28 | 100.21 | 117.14 | 258.52 |
| DRY WEIGHT & TARE | 83.76 | 89.62 | 97.00 | 123.87 |
| TARE WEIGHT | 50.92 | 51.73 | 51.88 | 51.22 |
| WEIGHT OF MOISTURE (gm) | 5.52 | 10.59 | 20.14 | 134.65 |
| WEIGHT OF DRY SOIL (gm) | 32.84 | 37.89 | 45.12 | 72.65 |
| MOISTURE CONTENT (%) | 16.81 | 27.95 | 44.64 | 185.34 |




Description: CLAYEY SAND; olive brown.

USCS: (SC)

| | |
|---|---|
| TECH | TJ |
| DATE | 10/13/15 |
| CHECK | |
| REVIEW | |
| APPROVE | |

ACL

ADVANCED CHEMISTRY LABS, INC.

Phone: (770) 409-1444
Fax: (770) 409-1844
e-mail: acl@acl-labs.net

3039 Amwiler Road • Suite 100 • Atlanta, GA 30360
P.O. Box 88610 • Atlanta, GA 30356
www.acl-labs.com

**Client:** Golder Associates, Inc.
3730 Chamblee Tucker Road
Atlanta, GA 30341-0000

**Client Proj #:** 1524908
**ACL Project #:** 68442
**Date Received:** 10/13/2015
**Date Reported:** 10/30/2015

**Contact:** Mr. Henry Mock

**Sample ID:** B-4 38.5-40'

**Matrix:** Soil

**ACL #:** 307836

**Date/Time Sampled:** 10/13/2015 11:15

| Analyte (Method) | Result | PQL | Units | DF | Prep Date/Time | Analysis Date/Time | Analyst |
|---|---|---|---|---|---|---|---|
| Sol. Chloride (9252A)* | 8350 | 500 | mg/kg | 50 | 10/16/2015 8:30 | 10/16/2015 8:30 | MM |
| Sol. Sulfate (9038)* | 559 | 200 | mg/kg | 20 | 10/19/2015 10:20 | 10/19/2015 10:20 | MM |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396.00 |
| **SAMPLE NUMBER:** | 15-1438 | **DATE SAMPLE RECEIVED:** | 10/1/2015 |
| **DESCRIPTION OF SOIL:** | Various | | |
| **TESTED BY:** | MM | **DATE OF TESTING:** | 10/1/2015 |
| | | **DATE OF WEIGHING:** | 10/2/2015 |

| **BORING NO.** | B-5 | B-5 | B-5 | B-5 | B-5 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 15-1438C | 15-1438F | 15-1438J | 15-1438M | 15-1438T |
| **SAMPLE DEPTH** | 2.0-4.0' | 6.0-8.0' | 13.5-15.0' | 23.5-25.0' | 33.5-35.0' |
| **WATER CONTENT, W%** | 27.9 | 24.1 | 36.1 | 26.8 | 39.0 |

| **BORING NO.** | B-5 | B-5 | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 15-1438W | 15-1438Z | | | |
| **SAMPLE DEPTH** | 43.5-45.0' | 53.5-55.0' | | | |
| **WATER CONTENT, W%** | 33.4 | 38.9 | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | B-5 | 4.0 | Poorly Graded Fine SAND (SP-SM) with Silt A-3 | NP | NP | NP | 1.39 | 2.27 |
| ⊠ | B-5 | 8.0 | Silty Fine SAND (SM) A-2-4 | NP | NP | NP | | |
| ▲ | B-5 | 15.0 | Silty Fine SAND (SM) A-2-4 | NP | NP | NP | | |
| ★ | B-5 | 25.0 | Poorly Graded Fine SAND (SP-SM) with Silt A-3 | NP | NP | NP | 1.79 | 2.45 |
| ⊙ | B-5 | 35.0 | Silty Fine SAND (SM) A-2-4 | NP | NP | NP | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | B-5 | 4.0 | 9.52 | 0.387 | 0.176 | 0.088 | 0.0 | 93.4 | 6.6 | |
| ⊠ | B-5 | 8.0 | 9.52 | 0.402 | 0.169 | | 0.0 | 85.3 | 14.6 | |
| ▲ | B-5 | 15.0 | 9.52 | 0.332 | 0.113 | | 0.3 | 79.9 | 19.7 | |
| ★ | B-5 | 25.0 | 9.52 | 0.385 | 0.17 | | 0.1 | 89.4 | 10.5 | |
| ⊙ | B-5 | 35.0 | 4.76 | 0.227 | 0.104 | | 0.0 | 67.2 | 32.8 | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-5** | **45.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ⊠ | **B-5** | **55.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-5** | **45.0** | **4.76** | **0.357** | **0.157** | | **0.0** | **79.1** | **20.9** | |
| ⊠ | **B-5** | **55.0** | **9.52** | **1.393** | **0.176** | | **0.8** | **73.2** | **26.0** | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-5** | **4.0** | **NP** | **NP** | **NP** | **7** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ⊠ | **B-5** | **8.0** | **NP** | **NP** | **NP** | **15** | **Silty Fine SAND (SM) A-2-4** |
| ▲ | **B-5** | **15.0** | **NP** | **NP** | **NP** | **20** | **Silty Fine SAND (SM) A-2-4** |
| ★ | **B-5** | **25.0** | **NP** | **NP** | **NP** | **10** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ⊙ | **B-5** | **35.0** | **NP** | **NP** | **NP** | **33** | **Silty Fine SAND (SM) A-2-4** |
| ✿ | **B-5** | **45.0** | **NP** | **NP** | **NP** | **21** | **Silty Fine SAND (SM) A-2-4** |
| ○ | **B-5** | **55.0** | **NP** | **NP** | **NP** | **26** | **Silty Fine SAND (SM) A-2-4** |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## ORGANIC IMPURITIES DETERMINATION
## (AASHTO T267)

**PROJECT:** US 21 Bridge Replacement over Harbor River **PROJECT NO.:** G5396.00

**SAMPLE NUMBER:** 15-1438G **DATE SAMPLE RECEIVED:**

**DESCRIPTION OF SOIL:**

**TESTED BY:** JH **DATE OF TESTING:** 10/13/2015

**DATE OF WEIGHING:** 10/14/2015

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | B-5 | | | | |
| **SAMPLE NO.** | 15-1438G | | | | |
| **SAMPLE DEPTH** | 8.0'-10.0' | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (BEFORE IGNITION) (GRAMS)** | 169.97 | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (AFTER IGNITION) (GRAMS)** | 169.86 | | | | |
| **WT. OF CRUCIBLE (GRAMS)** | 129.97 | | | | |
| **WT. OF DRY SOIL (BEFORE IGNITION) (GRAMS)** | 40.00 | | | | |
| **WT. OF DRY SOIL (AFTER IGNITION) (GRAMS)** | 39.89 | | | | |
| **IGNITION LOSS (GRAMS)** | 0.11 | | | | |
| **ORGANIC IMPURITIES %** | 0.27 | | | | |

# Determining pH of Soil for Use in Corrosion Testing
## AASHTO T 289

| | | | |
|---|---|---|---|
| PROJECT TITLE | F&ME/HARBOR RIVER/SC | SAMPLE ID | B-5 15-1438P |
| PROJECT NO. | 1524908.09 | SAMPLE TYPE | Bag |
| REMARKS | F&ME Project No. G5396 | SAMPLE DEPTH | 28.5 - 30.0' |

**SAMPLE PREPARATION**

| | |
|---|---|
| Sieved through the #10 Sieve | YES |
| Air Dry | YES |
| Type of Water | DISTILLED |

| Trial | pH | Temperature |
|---|---|---|
| 1 | 8.20 | 20.1 |
| 2 | 8.19 | 20.2 |
| 3 | 8.21 | 20.2 |
| **AVERAGE** | 8.20 | 20.2 |

**Description** SILTY CLAY; olive brown.

**USCS** (CL)

| | |
|---|---|
| TECH | TJ |
| DATE | 10/13/15 |
| CHECK | |
| REVIEW | |
| APPROVE | |

# Determining Minimum Laboratory Soil Resistivity
## AASHTO T 288

| | | | |
|---|---|---|---|
| PROJECT TITLE | F&ME/HARBOR RIVER/SC | SAMPLE ID | B-5 15-1438Q |
| PROJECT NO. | 1524908.09 | SAMPLE TYPE | Bag |
| REMARKS | F&ME Project No. G5396 | SAMPLE DEPTH | 28.5 - 30.0' |

SAMPLE PREPARATION — Sieved through the #10 Sieve: Yes


TEST APPARATUS — Miller Soilbox and Nilsson 400 Soil Resistance Meter.

Identification: Lowest resistivity

| SPECIMEN (Point) | 1 | 2 | 3 | 4 |
|---|---|---|---|---|
| RESISTIVITY (ohms-cm) | 550 | 210 | 9.5 | 10.0 |

MOISTURE CONTENT

| | | | | |
|---|---|---|---|---|
| WET WEIGHT & TARE | 108.40 | 132.51 | 131.98 | 358.88 |
| DRY WEIGHT & TARE | 100.56 | 117.40 | 109.63 | 244.07 |
| TARE WEIGHT | 51.87 | 50.72 | 51.50 | 52.16 |
| WEIGHT OF MOISTURE (gm) | 7.84 | 15.11 | 22.35 | 114.81 |
| WEIGHT OF DRY SOIL (gm) | 48.69 | 66.68 | 58.13 | 191.91 |
| MOISTURE CONTENT (%) | 16.10 | 22.66 | 38.45 | 59.82 |




Description: SILTY CLAY; olive brown.

USCS: (CL)

| | |
|---|---|
| TECH | TJ |
| DATE | 10/13/15 |
| CHECK | |
| REVIEW | |
| APPROVE | |

ACL

ADVANCED CHEMISTRY LABS, INC.

Phone: (770) 409-1444
Fax: (770) 409-1844
e-mail: acl@acl-labs.net

3039 Amwiler Road • Suite 100 • Atlanta, GA 30360
P.O. Box 88610 • Atlanta, GA 30356
www.acl-labs.com

**Client:** Golder Associates, Inc.
3730 Chamblee Tucker Road
Atlanta, GA 30341-0000

**Client Proj #:** 1524908
**ACL Project #:** 68442
**Date Received:** 10/13/2015
**Date Reported:** 10/30/2015

**Contact:** Mr. Henry Mock

**Sample ID:** B-5 28.5-30'

**Matrix:** Soil

**ACL #:** 307837

**Date/Time Sampled:** 10/13/2015 11:15

| Analyte (Method) | Result | PQL | Units | DF | Prep Date/Time | Analysis Date/Time | Analyst |
|---|---|---|---|---|---|---|---|
| Sol. Chloride (9252A)* | 8360 | 500 | mg/kg | 50 | 10/16/2015 8:30 | 10/16/2015 8:30 | MM |
| Sol. Sulfate (9038)* | 488 | 200 | mg/kg | 20 | 10/19/2015 10:20 | 10/19/2015 10:20 | MM |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396.00 |
| **SAMPLE NUMBER:** | 15-1439 | **DATE SAMPLE RECEIVED:** | 10/1/2015 |
| **DESCRIPTION OF SOIL:** | Various | | |
| **TESTED BY:** | MM | **DATE OF TESTING:** | 10/1/2015 |
| | | **DATE OF WEIGHING:** | 10/2/2015 |

| **BORING NO.** | B-6 | B-6 | B-6 | B-6 | B-6 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 15-1439D | 15-1439G | 15-1439J | 15-1439M | 15-1439P |
| **SAMPLE DEPTH** | 4.0-6.0' | 8.0-10.0' | 13.5-15.0' | 23.5-25.0' | 28.5-30.0' |
| **WATER CONTENT, W%** | 28.4 | 24.6 | 34.8 | 24.8 | 28.8 |

| **BORING NO.** | B-6 | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 15-1439S | | | | |
| **SAMPLE DEPTH** | 38.5-40.0' | | | | |
| **WATER CONTENT, W%** | 27.5 | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |


| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-6** | **6.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ⊠ | **B-6** | **10.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ▲ | **B-6** | **15.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ★ | **B-6** | **25.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ⊙ | **B-6** | **30.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-2-4** | **NP** | **NP** | **NP** | **1.73** | **2.46** |

| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-6** | **6.0** | **2** | **0.381** | **0.166** | | **0.0** | **82.8** | **17.2** | |
| ⊠ | **B-6** | **10.0** | **4.76** | **0.405** | **0.153** | | **0.0** | **84.3** | **15.7** | |
| ▲ | **B-6** | **15.0** | **9.52** | **0.178** | **0.097** | | **0.3** | **73.6** | **26.1** | |
| ★ | **B-6** | **25.0** | **4.76** | **0.387** | **0.174** | | **0.0** | **86.3** | **13.7** | |
| ⊙ | **B-6** | **30.0** | **4.76** | **0.385** | **0.168** | | **0.0** | **89.0** | **11.0** | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|
| ● **B-6** | **40.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |


| BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|
| ● **B-6** | **40.0** | **2** | **0.357** | **0.161** | | **0.0** | **81.7** | **18.3** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-6** | **6.0** | **NP** | **NP** | **NP** | **17** | **Silty Fine SAND (SM) A-2-4** |
| ⊠ | **B-6** | **10.0** | **NP** | **NP** | **NP** | **16** | **Silty Fine SAND (SM) A-2-4** |
| ▲ | **B-6** | **15.0** | **NP** | **NP** | **NP** | **26** | **Silty Fine SAND (SM) A-2-4** |
| ★ | **B-6** | **25.0** | **NP** | **NP** | **NP** | **14** | **Silty Fine SAND (SM) A-2-4** |
| ⊙ | **B-6** | **30.0** | **NP** | **NP** | **NP** | **11** | **Poorly Graded Fine SAND (SP-SM) with Silt A-2-4** |
| ✿ | **B-6** | **40.0** | **NP** | **NP** | **NP** | **18** | **Silty Fine SAND (SM) A-2-4** |

ATTERBERG LIMITS G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## ORGANIC IMPURITIES DETERMINATION
## (AASHTO T267)

**PROJECT:** US 21 Bridge Replacement over Harbor River **PROJECT NO.:** G5396.00

**SAMPLE NUMBER:** 15-1439A **DATE SAMPLE RECEIVED:**

**DESCRIPTION OF SOIL:**

**TESTED BY:** JH **DATE OF TESTING:** 10/13/2015

**DATE OF WEIGHING:** 10/14/2015

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | B-6 | | | | |
| **SAMPLE NO.** | 15-1439A | | | | |
| **SAMPLE DEPTH** | 2.0'-4.0' | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (BEFORE IGNITION) (GRAMS)** | 150.80 | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (AFTER IGNITION) (GRAMS)** | 150.59 | | | | |
| **WT. OF CRUCIBLE (GRAMS)** | 110.80 | | | | |
| **WT. OF DRY SOIL (BEFORE IGNITION) (GRAMS)** | 40.00 | | | | |
| **WT. OF DRY SOIL (AFTER IGNITION) (GRAMS)** | 39.79 | | | | |
| **IGNITION LOSS (GRAMS)** | 0.21 | | | | |
| **ORGANIC IMPURITIES %** | 0.53 | | | | |

# Determining pH of Soil for Use in Corrosion Testing
## AASHTO T 289

| | | | |
|---|---|---|---|
| PROJECT TITLE | F&ME/HARBOR RIVER/SC | SAMPLE ID | B-6 15-1439V |
| PROJECT NO. | 1524908.09 | SAMPLE TYPE | Bag |
| REMARKS | F&ME Project No. G5396 | SAMPLE DEPTH | 58.5 - 60.0' |

**SAMPLE PREPARATION**

| | |
|---|---|
| Sieved through the #10 Sieve | YES |
| Air Dry | YES |
| Type of Water | DISTILLED |

| Trial | pH | Temperature |
|---|---|---|
| 1 | 7.66 | 20.1 |
| 2 | 7.67 | 20.1 |
| 3 | 7.64 | 20.1 |
| **AVERAGE** | 7.66 | 20.1 |

| | |
|---|---|
| **Description** | SILTY CLAY; grayish brown. |
| **USCS** | (CL) |

| | |
|---|---|
| TECH | TJ |
| DATE | 10/13/15 |
| CHECK | |
| REVIEW | |
| APPROVE | |

# Determining Minimum Laboratory Soil Resistivity
## AASHTO T 288

| | | | | |
|---|---|---|---|---|
| PROJECT TITLE | F&ME/HARBOR RIVER/SC | SAMPLE ID | B-6 | 15-1439W |
| PROJECT NO. | 1524908.09 | SAMPLE TYPE | Bag | |
| REMARKS | F&ME Project No. G5396 | SAMPLE DEPTH | 58.5 - 60.0' | |


SAMPLE PREPARATION — Sieved through the #10 Sieve: Yes
TEST APPARATUS — Miller Soilbox and Nilsson 400 Soil Resistance Meter.

Identification: Lowest resistivity

| SPECIMEN (Point) | 1 | 2 | 3 | 4 |
|---|---|---|---|---|
| RESISTIVITY (ohms-cm) | 1,500 | 850 | 85 | 120 |

MOISTURE CONTENT

| | | | | |
|---|---|---|---|---|
| WET WEIGHT & TARE | 110.92 | 145.08 | 179.10 | 321.03 |
| DRY WEIGHT & TARE | 99.29 | 121.54 | 132.64 | 166.52 |
| TARE WEIGHT | 48.19 | 43.00 | 52.04 | 52.01 |
| WEIGHT OF MOISTURE (gm) | 11.63 | 23.54 | 46.46 | 154.51 |
| WEIGHT OF DRY SOIL (gm) | 51.10 | 78.54 | 80.60 | 114.51 |
| MOISTURE CONTENT (%) | 22.76 | 29.97 | 57.64 | 134.93 |




Description: SILTY CLAY; grayish brown.

USCS: (CL)

| | |
|---|---|
| TECH | TJ |
| DATE | 10/13/15 |
| CHECK | |
| REVIEW | |
| APPROVE | |

ACL

ADVANCED CHEMISTRY LABS, INC.

Phone: (770) 409-1444
Fax: (770) 409-1844
e-mail: acl@acl-labs.net

3039 Amwiler Road • Suite 100 • Atlanta, GA 30360
P.O. Box 88610 • Atlanta, GA 30356
www.acl-labs.com

**Client:** Golder Associates, Inc.
3730 Chamblee Tucker Road
Atlanta, GA 30341-0000

**Client Proj #:** 1524908
**ACL Project #:** 68442
**Date Received:** 10/13/2015
**Date Reported:** 10/30/2015

**Contact:** Mr. Henry Mock

**Sample ID:** B-6 58.5-60'

**Matrix:** Soil

**ACL #:** 307838

**Date/Time Sampled:** 10/13/2015 11:15

| Analyte (Method) | Result | PQL | Units | DF | Prep Date/Time | Analysis Date/Time | Analyst |
|---|---|---|---|---|---|---|---|
| Sol. Chloride (9252A)* | 16000 | 1000 | mg/kg | 100 | 10/16/2015 8:30 | 10/16/2015 8:30 | MM |
| Sol. Sulfate (9038)* | 763 | 200 | mg/kg | 20 | 10/19/2015 10:20 | 10/19/2015 10:20 | MM |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1197 | **DATE SAMPLE RECEIVED:** | 7/21/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 7/25/2016 |
| | | **DATE OF WEIGHING:** | 7/26/2016 |

| **BORING NO.** | B-7 | B-7 | B-7 | B-7 | B-7 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1197C | 16-1197F | 16-1197I | 16-1197L | 16-1197O |
| **SAMPLE DEPTH** | 4.0-6.0' | 8.0-10.0' | 13.5-15.0' | 18.5-20.0' | 43.5-45.0' |
| **WATER CONTENT, W%** | 24.2 | 33.1 | 31.3 | 24.2 | 38.0 |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | B-7 | 6.0 | Silty Fine SAND (SM) A-2-4 | NP | NP | NP | | |
| ⊠ | B-7 | 10.0 | Silty Fine SAND (SM) A-2-4 | NP | NP | NP | | |
| ▲ | B-7 | 15.0 | Silty F/M SAND (SM) A-2-4 | NP | NP | NP | | |
| ★ | B-7 | 20.0 | Poorly Graded F/C SAND (SP-SM) with Silt A-2-4 | NP | NP | NP | 0.89 | 1.78 |
| ⊙ | B-7 | 45.0 | Silty Fine SAND (SM) A-2-4 | NP | NP | NP | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | B-7 | 6.0 | 19.1 | 0.801 | 0.141 | | 4.0 | 83.2 | 12.8 | |
| ⊠ | B-7 | 10.0 | 19.1 | 0.954 | 0.158 | | 3.0 | 78.8 | 18.2 | |
| ▲ | B-7 | 15.0 | 9.52 | 0.957 | 0.177 | | 0.3 | 80.9 | 18.9 | |
| ★ | B-7 | 20.0 | 19.1 | 3.859 | 0.118 | | 4.0 | 85.1 | 10.8 | |
| ⊙ | B-7 | 45.0 | 2 | 0.351 | 0.155 | | 0.0 | 82.1 | 17.9 | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-7** | **6.0** | **NP** | **NP** | **NP** | **13** | **Silty Fine SAND (SM) A-2-4** |
| ⊠ | **B-7** | **10.0** | **NP** | **NP** | **NP** | **18** | **Silty Fine SAND (SM) A-2-4** |
| ▲ | **B-7** | **15.0** | **NP** | **NP** | **NP** | **19** | **Silty F/M SAND (SM) A-2-4** |
| ★ | **B-7** | **20.0** | **NP** | **NP** | **NP** | **11** | **Poorly Graded F/C SAND (SP-SM) with Silt A-2-4** |
| ⊙ | **B-7** | **45.0** | **NP** | **NP** | **NP** | **18** | **Silty Fine SAND (SM) A-2-4** |

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 08/23/16 |
| Tested By: | jbr |
| Checked By: | jdt |

# Rapid Determination of Carbonate Content of Soils by ASTM D4373


| Boring ID | Sample ID | Depth, ft | *$CO_2$ Pressure, psi | Weight of Sample used, g | Weight $CaCO_3$, grams | Calcite Equivalent, % |
|---|---|---|---|---|---|---|
| B-7 | 16-1197P | 28.5-30 | 0.20 | 2.00 | 0.08 | 8 |

Notes: Calcium Carbonate content precise to +/- 1.5%

*$CO_2$ Pressure is based on the weight of sample as indicated in the table.

The reported Calcite Equivalent (%) is based on one gram

Figure 1: Calibration Curve




Weight Calcium Carbonate, g

% Calcite Equivalent = Weight x 100

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1242 | **DATE SAMPLE RECEIVED:** | 7/29/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | JH | **DATE OF TESTING:** | 8/1/2016 |
| | | **DATE OF WEIGHING:** | 8/2/2016 |

| **BORING NO.** | B-8 | B-8 | B-8 | B-8 | B-8 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1242C | 16-1242S | 16-1242F | 16-1242I | 16-1242M |
| **SAMPLE DEPTH** | 4.0-6.0' | 18.5-20.0' | 23.5-25.0' | 28.5-30.0' | 43.5-45.0' |
| **WATER CONTENT, W%** | 24.0 | 73.8 | 54.5 | 38.8 | 27.3 |

| **BORING NO.** | B-8 | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1242P | | | | |
| **SAMPLE DEPTH** | 48.5-50.0' | | | | |
| **WATER CONTENT, W%** | 37.1 | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |


| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | B-8 | 6.0 | Poorly Graded F/M SAND (SP-SM) with Silt A-2-4 | NP | NP | NP | 0.89 | 2.14 |
| ⊠ | B-8 | 20.0 | Sandy Lean CLAY (CL) A-6(8) | 34 | 20 | 14 | | |
| ▲ | B-8 | 25.0 | Clayey F/M SAND (SC) A-2-6(0) | 30 | 19 | 11 | | |
| ★ | B-8 | 30.0 | Silty F/M SAND (SM) A-2-4 | NP | NP | NP | | |
| ⊙ | B-8 | 45.0 | Poorly Graded F/M SAND (SP-SM) with Silt A-3 | NP | NP | NP | 1.54 | 2.04 |

| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | B-8 | 6.0 | 9.52 | 0.396 | 0.139 | | 1.0 | 87.2 | 11.9 | |
| ⊠ | B-8 | 20.0 | 4.76 | 0.162 | | | 0.0 | 32.5 | 67.5 | |
| ▲ | B-8 | 25.0 | 9.52 | 0.412 | 0.112 | | 0.2 | 64.8 | 34.9 | |
| ★ | B-8 | 30.0 | 9.52 | 1.559 | 0.156 | | 1.0 | 77.0 | 22.0 | |
| ⊙ | B-8 | 45.0 | 4.76 | 0.381 | 0.169 | 0.087 | 0.0 | 93.5 | 6.5 | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-8** | **50.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **1.64** | **2.18** |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-8** | **50.0** | **2** | **0.377** | **0.169** | **0.081** | **0.0** | **91.8** | **8.2** | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-8** | **6.0** | **NP** | **NP** | **NP** | **12** | **Poorly Graded F/M SAND (SP-SM) with Silt A-2-4** |
| ⊠ | **B-8** | **20.0** | **34** | **20** | **14** | **68** | **Sandy Lean CLAY (CL) A-6(8)** |
| ▲ | **B-8** | **25.0** | **30** | **19** | **11** | **35** | **Clayey F/M SAND (SC) A-2-6(0)** |
| ★ | **B-8** | **30.0** | **NP** | **NP** | **NP** | **22** | **Silty F/M SAND (SM) A-2-4** |
| ⊙ | **B-8** | **45.0** | **NP** | **NP** | **NP** | **7** | **Poorly Graded F/M SAND (SP-SM) with Silt A-3** |
| ✿ | **B-8** | **50.0** | **NP** | **NP** | **NP** | **8** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |

ATTERBERG LIMITS G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 08/23/16 |
| Tested By: | jbr |
| Checked By: | jdt |

# Rapid Determination of Carbonate Content of Soils by ASTM D4373


| Boring ID | Sample ID | Depth, ft | *$CO_2$ Pressure, psi | Weight of Sample used, g | Weight $CaCO_3$, grams | Calcite Equivalent, % |
|---|---|---|---|---|---|---|
| B-8 | 16-1242J | 33.5-35 | 0.20 | 1.00 | 0.16 | 16 |

Notes: Calcium Carbonate content precise to +/- 1.5%

*$CO_2$ Pressure is based on the weight of sample as indicated in the table.

The reported Calcite Equivalent (%) is based on one gram

Figure 1: Calibration Curve




% Calcite Equivalent = Weight x 100

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1243 | **DATE SAMPLE RECEIVED:** | 7/29/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 8/1/2016 |
| | | **DATE OF WEIGHING:** | 8/2/2016 |

| **BORING NO.** | B-9 | B-9 | B-9 | B-9 | B-9 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1243F | 16-1243I | 16-1243L | 16-1243C | 16-1243P |
| **SAMPLE DEPTH** | 2.0-4.0' | 4.0-6.0' | 8.0-10.0' | 28.5-30.0' | 43.5-45.0' |
| **WATER CONTENT, W%** | 22.6 | 21.9 | 25.6 | 88.5 | 25.6 |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-9** | **4.0** | **Poorly Graded F/C SAND (SP-SM) with Silt A-1-b** | **NP** | **NP** | **NP** | **0.70** | **8.97** |
| ⊠ | **B-9** | **6.0** | **Poorly Graded F/C SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **0.84** | **4.40** |
| ▲ | **B-9** | **10.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **0.98** | **2.15** |
| ★ | **B-9** | **30.0** | **Fat CLAY with Fine Sand (CH) A-7-5(24)** | **58** | **30** | **28** | | |
| ⊙ | **B-9** | **45.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **1.51** | **2.21** |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-9** | **4.0** | **19.1** | **7.521** | **0.568** | **0.091** | **8.4** | **83.8** | **7.7** | |
| ⊠ | **B-9** | **6.0** | **9.52** | **3.326** | **0.282** | **0.088** | **2.2** | **90.7** | **7.2** | |
| ▲ | **B-9** | **10.0** | **9.52** | **0.35** | **0.152** | | **0.1** | **89.6** | **10.3** | |
| ★ | **B-9** | **30.0** | **9.52** | **0.27** | | | **0.2** | **20.7** | **79.1** | |
| ⊙ | **B-9** | **45.0** | **19.1** | **0.399** | **0.173** | **0.085** | **1.2** | **91.4** | **7.5** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-9** | **4.0** | **NP** | **NP** | **NP** | **8** | **Poorly Graded F/C SAND (SP-SM) with Silt A-1-b** |
| ⊠ | **B-9** | **6.0** | **NP** | **NP** | **NP** | **7** | **Poorly Graded F/C SAND (SP-SM) with Silt A-3** |
| ▲ | **B-9** | **10.0** | **NP** | **NP** | **NP** | **10** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ★ | **B-9** | **30.0** | **58** | **30** | **28** | **79** | **Fat CLAY with Fine Sand (CH) A-7-5(24)** |
| ⊙ | **B-9** | **45.0** | **NP** | **NP** | **NP** | **7** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |

ATTERBERG LIMITS G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 08/23/16 |
| Tested By: | jbr |
| Checked By: | jdt |

# Rapid Determination of Carbonate Content of Soils by ASTM D4373


| Boring ID | Sample ID | Depth, ft | *$CO_2$ Pressure, psi | Weight of Sample used, g | Weight $CaCO_3$, grams | Calcite Equivalent, % |
|---|---|---|---|---|---|---|
| B-9 | 16-1243M | 13.5-15 | 0.30 | 5.00 | 0.05 | 5 |

Notes: Calcium Carbonate content precise to +/- 1.5%

*$CO_2$ Pressure is based on the weight of sample as indicated in the table.

The reported Calcite Equivalent (%) is based on one gram

Figure 1: Calibration Curve




% Calcite Equivalent = Weight x 100

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1110 | **DATE SAMPLE RECEIVED:** | 7/5/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 7/12/2016 |
| | | **DATE OF WEIGHING:** | 7/13/2016 |

| **BORING NO.** | B-10 | B-10 | B-10 | B-10 | B-10 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1110C | 16-1110F | 16-1110I | 16-1110L | 16-1110O |
| **SAMPLE DEPTH** | 3.5-5.5' | 7.5-9.5' | 25.0-26.5' | 46.0-47.5' | 56.5-58.0' |
| **WATER CONTENT, W%** | 50.0 | 24.1 | 58.3 | 21.9 | 58.1 |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-10** | **5.5** | **Clayey Fine SAND (SC) A-4(1)** | **26** | **17** | **9** | | |
| ⊠ | **B-10** | **9.5** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **1.28** | **2.13** |
| ▲ | **B-10** | **26.5** | **Sandy SILT (ML) A-4(2)** | **33** | **26** | **7** | | |
| ★ | **B-10** | **47.5** | **Poorly Graded F/C SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **0.86** | **3.56** |
| ⊙ | **B-10** | **58.0** | **Silty F/M SAND (SM) A-2-6(0)** | **39** | **27** | **12** | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-10** | **5.5** | **4.76** | **0.217** | **0.086** | | **0.0** | **58.9** | **41.1** | |
| ⊠ | **B-10** | **9.5** | **4.76** | **0.377** | **0.16** | **0.079** | **0.0** | **92.1** | **7.9** | |
| ▲ | **B-10** | **26.5** | **2** | **0.14** | | | **0.0** | **42.8** | **57.2** | |
| ★ | **B-10** | **47.5** | **19.1** | **8.124** | **0.39** | **0.141** | **7.0** | **87.0** | **6.0** | |
| ⊙ | **B-10** | **58.0** | **19.1** | **1.721** | **0.108** | | **2.8** | **66.2** | **31.0** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-10** | **5.5** | **26** | **17** | **9** | **41** | **Clayey Fine SAND (SC) A-4(1)** |
| ⊠ | **B-10** | **9.5** | **NP** | **NP** | **NP** | **8** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ▲ | **B-10** | **26.5** | **33** | **26** | **7** | **57** | **Sandy SILT (ML) A-4(2)** |
| ★ | **B-10** | **47.5** | **NP** | **NP** | **NP** | **6** | **Poorly Graded F/C SAND (SP-SM) with Silt A-3** |
| ⊙ | **B-10** | **58.0** | **39** | **27** | **12** | **31** | **Silty F/M SAND (SM) A-2-6(0)** |

ATTERBERG LIMITS G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | GA |
| Sample ID: | --- | Test Date: | 08/09/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 386279 | | |

# pH of Soil by ASTM D4972

| Boring ID | Sample ID | Depth | Visual Description | pH of Soil in Distilled Water | pH of Soil in Calcium Chloride |
|---|---|---|---|---|---|
| B-10 | --- | 30.5-32 ft | Moist, dark gray silty sand | 7.1 | 6.8 |

Notes: Sample Preparation: screened through #10 sieve

Method A, pH meter used

| | |
|---|---|
| Client: | F&ME Consultants |
| Project: | US-21 Replacement Bridge over Harbor River |
| Location: | --- |
| GTX#: | 305005 |
| Test Date: | 08/09/16 |
| Tested By: | jm |
| Checked By: | mcm |

# Laboratory Measurement of Soil Resistivity Using the Wenner Four-Electrode Method by ASTM G57 (Laboratory Measurement)

| Boring ID | Sample ID | Depth, ft. | Sample Description | Electrical Resistivity, ohm-cm | Electrical Conductivity, $(ohm\text{-}cm)^{-1}$ |
|---|---|---|---|---|---|
| B-10 | --- | 30.5-32 | Moist, dark gray silty sand | 62 | 1.61E-02 |

Notes: Test Equipment: Nilsson Model 400 Soil Resistance Meter, MC Miller Soil Box
Water added to sample to create a thick slurry prior to testing (saturated condition).
Electrical Conductivity is calculated as inverse of Electrical Resistivity (per ASTM G57)
Test conducted in standard laboratory atmosphere: 68-73 F

**Project Name:** US-21 REP. BRIDGE OVER HARBOR
**Project Number:** 305005
**Lab Number:** L1623916
**Report Date:** 08/08/16

## SAMPLE RESULTS

Lab ID: L1623916-01
Client ID: B-10 / 30.5-32.0 FT
Sample Location: Not Specified
Matrix: Soil
Date Collected: 08/01/16 11:51
Date Received: 08/02/16
Field Prep: Not Specified

| Parameter | Result | Qualifier | Units | RL | MDL | Dilution Factor | Date Prepared | Date Analyzed | Analytical Method | Analyst |
|---|---|---|---|---|---|---|---|---|---|---|
| **General Chemistry - Westborough Lab** | | | | | | | | | | |
| Solids, Total | 56.7 | | % | 0.100 | NA | 1 | - | 08/03/16 02:46 | 121,2540G | VB |
| Chloride | 8400 | | mg/kg | 170 | -- | 10 | - | 08/05/16 18:53 | 1,9251 | |
| Sulfate | 2400 | | mg/kg | 880 | -- | 5 | - | 08/04/16 11:30 | 1,9038 | AW |

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 08/23/16 |
| Tested By: | jbr |
| Checked By: | jdt |

# Rapid Determination of Carbonate Content of Soils by ASTM D4373


| Boring ID | Sample ID | Depth, ft | *$CO_2$ Pressure, psi | Weight of Sample used, g | Weight $CaCO_3$, grams | Calcite Equivalent, % |
|---|---|---|---|---|---|---|
| B-10 | --- | 86.5-88 | 5.60 | 1.00 | 4.60 | 460 |

Notes: Calcium Carbonate content precise to +/- 1.5%

*$CO_2$ Pressure is based on the weight of sample as indicated in the table.

The reported Calcite Equivalent (%) is based on one gram

Figure 1: Calibration Curve



# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1111 | **DATE SAMPLE RECEIVED:** | 7/5/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 7/12/2016 |
| | | **DATE OF WEIGHING:** | 7/13/2016 |

| **BORING NO.** | B-11 | B-11 | B-11 | B-11 | B-11 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1111C | 16-1111F | 16-1111I | 16-1111L | 16-1111O |
| **SAMPLE DEPTH** | 26.0-28.0' | 28.0.-30.0' | 30.0-32.0' | 36.5-38.0' | 83.0-84.5' |
| **WATER CONTENT, W%** | 33.7 | 57.6 | 30.5 | 93.7 | 45.3 |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-11** | **28.0** | **Silty Fine SAND (SM) A-2-4** | **22** | **NP** | **NP** | | |
| ⊠ | **B-11** | **30.0** | **Sandy Lean CLAY (CL) A-4(2)** | **26** | **17** | **9** | | |
| ▲ | **B-11** | **32.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ★ | **B-11** | **38.0** | **Elastic SILT (MH) A-7-5(25)** | **58** | **35** | **23** | | |
| ⊙ | **B-11** | **84.5** | **Silty Fine SAND (SM) A-4(0)** | **31** | **NP** | **NP** | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-11** | **28.0** | **9.52** | **0.409** | **0.166** | | **0.0** | **81.8** | **18.1** | |
| ⊠ | **B-11** | **30.0** | **19.1** | **0.376** | | | **0.5** | **47.4** | **52.1** | |
| ▲ | **B-11** | **32.0** | **9.52** | **0.386** | **0.162** | | **0.2** | **84.5** | **15.3** | |
| ★ | **B-11** | **38.0** | **9.52** | **0.133** | | | **0.0** | **12.1** | **87.9** | |
| ⊙ | **B-11** | **84.5** | **9.52** | **0.402** | **0.081** | | **0.3** | **53.7** | **46.0** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-11** | **28.0** | **22** | **NP** | **NP** | **18** | **Silty Fine SAND (SM) A-2-4** |
| ⊠ | **B-11** | **30.0** | **26** | **17** | **9** | **52** | **Sandy Lean CLAY (CL) A-4(2)** |
| ▲ | **B-11** | **32.0** | **NP** | **NP** | **NP** | **15** | **Silty Fine SAND (SM) A-2-4** |
| ★ | **B-11** | **38.0** | **58** | **35** | **23** | **88** | **Elastic SILT (MH) A-7-5(25)** |
| ⊙ | **B-11** | **84.5** | **31** | **NP** | **NP** | **46** | **Silty Fine SAND (SM) A-4(0)** |

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | GA |
| Sample ID: | --- | Test Date: | 08/09/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 386279 | | |

# pH of Soil by ASTM D4972

| Boring ID | Sample ID | Depth | Visual Description | pH of Soil in Distilled Water | pH of Soil in Calcium Chloride |
|---|---|---|---|---|---|
| B-11 | --- | 92.5-94 ft | Moist, dark olive clay with sand | 7.0 | 6.8 |

Notes: Sample Preparation: screened through #10 sieve

Method A, pH meter used

| | |
|---|---|
| Client: | F&ME Consultants |
| Project: | US-21 Replacement Bridge over Harbor River |
| Location: | --- |
| GTX#: | 305005 |
| Test Date: | 08/09/16 |
| Tested By: | jm |
| Checked By: | mcm |

# Laboratory Measurement of Soil Resistivity Using the Wenner Four-Electrode Method by ASTM G57 (Laboratory Measurement)

| Boring ID | Sample ID | Depth, ft. | Sample Description | Electrical Resistivity, ohm-cm | Electrical Conductivity, $(ohm\text{-}cm)^{-1}$ |
|---|---|---|---|---|---|
| B-11 | --- | 92.5-94 | Moist, olive clay with sand | 101 | 9.91E-03 |

Notes: Test Equipment: Nilsson Model 400 Soil Resistance Meter, MC Miller Soil Box
Water added to sample to create a thick slurry prior to testing (saturated condition).
Electrical Conductivity is calculated as inverse of Electrical Resistivity (per ASTM G57)
Test conducted in standard laboratory atmosphere: 68-73 F

**Project Name:** US-21 REP. BRIDGE OVER HARBOR
**Project Number:** 305005
**Lab Number:** L1623916
**Report Date:** 08/08/16

## SAMPLE RESULTS

Lab ID: L1623916-02
Client ID: B-11 / 92.5-94.0 FT
Sample Location: Not Specified
Matrix: Soil
Date Collected: 08/01/16 11:59
Date Received: 08/02/16
Field Prep: Not Specified

| Parameter | Result | Qualifier | Units | RL | MDL | Dilution Factor | Date Prepared | Date Analyzed | Analytical Method | Analyst |
|---|---|---|---|---|---|---|---|---|---|---|
| **General Chemistry - Westborough Lab** | | | | | | | | | | |
| Solids, Total | 62.2 | | % | 0.100 | NA | 1 | - | 08/03/16 02:46 | 121,2540G | VB |
| Chloride | 5700 | | mg/kg | 140 | -- | 10 | - | 08/05/16 17:53 | 1,9251 | |
| Sulfate | 2000 | | mg/kg | 800 | -- | 5 | - | 08/04/16 11:30 | 1,9038 | AW |

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 08/23/16 |
| Tested By: | jbr |
| Checked By: | jdt |

# Rapid Determination of Carbonate Content of Soils by ASTM D4373


| Boring ID | Sample ID | Depth, ft | *$CO_2$ Pressure, psi | Weight of Sample used, g | Weight $CaCO_3$, grams | Calcite Equivalent, % |
|---|---|---|---|---|---|---|
| B-11 | --- | 68.5-70 | 5.50 | 1.00 | 4.51 | 451 |

Notes: Calcium Carbonate content precise to +/- 1.5%

*$CO_2$ Pressure is based on the weight of sample as indicated in the table.

The reported Calcite Equivalent (%) is based on one gram

Figure 1: Calibration Curve



# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1182 | **DATE SAMPLE RECEIVED:** | 7/15/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 7/20/2016 |
| | | **DATE OF WEIGHING:** | 7/21/2016 |

| **BORING NO.** | B-12 | B-12 | B-12 | B-12 | B-12 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1182C | 16-1182F | 16-1182I | 16-1182L | 16-1182O |
| **SAMPLE DEPTH** | 37.0-39.0' | 45.5-47.0' | 61.0-62.5' | 80.0-81.5' | 96.5-98.0' |
| **WATER CONTENT, W%** | 32.9 | 24.6 | 81.2 | 61.8 | 33.7 |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-12** | **39.0** | **Silty F/M SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ⊠ | **B-12** | **47.0** | **Poorly Graded F/C SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **1.18** | **5.30** |
| ▲ | **B-12** | **62.5** | **Silty F/M SAND (SM) A-5(0)** | **51** | **NP** | **NP** | | |
| ★ | **B-12** | **81.5** | **Silty Fine SAND (SM) A-7-5(4)** | **44** | **31** | **13** | | |
| ⊙ | **B-12** | **98.0** | **Silty F/M SAND (SM) A-4(0)** | **30** | **NP** | **NP** | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-12** | **39.0** | **9.52** | **0.672** | **0.113** | | **1.3** | **74.9** | **23.8** | |
| ⊠ | **B-12** | **47.0** | **19.1** | **5.662** | **0.296** | | **6.4** | **83.2** | **10.4** | |
| ▲ | **B-12** | **62.5** | **4.76** | **0.561** | **0.078** | | **0.0** | **52.0** | **48.0** | |
| ★ | **B-12** | **81.5** | **4.76** | **0.184** | **0.079** | | **0.0** | **53.4** | **46.6** | |
| ⊙ | **B-12** | **98.0** | **9.52** | **1.56** | **0.076** | | **0.9** | **49.3** | **49.7** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-12** | **39.0** | **NP** | **NP** | **NP** | **24** | **Silty F/M SAND (SM) A-2-4** |
| ⊠ | **B-12** | **47.0** | **NP** | **NP** | **NP** | **10** | **Poorly Graded F/C SAND (SP-SM) with Silt A-3** |
| ▲ | **B-12** | **62.5** | **51** | **NP** | **NP** | **48** | **Silty F/M SAND (SM) A-5(0)** |
| ★ | **B-12** | **81.5** | **44** | **31** | **13** | **47** | **Silty Fine SAND (SM) A-7-5(4)** |
| ⊙ | **B-12** | **98.0** | **30** | **NP** | **NP** | **50** | **Silty F/M SAND (SM) A-4(0)** |

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 08/23/16 |
| Tested By: | jbr |
| Checked By: | jdt |

# Rapid Determination of Carbonate Content of Soils by ASTM D4373


| Boring ID | Sample ID | Depth, ft | *$CO_2$ Pressure, psi | Weight of Sample used, g | Weight $CaCO_3$, grams | Calcite Equivalent, % |
|---|---|---|---|---|---|---|
| B-12 | --- | 115.5-117 | 6.00 | 1.00 | 4.93 | 493 |

Notes: Calcium Carbonate content precise to +/- 1.5%

*$CO_2$ Pressure is based on the weight of sample as indicated in the table.

The reported Calcite Equivalent (%) is based on one gram

Figure 1: Calibration Curve



# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1039 | **DATE SAMPLE RECEIVED:** | 7/6/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 7/6/2016 |
| | | **DATE OF WEIGHING:** | 7/7/2016 |

| **BORING NO.** | B-13 | B-13 | B-13 | B-13 | B-13 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1039C | 16-1039F | 16-1039I | 16-1039L | 16-1039O |
| **SAMPLE DEPTH** | 32.0-34.0' | 42.5-44.0' | 52.5-54.0' | 63.5-65.0' | 99.5-101.0' |
| **WATER CONTENT, W%** | 34.6 | 63.6 | 78.3 | 73.8 | 37.3 |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-13** | **34.0** | **Silty F/M SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ⊠ | **B-13** | **44.0** | **Sandy Lean CLAY (CL) A-7-6(11)** | **41** | **20** | **21** | | |
| ▲ | **B-13** | **54.0** | **Sandy SILT (ML) A-4(0)** | **23** | **NP** | **NP** | | |
| ★ | **B-13** | **65.0** | **Clayey F/M SAND (SC) A-7-6(11)** | **67** | **29** | **38** | | |
| ⊙ | **B-13** | **101.0** | **Sandy SILT (ML) A-4(1)** | **30** | **24** | **6** | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-13** | **34.0** | **19.1** | **3.252** | **0.129** | | **4.4** | **72.8** | **22.8** | |
| ⊠ | **B-13** | **44.0** | **4.76** | **0.54** | | | **0.0** | **35.8** | **64.2** | |
| ▲ | **B-13** | **54.0** | **19.1** | **2.717** | | | **2.1** | **32.6** | **65.3** | |
| ★ | **B-13** | **65.0** | **9.52** | **0.501** | **0.085** | | **0.2** | **55.9** | **43.9** | |
| ⊙ | **B-13** | **101.0** | **19.1** | **2.809** | | | **4.2** | **45.6** | **50.2** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-13** | **34.0** | **NP** | **NP** | **NP** | **23** | **Silty F/M SAND (SM) A-2-4** |
| ⊠ | **B-13** | **44.0** | **41** | **20** | **21** | **64** | **Sandy Lean CLAY (CL) A-7-6(11)** |
| ▲ | **B-13** | **54.0** | **23** | **NP** | **NP** | **65** | **Sandy SILT (ML) A-4(0)** |
| ★ | **B-13** | **65.0** | **67** | **29** | **38** | **44** | **Clayey F/M SAND (SC) A-7-6(11)** |
| ⊙ | **B-13** | **101.0** | **30** | **24** | **6** | **50** | **Sandy SILT (ML) A-4(1)** |

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | GA |
| Sample ID: | --- | Test Date: | 08/09/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 386279 | | |

# pH of Soil by ASTM D4972

| Boring ID | Sample ID | Depth | Visual Description | pH of Soil in Distilled Water | pH of Soil in Calcium Chloride |
|---|---|---|---|---|---|
| B-13 | --- | 58-59.5 ft | Moist, dark olive silty sand | 7.2 | 7.0 |

Notes: Sample Preparation: screened through #10 sieve

Method A, pH meter used

| | |
|---|---|
| Client: | F&ME Consultants |
| Project: | US-21 Replacement Bridge over Harbor River |
| Location: | --- |
| GTX#: | 305005 |
| Test Date: | 08/09/16 |
| Tested By: | jm |
| Checked By: | mcm |

# Laboratory Measurement of Soil Resistivity Using the Wenner Four-Electrode Method by ASTM G57 (Laboratory Measurement)

| Boring ID | Sample ID | Depth, ft. | Sample Description | Electrical Resistivity, ohm-cm | Electrical Conductivity, $(ohm\text{-}cm)^{-1}$ |
|---|---|---|---|---|---|
| B-13 | --- | 58-59.5 | Moist, dark olive silty sand | 76 | 1.31E-02 |

Notes: Test Equipment: Nilsson Model 400 Soil Resistance Meter, MC Miller Soil Box
Water added to sample to create a thick slurry prior to testing (saturated condition).
Electrical Conductivity is calculated as inverse of Electrical Resistivity (per ASTM G57)
Test conducted in standard laboratory atmosphere: 68-73 F

**Project Name:** US-21 REP. BRIDGE OVER HARBOR
**Project Number:** 305005
**Lab Number:** L1623916
**Report Date:** 08/08/16

## SAMPLE RESULTS

Lab ID: L1623916-03
Client ID: B-13 / 58.0-59.5 FT
Sample Location: Not Specified
Matrix: Soil
Date Collected: 08/01/16 12:04
Date Received: 08/02/16
Field Prep: Not Specified

| Parameter | Result | Qualifier | Units | RL | MDL | Dilution Factor | Date Prepared | Date Analyzed | Analytical Method | Analyst |
|---|---|---|---|---|---|---|---|---|---|---|
| **General Chemistry - Westborough Lab** | | | | | | | | | | |
| Solids, Total | 67.4 | | % | 0.100 | NA | 1 | - | 08/03/16 02:46 | 121,2540G | VB |
| Chloride | 7600 | | mg/kg | 140 | -- | 10 | - | 08/05/16 17:55 | 1,9251 | |
| Sulfate | 1700 | | mg/kg | 740 | -- | 5 | - | 08/04/16 11:30 | 1,9038 | AW |

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 08/23/16 |
| Tested By: | jbr |
| Checked By: | jdt |

# Rapid Determination of Carbonate Content of Soils by ASTM D4373


| Boring ID | Sample ID | Depth, ft | *$CO_2$ Pressure, psi | Weight of Sample used, g | Weight $CaCO_3$, grams | Calcite Equivalent, % |
|---|---|---|---|---|---|---|
| B-13 | --- | 94.5-96 | 5.60 | 1.00 | 4.60 | 460 |

Notes: Calcium Carbonate content precise to +/- 1.5%

*$CO_2$ Pressure is based on the weight of sample as indicated in the table.

The reported Calcite Equivalent (%) is based on one gram

Figure 1: Calibration Curve



# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1008 | **DATE SAMPLE RECEIVED:** | 7/6/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 7/6/2016 |
| | | **DATE OF WEIGHING:** | 7/7/2016 |

| **BORING NO.** | B-14 | B-14 | B-14 | B-14 | B-14 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1008C | 16-1008F | 16-1008I | 16-1008L | 16-1008O |
| **SAMPLE DEPTH** | 8.0-10.0' | 23.5-25.0' | 28.5-30.0' | 38.5-40.0' | 48.5-50.0' |
| **WATER CONTENT, W%** | 32.4 | 38.6 | 50.9 | 56.1 | 46.2 |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-14** | **10.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ⊠ | **B-14** | **25.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ▲ | **B-14** | **30.0** | **Silty F/M SAND (SM) A-4(1)** | **31** | **24** | **7** | | |
| ★ | **B-14** | **40.0** | **Sandy SILT (ML) A-7-5(4)** | **47** | **36** | **11** | | |
| ⊙ | **B-14** | **50.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-14** | **10.0** | **4.76** | **0.328** | **0.139** | | **0.0** | **86.2** | **13.8** | |
| ⊠ | **B-14** | **25.0** | **4.76** | **0.354** | **0.16** | | **0.0** | **82.4** | **17.6** | |
| ▲ | **B-14** | **30.0** | **9.52** | **1.321** | **0.094** | | **0.3** | **56.0** | **43.7** | |
| ★ | **B-14** | **40.0** | **4.76** | **0.157** | | | **0.0** | **48.0** | **52.0** | |
| ⊙ | **B-14** | **50.0** | **9.52** | **0.359** | **0.139** | | **0.0** | **69.8** | **30.1** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-14** | **10.0** | **NP** | **NP** | **NP** | **14** | **Silty Fine SAND (SM) A-2-4** |
| ⊠ | **B-14** | **25.0** | **NP** | **NP** | **NP** | **18** | **Silty Fine SAND (SM) A-2-4** |
| ▲ | **B-14** | **30.0** | **31** | **24** | **7** | **44** | **Silty F/M SAND (SM) A-4(1)** |
| ★ | **B-14** | **40.0** | **47** | **36** | **11** | **52** | **Sandy SILT (ML) A-7-5(4)** |
| ⊙ | **B-14** | **50.0** | **NP** | **NP** | **NP** | **30** | **Silty Fine SAND (SM) A-2-4** |

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | GA |
| Sample ID: | --- | Test Date: | 08/09/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 386279 | | |

# pH of Soil by ASTM D4972

| Boring ID | Sample ID | Depth | Visual Description | pH of Soil in Distilled Water | pH of Soil in Calcium Chloride |
|---|---|---|---|---|---|
| B-14 | --- | 33.5-35 ft | Moist, olive gray clay with sand | 7.4 | 7.1 |

Notes: Sample Preparation: screened through #10 sieve

Method A, pH meter used

| | |
|---|---|
| Client: | F&ME Consultants |
| Project: | US-21 Replacement Bridge over Harbor River |
| Location: | --- |
| GTX#: | 305005 |
| Test Date: | 08/09/16 |
| Tested By: | jm |
| Checked By: | mcm |

# Laboratory Measurement of Soil Resistivity Using the Wenner Four-Electrode Method by ASTM G57 (Laboratory Measurement)

| Boring ID | Sample ID | Depth, ft. | Sample Description | Electrical Resistivity, ohm-cm | Electrical Conductivity, $(ohm\text{-}cm)^{-1}$ |
|---|---|---|---|---|---|
| B-14 | --- | 33.5-35 | Moist, olive gray clay with sand | 71 | 1.40E-02 |

Notes: Test Equipment: Nilsson Model 400 Soil Resistance Meter, MC Miller Soil Box
Water added to sample to create a thick slurry prior to testing (saturated condition).
Electrical Conductivity is calculated as inverse of Electrical Resistivity (per ASTM G57)
Test conducted in standard laboratory atmosphere: 68-73 F

**Project Name:** US-21 REP. BRIDGE OVER HARBOR
**Project Number:** 305005
**Lab Number:** L1623916
**Report Date:** 08/08/16

## SAMPLE RESULTS

Lab ID: L1623916-04
Client ID: B-14 / 33.5-35.0 FT
Sample Location: Not Specified
Matrix: Soil
Date Collected: 08/01/16 12:11
Date Received: 08/02/16
Field Prep: Not Specified

| Parameter | Result | Qualifier | Units | RL | MDL | Dilution Factor | Date Prepared | Date Analyzed | Analytical Method | Analyst |
|---|---|---|---|---|---|---|---|---|---|---|
| **General Chemistry - Westborough Lab** | | | | | | | | | | |
| Solids, Total | 73.8 | | % | 0.100 | NA | 1 | - | 08/03/16 02:46 | 121,2540G | VB |
| Chloride | 6900 | | mg/kg | 130 | -- | 10 | - | 08/05/16 17:59 | 1,9251 | |
| Sulfate | 1600 | | mg/kg | 660 | -- | 4.9 | - | 08/04/16 11:30 | 1,9038 | AW |

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 08/23/16 |
| Tested By: | jbr |
| Checked By: | jdt |

# Rapid Determination of Carbonate Content of Soils by ASTM D4373


| Boring ID | Sample ID | Depth, ft | *$CO_2$ Pressure, psi | Weight of Sample used, g | Weight $CaCO_3$, grams | Calcite Equivalent, % |
|---|---|---|---|---|---|---|
| B-14 | --- | 72.5-74 | 4.90 | 10.00 | 0.40 | 40 |

Notes: Calcium Carbonate content precise to +/- 1.5%

*$CO_2$ Pressure is based on the weight of sample as indicated in the table.

The reported Calcite Equivalent (%) is based on one gram

Figure 1: Calibration Curve



# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1285 | **DATE SAMPLE RECEIVED:** | 8/5/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 8/9/2016 |
| | | **DATE OF WEIGHING:** | 8/10/2016 |

| **BORING NO.** | B-15 | B-15 | B-15 | B-15 | B-15 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1285C | 16-1285F | 16-1285I | 16-1285L | 16-1285P |
| **SAMPLE DEPTH** | 4.0-6.0' | 6.0-8.0' | 13.5-15.0' | 18.5-20.0' | 43.5-45.0' |
| **WATER CONTENT, W%** | 26.2 | 23.5 | 23.8 | 33.2 | 31.6 |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-15** | **6.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **1.62** | **2.20** |
| ⊠ | **B-15** | **8.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **1.38** | **2.05** |
| ▲ | **B-15** | **15.0** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **1.23** | **2.33** |
| ★ | **B-15** | **20.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ⊙ | **B-15** | **45.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-15** | **6.0** | **4.76** | **0.389** | **0.17** | **0.081** | **0.0** | **91.8** | **8.2** | |
| ⊠ | **B-15** | **8.0** | **2** | **0.396** | **0.173** | **0.093** | **0.0** | **94.9** | **5.1** | |
| ▲ | **B-15** | **15.0** | **4.76** | **0.4** | **0.187** | **0.095** | **0.0** | **94.5** | **5.5** | |
| ★ | **B-15** | **20.0** | **9.52** | **0.409** | **0.173** | | **0.2** | **82.3** | **17.5** | |
| ⊙ | **B-15** | **45.0** | **19.1** | **0.388** | **0.165** | | **0.6** | **78.7** | **20.7** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-15** | **6.0** | **NP** | **NP** | **NP** | **8** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ⊠ | **B-15** | **8.0** | **NP** | **NP** | **NP** | **5** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ▲ | **B-15** | **15.0** | **NP** | **NP** | **NP** | **6** | **Poorly Graded Fine SAND (SP-SM) with Silt A-3** |
| ★ | **B-15** | **20.0** | **NP** | **NP** | **NP** | **18** | **Silty Fine SAND (SM) A-2-4** |
| ⊙ | **B-15** | **45.0** | **NP** | **NP** | **NP** | **21** | **Silty Fine SAND (SM) A-2-4** |

ATTERBERG LIMITS G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## ORGANIC IMPURITIES DETERMINATION
## (AASHTO T267)

**PROJECT:** US 21 Bridge Replacement over Harbor River

**PROJECT NO.:** G5396

**SAMPLE NUMBER:** 16-1285

**DATE SAMPLE RECEIVED:** 8/8/2016

**DESCRIPTION OF SOIL:**

**TESTED BY:** MB

**DATE OF TESTING:** 8/10/2016

**DATE OF WEIGHING:** 8/10/2016

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | B-15 | | | | |
| **SAMPLE NO.** | 16-1285M | | | | |
| **SAMPLE DEPTH** | 38.5-40.0' | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (BEFORE IGNITION) (GRAMS)** | 177.48 | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (AFTER IGNITION) (GRAMS)** | 175.82 | | | | |
| **WT. OF CRUCIBLE (GRAMS)** | 137.48 | | | | |
| **WT. OF DRY SOIL (BEFORE IGNITION) (GRAMS)** | 40.00 | | | | |
| **WT. OF DRY SOIL (AFTER IGNITION) (GRAMS)** | 38.34 | | | | |
| **IGNITION LOSS (GRAMS)** | 1.66 | | | | |
| **ORGANIC IMPURITIES %** | 4.15 | | | | |

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 08/23/16 |
| Tested By: | jbr |
| Checked By: | jdt |

# Rapid Determination of Carbonate Content of Soils by ASTM D4373


| Boring ID | Sample ID | Depth, ft | *$CO_2$ Pressure, psi | Weight of Sample used, g | Weight $CaCO_3$, grams | Calcite Equivalent, % |
|---|---|---|---|---|---|---|
| B-15 | 16-1285Q | 58.5-60 | 0.20 | 2.00 | 0.08 | 8 |

Notes: Calcium Carbonate content precise to +/- 1.5%

*$CO_2$ Pressure is based on the weight of sample as indicated in the table.

The reported Calcite Equivalent (%) is based on one gram

Figure 1: Calibration Curve




% Calcite Equivalent = Weight x 100

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1286 | **DATE SAMPLE RECEIVED:** | 8/5/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 8/9/2016 |
| | | **DATE OF WEIGHING:** | 8/10/2016 |

| **BORING NO.** | B-16 | B-16 | B-16 | B-16 | B-16 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1286C | 16-1286F | 16-1286I | 16-1286L | 16-1286O |
| **SAMPLE DEPTH** | 6.0-8.0' | 13.5-15.0' | 23.5-25.0' | 38.5-40.0' | 48.5-50.0' |
| **WATER CONTENT, W%** | 24.5 | 24.3 | 37.4 | 56.7 | 84.8 |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **B-16** | **8.0** | **Poorly Graded Fine SAND (SP) A-3** | **NP** | **NP** | **NP** | **1.22** | **1.81** |
| ⊠ | **B-16** | **15.0** | **Poorly Graded Fine SAND (SP) A-3** | **NP** | **NP** | **NP** | **1.37** | **1.81** |
| ▲ | **B-16** | **25.0** | **Silty Fine SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ★ | **B-16** | **40.0** | **Clayey Fine SAND (SC) A-6(4)** | **36** | **21** | **15** | | |
| ⊙ | **B-16** | **50.0** | **Elastic SILT (MH) A-7-5(25)** | **75** | **35** | **40** | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **B-16** | **8.0** | **4.76** | **0.391** | **0.174** | **0.107** | **0.0** | **97.9** | **2.1** | |
| ⊠ | **B-16** | **15.0** | **4.76** | **0.4** | **0.17** | **0.098** | **0.0** | **97.9** | **2.1** | |
| ▲ | **B-16** | **25.0** | **4.76** | **0.393** | **0.179** | | **0.0** | **86.1** | **13.9** | |
| ★ | **B-16** | **40.0** | **4.76** | **0.179** | **0.081** | | **0.0** | **53.4** | **46.6** | |
| ⊙ | **B-16** | **50.0** | **4.76** | **0.118** | | | **0.0** | **9.0** | **91.0** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **B-16** | **8.0** | **NP** | **NP** | **NP** | **2** | **Poorly Graded Fine SAND (SP) A-3** |
| ⊠ | **B-16** | **15.0** | **NP** | **NP** | **NP** | **2** | **Poorly Graded Fine SAND (SP) A-3** |
| ▲ | **B-16** | **25.0** | **NP** | **NP** | **NP** | **14** | **Silty Fine SAND (SM) A-2-4** |
| ★ | **B-16** | **40.0** | **36** | **21** | **15** | **47** | **Clayey Fine SAND (SC) A-6(4)** |
| ⊙ | **B-16** | **50.0** | **75** | **35** | **40** | **91** | **Elastic SILT (MH) A-7-5(25)** |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## ORGANIC IMPURITIES DETERMINATION
## (AASHTO T267)

**PROJECT:** US 21 Bridge Replacement over Harbor River

**PROJECT NO.:** G5396

**SAMPLE NUMBER:** 16-1286

**DATE SAMPLE RECEIVED:** 8/8/2016

**DESCRIPTION OF SOIL:**

**TESTED BY:** MB

**DATE OF TESTING:** 8/10/2016

**DATE OF WEIGHING:** 8/10/2016

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | B-16 | | | | |
| **SAMPLE NO.** | 16-1286P | | | | |
| **SAMPLE DEPTH** | 53.5-55.0' | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (BEFORE IGNITION) (GRAMS)** | 139.63 | | | | |
| **WT. OF CRUCIBLE + DRY SOIL (AFTER IGNITION) (GRAMS)** | 136.74 | | | | |
| **WT. OF CRUCIBLE (GRAMS)** | 99.63 | | | | |
| **WT. OF DRY SOIL (BEFORE IGNITION) (GRAMS)** | 40.00 | | | | |
| **WT. OF DRY SOIL (AFTER IGNITION) (GRAMS)** | 37.11 | | | | |
| **IGNITION LOSS (GRAMS)** | 2.89 | | | | |
| **ORGANIC IMPURITIES %** | 7.22 | | | | |

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 08/23/16 |
| Tested By: | jbr |
| Checked By: | jdt |

# Rapid Determination of Carbonate Content of Soils by ASTM D4373


| Boring ID | Sample ID | Depth, ft | *$CO_2$ Pressure, psi | Weight of Sample used, g | Weight $CaCO_3$, grams | Calcite Equivalent, % |
|---|---|---|---|---|---|---|
| B-16 | 16-1286Q | 78.5-80 | 1.80 | 10.00 | 0.15 | 15 |

Notes: Calcium Carbonate content precise to +/- 1.5%

*$CO_2$ Pressure is based on the weight of sample as indicated in the table.

The reported Calcite Equivalent (%) is based on one gram

Figure 1: Calibration Curve




% Calcite Equivalent = Weight x 100

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 15-1799 | **DATE SAMPLE RECEIVED:** | 12/3/2015 |
| **DESCRIPTION OF SOIL:** | Various | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 12/3/2015 |
| | | **DATE OF WEIGHING:** | 12/4/2015 |

| **BORING NO.** | TS-1 | TS-1 | TS-1 | TS-1 | TS-1 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 15-1799C | 15-1799F | 15-1799I | 15-1799L | 15-1799O |
| **SAMPLE DEPTH** | 6.0-8.0' | 16.0-18.0' | 22.0-24.0' | 26.0-28.0' | 32.0-34.0' |
| **WATER CONTENT, W%** | 25.9 | 52.2 | 26.7 | 65.5 | 40.2 |

| **BORING NO.** | TS-1 | TS-1 | TS-1 | TS-1 | TS-1 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 15-1799R | 15-1799U | 15-1799X | 15-1799AA | 15-1799DD |
| **SAMPLE DEPTH** | 44.0-46.0' | 46.0-48.0' | 56.0-58.0' | 72.0-74.0' | 76.0-78.0' |
| **WATER CONTENT, W%** | 24.0 | 20.1 | 62.4 | 61.7 | 44.5 |


| **BORING NO.** | TS-1 | TS-1 | TS-1 | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 15-1799GG | 15-1799JJ | 15-1799MM | | |
| **SAMPLE DEPTH** | 80.0-82.0' | 104.0-106.0' | 120.0-122.0' | | |
| **WATER CONTENT, W%** | 42.6 | 33.4 | 35.4 | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | TS-1 | 8.0 | Silty Fine SAND (SM) A-2-4 | NP | NP | NP | | |
| ⊠ | TS-1 | 18.0 | Silty, Clayey Fine SAND (SC-SM) A-4(0) | 25 | 21 | 4 | | |
| ▲ | TS-1 | 24.0 | Silty Fine SAND (SM) A-2-4 | NP | NP | NP | | |
| ★ | TS-1 | 28.0 | Sandy SILT (ML) A-7-6(9) | 42 | 27 | 15 | | |
| ⊙ | TS-1 | 34.0 | Silty Fine SAND (SM) A-2-4 | NP | NP | NP | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | TS-1 | 8.0 | 9.52 | 0.393 | 0.194 | | 0.3 | 85.8 | 13.9 | |
| ⊠ | TS-1 | 18.0 | 4.76 | 0.177 | 0.076 | | 0.0 | 50.3 | 49.7 | |
| ▲ | TS-1 | 24.0 | 2 | 0.372 | 0.167 | | 0.0 | 83.7 | 16.3 | |
| ★ | TS-1 | 28.0 | 4.76 | 0.391 | | | 0.0 | 34.4 | 65.6 | |
| ⊙ | TS-1 | 34.0 | 19.1 | 0.915 | 0.157 | | 1.0 | 70.7 | 28.3 | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | TS-1 | 46.0 | Silty F/C SAND (SM) A-2-4 | NP | NP | NP | 1.48 | 6.62 |
| ⊠ | TS-1 | 48.0 | Poorly Graded F/C SAND (SP-SM)with Silt A-1-b | NP | NP | NP | 0.72 | 5.57 |
| ▲ | TS-1 | 58.0 | Sandy SILT (ML) A-5(4) | 44 | 39 | 5 | | |
| ★ | TS-1 | 74.0 | Sandy Elastic SILT (MH) A-7-5(16) | 55 | 32 | 23 | | |
| ⊙ | TS-1 | 78.0 | Sandy SILT (ML) A-4(4) | 31 | 23 | 8 | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | TS-1 | 46.0 | 9.52 | 4.333 | 0.269 | | 3.7 | 84.1 | 12.2 | |
| ⊠ | TS-1 | 48.0 | 19.1 | 6.971 | 0.594 | 0.149 | 10.1 | 80.1 | 9.8 | |
| ▲ | TS-1 | 58.0 | 4.76 | 0.406 | | | 0.0 | 35.8 | 64.2 | |
| ★ | TS-1 | 74.0 | 9.52 | 0.293 | | | 0.6 | 32.1 | 67.4 | |
| ⊙ | TS-1 | 78.0 | 9.52 | 1.814 | | | 2.0 | 33.3 | 64.7 | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **TS-1** | **82.0** | **Silty Fine SAND (SM) A-4(0)** | **NP** | **NP** | **NP** | | |
| ⊠ | **TS-1** | **106.0** | **Sandy SILT (ML) A-4(0)** | **NP** | **NP** | **NP** | | |
| ▲ | **TS-1** | **122.0** | **Sandy SILT (ML) A-4(0)** | **NP** | **NP** | **NP** | | |
| | | | | | | | | |
| | | | | | | | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **TS-1** | **82.0** | **4.76** | **0.384** | **0.076** | | **0.0** | **50.9** | **49.1** | |
| ⊠ | **TS-1** | **106.0** | **4.76** | **0.31** | | | **0.0** | **43.2** | **56.8** | |
| ▲ | **TS-1** | **122.0** | **9.52** | **0.362** | | | **0.2** | **44.5** | **55.3** | |
| | | | | | | | | | | |
| | | | | | | | | | | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | TS-1 | 8.0 | NP | NP | NP | 14 | Silty Fine SAND (SM) A-2-4 |
| ⊠ | TS-1 | 18.0 | 25 | 21 | 4 | 50 | Silty, Clayey Fine SAND (SC-SM) A-4(0) |
| ▲ | TS-1 | 24.0 | NP | NP | NP | 16 | Silty Fine SAND (SM) A-2-4 |
| ★ | TS-1 | 28.0 | 42 | 27 | 15 | 66 | Sandy SILT (ML) A-7-6(9) |
| ⊙ | TS-1 | 34.0 | NP | NP | NP | 28 | Silty Fine SAND (SM) A-2-4 |
| ✿ | TS-1 | 46.0 | NP | NP | NP | 12 | Silty F/C SAND (SM) A-2-4 |
| ○ | TS-1 | 48.0 | NP | NP | NP | 10 | Poorly Graded F/C SAND (SP-SM)with Silt A-1-b |
| △ | TS-1 | 58.0 | 44 | 39 | 5 | 64 | Sandy SILT (ML) A-5(4) |
| ⊗ | TS-1 | 74.0 | 55 | 32 | 23 | 67 | Sandy Elastic SILT (MH) A-7-5(16) |
| ⊕ | TS-1 | 78.0 | 31 | 23 | 8 | 65 | Sandy SILT (ML) A-4(4) |
| □ | TS-1 | 82.0 | NP | NP | NP | 49 | Silty Fine SAND (SM) A-4(0) |
| ⊛ | TS-1 | 106.0 | NP | NP | NP | 57 | Sandy SILT (ML) A-4(0) |
| ◓ | TS-1 | 122.0 | NP | NP | NP | 55 | Sandy SILT (ML) A-4(0) |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1140 & 16-1212 | **DATE SAMPLE RECEIVED:** | 8/8/2016 |
| **DESCRIPTION OF SOIL:** | Various | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 8/10/2016 |
| | | **DATE OF WEIGHING:** | 8/11/2016 |

| **BORING NO.** | SB-1 | SB-1 | SB-1 | SB-1 | SB-1 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1140A | 16-1140D | 16-1140G | 16-1140J | 16-1140M |
| **SAMPLE DEPTH** | 44.0-46.0' | 93.5-95.0' | 138.5-140.0' | 178.5-180.0' | 238.5-240.0' |
| **WATER CONTENT, W%** | 55.4 | 44.7 | 68.0 | 32.9 | 34.4 |

| **BORING NO.** | SB-1 | SB-1 | SB-1 | SB-1 | SB-1 |
|---|---|---|---|---|---|
| **SAMPLE NO.** | 16-1212A | 16-1212D | 16-1212G | 16-1212J | 16-1212M |
| **SAMPLE DEPTH** | 275.0-277.0' | 303.0-308.0' | 338.0-343.0' | 358.0-363.0' | 381.0-385.0' |
| **WATER CONTENT, W%** | 30.1 | 30.3 | 25.9 | 17.4 | 38.3 |


| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| **BORING NO.** | | | | | |
|---|---|---|---|---|---|
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **SB-1** | **46.0** | **Clayey Fine SAND (SC) A-2-7(2)** | **42** | **20** | **22** | | |
| ⊠ | **SB-1** | **95.0** | **Silty Fine SAND (SM) A-4(0)** | **NP** | **NP** | **NP** | | |
| ▲ | **SB-1** | **140.0** | **Fat CLAY (CH) A-7-6(33)** | **63** | **29** | **34** | | |
| ★ | **SB-1** | **180.0** | **Silty Fine SAND (SM) A-4(0)** | **NP** | **NP** | **NP** | | |
| ⊙ | **SB-1** | **240.0** | **Lean CLAY (CL) A-6(16)** | **40** | **23** | **17** | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **SB-1** | **46.0** | **9.52** | **0.419** | **0.124** | | **0.6** | **67.5** | **31.9** | |
| ⊠ | **SB-1** | **95.0** | **9.52** | **3.117** | **0.098** | | **2.2** | **56.5** | **41.3** | |
| ▲ | **SB-1** | **140.0** | **4.76** | **0.131** | | | **0.0** | **13.7** | **86.3** | |
| ★ | **SB-1** | **180.0** | **9.52** | **0.402** | **0.084** | | **0.2** | **56.3** | **43.5** | |
| ⊙ | **SB-1** | **240.0** | **4.76** | **0.122** | | | **0.0** | **12.2** | **87.8** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 11/2/16

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **SB-1** | **277.0** | **SILT (ML) with Sand A-4(1)** | **32** | **30** | **2** | | |
| ⊠ | **SB-1** | **308.0** | **Gravelly SILT (ML) with Sand A-4(1)** | **37** | **34** | **3** | | |
| ▲ | **SB-1** | **343.0** | **SILT (ML) with Sand A-6(12)** | **40** | **26** | **14** | | |
| ★ | **SB-1** | **363.0** | **Sandy SILT (ML) A-4(4)** | **33** | **24** | **9** | | |
| ⊙ | **SB-1** | **385.0** | **Elastic SILT (MH) A-7-5(31)** | **63** | **38** | **25** | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **SB-1** | **277.0** | **4.76** | **0.374** | | | **0.0** | **28.7** | **71.3** | |
| ⊠ | **SB-1** | **308.0** | **19.1** | **9.69** | | | **23.6** | **23.2** | **53.3** | |
| ▲ | **SB-1** | **343.0** | **9.52** | **0.21** | | | **0.6** | **16.5** | **82.9** | |
| ★ | **SB-1** | **363.0** | **19.1** | **7.814** | | | **8.6** | **26.8** | **64.6** | |
| ⊙ | **SB-1** | **385.0** | **4.76** | **0.079** | | | **0.0** | **5.3** | **94.7** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 11/2/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | SB-1 | 46.0 | 42 | 20 | 22 | 32 | Clayey Fine SAND (SC) A-2-7(2) |
| ⊠ | SB-1 | 95.0 | NP | NP | NP | 41 | Silty Fine SAND (SM) A-4(0) |
| ▲ | SB-1 | 140.0 | 63 | 29 | 34 | 86 | Fat CLAY (CH) A-7-6(33) |
| ★ | SB-1 | 180.0 | NP | NP | NP | 43 | Silty Fine SAND (SM) A-4(0) |
| ⊙ | SB-1 | 240.0 | 40 | 23 | 17 | 88 | Lean CLAY (CL) A-6(16) |
| ✿ | SB-1 | 277.0 | 32 | 30 | 2 | 71 | SILT (ML) with Sand A-4(1) |
| ○ | SB-1 | 308.0 | 37 | 34 | 3 | 53 | Gravelly SILT (ML) with Sand A-4(1) |
| △ | SB-1 | 343.0 | 40 | 26 | 14 | 83 | SILT (ML) with Sand A-6(12) |
| ⊗ | SB-1 | 363.0 | 33 | 24 | 9 | 65 | Sandy SILT (ML) A-4(4) |
| ⊕ | SB-1 | 385.0 | 63 | 38 | 25 | 95 | Elastic SILT (MH) A-7-5(31) |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## ORGANIC IMPURITIES DETERMINATION
## (AASHTO T267)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacment over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1140 | **DATE SAMPLE RECEIVED:** | 8/8/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 8/10/2016 |
| | | **DATE OF WEIGHING:** | 8/10/2016 |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | SB-1 | SB-1 | | | |
| **SAMPLE NO.** | 16-1140R/SS-10 | 16-1140S/SS-19 | | | |
| **SAMPLE DEPTH** | 18.0-20.0' | 36.0-38.0' | | | |
| **WT. OF CRUCIBLE + DRY SOIL (BEFORE IGNITION) (GRAMS)** | 169.95 | 175.57 | | | |
| **WT. OF CRUCIBLE + DRY SOIL (AFTER IGNITION) (GRAMS)** | 169.18 | 175.00 | | | |
| **WT. OF CRUCIBLE (GRAMS)** | 129.95 | 135.57 | | | |
| **WT. OF DRY SOIL (BEFORE IGNITION) (GRAMS)** | 40.00 | 40.00 | | | |
| **WT. OF DRY SOIL (AFTER IGNITION) (GRAMS)** | 39.23 | 39.43 | | | |
| **IGNITION LOSS (GRAMS)** | 0.77 | 0.57 | | | |
| **ORGANIC IMPURITIES %** | 1.92 | 1.42 | | | |

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 08/23/16 |
| Tested By: | jbr |
| Checked By: | jdt |

# Rapid Determination of Carbonate Content of Soils by ASTM D4373


| Boring ID | Sample ID | Depth, ft | *$CO_2$ Pressure, psi | Weight of Sample used, g | Weight $CaCO_3$, grams | Calcite Equivalent, % |
|---|---|---|---|---|---|---|
| SB-1 | 16-1140P | 168.5-170 | 6.20 | 1.00 | 5.09 | 509 |
| SB-1 | 16-1140Q | 198.5-200 | 5.40 | 1.00 | 4.43 | 443 |
| SB-1 | 16-1212U | 255-257 | 4.40 | 1.00 | 3.61 | 361 |
| SB-1 | 16-1212V | 308-313 | 3.90 | 1.00 | 3.20 | 320 |
| SB-1 | 16-1212W | 373-378 | 2.70 | 1.00 | 2.22 | 222 |

Notes: Calcium Carbonate content precise to +/- 1.5%

*$CO_2$ Pressure is based on the weight of sample as indicated in the table.

The reported Calcite Equivalent (%) is based on one gram

Figure 1: Calibration Curve





Weight Calcium Carbonate, g

% Calcite Equivalent = Weight x 100

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-1 | Test Date: | 11/04/16 | Checked By: | mcm |
| Depth : | 130.0-133.5 ft | Test Id: | 397424 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy silt | | | | |
| Sample Comment: | --- | | | | |

# Particle Size Analysis - ASTM D422




| %Cobble | %Gravel | %Sand | %Silt & Clay Size |
|---|---|---|---|
| — | 0.0 | 33.7 | 66.3 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| #4 | 4.75 | 100 | | |
| #10 | 2.00 | 100 | | |
| #20 | 0.85 | 99 | | |
| #40 | 0.42 | 98 | | |
| #60 | 0.25 | 97 | | |
| #100 | 0.15 | 93 | | |
| #200 | 0.075 | 66 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ = 0.1220 mm | $D_{30}$ = N/A |
| $D_{60}$ = N/A | $D_{15}$ = N/A |
| $D_{50}$ = N/A | $D_{10}$ = N/A |
| $C_u$ = N/A | $C_c$ = N/A |

**Classification**

ASTM Sandy Silt (ML)

AASHTO Clayey Soils (A-7-5 (8))


**Sample / Test Description**

Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-1 | Test Date: | 11/04/16 | Checked By: | mcm |
| Depth : | 130.0-133.5 ft | Test Id: | 397422 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy silt | | | | |
| Sample Comment: | --- | | | | |

# Atterberg Limits - ASTM D4318




| Symbol | Sample ID | Boring | Depth | Natural Moisture Content, % | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-1 | SB-1 | 130.0-133.5 ft | 38 | 42 | 30 | 12 | 0.6 | Sandy Silt (ML) |

Sample Prepared using the WET method
2% Retained on #40 Sieve
Dry Strength: HIGH
Dilatancy: SLOW
Toughness: LOW

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | jbr |
| Sample ID: | --- | Test Date: | 08/30/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 387124 | | |


# Moisture Content of Soil and Rock - ASTM D2216

| Boring ID | Sample ID | Depth | Description | Moisture Content,% |
|---|---|---|---|---|
| SB-1 | UD- 2 | 145.0-148.0 ft | Moist, olive sandy silt | 33.1 |

Notes: Temperature of Drying : 110º Celsius

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | jbr |
| Sample ID: | UD-2 | Test Date: | 08/31/16 | Checked By: | mcm |
| Depth : | 145.0-148.0 ft | Test Id: | 387107 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy silt | | | | |
| Sample Comment: | --- | | | | |

# Particle Size Analysis - ASTM D422




| % Cobble | % Gravel | % Sand | % Silt & Clay Size |
|---|---|---|---|
| — | 0.2 | 42.5 | 57.3 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| 0.375 in | 9.50 | 100 | | |
| #4 | 4.75 | 100 | | |
| #10 | 2.00 | 97 | | |
| #20 | 0.85 | 96 | | |
| #40 | 0.42 | 94 | | |
| #60 | 0.25 | 91 | | |
| #100 | 0.15 | 84 | | |
| #200 | 0.075 | 57 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ =0.1641 mm | $D_{30}$ =N/A |
| $D_{60}$ =0.0805 mm | $D_{15}$ =N/A |
| $D_{50}$ =N/A | $D_{10}$ =N/A |
| $C_u$ =N/A | $C_c$ =N/A |

**Classification**

ASTM Sandy Silt (ML)

AASHTO Clayey Soils (A-6 (6))

**Sample/Test Description**


Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

printed 9/8/2016 3:36:05 PM

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-2 | Test Date: | 08/31/16 | Checked By: | mcm |
| Depth : | 145.0-148.0 ft | Test Id: | 387115 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy silt | | | | |
| Sample Comment: | --- | | | | |

# Atterberg Limits - ASTM D4318





| Symbol | Sample ID | Boring | Depth | Natural Moisture Content,% | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-2 | SB-1 | 45.0-148. ft | 33 | 38 | 25 | 13 | 0.6 | Sandy Silt (ML) |


Sample Prepared using the WET method
6% Retained on #40 Sieve
Dry Strength: VERY HIGH
Dilatancy: RAPID
Toughness: LOW

GeoTesting EXPRESS

| | |
|---|---|
| Client: F&ME Consultants | |
| Project Name: US-21 Replacement Bridge | |
| Project Location: --- | |
| Project Number: GTX-305005 | |
| Tested By: md | Checked By: mcm |
| Boring ID: SB-1 | |
| Preparation: intact | |
| Description: Moist, olive sandy silt | |
| Classification: Sandy silt | |
| Group Symbol: ML | |
| Liquid Limit: 38 | Plastic Limit: 25 |
| Plasticity Index: 13 | Estimated Specific Gravity: 2.7 |


## CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767




| | | | | | |
|---|---|---|---|---|---|
| Symbol | | ■ | ● | ▲ | |
| Sample ID | | UD-2 | UD-2 | UD-2 | |
| Depth, ft | | 145.0-148.0 ft | 145.0-148.0 ft | 145.0-148.0 ft | |
| Test Number | | CU-8-1 | CU-8-2 | CU-8-3 | |
| Initial | Height, in | 6.100 | 5.890 | 6.200 | |
| | Diameter, in | 2.860 | 2.850 | 2.850 | |
| | Moisture Content (from Cuttings), % | 33.8 | 33.2 | 29.9 | |
| | Dry Density, pcf | 85.9 | 88.2 | 93.1 | |
| | Saturation (Wet Method), % | 94.8 | 98.2 | 99.7 | |
| | Void Ratio | 0.963 | 0.912 | 0.810 | |
| Before Shear | Moisture Content, % | 33.3 | 31.2 | 25.8 | |
| | Dry Density, pcf | 88.8 | 91.5 | 99.3 | |
| | Cross-sectional Area (Method A), in² | 6.273 | 6.205 | 6.049 | |
| | Saturation, % | 100.0 | 100.0 | 100.0 | |
| | Void Ratio | 0.898 | 0.842 | 0.698 | |
| | Back Pressure, psi | 131.0 | 121.0 | 33.00 | |
| Vertical Effective Consolidation Stress, psi | | 39.97 | 49.98 | 59.94 | |
| Horizontal Effective Consolidation Stress, psi | | 40.00 | 50.00 | 59.99 | |
| Vertical Strain after Consolidation, % | | 0.7774 | 0.7386 | 0.8643 | |
| Volumetric Strain after Consolidation, % | | 2.735 | 3.028 | 5.571 | |
| Time to 50% Consolidation, min | | 1.000 | 0.6400 | 1.000 | |
| Shear Strength, psi | | 27.13 | 34.45 | 45.85 | |
| Strain at Failure, % | | 2.08 | 2.27 | 9.63 | |
| Strain Rate, %/min | | 0.01600 | 0.01600 | 0.01600 | |
| Deviator Stress at Failure, psi | | 54.25 | 68.90 | 91.70 | |
| Effective Minor Principal Stress at Failure, psi | | 12.82 | 17.93 | 22.91 | |
| Effective Major Principal Stress at Failure, psi | | 67.07 | 86.84 | 114.6 | |
| B-Value | | 0.96 | 0.95 | 1.00 | |


Notes:
- Before Shear Saturation set to 100% for phase calculation.
- Moisture Content determined by ASTM D2216.
- Atterberg Limits determined by ASTM D4318.
- Deviator Stress includes membrane correction.
- Values for c and φ determined from best-fit straight line for the specific test conditions. Actual strength parameters may vary and should be determined by an engineer for site conditions.





Remarks:

System O

# CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767





| | Sample No. | Test No. | Depth | Tested By | Test Date | Checked By | Check Date | Test File |
|---|---|---|---|---|---|---|---|---|
| ■ | UD-2 | CU-8-1 | 145.0-148.0 ft | md | 8/28/16 | mcm | 9/9/16 | 305005-CU-8-1m.dat |
| ● | UD-2 | CU-8-2 | 145.0-148.0 ft | md | 8/28/16 | mcm | 9/8/16 | 305005-CU-8-2m.dat |
| ▲ | UD-2 | CU-8-3 | 145.0-148.0 ft | md | 8/28/16 | mm | 9/9/16 | 305005-CU-8-3m.dat |
| | | | | | | | | |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: SB-1 | Sample Type: intact | |
| Description: Moist, olive sandy silt | | |
| Remarks: System O | | |

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-4 | Test Date: | 11/04/16 | Checked By: | mcm |
| Depth : | 200.0-203.0 ft | Test Id: | 397425 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy silt | | | | |
| Sample Comment: | --- | | | | |

# Particle Size Analysis - ASTM D422




| %Cobble | %Gravel | %Sand | %Silt & Clay Size |
|---|---|---|---|
| – | 0.1 | 47.8 | 52.1 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| 0.375 in | 9.50 | 100 | | |
| #4 | 4.75 | 100 | | |
| #10 | 2.00 | 100 | | |
| #20 | 0.85 | 100 | | |
| #40 | 0.42 | 99 | | |
| #60 | 0.25 | 98 | | |
| #100 | 0.15 | 83 | | |
| #200 | 0.075 | 52 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ = 0.1611 mm | $D_{30}$ = N/A |
| $D_{60}$ = 0.0896 mm | $D_{15}$ = N/A |
| $D_{50}$ = N/A | $D_{10}$ = N/A |
| $C_u$ = N/A | $C_c$ = N/A |

**Classification**

ASTM Sandy Silt (ML)

AASHTO Clayey Soils (A-7-6 (6))


**Sample / Test Description**

Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-4 | Test Date: | 11/04/16 | Checked By: | mcm |
| Depth : | 200.0-203.0 ft | Test Id: | 397423 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy silt | | | | |
| Sample Comment: | --- | | | | |

# Atterberg Limits - ASTM D4318




| Symbol | Sample ID | Boring | Depth | Natural Moisture Content, % | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-4 | SB-1 | 00.0-203. ft | 32 | 43 | 27 | 16 | 0.3 | Sandy Silt (ML) |

Sample Prepared using the WET method
1% Retained on #40 Sieve
Dry Strength: HIGH
Dilatancy: SLOW
Toughness: LOW

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | jbr |
| Sample ID: | --- | Test Date: | 08/30/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 387124 | | |


# Moisture Content of Soil and Rock - ASTM D2216

| Boring ID | Sample ID | Depth | Description | Moisture Content,% |
|---|---|---|---|---|
| SB-1 | UD-5 | 230.0-233.0 ft | Moist, olive silt with sand | 32.6 |

Notes: Temperature of Drying : 110º Celsius

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | jbr |
| Sample ID: | UD-5 | Test Date: | 08/31/16 | Checked By: | mcm |
| Depth : | 230.0-233.0 ft | Test Id: | 387108 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive silt with sand | | | | |
| Sample Comment: | --- | | | | |

# Particle Size Analysis - ASTM D422




| % Cobble | % Gravel | % Sand | % Silt & Clay Size |
|---|---|---|---|
| — | 1.0 | 21.3 | 77.7 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| 0.375 in | 9.50 | 100 | | |
| #4 | 4.75 | 99 | | |
| #10 | 2.00 | 98 | | |
| #20 | 0.85 | 98 | | |
| #40 | 0.42 | 97 | | |
| #60 | 0.25 | 96 | | |
| #100 | 0.15 | 92 | | |
| #200 | 0.075 | 78 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ =0.1069 mm | $D_{30}$ =N/A |
| $D_{60}$ =N/A | $D_{15}$ =N/A |
| $D_{50}$ =N/A | $D_{10}$ =N/A |
| $C_u$ =N/A | $C_c$ =N/A |

**Classification**

ASTM Silt with sand (ML)

AASHTO Clayey Soils (A-7-5 (15))


**Sample/Test Description**

Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-5 | Test Date: | 08/31/16 | Checked By: | mcm |
| Depth : | 230.0-233.0 ft | Test Id: | 387116 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive silt with sand | | | | |
| Sample Comment: | --- | | | | |

# Atterberg Limits - ASTM D4318





| Symbol | Sample ID | Boring | Depth | Natural Moisture Content,% | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-5 | SB-1 | 30.0-233. ft | 33 | 48 | 30 | 18 | 0.1 | Silt with sand (ML) |


Sample Prepared using the WET method
3% Retained on #40 Sieve
Dry Strength: VERY HIGH
Dilatancy: RAPID
Toughness: LOW

GeoTesting EXPRESS

| | |
|---|---|
| Client: F&ME Consultants | |
| Project Name: US-21 Replacement Bridge | |
| Project Location: --- | |
| Project Number: GTX-305005 | |
| Tested By: md | Checked By: mcm |
| Boring ID: SB-1 | |
| Preparation: intact | |
| Description: Moist, olive silt with sand | |
| Classification: Silt with sand | |
| Group Symbol: ML | |
| Liquid Limit: 48 | Plastic Limit: 30 |
| Plasticity Index: 18 | Estimated Specific Gravity: 2.7 |


## CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767




| | | | | |
|---|---|---|---|---|
| Symbol | | ■ | ● | ▲ |
| Sample ID | | UD-5 | UD-5 | UD-5 |
| Depth, ft | | 230.0-233.0 ft | 230.0-233.0 ft | 230.0-233.0 ft |
| Test Number | | CU-7-1 | CU-7-2 | CU-7-3 |
| Initial | Height, in | 6.150 | 6.150 | 6.100 |
| | Diameter, in | 2.850 | 2.840 | 2.830 |
| | Moisture Content (from Cuttings), % | 31.0 | 29.5 | 29.4 |
| | Dry Density, pcf | 89.8 | 89.9 | 90.8 |
| | Saturation (Wet Method), % | 95.5 | 91.2 | 92.6 |
| | Void Ratio | 0.876 | 0.875 | 0.857 |
| Before Shear | Moisture Content, % | 31.5 | 29.1 | 27.8 |
| | Dry Density, pcf | 91.1 | 94.4 | 96.3 |
| | Cross-sectional Area (Method A), in² | 6.371 | 6.129 | 6.058 |
| | Saturation, % | 100.0 | 100.0 | 100.0 |
| | Void Ratio | 0.849 | 0.785 | 0.750 |
| | Back Pressure, psi | 141.0 | 121.0 | 123.0 |
| Vertical Effective Consolidation Stress, psi | | 79.96 | 89.91 | 99.90 |
| Horizontal Effective Consolidation Stress, psi | | 80.02 | 90.00 | 100.0 |
| Vertical Strain after Consolidation, % | | 1.201 | 1.611 | 2.136 |
| Volumetric Strain after Consolidation, % | | 1.133 | 4.820 | 5.775 |
| Time to 50% Consolidation, min | | 0.2500 | 13.39 | 42.25 |
| Shear Strength, psi | | 61.43 | 64.32 | 63.57 |
| Strain at Failure, % | | 2.64 | 3.03 | 3.35 |
| Strain Rate, %/min | | 0.01600 | 0.01600 | 0.01600 |
| Deviator Stress at Failure, psi | | 122.9 | 128.6 | 127.1 |
| Effective Minor Principal Stress at Failure, psi | | 35.12 | 38.10 | 37.52 |
| Effective Major Principal Stress at Failure, psi | | 158.0 | 166.7 | 164.7 |
| B-Value | | 0.95 | 0.95 | 0.95 |


Notes:
- Before Shear Saturation set to 100% for phase calculation.
- Moisture Content determined by ASTM D2216.
- Atterberg Limits determined by ASTM D4318.
- Deviator Stress includes membrane correction.
- Values for c and φ determined from best-fit straight line for the specific test conditions. Actual strength parameters may vary and should be determined by an engineer for site conditions.





Remarks:

System K

# CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767




| | Sample No. | Test No. | Depth | Tested By | Test Date | Checked By | Check Date | Test File |
|---|---|---|---|---|---|---|---|---|
| ■ | UD-5 | CU-7-1 | 230.0-233.0 ft | md | 8/28/16 | mcm | 9/8/16 | 305005-CU-7-1m.dat |
| ● | UD-5 | CU-7-2 | 230.0-233.0 ft | md | 8/26/16 | mcm | 9/8/16 | 305005-CU-7-2m.dat |
| ▲ | UD-5 | CU-7-3 | 230.0-233.0 ft | md | 8/26/16 | mcm | 9/8/16 | 305005-CU-7-3m.dat |
| | | | | | | | | |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: SB-1 | Sample Type: intact | |
| Description: Moist, olive silt with sand | | |
| Remarks: System K | | |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

**PROJECT:** US 21 Bridge Replacement over Harbor River **PROJECT NO.:** G5396

**SAMPLE NUMBER:** 16-1208D **DATE SAMPLE RECEIVED:**

**DESCRIPTION OF SOIL:** Sandy Fat Clay (CH) A-7-6(34)

**TESTED BY:** Fugro **DATE OF TESTING:**

**DATE OF WEIGHING:**

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | SB-1/UD-6 | | | | |
| **SAMPLE NO.** | 16-1208D | | | | |
| **SAMPLE DEPTH** | 257.0-260.0' | | | | |
| **WATER CONTENT, W%** | 31.6 | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |


| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **SB-1** | **260.0** | **Sandy Fat CLAY (CH) A-7-6(34)** | **76** | **21** | **55** | | |

| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **SB-1** | **260.0** | **9.52** | **1.102** | | | **0.0** | **34.9** | **65.1** | |

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **SB-1** | **260.0** | **76** | **21** | **55** | **65** | **Sandy Fat CLAY (CH) A-7-6(34)** |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

**PROJECT:** US 21 Bridge Replacement over Harbor River **PROJECT NO.:** G5396

**SAMPLE NUMBER:** **DATE SAMPLE RECEIVED:**

**DESCRIPTION OF SOIL:** Fat Clay (CH) A-7-6(104)

**TESTED BY:** Fugro **DATE OF TESTING:**

**DATE OF WEIGHING:**

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | SB-1/UD-9 | | | | |
| **SAMPLE NO.** | 16-1211D | | | | |
| **SAMPLE DEPTH** | 378.0-381.0' | | | | |
| **WATER CONTENT, W%** | 39.3 | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|
| ● **SB-1** | **381.0** | **Fat CLAY (CH) A-7-6(104)** | **133** | **29** | **104** | | |


| BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|
| ● **SB-1** | **381.0** | **4.76** | **0.146** | | | **0.0** | **12.2** | **87.8** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 11/2/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River


**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **SB-1** | **381.0** | **133** | **29** | **104** | **88** | **Fat CLAY (CH) A-7-6(104)** |

# UNCONFINED COMPRESSIVE STRENGTH TEST REPORT
ASTM D2166 / AASHTO T208

## Stress/Strain Curve - Sample 16-1212P




| | | | |
|---|---|---|---|
| Average Initial Diameter (Do): | 2.328 in. | Sample Volume: | 21.142 $in^3$ |
| Average Initial Height (Lo): | 4.967 in. | Sample Volume: | 0.012 $ft^3$ |
| Average Initial Area (Ao): | 4.257 $in^2$ | Moist Sample Weight: | 1.47 lbs. |
| In-Situ Moist Unit Weight: | 119.7 pcf | In-Situ Dry Unit Weight: | 92.8 pcf |
| Failure Mode: | | | |

| | | | |
|---|---|---|---|
| Project Name | US-21 Bridge Replacement over Harbor River | | |
| Project Number | G5396.00 | Date | 8/11/2016 |
| SCDOT File # | P026862 | PIN # | |
| Sample/Location | SB-1 / NQ-1 | | |
| Depth/Elevation | 250.0' - 255.0' | | |


Sample Type : Undisturbed - Shelby Tube
Target Strain Rate : 1% per minute
Description:

| | |
|---|---|
| PI= | % Fines= |
| NMC = 29.0% | L/D Ratio = 2.13 |
| $\sigma_{c\text{-}ULT}$ = 143.5 | $\varepsilon_{ULT}$ = 4.6% |

F&ME CONSULTANTS
3112 Devine Street Columbia, SC 29205
Geotechnical · Environmental · Materials

# UNCONFINED COMPRESSIVE STRENGTH TEST REPORT
## ASTM D2166 / AASHTO T208

### Stress/Strain Curve - Sample 16-1212Q




| | | | |
|---|---|---|---|
| Average Initial Diameter (Do): | 2.395 in. | Sample Volume: | 23.025 $in^3$ |
| Average Initial Height (Lo): | 5.111 in. | Sample Volume: | 0.013 $ft^3$ |
| Average Initial Area (Ao): | 4.505 $in^2$ | Moist Sample Weight: | 1.56 lbs. |
| In-Situ Moist Unit Weight: | 116.8 pcf | In-Situ Dry Unit Weight: | 88.7 pcf |
| Failure Mode: | | | |

| | | | |
|---|---|---|---|
| Project Name | US-21 Bridge Replacement over Harbor River | | |
| Project Number | G5396.00 | Date | 8/11/2016 |
| SCDOT File # | P026862 | PIN # | |
| Sample/Location | SB-1 / NQ-11 | | |
| Depth/Elevation | 298.0' - 303.0' | | |

Sample Type : Undisturbed - Shelby Tube
Target Strain Rate : 1% per minute
Description:

| | |
|---|---|
| PI= | % Fines= |
| NMC = 31.7% | L/D Ratio = 2.13 |
| $\sigma_{c\text{-}ULT}$ = 166.5 | $\varepsilon_{ULT}$ = 3.9% |



F&ME CONSULTANTS

3112 Devine Street Columbia, SC 29205

Geotechnical · Environmental · Materials

# UNCONFINED COMPRESSIVE STRENGTH TEST REPORT
## ASTM D2166 / AASHTO T208

### Stress/Strain Curve - Sample 16-1212R




| | | | |
|---|---|---|---|
| Average Initial Diameter (Do): | 2.445 in. | Sample Volume: | 24.875 $in^3$ |
| Average Initial Height (Lo): | 5.298 in. | Sample Volume: | 0.014 $ft^3$ |
| Average Initial Area (Ao): | 4.695 $in^2$ | Moist Sample Weight: | 1.63 lbs. |
| In-Situ Moist Unit Weight: | 112.9 pcf | In-Situ Dry Unit Weight: | 92.3 pcf |
| Failure Mode: | | | |

| | | | |
|---|---|---|---|
| Project Name | US-21 Bridge Replacement over Harbor River | | |
| Project Number | G5396.00 | Date | 8/11/2016 |
| SCDOT File # | P026862 | PIN # | |
| Sample/Location | SB-1 / NQ-16 | | |
| Depth/Elevation | 323.0' - 328.0' | | |

Sample Type : Undisturbed - Shelby Tube
Target Strain Rate : 1% per minute
Description:

| | |
|---|---|
| PI= | % Fines= |
| NMC = 22.3% | L/D Ratio = 2.17 |
| $\sigma_{c\text{-}ULT}$ = 85.9 | $\varepsilon_{ULT}$ = 3.7% |



F&ME CONSULTANTS

3112 Devine Street Columbia, SC 29205

Geotechnical · Environmental · Materials

# UNCONFINED COMPRESSIVE STRENGTH TEST REPORT
ASTM D2166 / AASHTO T208

## Stress/Strain Curve - Sample 16-1212S




| | | | |
|---|---|---|---|
| Average Initial Diameter (Do): | 2.416 in. | Sample Volume: | 25.352 $in^3$ |
| Average Initial Height (Lo): | 5.53 in. | Sample Volume: | 0.0147 $ft^3$ |
| Average Initial Area (Ao): | 4.584 $in^2$ | Moist Sample Weight: | 1.78 lbs. |
| In-Situ Moist Unit Weight: | 121.5 pcf | In-Situ Dry Unit Weight: | 95.9 pcf |
| Failure Mode: | | | |

| | | | |
|---|---|---|---|
| Project Name | US-21 Bridge Replacement over Harbor River | | |
| Project Number | G5396.00 | Date | 8/11/2016 |
| SCDOT File # | P026862 | PIN # | |
| Sample/Location | SB-1 / NQ-23 | | |
| Depth/Elevation | 358.0' - 363.0' | | |


Sample Type : Undisturbed - Shelby Tube
Target Strain Rate : 1% per minute
Description:

| | |
|---|---|
| PI= | % Fines= |
| NMC = 26.8% | L/D Ratio = 2.29 |
| $\sigma_{c\text{-}ULT}$ = 236.4 | $\varepsilon_{ULT}$ = 4.8% |

F&ME CONSULTANTS
3112 Devine Street Columbia, SC 29205
Geotechnical · Environmental · Materials

# UNCONFINED COMPRESSIVE STRENGTH TEST REPORT
## ASTM D2166 / AASHTO T208

### Stress/Strain Curve - Sample 16-1212T




| | | | |
|---|---|---|---|
| Average Initial Diameter (Do): | 2.391 in. | Sample Volume: | 22.284 $in^3$ |
| Average Initial Height (Lo): | 4.963 in. | Sample Volume: | 0.0129 $ft^3$ |
| Average Initial Area (Ao): | 4.490 $in^2$ | Moist Sample Weight: | 1.50 lbs. |
| In-Situ Moist Unit Weight: | 116.4 pcf | In-Situ Dry Unit Weight: | 88.0 pcf |
| Failure Mode: | | | |

| | | | |
|---|---|---|---|
| Project Name | US-21 Bridge Replacement over Harbor River | | |
| Project Number | G5396.00 | Date | 8/11/2016 |
| SCDOT File # | P026862 | PIN # | |
| Sample/Location | SB-1 / NQ-27 | | |
| Depth/Elevation | 381.0' - 385.0' | | |

Sample Type : Undisturbed - Shelby Tube
Target Strain Rate : 1% per minute
Description:

| | |
|---|---|
| PI= | % Fines= |
| NMC = 32.3% | L/D Ratio = 2.08 |
| $\sigma_{c\text{-}ULT}$ = 233.5 | $\varepsilon_{ULT}$ = 4.1% |


F&ME CONSULTANTS


3112 Devine Street Columbia, SC 29205


Geotechnical · Environmental · Materials

GeoTesting EXPRESS

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 10/28/16, 11/3/16 |
| Tested By: | sg |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD-1 |
| Depth, ft: | 130.0-133.5 |
| **Test Confining Pressure, psi:** | **35 55** |
| Visual Description: | Moist, olive sandy silt |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015









Notes: Data from two tests, each at a different confining pressure, plotted together on the same graph.

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 11/03/16 |
| Tested By: | sg |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD-1 |
| Depth, ft: | 130.0-133.5 |
| **Test Confining Pressure, psi:** | **35** |
| Visual Description: | Moist, olive sandy silt |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015




| | |
|---|---|
| Initial Diameter, in: | 2.49 |
| Initial Height, in: | 5.00 |
| Initial Mass, grams: | 699 |
| Initial Moisture Content, %: | 38.0 |
| Initial Dry Density, pcf: | 79.3 |
| Initial Bulk Density, pcf: | 109.4 |
| Initial Degree of Saturation: | 92.2 |
| Initial Void Ratio: | 1.10 |

| | |
|---|---|
| Final Diameter, in: | 2.45 |
| Final Height, in: | 4.90 |
| Final Mass, grams: | 698.39 |
| Final Moisture Content, %: | 36.6 |
| Final Dry Density, pcf: | 83.7 |
| Final Bulk Density, pcf: | 114.4 |
| Final Degree of Saturation: | 99.1 |
| Final Void Ratio: | 0.99 |

Notes: Moisture content obtained from sample trimmings

Isotropic stress conditions

GeoTesting EXPRESS

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 11/03/16 |
| Tested By: | sg |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD-1 |
| Depth, ft: | 130.0-133.5 |
| **Test Confining Pressure, psi:** | **35** |
| Visual Description: | Moist, olive sandy silt |
| Test Conditions: | Confining Stress of 35 psi over a range of strains from 0.000112 to 6.15% with a forced sinusoidal vibration. |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015

Apparatus Used: Geocomp Corp. quasi-fixed/free boundry condition automated RCTS Test System

| | | | |
|---|---|---|---|
| Active Mass, g: | 2144.75 | Torque Calibration Factor, N-m/V: | 12.9 |
| Passive Mass, g: | 1053.2 | Accelerometer Calibration Factor, rad/s$^2$/V: | 3293 |
| Active Inertia, kg-m$^2$: | 1.66E-03 | | |
| Passive Inertia, kg-m$^2$: | 0.0012425 | | |

| Elapsed Time | Excitation | Frequency | Axial Strain | Volumetric Strain | * Pore Pressure | Effective Confining Stress | Average Strain Amplitude | Shear Modulus, G | Damping Ratio, D |
|---|---|---|---|---|---|---|---|---|---|
| min | % | Hz | % | % | psi | psi | % | psi | % |
| 0.31 | 0.040 | 116 | 2.91E-02 | 0.029 | --- | 35 | 1.12E-04 | 1.12E+04 | 3.19 |
| 0.52 | 0.100 | 115 | 2.91E-02 | 0.029 | --- | 35 | 6.53E-04 | 1.12E+04 | 2.43 |
| 0.62 | 0.158 | 115 | 2.91E-02 | 0.029 | --- | 35 | 1.27E-03 | 1.12E+04 | 2.32 |
| 0.73 | 0.251 | 115 | 2.91E-02 | 0.029 | --- | 35 | 1.91E-03 | 1.11E+04 | 2.68 |
| 0.83 | 0.398 | 114 | 2.91E-02 | 0.029 | --- | 35 | 3.09E-03 | 1.09E+04 | 2.77 |
| 0.93 | 0.631 | 113 | 2.91E-02 | 0.029 | --- | 35 | 5.53E-03 | 1.07E+04 | 2.86 |
| 1.04 | 1.000 | 111 | 2.91E-02 | 0.029 | --- | 35 | 9.17E-03 | 1.03E+04 | 3.23 |
| 1.14 | 1.586 | 109 | 2.91E-02 | 0.029 | --- | 35 | 1.50E-02 | 9.81E+03 | 3.68 |
| 1.24 | 2.515 | 106 | 2.91E-02 | 0.029 | --- | 35 | 2.35E-02 | 9.20E+03 | 4.20 |
| 1.35 | 3.989 | 101 | 2.91E-02 | 0.029 | --- | 35 | 3.87E-02 | 8.35E+03 | 5.03 |
| 1.56 | 6.338 | 90 | 2.91E-02 | 0.029 | --- | 35 | 8.69E-02 | 6.49E+03 | 6.77 |
| 1.87 | 10.087 | 72 | 2.91E-02 | 0.029 | --- | 35 | 2.33E-01 | 4.10E+03 | 9.48 |
| 2.18 | 16.021 | 54 | 2.91E-02 | 0.029 | --- | 35 | 6.36E-01 | 2.25E+03 | 12.54 |
| 2.49 | 25.446 | 36 | 2.91E-02 | 0.029 | --- | 35 | 1.91E+00 | 9.70E+02 | 16.91 |
| 2.80 | 40.386 | 20 | 2.91E-02 | 0.029 | --- | 35 | 6.15E+00 | 1.66E+02 | 40.01 |

The Shear Wave Velocity can be determined by the following equation:


Vs = sqrt(G*g/bulk density)


where: Vs = shear wave velocity
G = shear modulus
g = acceleration due to gravity, 9.81 m/sec$^2$
final bulk density

* Test is run with drainage valve open, but speed of test is such that excess pore pressure could develop, at higher shear strains within specimen.

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 10/28/16 |
| Tested By: | sg |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD-1 |
| Depth, ft: | 130.0-133.5 |
| **Test Confining Pressure, psi:** | **55** |
| Visual Description: | Moist, olive sandy silt |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015




| | |
|---|---|
| Initial Diameter, in: | 2.85 |
| Initial Height, in: | 6.00 |
| Initial Mass, grams: | 1106 |
| Initial Moisture Content, %: | 40.1 |
| Initial Dry Density, pcf: | 78.6 |
| Initial Bulk Density, pcf: | 110.1 |
| Initial Degree of Saturation: | 95.7 |
| Initial Void Ratio: | 1.12 |

| | |
|---|---|
| Final Diameter, in: | 2.79 |
| Final Height, in: | 5.87 |
| Final Mass, grams: | 1092 |
| Final Moisture Content, %: | 37.1 |
| Final Dry Density, pcf: | 83.5 |
| Final Bulk Density, pcf: | 114.5 |
| Final Degree of Saturation: | 99.9 |
| Final Void Ratio: | 0.99 |

Notes: Moisture content obtained from sample trimmings

Isotropic stress conditions

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 10/28/16 |
| Tested By: | sg |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD-1 |
| Depth, ft: | 130.0-133.5 |
| **Test Confining Pressure, psi:** | **55** |
| Visual Description: | Moist, olive sandy silt |
| Test Conditions: | Confining Stress of 55 psi over a range of strains from 0.0000519 to 4.99% with a forced sinusoidal vibration. |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015

Apparatus Used: Geocomp Corp. quasi-fixed/free boundry condition automated RCTS Test System

| | | | |
|---|---|---|---|
| Active Mass, g: | 2144.75 | Torque Calibration Factor, N-m/V: | 12.9 |
| Passive Mass, g: | 1053.2 | Accelerometer Calibration Factor, rad/s$^2$/V: | 3293 |
| Active Inertia, kg-m$^2$: | 1.66E-03 | | |
| Passive Inertia, kg-m$^2$: | 0.0012425 | | |

| Elapsed Time | Excitation | Frequency | Axial Strain | Volumetric Strain | * Pore Pressure | Effective Confining Stress | Average Strain Amplitude | Shear Modulus, G | Damping Ratio, D |
|---|---|---|---|---|---|---|---|---|---|
| min | % | Hz | % | % | psi | psi | % | psi | % |
| 0.31 | 0.039 | 172 | 4.35E-02 | 0.043 | --- | 54 | 5.19E-05 | 2.00E+04 | 1.22 |
| 0.52 | 0.098 | 172 | 4.35E-02 | 0.043 | --- | 54 | 1.49E-04 | 1.99E+04 | 1.95 |
| 0.62 | 0.156 | 172 | 4.35E-02 | 0.043 | --- | 54 | 2.62E-04 | 1.99E+04 | 1.91 |
| 0.73 | 0.247 | 171 | 4.35E-02 | 0.043 | --- | 54 | 5.55E-04 | 1.98E+04 | 1.89 |
| 0.83 | 0.392 | 171 | 4.35E-02 | 0.043 | --- | 54 | 1.14E-03 | 1.98E+04 | 1.97 |
| 0.93 | 0.621 | 171 | 4.35E-02 | 0.043 | --- | 54 | 2.05E-03 | 1.96E+04 | 1.93 |
| 1.04 | 0.983 | 170 | 4.35E-02 | 0.043 | --- | 54 | 3.53E-03 | 1.94E+04 | 2.02 |
| 1.14 | 1.558 | 168 | 4.35E-02 | 0.043 | --- | 54 | 5.79E-03 | 1.90E+04 | 2.17 |
| 1.24 | 2.470 | 166 | 4.35E-02 | 0.043 | --- | 54 | 8.91E-03 | 1.85E+04 | 2.41 |
| 1.35 | 3.919 | 163 | 4.35E-02 | 0.043 | --- | 54 | 1.45E-02 | 1.77E+04 | 2.81 |
| 1.56 | 6.230 | 154 | 4.35E-02 | 0.043 | --- | 54 | 2.98E-02 | 1.56E+04 | 3.75 |
| 1.87 | 9.925 | 137 | 4.35E-02 | 0.043 | --- | 54 | 6.75E-02 | 1.23E+04 | 5.44 |
| 2.28 | 15.835 | 114 | 4.35E-02 | 0.043 | --- | 54 | 1.58E-01 | 8.31E+03 | 7.87 |
| 2.80 | 25.282 | 81 | 4.35E-02 | 0.043 | --- | 54 | 4.36E-01 | 4.13E+03 | 11.39 |
| 3.52 | 40.388 | 20 | 4.35E-02 | 0.043 | --- | 54 | 4.99E+00 | 1.38E+02 | 49.99 |

The Shear Wave Velocity can be determined by the following equation:


Vs = sqrt(G*g/bulk density)

where: Vs = shear wave velocity
G = shear modulus
g = acceleration due to gravity, 9.81 m/sec$^2$
final bulk density

* Test is run with drainage valve open, but speed of test is such that excess pore pressure could develop, at higher shear strains within specimen.

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-1 | Test Date: | 11/04/16 | Checked By: | mcm |
| Depth : | 130.0-133.5 ft | Test Id: | 397424 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy silt | | | | |
| Sample Comment: | --- | | | | |

# Particle Size Analysis - ASTM D422




| %Cobble | %Gravel | %Sand | %Silt & Clay Size |
|---|---|---|---|
| — | 0.0 | 33.7 | 66.3 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| #4 | 4.75 | 100 | | |
| #10 | 2.00 | 100 | | |
| #20 | 0.85 | 99 | | |
| #40 | 0.42 | 98 | | |
| #60 | 0.25 | 97 | | |
| #100 | 0.15 | 93 | | |
| #200 | 0.075 | 66 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ = 0.1220 mm | $D_{30}$ = N/A |
| $D_{60}$ = N/A | $D_{15}$ = N/A |
| $D_{50}$ = N/A | $D_{10}$ = N/A |
| $C_u$ = N/A | $C_c$ = N/A |

**Classification**

ASTM Sandy Silt (ML)

AASHTO Clayey Soils (A-7-5 (8))


**Sample / Test Description**

Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-1 | Test Date: | 11/04/16 | Checked By: | mcm |
| Depth : | 130.0-133.5 ft | Test Id: | 397422 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy silt | | | | |
| Sample Comment: | --- | | | | |

# Atterberg Limits - ASTM D4318






| Symbol | Sample ID | Boring | Depth | Natural Moisture Content, % | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-1 | SB-1 | 130.0-133.5 ft | 38 | 42 | 30 | 12 | 0.6 | Sandy Silt (ML) |

Sample Prepared using the WET method
2% Retained on #40 Sieve
Dry Strength: HIGH
Dilatancy: SLOW
Toughness: LOW

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 10/18/16, 10/19/16, 10/25/16 |
| Tested By: | njh |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD-4 |
| Depth, ft: | 200.0-203.0 |
| **Test Confining Pressure, psi:** | **60 70 80** |
| Visual Description: | Moist, olive gray silty clay |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015









Notes: Data from three tests, each at a different confining pressure, plotted together on the same graph.

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 10/18/16 |
| Tested By: | njh |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD4 |
| Depth, ft: | 200.0-203.0 |
| **Test Confining Pressure, psi:** | **60** |
| Visual Description: | Moist, olive gray clay |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015




| | |
|---|---|
| Initial Diameter, in: | 2.83 |
| Initial Height, in: | 5.80 |
| Initial Mass, grams: | 1110 |
| Initial Moisture Content, %: | 31.7 |
| Initial Dry Density, pcf: | 88.0 |
| Initial Bulk Density, pcf: | 115.9 |
| Initial Degree of Saturation: | 95.1 |
| Initial Void Ratio: | 0.89 |

| | |
|---|---|
| Final Diameter, in: | 2.81 |
| Final Height, in: | 5.73 |
| Final Mass, grams: | 1095 |
| Final Moisture Content, %: | 27.4 |
| Final Dry Density, pcf: | 90.3 |
| Final Bulk Density, pcf: | 115.0 |
| Final Degree of Saturation: | 86.7 |
| Final Void Ratio: | 0.84 |

Notes: Moisture content obtained from sample trimmings

Isotropic stress conditions

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 10/18/16 |
| Tested By: | njh |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD4 |
| Depth, ft: | 200.0-203.0 |
| **Test Confining Pressure, psi:** | **60** |
| Visual Description: | Moist, olive gray clay |
| Test Conditions: | Confining Stress of 60 psi over a range of strains from 0.00000997 to 7.17% with a forced sinusoidal vibration. |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015

Apparatus Used: Geocomp Corp. quasi-fixed/free boundry condition automated RCTS Test System

| | | | |
|---|---|---|---|
| Active Mass, g: | 2144.75 | Torque Calibration Factor, N-m/V: | 12.9 |
| Passive Mass, g: | 1053.2 | Accelerometer Calibration Factor, rad/s$^2$/V: | 3293 |
| Active Inertia, kg-m$^2$: | 1.66E-03 | | |
| Passive Inertia, kg-m$^2$: | 0.0012425 | | |

| Elapsed Time | Excitation | Frequency | Axial Strain | Volumetric Strain | * Pore Pressure | Effective Confining Stress | Average Strain Amplitude | Shear Modulus, G | Damping Ratio, D |
|---|---|---|---|---|---|---|---|---|---|
| min | % | Hz | % | % | psi | psi | % | psi | % |
| 1.97 | 0.153 | 225 | 4.13E-02 | 0.041 | --- | 60 | 9.97E-06 | 3.44E+04 | 0.01 |
| 2.38 | 0.963 | 226 | 4.13E-02 | 0.041 | --- | 60 | 4.10E-05 | 3.49E+04 | 0.60 |
| 2.49 | 1.525 | 225 | 4.13E-02 | 0.041 | --- | 60 | 7.23E-05 | 3.44E+04 | 0.80 |
| 2.59 | 2.418 | 225 | 4.13E-02 | 0.041 | --- | 60 | 1.40E-04 | 3.43E+04 | 0.88 |
| 2.69 | 3.833 | 224 | 4.13E-02 | 0.041 | --- | 60 | 5.94E-04 | 3.39E+04 | 0.84 |
| 2.80 | 6.078 | 221 | 4.13E-02 | 0.041 | --- | 60 | 2.75E-03 | 3.30E+04 | 0.99 |
| 2.90 | 9.643 | 217 | 4.13E-02 | 0.041 | --- | 60 | 5.96E-03 | 3.15E+04 | 1.28 |
| 3.11 | 15.359 | 206 | 4.13E-02 | 0.041 | --- | 60 | 1.32E-02 | 2.82E+04 | 2.08 |
| 3.31 | 24.442 | 194 | 4.13E-02 | 0.041 | --- | 60 | 2.45E-02 | 2.47E+04 | 3.11 |
| 3.62 | 39.145 | 175 | 4.13E-02 | 0.041 | --- | 60 | 4.92E-02 | 1.97E+04 | 4.39 |
| 3.83 | 62.122 | 165 | 4.13E-02 | 0.041 | --- | 60 | 6.85E-02 | 1.72E+04 | 5.29 |
| 4.25 | 99.226 | 139 | 4.13E-02 | 0.041 | --- | 60 | 1.38E-01 | 1.21E+04 | 7.17 |

The Shear Wave Velocity can be determined by the following equation:


Vs = sqrt(G*g/bulk density)


where: Vs = shear wave velocity
G = shear modulus
g = acceleration due to gravity, 9.81 m/sec$^2$
final bulk density

* Test is run with drainage valve open, but speed of test is such that excess pore pressure could develop, at higher shear strains within specimen.

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 10/18/16 |
| Tested By: | njh |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD4 |
| Depth, ft: | 200.0-203.0 |
| **Test Confining Pressure, psi:** | **70** |
| Visual Description: | Moist, olive gray silty clay |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015




| | |
|---|---|
| Initial Diameter, in: | 2.84 |
| Initial Height, in: | 5.89 |
| Initial Mass, grams: | 1132 |
| Initial Moisture Content, %: | 31.5 |
| Initial Dry Density, pcf: | 87.9 |
| Initial Bulk Density, pcf: | 115.6 |
| Initial Degree of Saturation: | 94.2 |
| Initial Void Ratio: | 0.89 |

| | |
|---|---|
| Final Diameter, in: | 2.81 |
| Final Height, in: | 5.78 |
| Final Mass, grams: | 1122 |
| Final Moisture Content, %: | 30.1 |
| Final Dry Density, pcf: | 91.5 |
| Final Bulk Density, pcf: | 119.1 |
| Final Degree of Saturation: | 98.3 |
| Final Void Ratio: | 0.82 |

Notes: Moisture content obtained from sample trimmings

Isotropic stress conditions

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 10/18/16 |
| Tested By: | njh |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD4 |
| Depth, ft: | 200.0-203.0 |
| **Test Confining Pressure, psi:** | **70** |
| Visual Description: | Moist, olive gray silty clay |
| Test Conditions: | Confining Stress of 70 psi over a range of strains from 0.0000247 to 6.74% with a forced sinusoidal vibration. |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015

Apparatus Used: Geocomp Corp. quasi-fixed/free boundry condition automated RCTS Test System

| | | | |
|---|---|---|---|
| Active Mass, g: | 2144.75 | Torque Calibration Factor, N-m/V: | 12.9 |
| Passive Mass, g: | 1053.2 | Accelerometer Calibration Factor, rad/s$^2$/V: | 3293 |
| Active Inertia, kg-m$^2$: | 1.66E-03 | | |
| Passive Inertia, kg-m$^2$: | 0.0012425 | | |

| Elapsed Time | Excitation | Frequency | Axial Strain | Volumetric Strain | * Pore Pressure | Effective Confining Stress | Average Strain Amplitude | Shear Modulus, G | Damping Ratio, D |
|---|---|---|---|---|---|---|---|---|---|
| min | % | Hz | % | % | psi | psi | % | psi | % |
| 0.73 | 0.243 | 219 | 4.41E-02 | 0.044 | --- | 70 | 2.47E-05 | 3.29E+04 | 0.55 |
| 1.14 | 1.530 | 218 | 4.41E-02 | 0.044 | --- | 70 | 4.54E-04 | 3.24E+04 | 1.06 |
| 1.24 | 2.424 | 218 | 4.41E-02 | 0.044 | --- | 70 | 7.70E-04 | 3.23E+04 | 1.12 |
| 1.35 | 3.842 | 218 | 4.41E-02 | 0.044 | --- | 70 | 1.38E-03 | 3.21E+04 | 1.15 |
| 1.45 | 6.091 | 217 | 4.41E-02 | 0.044 | --- | 70 | 2.47E-03 | 3.18E+04 | 1.24 |
| 1.56 | 9.657 | 214 | 4.41E-02 | 0.044 | --- | 70 | 4.70E-03 | 3.09E+04 | 1.44 |
| 1.66 | 15.321 | 210 | 4.41E-02 | 0.044 | --- | 70 | 8.40E-03 | 2.96E+04 | 1.82 |
| 1.87 | 24.378 | 201 | 4.41E-02 | 0.044 | --- | 70 | 1.65E-02 | 2.67E+04 | 2.73 |
| 2.07 | 38.803 | 190 | 4.41E-02 | 0.044 | --- | 70 | 2.95E-02 | 2.36E+04 | 3.69 |
| 2.38 | 61.938 | 172 | 4.41E-02 | 0.044 | --- | 70 | 5.67E-02 | 1.91E+04 | 5.16 |
| 2.69 | 98.715 | 155 | 4.41E-02 | 0.044 | --- | 70 | 9.18E-02 | 1.53E+04 | 6.74 |

The Shear Wave Velocity can be determined by the following equation:


Vs = sqrt(G*g/bulk density)


where: Vs = shear wave velocity
G = shear modulus
g = acceleration due to gravity, 9.81 m/sec$^2$
final bulk density

* Test is run with drainage valve open, but speed of test is such that excess pore pressure could develop, at higher shear strains within specimen.

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 10/18/16 |
| Tested By: | njh |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD4 |
| Depth, ft: | 200.0-203.0 |
| **Test Confining Pressure, psi:** | **80** |
| Visual Description: | Moist, olive gray silty clay |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015




| | |
|---|---|
| Initial Diameter, in: | 2.83 |
| Initial Height, in: | 5.99 |
| Initial Mass, grams: | 1130 |
| Initial Moisture Content, %: | 31.7 |
| Initial Dry Density, pcf: | 86.8 |
| Initial Bulk Density, pcf: | 114.3 |
| Initial Degree of Saturation: | 92.1 |
| Initial Void Ratio: | 0.92 |

| | |
|---|---|
| Final Diameter, in: | 2.79 |
| Final Height, in: | 5.85 |
| Final Mass, grams: | 1113 |
| Final Moisture Content, %: | 30.6 |
| Final Dry Density, pcf: | 91.3 |
| Final Bulk Density, pcf: | 119.3 |
| Final Degree of Saturation: | 99.5 |
| Final Void Ratio: | 0.82 |

Notes: Moisture content obtained from sample trimmings

Isotropic stress conditions

| | |
|---|---|
| Client: | F&ME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 10/18/16 |
| Tested By: | njh |
| Checked By: | jdt |
| Boring ID: | SB-1 |
| Sample ID: | UD4 |
| Depth, ft: | 200.0-203.0 |
| **Test Confining Pressure, psi:** | **80** |
| Visual Description: | Moist, olive gray silty clay |
| Test Conditions: | Confining Stress of 80 psi over a range of strains from 0.000113 to 7.05% with a forced sinusoidal vibration. |
| Preparation: | Extruded from tube, cut, trimmed and placed into apparatus at the as-received density and moisture content. |

# Modulus and Damping of Soils by Resonant-Column Method by ASTM D4015

Apparatus Used: Geocomp Corp. quasi-fixed/free boundry condition automated RCTS Test System

| | | | |
|---|---|---|---|
| Active Mass, g: | 2144.75 | Torque Calibration Factor, N-m/V: | 12.9 |
| Passive Mass, g: | 1053.2 | Accelerometer Calibration Factor, rad/s$^2$/V: | 3293 |
| Active Inertia, kg-m$^2$: | 1.66E-03 | | |
| Passive Inertia, kg-m$^2$: | 0.0012425 | | |

| Elapsed Time | Excitation | Frequency | Axial Strain | Volumetric Strain | * Pore Pressure | Effective Confining Stress | Average Strain Amplitude | Shear Modulus, G | Damping Ratio, D |
|---|---|---|---|---|---|---|---|---|---|
| min | % | Hz | % | % | psi | psi | % | psi | % |
| 0.73 | 0.243 | 214 | 5.58E-02 | 0.056 | --- | 80 | 1.13E-04 | 3.20E+04 | 0.56 |
| 0.93 | 0.611 | 215 | 5.58E-02 | 0.056 | --- | 80 | 1.93E-04 | 3.23E+04 | 0.80 |
| 1.04 | 0.966 | 215 | 5.58E-02 | 0.056 | --- | 80 | 3.40E-04 | 3.22E+04 | 0.93 |
| 1.14 | 1.532 | 215 | 5.58E-02 | 0.056 | --- | 80 | 6.06E-04 | 3.21E+04 | 1.00 |
| 1.24 | 2.428 | 215 | 5.58E-02 | 0.056 | --- | 80 | 9.19E-04 | 3.21E+04 | 1.02 |
| 1.35 | 3.847 | 214 | 5.58E-02 | 0.056 | --- | 80 | 1.48E-03 | 3.19E+04 | 1.04 |
| 1.45 | 6.100 | 213 | 5.58E-02 | 0.056 | --- | 80 | 2.48E-03 | 3.16E+04 | 1.10 |
| 1.55 | 9.672 | 212 | 5.58E-02 | 0.056 | --- | 80 | 4.09E-03 | 3.10E+04 | 1.28 |
| 1.66 | 15.338 | 209 | 5.58E-02 | 0.056 | --- | 80 | 6.64E-03 | 3.01E+04 | 1.54 |
| 1.76 | 24.337 | 205 | 5.58E-02 | 0.056 | --- | 80 | 1.10E-02 | 2.87E+04 | 1.95 |
| 1.97 | 38.749 | 194 | 5.58E-02 | 0.056 | --- | 80 | 2.17E-02 | 2.55E+04 | 3.00 |
| 2.28 | 61.840 | 177 | 5.58E-02 | 0.056 | --- | 80 | 4.64E-02 | 2.09E+04 | 4.29 |
| 2.69 | 98.957 | 146 | 5.58E-02 | 0.056 | --- | 80 | 1.23E-01 | 1.38E+04 | 7.05 |

The Shear Wave Velocity can be determined by the following equation:


Vs = sqrt(G*g/bulk density)

where: Vs = shear wave velocity
G = shear modulus
g = acceleration due to gravity, 9.81 m/sec$^2$
final bulk density

* Test is run with drainage valve open, but speed of test is such that excess pore pressure could develop, at higher shear strains within specimen.

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-4 | Test Date: | 11/04/16 | Checked By: | mcm |
| Depth : | 200.0-203.0 ft | Test Id: | 397425 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy silt | | | | |
| Sample Comment: | --- | | | | |

# Particle Size Analysis - ASTM D422




| %Cobble | %Gravel | %Sand | %Silt & Clay Size |
|---|---|---|---|
| – | 0.1 | 47.8 | 52.1 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| 0.375 in | 9.50 | 100 | | |
| #4 | 4.75 | 100 | | |
| #10 | 2.00 | 100 | | |
| #20 | 0.85 | 100 | | |
| #40 | 0.42 | 99 | | |
| #60 | 0.25 | 98 | | |
| #100 | 0.15 | 83 | | |
| #200 | 0.075 | 52 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ = 0.1611 mm | $D_{30}$ = N/A |
| $D_{60}$ = 0.0896 mm | $D_{15}$ = N/A |
| $D_{50}$ = N/A | $D_{10}$ = N/A |
| $C_u$ = N/A | $C_c$ = N/A |

**Classification**

ASTM Sandy Silt (ML)

AASHTO Clayey Soils (A-7-6 (6))


**Sample / Test Description**

Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---


| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | SB-1 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-4 | Test Date: | 11/04/16 | Checked By: | mcm |
| Depth : | 200.0-203.0 ft | Test Id: | 397423 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy silt | | | | |
| Sample Comment: | --- | | | | |


# Atterberg Limits - ASTM D4318





| Symbol | Sample ID | Boring | Depth | Natural Moisture Content, % | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-4 | SB-1 | 00.0-203. ft | 32 | 43 | 27 | 16 | 0.3 | Sandy Silt (ML) |


Sample Prepared using the WET method
1% Retained on #40 Sieve
Dry Strength: HIGH
Dilatancy: SLOW
Toughness: LOW








**RESONANT COLUMN TEST**
Three Stages of Isotropic Consolidation - OCR = 1
Sample: UD-6a  Depth: 257.85 ft
Boring SB-1




**RESONANT COLUMN TEST**
Three Stages of Isotropic Consolidation - OCR = 1
Sample: UD-9a Depth: 380.55 ft
Boring SB-1





| GRAVEL | | SAND | | | SILT or CLAY |
|---|---|---|---|---|---|
| Coarse | Fine | Coarse | Medium | Fine | |

| SYMBOL | BORING | DEPTH, FT | $C_c$ | $C_u$ | $D_{50}$ | $D_{90}$ | CLASSIFICATION |
|---|---|---|---|---|---|---|---|
| ● | SB-1_UD-6a | 257.85 | | | | 0.54 | Sandy Clay, greenish gray |
| ⊠ | SB-1_UD-9a | 380.55 | | | | 0.09 | Clay, olive gray and greenish gray, with san pockets and carbonate nodules |
| ✳ | | | | | | | |
| ⊗ | | | | | | | |

**GRAIN SIZE CURVE**

PLATE 1




**PLASTICITY CHART**
**Project No. 04.11160019**

| Sample | LL | PL | PI |
|---|---|---|---|
| SB-1_UD-6a | 76 | 21 | 55 |
| SB-1_UD-9a | 133 | 29 | 104 |

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | jbr |
| Sample ID: | --- | Test Date: | 08/30/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 387124 | | |

# Moisture Content of Soil and Rock - ASTM D2216


| Boring ID | Sample ID | Depth | Description | Moisture Content,% |
|---|---|---|---|---|
| AP-1 | UD-1 | 16.0-18.0 ft | Moist, olive sandy clay | 63.0 |

Notes: Temperature of Drying : 110º Celsius

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-1 | Sample Type: | tube | Tested By: | jbr |
| Sample ID: | UD-1 | Test Date: | 08/26/16 | Checked By: | mcm |
| Depth : | 16.0-18.0 ft | Test Id: | 387101 | | |

Test Comment: ---
Visual Description: Moist, olive sandy clay
Sample Comment: ---

# Particle Size Analysis - ASTM D422




| % Cobble | % Gravel | % Sand | % Silt & Clay Size |
|---|---|---|---|
| — | 0.0 | 39.0 | 61.0 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| #4 | 4.75 | 100 | | |
| #10 | 2.00 | 100 | | |
| #20 | 0.85 | 99 | | |
| #40 | 0.42 | 98 | | |
| #60 | 0.25 | 97 | | |
| #100 | 0.15 | 92 | | |
| #200 | 0.075 | 61 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ = 0.1278 mm | $D_{30}$ = N/A |
| $D_{60}$ = N/A | $D_{15}$ = N/A |
| $D_{50}$ = N/A | $D_{10}$ = N/A |
| $C_u$ = N/A | $C_c$ = N/A |

**Classification**

ASTM Sandy Fat clay (CH)

AASHTO Clayey Soils (A-7-6 (24))


**Sample/Test Description**

Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-1 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-1 | Test Date: | 08/31/16 | Checked By: | mcm |
| Depth : | 16.0-18.0 ft | Test Id: | 387109 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy clay | | | | |
| Sample Comment: | --- | | | | |

# Atterberg Limits - ASTM D4318





| Symbol | Sample ID | Boring | Depth | Natural Moisture Content,% | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-1 | AP-1 | 16.0-18.0 ft | 63 | 65 | 21 | 44 | 1 | Sandy Fat clay (CH) |


Sample Prepared using the WET method
2% Retained on #40 Sieve
Dry Strength: VERY HIGH
Dilatancy: NONE
Toughness: MEDIUM

GeoTesting EXPRESS

| | |
|---|---|
| Client: F&ME Consultants | |
| Project Name: US 21 Replacement Bridge | |
| Project Location: --- | |
| Project Number: GTX-305005 | |
| Tested By: md | Checked By: mcm |
| Boring ID: AP-1 | |
| Preparation: intact | |
| Description: Moist, gray clay with sand | |
| Classification: Fat clay | |
| Group Symbol: CH | |
| Liquid Limit: --- | Plastic Limit: --- |
| Plasticity Index: --- | Estimated Specific Gravity: 2.7 |

## CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767




| | | | | | |
|---|---|---|---|---|---|
| Symbol | | ■ | ● | | |
| Sample ID | | ST-1 | ST-1 | | |
| Depth, ft | | 16.0-18.0 ft | 16.0-18.0 ft | | |
| Test Number | | CU-5-1 | CU-5-2 | | |
| Initial | Height, in | 4.680 | 4.500 | | |
| | Diameter, in | 2.020 | 2.030 | | |
| | Moisture Content (from Cuttings), % | 50.2 | 60.1 | | |
| | Dry Density, pcf | 66.5 | 63.3 | | |
| | Saturation (Wet Method), % | 88.4 | 97.5 | | |
| | Void Ratio | 1.53 | 1.66 | | |
| Before Shear | Moisture Content, % | 51.2 | 59.6 | | |
| | Dry Density, pcf | 70.7 | 64.6 | | |
| | Cross-sectional Area (Method A), in² | 3.034 | 3.180 | | |
| | Saturation, % | 100.0 | 100.0 | | |
| | Void Ratio | 1.38 | 1.61 | | |
| | Back Pressure, psi | 51.00 | 160.8 | | |
| Vertical Effective Consolidation Stress, psi | | 4.947 | 9.959 | | |
| Horizontal Effective Consolidation Stress, psi | | 4.994 | 9.982 | | |
| Vertical Strain after Consolidation, % | | 0.5866 | 0.3451 | | |
| Volumetric Strain after Consolidation, % | | 5.758 | 2.070 | | |
| Time to 50% Consolidation, min | | 262.4 | 18.06 | | |
| Shear Strength, psi | | 2.440 | 4.369 | | |
| Strain at Failure, % | | 7.12 | 2.18 | | |
| Strain Rate, %/min | | 0.01600 | 0.01600 | | |
| Deviator Stress at Failure, psi | | 4.880 | 8.738 | | |
| Effective Minor Principal Stress at Failure, psi | | 1.007 | 3.054 | | |
| Effective Major Principal Stress at Failure, psi | | 5.887 | 11.79 | | |
| B-Value | | 0.96 | 0.95 | | |

Notes:
- Before Shear Saturation set to 100% for phase calculation.
- Moisture Content determined by ASTM D2216.
- Deviator Stress includes membrane correction.
- Values for c and φ determined from best-fit straight line for the specific test conditions. Actual strength parameters may vary and should be determined by an engineer for site conditions.








Remarks:

System B

# CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767





| | Sample No. | Test No. | Depth | Tested By | Test Date | Checked By | Check Date | Test File |
|---|---|---|---|---|---|---|---|---|
| ■ | ST-1 | CU-5-1 | 16.0-18.0 ft | md | 8/24/16 | mcm | 9/7/16 | 305005-CU-5-1m.dat |
| ● | ST-1 | CU-5-2 | 16.0-18.0 ft | md | 8/24/16 | mcm | 9/7/16 | 305005-CU-5-2m.dat |
| | | | | | | | | |
| | | | | | | | | |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US 21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Sample Type: intact | |
| Description: Moist, gray clay with sand | | |
| Remarks: System B | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Summary Report






| | | | | Before Test | After Test |
|---|---|---|---|---|---|
| Current Vertical Effective Stress: --- | | | | Water Content, % | 85.59 | 49.46 |
| Preconsolidation Stress: --- | | | | Dry Unit Weight, pcf | 50.811 | 72.587 |
| Compression Ratio: --- | | | | Saturation, % | 99.16 | 100.00 |
| Diameter: 2.5 in | | Height: 1 in | | Void Ratio | 2.36 | 1.35 |
| LL: 65 | PL: 21 | PI: 44 | GS: 2.74 | | | |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System V, Swell Pressure = 0.0704 tsf | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 1 of 11
Constant Volume Step
Stress: 0.0704 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 2 of 11
Constant Load Step
Stress: 0.125 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 3 of 11
Constant Load Step
Stress: 0.25 tsf









| | | |
|---|---|---|
| Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 4 of 11
Constant Load Step
Stress: 0.5 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 5 of 11
Constant Load Step
Stress: 1 tsf









| | | |
|---|---|---|
| Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 6 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 7 of 11
Constant Load Step
Stress: 4 tsf









| | | |
|---|---|---|
| Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 8 of 11
Constant Load Step
Stress: 8 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 9 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 10 of 11
Constant Load Step
Stress: 0.5 tsf









| | | |
|---|---|---|
| Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 11 of 11
Constant Load Step
Stress: 0.125 tsf




| | | |
|---|---|---|
| Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

| | | |
|---|---|---|
| Specimen Diameter: 2.50 in | Estimated Specific Gravity: 2.74 | Liquid Limit: 65 |
| Initial Height: 1.00 in | Initial Void Ratio: 2.36 | Plastic Limit: 21 |
| Final Height: 0.70 in | Final Void Ratio: 1.35 | Plasticity Index: 44 |

| | Before Test Trimmings | Before Test Specimen | After Test Specimen | After Test Trimmings |
|---|---|---|---|---|
| Container ID | 15994 | RING | | B-295 |
| Mass Container, gm | 8.45 | 110.11 | 110.11 | 8.28 |
| Mass Container + Wet Soil, gm | 133.6 | 231.62 | 207.96 | 105.89 |
| Mass Container + Dry Soil, gm | 78.91 | 175.58 | 175.58 | 73.59 |
| Mass Dry Soil, gm | 70.46 | 65.471 | 65.471 | 65.31 |
| Water Content, % | 77.62 | 85.59 | 49.46 | 49.46 |
| Void Ratio | --- | 2.36 | 1.35 | --- |
| Degree of Saturation, % | --- | 99.16 | 100.00 | --- |
| Dry Unit Weight, pcf | --- | 50.811 | 72.587 | --- |

Note: Specific Gravity and Void Ratios are calculated assuming the degree of saturation equals 100% at the end of the test. Therefore, values may not represent actual values for the specimen.

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System V, Swell Pressure = 0.0704 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Log of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Log T50 min | Cv ft²/s | Mv 1/tsf | k ft/day | Ca % |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.0704 | 0.003665 | 2.35 | 0.367 | 0.000 | 0.00e+00 | 5.21e-02 | 0.00e+00 | 0.00e+00 |
| 2 | 0.125 | 0.008537 | 2.33 | 0.854 | 1.818 | 3.10e-06 | 8.92e-02 | 7.45e-04 | 0.00e+00 |
| 3 | 0.250 | 0.02273 | 2.29 | 2.27 | 0.000 | 0.00e+00 | 1.14e-01 | 0.00e+00 | 0.00e+00 |
| 4 | 0.500 | 0.05048 | 2.19 | 5.05 | 4.388 | 1.21e-06 | 1.11e-01 | 3.61e-04 | 0.00e+00 |
| 5 | 1.00 | 0.1173 | 1.97 | 11.7 | 0.000 | 0.00e+00 | 1.34e-01 | 0.00e+00 | 0.00e+00 |
| 6 | 2.00 | 0.2359 | 1.57 | 23.6 | 17.652 | 2.19e-07 | 1.19e-01 | 7.00e-05 | 0.00e+00 |
| 7 | 4.00 | 0.3472 | 1.19 | 34.7 | 0.000 | 0.00e+00 | 5.57e-02 | 0.00e+00 | 0.00e+00 |
| 8 | 8.00 | 0.4299 | 0.916 | 43.0 | 7.643 | 2.79e-07 | 2.07e-02 | 1.56e-05 | 0.00e+00 |
| 9 | 2.00 | 0.4089 | 0.987 | 40.9 | 0.000 | 0.00e+00 | 3.50e-03 | 0.00e+00 | 0.00e+00 |
| 10 | 0.500 | 0.3784 | 1.09 | 37.8 | 0.000 | 0.00e+00 | 2.04e-02 | 0.00e+00 | 0.00e+00 |
| 11 | 0.125 | 0.3475 | 1.19 | 34.7 | 0.000 | 0.00e+00 | 8.24e-02 | 0.00e+00 | 0.00e+00 |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System V, Swell Pressure = 0.0704 tsf | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Square Root of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Sq.Rt. T90 min | Cv ft²/s | Mv 1/tsf | k ft/day |
|---|---|---|---|---|---|---|---|---|
| 1 | 0.0704 | 0.003665 | 2.35 | 0.367 | 5.902 | 4.14e-06 | 5.21e-02 | 5.82e-04 |
| 2 | 0.125 | 0.008537 | 2.33 | 0.854 | 13.764 | 1.76e-06 | 8.92e-02 | 4.24e-04 |
| 3 | 0.250 | 0.02273 | 2.29 | 2.27 | 21.383 | 1.11e-06 | 1.14e-01 | 3.41e-04 |
| 4 | 0.500 | 0.05048 | 2.19 | 5.05 | 18.440 | 1.24e-06 | 1.11e-01 | 3.70e-04 |
| 5 | 1.00 | 0.1173 | 1.97 | 11.7 | 55.324 | 3.72e-07 | 1.34e-01 | 1.34e-04 |
| 6 | 2.00 | 0.2359 | 1.57 | 23.6 | 78.285 | 2.13e-07 | 1.19e-01 | 6.79e-05 |
| 7 | 4.00 | 0.3472 | 1.19 | 34.7 | 50.153 | 2.46e-07 | 5.57e-02 | 3.69e-05 |
| 8 | 8.00 | 0.4299 | 0.916 | 43.0 | 32.140 | 2.85e-07 | 2.07e-02 | 1.59e-05 |
| 9 | 2.00 | 0.4089 | 0.987 | 40.9 | 20.221 | 4.09e-07 | 3.50e-03 | 3.86e-06 |
| 10 | 0.500 | 0.3784 | 1.09 | 37.8 | 52.762 | 1.71e-07 | 2.04e-02 | 9.40e-06 |
| 11 | 0.125 | 0.3475 | 1.19 | 34.7 | 233.771 | 4.26e-08 | 8.24e-02 | 9.47e-06 |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: SU-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/24/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-5 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System V, Swell Pressure = 0.0704 tsf | | |
| | Displacement at End of Increment | | |

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | jbr |
| Sample ID: | --- | Test Date: | 08/30/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 387124 | | |


# Moisture Content of Soil and Rock - ASTM D2216

| Boring ID | Sample ID | Depth | Description | Moisture Content,% |
|---|---|---|---|---|
| AP-1 | UD-2 | 18.0-20.0 ft | Moist, olive clay with sand | 86.3 |

Notes: Temperature of Drying : 110º Celsius

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-1 | Sample Type: | tube | Tested By: | jbr |
| Sample ID: | UD-2 | Test Date: | 08/24/16 | Checked By: | mcm |
| Depth : | 18.0-20.0 ft | Test Id: | 387102 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive clay with sand | | | | |
| Sample Comment: | --- | | | | |

# Particle Size Analysis - ASTM D422




| % Cobble | % Gravel | % Sand | % Silt & Clay Size |
|---|---|---|---|
| — | 0.2 | 26.5 | 73.3 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| 0.375 in | 9.50 | 100 | | |
| #4 | 4.75 | 100 | | |
| #10 | 2.00 | 98 | | |
| #20 | 0.85 | 96 | | |
| #40 | 0.42 | 94 | | |
| #60 | 0.25 | 94 | | |
| #100 | 0.15 | 84 | | |
| #200 | 0.075 | 73 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ =0.1582 mm | $D_{30}$ =N/A |
| $D_{60}$ =N/A | $D_{15}$ =N/A |
| $D_{50}$ =N/A | $D_{10}$ =N/A |
| $C_u$ =N/A | $C_c$ =N/A |

**Classification**

ASTM Fat clay with sand (CH)

AASHTO Clayey Soils (A-7-5 (60))


**Sample/Test Description**

Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-1 | Sample Type: | tube | Tested By: | cam |
| Sample ID: | UD-2 | Test Date: | 08/26/16 | Checked By: | mcm |
| Depth : | 18.0-20.0 ft | Test Id: | 387110 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive clay with sand | | | | |
| Sample Comment: | --- | | | | |

# Atterberg Limits - ASTM D4318





| Symbol | Sample ID | Boring | Depth | Natural Moisture Content,% | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-2 | AP-1 | 18.0-20.0 ft | 86 | 111 | 34 | 77 | 0.7 | Fat clay with sand (CH) |


Sample Prepared using the WET method
6% Retained on #40 Sieve
Dry Strength: VERY HIGH
Dilatancy: SLOW
Toughness: LOW

GeoTesting EXPRESS

| | |
|---|---|
| Client: F&ME Consultants | |
| Project Name: US-21 Replacement Bridge | |
| Project Location: --- | |
| Project Number: GTX-305005 | |
| Tested By: md | Checked By: mcm |
| Boring ID: AP-1 | |
| Preparation: Intact | |
| Description: Moist, olive clay with sand | |
| Classification: Fat clay with sand | |
| Group Symbol: CH | |
| Liquid Limit: 111 | Plastic Limit: 34 |
| Plasticity Index: 77 | Estimated Specific Gravity: 2.7 |

## CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767




| | | ■ | ● | ▲ | |
|---|---|---|---|---|---|
| Symbol | | | | | |
| Sample ID | | ST-2 | ST-2 | ST-2 | |
| Depth, ft | | 18.0-20.0 ft | 18.0-20.0 ft | 18.0-20.0 ft | |
| Test Number | | CU-3-1 | CU-3-2 | CU-3-3 | |
| Initial | Height, in | 4.550 | 4.540 | 4.490 | |
| | Diameter, in | 2.030 | 2.030 | 2.030 | |
| | Moisture Content (from Cuttings), % | 71.3 | 84.8 | 84.8 | |
| | Dry Density, pcf | 55.7 | 46.4 | 49.5 | |
| | Saturation (Wet Method), % | 95.0 | 87.0 | 95.0 | |
| | Void Ratio | 2.02 | 2.63 | 2.41 | |
| Before Shear | Moisture Content, % | 71.0 | 69.6 | 66.8 | |
| | Dry Density, pcf | 57.8 | 58.6 | 60.1 | |
| | Cross-sectional Area (Method A), in² | 3.123 | 2.614 | 2.723 | |
| | Saturation, % | 100.0 | 100.0 | 100.0 | |
| | Void Ratio | 1.92 | 1.88 | 1.80 | |
| | Back Pressure, psi | 127.0 | 29.02 | 28.99 | |
| Vertical Effective Consolidation Stress, psi | | 5.008 | 9.831 | 14.86 | |
| Horizontal Effective Consolidation Stress, psi | | 5.009 | 9.968 | 15.01 | |
| Vertical Strain after Consolidation, % | | 0.03924 | 1.773 | 2.088 | |
| Volumetric Strain after Consolidation, % | | 3.576 | 20.60 | 17.44 | |
| Time to 50% Consolidation, min | | 148.8 | 458.0 | 342.3 | |
| Shear Strength, psi | | 3.011 | 4.650 | 3.939 | |
| Strain at Failure, % | | 6.18 | 10.9 | 11.0 | |
| Strain Rate, %/min | | 0.01600 | 0.01600 | 0.01600 | |
| Deviator Stress at Failure, psi | | 6.022 | 9.300 | 7.877 | |
| Effective Minor Principal Stress at Failure, psi | | 1.355 | 1.207 | 1.622 | |
| Effective Major Principal Stress at Failure, psi | | 7.376 | 10.51 | 9.499 | |
| B-Value | | 0.95 | 0.99 | 0.95 | |

Notes:
- Before Shear Saturation set to 100% for phase calculation.
- Moisture Content determined by ASTM D2216.
- Atterberg Limits determined by ASTM D4318.
- Deviator Stress includes membrane correction.
- Values for c and φ determined from best-fit straight line for the specific test conditions. Actual strength parameters may vary and should be determined by an engineer for site conditions.








Remarks:

System T. Note CU-2-2 test specimen not used in determining cohesion or friction values.

# CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767





| | Sample No. | Test No. | Depth | Tested By | Test Date | Checked By | Check Date | Test File |
|---|---|---|---|---|---|---|---|---|
| ■ | ST-2 | CU-3-1 | 18.0-20.0 ft | md | 8/22/16 | mcm | 8/29/16 | 305005-CU-3-1m.dat |
| ● | ST-2 | CU-3-2 | 18.0-20.0 ft | md | 8/22/16 | mcm | 8/29/16 | 305005-CU-3-2m.dat |
| ▲ | ST-2 | CU-3-3 | 18.0-20.0 ft | md | 8/22/16 | mcm | 8/29/16 | 305005-CU-3-3m.dat |
| | | | | | | | | |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Sample Type: Intact | |
| Description: Moist, olive clay with sand | | |
| Remarks: System T. Note CU-2-2 test specimen not used in determining cohesion or friction values. | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Summary Report






| | | | | | Before Test | After Test |
|---|---|---|---|---|---|---|
| Current Vertical Effective Stress: --- | | | | Water Content, % | 89.14 | 52.62 |
| Preconsolidation Stress: --- | | | | Dry Unit Weight, pcf | 48.913 | 69.876 |
| Compression Ratio: --- | | | | Saturation, % | 98.06 | 100.00 |
| Diameter: 2.5 in | | Height: 1 in | | Void Ratio | 2.48 | 1.43 |
| LL: 111 | PL: 34 | PI: 77 | GS: 2.72 | | | |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System R, Swell Pressure = 0.0919 tsf | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 1 of 11
Constant Volume Step
Stress: 0.0919 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 2 of 11
Constant Load Step
Stress: 0.125 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 3 of 11
Constant Load Step
Stress: 0.25 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 4 of 11
Constant Load Step
Stress: 0.5 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 5 of 11
Constant Load Step
Stress: 1 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 6 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 7 of 11
Constant Load Step
Stress: 4 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 8 of 11
Constant Load Step
Stress: 8 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 9 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 10 of 11
Constant Load Step
Stress: 0.5 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 11 of 11
Constant Load Step
Stress: 0.125 tsf




| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

| | | |
|---|---|---|
| Specimen Diameter: 2.50 in | Estimated Specific Gravity: 2.72 | Liquid Limit: 111 |
| Initial Height: 1.00 in | Initial Void Ratio: 2.48 | Plastic Limit: 34 |
| Final Height: 0.70 in | Final Void Ratio: 1.43 | Plasticity Index: 77 |

| | Before Test Trimmings | Before Test Specimen | After Test Specimen | After Test Trimmings |
|---|---|---|---|---|
| Container ID | 15389 | RING | | C-1647 |
| Mass Container, gm | 8.21 | 109.02 | 109.02 | 8.42 |
| Mass Container + Wet Soil, gm | 241.13 | 228.23 | 205.21 | 99.61 |
| Mass Container + Dry Soil, gm | 141.82 | 172.05 | 172.05 | 68.17 |
| Mass Dry Soil, gm | 133.61 | 63.026 | 63.026 | 59.75 |
| Water Content, % | 74.33 | 89.14 | 52.62 | 52.62 |
| Void Ratio | --- | 2.48 | 1.43 | --- |
| Degree of Saturation, % | --- | 98.06 | 100.00 | --- |
| Dry Unit Weight, pcf | --- | 48.913 | 69.876 | --- |

Note: Specific Gravity and Void Ratios are calculated assuming the degree of saturation equals 100% at the end of the test. Therefore, values may not represent actual values for the specimen.

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System R, Swell Pressure = 0.0919 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Log of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Log T50 min | Cv ft²/s | Mv 1/tsf | k ft/day | Ca % |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.0919 | 0.0001397 | 2.48 | 0.0140 | 0.000 | 0.00e+00 | 1.52e-03 | 0.00e+00 | 0.00e+00 |
| 2 | 0.125 | 0.002189 | 2.47 | 0.219 | 0.000 | 0.00e+00 | 6.20e-02 | 0.00e+00 | 0.00e+00 |
| 3 | 0.250 | 0.02128 | 2.40 | 2.13 | 4.360 | 1.28e-06 | 1.53e-01 | 5.26e-04 | 0.00e+00 |
| 4 | 0.500 | 0.04825 | 2.31 | 4.82 | 4.805 | 1.11e-06 | 1.08e-01 | 3.22e-04 | 0.00e+00 |
| 5 | 1.00 | 0.1264 | 2.04 | 12.6 | 0.000 | 0.00e+00 | 1.56e-01 | 0.00e+00 | 0.00e+00 |
| 6 | 2.00 | 0.2444 | 1.63 | 24.4 | 18.156 | 2.08e-07 | 1.18e-01 | 6.63e-05 | 0.00e+00 |
| 7 | 4.00 | 0.3324 | 1.32 | 33.2 | 14.875 | 1.94e-07 | 4.40e-02 | 2.30e-05 | 0.00e+00 |
| 8 | 8.00 | 0.4049 | 1.07 | 40.5 | 11.940 | 1.90e-07 | 1.81e-02 | 9.30e-06 | 0.00e+00 |
| 9 | 2.00 | 0.3820 | 1.15 | 38.2 | 0.000 | 0.00e+00 | 3.82e-03 | 0.00e+00 | 0.00e+00 |
| 10 | 0.500 | 0.3514 | 1.25 | 35.1 | 19.511 | 1.17e-07 | 2.04e-02 | 6.44e-06 | 0.00e+00 |
| 11 | 0.125 | 0.3185 | 1.37 | 31.9 | 0.000 | 0.00e+00 | 8.77e-02 | 0.00e+00 | 0.00e+00 |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System R, Swell Pressure = 0.0919 tsf | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Square Root of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Sq.Rt. T90 min | Cv ft²/s | Mv 1/tsf | k ft/day |
|---|---|---|---|---|---|---|---|---|
| 1 | 0.0919 | 0.0001397 | 2.48 | 0.0140 | 0.000 | 0.00e+00 | 1.52e-03 | 0.00e+00 |
| 2 | 0.125 | 0.002189 | 2.47 | 0.219 | 22.890 | 1.07e-06 | 6.20e-02 | 1.79e-04 |
| 3 | 0.250 | 0.02128 | 2.40 | 2.13 | 15.976 | 1.50e-06 | 1.53e-01 | 6.18e-04 |
| 4 | 0.500 | 0.04825 | 2.31 | 4.82 | 21.822 | 1.05e-06 | 1.08e-01 | 3.05e-04 |
| 5 | 1.00 | 0.1264 | 2.04 | 12.6 | 74.186 | 2.75e-07 | 1.56e-01 | 1.16e-04 |
| 6 | 2.00 | 0.2444 | 1.63 | 24.4 | 85.426 | 1.91e-07 | 1.18e-01 | 6.06e-05 |
| 7 | 4.00 | 0.3324 | 1.32 | 33.2 | 70.490 | 1.76e-07 | 4.40e-02 | 2.09e-05 |
| 8 | 8.00 | 0.4049 | 1.07 | 40.5 | 49.359 | 1.98e-07 | 1.81e-02 | 9.69e-06 |
| 9 | 2.00 | 0.3820 | 1.15 | 38.2 | 19.291 | 4.68e-07 | 3.82e-03 | 4.82e-06 |
| 10 | 0.500 | 0.3514 | 1.25 | 35.1 | 86.546 | 1.14e-07 | 2.04e-02 | 6.25e-06 |
| 11 | 0.125 | 0.3185 | 1.37 | 31.9 | 201.559 | 5.38e-08 | 8.77e-02 | 1.27e-05 |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-1 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-3 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System R, Swell Pressure = 0.0919 tsf | | |
| | Displacement at End of Increment | | |

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | jbr |
| Sample ID: | --- | Test Date: | 08/30/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 387124 | | |


# Moisture Content of Soil and Rock - ASTM D2216

| Boring ID | Sample ID | Depth | Description | Moisture Content,% |
|---|---|---|---|---|
| AP-2 | UD-1 | 16.0-18.0 ft | Moist, olive clayey sand | 56.0 |

Notes: Temperature of Drying : 110º Celsius

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-2 | Sample Type: | tube | Tested By: | jbr |
| Sample ID: | UD-1 | Test Date: | 08/23/16 | Checked By: | mcm |
| Depth : | 16.0-18.0 ft | Test Id: | 387103 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive clayey sand | | | | |
| Sample Comment: | --- | | | | |

# Particle Size Analysis - ASTM D422




| % Cobble | % Gravel | % Sand | % Silt & Clay Size |
|---|---|---|---|
| — | 2.1 | 48.0 | 49.9 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| 0.75 in | 19.00 | 100 | | |
| 0.5 in | 12.50 | 98 | | |
| 0.375 in | 9.50 | 98 | | |
| #4 | 4.75 | 98 | | |
| #10 | 2.00 | 98 | | |
| #20 | 0.85 | 97 | | |
| #40 | 0.42 | 97 | | |
| #60 | 0.25 | 96 | | |
| #100 | 0.15 | 83 | | |
| #200 | 0.075 | 50 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ =0.1600 mm | $D_{30}$ =N/A |
| $D_{60}$ =0.0925 mm | $D_{15}$ =N/A |
| $D_{50}$ =0.0752 mm | $D_{10}$ =N/A |
| $C_u$ =N/A | $C_c$ =N/A |

**Classification**

ASTM Clayey sand (SC)

AASHTO Clayey Soils (A-7-6 (17))

**Sample/Test Description**


Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

printed 9/8/2016 3:35:57 PM

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-2 | Sample Type: | tube | Tested By: | cam |
| Sample ID: | UD-1 | Test Date: | 08/22/16 | Checked By: | mcm |
| Depth : | 16.0-18.0 ft | Test Id: | 387111 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive clayey sand | | | | |
| Sample Comment: | --- | | | | |

# Atterberg Limits - ASTM D4318





| Symbol | Sample ID | Boring | Depth | Natural Moisture Content,% | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-1 | AP-2 | 16.0-18.0 ft | 56 | 66 | 22 | 44 | 0.8 | Clayey sand (SC) |


Sample Prepared using the WET method
3% Retained on #40 Sieve
Dry Strength: VERY HIGH
Dilatancy: SLOW
Toughness: LOW

GeoTesting EXPRESS

| | |
|---|---|
| Client: F&ME Consultants | |
| Project Name: US 21 Replacement Bridge | |
| Project Location: --- | |
| Project Number: GTX-305005 | |
| Tested By: md | Checked By: mcm |
| Boring ID: AP-2 | |
| Preparation: intact | |
| Description: Moist, olive clayey sand | |
| Classification: Clayey sand | |
| Group Symbol: SC | |
| Liquid Limit: 66 | Plastic Limit: 22 |
| Plasticity Index: 44 | Estimated Specific Gravity: 2.7 |

## CONSOLIDATED DRAINED TRIAXIAL TEST by ASTM D4767




| | | | | | |
|---|---|---|---|---|---|
| Symbol | | ■ | ● | ▲ | |
| Sample ID | | ST-1 | ST-1 | ST-1 | |
| Depth, ft | | 16.0-18.0 ft | 16.0-18.0 ft | 16.0-18.0 ft | |
| Test Number | | CU-2-1 | CU-2-2 | CU-2-3 | |
| Initial | Height, in | 4.650 | 4.720 | 4.390 | |
| | Diameter, in | 2.050 | 2.030 | 2.030 | |
| | Moisture Content (from Cuttings), % | 72.9 | 49.2 | 52.1 | |
| | Dry Density, pcf | 56.4 | 69.3 | 66.4 | |
| | Saturation (Wet Method), % | 99.0 | 92.7 | 91.5 | |
| | Void Ratio | 1.99 | 1.43 | 1.54 | |
| Before Shear | Moisture Content, % | 70.4 | 47.1 | 47.2 | |
| | Dry Density, pcf | 58.1 | 74.2 | 74.1 | |
| | Cross-sectional Area (Method A), in² | 3.205 | 3.042 | 2.998 | |
| | Saturation, % | 100.0 | 100.0 | 100.0 | |
| | Void Ratio | 1.90 | 1.27 | 1.28 | |
| | Back Pressure, psi | 139.0 | 150.8 | 150.9 | |
| Vertical Effective Consolidation Stress, psi | | 5.002 | 9.937 | 14.76 | |
| Horizontal Effective Consolidation Stress, psi | | 5.002 | 9.987 | 14.99 | |
| Vertical Strain after Consolidation, % | | 0.01752 | 0.6124 | 2.957 | |
| Volumetric Strain after Consolidation, % | | 3.012 | 6.546 | 9.651 | |
| Time to 50% Consolidation, min | | 92.16 | 45.56 | 161.3 | |
| Shear Strength, psi | | 2.690 | 3.838 | 6.597 | |
| Strain at Failure, % | | 6.63 | 9.40 | 5.69 | |
| Strain Rate, %/min | | 0.01600 | 0.01600 | 0.01600 | |
| Deviator Stress at Failure, psi | | 5.381 | 7.677 | 13.19 | |
| Effective Minor Principal Stress at Failure, psi | | 1.747 | 2.795 | 3.775 | |
| Effective Major Principal Stress at Failure, psi | | 7.128 | 10.47 | 16.97 | |
| B-Value | | 0.95 | 0.95 | 0.95 | |


Notes:
- Before Shear Saturation set to 100% for phase calculation.
- Moisture Content determined by ASTM D2216.
- Atterberg Limits determined by ASTM D4318.
- Deviator Stress includes membrane correction.
- Values for c and φ determined from best-fit straight line for the specific test conditions. Actual strength parameters may vary and should be determined by an engineer for site conditions.





Remarks:

System B. Note CU-2-3 test specimen was not used in determining cohesion or friction values.

# CONSOLIDATED DRAINED TRIAXIAL TEST by ASTM D4767





| | Sample No. | Test No. | Depth | Tested By | Test Date | Checked By | Check Date | Test File |
|---|---|---|---|---|---|---|---|---|
| ■ | ST-1 | CU-2-1 | 16.0-18.0 ft | md | 8/19/16 | mcm | 8/31/16 | 305005-CU-2-1m.dat |
| ● | ST-1 | CU-2-2 | 16.0-18.0 ft | md | 8/18/16 | mcm | 8/31/16 | 305005-CU-2-2m.dat |
| ▲ | ST-1 | CU-2-3 | 16.0-18.0 ft | md | 8/18/16 | mcm | 8/31/16 | 305005-CU-2-3m.dat |
| | | | | | | | | |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US 21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Sample Type: intact | |
| Description: Moist, olive clayey sand | | |
| Remarks: System B. Note CU-2-3 test specimen was not used in determining cohesion or friction values. | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Summary Report






| | | | | Before Test | After Test |
|---|---|---|---|---|---|
| Current Vertical Effective Stress: --- | | | | Water Content, % | 51.80 | 34.90 |
| Preconsolidation Stress: --- | | | | Dry Unit Weight, pcf | 69.92 | 87.4 |
| Compression Ratio: --- | | | | Saturation, % | 98.17 | 100.00 |
| Diameter: 2.5 in | | Height: 1 in | | Void Ratio | 1.44 | 0.96 |
| LL: 66 | PL: 22 | PI: 44 | GS: 2.74 | | | |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clayey sand | | |
| | Remarks: System S, Swell Pressure = 0.0658 tsf | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 1 of 11
Constant Volume Step
Stress: 0.0658 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clayey sand | | |
| Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 2 of 11
Constant Load Step
Stress: 0.125 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clayey sand | | |
| Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 3 of 11
Constant Load Step
Stress: 0.25 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clayey sand | | |
| | Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 4 of 11
Constant Load Step
Stress: 0.5 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clayey sand | | |
| | Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 5 of 11
Constant Load Step
Stress: 1 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clayey sand | | |
| | Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 6 of 11
Constant Load Step
Stress: 2 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clayey sand | | |
| | Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 7 of 11
Constant Load Step
Stress: 4 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clayey sand | | |
| | Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 8 of 11
Constant Load Step
Stress: 8 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clayey sand | | |
| | Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 9 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clayey sand | | |
| Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 10 of 11
Constant Load Step
Stress: 0.5 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clayey sand | | |
| Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 11 of 11
Constant Load Step
Stress: 0.125 tsf




| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clayey sand | | |
| Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

| | | |
|---|---|---|
| Specimen Diameter: 2.50 in | Estimated Specific Gravity: 2.74 | Liquid Limit: 66 |
| Initial Height: 1.00 in | Initial Void Ratio: 1.44 | Plastic Limit: 22 |
| Final Height: 0.80 in | Final Void Ratio: 0.956 | Plasticity Index: 44 |

| | Before Test Trimmings | Before Test Specimen | After Test Specimen | After Test Trimmings |
|---|---|---|---|---|
| Container ID | 16719 | RING | | 9370 |
| Mass Container, gm | 8.86 | 111.44 | 111.44 | 8.57 |
| Mass Container + Wet Soil, gm | 211.34 | 248.2 | 232.98 | 128.77 |
| Mass Container + Dry Soil, gm | 128.42 | 201.53 | 201.53 | 97.67 |
| Mass Dry Soil, gm | 119.56 | 90.093 | 90.093 | 89.1 |
| Water Content, % | 69.35 | 51.80 | 34.90 | 34.90 |
| Void Ratio | --- | 1.44 | 0.96 | --- |
| Degree of Saturation, % | --- | 98.17 | 100.00 | --- |
| Dry Unit Weight, pcf | --- | 69.92 | 87.4 | --- |

Note: Specific Gravity and Void Ratios are calculated assuming the degree of saturation equals 100% at the end of the test. Therefore, values may not represent actual values for the specimen.

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clayey sand | | |
| | Remarks: System S, Swell Pressure = 0.0658 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Log of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Log T50 min | Cv ft²/s | Mv 1/tsf | k ft/day | Ca % |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.0658 | 0.009670 | 1.42 | 0.967 | 0.000 | 0.00e+00 | 1.47e-01 | 0.00e+00 | 0.00e+00 |
| 2 | 0.125 | 0.02134 | 1.39 | 2.13 | 5.659 | 9.76e-07 | 1.97e-01 | 5.19e-04 | 0.00e+00 |
| 3 | 0.250 | 0.04108 | 1.34 | 4.11 | 0.000 | 0.00e+00 | 1.58e-01 | 0.00e+00 | 0.00e+00 |
| 4 | 0.500 | 0.06929 | 1.28 | 6.93 | 4.867 | 1.05e-06 | 1.13e-01 | 3.18e-04 | 0.00e+00 |
| 5 | 1.00 | 0.1145 | 1.16 | 11.5 | 3.045 | 1.54e-06 | 9.05e-02 | 3.77e-04 | 0.00e+00 |
| 6 | 2.00 | 0.1741 | 1.02 | 17.4 | 2.268 | 1.84e-06 | 5.95e-02 | 2.95e-04 | 0.00e+00 |
| 7 | 4.00 | 0.2304 | 0.881 | 23.0 | 2.275 | 1.59e-06 | 2.82e-02 | 1.21e-04 | 0.00e+00 |
| 8 | 8.00 | 0.2827 | 0.753 | 28.3 | 1.266 | 2.49e-06 | 1.31e-02 | 8.79e-05 | 0.00e+00 |
| 9 | 2.00 | 0.2717 | 0.781 | 27.2 | 0.000 | 0.00e+00 | 1.85e-03 | 0.00e+00 | 0.00e+00 |
| 10 | 0.500 | 0.2578 | 0.814 | 25.8 | 2.399 | 1.28e-06 | 9.25e-03 | 3.21e-05 | 0.00e+00 |
| 11 | 0.125 | 0.2367 | 0.866 | 23.7 | 0.000 | 0.00e+00 | 5.61e-02 | 0.00e+00 | 0.00e+00 |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| | Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clayey sand | | |
| | Remarks: System S, Swell Pressure = 0.0658 tsf | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Square Root of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Sq.Rt. T90 min | Cv ft²/s | Mv 1/tsf | k ft/day |
|---|---|---|---|---|---|---|---|---|
| 1 | 0.0658 | 0.009670 | 1.42 | 0.967 | 48.028 | 5.06e-07 | 1.47e-01 | 2.01e-04 |
| 2 | 0.125 | 0.02134 | 1.39 | 2.13 | 26.995 | 8.81e-07 | 1.97e-01 | 4.69e-04 |
| 3 | 0.250 | 0.04108 | 1.34 | 4.11 | 19.010 | 1.21e-06 | 1.58e-01 | 5.16e-04 |
| 4 | 0.500 | 0.06929 | 1.28 | 6.93 | 18.500 | 1.18e-06 | 1.13e-01 | 3.60e-04 |
| 5 | 1.00 | 0.1145 | 1.16 | 11.5 | 17.554 | 1.15e-06 | 9.05e-02 | 2.81e-04 |
| 6 | 2.00 | 0.1741 | 1.02 | 17.4 | 11.121 | 1.62e-06 | 5.95e-02 | 2.59e-04 |
| 7 | 4.00 | 0.2304 | 0.881 | 23.0 | 9.520 | 1.64e-06 | 2.82e-02 | 1.25e-04 |
| 8 | 8.00 | 0.2827 | 0.753 | 28.3 | 5.535 | 2.45e-06 | 1.31e-02 | 8.65e-05 |
| 9 | 2.00 | 0.2717 | 0.781 | 27.2 | 2.193 | 5.84e-06 | 1.85e-03 | 2.91e-05 |
| 10 | 0.500 | 0.2578 | 0.814 | 25.8 | 10.719 | 1.24e-06 | 9.25e-03 | 3.09e-05 |
| 11 | 0.125 | 0.2367 | 0.866 | 23.7 | 40.735 | 3.41e-07 | 5.61e-02 | 5.17e-05 |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 08/19/16 | Depth: 16.0-18.0 ft |
| Test No.: IP-2 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clayey sand | | |
| Remarks: System S, Swell Pressure = 0.0658 tsf | | |
| Displacement at End of Increment | | |

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | jbr |
| Sample ID: | --- | Test Date: | 08/30/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 387124 | | |


# Moisture Content of Soil and Rock - ASTM D2216

| Boring ID | Sample ID | Depth | Description | Moisture Content,% |
|---|---|---|---|---|
| AP-2 | UD-2 | 18.0-20.0 ft | Moist, olive sandy clay | 69.3 |

Notes: Temperature of Drying : 110º Celsius

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-2 | Sample Type: | tube | Tested By: | jbr |
| Sample ID: | UD-2 | Test Date: | 08/26/16 | Checked By: | mcm |
| Depth : | 18.0-20.0 ft | Test Id: | 387104 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy clay | | | | |
| Sample Comment: | --- | | | | |

# Particle Size Analysis - ASTM D422




| % Cobble | % Gravel | % Sand | % Silt & Clay Size |
|---|---|---|---|
| — | 0.0 | 36.5 | 63.5 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| #4 | 4.75 | 100 | | |
| #10 | 2.00 | 100 | | |
| #20 | 0.85 | 98 | | |
| #40 | 0.42 | 96 | | |
| #60 | 0.25 | 96 | | |
| #100 | 0.15 | 88 | | |
| #200 | 0.075 | 64 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ =0.1387 mm | $D_{30}$ =N/A |
| $D_{60}$ =N/A | $D_{15}$ =N/A |
| $D_{50}$ =N/A | $D_{10}$ =N/A |
| $C_u$ =N/A | $C_c$ =N/A |

**Classification**

ASTM Sandy Fat clay (CH)

AASHTO Clayey Soils (A-7-6 (33))


**Sample/Test Description**

Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-2 | Sample Type: | tube | Tested By: | cam |
| Sample ID: | UD-2 | Test Date: | 08/29/16 | Checked By: | mcm |
| Depth : | 18.0-20.0 ft | Test Id: | 387112 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive sandy clay | | | | |
| Sample Comment: | --- | | | | |

# Atterberg Limits - ASTM D4318





| Symbol | Sample ID | Boring | Depth | Natural Moisture Content,% | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-2 | AP-2 | 18.0-20.0 ft | 69 | 81 | 27 | 54 | 0.8 | Sandy Fat clay (CH) |


Sample Prepared using the WET method
4% Retained on #40 Sieve
Dry Strength: VERY HIGH
Dilatancy: SLOW
Toughness: LOW

GeoTesting EXPRESS

| | |
|---|---|
| Client: F&ME Consultants | |
| Project Name: US-21 Replacement Bridge | |
| Project Location: --- | |
| Project Number: GTX-305005 | |
| Tested By: md | Checked By: mcm |
| Boring ID: AP-2 | |
| Preparation: intact | |
| Description: Moist, olive sandy clay | |
| Classification: Sandy Fat clay | |
| Group Symbol: CH | |
| Liquid Limit: 81 | Plastic Limit: 27 |
| Plasticity Index: 54 | Estimated Specific Gravity: 2.7 |


## CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767




| | | | | | |
|---|---|---|---|---|---|
| Symbol | | ■ | ● | ▲ | |
| Sample ID | | ST-2 | ST-2 | ST-2 | |
| Depth, ft | | 18.0-20.0 ft | 18.0-20.0 ft | 18.0-20.0 ft | |
| Test Number | | CU-4-1 | CU-4-2 | CU-4-3 | |
| Initial | Height, in | 4.500 | 4.350 | 4.380 | |
| | Diameter, in | 2.030 | 2.010 | 2.030 | |
| | Moisture Content (from Cuttings), % | 64.9 | 70.2 | 80.2 | |
| | Dry Density, pcf | 60.5 | 54.4 | 52.1 | |
| | Saturation (Wet Method), % | 98.2 | 90.4 | 96.8 | |
| | Void Ratio | 1.78 | 2.10 | 2.24 | |
| Before Shear | Moisture Content, % | 63.4 | 70.4 | 70.2 | |
| | Dry Density, pcf | 62.1 | 58.1 | 58.2 | |
| | Cross-sectional Area (Method A), in² | 3.153 | 3.020 | 3.006 | |
| | Saturation, % | 100.0 | 100.0 | 100.0 | |
| | Void Ratio | 1.71 | 1.90 | 1.90 | |
| | Back Pressure, psi | 96.99 | 151.0 | 150.7 | |
| Vertical Effective Consolidation Stress, psi | | 5.008 | 9.886 | 14.67 | |
| Horizontal Effective Consolidation Stress, psi | | 5.005 | 10.00 | 14.97 | |
| Vertical Strain after Consolidation, % | | 0.002069 | 1.405 | 3.740 | |
| Volumetric Strain after Consolidation, % | | 2.531 | 5.704 | 10.72 | |
| Time to 50% Consolidation, min | | 72.25 | 90.25 | 169.0 | |
| Shear Strength, psi | | 3.498 | 3.528 | 4.459 | |
| Strain at Failure, % | | 5.48 | 7.76 | 12.0 | |
| Strain Rate, %/min | | 0.01600 | 0.01600 | 0.01600 | |
| Deviator Stress at Failure, psi | | 6.995 | 7.055 | 8.918 | |
| Effective Minor Principal Stress at Failure, psi | | 1.703 | 2.455 | 3.977 | |
| Effective Major Principal Stress at Failure, psi | | 8.698 | 9.510 | 12.90 | |
| B-Value | | 0.95 | 0.95 | 0.95 | |


Notes:
- Before Shear Saturation set to 100% for phase calculation.
- Moisture Content determined by ASTM D2216.
- Atterberg Limits determined by ASTM D4318.
- Deviator Stress includes membrane correction.
- Values for c and φ determined from best-fit straight line for the specific test conditions. Actual strength parameters may vary and should be determined by an engineer for site conditions.





Remarks:

System X. Note CU-1-1 test specimen was not used in determining cohesion or friction values.

# CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767





| | Sample No. | Test No. | Depth | Tested By | Test Date | Checked By | Check Date | Test File |
|---|---|---|---|---|---|---|---|---|
| ■ | ST-2 | CU-4-1 | 18.0-20.0 ft | md | 8/23/16 | mcm | 8/30/16 | 305005-CU-4-1m.dat |
| ● | ST-2 | CU-4-2 | 18.0-20.0 ft | md | 08/23/16 | mcm | 8/30/16 | 305005-CU-4-2m.dat |
| ▲ | ST-2 | CU-4-3 | 18.0-20.0 ft | md | 08/23/16 | mcm | 8/30/16 | 305005-CU-4-3m.dat |
| | | | | | | | | |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Sample Type: intact | |
| Description: Moist, olive sandy clay | | |
| Remarks: System X. Note CU-1-1 test specimen was not used in determining cohesion or friction values. | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Summary Report






| | | | | Before Test | After Test |
|---|---|---|---|---|---|
| Current Vertical Effective Stress: --- | | | | Water Content, % | 57.55 | 32.34 |
| Preconsolidation Stress: --- | | | | Dry Unit Weight, pcf | 65.031 | 90.12 |
| Compression Ratio: --- | | | | Saturation, % | 97.45 | 100.00 |
| Diameter: 2.5 in | | Height: 1 in | | Void Ratio | 1.60 | 0.88 |
| LL: 81 | PL: 27 | PI: 54 | GS: 2.71 | | | |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System Q, Swell Pressure = 0.0659 tsf | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 1 of 11
Constant Volume Step
Stress: 0.0659 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 2 of 11
Constant Load Step
Stress: 0.125 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 3 of 11
Constant Load Step
Stress: 0.25 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 4 of 11
Constant Load Step
Stress: 0.5 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 5 of 11
Constant Load Step
Stress: 1 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 6 of 11
Constant Load Step
Stress: 2 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 7 of 11
Constant Load Step
Stress: 4 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 8 of 11
Constant Load Step
Stress: 8 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 9 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 10 of 11
Constant Load Step
Stress: 0.5 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 11 of 11
Constant Load Step
Stress: 0.125 tsf




| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

| | | |
|---|---|---|
| Specimen Diameter: 2.50 in | Estimated Specific Gravity: 2.71 | Liquid Limit: 81 |
| Initial Height: 1.00 in | Initial Void Ratio: 1.60 | Plastic Limit: 27 |
| Final Height: 0.72 in | Final Void Ratio: 0.876 | Plasticity Index: 54 |

| | Before Test Trimmings | Before Test Specimen | After Test Specimen | After Test Trimmings |
|---|---|---|---|---|
| Container ID | C-2032 | RING | | C-1962 |
| Mass Container, gm | 8.52 | 111.14 | 111.14 | 8.44 |
| Mass Container + Wet Soil, gm | 220 | 243.16 | 222.03 | 119.18 |
| Mass Container + Dry Soil, gm | 127.93 | 194.93 | 194.93 | 92.12 |
| Mass Dry Soil, gm | 119.41 | 83.793 | 83.793 | 83.68 |
| Water Content, % | 77.10 | 57.55 | 32.34 | 32.34 |
| Void Ratio | --- | 1.60 | 0.88 | --- |
| Degree of Saturation, % | --- | 97.45 | 100.00 | --- |
| Dry Unit Weight, pcf | --- | 65.031 | 90.12 | --- |

Note: Specific Gravity and Void Ratios are calculated assuming the degree of saturation equals 100% at the end of the test. Therefore, values may not represent actual values for the specimen.

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| | Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive sandy clay | | |
| | Remarks: System Q, Swell Pressure = 0.0659 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Log of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Log T50 min | Cv ft²/s | Mv 1/tsf | k ft/day | Ca % |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.0659 | 0.002648 | 1.59 | 0.265 | 0.000 | 0.00e+00 | 4.02e-02 | 0.00e+00 | 0.00e+00 |
| 2 | 0.125 | 0.008293 | 1.58 | 0.829 | 1.928 | 2.92e-06 | 9.54e-02 | 7.53e-04 | 0.00e+00 |
| 3 | 0.250 | 0.02363 | 1.54 | 2.36 | 1.789 | 3.08e-06 | 1.23e-01 | 1.02e-03 | 0.00e+00 |
| 4 | 0.500 | 0.04876 | 1.47 | 4.88 | 1.845 | 2.87e-06 | 1.01e-01 | 7.78e-04 | 0.00e+00 |
| 5 | 1.00 | 0.1129 | 1.31 | 11.3 | 7.718 | 6.24e-07 | 1.28e-01 | 2.16e-04 | 0.00e+00 |
| 6 | 2.00 | 0.1972 | 1.09 | 19.7 | 5.999 | 6.78e-07 | 8.43e-02 | 1.54e-04 | 0.00e+00 |
| 7 | 4.00 | 0.2734 | 0.889 | 27.3 | 5.715 | 5.83e-07 | 3.81e-02 | 5.99e-05 | 0.00e+00 |
| 8 | 8.00 | 0.3362 | 0.725 | 33.6 | 4.146 | 6.64e-07 | 1.57e-02 | 2.81e-05 | 0.00e+00 |
| 9 | 2.00 | 0.3213 | 0.764 | 32.1 | 1.793 | 1.43e-06 | 2.49e-03 | 9.62e-06 | 0.00e+00 |
| 10 | 0.500 | 0.3022 | 0.814 | 30.2 | 6.717 | 4.02e-07 | 1.27e-02 | 1.38e-05 | 0.00e+00 |
| 11 | 0.125 | 0.2784 | 0.876 | 27.8 | 0.000 | 0.00e+00 | 6.34e-02 | 0.00e+00 | 0.00e+00 |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System Q, Swell Pressure = 0.0659 tsf | | |
| Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Square Root of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Sq.Rt. T90 min | Cv ft²/s | Mv 1/tsf | k ft/day |
|---|---|---|---|---|---|---|---|---|
| 1 | 0.0659 | 0.002648 | 1.59 | 0.265 | 176.539 | 1.39e-07 | 4.02e-02 | 1.50e-05 |
| 2 | 0.125 | 0.008293 | 1.58 | 0.829 | 7.943 | 3.06e-06 | 9.54e-02 | 7.86e-04 |
| 3 | 0.250 | 0.02363 | 1.54 | 2.36 | 5.565 | 4.27e-06 | 1.23e-01 | 1.41e-03 |
| 4 | 0.500 | 0.04876 | 1.47 | 4.88 | 12.180 | 1.87e-06 | 1.01e-01 | 5.07e-04 |
| 5 | 1.00 | 0.1129 | 1.31 | 11.3 | 23.249 | 8.92e-07 | 1.28e-01 | 3.09e-04 |
| 6 | 2.00 | 0.1972 | 1.09 | 19.7 | 31.229 | 5.61e-07 | 8.43e-02 | 1.27e-04 |
| 7 | 4.00 | 0.2734 | 0.889 | 27.3 | 26.374 | 5.44e-07 | 3.81e-02 | 5.59e-05 |
| 8 | 8.00 | 0.3362 | 0.725 | 33.6 | 20.477 | 5.79e-07 | 1.57e-02 | 2.45e-05 |
| 9 | 2.00 | 0.3213 | 0.764 | 32.1 | 11.581 | 9.55e-07 | 2.49e-03 | 6.41e-06 |
| 10 | 0.500 | 0.3022 | 0.814 | 30.2 | 22.537 | 5.16e-07 | 1.27e-02 | 1.77e-05 |
| 11 | 0.125 | 0.2784 | 0.876 | 27.8 | 107.764 | 1.15e-07 | 6.34e-02 | 1.96e-05 |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-2 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 18.0-20.0 ft |
| Test No.: IP-4 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive sandy clay | | |
| Remarks: System Q, Swell Pressure = 0.0659 tsf | | |
| Displacement at End of Increment | | |

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | jbr |
| Sample ID: | --- | Test Date: | 08/30/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 387124 | | |


# Moisture Content of Soil and Rock - ASTM D2216

| Boring ID | Sample ID | Depth | Description | Moisture Content,% |
|---|---|---|---|---|
| AP-3 | UD-1 | 25.0-27.0 ft | Moist, olive clay with sand | 83.0 |

Notes: Temperature of Drying : 110º Celsius

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-3 | Sample Type: | tube | Tested By: | jbr |
| Sample ID: | UD-1 | Test Date: | 08/29/16 | Checked By: | mcm |
| Depth : | 25.0-27.0 ft | Test Id: | 387105 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive clay with sand | | | | |
| Sample Comment: | Sample contains shells and shell fragments | | | | |

# Particle Size Analysis - ASTM D422




| % Cobble | % Gravel | % Sand | % Silt & Clay Size |
|---|---|---|---|
| — | 0.1 | 20.4 | 79.5 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| 0.375 in | 9.50 | 100 | | |
| #4 | 4.75 | 100 | | |
| #10 | 2.00 | 99 | | |
| #20 | 0.85 | 97 | | |
| #40 | 0.42 | 97 | | |
| #60 | 0.25 | 96 | | |
| #100 | 0.15 | 95 | | |
| #200 | 0.075 | 79 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ =0.0966 mm | $D_{30}$ =N/A |
| $D_{60}$ =N/A | $D_{15}$ =N/A |
| $D_{50}$ =N/A | $D_{10}$ =N/A |
| $C_u$ =N/A | $C_c$ =N/A |

**Classification**

ASTM Fat clay with sand (CH)

AASHTO Clayey Soils (A-7-6 (50))


**Sample/Test Description**

Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-3 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-1 | Test Date: | 08/31/16 | Checked By: | mcm |
| Depth : | 25.0-27.0 ft | Test Id: | 387113 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive clay with sand | | | | |
| Sample Comment: | Sample contains shells and shell fragments | | | | |

# Atterberg Limits - ASTM D4318





| Symbol | Sample ID | Boring | Depth | Natural Moisture Content,% | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-1 | AP-3 | 25.0-27.0 ft | 83 | 85 | 27 | 58 | 1 | Fat clay with sand (CH) |


Sample Prepared using the WET method
3% Retained on #40 Sieve
Dry Strength: VERY HIGH
Dilatancy: NONE
Toughness: MEDIUM

GeoTesting EXPRESS

| | |
|---|---|
| Client: F&ME Consultants | |
| Project Name: US-21 Replacement Bridge | |
| Project Location: --- | |
| Project Number: GTX-305005 | |
| Tested By: md | Checked By: mcm |
| Boring ID: AP-3 | |
| Preparation: intact | |
| Description: Moist, olive clay with sand | |
| Classification: Fat clay with sand | |
| Group Symbol: CH | |
| Liquid Limit: 85 | Plastic Limit: 27 |
| Plasticity Index: 58 | Estimated Specific Gravity: 2.7 |


## CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767




| | | | | | |
|---|---|---|---|---|---|
| Symbol | | ■ | ● | ▲ | |
| Sample ID | | ST-1 | ST-1 | ST-1 | |
| Depth, ft | | 25.0-27.0 ft | 25.0.-27.0 ft | 25.0-27.0 ft | |
| Test Number | | CU-6-1 | CU-6-2 | CU-6-3 | |
| Initial | Height, in | 4.720 | 4.620 | 4.580 | |
| | Diameter, in | 2.030 | 2.030 | 2.030 | |
| | Moisture Content (from Cuttings), % | 81.4 | 86.2 | 82.4 | |
| | Dry Density, pcf | 51.4 | 50.4 | 50.0 | |
| | Saturation (Wet Method), % | 96.3 | 99.3 | 93.8 | |
| | Void Ratio | 2.28 | 2.35 | 2.37 | |
| Before Shear | Moisture Content, % | 82.9 | 85.0 | 69.4 | |
| | Dry Density, pcf | 52.0 | 51.1 | 58.7 | |
| | Cross-sectional Area (Method A), in² | 3.214 | 3.191 | 2.870 | |
| | Saturation, % | 100.0 | 100.0 | 100.0 | |
| | Void Ratio | 2.24 | 2.30 | 1.87 | |
| | Back Pressure, psi | 152.9 | 160.8 | 39.02 | |
| Vertical Effective Consolidation Stress, psi | | 4.946 | 9.960 | 14.65 | |
| Horizontal Effective Consolidation Stress, psi | | 4.999 | 9.962 | 14.97 | |
| Vertical Strain after Consolidation, % | | 0.6778 | 0.08763 | 3.850 | |
| Volumetric Strain after Consolidation, % | | 1.541 | 1.531 | 14.69 | |
| Time to 50% Consolidation, min | | 45.56 | 16.81 | 297.6 | |
| Shear Strength, psi | | 3.695 | 4.164 | 4.763 | |
| Strain at Failure, % | | 2.24 | 2.33 | 8.61 | |
| Strain Rate, %/min | | 0.01600 | 0.01600 | 0.01600 | |
| Deviator Stress at Failure, psi | | 7.391 | 8.329 | 9.526 | |
| Effective Minor Principal Stress at Failure, psi | | 1.536 | 2.888 | 1.698 | |
| Effective Major Principal Stress at Failure, psi | | 8.927 | 11.22 | 11.22 | |
| B-Value | | 0.95 | 0.95 | 0.96 | |


Notes:
- Before Shear Saturation set to 100% for phase calculation.
- Moisture Content determined by ASTM D2216.
- Atterberg Limits determined by ASTM D4318.
- Deviator Stress includes membrane correction.
- Values for c and φ determined from best-fit straight line for the specific test conditions. Actual strength parameters may vary and should be determined by an engineer for site conditions.





Remarks:

System X

# CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767





| | Sample No. | Test No. | Depth | Tested By | Test Date | Checked By | Check Date | Test File |
|---|---|---|---|---|---|---|---|---|
| ■ | ST-1 | CU-6-1 | 25.0-27.0 ft | md | 8/25/16 | mcm | 9/7/16 | 305005-CU-6-1m.dat |
| ● | ST-1 | CU-6-2 | 25.0.-27.0 ft | md | 08/26/16 | mcm | 9/7/16 | 305005-CU-6-2m.dat |
| ▲ | ST-1 | CU-6-3 | 25.0-27.0 ft | md | 08/25/16 | mcm | 9/7/16 | 305005-CU-6-3m.dat |
| | | | | | | | | |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Sample Type: intact | |
| Description: Moist, olive clay with sand | | |
| Remarks: System X | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Summary Report






| | | | | | Before Test | After Test |
|---|---|---|---|---|---|---|
| Current Vertical Effective Stress: --- | | | | Water Content, % | 105.01 | 58.58 |
| Preconsolidation Stress: --- | | | | Dry Unit Weight, pcf | 43.621 | 65.827 |
| Compression Ratio: --- | | | | Saturation, % | 98.28 | 100.00 |
| Diameter: 2.5 in | | Height: 1 in | | Void Ratio | 2.95 | 1.62 |
| LL: 85 | PL: 27 | PI: 58 | GS: 2.76 | | | |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| | Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| | Description: Moist, grey clay | | |
| | Remarks: System S, Swell Pressure = | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 1 of 11
Constant Volume Step
Stress: 0.0642 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| Description: Moist, grey clay | | |
| Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 2 of 11
Constant Load Step
Stress: 0.125 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| | Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| | Description: Moist, grey clay | | |
| | Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 3 of 11
Constant Load Step
Stress: 0.25 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| Description: Moist, grey clay | | |
| Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 4 of 11
Constant Load Step
Stress: 0.5 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| Description: Moist, grey clay | | |
| Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 5 of 11
Constant Load Step
Stress: 1 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| | Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| | Description: Moist, grey clay | | |
| | Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 6 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| Description: Moist, grey clay | | |
| Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 7 of 11
Constant Load Step
Stress: 4 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| Description: Moist, grey clay | | |
| Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 8 of 11
Constant Load Step
Stress: 8 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| | Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| | Description: Moist, grey clay | | |
| | Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 9 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| Description: Moist, grey clay | | |
| Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 10 of 11
Constant Load Step
Stress: 0.5 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| Description: Moist, grey clay | | |
| Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 11 of 11
Constant Load Step
Stress: 0.125 tsf




| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| Description: Moist, grey clay | | |
| Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

| | | |
|---|---|---|
| Specimen Diameter: 2.50 in | Estimated Specific Gravity: 2.76 | Liquid Limit: 85 |
| Initial Height: 1.00 in | Initial Void Ratio: 2.95 | Plastic Limit: 27 |
| Final Height: 0.66 in | Final Void Ratio: 1.62 | Plasticity Index: 58 |

| | Before Test Trimmings | Before Test Specimen | After Test Specimen | After Test Trimmings |
|---|---|---|---|---|
| Container ID | C-1757 | RING | | C-1676 |
| Mass Container, gm | 8.34 | 108.89 | 108.89 | 8.64 |
| Mass Container + Wet Soil, gm | 169.13 | 224.12 | 198.02 | 97.49 |
| Mass Container + Dry Soil, gm | 93.83 | 165.1 | 165.1 | 64.67 |
| Mass Dry Soil, gm | 85.49 | 56.207 | 56.207 | 56.03 |
| Water Content, % | 88.08 | 105.01 | 58.58 | 58.58 |
| Void Ratio | --- | 2.95 | 1.62 | --- |
| Degree of Saturation, % | --- | 98.28 | 100.00 | --- |
| Dry Unit Weight, pcf | --- | 43.621 | 65.827 | --- |

Note: Specific Gravity and Void Ratios are calculated assuming the degree of saturation equals 100% at the end of the test. Therefore, values may not represent actual values for the specimen.

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| | Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| | Description: Moist, grey clay | | |
| | Remarks: System S, Swell Pressure = | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Log of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Log T50 min | Cv ft²/s | Mv 1/tsf | k ft/day | Ca % |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.0642 | 0.002508 | 2.94 | 0.251 | 0.000 | 0.00e+00 | 3.90e-02 | 0.00e+00 | 0.00e+00 |
| 2 | 0.125 | 0.007295 | 2.92 | 0.729 | 1.399 | 4.03e-06 | 7.88e-02 | 8.57e-04 | 0.00e+00 |
| 3 | 0.250 | 0.01687 | 2.88 | 1.69 | 1.511 | 3.68e-06 | 7.66e-02 | 7.61e-04 | 0.00e+00 |
| 4 | 0.500 | 0.03916 | 2.79 | 3.92 | 3.672 | 1.47e-06 | 8.92e-02 | 3.53e-04 | 0.00e+00 |
| 5 | 1.00 | 0.1054 | 2.53 | 10.5 | 0.000 | 0.00e+00 | 1.32e-01 | 0.00e+00 | 0.00e+00 |
| 6 | 2.00 | 0.2476 | 1.97 | 24.8 | 25.262 | 1.53e-07 | 1.42e-01 | 5.87e-05 | 0.00e+00 |
| 7 | 4.00 | 0.3440 | 1.59 | 34.4 | 15.415 | 1.83e-07 | 4.82e-02 | 2.38e-05 | 0.00e+00 |
| 8 | 8.00 | 0.4206 | 1.29 | 42.1 | 0.000 | 0.00e+00 | 1.92e-02 | 0.00e+00 | 0.00e+00 |
| 9 | 2.00 | 0.4006 | 1.37 | 40.1 | 0.000 | 0.00e+00 | 3.34e-03 | 0.00e+00 | 0.00e+00 |
| 10 | 0.500 | 0.3697 | 1.49 | 37.0 | 19.431 | 1.11e-07 | 2.06e-02 | 6.16e-06 | 0.00e+00 |
| 11 | 0.125 | 0.3373 | 1.62 | 33.7 | 0.000 | 0.00e+00 | 8.62e-02 | 0.00e+00 | 0.00e+00 |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| | Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| | Description: Moist, grey clay | | |
| | Remarks: System S, Swell Pressure = | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Square Root of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Sq.Rt. T90 min | Cv ft²/s | Mv 1/tsf | k ft/day |
|---|---|---|---|---|---|---|---|---|
| 1 | 0.0642 | 0.002508 | 2.94 | 0.251 | 184.101 | 1.33e-07 | 3.90e-02 | 1.40e-05 |
| 2 | 0.125 | 0.007295 | 2.92 | 0.729 | 6.160 | 3.94e-06 | 7.88e-02 | 8.38e-04 |
| 3 | 0.250 | 0.01687 | 2.88 | 1.69 | 12.448 | 1.92e-06 | 7.66e-02 | 3.97e-04 |
| 4 | 0.500 | 0.03916 | 2.79 | 3.92 | 13.265 | 1.75e-06 | 8.92e-02 | 4.20e-04 |
| 5 | 1.00 | 0.1054 | 2.53 | 10.5 | 54.411 | 3.88e-07 | 1.32e-01 | 1.39e-04 |
| 6 | 2.00 | 0.2476 | 1.97 | 24.8 | 118.237 | 1.41e-07 | 1.42e-01 | 5.40e-05 |
| 7 | 4.00 | 0.3440 | 1.59 | 34.4 | 72.960 | 1.67e-07 | 4.82e-02 | 2.17e-05 |
| 8 | 8.00 | 0.4206 | 1.29 | 42.1 | 58.751 | 1.59e-07 | 1.92e-02 | 8.24e-06 |
| 9 | 2.00 | 0.4006 | 1.37 | 40.1 | 12.642 | 6.74e-07 | 3.34e-03 | 6.08e-06 |
| 10 | 0.500 | 0.3697 | 1.49 | 37.0 | 105.455 | 8.80e-08 | 2.06e-02 | 4.89e-06 |
| 11 | 0.125 | 0.3373 | 1.62 | 33.7 | 189.648 | 5.41e-08 | 8.62e-02 | 1.26e-05 |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 8/26/16 | Depth: 25-27 ft |
| Test No.: IP-6 | Sample Type: intact | Elevation: --- |
| Description: Moist, grey clay | | |
| Remarks: System S, Swell Pressure = | | |
| Displacement at End of Increment | | |

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | jbr |
| Sample ID: | --- | Test Date: | 08/30/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 387124 | | |


# Moisture Content of Soil and Rock - ASTM D2216

| Boring ID | Sample ID | Depth | Description | Moisture Content,% |
|---|---|---|---|---|
| AP-3 | UD-2 | 27.0-29.0 ft | Moist, olive clay with sand | 78.8 |

Notes: Temperature of Drying : 110º Celsius

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-3 | Sample Type: | tube | Tested By: | jbr |
| Sample ID: | UD-2 | Test Date: | 08/23/16 | Checked By: | mcm |
| Depth : | 27.0-29.0 ft | Test Id: | 387106 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive clay with sand | | | | |
| Sample Comment: | --- | | | | |

# Particle Size Analysis - ASTM D422




| % Cobble | % Gravel | % Sand | % Silt & Clay Size |
|---|---|---|---|
| — | 0.1 | 18.5 | 81.4 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| 0.375 in | 9.50 | 100 | | |
| #4 | 4.75 | 100 | | |
| #10 | 2.00 | 100 | | |
| #20 | 0.85 | 99 | | |
| #40 | 0.42 | 98 | | |
| #60 | 0.25 | 98 | | |
| #100 | 0.15 | 97 | | |
| #200 | 0.075 | 81 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ =0.0878 mm | $D_{30}$ =N/A |
| $D_{60}$ =N/A | $D_{15}$ =N/A |
| $D_{50}$ =N/A | $D_{10}$ =N/A |
| $C_u$ =N/A | $C_c$ =N/A |

**Classification**

ASTM Fat clay with sand (CH)

AASHTO Clayey Soils (A-7-6 (43))


**Sample/Test Description**

Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-3 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-2 | Test Date: | 08/31/16 | Checked By: | mcm |
| Depth : | 27.0-29.0 ft | Test Id: | 387114 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, olive clay with sand | | | | |
| Sample Comment: | --- | | | | |

# Atterberg Limits - ASTM D4318





| Symbol | Sample ID | Boring | Depth | Natural Moisture Content,% | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-2 | AP-3 | 27.0-29.0 ft | 79 | 74 | 25 | 49 | 1.1 | Fat clay with sand (CH) |


Sample Prepared using the WET method
2% Retained on #40 Sieve
Dry Strength: VERY HIGH
Dilatancy: NONE
Toughness: MEDIUM

GeoTesting EXPRESS

| | |
|---|---|
| Client: F&ME Consultants | |
| Project Name: US-21 Replacement Bridge | |
| Project Location: --- | |
| Project Number: GTX-305005 | |
| Tested By: md | Checked By: mcm |
| Boring ID: AP-3 | |
| Preparation: intact | |
| Description: Moist, olive clay with sand | |
| Classification: Fat clay with sand | |
| Group Symbol: CH | |
| Liquid Limit: 74 | Plastic Limit: 25 |
| Plasticity Index: 49 | Estimated Specific Gravity: 2.7 |


## CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767




| | | ■ | ● | ▲ | |
|---|---|---|---|---|---|
| Symbol | | | | | |
| Sample ID | | ST-2 | ST-2 | ST-2 | |
| Depth, ft | | 27.0-29.0 ft | 27.0-29.0 ft | 27.0-29.0 ft | |
| Test Number | | CU-1-1 | CU-1-2 | CU-1-3A | |
| Initial | Height, in | 4.550 | 4.750 | 4.410 | |
| | Diameter, in | 2.030 | 2.030 | 2.040 | |
| | Moisture Content (from Cuttings), % | 59.7 | 78.5 | 94.1 | |
| | Dry Density, pcf | 62.0 | 51.8 | 47.3 | |
| | Saturation (Wet Method), % | 93.8 | 94.1 | 99.3 | |
| | Void Ratio | 1.72 | 2.25 | 2.56 | |
| Before Shear | Moisture Content, % | 62.7 | 74.6 | 85.0 | |
| | Dry Density, pcf | 62.6 | 55.9 | 51.2 | |
| | Cross-sectional Area (Method A), in² | 3.208 | 3.048 | 3.185 | |
| | Saturation, % | 100.0 | 100.0 | 100.0 | |
| | Void Ratio | 1.69 | 2.02 | 2.29 | |
| | Back Pressure, psi | 149.0 | 152.8 | 162.9 | |
| Vertical Effective Consolidation Stress, psi | | 4.995 | 9.855 | 14.56 | |
| Horizontal Effective Consolidation Stress, psi | | 5.004 | 9.975 | 14.97 | |
| Vertical Strain after Consolidation, % | | 0.1308 | 1.490 | 5.016 | |
| Volumetric Strain after Consolidation, % | | 1.243 | 7.152 | 7.479 | |
| Time to 50% Consolidation, min | | 9.610 | 121.0 | 30.25 | |
| Shear Strength, psi | | 3.769 | 3.482 | 4.897 | |
| Strain at Failure, % | | 2.33 | 8.55 | 5.65 | |
| Strain Rate, %/min | | 0.01600 | 0.01600 | 0.01600 | |
| Deviator Stress at Failure, psi | | 7.539 | 6.965 | 9.794 | |
| Effective Minor Principal Stress at Failure, psi | | 1.790 | 2.097 | 10.87 | |
| Effective Major Principal Stress at Failure, psi | | 9.329 | 9.062 | 20.67 | |
| B-Value | | 0.96 | 0.95 | 0.96 | |


Notes:
- Before Shear Saturation set to 100% for phase calculation.
- Moisture Content determined by ASTM D2216.
- Atterberg Limits determined by ASTM D4318.
- Deviator Stress includes membrane correction.
- Values for c and φ determined from best-fit straight line for the specific test conditions. Actual strength parameters may vary and should be determined by an engineer for site conditions.





Remarks:

System X

# CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767





| | Sample No. | Test No. | Depth | Tested By | Test Date | Checked By | Check Date | Test File |
|---|---|---|---|---|---|---|---|---|
| ■ | ST-2 | CU-1-1 | 27.0-29.0 ft | md | 8/16/16 | mcm | 9/8/16 | 305005-CU-1-1m.dat |
| ● | ST-2 | CU-1-2 | 27.0-29.0 ft | md | 8/16/16 | mcm | 9/8/16 | 305005-CU-1-2m.dat |
| ▲ | ST-2 | CU-1-3A | 27.0-29.0 ft | md | 8/22/16 | mcm | 9/8/16 | 305005-CU-1-3Am.dat |
| | | | | | | | | |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Sample Type: intact | |
| Description: Moist, olive clay with sand | | |
| Remarks: System X | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Summary Report






| | | | | Before Test | After Test |
|---|---|---|---|---|---|
| Current Vertical Effective Stress: --- | | | | Water Content, % | 83.73 | 52.10 |
| Preconsolidation Stress: --- | | | | Dry Unit Weight, pcf | 51.8 | 70.476 |
| Compression Ratio: --- | | | | Saturation, % | 99.63 | 100.00 |
| Diameter: 2.5 in | | Height: 1 in | | Void Ratio | 2.30 | 1.43 |
| LL: --- | PL: --- | PI: --- | GS: 2.74 | | | |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| | Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System W, Swell Pressure = 0.0675 tsf | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 1 of 11
Constant Volume Step
Stress: 0.0675 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 2 of 11
Constant Load Step
Stress: 0.125 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 3 of 11
Constant Load Step
Stress: 0.25 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 4 of 11
Constant Load Step
Stress: 0.5 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 5 of 11
Constant Load Step
Stress: 1 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 6 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 7 of 11
Constant Load Step
Stress: 4 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 8 of 11
Constant Load Step
Stress: 8 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 9 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 10 of 11
Constant Load Step
Stress: 0.5 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| | Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 11 of 11
Constant Load Step
Stress: 0.125 tsf




| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

| | | |
|---|---|---|
| Specimen Diameter: 2.50 in | Estimated Specific Gravity: 2.74 | Liquid Limit: --- |
| Initial Height: 1.00 in | Initial Void Ratio: 2.30 | Plastic Limit: --- |
| Final Height: 0.73 in | Final Void Ratio: 1.43 | Plasticity Index: --- |

| | Before Test Trimmings | Before Test Specimen | After Test Specimen | After Test Trimmings |
|---|---|---|---|---|
| Container ID | | RING | | B-990 |
| Mass Container, gm | 0 | 109.41 | 109.41 | 7.92 |
| Mass Container + Wet Soil, gm | 122.63 | 232.04 | 210.93 | 107.44 |
| Mass Container + Dry Soil, gm | 65.43 | 176.15 | 176.15 | 73.35 |
| Mass Dry Soil, gm | 65.43 | 66.745 | 66.745 | 65.43 |
| Water Content, % | 87.42 | 83.73 | 52.10 | 52.10 |
| Void Ratio | --- | 2.30 | 1.43 | --- |
| Degree of Saturation, % | --- | 99.63 | 100.00 | --- |
| Dry Unit Weight, pcf | --- | 51.8 | 70.476 | --- |

Note: Specific Gravity and Void Ratios are calculated assuming the degree of saturation equals 100% at the end of the test. Therefore, values may not represent actual values for the specimen.

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| | Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System W, Swell Pressure = 0.0675 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Log of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Log T50 min | Cv ft²/s | Mv 1/tsf | k ft/day | Ca % |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.0675 | 0.001166 | 2.30 | 0.117 | 0.000 | 0.00e+00 | 1.73e-02 | 0.00e+00 | 0.00e+00 |
| 2 | 0.125 | 0.004898 | 2.29 | 0.490 | 0.000 | 0.00e+00 | 6.49e-02 | 0.00e+00 | 0.00e+00 |
| 3 | 0.250 | 0.01441 | 2.26 | 1.44 | 1.040 | 5.37e-06 | 7.61e-02 | 1.10e-03 | 0.00e+00 |
| 4 | 0.500 | 0.03951 | 2.17 | 3.95 | 1.335 | 4.04e-06 | 1.00e-01 | 1.09e-03 | 0.00e+00 |
| 5 | 1.00 | 0.09292 | 2.00 | 9.29 | 0.000 | 0.00e+00 | 1.07e-01 | 0.00e+00 | 0.00e+00 |
| 6 | 2.00 | 0.2160 | 1.59 | 21.6 | 0.000 | 0.00e+00 | 1.23e-01 | 0.00e+00 | 0.00e+00 |
| 7 | 4.00 | 0.3117 | 1.27 | 31.2 | 9.347 | 3.30e-07 | 4.78e-02 | 4.26e-05 | 0.00e+00 |
| 8 | 8.00 | 0.3866 | 1.03 | 38.7 | 5.938 | 4.07e-07 | 1.87e-02 | 2.05e-05 | 0.00e+00 |
| 9 | 2.00 | 0.3666 | 1.09 | 36.7 | 3.892 | 5.69e-07 | 3.33e-03 | 5.11e-06 | 0.00e+00 |
| 10 | 0.500 | 0.3388 | 1.18 | 33.9 | 15.451 | 1.55e-07 | 1.85e-02 | 7.73e-06 | 0.00e+00 |
| 11 | 0.125 | 0.3071 | 1.29 | 30.7 | 42.917 | 6.09e-08 | 8.46e-02 | 1.39e-05 | 0.00e+00 |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| | Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| | Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| | Description: Moist, olive clay with sand | | |
| | Remarks: System W, Swell Pressure = 0.0675 tsf | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Square Root of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Sq.Rt. T90 min | Cv ft²/s | Mv 1/tsf | k ft/day |
|---|---|---|---|---|---|---|---|---|
| 1 | 0.0675 | 0.001166 | 2.30 | 0.117 | 48.912 | 5.01e-07 | 1.73e-02 | 2.33e-05 |
| 2 | 0.125 | 0.004898 | 2.29 | 0.490 | 8.899 | 2.74e-06 | 6.49e-02 | 4.80e-04 |
| 3 | 0.250 | 0.01441 | 2.26 | 1.44 | 4.112 | 5.85e-06 | 7.61e-02 | 1.20e-03 |
| 4 | 0.500 | 0.03951 | 2.17 | 3.95 | 8.449 | 2.75e-06 | 1.00e-01 | 7.44e-04 |
| 5 | 1.00 | 0.09292 | 2.00 | 9.29 | 37.237 | 5.75e-07 | 1.07e-01 | 1.66e-04 |
| 6 | 2.00 | 0.2160 | 1.59 | 21.6 | 52.562 | 3.34e-07 | 1.23e-01 | 1.11e-04 |
| 7 | 4.00 | 0.3117 | 1.27 | 31.2 | 37.716 | 3.53e-07 | 4.78e-02 | 4.55e-05 |
| 8 | 8.00 | 0.3866 | 1.03 | 38.7 | 25.023 | 4.15e-07 | 1.87e-02 | 2.10e-05 |
| 9 | 2.00 | 0.3666 | 1.09 | 36.7 | 19.766 | 4.82e-07 | 3.33e-03 | 4.33e-06 |
| 10 | 0.500 | 0.3388 | 1.18 | 33.9 | 58.196 | 1.77e-07 | 1.85e-02 | 8.83e-06 |
| 11 | 0.125 | 0.3071 | 1.29 | 30.7 | 188.851 | 5.96e-08 | 8.46e-02 | 1.36e-05 |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-3 | Tested By: md | Checked By: mcm |
| Sample No.: UD-2 | Test Date: 8/19/16 | Depth: 27.0-29.0 ft |
| Test No.: IP-1 | Sample Type: intact | Elevation: --- |
| Description: Moist, olive clay with sand | | |
| Remarks: System W, Swell Pressure = 0.0675 tsf | | |
| Displacement at End of Increment | | |

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | --- | Sample Type: | --- | Tested By: | GA |
| Sample ID: | --- | Test Date: | 10/31/16 | Checked By: | mcm |
| Depth : | --- | Test Id: | 397035 | | |


# Moisture Content of Soil and Rock - ASTM D2216

| Boring ID | Sample ID | Depth | Description | Moisture Content,% |
|---|---|---|---|---|
| AP-4 | UD-1 | 38.0-40.0 ft | Moist, very dark greenish gray clay with sand | 69.0 |

Notes: Temperature of Drying : 110º Celsius

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-4 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-1 | Test Date: | 10/31/16 | Checked By: | mcm |
| Depth : | 38.0-40.0 ft | Test Id: | 397033 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, very dark greenish gray clay with sand | | | | |
| Sample Comment: | --- | | | | |

# Particle Size Analysis - ASTM D422




| % Cobble | % Gravel | % Sand | % Silt & Clay Size |
|---|---|---|---|
| — | 0.0 | 28.7 | 71.3 |

| Sieve Name | Sieve Size, mm | Percent Finer | Spec. Percent | Complies |
|---|---|---|---|---|
| #4 | 4.75 | 100 | | |
| #10 | 2.00 | 100 | | |
| #20 | 0.85 | 100 | | |
| #40 | 0.42 | 100 | | |
| #60 | 0.25 | 100 | | |
| #100 | 0.15 | 98 | | |
| #200 | 0.075 | 71 | | |
| | | | | |
| | | | | |

**Coefficients**

| | |
|---|---|
| $D_{85}$ =0.1068 mm | $D_{30}$ =N/A |
| $D_{60}$ =N/A | $D_{15}$ =N/A |
| $D_{50}$ =N/A | $D_{10}$ =N/A |
| $C_u$ =N/A | $C_c$ =N/A |

**Classification**

ASTM Fat clay with sand (CH)

AASHTO Clayey Soils (A-7-6 (34))


**Sample/Test Description**

Sand/Gravel Particle Shape : ---

Sand/Gravel Hardness : ---

| | | | | | |
|---|---|---|---|---|---|
| Client: | F&ME Consultants | | | | |
| Project: | US-21 Replacement Bridge over Harbor River | | | | |
| Location: | --- | | | Project No: | GTX-305005 |
| Boring ID: | AP-4 | Sample Type: | tube | Tested By: | GA |
| Sample ID: | UD-1 | Test Date: | 10/31/16 | Checked By: | mcm |
| Depth : | 38.0-40.0 ft | Test Id: | 397034 | | |
| Test Comment: | --- | | | | |
| Visual Description: | Moist, very dark greenish gray clay with sand | | | | |
| Sample Comment: | --- | | | | |

# Atterberg Limits - ASTM D4318




| Symbol | Sample ID | Boring | Depth | Natural Moisture Content,% | Liquid Limit | Plastic Limit | Plasticity Index | Liquidity Index | Soil Classification |
|---|---|---|---|---|---|---|---|---|---|
| ◆ | UD-1 | AP-4 | 38.0-40.0 ft | 69 | 71 | 24 | 47 | 1 | Fat clay with sand (CH) |

Sample Prepared using the WET method
0% Retained on #40 Sieve
Dry Strength: HIGH
Dilatancy: SLOW
Toughness: LOW

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1281 | **DATE SAMPLE RECEIVED:** | 8/8/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 8/19/2016 |
| | | **DATE OF WEIGHING:** | 8/22/2016 |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | AP-4/UD-2 | AP-4/UD-3 | | | |
| **SAMPLE NO.** | 16-1281E | 16-1281H | | | |
| **SAMPLE DEPTH** | 40.0-42.0' | 70.0-72.0' | | | |
| **WATER CONTENT, W%** | 33.8 | 58.8 | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **AP-4** | **42.0** | **Silty SAND (SM) A-2-4** | **NP** | **NP** | **NP** | | |
| ⊠ | **AP-4** | **72.0** | **Sandy SILT (ML) A-4(0)** | **NP** | **NP** | **NP** | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **AP-4** | **42.0** | **9.52** | **0.574** | **0.168** | | **0.2** | **78.4** | **21.5** | |
| ⊠ | **AP-4** | **72.0** | **4.76** | **0.172** | | | **0.0** | **48.0** | **52.0** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/18/16

# ATTERBERG LIMITS' RESULTS


**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort





| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **AP-4** | **42.0** | **NP** | **NP** | **NP** | **21** | **Silty SAND (SM) A-2-4** |
| ⊠ | **AP-4** | **72.0** | **NP** | **NP** | **NP** | **52** | **Sandy SILT (ML) A-4(0)** |

# TRIAXIAL SHEAR TEST REPORT
## ASTM D4767 / AASHTO T297




## Stress-Strain Curves




| | | Sample 1 | Sample 2 | Sample 3 |
|---|---|---|---|---|
| Initial | Water Content, % | 33.8% | 33.8% | 33.8% |
| | Void Ratio | 1.13 | 1.40 | 0.88 |
| | Diameter, in. | 2.84 | 2.84 | 2.85 |
| | Height, in. | 5.74 | 5.84 | 5.87 |
| | Volume, $in^3$ | 36.47 | 36.94 | 37.35 |
| Final | Water Content, % | 59.5% | 53.8% | 33.8% |
| | Void Ratio | 1.56 | 1.40 | 0.90 |
| | Diameter, in. | 2.84 | 2.84 | 2.85 |
| | Height, in. | 5.66 | 5.72 | 5.79 |
| | Volume, $in^3$ | 35.95 | 36.19 | 36.84 |
| | Saturation, % | 100.0% | 100.0% | 100.0% |
| | Dry Density, PCF | 64.9 | 69.1 | 87.0 |
| | Cell Pressure (ksf) | 5.76 | 6.48 | 7.20 |
| | Sample Pressure (ksf) | 5.04 | 5.04 | 5.04 |
| | Stress at Failure (ksf) | 1.87 | 2.67 | 2.47 |
| | Strain at Failure, % | 4.4% | 1.9% | 2.6% |
| | $\sigma_1$ at Failure (ksf) | 2.59 | 4.11 | 4.63 |
| | $\sigma_3$ at Failure (ksf) | 0.72 | 1.44 | 2.16 |
| | $\sigma'_1$ at Failure (ksf) | 1.91 | 2.77 | 2.92 |
| | $\sigma'_3$ at Failure (ksf) | 0.04 | 0.10 | 0.45 |

Project Name: US 21 Bridge Replacement over Harbor River

Project Number: G5396 Date: 9/1/2016

SCDOT Project ID: P026862

Location/Sample: AP-4/UD-2 / Sample #16-1281A

Depth/Elevation: 40.0' - 42.0'

Type of Test : Consolidated Undrained

Sample Type : Undisturbed - Shelby Tube

Description: Dark Grey Silty Fine to Medium SAND (SM), A-2-4

PI= NP % Fines= 21.5

C= 0.59 ksf C'= 0.59 ksf


$\phi$= 13° $\phi'$= 24°

F&ME CONSULTANTS


3112 Devine Street Columbia, SC 29205

Geotechnical · Environmental · Materials

# TRIAXIAL SHEAR TEST REPORT
## ASTM D4767 / AASHTO T297




## Stress-Strain Curves




| | | Sample 1 | Sample 2 | Sample 3 |
|---|---|---|---|---|
| Initial | Water Content, % | 58.8% | 58.8% | 58.8% |
| | Void Ratio | 1.75 | 1.49 | 1.51 |
| | Diameter, in. | 2.87 | 2.87 | 2.86 |
| | Height, in. | 5.86 | 5.90 | 5.90 |
| | Volume, $in^3$ | 37.81 | 38.26 | 37.79 |
| Final | Water Content, % | 57.0% | 52.0% | 56.6% |
| | Void Ratio | 1.61 | 1.36 | 1.45 |
| | Diameter, in. | 2.87 | 2.87 | 2.86 |
| | Height, in. | 5.47 | 5.79 | 5.82 |
| | Volume, $in^3$ | 35.31 | 37.56 | 37.31 |
| | Saturation, % | 93.9% | 100.0% | 100.0% |
| | Dry Density, PCF | 63.5 | 70.3 | 67.7 |
| | Cell Pressure (ksf) | 7.20 | 7.92 | 8.64 |
| | Sample Pressure (ksf) | 5.04 | 5.04 | 5.04 |
| | Stress at Failure (ksf) | 1.67 | 7.16 | 10.06 |
| | Strain at Failure, % | 3.6% | 4.2% | 2.9% |
| | $\sigma_1$ at Failure (ksf) | 3.83 | 10.04 | 13.66 |
| | $\sigma_3$ at Failure (ksf) | 2.16 | 2.88 | 3.60 |
| | $\sigma'_1$ at Failure (ksf) | 2.23 | 7.40 | 10.46 |
| | $\sigma'_3$ at Failure (ksf) | 0.56 | 0.24 | 0.40 |

| | |
|---|---|
| Project Name | US 21 Bridge Replacement over Harbor River |
| Project Number | G5396 |
| Date | 9/8/2016 |
| SCDOT Project ID | P026862 |
| Location/Sample | AP-4/UD-3 / Sample #16-1281B |
| Depth/Elevation | 70.0' - 72.0' |


Type of Test : Consolidated Undrained
Sample Type : Undisturbed - Shelby Tube
Description: Dark Grey Fine Sandy SILT (ML), A-4(0)

PI= NP  % Fines= 52.0
C= 0  C'= --
$\phi$= 34°  $\phi$'= --

F&ME CONSULTANTS
3112 Devine Street Columbia, SC 29205
Geotechnical · Environmental · Materials

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Summary Report






| | | | | Before Test | After Test |
|---|---|---|---|---|---|
| Current Vertical Effective Stress: --- | | | | Water Content, % | 76.63 | 57.24 |
| Preconsolidation Stress: --- | | | | Dry Unit Weight, pcf | 53.798 | 66.486 |
| Compression Ratio: --- | | | | Saturation, % | 96.53 | 100.00 |
| Diameter: 2.5 in | | Height: 1 in | | Void Ratio | 2.17 | 1.56 |
| LL: --- | PL: --- | PI: --- | GS: 2.73 | | | |

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| | Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| | Description: Moist, very dark greenish gray clay with sand | | |
| | Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |
| | Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 1 of 11
Constant Volume Step
Stress: 0.0682 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| | Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| | Description: Moist, very dark greenish gray clay with sand | | |
| | Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 2 of 11
Constant Load Step
Stress: 0.125 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| Description: Moist, very dark greenish gray clay with sand | | |
| Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 3 of 11
Constant Load Step
Stress: 0.25 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| Description: Moist, very dark greenish gray clay with sand | | |
| Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 4 of 11
Constant Load Step
Stress: 0.5 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| Description: Moist, very dark greenish gray clay with sand | | |
| Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 5 of 11
Constant Load Step
Stress: 1 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| Description: Moist, very dark greenish gray clay with sand | | |
| Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 6 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| Description: Moist, very dark greenish gray clay with sand | | |
| Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 7 of 11
Constant Load Step
Stress: 4 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| Description: Moist, very dark greenish gray clay with sand | | |
| Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 8 of 11
Constant Load Step
Stress: 8 tsf









| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| | Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| | Description: Moist, very dark greenish gray clay with sand | | |
| | Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 9 of 11
Constant Load Step
Stress: 2 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| Description: Moist, very dark greenish gray clay with sand | | |
| Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 10 of 11
Constant Load Step
Stress: 0.5 tsf









| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| Description: Moist, very dark greenish gray clay with sand | | |
| Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

Time Curve 11 of 11
Constant Load Step
Stress: 0.125 tsf




| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| Description: Moist, very dark greenish gray clay with sand | | |
| Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

| | | |
|---|---|---|
| Specimen Diameter: 2.50 in | Estimated Specific Gravity: 2.73 | Liquid Limit: --- |
| Initial Height: 1.00 in | Initial Void Ratio: 2.17 | Plastic Limit: --- |
| Final Height: 0.81 in | Final Void Ratio: 1.56 | Plasticity Index: --- |

| | Before Test Trimmings | Before Test Specimen | After Test Specimen | After Test Trimmings |
|---|---|---|---|---|
| Container ID | a31 | RING | a34 | a34 |
| Mass Container, gm | 16.39 | 17.08 | 17.08 | 17.08 |
| Mass Container + Wet Soil, gm | 92.25 | 139.52 | 126.08 | 126.08 |
| Mass Container + Dry Soil, gm | 61.37 | 86.4 | 86.4 | 86.4 |
| Mass Dry Soil, gm | 44.98 | 69.32 | 69.32 | 69.32 |
| Water Content, % | 68.65 | 76.63 | 57.24 | 57.24 |
| Void Ratio | --- | 2.17 | 1.56 | --- |
| Degree of Saturation, % | --- | 96.53 | 100.00 | --- |
| Dry Unit Weight, pcf | --- | 53.798 | 66.486 | --- |

Note: Specific Gravity and Void Ratios are calculated assuming the degree of saturation equals 100% at the end of the test. Therefore, values may not represent actual values for the specimen.

| | | | |
|---|---|---|---|
| GeoTesting EXPRESS | Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| | Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| | Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| | Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| | Description: Moist, very dark greenish gray clay with sand | | |
| | Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Log of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Log T50 min | Cv ft²/s | Mv 1/tsf | k cm/s | Ca % |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.0682 | 0.002345 | 2.16 | 0.235 | 0.000 | 0.00e+00 | 3.44e-02 | 0.00e+00 | 0.00e+00 |
| 2 | 0.125 | 0.004319 | 2.15 | 0.432 | 0.000 | 0.00e+00 | 3.47e-02 | 0.00e+00 | 0.00e+00 |
| 3 | 0.250 | 0.01344 | 2.12 | 1.34 | 7.623 | 7.35e-07 | 7.30e-02 | 5.10e-08 | 0.00e+00 |
| 4 | 0.500 | 0.02224 | 2.10 | 2.22 | 4.343 | 1.27e-06 | 3.52e-02 | 4.24e-08 | 0.00e+00 |
| 5 | 1.00 | 0.03278 | 2.06 | 3.28 | 1.756 | 3.07e-06 | 2.11e-02 | 6.16e-08 | 0.00e+00 |
| 6 | 2.00 | 0.05810 | 1.98 | 5.81 | 0.000 | 0.00e+00 | 2.53e-02 | 0.00e+00 | 0.00e+00 |
| 7 | 4.00 | 0.1686 | 1.63 | 16.9 | 0.000 | 0.00e+00 | 5.52e-02 | 0.00e+00 | 0.00e+00 |
| 8 | 8.00 | 0.2721 | 1.30 | 27.2 | 13.862 | 2.50e-07 | 2.59e-02 | 6.16e-09 | 0.00e+00 |
| 9 | 2.00 | 0.2535 | 1.36 | 25.3 | 0.000 | 0.00e+00 | 3.11e-03 | 0.00e+00 | 0.00e+00 |
| 10 | 0.500 | 0.2226 | 1.46 | 22.3 | 0.000 | 0.00e+00 | 2.06e-02 | 0.00e+00 | 0.00e+00 |
| 11 | 0.125 | 0.1908 | 1.56 | 19.1 | 0.000 | 0.00e+00 | 8.47e-02 | 0.00e+00 | 0.00e+00 |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| Description: Moist, very dark greenish gray clay with sand | | |
| Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |
| Displacement at End of Increment | | |

# One-Dimensional Consolidation by ASTM D2435 - Method B

## Square Root of Time Coefficients

| Step | Applied Stress tsf | Final Displacement in | Void Ratio | Strain at End % | Sq.Rt. T90 min | Cv ft²/s | Mv 1/tsf | k cm/s |
|---|---|---|---|---|---|---|---|---|
| 1 | 0.0682 | 0.002345 | 2.16 | 0.235 | 156.469 | 1.56e-07 | 3.44e-02 | 5.12e-09 |
| 2 | 0.125 | 0.004319 | 2.15 | 0.432 | 93.234 | 2.61e-07 | 3.47e-02 | 8.64e-09 |
| 3 | 0.250 | 0.01344 | 2.12 | 1.34 | 20.743 | 1.16e-06 | 7.30e-02 | 8.07e-08 |
| 4 | 0.500 | 0.02224 | 2.10 | 2.22 | 17.290 | 1.37e-06 | 3.52e-02 | 4.58e-08 |
| 5 | 1.00 | 0.03278 | 2.06 | 3.28 | 5.957 | 3.90e-06 | 2.11e-02 | 7.81e-08 |
| 6 | 2.00 | 0.05810 | 1.98 | 5.81 | 23.280 | 9.60e-07 | 2.53e-02 | 2.31e-08 |
| 7 | 4.00 | 0.1686 | 1.63 | 16.9 | 53.337 | 3.62e-07 | 5.52e-02 | 1.90e-08 |
| 8 | 8.00 | 0.2721 | 1.30 | 27.2 | 49.954 | 2.99e-07 | 2.59e-02 | 7.35e-09 |
| 9 | 2.00 | 0.2535 | 1.36 | 25.3 | 14.786 | 9.02e-07 | 3.11e-03 | 2.67e-09 |
| 10 | 0.500 | 0.2226 | 1.46 | 22.3 | 40.501 | 3.52e-07 | 2.06e-02 | 6.89e-09 |
| 11 | 0.125 | 0.1908 | 1.56 | 19.1 | 182.068 | 8.48e-08 | 8.47e-02 | 6.83e-09 |

GeoTesting EXPRESS

| | | |
|---|---|---|
| Project: US-21 Replacement Bridge | Location: --- | Project No.: GTX-305005 |
| Boring No.: AP-4 | Tested By: jm | Checked By: mcm |
| Sample No.: UD-1 | Test Date: 10/3/16 | Depth: 38-40 ft |
| Test No.: IP-7 | Sample Type: intact | Elevation: --- |
| Description: Moist, very dark greenish gray clay with sand | | |
| Remarks: System 5077 Swell Pressure = 0.0682 tsf | | |
| Displacement at End of Increment | | |

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1282 | **DATE SAMPLE RECEIVED:** | 8/29/2016 |
| **DESCRIPTION OF SOIL:** | VARIOUS | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 8/29/2016 |
| | | **DATE OF WEIGHING:** | 9/1/2016 |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | AP-5/UD-1 & UD-2 | AP-5/UD-4 | | | |
| **SAMPLE NO.** | 16-1282E | 16-1282H | | | |
| **SAMPLE DEPTH** | 6.0-10.0' | 30.0-32.0' | | | |
| **WATER CONTENT, W%** | 21.6 | 26.6 | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **AP-5** | **10.0** | **Poorly Graded Fine SAND (SP) A-3** | **NP** | **NP** | **NP** | **1.42** | **1.88** |
| ⊠ | **AP-5** | **32.0** | **Poorly Graded Fine SAND (SP) A-3** | **NP** | **NP** | **NP** | **1.39** | **1.91** |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **AP-5** | **10.0** | **2** | **0.394** | **0.168** | **0.094** | **0.0** | **97.0** | **3.0** | |
| ⊠ | **AP-5** | **32.0** | **2** | **0.363** | **0.162** | **0.089** | **0.0** | **97.1** | **2.9** | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 11/4/16

# ATTERBERG LIMITS' RESULTS


**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River


**PROJECT COUNTY** Beaufort




| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **AP-5** | **10.0** | **NP** | **NP** | **NP** | **3** | **Poorly Graded Fine SAND (SP) A-3** |
| ⊠ | **AP-5** | **32.0** | **NP** | **NP** | **NP** | **3** | **Poorly Graded Fine SAND (SP) A-3** |

# DIRECT SHEAR TEST REPORT
## ASTM - D3080 / AASHTO T236




| Sample 1 | |
|---|---|
| Normal Stress (psi) | 12.5 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 23.6% |
| Wet Density (pcf) | 121.0 |
| Dry Density (pcf) | 97.9 |
| t50 (min.) | 0.2 |
| Saturation (%) | 90.9% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 3.33 |
| 0.010 | 5.26 |
| 0.015 | 6.68 |
| 0.020 | 7.86 |
| 0.030 | 9.56 |
| 0.040 | 10.71 |
| 0.050 | 11.58 |
| 0.060 | 12.15 |
| 0.070 | 12.47 |
| 0.080 | 12.59 |
| 0.090 | 12.71 |
| 0.100 | 12.74 |
| 0.125 | 11.98 |
| 0.150 | 10.46 |
| 0.175 | 9.57 |
| 0.200 | 9.27 |
| 0.225 | 9.14 |
| 0.250 | 8.95 |
| 0.300 | 8.86 |
| 0.350 | 8.90 |
| 0.400 | 8.83 |
| Max Shear Stress | **12.75** |

| Sample 2 | |
|---|---|
| Normal Stress (psi) | 16.7 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 24.4% |
| Wet Density (pcf) | 122.0 |
| Dry Density (pcf) | 98.1 |
| t50 (min) | 0.2 |
| Saturation (%) | 94.2% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 3.38 |
| 0.010 | 6.12 |
| 0.015 | 8.12 |
| 0.020 | 9.63 |
| 0.030 | 11.79 |
| 0.040 | 13.12 |
| 0.050 | 14.03 |
| 0.060 | 14.49 |
| 0.070 | 14.81 |
| 0.080 | 14.93 |
| 0.090 | 14.91 |
| 0.100 | 14.88 |
| 0.125 | 14.13 |
| 0.150 | 13.06 |
| 0.175 | 12.48 |
| 0.200 | 12.13 |
| 0.225 | 11.92 |
| 0.250 | 11.64 |
| 0.300 | 11.61 |
| 0.350 | 11.48 |
| 0.400 | 11.25 |
| Max Shear Stress | **14.93** |

| Sample 3 | |
|---|---|
| Normal Stress (psi) | 20.8 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 24.3% |
| Wet Density (pcf) | 122.2 |
| Dry Density (pcf) | 98.3 |
| t50 (min.) | 0.2 |
| Saturation (%) | 94.4% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 0.96 |
| 0.010 | 4.22 |
| 0.015 | 6.77 |
| 0.020 | 8.66 |
| 0.030 | 11.48 |
| 0.040 | 13.54 |
| 0.050 | 14.98 |
| 0.060 | 16.09 |
| 0.070 | 16.96 |
| 0.080 | 17.49 |
| 0.090 | 17.77 |
| 0.100 | 17.90 |
| 0.125 | 17.71 |
| 0.150 | 17.19 |
| 0.175 | 16.30 |
| 0.200 | 14.97 |
| 0.225 | 13.85 |
| 0.250 | 13.43 |
| 0.300 | 13.29 |
| 0.350 | 13.22 |
| 0.400 | 13.25 |
| Max Shear Stress | **17.97** |

Project Name: US 21 Bridge Replacement over Harbor River

Project Number: G5396 Date: 9/8/16

SCDOT Project ID: P026862

Location/Sample: AP-5, UD-1 & UD-2 / Sample #16-1282A

Depth/Elevation: 6.0' - 10.0'

Type of Test : Direct Shear - 4" by 4" Square Shear Box

Sample Type : Remolded 1" Thick, Innundated

Description: Grey Poorly Graded Fine SAND with Silt (SP-SM), A-3

PI= NP % Fines= 3.0

SG= 2.65 Box Gap= 1.0 mm


$\phi$= 32.1° $C_{apparent}$= 4.74 psi



F&ME CONSULTANTS

3112 Devine Street Columbia, SC 29205

Geotechnical · Environmental · Materials

# DIRECT SHEAR TEST REPORT
## ASTM - D3080 / AASHTO T236




| Sample 1 | |
|---|---|
| Normal Stress (psi) | 12.5 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 23.3% |
| Wet Density (pcf) | 119.0 |
| Dry Density (pcf) | 96.5 |
| t50 (min.) | 0.2 |
| Saturation (%) | 86.6% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 2.35 |
| 0.010 | 3.13 |
| 0.015 | 3.77 |
| 0.020 | 4.22 |
| 0.030 | 5.09 |
| 0.040 | 5.91 |
| 0.050 | 6.64 |
| 0.060 | 7.27 |
| 0.070 | 7.83 |
| 0.080 | 8.27 |
| 0.090 | 8.61 |
| 0.100 | 8.91 |
| 0.125 | 9.38 |
| 0.150 | 9.66 |
| 0.175 | 9.79 |
| 0.200 | 9.84 |
| 0.225 | 9.71 |
| 0.250 | 9.41 |
| 0.300 | 9.08 |
| 0.350 | 8.89 |
| 0.400 | 8.88 |
| Max Shear Stress | **9.84** |

| Sample 2 | |
|---|---|
| Normal Stress (psi) | 16.7 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 23.0% |
| Wet Density (pcf) | 118.6 |
| Dry Density (pcf) | 96.4 |
| t50 (min) | 0.2 |
| Saturation (%) | 85.3% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 2.43 |
| 0.010 | 3.84 |
| 0.015 | 4.83 |
| 0.020 | 5.64 |
| 0.030 | 6.84 |
| 0.040 | 7.87 |
| 0.050 | 8.73 |
| 0.060 | 9.43 |
| 0.070 | 10.04 |
| 0.080 | 10.50 |
| 0.090 | 10.83 |
| 0.100 | 11.12 |
| 0.125 | 11.64 |
| 0.150 | 11.95 |
| 0.175 | 12.13 |
| 0.200 | 12.26 |
| 0.225 | 12.29 |
| 0.250 | 12.16 |
| 0.300 | 11.68 |
| 0.350 | 11.44 |
| 0.400 | 11.47 |
| Max Shear Stress | **12.31** |

| Sample 3 | |
|---|---|
| Normal Stress (psi) | 20.8 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 22.8% |
| Wet Density (pcf) | 119.6 |
| Dry Density (pcf) | 97.4 |
| t50 (min.) | 0.2 |
| Saturation (%) | 86.6% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 2.63 |
| 0.010 | 3.94 |
| 0.015 | 4.88 |
| 0.020 | 5.74 |
| 0.030 | 7.31 |
| 0.040 | 8.56 |
| 0.050 | 9.57 |
| 0.060 | 10.41 |
| 0.070 | 11.10 |
| 0.080 | 11.71 |
| 0.090 | 12.18 |
| 0.100 | 12.54 |
| 0.125 | 13.16 |
| 0.150 | 13.60 |
| 0.175 | 13.85 |
| 0.200 | 14.01 |
| 0.225 | 14.09 |
| 0.250 | 14.18 |
| 0.300 | 14.23 |
| 0.350 | 14.11 |
| 0.400 | 13.92 |
| Max Shear Stress | **14.24** |

| | |
|---|---|
| Project Name | US 21 Bridge Replacement over Harbor River |
| Project Number | G5396 |
| Date | 9/21/16 |
| SCDOT Project ID | P026862 |
| Location/Sample | AP-5, UD-4 / Sample #16-1282B |
| Depth/Elevation | 30.0' - 32.0' |

Type of Test : Direct Shear - 4" by 4" Square Shear Box
Sample Type : Remolded 1" Thick, Innundated

| | | | |
|---|---|---|---|
| Description: | Grey Poorly Graded Fine SAND with Silt (SP-SM), A-3 | | |
| PI= | NP | % Fines= | 2.9 |
| SG= | 2.65 | Box Gap= | 1.0 mm |
| ϕ= | 27.9° | $C_{apparent}$= | 3.29 psi |

F&ME CONSULTANTS
3112 Devine Street Columbia, SC 29205
Geotechnical · Environmental · Materials

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1189 | **DATE SAMPLE RECEIVED:** | 7/19/2016 |
| **DESCRIPTION OF SOIL:** | Poorly Graded F/M SAND (SP-SM) with Silt A-3 | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 7/25/2016 |
| | | **DATE OF WEIGHING:** | 7/26/2016 |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | BS-1 | | | | |
| **SAMPLE NO.** | 16-1189C | | | | |
| **SAMPLE DEPTH** | 0.0-5.0' | | | | |
| **WATER CONTENT, W%** | 5.3 | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **BS-1** | **5.0** | **Poorly Graded F/M SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **0.99** | **2.18** |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **BS-1** | **5.0** | **25.4** | **19.331** | **0.158** | **0.079** | **11.4** | **81.0** | **7.6** | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort





| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **BS-1** | **5.0** | **NP** | **NP** | **NP** | **8** | **Poorly Graded F/M SAND (SP-SM) with Silt A-3** |

# MOISTURE-DENSITY RELATIONSHIP

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | |
|---|---|
| Source of Material | **BS-1 5.0** |
| Description of Material | **Poorly Graded F/M SAND (SP-SM) with Silt A-3** |
| Test Method | **698A** |

TEST RESULTS

| | | |
|---|---|---|
| Maximum Dry Density | **100.3** | **PCF** |
| Optimum Water Content | **17.3** | **%** |

ATTERBERG LIMITS

| LL | PL | PI |
|---|---|---|
| **NP** | **NP** | **NP** |

Curves of 100% Saturation for Specific Gravity Equal to:


2.80


2.70

2.60

COMPACTION G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# DIRECT SHEAR TEST REPORT
## ASTM - D3080 / AASHTO T236




| Sample 1 | |
|---|---|
| Normal Stress (psi) | 12.5 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 19.0% |
| Wet Density (pcf) | 114.3 |
| Dry Density (pcf) | 96.0 |
| t50 (min.) | 0.2 |
| Saturation (%) | 69.8% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 2.94 |
| 0.010 | 4.93 |
| 0.015 | 6.73 |
| 0.020 | 7.92 |
| 0.030 | 9.75 |
| 0.040 | 10.91 |
| 0.050 | 11.75 |
| 0.060 | 12.31 |
| 0.070 | 12.70 |
| 0.080 | 12.95 |
| 0.090 | 13.13 |
| 0.100 | 13.22 |
| 0.125 | 13.11 |
| 0.150 | 12.40 |
| 0.175 | 10.97 |
| 0.200 | 10.64 |
| 0.225 | 10.51 |
| 0.250 | 10.37 |
| 0.300 | 10.23 |
| 0.350 | 10.12 |
| 0.400 | 10.06 |
| Max Shear Stress | **13.22** |

| Sample 2 | |
|---|---|
| Normal Stress (psi) | 16.7 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 19.3% |
| Wet Density (pcf) | 114.0 |
| Dry Density (pcf) | 95.6 |
| t50 (min) | 0.2 |
| Saturation (%) | 70.0% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 3.24 |
| 0.010 | 5.38 |
| 0.015 | 7.19 |
| 0.020 | 8.89 |
| 0.030 | 11.54 |
| 0.040 | 13.28 |
| 0.050 | 14.46 |
| 0.060 | 15.21 |
| 0.070 | 15.71 |
| 0.080 | 16.03 |
| 0.090 | 16.22 |
| 0.100 | 16.32 |
| 0.125 | 16.23 |
| 0.150 | 15.15 |
| 0.175 | 14.08 |
| 0.200 | 13.38 |
| 0.225 | 13.04 |
| 0.250 | 12.88 |
| 0.300 | 12.78 |
| 0.350 | 12.54 |
| 0.400 | 12.29 |
| Max Shear Stress | **16.34** |

| Sample 3 | |
|---|---|
| Normal Stress (psi) | 20.8 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 18.9% |
| Wet Density (pcf) | 114.8 |
| Dry Density (pcf) | 96.5 |
| t50 (min.) | 0.2 |
| Saturation (%) | 70.2% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 4.73 |
| 0.010 | 7.23 |
| 0.015 | 9.00 |
| 0.020 | 10.43 |
| 0.030 | 12.89 |
| 0.040 | 14.64 |
| 0.050 | 16.09 |
| 0.060 | 17.07 |
| 0.070 | 17.78 |
| 0.080 | 18.25 |
| 0.090 | 18.57 |
| 0.100 | 18.77 |
| 0.125 | 18.87 |
| 0.150 | 18.59 |
| 0.175 | 17.70 |
| 0.200 | 16.76 |
| 0.225 | 16.12 |
| 0.250 | 15.82 |
| 0.300 | 15.58 |
| 0.350 | 15.35 |
| 0.400 | 15.25 |
| Max Shear Stress | **18.90** |

Project Name: US 21 Bridge Replacement over Harbor River

Project Number: G5396 Date: 8/3/2016

SCDOT Project ID: P026862

Location/Sample: BS-1 / Sample #16-1189

Depth/Elevation: 0.0' - 5.0'

Type of Test : Direct Shear - 4" by 4" Square Shear Box

Sample Type : Remolded 1" Thick, Non-Innundated

Description: Grey Poorly Graded Fine to Medium SAND with Silt (SP-SM), A-3

PI= NP % Fines= 7.6

SG= 2.65 Box Gap= 0.75mm

ϕ= 34.4° $C_{apparent}$= 4.74 psi

F&ME CONSULTANTS

3112 Devine Street Columbia, SC 29205

Geotechnical · Environmental · Materials

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1190 | **DATE SAMPLE RECEIVED:** | 7/19/2016 |
| **DESCRIPTION OF SOIL:** | Poorly Graded F/M SAND (SP-SM) with Silt A-3 | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 7/25/2016 |
| | | **DATE OF WEIGHING:** | 7/26/2016 |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | BS-2 | | | | |
| **SAMPLE NO.** | 16-1190C | | | | |
| **SAMPLE DEPTH** | 0.0-5.0' | | | | |
| **WATER CONTENT, W%** | 5.6 | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| | BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|---|
| ● | **BS-2** | **5.0** | **Poorly Graded F/M SAND (SP-SM) with Silt A-3** | **NP** | **NP** | **NP** | **1.02** | **2.19** |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |


| | BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|---|
| ● | **BS-2** | **5.0** | **19.1** | **5.143** | **0.157** | **0.078** | **5.4** | **86.2** | **8.3** | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort





| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **BS-2** | **5.0** | **NP** | **NP** | **NP** | **8** | **Poorly Graded F/M SAND (SP-SM) with Silt A-3** |

# MOISTURE-DENSITY RELATIONSHIP

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | |
|---|---|
| Source of Material | **BS-2 5.0** |
| Description of Material | **Poorly Graded F/M SAND (SP-SM) with Silt A-3** |
| Test Method | **698A** |

TEST RESULTS

| | | |
|---|---|---|
| Maximum Dry Density | **100.8** | **PCF** |
| Optimum Water Content | **16.6** | **%** |

ATTERBERG LIMITS

| LL | PL | PI |
|---|---|---|
| **NP** | **NP** | **NP** |

Curves of 100% Saturation for Specific Gravity Equal to:


2.80


2.70

2.60

COMPACTION G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# DIRECT SHEAR TEST REPORT
## ASTM - D3080 / AASHTO T236




| Sample 1 | |
|---|---|
| Normal Stress (psi) | 12.5 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 19.5% |
| Wet Density (pcf) | 115.2 |
| Dry Density (pcf) | 96.4 |
| t50 (min.) | 0.2 |
| Saturation (%) | 72.2% |

| Horizontal Displacement (in.) | Shear Stress (psi) |
|---|---|
| 0.000 | 0.00 |
| 0.005 | 3.34 |
| 0.010 | 4.94 |
| 0.015 | 6.00 |
| 0.020 | 6.88 |
| 0.030 | 8.32 |
| 0.040 | 9.34 |
| 0.050 | 10.09 |
| 0.060 | 10.61 |
| 0.070 | 11.01 |
| 0.080 | 11.30 |
| 0.090 | 11.49 |
| 0.100 | 11.57 |
| 0.125 | 11.54 |
| 0.150 | 11.12 |
| 0.175 | 10.46 |
| 0.200 | 10.00 |
| 0.225 | 9.68 |
| 0.250 | 9.42 |
| 0.300 | 9.18 |
| 0.350 | 9.06 |
| 0.400 | 8.98 |
| Max Shear Stress | **11.61** |

| Sample 2 | |
|---|---|
| Normal Stress (psi) | 16.7 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 18.9% |
| Wet Density (pcf) | 114.3 |
| Dry Density (pcf) | 96.2 |
| t50 (min) | 0.2 |
| Saturation (%) | 69.5% |

| Horizontal Displacement (in.) | Shear Stress (psi) |
|---|---|
| 0.000 | 0.00 |
| 0.005 | 3.67 |
| 0.010 | 5.74 |
| 0.015 | 7.08 |
| 0.020 | 8.16 |
| 0.030 | 9.91 |
| 0.040 | 11.34 |
| 0.050 | 12.40 |
| 0.060 | 13.10 |
| 0.070 | 13.60 |
| 0.080 | 13.91 |
| 0.090 | 14.12 |
| 0.100 | 14.23 |
| 0.125 | 14.14 |
| 0.150 | 13.73 |
| 0.175 | 13.23 |
| 0.200 | 12.93 |
| 0.225 | 12.74 |
| 0.250 | 12.65 |
| 0.300 | 12.44 |
| 0.350 | 12.16 |
| 0.400 | 11.90 |
| Max Shear Stress | **14.24** |

| Sample 3 | |
|---|---|
| Normal Stress (psi) | 20.8 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 18.6% |
| Wet Density (pcf) | 114.3 |
| Dry Density (pcf) | 96.4 |
| t50 (min.) | 0.2 |
| Saturation (%) | 68.9% |

| Horizontal Displacement (in.) | Shear Stress (psi) |
|---|---|
| 0.000 | 0.00 |
| 0.005 | 4.35 |
| 0.010 | 7.14 |
| 0.015 | 8.89 |
| 0.020 | 10.36 |
| 0.030 | 12.65 |
| 0.040 | 14.14 |
| 0.050 | 15.20 |
| 0.060 | 15.89 |
| 0.070 | 16.34 |
| 0.080 | 16.61 |
| 0.090 | 16.79 |
| 0.100 | 16.89 |
| 0.125 | 16.70 |
| 0.150 | 16.09 |
| 0.175 | 15.24 |
| 0.200 | 14.17 |
| 0.225 | 13.55 |
| 0.250 | 13.37 |
| 0.300 | 13.34 |
| 0.350 | 13.28 |
| 0.400 | 13.13 |
| Max Shear Stress | **16.91** |

Project Name: US 21 Bridge Replacement over Harbor River

Project Number: G5396 Date: 8/12/16

SCDOT Project ID: P026862

Location/Sample: BS-2 / Sample #16-1190

Depth/Elevation: 0.0' - 5.0'

Type of Test : Direct Shear - 4" by 4" Square Shear Box

Sample Type : Remolded 1" Thick, Non-Innundated

Description: Grey Poorly Graded Fine to Medium SAND with Silt (SP-SM), A-3

PI= NP

SG= 2.65

$\phi$= 32.6°

% Fines= 8.3

Box Gap= 1.0 mm

$C_{apparent}$= 3.61 psi

F&ME CONSULTANTS

3112 Devine Street Columbia, SC 29205

Geotechnical · Environmental · Materials

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1191 | **DATE SAMPLE RECEIVED:** | 7/19/2016 |
| **DESCRIPTION OF SOIL:** | Poorly Graded F/M SAND (SP) A-3 | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 7/25/2016 |
| | | **DATE OF WEIGHING:** | 7/26/2016 |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | BS-3 | | | | |
| **SAMPLE NO.** | 16-1191C | | | | |
| **SAMPLE DEPTH** | 0.0-5.0' | | | | |
| **WATER CONTENT, W%** | 1.3 | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|
| ● **BS-3** | **5.0** | **Poorly Graded F/M SAND (SP) A-3** | **NP** | **NP** | **NP** | **0.80** | **1.57** |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |


| BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|
| ● **BS-3** | **5.0** | **9.52** | **0.393** | **0.203** | **0.15** | **0.1** | **98.2** | **1.7** | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort





| BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|
| ● **BS-3** | **5.0** | **NP** | **NP** | **NP** | **2** | **Poorly Graded F/M SAND (SP) A-3** |

# MOISTURE-DENSITY RELATIONSHIP

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | |
|---|---|
| Source of Material | **BS-3 5.0** |
| Description of Material | **Poorly Graded F/M SAND (SP)** |
| | **A-3** |
| Test Method | **698A** |

TEST RESULTS

| | |
|---|---|
| Maximum Dry Density | **97.8 PCF** |
| Optimum Water Content | **18.1 %** |

ATTERBERG LIMITS

| LL | PL | PI |
|---|---|---|
| **NP** | **NP** | **NP** |

Curves of 100% Saturation for Specific Gravity Equal to:


2.80


2.70

2.60

COMPACTION G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# DIRECT SHEAR TEST REPORT
## ASTM - D3080 / AASHTO T236




| Sample 1 | |
|---|---|
| Normal Stress (psi) | 12.5 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 17.6% |
| Wet Density (pcf) | 112.5 |
| Dry Density (pcf) | 95.7 |
| t50 (min.) | 0.2 |
| Saturation (%) | 64.0% |

| Horizontal Displacement (in.) | Shear Stress (psi) |
|---|---|
| 0.000 | 0.00 |
| 0.005 | 0.98 |
| 0.010 | 1.93 |
| 0.015 | 2.88 |
| 0.020 | 3.83 |
| 0.030 | 5.35 |
| 0.040 | 6.38 |
| 0.050 | 7.68 |
| 0.060 | 8.76 |
| 0.070 | 9.63 |
| 0.080 | 10.31 |
| 0.090 | 10.87 |
| 0.100 | 11.38 |
| 0.125 | 12.08 |
| 0.150 | 12.39 |
| 0.175 | 12.24 |
| 0.200 | 11.68 |
| 0.225 | 11.04 |
| 0.250 | 10.59 |
| 0.300 | 10.14 |
| 0.350 | 9.89 |
| 0.400 | 9.64 |
| Max Shear Stress | **12.41** |

| Sample 2 | |
|---|---|
| Normal Stress (psi) | 16.7 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 17.5% |
| Wet Density (pcf) | 111.6 |
| Dry Density (pcf) | 95.0 |
| t50 (min) | 0.2 |
| Saturation (%) | 62.6% |

| Horizontal Displacement (in.) | Shear Stress (psi) |
|---|---|
| 0.000 | 0.00 |
| 0.005 | 1.03 |
| 0.010 | 2.11 |
| 0.015 | 3.27 |
| 0.020 | 4.25 |
| 0.030 | 6.56 |
| 0.040 | 8.35 |
| 0.050 | 10.40 |
| 0.060 | 11.91 |
| 0.070 | 13.03 |
| 0.080 | 13.85 |
| 0.090 | 14.45 |
| 0.100 | 14.93 |
| 0.125 | 15.54 |
| 0.150 | 15.63 |
| 0.175 | 15.22 |
| 0.200 | 14.24 |
| 0.225 | 13.17 |
| 0.250 | 12.49 |
| 0.300 | 12.16 |
| 0.350 | 12.04 |
| 0.400 | 11.88 |
| Max Shear Stress | **15.64** |

| Sample 3 | |
|---|---|
| Normal Stress (psi) | 20.8 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 18.1% |
| Wet Density (pcf) | 112.5 |
| Dry Density (pcf) | 95.2 |
| t50 (min.) | 0.2 |
| Saturation (%) | 65.1% |

| Horizontal Displacement (in.) | Shear Stress (psi) |
|---|---|
| 0.000 | 0.00 |
| 0.005 | 1.09 |
| 0.010 | 2.48 |
| 0.015 | 3.71 |
| 0.020 | 4.81 |
| 0.030 | 7.17 |
| 0.040 | 9.55 |
| 0.050 | 11.50 |
| 0.060 | 13.05 |
| 0.070 | 14.34 |
| 0.080 | 15.40 |
| 0.090 | 16.20 |
| 0.100 | 16.84 |
| 0.125 | 17.66 |
| 0.150 | 17.85 |
| 0.175 | 17.44 |
| 0.200 | 16.74 |
| 0.225 | 15.60 |
| 0.250 | 14.68 |
| 0.300 | 14.02 |
| 0.350 | 13.83 |
| 0.400 | 13.72 |
| Max Shear Stress | **17.87** |

Project Name: US 21 Bridge Replacement over Harbor River

Project Number: G5396 Date: 8/31/16

SCDOT Project ID: P026862

Location/Sample: BS-3 / Sample #16-1191

Depth/Elevation: 0.0' - 5.0'

Type of Test : Direct Shear - 4" by 4" Square Shear Box

Sample Type : Remolded 1" Thick, Non-Innundated

Description: Grey Poorly Graded Fine to Medium SAND (SP), A-3

PI= NP % Fines= 1.7

SG= 2.65 Box Gap= 1.0 mm

$\phi$= 33.5° $C_{apparent}$= 4.34 psi

F&ME CONSULTANTS

3112 Devine Street Columbia, SC 29205

Geotechnical · Environmental · Materials

# F&ME CONSULTANTS
# 3112 Devine Street
# Columbia, South Carolina 29205

## MOISTURE CONTENT DETERMINATION
## (AASHTO T265)

| | | | |
|---|---|---|---|
| **PROJECT:** | US 21 Bridge Replacement over Harbor River | **PROJECT NO.:** | G5396 |
| **SAMPLE NUMBER:** | 16-1192 | **DATE SAMPLE RECEIVED:** | 7/19/2016 |
| **DESCRIPTION OF SOIL:** | Poorly Graded F/M SAND (SP) A-3 | | |
| **TESTED BY:** | MB | **DATE OF TESTING:** | 7/25/2016 |
| | | **DATE OF WEIGHING:** | 7/26/2016 |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | BS-4 | | | | |
| **SAMPLE NO.** | 16-1192C | | | | |
| **SAMPLE DEPTH** | 0.0-5.0' | | | | |
| **WATER CONTENT, W%** | 2.6 | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |


| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| **BORING NO.** | | | | | |
| **SAMPLE NO.** | | | | | |
| **SAMPLE DEPTH** | | | | | |
| **WATER CONTENT, W%** | | | | | |

# GRAIN SIZE DISTRIBUTION

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| COBBLES | GRAVEL | | SAND | | | SILT OR CLAY |
|---|---|---|---|---|---|---|
| | coarse | fine | coarse | medium | fine | |

| BOREHOLE | DEPTH | Classification | LL | PL | PI | Cc | Cu |
|---|---|---|---|---|---|---|---|
| ● **BS-4** | **5.0** | **Poorly Graded F/M SAND (SP) A-3** | **NP** | **NP** | **NP** | **0.98** | **1.72** |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |


| BOREHOLE | DEPTH | D100 | D95 | D50 | D10 | %Gravel | %Sand | %Silt | %Clay |
|---|---|---|---|---|---|---|---|---|---|
| ● **BS-4** | **5.0** | **9.52** | **0.4** | **0.181** | **0.125** | **0.6** | **96.6** | **2.9** | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

GRAIN SIZE G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# ATTERBERG LIMITS' RESULTS

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort





| | BOREHOLE | DEPTH | LL | PL | PI | Fines | Classification |
|---|---|---|---|---|---|---|---|
| ● | **BS-4** | **5.0** | **NP** | **NP** | **NP** | **3** | **Poorly Graded F/M SAND (SP) A-3** |

# MOISTURE-DENSITY RELATIONSHIP

**PROJECT ID** P026862 **PROJECT NAME** US 21 Bridge Replacement over Harbor River

**PROJECT COUNTY** Beaufort




| | |
|---|---|
| Source of Material | **BS-4 5.0** |
| Description of Material | **Poorly Graded F/M SAND (SP)** |
| | **A-3** |
| Test Method | **698A** |

TEST RESULTS

| | |
|---|---|
| Maximum Dry Density | **94.6 PCF** |
| Optimum Water Content | **15.8 %** |

ATTERBERG LIMITS

| LL | PL | PI |
|---|---|---|
| **NP** | **NP** | **NP** |

Curves of 100% Saturation for Specific Gravity Equal to:


2.80


2.70

2.60

COMPACTION G5396 - HARBOR RIVER SPT AND CPT.GPJ GINT STD US LAB.GDT 10/5/16

# DIRECT SHEAR TEST REPORT
## ASTM - D3080 / AASHTO T236




| Sample 1 | |
|---|---|
| Normal Stress (psi) | 12.5 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 16.8% |
| Wet Density (pcf) | 106.8 |
| Dry Density (pcf) | 91.5 |
| t50 (min.) | 0.2 |
| Saturation (%) | 55.1% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 0.99 |
| 0.010 | 1.94 |
| 0.015 | 2.89 |
| 0.020 | 3.81 |
| 0.030 | 5.74 |
| 0.040 | 6.94 |
| 0.050 | 7.94 |
| 0.060 | 8.92 |
| 0.070 | 9.74 |
| 0.080 | 10.45 |
| 0.090 | 10.98 |
| 0.100 | 11.40 |
| 0.125 | 11.97 |
| 0.150 | 12.20 |
| 0.175 | 12.19 |
| 0.200 | 11.77 |
| 0.225 | 11.22 |
| 0.250 | 10.72 |
| 0.300 | 10.33 |
| 0.350 | 9.84 |
| 0.400 | 9.45 |
| Max Shear Stress | **12.22** |

| Sample 2 | |
|---|---|
| Normal Stress (psi) | 16.7 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 16.6% |
| Wet Density (pcf) | 106.8 |
| Dry Density (pcf) | 91.6 |
| t50 (min) | 0.2 |
| Saturation (%) | 54.6% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 3.99 |
| 0.010 | 6.27 |
| 0.015 | 7.61 |
| 0.020 | 8.71 |
| 0.030 | 10.34 |
| 0.040 | 11.46 |
| 0.050 | 12.32 |
| 0.060 | 12.94 |
| 0.070 | 13.42 |
| 0.080 | 13.79 |
| 0.090 | 14.07 |
| 0.100 | 14.28 |
| 0.125 | 14.49 |
| 0.150 | 14.46 |
| 0.175 | 14.18 |
| 0.200 | 13.69 |
| 0.225 | 12.99 |
| 0.250 | 12.11 |
| 0.300 | 11.63 |
| 0.350 | 11.70 |
| 0.400 | 11.70 |
| Max Shear Stress | **14.51** |

| Sample 3 | |
|---|---|
| Normal Stress (psi) | 20.8 |
| Speed (in./min.) | 0.01 |
| Sample Width (in.) | 4.00 |
| Percent Moisture | 16.3% |
| Wet Density (pcf) | 108.0 |
| Dry Density (pcf) | 92.9 |
| t50 (min.) | 0.2 |
| Saturation (%) | 55.2% |
| Horizontal Displacement (in.) | Shear Stress (psi) |
| 0.000 | 0.00 |
| 0.005 | 4.47 |
| 0.010 | 7.29 |
| 0.015 | 9.08 |
| 0.020 | 10.59 |
| 0.030 | 12.59 |
| 0.040 | 14.03 |
| 0.050 | 15.07 |
| 0.060 | 15.80 |
| 0.070 | 16.30 |
| 0.080 | 16.65 |
| 0.090 | 16.88 |
| 0.100 | 17.06 |
| 0.125 | 17.20 |
| 0.150 | 17.11 |
| 0.175 | 16.81 |
| 0.200 | 15.99 |
| 0.225 | 15.36 |
| 0.250 | 15.15 |
| 0.300 | 14.89 |
| 0.350 | 14.11 |
| 0.400 | 13.81 |
| Max Shear Stress | **17.21** |

| | | | |
|---|---|---|---|
| Project Name | US 21 Bridge Replacement over Harbor River | | |
| Project Number | G5396 | Date | 9/1/16 |
| SCDOT Project ID | P026862 | | |
| Location/Sample | BS-4 / Sample #16-1192 | | |
| Depth/Elevation | 0.0' - 5.0' | | |

Type of Test : Direct Shear - 4" by 4" Square Shear Box
Sample Type : Remolded 1" Thick, Non-Innundated

| | | | |
|---|---|---|---|
| Description: | Grey Poorly Graded Fine to Medium SAND (SP), A-3 | | |
| PI= | NP | % Fines= | 2.9 |
| SG= | 2.65 | Box Gap= | 1.0 mm |
| ϕ= | 31.0° | $C_{apparent}$= | 4.63 psi |


F&ME CONSULTANTS
3112 Devine Street Columbia, SC 29205
Geotechnical · Environmental · Materials

| | |
|---|---|
| Client: | FME Consultants |
| Project Name: | US-21 Replacement Bridge over Harbor River |
| Project Location: | --- |
| GTX #: | 305005 |
| Test Date: | 8/23/2016 |
| Tested By: | jbr |
| Checked By: | emm |

# pH of Water by ASTM D1293

| Boring ID | Sample ID | Depth, ft | Description | pH of water | Temperature, °C |
|---|---|---|---|---|---|
| East End | 16-1283 | --- | Wet, clear water | 6.9 | 19 |
| West End | 16-1284 | --- | Wet, clear water | 6.8 | 19 |

Notes: Method B, pH meter used

| | |
|---|---|
| Client: | FME Consultants |
| Project: | US-21 Replacement Bridge over Harbor River |
| Location: | --- |
| GTX#: | 305005 |
| Test Date: | 09/01/16 |
| Tested By: | jbr |
| Checked By: | mcm |

# Laboratory Measurement of Soil Resistivity Using the Wenner Four-Electrode Method by ASTM G57 (Laboratory Measurement)

| Boring ID | Sample ID | Depth, ft. | Sample Description | Electrical Resistivity, ohm-cm | Electrical Conductivity, $(ohm\text{-}cm)^{-1}$ |
|---|---|---|---|---|---|
| East End | 16-1283 | --- | Wet, clear water | 26 | 3.87E-02 |
| West End | 16-1284 | --- | Wet, clear water | 27 | 3.72E-02 |

Notes: Test Equipment: Nilsson Model 400 Soil Resistance Meter, MC Miller Soil Box

Water added to sample to create a thick slurry prior to testing (saturated condition).

Electrical Conductivity is calculated as inverse of Electrical Resistivity (per ASTM G57)

Test conducted in standard laboratory atmosphere: 68-73 F

# FUGRO CONSULTANTS, INC.

6100 HILLCROFT
PHONE (713) 369-5400

HOUSTON, TEXAS 77081
FAX (713) 369-5518

## RESULTS OF TESTS

**PROJECT:** US-21 REPLACEMENT BRIDGE (GTX 305005)
SAMPLE ID: EAST END 16-1283

**FOR:** GEOTESTING EXPRESS, INC.
125 NAGOG PARK ACTION, MA 01720

**REPORTED TO:** ETHAN MARRO

**LAB NUMBER:** 0817030

**REPORT DATE:** 08-22-16
**CLIENT NUMBER:**
**JOB NUMBER:** 04.1115-0003
**REPORT NUMBER:**
**DATE SAMPLED:**
**TIME SAMPLED:**
**SAMPLED BY:** CLIENT
**DATE RECEIVED:**
**TIME RECEIVED:**
**RECEIVED BY:**

| PARAMETER | RESULTS | UNITS | METHOD | TIME/DATE | ANALYST |
|---|---|---|---|---|---|
| Sulfate, Soluble | 23,227 | mg/L | ASTM D-516 ** | 1400/08-19-16 | SD |
| Chloride, Soluble | 16,396 | mg/L | ASTM D-512 ** | 1100/08-22-16 | SD |

SO4CL 078-16

Respectfully submitted,

*** Dry weight basis**

Steve DeGregorio
Chemist

SD

**** WATER EXTRACTION PERFORMED BY USING A 1:10 RATIO OF SAMPLE AND REAGENT WATER FOLLOWED BY CENTRIFUGE AND VACUUME FILTRATION. THE WATER EXTRACT IS THEN ANALYZED USING THE ASTM D-512 AND D-516 METHODS.**

**THE RESULTS RELATE AS TO THE LOCATION TESTED AND NO OTHER REFERENCE SHALL BE MADE.
THIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE WRITTEN APPROVAL OF THE LABORATORY.**

**END OF REPORT**

# FUGRO CONSULTANTS, INC.

6100 HILLCROFT
PHONE (713) 369-5400

HOUSTON, TEXAS 77081
FAX (713) 369-5518

## RESULTS OF TESTS

**PROJECT:** US-21 REPLACEMENT BRIDGE (GTX 305005)
SAMPLE ID: WEST END 16-1284

**FOR:** GEOTESTING EXPRESS, INC.
125 NAGOG PARK ACTION, MA 01720

**REPORTED TO:** ETHAN MARRO

**LAB NUMBER:** 0817031

**REPORT DATE:** 08-22-16
**CLIENT NUMBER:**
**JOB NUMBER:** 04.1115-0003
**REPORT NUMBER:**
**DATE SAMPLED:**
**TIME SAMPLED:**
**SAMPLED BY:** CLIENT
**DATE RECEIVED:**
**TIME RECEIVED:**
**RECEIVED BY:**

| PARAMETER | RESULTS | UNITS | METHOD | TIME/DATE | ANALYST |
|---|---|---|---|---|---|
| Sulfate, Soluble | 22,715 | mg/L | ASTM D-516 ** | 1400/08-19-16 | SD |
| Chloride, Soluble | 16,596 | mg/L | ASTM D-512 ** | 1100/08-22-16 | SD |

SO4CL 078-16

Respectfully submitted,

* Dry weight basis

Steve DeGregorio
Chemist


SD

** WATER EXTRACTION PERFORMED BY USING A 1:10 RATIO OF SAMPLE AND REAGENT WATER FOLLOWED BY CENTRIFUGE AND VACUUME FILTRATION. THE WATER EXTRACT IS THEN ANALYZED USING THE ASTM D-512 AND D-516 METHODS.

THE RESULTS RELATE AS TO THE LOCATION TESTED AND NO OTHER REFERENCE SHALL BE MADE.
THIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE WRITTEN APPROVAL OF THE LABORATORY.

**END OF REPORT**

# APPENDIX C
## Soil Parameter Determination




Borings Included: B-1, B-3, B-4, and B-7


**West Embankment 1 (<59+00)**

**Harbor River Bridge**
**Harbor Island, South Carolina**

GeoEngineers

**Figure C-1**

18461-007-01




Borings Included: B-8, B-9


**West Embankment 2, 3, and 4**
**(59+00 to 70+40)**

**Harbor River Bridge**
**Harbor Island, South Carolina**

GeoEngineers

**Figure C-2**


18461-007-01




Borings Included: B-2, B-16

| East Embankment 1 and 2<br>(103+80 to 112+00) | |
|---|---|
| Harbor River Bridge<br>Harbor Island, South Carolina | |
| GeoEngineers | Figure C-3 |

18461-007-01




Borings Included: B-5, B-6


**East Embankment 3**
**(>112+00)**

**Harbor River Bridge**
**Harbor Island, South Carolina**

GeoEngineers

**Figure C-4**

18461-007-01




Borings Included: B-1, B-3, B-4, and B-7


**West Embankment 1 (<59+00)**

**Harbor River Bridge**
**Harbor Island, South Carolina**

GeoEngineers

**Figure C-5**

18461-007-01




Borings Included: B-8, B-9


**West Embankment 2, 3, and 4**
**(59+00 to 70+40)**

Harbor River Bridge
Harbor Island, South Carolina

GeoEngineers

**Figure C-6**


18461-007-01




Borings Included: B-2, B-16

| East Embankment 1 and 2<br>(103+80 to 112+00) | |
|---|---|
| Harbor River Bridge<br>Harbor Island, South Carolina | |
| GeoEngineers | Figure C-7 |

18461-007-01




Borings Included: B-5, B-6


**East Embankment 3**
**(>112+00)**

**Harbor River Bridge**
**Harbor Island, South Carolina**

GeoEngineers

**Figure C-8**

18461-007-01




Borings Included: B-1, B-3, B-4, and B-7


**West Embankment 1**
**(<59+00)**

**Harbor River Bridge**
**Harbor Island, South Carolina**

GeoEngineers

**Figure C-9**

18461-007-01




Borings Included: B-8, B-9


**West Embankment 2, 3, and 4**
**(59+00 to 70+40)**

Harbor River Bridge
Harbor Island, South Carolina

GeoEngineers

**Figure C-10**

18461-007-01




Borings Included: B-2, B-16


**East Embankment 1 and 2**
**(103+80 to 112+00)**

**Harbor River Bridge**
**Harbor Island, South Carolina**

GeoEngineers

**Figure C-11**

18461-007-01




Borings Included: B-5, B-6

**East Embankment 3**
**(>112+00)**

**Harbor River Bridge**
**Harbor Island, South Carolina**

GeoEngineers

**Figure C-12**

18461-007-01

# APPENDIX D
## Consolidation Analyses

Project: 18461-007-01
Author: IAH

Analysis: West Embankment 1
< 59+00

| | | |
|---|---|---|
| Cross Section | 57+99 | |
| Ground Surface Elevation | 10 | ft |
| Groundwater Elevation | 0 | ft |
| Embankment Height | 6.2 | ft |
| Embankment Total Unit Weight | 125 | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 775 | psf |
| Settlement | 1.2 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Silts/Clays | 12 | 95 | - | - | - | - | 12 | 6 | 0.03 | 97.3 | 570 | 754 | - | - |
| Silts/Clays | 0 | 32.6 | 0.557 | 0.072 | 0.035 | 2.375 | 5 | -2.5 | 0.10 | 91.7 | 1222 | 710 | 2901 | 0.07 |
| Silts/Clays | -5 | 32.6 | 0.557 | 0.072 | 0.035 | 2.125 | 2 | -6 | 0.13 | 89.3 | 1336 | 692 | 2838 | 0.03 |
| Sands | -7 | 37.6 | - | - | - | - | 43 | -28.5 | 0.32 | 74.3 | 2177 | 576 | - | - |
| Hawthorn Marl | -50 | 57.6 | - | - | - | - | 20 | -60 | 0.58 | 56.0 | 3561 | 434 | - | - |
| Cooper Group Limestone | -70 | 57.6 | - | - | - | - | 130 | -135 | 1.21 | 34.0 | 7881 | 264 | - | - |
| | -200 | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: West Embankment 2
59+00 to 69+65

| | | |
|---|---|---|
| Cross Section | 60+88 | |
| Ground Surface Elevation | 10 | ft |
| Groundwater Elevation | 0 | ft |
| Embankment Height | 8.2 | ft |
| Embankment Total Unit Weight | 125 | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 1025 | psf |
| Settlement | 2.1 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Silts/Clays | 10 | 95 | - | - | - | - | 10 | 5 | 0.04 | 96.7 | 475 | 991 | - | - |
| Silts/Clays | 0 | 32.6 | 0.359 | 0.047 | 0.035 | 2.375 | 5 | -2.5 | 0.10 | 91.7 | 1032 | 940 | 2450 | 0.07 |
| Silts/Clays | -5 | 32.6 | 0.359 | 0.047 | 0.035 | 2.125 | 5 | -7.5 | 0.15 | 88.3 | 1195 | 905 | 2538 | 0.06 |
| Silts/Clays | -10 | 32.6 | 0.359 | 0.047 | 0.035 | 1.875 | 5 | -12.5 | 0.19 | 85.0 | 1358 | 871 | 2545 | 0.05 |
| Sands (2) | -15 | 37.6 | - | - | - | - | 35 | -32.5 | 0.35 | 71.7 | 2097 | 735 | - | - |
| Hawthorn Marl | -50 | 57.6 | - | - | - | - | 20 | -60 | 0.58 | 56.0 | 3331 | 574 | - | - |
| Cooper Group Limestone | -70 | 57.6 | - | - | - | - | 130 | -135 | 1.21 | 34.0 | 7651 | 349 | - | - |
| | -200 | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: West Embankment 2
59+00 to 69+65

| | | |
|---|---|---|
| Cross Section | **65+00** | |
| Ground Surface Elevation | **3** | ft |
| Groundwater Elevation | **0** | ft |
| Embankment Height | **10.2** | ft |
| Embankment Total Unit Weight | **125** | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 1275 | psf |
| Settlement | 4.3 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Sands (1)** | **3** | **100** | **-** | **-** | **-** | **-** | 3 | 1.5 | 0.01 | 99.0 | 150 | 1262 | - | - |
| **Sands (1)** | **0** | **37.6** | **-** | **-** | **-** | **-** | 10 | -5 | 0.07 | 94.7 | 488 | 1207 | - | - |
| **Silts/Clays** | **-10** | **32.6** | **0.359** | **0.047** | **0.035** | **2.225** | 5 | -12.5 | 0.13 | 89.7 | 758 | 1143 | 1685 | 0.17 |
| **Silts/Clays** | **-15** | **32.6** | **0.359** | **0.047** | **0.035** | **1.975** | 7 | -18.5 | 0.18 | 85.7 | 953 | 1092 | 1882 | 0.19 |
| **Sands (2)** | **-22** | **37.6** | **-** | **-** | **-** | **-** | 28 | -36 | 0.33 | 74.0 | 1594 | 944 | - | - |
| **Hawthorn Marl** | **-50** | **57.6** | **-** | **-** | **-** | **-** | 22 | -61 | 0.53 | 58.4 | 2754 | 745 | - | - |
| **Cooper Group Limestone** | **-72** | **57.6** | **-** | **-** | **-** | **-** | 128 | -136 | 1.16 | 35.2 | 7074 | 449 | - | - |
| | **-200** | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: West Embankment 2
59+00 to 69+65

| | | |
|---|---|---|
| Cross Section | 67+04 | |
| Ground Surface Elevation | 3 | ft |
| Groundwater Elevation | 0 | ft |
| Embankment Height | 11.2 | ft |
| Embankment Total Unit Weight | 125 | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 1400 | psf |
| Settlement | 22.2 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Sands (1) | 3 | 100 | - | - | - | - | 3 | 1.5 | 0.01 | 99.0 | 150 | 1386 | - | - |
| Sands (1) | 0 | 37.6 | - | - | - | - | 5 | -2.5 | 0.05 | 96.3 | 394 | 1349 | - | - |
| Silts/Clays | -5 | 32.6 | 0.359 | 0.047 | 0.035 | 2.500 | 5 | -7.5 | 0.09 | 93.0 | 570 | 1302 | 1424 | 0.31 |
| Silts/Clays | -10 | 32.6 | 0.359 | 0.047 | 0.035 | 2.250 | 5 | -12.5 | 0.13 | 89.7 | 733 | 1255 | 1648 | 0.23 |
| Silts/Clays | -15 | 32.6 | 0.359 | 0.047 | 0.035 | 2.000 | 5 | -17.5 | 0.17 | 86.3 | 896 | 1209 | 1791 | 0.20 |
| Silts/Clays | -20 | 32.6 | 0.359 | 0.047 | 0.035 | 1.750 | 5 | -22.5 | 0.21 | 83.0 | 1059 | 1162 | 1852 | 0.20 |
| Silts/Clays | -25 | 32.6 | 0.359 | 0.047 | 0.035 | 1.500 | 5 | -27.5 | 0.25 | 79.7 | 1222 | 1115 | 1832 | 0.23 |
| Silts/Clays | -30 | 32.6 | 0.359 | 0.047 | 0.035 | 1.250 | 5 | -32.5 | 0.30 | 76.3 | 1385 | 1069 | 1731 | 0.29 |
| Silts/Clays | -35 | 32.6 | 0.359 | 0.047 | 0.035 | 1.000 | 5 | -37.5 | 0.34 | 73.0 | 1548 | 1022 | 1548 | 0.40 |
| Sands (2) | -40 | 37.6 | - | - | - | - | 8 | -44 | 0.39 | 68.7 | 1779 | 961 | - | - |
| Hawthorn Marl | -48 | 57.6 | - | - | - | - | 24 | -60 | 0.53 | 58.8 | 2621 | 823 | - | - |
| Cooper Group Limestone | -72 | 57.6 | - | - | - | - | 128 | -136 | 1.16 | 35.2 | 6999 | 493 | - | - |
| | -200 | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: East Embankment 2
104+55 to 112+00

| | | |
|---|---|---|
| Cross Section | **105+97** | |
| Ground Surface Elevation | **3** | ft |
| Groundwater Elevation | **0** | ft |
| Embankment Height | **14.2** | ft |
| Embankment Total Unit Weight | **125** | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 1775 | psf |
| Settlement | 7.5 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Sands (1)** | **3** | **100** | **-** | **-** | **-** | **-** | 5 | 0.5 | 0.02 | 98.3 | 250 | 1745 | - | - |
| **Sands (2)** | **-2** | **57.6** | **-** | **-** | **-** | **-** | 13 | -8.5 | 0.10 | 92.3 | 874 | 1639 | - | - |
| **Sands (3)** | **-15** | **37.6** | **-** | **-** | **-** | **-** | 30 | -30 | 0.28 | 78.0 | 1813 | 1385 | - | - |
| **Silts/Clays** | **-45** | **32.6** | **0.386** | **0.050** | **0.035** | **1.000** | 5 | -47.5 | 0.42 | 66.3 | 2458 | 1177 | 2458 | 0.33 |
| **Silts/Clays** | **-50** | **32.6** | **0.386** | **0.050** | **0.035** | **1.000** | 5 | -52.5 | 0.46 | 63.0 | 2621 | 1118 | 2621 | 0.30 |
| **Sands (4)** | **-55** | **37.6** | **-** | **-** | **-** | **-** | 10 | -60 | 0.53 | 58.8 | 2891 | 1044 | - | - |
| **Hawthorn Marl** | **-65** | **57.6** | **-** | **-** | **-** | **-** | 12 | -71 | 0.62 | 54.4 | 3424 | 966 | - | - |
| **Cooper Group Limestone** | **-77** | **57.6** | **-** | **-** | **-** | **-** | 123 | -138.5 | 1.18 | 34.7 | 7312 | 616 | - | - |
| | **-200** | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: East Embankment 2
104+55 to 112+00

| | | |
|---|---|---|
| Cross Section | **109+84** | |
| Ground Surface Elevation | **3** | ft |
| Groundwater Elevation | **0** | ft |
| Embankment Height | **11.2** | ft |
| Embankment Total Unit Weight | **125** | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 1400 | psf |
| Settlement | 6.1 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Sands (1)** | **3** | **100** | **-** | **-** | **-** | **-** | 5 | 0.5 | 0.02 | 98.3 | 250 | 1377 | - | - |
| **Sands (2)** | **-2** | **57.6** | **-** | **-** | **-** | **-** | 13 | -8.5 | 0.10 | 92.3 | 874 | 1293 | - | - |
| **Sands (3)** | **-15** | **37.6** | **-** | **-** | **-** | **-** | 30 | -30 | 0.28 | 78.0 | 1813 | 1092 | - | - |
| **Silts/Clays** | **-45** | **32.6** | **0.386** | **0.050** | **0.035** | **1.000** | 10 | -50 | 0.44 | 64.7 | 2540 | 905 | 2540 | 0.51 |
| **Sands (4)** | **-55** | **37.6** | **-** | **-** | **-** | **-** | 10 | -60 | 0.53 | 58.8 | 2891 | 823 | - | - |
| **Hawthorn Marl** | **-65** | **57.6** | **-** | **-** | **-** | **-** | 12 | -71 | 0.62 | 54.4 | 3424 | 762 | - | - |
| **Cooper Group Limestone** | **-77** | **57.6** | **-** | **-** | **-** | **-** | 123 | -138.5 | 1.18 | 34.7 | 7312 | 486 | - | - |
| | **-200** | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: East Embankment 3
>112+00

| | | |
|---|---|---|
| Cross Section | **116+48** | |
| Ground Surface Elevation | **10** | ft |
| Groundwater Elevation | **0** | ft |
| Embankment Height | **10.2** | ft |
| Embankment Total Unit Weight | **125** | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 1275 | psf |
| Settlement | 1.1 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Sands (1)** | **10** | **100** | **-** | **-** | **-** | **-** | 13 | 3.5 | 0.05 | 95.7 | 650 | 1220 | - | - |
| **Sands (2)** | **-3** | **57.6** | **-** | **-** | **-** | **-** | 7 | -6.5 | 0.14 | 89.0 | 1502 | 1135 | - | - |
| **Silts/Clays (1)** | **-10** | **32.6** | **0.386** | **0.050** | **0.035** | **2.250** | 5 | -12.5 | 0.19 | 85.0 | 1785 | 1084 | 4016 | 0.05 |
| **Sands (3)** | **-15** | **57.6** | **-** | **-** | **-** | **-** | 8 | -19 | 0.24 | 80.7 | 2097 | 1029 | - | - |
| **Silts/Clays (2)** | **-23** | **32.6** | **0.386** | **0.050** | **0.035** | **1.500** | 5 | -25.5 | 0.30 | 76.3 | 2409 | 973 | 3613 | 0.04 |
| **Sands (4)** | **-28** | **37.6** | **-** | **-** | **-** | **-** | 28 | -42 | 0.43 | 65.3 | 3016 | 833 | - | - |
| **Hawthorn Marl** | **-56** | **57.6** | **-** | **-** | **-** | **-** | 21 | -66.5 | 0.64 | 53.4 | 4148 | 681 | - | - |
| **Cooper Group Limestone** | **-77** | **57.6** | **-** | **-** | **-** | **-** | 123 | -138.5 | 1.24 | 33.3 | 8295 | 425 | - | - |
| | **-200** | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: West Embankment 1
< 59+00

| | | |
|---|---|---|
| Cross Section | 57+99 | |
| Ground Surface Elevation | 10 | ft |
| Groundwater Elevation | 0 | ft |
| Embankment Height | 5.4 | ft |
| Embankment Total Unit Weight | 125 | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 675 | psf |
| Settlement | 1.1 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Silts/Clays | 12 | 95 | - | - | - | - | 12 | 6 | 0.03 | 97.3 | 570 | 657 | - | - |
| Silts/Clays | 0 | 32.6 | 0.557 | 0.072 | 0.035 | 2.375 | 5 | -2.5 | 0.10 | 91.7 | 1222 | 619 | 2901 | 0.06 |
| Silts/Clays | -5 | 32.6 | 0.557 | 0.072 | 0.035 | 2.125 | 2 | -6 | 0.13 | 89.3 | 1336 | 603 | 2838 | 0.02 |
| Sands | -7 | 37.6 | - | - | - | - | 43 | -28.5 | 0.32 | 74.3 | 2177 | 502 | - | - |
| Hawthorn Marl | -50 | 57.6 | - | - | - | - | 20 | -60 | 0.58 | 56.0 | 3561 | 378 | - | - |
| Cooper Group Limestone | -70 | 57.6 | - | - | - | - | 130 | -135 | 1.21 | 34.0 | 7881 | 230 | - | - |
| | -200 | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: West Embankment 2
59+00 to 69+65

| | | |
|---|---|---|
| Cross Section | **60+88** | |
| Ground Surface Elevation | **10** | ft |
| Groundwater Elevation | **0** | ft |
| Embankment Height | **7.4** | ft |
| Embankment Total Unit Weight | **125** | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 925 | psf |
| Settlement | 1.9 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Silts/Clays** | **10** | **95** | **-** | **-** | **-** | **-** | 10 | 5 | 0.04 | 96.7 | 475 | 894 | - | - |
| **Silts/Clays** | **0** | **32.6** | **0.359** | **0.047** | **0.035** | **2.375** | 5 | -2.5 | 0.10 | 91.7 | 1032 | 848 | 2450 | 0.06 |
| **Silts/Clays** | **-5** | **32.6** | **0.359** | **0.047** | **0.035** | **2.125** | 5 | -7.5 | 0.15 | 88.3 | 1195 | 817 | 2538 | 0.05 |
| **Silts/Clays** | **-10** | **32.6** | **0.359** | **0.047** | **0.035** | **1.875** | 5 | -12.5 | 0.19 | 85.0 | 1358 | 786 | 2545 | 0.05 |
| **Sands (2)** | **-15** | **37.6** | **-** | **-** | **-** | **-** | 35 | -32.5 | 0.35 | 71.7 | 2097 | 663 | - | - |
| **Hawthorn Marl** | **-50** | **57.6** | **-** | **-** | **-** | **-** | 20 | -60 | 0.58 | 56.0 | 3331 | 518 | - | - |
| **Cooper Group Limestone** | **-70** | **57.6** | **-** | **-** | **-** | **-** | 130 | -135 | 1.21 | 34.0 | 7651 | 315 | - | - |
| | **-200** | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: West Embankment 2
59+00 to 69+65

| | | |
|---|---|---|
| Cross Section | **65+00** | |
| Ground Surface Elevation | **3** | ft |
| Groundwater Elevation | **0** | ft |
| Embankment Height | **9.4** | ft |
| Embankment Total Unit Weight | **125** | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 1175 | psf |
| Settlement | 2.3 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Sands (1)** | **3** | **100** | **-** | **-** | **-** | **-** | 3 | 1.5 | 0.01 | 99.0 | 150 | 1163 | 1462 | - |
| **Sands (1)** | **0** | **37.6** | **-** | **-** | **-** | **-** | 10 | -5 | 0.07 | 94.7 | 488 | 1112 | 1742 | - |
| **Silts/Clays** | **-10** | **32.6** | **0.359** | **0.047** | **0.035** | **2.225** | 5 | -12.5 | 0.13 | 89.7 | 758 | 1054 | 1946 | 0.09 |
| **Silts/Clays** | **-15** | **32.6** | **0.359** | **0.047** | **0.035** | **1.975** | 7 | -18.5 | 0.18 | 85.7 | 953 | 1007 | 2088 | 0.10 |
| **Sands (2)** | **-22** | **37.6** | **-** | **-** | **-** | **-** | 28 | -36 | 0.33 | 74.0 | 1594 | 870 | 2574 | - |
| **Hawthorn Marl** | **-50** | **57.6** | **-** | **-** | **-** | **-** | 22 | -61 | 0.53 | 58.4 | 2754 | 686 | 3527 | - |
| **Cooper Group Limestone** | **-72** | **57.6** | **-** | **-** | **-** | **-** | 128 | -136 | 1.16 | 35.2 | 7074 | 414 | 5370 | - |
| | **-200** | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: West Embankment 2
59+00 to 69+65

| | | |
|---|---|---|
| Cross Section | 67+04 | |
| Ground Surface Elevation | 3 | ft |
| Groundwater Elevation | 0 | ft |
| Embankment Height | 10.4 | ft |
| Embankment Total Unit Weight | 125 | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 1300 | psf |
| Settlement | 6.4 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Sands (1) | 3 | 100 | - | - | - | - | 3 | 1.5 | 0.01 | 99.0 | 150 | 1287 | 1759 | - |
| Sands (1) | 0 | 37.6 | - | - | - | - | 5 | -2.5 | 0.05 | 96.3 | 394 | 1252 | 1959 | - |
| Silts/Clays | -5 | 32.6 | 0.359 | 0.047 | 0.035 | 2.500 | 5 | -7.5 | 0.09 | 93.0 | 570 | 1209 | 2081 | 0.12 |
| Silts/Clays | -10 | 32.6 | 0.359 | 0.047 | 0.035 | 2.250 | 5 | -12.5 | 0.13 | 89.7 | 733 | 1166 | 2190 | 0.10 |
| Silts/Clays | -15 | 32.6 | 0.359 | 0.047 | 0.035 | 2.000 | 5 | -17.5 | 0.17 | 86.3 | 896 | 1122 | 2298 | 0.08 |
| Silts/Clays | -20 | 32.6 | 0.359 | 0.047 | 0.035 | 1.750 | 5 | -22.5 | 0.21 | 83.0 | 1059 | 1079 | 2407 | 0.07 |
| Silts/Clays | -25 | 32.6 | 0.359 | 0.047 | 0.035 | 1.500 | 5 | -27.5 | 0.25 | 79.7 | 1222 | 1036 | 2516 | 0.06 |
| Silts/Clays | -30 | 32.6 | 0.359 | 0.047 | 0.035 | 1.250 | 5 | -32.5 | 0.30 | 76.3 | 1385 | 992 | 2625 | 0.05 |
| Silts/Clays | -35 | 32.6 | 0.359 | 0.047 | 0.035 | 1.000 | 5 | -37.5 | 0.34 | 73.0 | 1548 | 949 | 2734 | 0.05 |
| Sands (2) | -40 | 37.6 | - | - | - | - | 8 | -44 | 0.39 | 68.7 | 1779 | 893 | 2895 | - |
| Hawthorn Marl | -48 | 57.6 | - | - | - | - | 24 | -60 | 0.53 | 58.8 | 2621 | 764 | 3577 | - |
| Cooper Group Limestone | -72 | 57.6 | - | - | - | - | 128 | -136 | 1.16 | 35.2 | 6999 | 458 | 5431 | - |
| | -200 | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: East Embankment 2
104+55 to 112+00

| | | |
|---|---|---|
| Cross Section | 105+97 | |
| Ground Surface Elevation | 3 | ft |
| Groundwater Elevation | 0 | ft |
| Embankment Height | 13.4 | ft |
| Embankment Total Unit Weight | 125 | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 1675 | psf |
| Settlement | 0.9 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Sands (1) | 3 | 100 | - | - | - | - | 5 | 0.5 | 0.02 | 98.3 | 250 | 1647 | 2069 | - |
| Sands (2) | -2 | 57.6 | - | - | - | - | 13 | -8.5 | 0.10 | 92.3 | 874 | 1547 | 2583 | - |
| Sands (3) | -15 | 37.6 | - | - | - | - | 30 | -30 | 0.28 | 78.0 | 1813 | 1307 | 3256 | - |
| Silts/Clays | -45 | 32.6 | 0.386 | 0.050 | 0.035 | 1.000 | 5 | -47.5 | 0.42 | 66.3 | 2458 | 1111 | 3685 | 0.04 |
| Silts/Clays | -50 | 32.6 | 0.386 | 0.050 | 0.035 | 1.000 | 5 | -52.5 | 0.46 | 63.0 | 2621 | 1055 | 3787 | 0.04 |
| Sands (4) | -55 | 37.6 | - | - | - | - | 10 | -60 | 0.53 | 58.8 | 2891 | 985 | 3979 | - |
| Hawthorn Marl | -65 | 57.6 | - | - | - | - | 12 | -71 | 0.62 | 54.4 | 3424 | 911 | 4431 | - |
| Cooper Group Limestone | -77 | 57.6 | - | - | - | - | 123 | -138.5 | 1.18 | 34.7 | 7312 | 581 | 5833 | - |
| | -200 | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: East Embankment 2
104+55 to 112+00

| | | |
|---|---|---|
| Cross Section | 109+84 | |
| Ground Surface Elevation | 3 | ft |
| Groundwater Elevation | 0 | ft |
| Embankment Height | 10.4 | ft |
| Embankment Total Unit Weight | 125 | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 1300 | psf |
| Settlement | 0.7 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Sands (1) | 3 | 100 | - | - | - | - | 5 | 0.5 | 0.02 | 98.3 | 250 | 1278 | 1688 | - |
| Sands (2) | -2 | 57.6 | - | - | - | - | 13 | -8.5 | 0.10 | 92.3 | 874 | 1200 | 2225 | - |
| Sands (3) | -15 | 37.6 | - | - | - | - | 30 | -30 | 0.28 | 78.0 | 1813 | 1014 | 2954 | - |
| Silts/Clays | -45 | 32.6 | 0.386 | 0.050 | 0.035 | 1.000 | 10 | -50 | 0.44 | 64.7 | 2540 | 841 | 3486 | 0.06 |
| Sands (4) | -55 | 37.6 | - | - | - | - | 10 | -60 | 0.53 | 58.8 | 2891 | 764 | 3751 | - |
| Hawthorn Marl | -65 | 57.6 | - | - | - | - | 12 | -71 | 0.62 | 54.4 | 3424 | 707 | 4220 | - |
| Cooper Group Limestone | -77 | 57.6 | - | - | - | - | 123 | -138.5 | 1.18 | 34.7 | 7312 | 451 | 5660 | - |
| | -200 | | | | | | | | | | | | | |

Project: 18461-007-01
Author: IAH

Analysis: East Embankment 3
>112+00

| | | |
|---|---|---|
| Cross Section | **116+48** | |
| Ground Surface Elevation | **10** | ft |
| Groundwater Elevation | **0** | ft |
| Embankment Height | **9.4** | ft |
| Embankment Total Unit Weight | **125** | pcf |
| Embankment Design Width | 120 | ft |
| Load applied by Embankment | 1175 | psf |
| Settlement | 1.0 | in |

σ'v0 Δσv σ'p

| Material | Layer Top Elv. (ft) | Unit Weight (pcf) | Cce | Cre | Cv (ft^2/day) | OCR | Layer Thickness (ft) | Layer Center Elevation (ft) | z/B | Percent Vertical Stress | Effective Overburden Stress @ Center of Layer (psf) | Increase in Vertical Effective Stress (psf) | Preconsolidation Stress (psf) | Settlement of Layer (ft) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Sands (1)** | **10** | **100** | **-** | **-** | **-** | **-** | 13 | 3.5 | 0.05 | 95.7 | 650 | 1124 | - | - |
| **Sands (2)** | **-3** | **57.6** | **-** | **-** | **-** | **-** | 7 | -6.5 | 0.14 | 89.0 | 1502 | 1046 | - | - |
| **Silts/Clays (1)** | **-10** | **32.6** | **0.386** | **0.050** | **0.035** | **2.250** | 5 | -12.5 | 0.19 | 85.0 | 1785 | 999 | 4016 | 0.05 |
| **Sands (3)** | **-15** | **57.6** | **-** | **-** | **-** | **-** | 8 | -19 | 0.24 | 80.7 | 2097 | 948 | - | - |
| **Silts/Clays (2)** | **-23** | **32.6** | **0.386** | **0.050** | **0.035** | **1.500** | 5 | -25.5 | 0.30 | 76.3 | 2409 | 897 | 3613 | 0.03 |
| **Sands (4)** | **-28** | **37.6** | **-** | **-** | **-** | **-** | 28 | -42 | 0.43 | 65.3 | 3016 | 768 | - | - |
| **Hawthorn Marl** | **-56** | **57.6** | **-** | **-** | **-** | **-** | 21 | -66.5 | 0.64 | 53.4 | 4148 | 627 | - | - |
| **Cooper Group Limestone** | **-77** | **57.6** | **-** | **-** | **-** | **-** | 123 | -138.5 | 1.24 | 33.3 | 8295 | 391 | - | - |
| | **-200** | | | | | | | | | | | | | |

# APPENDIX E
## Soil Liquefaction Analyses

# 1. Static

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Yoon Seok Choi
Last Edited By: Heidi Cashman
Revision Number: 109
Date: 9/28/2017
Time: 2:14:51 PM
Tool Version: 8.16.1.13452
File Name: 1) Station 59_00.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 1. Static

Description: Static Case
Kind: SLOPE/W
Method: Morgenstern-Price
Settings
- Side Function
  - Interslice force function option: Half-Sine
- PWP Conditions Source: Piezometric Line
- Apply Phreatic Correction: No
- Use Staged Rapid Drawdown: No

Slip Surface
- Direction of movement: Right to Left
- Use Passive Mode: No
- Slip Surface Option: Entry and Exit
- Critical slip surfaces saved: 1
- Resisting Side Maximum Convex Angle: 1 °
- Driving Side Maximum Convex Angle: 5 °
- Optimize Critical Slip Surface Location: No

Tension Crack
Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 10 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.46
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

## Sands

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 29 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Hawthorn Marl

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 4,000 psf
Pore Water Pressure
Piezometric Line: 1

## Cooper Group Limestone

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 6,000 psf
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-91, 3) ft
Left-Zone Right Coordinate: (-41, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-23, 12) ft
Right-Zone Right Coordinate: (21, 12) ft
Right-Zone Increment: 9
Radius Increments: 4

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

## Piezometric Lines

### Piezometric Line 1

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

## Reinforcements

### Reinforcement 1

Type: Geosynthetic
Outside Point: (-41, 3) ft
Inside Point: (-6, 12) ft
Length: 36.138622 ft
Direction: 194.42 °
F of S Dependent: Yes
Pullout Resistance: 350 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: Yes
Tensile Capacity: 33,980 lbs

Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 350 lbs/ft
Max. Pullout Force: 12,648.518 lbs
Factored Tensile Capacity: 33,980 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -41 | 3 |
| Point 2 | -23 | 12 |
| Point 3 | 21 | 12 |
| Point 4 | 46 | 3 |
| Point 5 | -20 | 3 |
| Point 6 | 35 | 3 |
| Point 7 | -250 | 3 |
| Point 8 | 250 | 3 |
| Point 9 | 250 | -10 |
| Point 10 | -250 | -10 |
| Point 11 | 250 | -50 |
| Point 12 | -250 | -50 |
| Point 13 | 250 | -70 |
| Point 14 | -250 | -70 |
| Point 15 | 250 | -100 |
| Point 16 | -250 | -100 |
| Point 17 | -15 | 16 |
| Point 18 | 13 | 16 |
| Point 19 | 0 | 3 |
| Point 20 | 124 | 3 |
| Point 21 | 60 | 3 |
| Point 22 | -6 | 12 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Silts/Clays | 7,10,9,8,20,21,4,6,19,5,1 | 6,500 |
| Region 2 | Sands | 10,9,11,12 | 20,000 |
| Region 3 | Hawthorn Marl | 12,11,13,14 | 10,000 |
| Region 4 | Cooper Group Limestone | 14,13,15,16 | 15,000 |
| Region 5 | | 2,17,18,3,22 | 144 |
| Region 6 | Compacted Fill | 1,22,2 | 76.5 |
| Region 7 | Silts/Clays | 5,19,6,4,21,3,22,1 | 576 |

# 2. Static - Trafic

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Yoon Seok Choi
Last Edited By: Heidi Cashman
Revision Number: 109
Date: 9/28/2017
Time: 2:14:51 PM
Tool Version: 8.16.1.13452
File Name: 1) Station 59_00.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 2. Static - Trafic

Description: Static Case
Kind: SLOPE/W
Method: Morgenstern-Price
Settings
- Side Function
  - Interslice force function option: Half-Sine
- PWP Conditions Source: Piezometric Line
- Apply Phreatic Correction: No
- Use Staged Rapid Drawdown: No

Slip Surface
- Direction of movement: Right to Left
- Use Passive Mode: No
- Slip Surface Option: Entry and Exit
- Critical slip surfaces saved: 1
- Resisting Side Maximum Convex Angle: 1 °
- Driving Side Maximum Convex Angle: 5 °
- Optimize Critical Slip Surface Location: No

Tension Crack
Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 2 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.46
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

## Sands

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 29 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Hawthorn Marl

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 4,000 psf
Pore Water Pressure
Piezometric Line: 1

## Cooper Group Limestone

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 6,000 psf
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-91, 3) ft
Left-Zone Right Coordinate: (-41, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-23, 12) ft
Right-Zone Right Coordinate: (21, 12) ft
Right-Zone Increment: 9
Radius Increments: 4

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

## Piezometric Lines

### Piezometric Line 1

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

## Surcharge Loads

### Surcharge Load 1

Surcharge (Unit Weight): 400 pcf
Direction: Vertical

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| | -23 | 12 |
| | -23 | 13 |
| | 21 | 13 |

# Reinforcements

## Reinforcement 1

Type: Geosynthetic
Outside Point: (-41, 3) ft
Inside Point: (-6, 12) ft
Length: 36.138622 ft
Direction: 194.42 °
F of S Dependent: Yes
Pullout Resistance: 350 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: Yes
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 350 lbs/ft
Max. Pullout Force: 12,648.518 lbs
Factored Tensile Capacity: 33,980 lbs

# Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -41 | 3 |
| Point 2 | -23 | 12 |
| Point 3 | 21 | 12 |
| Point 4 | 46 | 3 |
| Point 5 | -20 | 3 |
| Point 6 | 35 | 3 |
| Point 7 | -250 | 3 |
| Point 8 | 250 | 3 |
| Point 9 | 250 | -10 |
| Point 10 | -250 | -10 |
| Point 11 | 250 | -50 |
| Point 12 | -250 | -50 |
| Point 13 | 250 | -70 |
| Point 14 | -250 | -70 |
| Point 15 | 250 | -100 |
| Point 16 | -250 | -100 |
| Point 17 | -15 | 16 |
| Point 18 | 13 | 16 |
| Point 19 | 0 | 3 |
| Point 20 | 124 | 3 |
| Point 21 | 60 | 3 |
| Point 22 | -6 | 12 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Silts/Clays | 7,10,9,8,20,21,4,6,19,5,1 | 6,500 |
| Region 2 | Sands | 10,9,11,12 | 20,000 |
| Region 3 | Hawthorn Marl | 12,11,13,14 | 10,000 |
| Region 4 | Cooper Group Limestone | 14,13,15,16 | 15,000 |
| Region 5 | | 2,17,18,3,22 | 144 |
| Region 6 | Compacted Fill | 1,22,2 | 76.5 |
| Region 7 | Silts/Clays | 5,19,6,4,21,3,22,1 | 576 |

# 1. Static- Preload

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Yoon Seok Choi
Last Edited By: Heidi Cashman
Revision Number: 144
Date: 9/28/2017
Time: 2:37:28 PM
Tool Version: 8.16.1.13452
File Name: 2) Station 69_00.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 1. Static- Preload

Description: Static Case
Kind: SLOPE/W
Method: Morgenstern-Price
Settings
- Side Function
  - Interslice force function option: Half-Sine
- PWP Conditions Source: Piezometric Line
- Apply Phreatic Correction: No
- Use Staged Rapid Drawdown: No

Slip Surface
- Direction of movement: Right to Left
- Use Passive Mode: No
- Slip Surface Option: Entry and Exit
- Critical slip surfaces saved: 1
- Resisting Side Maximum Convex Angle: 1 °
- Driving Side Maximum Convex Angle: 5 °
- Optimize Critical Slip Surface Location: No

Tension Crack
Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 1 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.38
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 4,000 psf
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 6,000 psf
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-99, 3) ft
Left-Zone Right Coordinate: (-49, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-15, 20) ft
Right-Zone Right Coordinate: (15, 20) ft
Right-Zone Increment: 6
Radius Increments: 4

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 4) ft

## Piezometric Lines

### Piezometric Line 1

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

## Reinforcements

### Reinforcement 1

Type: Geosynthetic
Outside Point: (-49, 3) ft

Inside Point: (30, 3) ft
Length: 79 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,460 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,460 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -49 | 3 |
| Point 2 | -23 | 16 |
| Point 3 | 23 | 16 |
| Point 4 | 50 | 3 |
| Point 5 | -36 | 3 |
| Point 6 | 36 | 3 |
| Point 7 | -250 | 3 |
| Point 8 | 250 | 3 |
| Point 9 | 250 | -3 |
| Point 10 | -250 | -3.00642 |
| Point 11 | 250 | -33 |
| Point 12 | -250 | -33 |
| Point 13 | 250 | -50 |
| Point 14 | -250 | -50 |
| Point 15 | 250 | -73 |
| Point 16 | -250 | -73 |
| Point 17 | 250 | -100 |
| Point 18 | -250 | -100 |
| Point 19 | -15 | 20 |
| Point 20 | 15 | 20 |
| Point 21 | 250 | 4 |
| Point 22 | 130 | 4 |
| Point 23 | 106 | 5 |
| Point 24 | 70 | 11 |
| Point 25 | 50 | 11 |
| Point 26 | 39.92762 | 7.84967 |
| Point 27 | 30 | 3 |
| Point 28 | 34.0309 | 4.9691 |

| | | |
|---|---|---|
| Point 29 | -49 | -73 |
| Point 30 | -49 | -3.00384 |
| Point 31 | -49 | -33 |
| Point 32 | -49 | -50 |
| Point 33 | 50 | -73 |
| Point 34 | 50 | -3.00257 |
| Point 35 | 50 | -33 |
| Point 36 | 50 | -50 |
| Point 37 | -49 | 0 |
| Point 38 | 50 | 0 |
| Point 39 | -250 | 0 |
| Point 40 | 250 | 0 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 2,5,27,28,3 | 761.09 |
| Region 2 | Compacted Fill | 2,1,5 | 84.5 |
| Region 3 | Compacted Fill | 3,28,26 | 48.411 |
| Region 4 | Sands (1) | 7,39,37,1 | 603 |
| Region 5 | Silts/Clays | 10,30,31,12 | 6,029 |
| Region 6 | Sands (2) | 12,31,32,14 | 3,417 |
| Region 7 | Hawthorn Marl | 32,14,16,29,33,15,13,36 | 11,500 |
| Region 8 | Cooper Group Limestone | 16,29,33,15,17,18 | 13,500 |
| Region 9 | Compacted Fill | 2,19,20,3 | 152 |
| Region 10 | Sands (1) | 8,21,22,23,24,25,26,28,27,6,4 | 584.79 |
| Region 11 | Sands (1) | 9,40,38,34 | 600.26 |
| Region 12 | Silts/Clays | 9,11,35,34 | 5,999.7 |
| Region 13 | Sands (2) | 11,13,36,35 | 3,400 |
| Region 14 | Sands (1) | 6,27,5,1,37,38,4 | 297 |
| Region 15 | Silts/Clays | 31,30,34,35 | 2,969.7 |
| Region 16 | Sands (2) | 32,31,35,36 | 1,683 |
| Region 17 | Sands (1) | 30,34,38,37 | 297.32 |
| Region 18 | Sands (1) | 39,37,30,10 | 604.03 |

| | | | |
|---|---|---|---|
| Region 19 | Sands (1) | 4,8,40,38 | 600 |

# 2. Static- Trafic

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Yoon Seok Choi
Last Edited By: Heidi Cashman
Revision Number: 144
Date: 9/28/2017
Time: 2:37:28 PM
Tool Version: 8.16.1.13452
File Name: 2) Station 69_00.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 2. Static- Trafic

Kind: SLOPE/W
Method: Morgenstern-Price
Settings
- Side Function
  - Interslice force function option: Half-Sine
- PWP Conditions Source: Piezometric Line
- Apply Phreatic Correction: No
- Use Staged Rapid Drawdown: No

Slip Surface
- Direction of movement: Right to Left
- Use Passive Mode: No
- Slip Surface Option: Entry and Exit
- Critical slip surfaces saved: 1
- Resisting Side Maximum Convex Angle: 1 °
- Driving Side Maximum Convex Angle: 5 °
- Optimize Critical Slip Surface Location: No
- Tension Crack

Tension Crack Option: (none)

F of S Distribution

F of S Calculation Option: Constant

Advanced

Number of Slices: 30

F of S Tolerance: 0.001

Minimum Slip Surface Depth: 3 ft

Search Method: Root Finder

Tolerable difference between starting and converged F of S: 3

Maximum iterations to calculate converged lambda: 20

Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb

Unit Weight: 125 pcf

Cohesion': 0 psf

Phi': 38 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb

Unit Weight: 100 pcf

Cohesion': 0 psf

Phi': 30 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

## Silts/Clays

Model: S=f(overburden)

Unit Weight: 95 pcf

Tau/Sigma Ratio: 0.38

Minimum Strength: 0 psf

Pore Water Pressure

Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb

Unit Weight: 100 pcf

Cohesion': 0 psf

Phi': 30 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

### Hawthorn Marl

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 4,000 psf
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 6,000 psf
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-99, 3) ft
Left-Zone Right Coordinate: (-49, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-23, 16) ft
Right-Zone Right Coordinate: (23, 16) ft
Right-Zone Increment: 9
Radius Increments: 4

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 4) ft

## Piezometric Lines

### Piezometric Line 1

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

## Surcharge Loads

### Surcharge Load 1

Surcharge (Unit Weight): 400 pcf
Direction: Vertical

### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| | -23 | 16 |
| | -23 | 17 |
| | 23 | 17 |

## Reinforcements

### Reinforcement 1

Type: Geosynthetic
Outside Point: (-49, 3) ft
Inside Point: (30, 3) ft
Length: 79 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,016 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,016 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -49 | 3 |
| Point 2 | -23 | 16 |
| Point 3 | 23 | 16 |
| Point 4 | 50 | 3 |
| Point 5 | -36 | 3 |
| Point 6 | 36 | 3 |
| Point 7 | -250 | 3 |
| Point 8 | 250 | 3 |
| Point 9 | 250 | -3 |
| Point 10 | -250 | -3.00642 |
| Point 11 | 250 | -33 |
| Point 12 | -250 | -33 |
| Point 13 | 250 | -50 |
| Point 14 | -250 | -50 |
| Point 15 | 250 | -73 |
| Point 16 | -250 | -73 |

| | | |
|---|---|---|
| Point 17 | 250 | -100 |
| Point 18 | -250 | -100 |
| Point 19 | -15 | 20 |
| Point 20 | 15 | 20 |
| Point 21 | 250 | 4 |
| Point 22 | 130 | 4 |
| Point 23 | 106 | 5 |
| Point 24 | 70 | 11 |
| Point 25 | 50 | 11 |
| Point 26 | 39.92762 | 7.84967 |
| Point 27 | 30 | 3 |
| Point 28 | 34.0309 | 4.9691 |
| Point 29 | -49 | -73 |
| Point 30 | -49 | -3.00384 |
| Point 31 | -49 | -33 |
| Point 32 | -49 | -50 |
| Point 33 | 50 | -73 |
| Point 34 | 50 | -3.00257 |
| Point 35 | 50 | -33 |
| Point 36 | 50 | -50 |
| Point 37 | -49 | 0 |
| Point 38 | 50 | 0 |
| Point 39 | -250 | 0 |
| Point 40 | 250 | 0 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 2,5,27,28,3 | 761.09 |
| Region 2 | Compacted Fill | 2,1,5 | 84.5 |
| Region 3 | Compacted Fill | 3,28,26 | 48.411 |
| Region 4 | Sands (1) | 7,39,37,1 | 603 |
| Region 5 | Silts/Clays | 10,30,31,12 | 6,029 |
| Region 6 | Sands (2) | 12,31,32,14 | 3,417 |
| Region 7 | Hawthorn Marl | 32,14,16,29,33,15,13,36 | 11,500 |
| Region 8 | Cooper Group Limestone | 16,29,33,15,17,18 | 13,500 |
| Region 9 | | 2,19,20,3 | 152 |
| Region 10 | Sands (1) | 8,21,22,23,24,25,26,28,27,6,4 | 584.79 |
| Region 11 | Sands (1) | 9,40,38,34 | 600.26 |
| Region 12 | Silts/Clays | 9,11,35,34 | 5,999.7 |
| Region 13 | Sands (2) | 11,13,36,35 | 3,400 |
| Region 14 | Sands (1) | 6,27,5,1,37,38,4 | 297 |
| Region 15 | Silts/Clays | 31,30,34,35 | 2,969.7 |
| Region 16 | Sands (2) | 32,31,35,36 | 1,683 |
| Region 17 | Sands (1) | 30,34,38,37 | 297.32 |
| Region 18 | Sands (1) | 39,37,30,10 | 604.03 |
| Region 19 | Sands (1) | 4,8,40,38 | 600 |

# 1. Static- Preload

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Yoon Seok Choi
Last Edited By: Heidi Cashman
Revision Number: 118
Date: 9/28/2017
Time: 3:06:31 PM
Tool Version: 8.16.1.13452
File Name: 3) Station 69_65 - No improvement.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 1. Static- Preload

Description: Static Case
Kind: SLOPE/W
Method: Morgenstern-Price
Settings
Side Function
Interslice force function option: Half-Sine
PWP Conditions Source: Piezometric Line
Apply Phreatic Correction: No
Use Staged Rapid Drawdown: No
Slip Surface
Direction of movement: Right to Left
Use Passive Mode: No
Slip Surface Option: Entry and Exit
Critical slip surfaces saved: 1
Resisting Side Maximum Convex Angle: 1 °
Driving Side Maximum Convex Angle: 5 °
Optimize Critical Slip Surface Location: No

Tension Crack
Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 1 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.37
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl

Model: Undrained (Phi=0)
Unit Weight: 100 pcf
Cohesion: 4,000 psf
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 6,000 psf
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-103, 3) ft
Left-Zone Right Coordinate: (-53, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-17, 21) ft
Right-Zone Right Coordinate: (17, 21) ft
Right-Zone Increment: 7
Radius Increments: 4

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

## Piezometric Lines

### Piezometric Line 1

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

## Reinforcements

### Reinforcement 1

Type: Geosynthetic
Outside Point: (-53, 3) ft

Inside Point: (53, 3) ft
Length: 106 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,406 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,406 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -53 | 3 |
| Point 2 | -23 | 18 |
| Point 3 | 23 | 18 |
| Point 4 | 53 | 3 |
| Point 5 | -38 | 3 |
| Point 6 | 38 | 3 |
| Point 7 | -250 | 3 |
| Point 8 | 250 | 3 |
| Point 9 | 250 | -4 |
| Point 10 | -250 | -4.00642 |
| Point 11 | 250 | -34 |
| Point 12 | -250 | -34 |
| Point 13 | 250 | -50 |
| Point 14 | -250 | -50 |
| Point 15 | 250 | -73 |
| Point 16 | -250 | -73 |
| Point 17 | 250 | -100 |
| Point 18 | -250 | -100 |
| Point 19 | -17 | 21 |
| Point 20 | 17 | 21 |
| Point 21 | 30 | 3 |
| Point 22 | -53 | -4 |
| Point 23 | -53 | -34 |
| Point 24 | -53 | -50 |
| Point 25 | 53 | -4 |
| Point 26 | 53 | -34 |
| Point 27 | 53 | -50 |
| Point 28 | -53 | 0 |

| | | |
|---|---|---|
| Point 29 | 53 | 0 |
| Point 30 | -250 | 0 |
| Point 31 | 250 | 0 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 2,5,21,6,3 | 915 |
| Region 2 | Compacted Fill | 2,1,5 | 112.5 |
| Region 3 | Compacted Fill | 3,6,4 | 112.5 |
| Region 4 | Sands (1) | 7,1,28,30 | 591 |
| Region 5 | Silts/Clays | 10,22,23,12 | 5,909.4 |
| Region 6 | Sands (2) | 12,23,24,14 | 3,152 |
| Region 7 | Hawthorn Marl | 24,14,16,15,13,27 | 11,500 |
| Region 8 | Cooper Group Limestone | 16,15,17,18 | 13,500 |
| Region 9 | Compacted Fill | 2,19,20,3 | 120 |
| Region 10 | Sands (1) | 4,8,31,29 | 591 |
| Region 11 | Silts/Clays | 9,11,26,25 | 5,910 |
| Region 12 | Sands (2) | 11,13,27,26 | 3,152 |
| Region 13 | Sands (1) | 6,21,5,1,28,29,4 | 318 |
| Region 14 | Silts/Clays | 23,22,25,26 | 3,180 |
| Region 15 | Sands (2) | 24,23,26,27 | 1,696 |
| Region 16 | Sands (1) | 22,25,29,28 | 424 |
| Region 17 | Sands (1) | 30,28,22,10 | 788.63 |
| Region 18 | Sands (1) | 29,31,9,25 | 788 |

# 2. Static- Traffic

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Yoon Seok Choi
Last Edited By: Heidi Cashman
Revision Number: 118
Date: 9/28/2017
Time: 3:06:31 PM
Tool Version: 8.16.1.13452
File Name: 3) Station 69_65 - No improvement.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 2. Static- Traffic

Description: Static Case
Kind: SLOPE/W
Method: Morgenstern-Price
Settings
- Side Function
  - Interslice force function option: Half-Sine
- PWP Conditions Source: Piezometric Line
- Apply Phreatic Correction: No
- Use Staged Rapid Drawdown: No

Slip Surface
- Direction of movement: Right to Left
- Use Passive Mode: No
- Slip Surface Option: Entry and Exit
- Critical slip surfaces saved: 1
- Resisting Side Maximum Convex Angle: 1 °
- Driving Side Maximum Convex Angle: 5 °
- Optimize Critical Slip Surface Location: No

Tension Crack
Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 1 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.37
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl

Model: Undrained (Phi=0)
Unit Weight: 100 pcf
Cohesion: 4,000 psf
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 6,000 psf
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-103, 3) ft
Left-Zone Right Coordinate: (-53, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-23, 18) ft
Right-Zone Right Coordinate: (23, 18) ft
Right-Zone Increment: 9
Radius Increments: 4

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

## Piezometric Lines

### Piezometric Line 1

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

## Surcharge Loads

### Surcharge Load 1

Surcharge (Unit Weight): 400 pcf
Direction: Vertical

### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| | -23 | 18 |
| | -23 | 19 |
| | 23 | 19 |

## Reinforcements

### Reinforcement 1

Type: Geosynthetic
Outside Point: (-53, 3) ft
Inside Point: (53, 3) ft
Length: 106 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,172 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,172 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -53 | 3 |
| Point 2 | -23 | 18 |
| Point 3 | 23 | 18 |
| Point 4 | 53 | 3 |
| Point 5 | -38 | 3 |
| Point 6 | 38 | 3 |
| Point 7 | -250 | 3 |
| Point 8 | 250 | 3 |
| Point 9 | 250 | -4 |
| Point 10 | -250 | -4.00642 |
| Point 11 | 250 | -34 |
| Point 12 | -250 | -34 |
| Point 13 | 250 | -50 |
| Point 14 | -250 | -50 |
| Point 15 | 250 | -73 |
| Point 16 | -250 | -73 |

| | | |
|---|---|---|
| Point 17 | 250 | -100 |
| Point 18 | -250 | -100 |
| Point 19 | -17 | 21 |
| Point 20 | 17 | 21 |
| Point 21 | 30 | 3 |
| Point 22 | -53 | -4 |
| Point 23 | -53 | -34 |
| Point 24 | -53 | -50 |
| Point 25 | 53 | -4 |
| Point 26 | 53 | -34 |
| Point 27 | 53 | -50 |
| Point 28 | -53 | 0 |
| Point 29 | 53 | 0 |
| Point 30 | -250 | 0 |
| Point 31 | 250 | 0 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 2,5,21,6,3 | 915 |
| Region 2 | Compacted Fill | 2,1,5 | 112.5 |
| Region 3 | Compacted Fill | 3,6,4 | 112.5 |
| Region 4 | Sands (1) | 7,1,28,30 | 591 |
| Region 5 | Silts/Clays | 10,22,23,12 | 5,909.4 |
| Region 6 | Sands (2) | 12,23,24,14 | 3,152 |
| Region 7 | Hawthorn Marl | 24,14,16,15,13,27 | 11,500 |
| Region 8 | Cooper Group Limestone | 16,15,17,18 | 13,500 |
| Region 9 | | 2,19,20,3 | 120 |
| Region 10 | Sands (1) | 4,8,31,29 | 591 |
| Region 11 | Silts/Clays | 9,11,26,25 | 5,910 |
| Region 12 | Sands (2) | 11,13,27,26 | 3,152 |
| | | | |

| | | | |
|---|---|---|---|
| Region 13 | Sands (1) | 6,21,5,1,28,29,4 | 318 |
| Region 14 | Silts/Clays | 23,22,25,26 | 3,180 |
| Region 15 | Sands (2) | 24,23,26,27 | 1,696 |
| Region 16 | Sands (1) | 22,25,29,28 | 424 |
| Region 17 | Sands (1) | 30,28,22,10 | 788.63 |
| Region 18 | Sands (1) | 29,31,9,25 | 788 |

# 1. Static - Preload

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Yoon Seok Choi
Last Edited By: Heidi Cashman
Revision Number: 106
Date: 9/29/2017
Time: 10:46:38 AM
Tool Version: 8.16.1.13452
File Name: 4) Station 70_40 - (2xGeotextile).gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 1. Static - Preload

Description: Static Case
Kind: SLOPE/W
Method: Morgenstern-Price
Settings
- Side Function
  - Interslice force function option: Half-Sine
- PWP Conditions Source: Piezometric Line
- Apply Phreatic Correction: No
- Use Staged Rapid Drawdown: No

Slip Surface
- Direction of movement: Right to Left
- Use Passive Mode: No
- Slip Surface Option: Entry and Exit
- Critical slip surfaces saved: 1
- Resisting Side Maximum Convex Angle: 1 °
- Driving Side Maximum Convex Angle: 5 °
- Optimize Critical Slip Surface Location: No

Tension Crack
Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 0.1 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.36
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl
Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 4,000 psf
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone
Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 6,000 psf
Pore Water Pressure
Piezometric Line: 1

### Sands (1) - Improved
Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Silts/Clays - Improved
Model: Mohr-Coulomb
Unit Weight: 95 pcf
Cohesion': 348 psf
Phi': 19.8 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (2) - Improved
Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit
Left Projection: Range
Left-Zone Left Coordinate: (-110, 3) ft
Left-Zone Right Coordinate: (-60, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-18, 24) ft
Right-Zone Right Coordinate: (18, 24) ft

Right-Zone Increment: 7
Radius Increments: 4

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

## Piezometric Lines

### Piezometric Line 1

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

## Reinforcements

### Reinforcement 1

Type: Geosynthetic
Outside Point: (-60, 3) ft
Inside Point: (60, 3) ft
Length: 120 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,641 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,641 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

### Reinforcement 2

Type: Geosynthetic
Outside Point: (-26, 19) ft
Inside Point: (-8, 19) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 391 psf
Resistance Reduction Factor: 1

Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 391 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 3

Type: Geosynthetic
Outside Point: (-28, 17) ft
Inside Point: (-10, 17) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 547 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 547 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 4

Type: Geosynthetic
Outside Point: (-30, 15) ft
Inside Point: (-12, 15) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 703 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 703 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 5

Type: Geosynthetic
Outside Point: (-32, 13) ft
Inside Point: (-14, 13) ft
Length: 18 ft

Direction: 180 °
F of S Dependent: No
Pullout Resistance: 859 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 859 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 6

Type: Geosynthetic
Outside Point: (-34, 11) ft
Inside Point: (-16, 11) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,016 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,016 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 7

Type: Geosynthetic
Outside Point: (-36, 9) ft
Inside Point: (-18, 9) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,172 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,172 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 8

Type: Geosynthetic
Outside Point: (-38, 7) ft
Inside Point: (-20, 7) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,328 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,328 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

## Reinforcement 9

Type: Geosynthetic
Outside Point: (-40, 5) ft
Inside Point: (40, 5) ft
Length: 80 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,484 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,484 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

## Reinforcement 10

Type: Geosynthetic
Outside Point: (8, 19) ft
Inside Point: (26, 19) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 391 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 391 lbs/ft

Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 11

Type: Geosynthetic
Outside Point: (10, 17) ft
Inside Point: (28, 17) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 547 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 547 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 12

Type: Geosynthetic
Outside Point: (12, 15) ft
Inside Point: (30, 15) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 703 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 703 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 13

Type: Geosynthetic
Outside Point: (14, 13) ft
Inside Point: (32, 13) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 859 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No

Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 859 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 14

Type: Geosynthetic
Outside Point: (16, 11) ft
Inside Point: (34, 11) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,016 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,016 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 15

Type: Geosynthetic
Outside Point: (18, 9) ft
Inside Point: (36, 9) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,172 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,172 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 16

Type: Geosynthetic
Outside Point: (20, 7) ft
Inside Point: (38, 7) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No

Pullout Resistance: 1,328 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,328 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -60 | 3 |
| Point 2 | -24 | 21 |
| Point 3 | 24 | 21 |
| Point 4 | 60 | 3 |
| Point 5 | -42 | 3 |
| Point 6 | 42 | 3 |
| Point 7 | -250 | 3 |
| Point 8 | 250 | 3 |
| Point 9 | 250 | -5 |
| Point 10 | -250 | -5 |
| Point 11 | 250 | -35 |
| Point 12 | -250 | -35 |
| Point 13 | 250 | -50 |
| Point 14 | -250 | -50 |
| Point 15 | 250 | -74 |
| Point 16 | -250 | -74 |
| Point 17 | 250 | -100 |
| Point 18 | -250 | -100 |
| Point 19 | -18 | 24 |
| Point 20 | 18 | 24 |
| Point 21 | -34 | -50 |
| Point 22 | -34 | -5 |
| Point 23 | -34 | -35 |
| Point 24 | 34 | -50 |
| Point 25 | 34 | -35 |
| Point 26 | 34 | -5 |
| Point 27 | -34 | 0 |
| Point 28 | 34 | 0 |
| Point 29 | -34 | 3 |
| Point 30 | 34 | 3 |
| Point 31 | -250 | 0 |

| | | |
|---|---|---|
| Point 32 | 250 | 0 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 2,5,29,30,6,3 | 1,188 |
| Region 2 | Compacted Fill | 2,1,5 | 162 |
| Region 3 | Compacted Fill | 3,6,4 | 162 |
| Region 4 | Sands (1) | 7,1,5,29,27,31 | 648 |
| Region 5 | Silts/Clays | 10,22,23,12 | 6,480 |
| Region 6 | Sands (2) | 12,23,21,14 | 3,240 |
| Region 7 | Hawthorn Marl | 14,21,24,13,15,16 | 12,000 |
| Region 8 | Cooper Group Limestone | 16,15,17,18 | 13,000 |
| Region 9 | Compacted Fill | 2,19,20,3 | 126 |
| Region 10 | Sands (1) | 30,6,4,8,32,28 | 648 |
| Region 11 | Silts/Clays | 9,11,25,26 | 6,480 |
| Region 12 | Sands (2) | 11,13,24,25 | 3,240 |
| Region 13 | Sands (2) - Improved | 21,23,25,24 | 1,020 |
| Region 14 | Silts/Clays - Improved | 23,22,26,25 | 2,040 |
| Region 15 | Sands (1) - Improved | 29,30,28,27 | 204 |
| Region 16 | Sands (1) - Improved | 22,26,28,27 | 340 |
| Region 17 | Sands (1) | 31,27,22,10 | 1,080 |
| Region 18 | Sands (1) | 28,32,9,26 | 1,080 |

# 2. Static - Traffic

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Yoon Seok Choi
Last Edited By: Heidi Cashman
Revision Number: 106
Date: 9/29/2017
Time: 10:46:38 AM
Tool Version: 8.16.1.13452
File Name: 4) Station 70_40 - (2xGeotextile).gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 2. Static - Traffic

Description: Static Case
Kind: SLOPE/W
Method: Morgenstern-Price
Settings
- Side Function
  - Interslice force function option: Half-Sine
- PWP Conditions Source: Piezometric Line
- Apply Phreatic Correction: No
- Use Staged Rapid Drawdown: No

Slip Surface
- Direction of movement: Right to Left
- Use Passive Mode: No
- Slip Surface Option: Entry and Exit
- Critical slip surfaces saved: 1
- Resisting Side Maximum Convex Angle: 1 °
- Driving Side Maximum Convex Angle: 5 °
- Optimize Critical Slip Surface Location: No

Tension Crack
Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 0.1 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.36
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl
Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 4,000 psf
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone
Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 6,000 psf
Pore Water Pressure
Piezometric Line: 1

### Sands (1) - Improved
Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Silts/Clays - Improved
Model: Mohr-Coulomb
Unit Weight: 95 pcf
Cohesion': 348 psf
Phi': 19.8 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (2) - Improved
Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit
Left Projection: Range
Left-Zone Left Coordinate: (-110, 3) ft
Left-Zone Right Coordinate: (-60, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-24, 21) ft
Right-Zone Right Coordinate: (24, 21) ft

Right-Zone Increment: 10
Radius Increments: 4

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

## Piezometric Lines

### Piezometric Line 1

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

## Surcharge Loads

### Surcharge Load 1

Surcharge (Unit Weight): 400 pcf
Direction: Vertical

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| | -24 | 21 |
| | -24 | 22 |
| | 24 | 22 |

## Reinforcements

### Reinforcement 1

Type: Geosynthetic
Outside Point: (-60, 3) ft
Inside Point: (60, 3) ft
Length: 120 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,406 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs

Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,406 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

### Reinforcement 2

Type: Geosynthetic
Outside Point: (-26, 19) ft
Inside Point: (-8, 19) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 156 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 156 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 3

Type: Geosynthetic
Outside Point: (-28, 17) ft
Inside Point: (-10, 17) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 313 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 313 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 4

Type: Geosynthetic
Outside Point: (-30, 15) ft
Inside Point: (-12, 15) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 469 psf

Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 469 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 5

Type: Geosynthetic
Outside Point: (-32, 13) ft
Inside Point: (-14, 13) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 625 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 625 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 6

Type: Geosynthetic
Outside Point: (-34, 11) ft
Inside Point: (-16, 11) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 781 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 781 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 7

Type: Geosynthetic
Outside Point: (-36, 9) ft
Inside Point: (-18, 9) ft

Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 938 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 938 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 8

Type: Geosynthetic
Outside Point: (-38, 7) ft
Inside Point: (-20, 7) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,094 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,094 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 9

Type: Geosynthetic
Outside Point: (-40, 5) ft
Inside Point: (40, 5) ft
Length: 80 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,250 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,250 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

### Reinforcement 10

Type: Geosynthetic
Outside Point: (8, 19) ft
Inside Point: (26, 19) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 156 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 156 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 11

Type: Geosynthetic
Outside Point: (10, 17) ft
Inside Point: (28, 17) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 313 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 313 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 12

Type: Geosynthetic
Outside Point: (12, 15) ft
Inside Point: (30, 15) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 469 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0

Factored Pullout Resistance: 469 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 13

Type: Geosynthetic
Outside Point: (14, 13) ft
Inside Point: (32, 13) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 625 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 625 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 14

Type: Geosynthetic
Outside Point: (16, 11) ft
Inside Point: (34, 11) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 781 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 781 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 15

Type: Geosynthetic
Outside Point: (18, 9) ft
Inside Point: (36, 9) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 938 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed

Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 938 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 16

Type: Geosynthetic
Outside Point: (20, 7) ft
Inside Point: (38, 7) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,094 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,094 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -60 | 3 |
| Point 2 | -24 | 21 |
| Point 3 | 24 | 21 |
| Point 4 | 60 | 3 |
| Point 5 | -42 | 3 |
| Point 6 | 42 | 3 |
| Point 7 | -250 | 3 |
| Point 8 | 250 | 3 |
| Point 9 | 250 | -5 |
| Point 10 | -250 | -5 |
| Point 11 | 250 | -35 |
| Point 12 | -250 | -35 |
| Point 13 | 250 | -50 |
| Point 14 | -250 | -50 |
| Point 15 | 250 | -74 |
| Point 16 | -250 | -74 |
| Point 17 | 250 | -100 |
| Point 18 | -250 | -100 |

| | | |
|---|---|---|
| Point 19 | -18 | 24 |
| Point 20 | 18 | 24 |
| Point 21 | -34 | -50 |
| Point 22 | -34 | -5 |
| Point 23 | -34 | -35 |
| Point 24 | 34 | -50 |
| Point 25 | 34 | -35 |
| Point 26 | 34 | -5 |
| Point 27 | -34 | 0 |
| Point 28 | 34 | 0 |
| Point 29 | -34 | 3 |
| Point 30 | 34 | 3 |
| Point 31 | -250 | 0 |
| Point 32 | 250 | 0 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 2,5,29,30,6,3 | 1,188 |
| Region 2 | Compacted Fill | 2,1,5 | 162 |
| Region 3 | Compacted Fill | 3,6,4 | 162 |
| Region 4 | Sands (1) | 7,1,5,29,27,31 | 648 |
| Region 5 | Silts/Clays | 10,22,23,12 | 6,480 |
| Region 6 | Sands (2) | 12,23,21,14 | 3,240 |
| Region 7 | Hawthorn Marl | 14,21,24,13,15,16 | 12,000 |
| Region 8 | Cooper Group Limestone | 16,15,17,18 | 13,000 |
| Region 9 | | 2,19,20,3 | 126 |
| Region 10 | Sands (1) | 30,6,4,8,32,28 | 648 |
| Region 11 | Silts/Clays | 9,11,25,26 | 6,480 |
| Region 12 | Sands (2) | 11,13,24,25 | 3,240 |
| Region 13 | Sands (2) - Improved | 21,23,25,24 | 1,020 |
| Region 14 | Silts/Clays - Improved | 23,22,26,25 | 2,040 |

| | | | |
|---|---|---|---|
| Region 15 | Sands (1) - Improved | 29,30,28,27 | 204 |
| Region 16 | Sands (1) - Improved | 22,26,28,27 | 340 |
| Region 17 | Sands (1) | 31,27,22,10 | 1,080 |
| Region 18 | Sands (1) | 28,32,9,26 | 1,080 |

# 3. Post Seismic

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Yoon Seok Choi
Last Edited By: Heidi Cashman
Revision Number: 106
Date: 9/29/2017
Time: 10:46:38 AM
Tool Version: 8.16.1.13452
File Name: 4) Station 70_40 - (2xGeotextile).gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 3. Post Seismic

Kind: SLOPE/W
Method: Morgenstern-Price
Settings
Side Function
Interslice force function option: Half-Sine
PWP Conditions Source: Piezometric Line
Apply Phreatic Correction: No
Use Staged Rapid Drawdown: No
Slip Surface
Direction of movement: Right to Left
Use Passive Mode: No
Slip Surface Option: Entry and Exit
Critical slip surfaces saved: 1
Resisting Side Maximum Convex Angle: 1 °
Driving Side Maximum Convex Angle: 5 °
Optimize Critical Slip Surface Location: No
Tension Crack

Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 0.1 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.36
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

## Cooper Group Limestone

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 6,000 psf
Pore Water Pressure
Piezometric Line: 1

## Sands (1) - Improved

Model: Mohr-Coulomb

Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Silts/Clays - Improved

Model: Mohr-Coulomb
Unit Weight: 95 pcf
Cohesion': 348 psf
Phi': 19.8 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (1) - Residual

Model: S=f(overburden)
Unit Weight: 100 pcf
Tau/Sigma Ratio: 0.08
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

### Sands (2) - Residual

Model: S=f(overburden)
Unit Weight: 100 pcf
Tau/Sigma Ratio: 0.08
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl - Seismic

Model: Undrained (Phi=0)
Unit Weight: 120 pcf
Cohesion: 3,400 psf
Pore Water Pressure
Piezometric Line: 1

### Sands (1) - Residual Improved

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 4.6 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (2) - Residual Improved

Model: Mohr-Coulomb

Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 4.6 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-110, 3) ft
Left-Zone Right Coordinate: (-60, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-24, 21) ft
Right-Zone Right Coordinate: (24, 21) ft
Right-Zone Increment: 10
Radius Increments: 4

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

## Piezometric Lines

### Piezometric Line 1

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

## Seismic Coefficients

Horz Seismic Coef.: 0.29

## Reinforcements

### Reinforcement 1

Type: Geosynthetic
Outside Point: (-60, 3) ft
Inside Point: (60, 3) ft
Length: 120 ft
Direction: 180 °

F of S Dependent: No
Pullout Resistance: 1,406 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,406 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

### Reinforcement 2

Type: Geosynthetic
Outside Point: (-26, 19) ft
Inside Point: (-8, 19) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 156 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 156 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 3

Type: Geosynthetic
Outside Point: (-28, 17) ft
Inside Point: (-10, 17) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 313 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 313 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 4

Type: Geosynthetic

Outside Point: (-30, 15) ft
Inside Point: (-12, 15) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 469 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 469 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 5

Type: Geosynthetic
Outside Point: (-32, 13) ft
Inside Point: (-14, 13) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 625 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 625 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 6

Type: Geosynthetic
Outside Point: (-34, 11) ft
Inside Point: (-16, 11) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 781 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 781 lbs/ft
Max. Pullout Force: 960 lbs

Factored Tensile Capacity: 960 lbs

### Reinforcement 7

Type: Geosynthetic
Outside Point: (-36, 9) ft
Inside Point: (-18, 9) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 938 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 938 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 8

Type: Geosynthetic
Outside Point: (-38, 7) ft
Inside Point: (-20, 7) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,094 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,094 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 9

Type: Geosynthetic
Outside Point: (-40, 5) ft
Inside Point: (40, 5) ft
Length: 80 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,250 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs

Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,250 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

### Reinforcement 10

Type: Geosynthetic
Outside Point: (8, 19) ft
Inside Point: (26, 19) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 156 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 156 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 11

Type: Geosynthetic
Outside Point: (10, 17) ft
Inside Point: (28, 17) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 313 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 313 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 12

Type: Geosynthetic
Outside Point: (12, 15) ft
Inside Point: (30, 15) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 469 psf

Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 469 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 13

Type: Geosynthetic
Outside Point: (14, 13) ft
Inside Point: (32, 13) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 625 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 625 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 14

Type: Geosynthetic
Outside Point: (16, 11) ft
Inside Point: (34, 11) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 781 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 781 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 15

Type: Geosynthetic
Outside Point: (18, 9) ft
Inside Point: (36, 9) ft

Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 938 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 938 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 16

Type: Geosynthetic
Outside Point: (20, 7) ft
Inside Point: (38, 7) ft
Length: 18 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,094 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,094 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -60 | 3 |
| Point 2 | -24 | 21 |
| Point 3 | 24 | 21 |
| Point 4 | 60 | 3 |
| Point 5 | -42 | 3 |
| Point 6 | 42 | 3 |
| Point 7 | -250 | 3 |
| Point 8 | 250 | 3 |
| Point 9 | 250 | -5 |
| Point 10 | -250 | -5 |
| Point 11 | 250 | -35 |
| Point 12 | -250 | -35 |
| Point 13 | 250 | -50 |

| | | |
|---|---|---|
| Point 14 | -250 | -50 |
| Point 15 | 250 | -74 |
| Point 16 | -250 | -74 |
| Point 17 | 250 | -100 |
| Point 18 | -250 | -100 |
| Point 19 | -18 | 24 |
| Point 20 | 18 | 24 |
| Point 21 | -34 | -50 |
| Point 22 | -34 | -5 |
| Point 23 | -34 | -35 |
| Point 24 | 34 | -50 |
| Point 25 | 34 | -35 |
| Point 26 | 34 | -5 |
| Point 27 | -34 | 0 |
| Point 28 | 34 | 0 |
| Point 29 | -34 | 3 |
| Point 30 | 34 | 3 |
| Point 31 | -250 | 0 |
| Point 32 | 250 | 0 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 2,5,29,30,6,3 | 1,188 |
| Region 2 | Compacted Fill | 2,1,5 | 162 |
| Region 3 | Compacted Fill | 3,6,4 | 162 |
| Region 4 | Sands (1) | 7,1,5,29,27,31 | 648 |
| Region 5 | Silts/Clays | 10,22,23,12 | 6,480 |

| | | | |
|---|---|---|---|
| Region 6 | Sands (2) - Residual | 12,23,21,14 | 3,240 |
| Region 7 | Hawthorn Marl - Seismic | 14,21,24,13,15,16 | 12,000 |
| Region 8 | Cooper Group Limestone | 16,15,17,18 | 13,000 |
| Region 9 | | 2,19,20,3 | 126 |
| Region 10 | Sands (1) | 30,6,4,8,32,28 | 648 |
| Region 11 | Silts/Clays | 9,11,25,26 | 6,480 |
| Region 12 | Sands (2) - Residual | 11,13,24,25 | 3,240 |
| Region 13 | Sands (2) - Residual Improved | 21,23,25,24 | 1,020 |
| Region 14 | Silts/Clays - Improved | 23,22,26,25 | 2,040 |
| Region 15 | Sands (1) - Improved | 29,30,28,27 | 204 |
| Region 16 | Sands (1) - Residual Improved | 22,26,28,27 | 340 |
| Region 17 | Sands (1) - Residual | 31,27,22,10 | 1,080 |
| Region 18 | Sands (1) - Residual | 28,32,9,26 | 1,080 |

# 1. Static - Preload

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Colton W. McInelly
Last Edited By: Heidi Cashman
Revision Number: 126
Date: 9/29/2017
Time: 11:12:51 AM
Tool Version: 8.16.1.13452
File Name: 5) Station 103_80.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 1. Static - Preload

Kind: SLOPE/W
Method: Morgenstern-Price
Settings
Side Function
Interslice force function option: Half-Sine
PWP Conditions Source: Piezometric Line
Apply Phreatic Correction: No
Use Staged Rapid Drawdown: No
Slip Surface
Direction of movement: Right to Left
Use Passive Mode: No
Slip Surface Option: Entry and Exit
Critical slip surfaces saved: 1
Resisting Side Maximum Convex Angle: 1 °
Driving Side Maximum Convex Angle: 5 °
Optimize Critical Slip Surface Location: No
Tension Crack

Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 5 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 0 psf
Phi': 41 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (3)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Silts/Clays
Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.23
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

### Sands (4)
Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl
Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 4,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone
Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 6,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (1) - Improved
Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (2) - Improved
Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 348 psf
Phi': 41 °
Phi-B: 0 °

Pore Water Pressure
Piezometric Line: 1

### Sands (3) - Improved
Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (4) - Improved
Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Silts/Clays - Improved
Model: Mohr-Coulomb
Unit Weight: 95 pcf
Cohesion': 348 psf
Phi': 13 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit
Left Projection: Range
Left-Zone Left Coordinate: (-107, 3) ft
Left-Zone Right Coordinate: (-57, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-20, 23) ft
Right-Zone Right Coordinate: (20, 23) ft
Right-Zone Increment: 8
Radius Increments: 10

## Slip Surface Limits
Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

# Piezometric Lines

## Piezometric Line 1

### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

# Reinforcements

## Reinforcement 1

Type: Geosynthetic
Outside Point: (-57, 3) ft
Inside Point: (34, 3) ft
Length: 91 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,563 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,563 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

## Reinforcement 2

Type: Geosynthetic
Outside Point: (34, 3) ft
Inside Point: (49, 7) ft
Length: 15.524175 ft
Direction: 194.93 °
F of S Dependent: No
Pullout Resistance: 1,563 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,563 lbs/ft
Max. Pullout Force: 24,264.285 lbs
Factored Tensile Capacity: 33,980 lbs

### Reinforcement 3

Type: Geosynthetic
Outside Point: (-42, 4) ft
Inside Point: (-28, 4) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,484 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,484 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 4

Type: Geosynthetic
Outside Point: (-40, 6) ft
Inside Point: (-26, 6) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,328 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,328 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 5

Type: Geosynthetic
Outside Point: (-38, 8) ft
Inside Point: (-24, 8) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,172 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0

Factored Pullout Resistance: 1,172 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 6

Type: Geosynthetic
Outside Point: (-36, 10) ft
Inside Point: (-22, 10) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,016 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,016 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 7

Type: Geosynthetic
Outside Point: (-34, 12) ft
Inside Point: (-20, 12) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 859 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 859 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 8

Type: Geosynthetic
Outside Point: (-32, 14) ft
Inside Point: (-18, 14) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 703 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed

Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 703 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 9

Type: Geosynthetic
Outside Point: (-30, 16) ft
Inside Point: (-16, 16) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 547 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 547 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 10

Type: Geosynthetic
Outside Point: (-28, 18) ft
Inside Point: (-14, 18) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 391 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 391 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 11

Type: Geosynthetic
Outside Point: (38, 4) ft
Inside Point: (28, 4) ft
Length: 10 ft
Direction: 0 °

F of S Dependent: No
Pullout Resistance: 1,484 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,484 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 12

Type: Geosynthetic
Outside Point: (40, 6) ft
Inside Point: (26, 6) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 1,328 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,328 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 13

Type: Geosynthetic
Outside Point: (38, 8) ft
Inside Point: (24, 8) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 1,172 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,172 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 14

Type: Geosynthetic

Outside Point: (36, 10) ft
Inside Point: (22, 10) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 1,016 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,016 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

## Reinforcement 15

Type: Geosynthetic
Outside Point: (34, 12) ft
Inside Point: (20, 12) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 859 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 859 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

## Reinforcement 16

Type: Geosynthetic
Outside Point: (32, 14) ft
Inside Point: (18, 14) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 703 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 703 lbs/ft
Max. Pullout Force: 960 lbs

Factored Tensile Capacity: 960 lbs

### Reinforcement 17

Type: Geosynthetic
Outside Point: (30, 16) ft
Inside Point: (16, 16) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 547 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 547 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 18

Type: Geosynthetic
Outside Point: (28, 18) ft
Inside Point: (14, 18) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 391 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 391 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -250 | 3 |
| Point 2 | -57 | 3 |
| Point 3 | -26 | 20 |
| Point 4 | -20 | 23 |
| Point 5 | 20 | 23 |
| Point 6 | 26 | 20 |
| Point 7 | 49 | 7 |
| Point 8 | 82 | 7 |

| | | |
|---|---|---|
| Point 9 | 94 | 3 |
| Point 10 | 250 | 3 |
| Point 11 | 34 | 3 |
| Point 12 | -43 | 3 |
| Point 13 | 41.1 | 4.9 |
| Point 14 | 250 | 0 |
| Point 15 | 250 | -15 |
| Point 16 | 250 | -31 |
| Point 17 | 250 | -50 |
| Point 18 | 250 | -67 |
| Point 19 | 250 | -77 |
| Point 20 | -250 | -77 |
| Point 21 | -250 | -67 |
| Point 22 | -250 | -50 |
| Point 23 | -250 | -31 |
| Point 24 | -250 | -15 |
| Point 25 | -250 | 0 |
| Point 26 | -36 | -67 |
| Point 27 | -36 | 0 |
| Point 28 | -36 | -15 |
| Point 29 | -36 | -31 |
| Point 30 | -36 | -50 |
| Point 31 | 36 | -67 |
| Point 32 | 36 | -50 |

| | | |
|---|---|---|
| Point 33 | 36 | -31 |
| Point 34 | 36 | -15 |
| Point 35 | 36 | 0 |
| Point 36 | -250 | -100 |
| Point 37 | 250 | -100 |
| Point 38 | -36 | 3 |
| Point 39 | 36 | 3.52 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 12,3,6,13,39,11,38 | 1,164.5 |
| Region 2 | Sands (1) | 1,2,12,38,27,25 | 642 |
| Region 3 | Sands (2) | 25,27,28,24 | 3,210 |
| Region 4 | Sands (3) | 24,28,29,23 | 3,424 |
| Region 5 | Silts/Clays | 23,29,30,22 | 4,066 |
| Region 6 | Sands (4) | 22,30,26,21 | 3,638 |
| Region 7 | Hawthorn Marl | 21,26,31,18,19,20 | 5,000 |
| Region 8 | Cooper Group Limestone | 20,19,37,36 | 11,500 |
| Region 9 | Compacted Fill | 2,12,3 | 119 |
| Region 10 | Compacted Fill | 6,13,7 | 75.5 |
| Region 11 | Compacted Fill | 4,5,6,3 | 138 |
| Region 12 | Sands (1) - Improved | 38,11,39,35,27 | 216.52 |
| Region 13 | Sands (2) | 14,15,34,35 | 3,210 |
| Region 14 | Sands (3) | 15,16,33,34 | 3,424 |
| Region 15 | Silts/Clays | 16,17,32,33 | 4,066 |
| Region 16 | Sands (4) | 17,18,31,32 | 3,638 |
| Region 17 | Sands (4) - Improved | 26,30,32,31 | 1,224 |
| Region 18 | Silts/Clays - Improved | 30,29,33,32 | 1,368 |
| Region 19 | Sands (3) - Improved | 29,28,34,33 | 1,152 |
| Region 20 | Sands (2) - Improved | 28,27,35,34 | 1,080 |
| Region 21 | Sands (1) | 8,9,10,14,35,39,13,7 | 827.48 |

# 2. Static - Trafic

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Colton W. McInelly
Last Edited By: Heidi Cashman
Revision Number: 126
Date: 9/29/2017
Time: 11:12:51 AM
Tool Version: 8.16.1.13452
File Name: 5) Station 103_80.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 2. Static - Trafic

Kind: SLOPE/W
Method: Morgenstern-Price
Settings
- Side Function
  - Interslice force function option: Half-Sine
- PWP Conditions Source: Piezometric Line
- Apply Phreatic Correction: No
- Use Staged Rapid Drawdown: No

Slip Surface
- Direction of movement: Right to Left
- Use Passive Mode: No
- Slip Surface Option: Entry and Exit
- Critical slip surfaces saved: 1
- Resisting Side Maximum Convex Angle: 1 °
- Driving Side Maximum Convex Angle: 5 °
- Optimize Critical Slip Surface Location: No
- Tension Crack

Tension Crack Option: (none)

F of S Distribution

F of S Calculation Option: Constant

Advanced

Number of Slices: 30

F of S Tolerance: 0.001

Minimum Slip Surface Depth: 5 ft

Search Method: Root Finder

Tolerable difference between starting and converged F of S: 3

Maximum iterations to calculate converged lambda: 20

Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb

Unit Weight: 125 pcf

Cohesion': 0 psf

Phi': 38 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb

Unit Weight: 100 pcf

Cohesion': 0 psf

Phi': 30 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb

Unit Weight: 120 pcf

Cohesion': 0 psf

Phi': 41 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

## Sands (3)

Model: Mohr-Coulomb

Unit Weight: 100 pcf

Cohesion': 0 psf

Phi': 30 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

### Silts/Clays
Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.23
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

### Sands (4)
Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl
Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 4,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone
Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 6,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (1) - Improved
Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (2) - Improved
Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 348 psf
Phi': 41 °
Phi-B: 0 °

Pore Water Pressure
Piezometric Line: 1

### Sands (3) - Improved

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (4) - Improved

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Silts/Clays - Improved

Model: Mohr-Coulomb
Unit Weight: 95 pcf
Cohesion': 348 psf
Phi': 13 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-107, 3) ft
Left-Zone Right Coordinate: (-57, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-26, 20) ft
Right-Zone Right Coordinate: (26, 20) ft
Right-Zone Increment: 10
Radius Increments: 10

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

# Piezometric Lines

## Piezometric Line 1

### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

# Surcharge Loads

## Surcharge Load 1

Surcharge (Unit Weight): 400 pcf
Direction: Vertical

### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| | -26 | 20 |
| | -26 | 21 |
| | 26 | 21 |

# Reinforcements

## Reinforcement 1

Type: Geosynthetic
Outside Point: (-57, 3) ft
Inside Point: (34, 3) ft
Length: 91 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,328 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,328 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

## Reinforcement 2

Type: Geosynthetic
Outside Point: (34, 3) ft
Inside Point: (49, 7) ft

Length: 15.524175 ft
Direction: 194.93 °
F of S Dependent: No
Pullout Resistance: 1,328 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,328 lbs/ft
Max. Pullout Force: 20,616.104 lbs
Factored Tensile Capacity: 33,980 lbs

### Reinforcement 3

Type: Geosynthetic
Outside Point: (-42, 4) ft
Inside Point: (-28, 4) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,250 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,250 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 4

Type: Geosynthetic
Outside Point: (-40, 6) ft
Inside Point: (-26, 6) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,094 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,094 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 5

Type: Geosynthetic
Outside Point: (-38, 8) ft
Inside Point: (-24, 8) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 938 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 938 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 6

Type: Geosynthetic
Outside Point: (-36, 10) ft
Inside Point: (-22, 10) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 781 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 781 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 7

Type: Geosynthetic
Outside Point: (-34, 12) ft
Inside Point: (-20, 12) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 625 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0

Factored Pullout Resistance: 625 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 8

Type: Geosynthetic
Outside Point: (-32, 14) ft
Inside Point: (-18, 14) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 469 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 469 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 9

Type: Geosynthetic
Outside Point: (-30, 16) ft
Inside Point: (-16, 16) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 313 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 313 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 10

Type: Geosynthetic
Outside Point: (-28, 18) ft
Inside Point: (-14, 18) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 156 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed

Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 156 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 11

Type: Geosynthetic
Outside Point: (38, 4) ft
Inside Point: (28, 4) ft
Length: 10 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 1,250 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,250 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 12

Type: Geosynthetic
Outside Point: (40, 6) ft
Inside Point: (26, 6) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 1,094 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,094 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 13

Type: Geosynthetic
Outside Point: (38, 8) ft
Inside Point: (24, 8) ft
Length: 14 ft
Direction: 0 °

F of S Dependent: No
Pullout Resistance: 938 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 938 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 14

Type: Geosynthetic
Outside Point: (36, 10) ft
Inside Point: (22, 10) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 781 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 781 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 15

Type: Geosynthetic
Outside Point: (34, 12) ft
Inside Point: (20, 12) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 625 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 625 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 16

Type: Geosynthetic

Outside Point: (32, 14) ft
Inside Point: (18, 14) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 469 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 469 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 17

Type: Geosynthetic
Outside Point: (30, 16) ft
Inside Point: (16, 16) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 313 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 313 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 18

Type: Geosynthetic
Outside Point: (28, 18) ft
Inside Point: (14, 18) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 156 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 156 lbs/ft
Max. Pullout Force: 960 lbs

Factored Tensile Capacity: 960 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -250 | 3 |
| Point 2 | -57 | 3 |
| Point 3 | -26 | 20 |
| Point 4 | -20 | 23 |
| Point 5 | 20 | 23 |
| Point 6 | 26 | 20 |
| Point 7 | 49 | 7 |
| Point 8 | 82 | 7 |
| Point 9 | 94 | 3 |
| Point 10 | 250 | 3 |
| Point 11 | 34 | 3 |
| Point 12 | -43 | 3 |
| Point 13 | 41.1 | 4.9 |
| Point 14 | 250 | 0 |
| Point 15 | 250 | -15 |
| Point 16 | 250 | -31 |
| Point 17 | 250 | -50 |
| Point 18 | 250 | -67 |
| Point 19 | 250 | -77 |
| Point 20 | -250 | -77 |
| Point 21 | -250 | -67 |
| Point 22 | -250 | -50 |
| Point 23 | -250 | -31 |
| Point 24 | -250 | -15 |
| Point 25 | -250 | 0 |
| Point 26 | -36 | -67 |
| Point 27 | -36 | 0 |
| Point 28 | -36 | -15 |
| Point 29 | -36 | -31 |
| Point 30 | -36 | -50 |
| Point 31 | 36 | -67 |
| Point 32 | 36 | -50 |
| Point 33 | 36 | -31 |
| Point 34 | 36 | -15 |
| Point 35 | 36 | 0 |
| Point 36 | -250 | -100 |
| Point 37 | 250 | -100 |
| Point 38 | -36 | 3 |
| Point 39 | 36 | 3.52 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 12,3,6,13,39,11,38 | 1,164.5 |
| Region 2 | Sands (1) | 1,2,12,38,27,25 | 642 |
| Region 3 | Sands (2) | 25,27,28,24 | 3,210 |
| Region 4 | Sands (3) | 24,28,29,23 | 3,424 |
| Region 5 | Silts/Clays | 23,29,30,22 | 4,066 |
| Region 6 | Sands (4) | 22,30,26,21 | 3,638 |
| Region 7 | Hawthorn Marl | 21,26,31,18,19,20 | 5,000 |
| Region 8 | Cooper Group Limestone | 20,19,37,36 | 11,500 |
| Region 9 | Compacted Fill | 2,12,3 | 119 |
| Region 10 | Compacted Fill | 6,13,7 | 75.5 |
| Region 11 | | 4,5,6,3 | 138 |
| Region 12 | Sands (1) - Improved | 38,11,39,35,27 | 216.52 |
| Region 13 | Sands (2) | 14,15,34,35 | 3,210 |
| Region 14 | Sands (3) | 15,16,33,34 | 3,424 |
| Region 15 | Silts/Clays | 16,17,32,33 | 4,066 |
| Region 16 | Sands (4) | 17,18,31,32 | 3,638 |
| Region 17 | Sands (4) - Improved | 26,30,32,31 | 1,224 |
| Region 18 | Silts/Clays - Improved | 30,29,33,32 | 1,368 |
| Region 19 | Sands (3) - Improved | 29,28,34,33 | 1,152 |
| Region 20 | Sands (2) - Improved | 28,27,35,34 | 1,080 |
| Region 21 | Sands (1) | 8,9,10,14,35,39,13,7 | 827.48 |

# 3. Post Seismic

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Colton W. McInelly
Last Edited By: Heidi Cashman
Revision Number: 126
Date: 9/29/2017
Time: 11:12:51 AM
Tool Version: 8.16.1.13452
File Name: 5) Station 103_80.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 3. Post Seismic

Kind: SLOPE/W
Method: Morgenstern-Price
Settings
Side Function
Interslice force function option: Half-Sine
PWP Conditions Source: Piezometric Line
Apply Phreatic Correction: No
Use Staged Rapid Drawdown: No
Slip Surface
Direction of movement: Right to Left
Use Passive Mode: No
Slip Surface Option: Entry and Exit
Critical slip surfaces saved: 1
Resisting Side Maximum Convex Angle: 1 °
Driving Side Maximum Convex Angle: 5 °
Optimize Critical Slip Surface Location: No
Tension Crack

Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 5 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 0 psf
Phi': 41 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.23
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 6,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (3) - Residual

Model: S=f(overburden)
Unit Weight: 100 pcf
Tau/Sigma Ratio: 0.09
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

### Sands (4) - Residual

Model: S=f(overburden)
Unit Weight: 100 pcf
Tau/Sigma Ratio: 0.09
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl - Seismic

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 3,400 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (1) - Improved

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (2) - Improved

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 348 psf
Phi': 41 °
Phi-B: 0 °
Pore Water Pressure

Piezometric Line: 1

### Silts/Clays - Improved

Model: Mohr-Coulomb
Unit Weight: 95 pcf
Cohesion': 348 psf
Phi': 13 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (3) - Residual Improved

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 5.1 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Sands (4) - Residual Improved

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 348 psf
Phi': 5.1 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-107, 3) ft
Left-Zone Right Coordinate: (-57, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-26, 20) ft
Right-Zone Right Coordinate: (26, 20) ft
Right-Zone Increment: 10
Radius Increments: 10

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

## Piezometric Lines

### Piezometric Line 1

#### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

## Seismic Coefficients

Horz Seismic Coef.: 0.46

## Reinforcements

### Reinforcement 1

Type: Geosynthetic
Outside Point: (-57, 3) ft
Inside Point: (34, 3) ft
Length: 91 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,328 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,328 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

### Reinforcement 2

Type: Geosynthetic
Outside Point: (34, 3) ft
Inside Point: (49, 7) ft
Length: 15.524175 ft
Direction: 194.93 °
F of S Dependent: No
Pullout Resistance: 1,328 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,328 lbs/ft
Max. Pullout Force: 20,616.104 lbs

Factored Tensile Capacity: 33,980 lbs

### Reinforcement 3

Type: Geosynthetic
Outside Point: (-42, 4) ft
Inside Point: (-28, 4) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,250 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,250 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 4

Type: Geosynthetic
Outside Point: (-40, 6) ft
Inside Point: (-26, 6) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,094 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,094 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 5

Type: Geosynthetic
Outside Point: (-38, 8) ft
Inside Point: (-24, 8) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 938 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs

Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 938 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 6

Type: Geosynthetic
Outside Point: (-36, 10) ft
Inside Point: (-22, 10) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 781 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 781 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 7

Type: Geosynthetic
Outside Point: (-34, 12) ft
Inside Point: (-20, 12) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 625 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 625 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 8

Type: Geosynthetic
Outside Point: (-32, 14) ft
Inside Point: (-18, 14) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 469 psf

Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 469 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 9

Type: Geosynthetic
Outside Point: (-30, 16) ft
Inside Point: (-16, 16) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 313 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 313 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 10

Type: Geosynthetic
Outside Point: (-28, 18) ft
Inside Point: (-14, 18) ft
Length: 14 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 156 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 156 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 11

Type: Geosynthetic
Outside Point: (38, 4) ft
Inside Point: (28, 4) ft

Length: 10 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 1,250 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,250 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 12

Type: Geosynthetic
Outside Point: (40, 6) ft
Inside Point: (26, 6) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 1,094 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,094 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 13

Type: Geosynthetic
Outside Point: (38, 8) ft
Inside Point: (24, 8) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 938 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 938 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 14

Type: Geosynthetic
Outside Point: (36, 10) ft
Inside Point: (22, 10) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 781 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 781 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 15

Type: Geosynthetic
Outside Point: (34, 12) ft
Inside Point: (20, 12) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 625 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 625 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 16

Type: Geosynthetic
Outside Point: (32, 14) ft
Inside Point: (18, 14) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 469 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0

Factored Pullout Resistance: 469 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 17

Type: Geosynthetic
Outside Point: (30, 16) ft
Inside Point: (16, 16) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 313 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 313 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

### Reinforcement 18

Type: Geosynthetic
Outside Point: (28, 18) ft
Inside Point: (14, 18) ft
Length: 14 ft
Direction: 0 °
F of S Dependent: No
Pullout Resistance: 156 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 960 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 156 lbs/ft
Max. Pullout Force: 960 lbs
Factored Tensile Capacity: 960 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -250 | 3 |
| Point 2 | -57 | 3 |
| Point 3 | -26 | 20 |
| Point 4 | -20 | 23 |
| Point 5 | 20 | 23 |
| Point 6 | 26 | 20 |

| | | |
|---|---|---|
| Point 7 | 49 | 7 |
| Point 8 | 82 | 7 |
| Point 9 | 94 | 3 |
| Point 10 | 250 | 3 |
| Point 11 | 34 | 3 |
| Point 12 | -43 | 3 |
| Point 13 | 41.1 | 4.9 |
| Point 14 | 250 | 0 |
| Point 15 | 250 | -15 |
| Point 16 | 250 | -31 |
| Point 17 | 250 | -50 |
| Point 18 | 250 | -67 |
| Point 19 | 250 | -77 |
| Point 20 | -250 | -77 |
| Point 21 | -250 | -67 |
| Point 22 | -250 | -50 |
| Point 23 | -250 | -31 |
| Point 24 | -250 | -15 |
| Point 25 | -250 | 0 |
| Point 26 | -36 | -67 |
| Point 27 | -36 | 0 |
| Point 28 | -36 | -15 |
| Point 29 | -36 | -31 |
| Point 30 | -36 | -50 |

| | | |
|---|---|---|
| Point 31 | 36 | -67 |
| Point 32 | 36 | -50 |
| Point 33 | 36 | -31 |
| Point 34 | 36 | -15 |
| Point 35 | 36 | 0 |
| Point 36 | -250 | -100 |
| Point 37 | 250 | -100 |
| Point 38 | -36 | 3 |
| Point 39 | 36 | 3.52 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 12,3,6,13,39,11,38 | 1,164.5 |
| Region 2 | Sands (1) | 1,2,12,38,27,25 | 642 |
| Region 3 | Sands (2) | 25,27,28,24 | 3,210 |
| Region 4 | Sands (3) - Residual | 24,28,29,23 | 3,424 |
| Region 5 | Silts/Clays | 23,29,30,22 | 4,066 |
| Region 6 | Sands (4) - Residual | 22,30,26,21 | 3,638 |
| Region 7 | Hawthorn Marl - Seismic | 21,26,31,18,19,20 | 5,000 |
| Region 8 | Cooper Group Limestone | 20,19,37,36 | 11,500 |
| Region 9 | Compacted Fill | 2,12,3 | 119 |
| Region 10 | Compacted Fill | 6,13,7 | 75.5 |
| Region 11 | | 4,5,6,3 | 138 |
| Region 12 | Sands (1) - Improved | 38,11,39,35,27 | 216.52 |
| Region 13 | Sands (2) | 14,15,34,35 | 3,210 |
| Region 14 | Sands (3) - Residual | 15,16,33,34 | 3,424 |
| Region 15 | Silts/Clays | 16,17,32,33 | 4,066 |
| Region 16 | Sands (4) - Residual | 17,18,31,32 | 3,638 |
| Region 17 | Sands (4) - Residual Improved | 26,30,32,31 | 1,224 |
| Region 18 | Silts/Clays - Improved | 30,29,33,32 | 1,368 |
| Region 19 | Sands (3) - Residual Improved | 29,28,34,33 | 1,152 |
| Region 20 | Sands (2) - Improved | 28,27,35,34 | 1,080 |
| Region 21 | Sands (1) | 8,9,10,14,35,39,13,7 | 827.48 |

# 1. Static - Preload

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Colton W. McInelly
Last Edited By: Heidi Cashman
Revision Number: 136
Date: 9/29/2017
Time: 11:51:20 AM
Tool Version: 8.16.1.13452
File Name: 6) Station 104_55.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 1. Static - Preload

Kind: SLOPE/W
Method: Morgenstern-Price
Settings
Side Function
Interslice force function option: Half-Sine
PWP Conditions Source: Piezometric Line
Apply Phreatic Correction: No
Use Staged Rapid Drawdown: No
Slip Surface
Direction of movement: Right to Left
Use Passive Mode: No
Slip Surface Option: Entry and Exit
Critical slip surfaces saved: 1
Resisting Side Maximum Convex Angle: 1 °
Driving Side Maximum Convex Angle: 5 °
Optimize Critical Slip Surface Location: No
Tension Crack

Tension Crack Option: (none)

F of S Distribution

F of S Calculation Option: Constant

Advanced

Number of Slices: 30

F of S Tolerance: 0.001

Minimum Slip Surface Depth: 5 ft

Search Method: Root Finder

Tolerable difference between starting and converged F of S: 3

Maximum iterations to calculate converged lambda: 20

Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb

Unit Weight: 125 pcf

Cohesion': 0 psf

Phi': 38 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb

Unit Weight: 100 pcf

Cohesion': 0 psf

Phi': 30 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb

Unit Weight: 120 pcf

Cohesion': 0 psf

Phi': 41 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

## Sands (3)

Model: Mohr-Coulomb

Unit Weight: 100 pcf

Cohesion': 0 psf

Phi': 30 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

### Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.22
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

### Sands (4)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 4,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 6,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-107, 3) ft
Left-Zone Right Coordinate: (-57, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-20, 21) ft
Right-Zone Right Coordinate: (20, 21) ft
Right-Zone Increment: 8
Radius Increments: 10

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

# Piezometric Lines

## Piezometric Line 1

### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

# Reinforcements

## Reinforcement 1

Type: Geosynthetic
Outside Point: (-57.00077, 3) ft
Inside Point: (40.97119, 3) ft
Length: 97.97196 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,406 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,406 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

# Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -250 | 3 |
| Point 2 | -56 | 3 |
| Point 3 | -26 | 18 |
| Point 4 | -20 | 21 |
| Point 5 | 20 | 21 |
| Point 6 | 26 | 18 |
| Point 7 | 56 | 3 |
| Point 8 | 82 | 7 |
| Point 9 | 94 | 3 |
| | | |

| | | |
|---|---|---|
| Point 10 | 250 | 3 |
| Point 11 | 41.1 | 3.00137 |
| Point 12 | -41 | 3 |
| Point 13 | 250 | 0 |
| Point 14 | 250 | -15 |
| Point 15 | 250 | -37 |
| Point 16 | 250 | -53 |
| Point 17 | 250 | -67 |
| Point 18 | 250 | -77 |
| Point 19 | -250 | -77 |
| Point 20 | -250 | -67 |
| Point 21 | -250 | -53 |
| Point 22 | -250 | -37 |
| Point 23 | -250 | -15 |
| Point 24 | -250 | 0 |
| Point 25 | -56 | -67 |
| Point 26 | -56 | 0 |
| Point 27 | -56.01575 | -15 |
| Point 28 | -56 | -37 |
| Point 29 | -56 | -53 |
| Point 30 | 56 | -67 |
| Point 31 | 56 | -53 |
| Point 32 | 56 | -37 |
| Point 33 | 56 | -15 |

| | | |
|---|---|---|
| Point 34 | 56 | 0 |
| Point 35 | -250 | -100 |
| Point 36 | 250 | -100 |
| Point 37 | 48 | 7 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 12,3,6,11 | 1,005.7 |
| Region 2 | Sands (1) | 1,2,26,24 | 582 |
| Region 3 | Sands (2) | 24,26,27,23 | 2,909.9 |
| Region 4 | Sands (3) | 23,27,28,22 | 4,267.8 |
| Region 5 | Silts/Clays | 22,28,29,21 | 3,104 |
| Region 6 | Sands (4) | 21,29,25,20 | 2,716 |
| Region 7 | Hawthorn Marl | 20,25,30,17,18,19 | 5,000 |
| Region 8 | Cooper Group Limestone | 19,18,36,35 | 11,500 |
| Region 9 | Compacted Fill | 2,12,3 | 112.5 |
| Region 10 | Compacted Fill | 6,11,37 | 81.935 |
| Region 11 | Compacted Fill | 4,5,6,3 | 138 |
| Region 12 | Sands (1) | 12,11,7,34,26,2 | 336.07 |
| Region 13 | Sands (2) | 13,14,33,34 | 2,910 |
| Region 14 | Sands (3) | 14,15,32,33 | 4,268 |
| Region 15 | Silts/Clays | 15,16,31,32 | 3,104 |
| Region 16 | Sands (4) | 16,17,30,31 | 2,716 |
| Region 17 | Sands (4) | 25,29,31,30 | 1,568 |
| Region 18 | Silts/Clays | 29,28,32,31 | 1,792 |
| Region 19 | Sands (3) | 28,27,33,32 | 2,464.2 |
| Region 20 | Sands (2) | 27,26,34,33 | 1,680.1 |
| Region 21 | Sands (1) | 8,9,10,13,34,7,37 | 726 |
| Region 22 | Sands (1) | 7,37,11 | 29.795 |

# 2. Static - Trafic

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Colton W. McInelly
Last Edited By: Heidi Cashman
Revision Number: 136
Date: 9/29/2017
Time: 11:51:20 AM
Tool Version: 8.16.1.13452
File Name: 6) Station 104_55.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 2. Static - Trafic

Kind: SLOPE/W
Method: Morgenstern-Price
Settings
- Side Function
  - Interslice force function option: Half-Sine
- PWP Conditions Source: Piezometric Line
- Apply Phreatic Correction: No
- Use Staged Rapid Drawdown: No

Slip Surface
- Direction of movement: Right to Left
- Use Passive Mode: No
- Slip Surface Option: Entry and Exit
- Critical slip surfaces saved: 1
- Resisting Side Maximum Convex Angle: 1 °
- Driving Side Maximum Convex Angle: 5 °
- Optimize Critical Slip Surface Location: No
- Tension Crack

Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 5 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 0 psf
Phi': 41 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (3)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.22
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

### Sands (4)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 30 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 4,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 6,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-107, 3) ft
Left-Zone Right Coordinate: (-57, 3) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-26, 18) ft
Right-Zone Right Coordinate: (26, 18) ft
Right-Zone Increment: 10
Radius Increments: 10

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

# Piezometric Lines

## Piezometric Line 1

### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

# Surcharge Loads

## Surcharge Load 1

Surcharge (Unit Weight): 400 pcf
Direction: Vertical

### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| | -26 | 18 |
| | -26 | 19 |
| | 26 | 19 |

# Reinforcements

## Reinforcement 1

Type: Geosynthetic
Outside Point: (-57.00077, 3) ft
Inside Point: (40.97119, 3) ft
Length: 97.97196 ft
Direction: 180 °
F of S Dependent: No
Pullout Resistance: 1,172 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: No
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 1,172 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -250 | 3 |
| Point 2 | -56 | 3 |
| Point 3 | -26 | 18 |
| Point 4 | -20 | 21 |
| Point 5 | 20 | 21 |
| Point 6 | 26 | 18 |
| Point 7 | 56 | 3 |
| Point 8 | 82 | 7 |
| Point 9 | 94 | 3 |
| Point 10 | 250 | 3 |
| Point 11 | 41.1 | 3.00137 |
| Point 12 | -41 | 3 |
| Point 13 | 250 | 0 |
| Point 14 | 250 | -15 |
| Point 15 | 250 | -37 |
| Point 16 | 250 | -53 |
| Point 17 | 250 | -67 |
| Point 18 | 250 | -77 |
| Point 19 | -250 | -77 |
| Point 20 | -250 | -67 |
| Point 21 | -250 | -53 |
| Point 22 | -250 | -37 |
| Point 23 | -250 | -15 |
| Point 24 | -250 | 0 |
| Point 25 | -56 | -67 |
| Point 26 | -56 | 0 |
| Point 27 | -56.01575 | -15 |
| Point 28 | -56 | -37 |
| Point 29 | -56 | -53 |
| Point 30 | 56 | -67 |
| Point 31 | 56 | -53 |
| Point 32 | 56 | -37 |
| Point 33 | 56 | -15 |
| Point 34 | 56 | 0 |
| Point 35 | -250 | -100 |
| Point 36 | 250 | -100 |
| Point 37 | 48 | 7 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| | | | |

| | | | |
|---|---|---|---|
| Region 1 | Compacted Fill | 12,3,6,11 | 1,005.7 |
| Region 2 | Sands (1) | 1,2,26,24 | 582 |
| Region 3 | Sands (2) | 24,26,27,23 | 2,909.9 |
| Region 4 | Sands (3) | 23,27,28,22 | 4,267.8 |
| Region 5 | Silts/Clays | 22,28,29,21 | 3,104 |
| Region 6 | Sands (4) | 21,29,25,20 | 2,716 |
| Region 7 | Hawthorn Marl | 20,25,30,17,18,19 | 5,000 |
| Region 8 | Cooper Group Limestone | 19,18,36,35 | 11,500 |
| Region 9 | Compacted Fill | 2,12,3 | 112.5 |
| Region 10 | Compacted Fill | 6,11,37 | 81.935 |
| Region 11 | | 4,5,6,3 | 138 |
| Region 12 | Sands (1) | 12,11,7,34,26,2 | 336.07 |
| Region 13 | Sands (2) | 13,14,33,34 | 2,910 |
| Region 14 | Sands (3) | 14,15,32,33 | 4,268 |
| Region 15 | Silts/Clays | 15,16,31,32 | 3,104 |
| Region 16 | Sands (4) | 16,17,30,31 | 2,716 |
| Region 17 | Sands (4) | 25,29,31,30 | 1,568 |
| Region 18 | Silts/Clays | 29,28,32,31 | 1,792 |
| Region 19 | Sands (3) | 28,27,33,32 | 2,464.2 |
| Region 20 | Sands (2) | 27,26,34,33 | 1,680.1 |
| Region 21 | Sands (1) | 8,9,10,13,34,7,37 | 726 |
| Region 22 | Sands (1) | 7,37,11 | 29.795 |

# 1. Static - Preload

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Colton W. McInelly
Last Edited By: Heidi Cashman
Revision Number: 129
Date: 9/29/2017
Time: 12:15:42 PM
Tool Version: 8.16.1.13452
File Name: 7) Station 112+00.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 1. Static - Preload

Kind: SLOPE/W
Method: Morgenstern-Price
Settings
Side Function
Interslice force function option: Half-Sine
PWP Conditions Source: Piezometric Line
Apply Phreatic Correction: No
Use Staged Rapid Drawdown: No
Slip Surface
Direction of movement: Right to Left
Use Passive Mode: No
Slip Surface Option: Entry and Exit
Critical slip surfaces saved: 1
Resisting Side Maximum Convex Angle: 1 °
Driving Side Maximum Convex Angle: 5 °
Optimize Critical Slip Surface Location: No
Tension Crack

Tension Crack Option: (none)

F of S Distribution

F of S Calculation Option: Constant

Advanced

Number of Slices: 30

F of S Tolerance: 0.001

Minimum Slip Surface Depth: 0.1 ft

Search Method: Root Finder

Tolerable difference between starting and converged F of S: 3

Maximum iterations to calculate converged lambda: 20

Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb

Unit Weight: 125 pcf

Cohesion': 0 psf

Phi': 38 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb

Unit Weight: 100 pcf

Cohesion': 0 psf

Phi': 32 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb

Unit Weight: 120 pcf

Cohesion': 0 psf

Phi': 40 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

## Sands (3)

Model: Mohr-Coulomb

Unit Weight: 120 pcf

Cohesion': 0 psf

Phi': 42 °

Phi-B: 0 °

Pore Water Pressure

Piezometric Line: 1

### Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.22
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

### Sands (4)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 31 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 4,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 6,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-84, 3) ft
Left-Zone Right Coordinate: (-34, 8) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-20, 15.5) ft
Right-Zone Right Coordinate: (10, 13.5) ft
Right-Zone Increment: 6
Radius Increments: 10

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

# Piezometric Lines

## Piezometric Line 1

### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

# Reinforcements

## Reinforcement 1

Type: Geosynthetic
Outside Point: (-34, 8) ft
Inside Point: (10, 3) ft
Length: 44.28318 ft
Direction: 173.52 °
F of S Dependent: Yes
Pullout Resistance: 781 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: Yes
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 781 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

# Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -250 | 3 |
| Point 2 | 250 | 3 |
| Point 3 | 250 | -2 |
| Point 4 | 250 | -15 |
| Point 5 | 250 | -58 |
| Point 6 | 250 | -60 |
| Point 7 | 250 | -61 |
| Point 8 | 250 | -77 |
| Point 9 | -250 | -77 |
| | | |

| | | |
|---|---|---|
| Point 10 | -250 | -61 |
| Point 11 | -250 | -60 |
| Point 12 | -250 | -58 |
| Point 13 | -250 | -15 |
| Point 14 | -250 | -2 |
| Point 15 | -250 | -100 |
| Point 16 | 250 | -100 |
| Point 17 | -80 | 3 |
| Point 18 | -50 | 7 |
| Point 19 | -34 | 8 |
| Point 20 | -26 | 12 |
| Point 21 | -20 | 15.5 |
| Point 22 | 10 | 13.5 |
| Point 23 | 17 | 9 |
| Point 24 | 22 | 9 |
| Point 25 | 54 | 6.5 |
| Point 26 | 70 | 3 |
| Point 27 | -22 | 6.5 |
| Point 28 | -13 | 6 |
| Point 29 | -3 | 4 |
| Point 30 | 3 | 5 |
| Point 31 | 250 | 0 |
| Point 32 | -250 | 0 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 19,20,23,30,29,28,27 | 213.25 |
| Region 2 | Sands (1) | 1,17,18,19,27,28,29,30,23,24,25,26,2,31,32 | 2,007.3 |
| Region 3 | Sands (2) | 14,13,4,3 | 6,500 |
| Region 4 | Sands (3) | 13,12,5,4 | 21,500 |
| Region 5 | Silts/Clays | 12,11,6,5 | 1,000 |
| Region 6 | Sands (4) | 11,10,7,6 | 500 |
| Region 7 | Hawthorn Marl | 10,7,8,9 | 8,000 |
| Region 8 | Cooper Group Limestone | 9,8,16,15 | 11,500 |
| Region 9 | Compacted Fill | 21,22,23,20 | 144.75 |
| Region 10 | Sands (1) | 32,31,3,14 | 1,000 |

# 2. Static - Traffic

Report generated using GeoStudio 2016. Copyright © 1991-2016 GEO-SLOPE International Ltd.

## File Information

File Version: 8.16
Created By: Colton W. McInelly
Last Edited By: Heidi Cashman
Revision Number: 129
Date: 9/29/2017
Time: 12:15:42 PM
Tool Version: 8.16.1.13452
File Name: 7) Station 112+00.gsz
Directory: Z:\18461-007-01 (US 21 Harbor River Bridge Design Phase)\3 - Technical Analysis\Slope-W\

## Project Settings

Length(L) Units: Feet
Time(t) Units: Seconds
Force(F) Units: Pounds
Pressure(p) Units: psf
Strength Units: psf
Unit Weight of Water: 62.4 pcf
View: 2D
Element Thickness: 1

## Analysis Settings

### 2. Static - Traffic

Kind: SLOPE/W
Method: Morgenstern-Price
Settings
- Side Function
  - Interslice force function option: Half-Sine
- PWP Conditions Source: Piezometric Line
- Apply Phreatic Correction: No
- Use Staged Rapid Drawdown: No

Slip Surface
- Direction of movement: Right to Left
- Use Passive Mode: No
- Slip Surface Option: Entry and Exit
- Critical slip surfaces saved: 1
- Resisting Side Maximum Convex Angle: 1 °
- Driving Side Maximum Convex Angle: 5 °
- Optimize Critical Slip Surface Location: No
- Tension Crack

Tension Crack Option: (none)
F of S Distribution
F of S Calculation Option: Constant
Advanced
Number of Slices: 30
F of S Tolerance: 0.001
Minimum Slip Surface Depth: 0.1 ft
Search Method: Root Finder
Tolerable difference between starting and converged F of S: 3
Maximum iterations to calculate converged lambda: 20
Max Absolute Lambda: 2

# Materials

## Compacted Fill

Model: Mohr-Coulomb
Unit Weight: 125 pcf
Cohesion': 0 psf
Phi': 38 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (1)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 32 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (2)

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 0 psf
Phi': 40 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Sands (3)

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 0 psf
Phi': 42 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Silts/Clays

Model: S=f(overburden)
Unit Weight: 95 pcf
Tau/Sigma Ratio: 0.22
Minimum Strength: 0 psf
Pore Water Pressure
Piezometric Line: 1

### Sands (4)

Model: Mohr-Coulomb
Unit Weight: 100 pcf
Cohesion': 0 psf
Phi': 31 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Hawthorn Marl

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 4,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

### Cooper Group Limestone

Model: Mohr-Coulomb
Unit Weight: 120 pcf
Cohesion': 6,000 psf
Phi': 0 °
Phi-B: 0 °
Pore Water Pressure
Piezometric Line: 1

## Slip Surface Entry and Exit

Left Projection: Range
Left-Zone Left Coordinate: (-84, 3) ft
Left-Zone Right Coordinate: (-34, 8) ft
Left-Zone Increment: 10
Right Projection: Range
Right-Zone Left Coordinate: (-26, 12) ft
Right-Zone Right Coordinate: (17, 9) ft
Right-Zone Increment: 9
Radius Increments: 10

## Slip Surface Limits

Left Coordinate: (-250, 3) ft
Right Coordinate: (250, 3) ft

# Piezometric Lines

## Piezometric Line 1

### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| Coordinate 1 | -250 | 0 |
| Coordinate 2 | 250 | 0 |

# Surcharge Loads

## Surcharge Load 1

Surcharge (Unit Weight): 400 pcf
Direction: Normal

### Coordinates

| | X (ft) | Y (ft) |
|---|---|---|
| | -26 | 12 |
| | -26 | 13 |
| | 17 | 10 |

# Reinforcements

## Reinforcement 1

Type: Geosynthetic
Outside Point: (-34, 8) ft
Inside Point: (10, 3) ft
Length: 44.28318 ft
Direction: 173.52 °
F of S Dependent: Yes
Pullout Resistance: 781 psf
Resistance Reduction Factor: 1
Force Distribution: Distributed
Anchorage: Yes
Tensile Capacity: 33,980 lbs
Reduction Factor: 1
Force Orientation: 0
Factored Pullout Resistance: 781 lbs/ft
Max. Pullout Force: 33,980 lbs
Factored Tensile Capacity: 33,980 lbs

## Points

| | X (ft) | Y (ft) |
|---|---|---|
| Point 1 | -250 | 3 |
| Point 2 | 250 | 3 |
| Point 3 | 250 | -2 |
| Point 4 | 250 | -15 |
| Point 5 | 250 | -58 |
| Point 6 | 250 | -60 |
| Point 7 | 250 | -61 |
| Point 8 | 250 | -77 |
| Point 9 | -250 | -77 |
| Point 10 | -250 | -61 |
| Point 11 | -250 | -60 |
| Point 12 | -250 | -58 |
| Point 13 | -250 | -15 |
| Point 14 | -250 | -2 |
| Point 15 | -250 | -100 |
| Point 16 | 250 | -100 |
| Point 17 | -80 | 3 |
| Point 18 | -50 | 7 |
| Point 19 | -34 | 8 |
| Point 20 | -26 | 12 |
| Point 21 | -20 | 15.5 |
| Point 22 | 10 | 13.5 |
| Point 23 | 17 | 9 |
| Point 24 | 22 | 9 |
| Point 25 | 54 | 6.5 |
| Point 26 | 70 | 3 |
| Point 27 | -22 | 6.5 |
| Point 28 | -13 | 6 |
| Point 29 | -3 | 4 |
| Point 30 | 3 | 5 |
| Point 31 | 250 | 0 |
| Point 32 | -250 | 0 |

## Regions

| | Material | Points | Area (ft²) |
|---|---|---|---|
| Region 1 | Compacted Fill | 19,20,23,30,29,28,27 | 213.25 |
| Region 2 | Sands (1) | 1,17,18,19,27,28,29,30,23,24,25,26,2,31,32 | 2,007.3 |
| Region 3 | Sands (2) | 14,13,4,3 | 6,500 |
| Region 4 | Sands (3) | 13,12,5,4 | 21,500 |
| Region 5 | Silts/Clays | 12,11,6,5 | 1,000 |
| | | | |

| | | | |
|---|---|---|---|
| Region 6 | Sands (4) | 11,10,7,6 | 500 |
| Region 7 | Hawthorn Marl | 10,7,8,9 | 8,000 |
| Region 8 | Cooper Group Limestone | 9,8,16,15 | 11,500 |
| Region 9 | | 21,22,23,20 | 144.75 |
| Region 10 | Sands (1) | 32,31,3,14 | 1,000 |

# APPENDIX F
## Global Stability Analyses

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:59 PM |
| Boring Designation: | B-1 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | 8 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 82 |
| Distance from sample hammer to ground surface (ft): | 5 |
| Borehole Diameter (in) | 6 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.26 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 8 | SP-SM | 8 | 100 | | Unsaturated |
| 2 | 4.0 | 7 | SP-SM | 8 | 100 | | Unsaturated |
| 3 | 6.0 | 6 | SP-SM | 8 | 100 | | Unsaturated |
| 4 | 8.0 | 6 | SP-SM | 8 | 100 | | |
| 5 | 10.0 | 3 | SP-SM | 8 | 100 | | |
| 6 | 12.0 | 4 | SP-SM | 8 | 100 | | |
| 7 | 14.0 | 8 | SP-SM | 8 | 100 | | |
| 8 | 16.0 | 2 | SP-SM | 8 | 100 | | |
| 9 | 18.0 | 2 | SP | 3 | 100 | | |
| 10 | 23.5 | 2 | SP | 3 | 100 | | |
| 11 | 28.5 | 4 | SP-SM | 7 | 100 | | |
| 12 | 33.5 | 4 | SP-SM | 7 | 100 | | |
| 13 | 38.5 | 3 | SP-SM | 7 | 100 | | |
| 14 | 43.5 | 1 | SP-SM | 11 | 100 | | |
| 15 | 48.5 | 1 | SM | 33 | 100 | | |
| 16 | 53.5 | 14 | ML | 50 | 120 | | Clay |
| 17 | 55.0 | 34 | ML | 50 | 120 | | Clay |
| 18 | 58.5 | 7 | ML | 50 | 120 | | Clay |
| 19 | 63.5 | 6 | ML | 50 | 120 | | Clay |
| 20 | 65.0 | 7 | ML | 50 | 120 | | Clay |
| 21 | 66.5 | 10 | ML | 50 | 120 | | Clay |
| 22 | 68.5 | 12 | ML | 50 | 120 | | Clay |
| 23 | 73.5 | 11 | ML | 50 | 120 | | Clay |
| 24 | 78.5 | 23 | ML | 50 | 120 | | Clay |
| 25 | 83.5 | 3 | SM | 15 | 120 | | Clay |
| 26 | 88.5 | 10 | SM | 15 | 120 | | Clay |
| 27 | 93.5 | 11 | SM | 15 | 120 | | Clay |
| 28 | 100.0 | 25 | SM | 15 | 120 | | Clay |
| 29 | 103.5 | 10 | SM | 15 | 120 | | Clay |
| 30 | 108.5 | 9 | SM | 15 | 120 | | Clay |
| 31 | 113.5 | 12 | SM | 15 | 120 | | Clay |
| 32 | 118.5 | 12 | SM | 15 | 120 | | Clay |
| 33 | 123.5 | 16 | SM | 15 | 120 | | Clay |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

**Liquefaction Calculations B-1 (SEE)**

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 8.0 | SP-SM | 8.0 | 100.0 | Unsaturated | 200 | 200 | 1.37 | 1.15 | 0.75 | 1.00 | 9.43 | 1.70 | 16.03 | 0.37 | 16.40 | 1.002 | 0.169 |
| 2 | 4.0 | 7.0 | SP-SM | 8.0 | 100.0 | Unsaturated | 400 | 400 | 1.37 | 1.15 | 0.75 | 1.00 | 8.25 | 1.70 | 14.03 | 0.37 | 14.39 | 0.997 | 0.168 |
| 3 | 6.0 | 6.0 | SP-SM | 8.0 | 100.0 | Unsaturated | 600 | 600 | 1.37 | 1.15 | 0.80 | 1.00 | 7.54 | 1.70 | 12.82 | 0.37 | 13.19 | 0.991 | 0.167 |
| 4 | 8.0 | 6.0 | SP-SM | 8.0 | 100.0 | | 800 | 800 | 1.37 | 1.15 | 0.80 | 1.00 | 7.54 | 1.64 | 12.39 | 0.37 | 12.75 | 0.985 | 0.166 |
| 5 | 10.0 | 3.0 | SP-SM | 8.0 | 100.0 | | 1000 | 875 | 1.37 | 1.15 | 0.85 | 1.00 | 4.01 | 1.67 | 6.69 | 0.37 | 7.06 | 0.978 | 0.189 |
| 6 | 12.0 | 4.0 | SP-SM | 8.0 | 100.0 | | 1200 | 950 | 1.37 | 1.15 | 0.85 | 1.00 | 5.34 | 1.56 | 8.35 | 0.37 | 8.72 | 0.971 | 0.207 |
| 7 | 14.0 | 8.0 | SP-SM | 8.0 | 100.0 | | 1400 | 1026 | 1.37 | 1.15 | 0.85 | 1.00 | 10.69 | 1.42 | 15.15 | 0.37 | 15.51 | 0.964 | 0.222 |
| 8 | 16.0 | 2.0 | SP-SM | 8.0 | 100.0 | | 1600 | 1101 | 1.37 | 1.15 | 0.95 | 1.00 | 2.99 | 1.49 | 4.46 | 0.37 | 4.83 | 0.957 | 0.235 |
| 9 | 18.0 | 2.0 | SP | 3.3 | 100.0 | | 1800 | 1176 | 1.37 | 1.15 | 0.95 | 1.00 | 2.99 | 1.44 | 4.31 | 0.00 | 4.31 | 0.949 | 0.245 |
| 10 | 23.5 | 2.0 | SP | 3.3 | 100.0 | | 2350 | 1383 | 1.37 | 1.15 | 0.95 | 1.00 | 2.99 | 1.31 | 3.91 | 0.00 | 3.91 | 0.926 | 0.266 |
| 11 | 28.5 | 4.0 | SP-SM | 7.4 | 100.0 | | 2850 | 1571 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 1.19 | 7.45 | 0.21 | 7.67 | 0.903 | 0.277 |
| 12 | 33.5 | 4.0 | SP-SM | 7.0 | 100.0 | | 3350 | 1759 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 1.11 | 7.00 | 0.14 | 7.13 | 0.879 | 0.283 |
| 13 | 38.5 | 3.0 | SP-SM | 7.0 | 100.0 | | 3850 | 1947 | 1.37 | 1.15 | 1.00 | 1.00 | 4.72 | 1.05 | 4.96 | 0.14 | 5.10 | 0.855 | 0.286 |
| 14 | 43.5 | 1.0 | SP-SM | 11.0 | 100.0 | | 4350 | 2135 | 1.37 | 1.15 | 1.00 | 1.00 | 1.57 | 0.99 | 1.56 | 1.61 | 3.17 | 0.830 | 0.286 |
| 15 | 48.5 | 1.0 | SM | 33.2 | 100.0 | | 4850 | 2323 | 1.37 | 1.15 | 1.00 | 1.00 | 1.57 | 0.95 | 1.49 | 5.47 | 6.95 | 0.805 | 0.284 |
| 16 | 53.5 | 14.0 | ML | 50.0 | 120.0 | Clay | 5450 | 2611 | 1.37 | 1.15 | 1.00 | 1.00 | 22.00 | 0.92 | 20.26 | 5.61 | 25.87 | 0.781 | 0.275 |
| 17 | 55.0 | 34.0 | ML | 50.0 | 120.0 | Clay | 5630 | 2697 | 1.37 | 1.15 | 1.00 | 1.00 | 53.44 | 0.94 | 50.13 | 5.61 | 55.75 | 0.773 | 0.273 |
| 18 | 58.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 6050 | 2899 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.86 | 9.44 | 5.61 | 15.06 | 0.757 | 0.267 |
| 19 | 63.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 6650 | 3187 | 1.37 | 1.15 | 1.00 | 1.00 | 9.43 | 0.81 | 7.67 | 5.61 | 13.29 | 0.734 | 0.259 |
| 20 | 65.0 | 7.0 | ML | 50.0 | 120.0 | Clay | 6830 | 3273 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.81 | 8.88 | 5.61 | 14.49 | 0.727 | 0.256 |
| 21 | 66.5 | 10.0 | ML | 50.0 | 120.0 | Clay | 7010 | 3360 | 1.37 | 1.15 | 1.00 | 1.00 | 15.72 | 0.81 | 12.74 | 5.61 | 18.35 | 0.720 | 0.254 |
| 22 | 68.5 | 12.0 | ML | 50.0 | 120.0 | Clay | 7250 | 3475 | 1.37 | 1.15 | 1.00 | 1.00 | 18.86 | 0.81 | 15.21 | 5.61 | 20.83 | 0.712 | 0.251 |
| 23 | 73.5 | 11.0 | ML | 50.0 | 120.0 | Clay | 7850 | 3763 | 1.37 | 1.15 | 1.00 | 1.00 | 17.29 | 0.77 | 13.35 | 5.61 | 18.96 | 0.691 | 0.244 |
| 24 | 78.5 | 23.0 | ML | 50.0 | 120.0 | Clay | 8450 | 4051 | 1.37 | 1.15 | 1.00 | 1.00 | 36.15 | 0.81 | 29.15 | 5.61 | 34.77 | 0.672 | 0.237 |
| 25 | 83.5 | 3.0 | SM | 15.0 | 120.0 | Clay | 9050 | 4339 | 1.37 | 1.15 | 1.00 | 1.00 | 4.72 | 0.65 | 3.09 | 3.26 | 6.35 | 0.654 | 0.231 |
| 26 | 88.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 9650 | 4627 | 1.37 | 1.15 | 1.00 | 1.00 | 15.72 | 0.68 | 10.65 | 3.26 | 13.91 | 0.639 | 0.225 |
| 27 | 93.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 10250 | 4915 | 1.37 | 1.15 | 1.00 | 1.00 | 17.29 | 0.66 | 11.44 | 3.26 | 14.71 | 0.625 | 0.220 |
| 28 | 100.0 | 25.0 | SM | 15.0 | 120.0 | Clay | 11030 | 5289 | 1.37 | 1.15 | 1.00 | 1.00 | 39.29 | 0.72 | 28.48 | 3.26 | 31.74 | 0.610 | 0.215 |
| 29 | 103.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 11450 | 5491 | 1.37 | 1.15 | 1.00 | 1.00 | 15.72 | 0.62 | 9.69 | 3.26 | 12.95 | 0.603 | 0.213 |
| 30 | 108.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 12050 | 5779 | 1.37 | 1.15 | 1.00 | 1.00 | 14.15 | 0.59 | 8.37 | 3.26 | 11.63 | 0.596 | 0.210 |
| 31 | 113.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 12650 | 6067 | 1.37 | 1.15 | 1.00 | 1.00 | 18.86 | 0.60 | 11.24 | 3.26 | 14.50 | 0.590 | 0.208 |
| 32 | 118.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 13250 | 6355 | 1.37 | 1.15 | 1.00 | 1.00 | 18.86 | 0.58 | 10.95 | 3.26 | 14.21 | 0.587 | 0.207 |
| 33 | 123.5 | 16.0 | SM | 15.0 | 120.0 | Clay | 13850 | 6643 | 1.37 | 1.15 | 1.00 | 1.00 | 25.15 | 0.59 | 14.92 | 3.26 | 18.18 | 0.586 | 0.207 |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

**Liquefaction Calculations B-1 (SEE)**

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.36 | 1.02 | 1.10 | 0.168 | 0.190 | 2.00 |
| 1.30 | 1.02 | 1.10 | 0.151 | 0.170 | 2.00 |
| 1.27 | 1.02 | 1.10 | 0.142 | 0.158 | 2.00 |
| 1.25 | 1.02 | 1.10 | 0.138 | 0.154 | 0.93 |
| 1.14 | 1.01 | 1.07 | 0.099 | 0.107 | 0.56 |
| 1.17 | 1.01 | 1.07 | 0.109 | 0.118 | 0.57 |
| 1.33 | 1.02 | 1.08 | 0.161 | 0.178 | 0.80 |
| 1.11 | 1.01 | 1.05 | 0.085 | 0.090 | 0.38 |
| 1.11 | 1.01 | 1.04 | 0.082 | 0.086 | 0.35 |
| 1.11 | 1.01 | 1.03 | 0.080 | 0.083 | 0.31 |
| 1.15 | 1.01 | 1.03 | 0.102 | 0.106 | 0.38 |
| 1.14 | 1.01 | 1.02 | 0.099 | 0.102 | 0.36 |
| 1.12 | 1.01 | 1.01 | 0.087 | 0.088 | 0.31 |
| 1.10 | 1.01 | 1.00 | 0.076 | 0.077 | 0.27 |
| 1.14 | 1.01 | 0.99 | 0.098 | 0.098 | 0.35 |
| 1.76 | 1.05 | 0.96 | 0.312 | 0.317 | 2.00 |
| 2.20 | 1.08 | 0.93 | 2.000 | 2.000 | 2.00 |
| 1.32 | 1.02 | 0.97 | 0.157 | 0.154 | 2.00 |
| 1.27 | 1.02 | 0.96 | 0.142 | 0.139 | 2.00 |
| 1.30 | 1.02 | 0.95 | 0.152 | 0.148 | 2.00 |
| 1.43 | 1.03 | 0.94 | 0.187 | 0.182 | 2.00 |
| 1.53 | 1.04 | 0.93 | 0.216 | 0.209 | 2.00 |
| 1.45 | 1.03 | 0.93 | 0.194 | 0.185 | 2.00 |
| 2.20 | 1.08 | 0.83 | 1.057 | 0.951 | 2.00 |
| 1.13 | 1.01 | 0.94 | 0.094 | 0.090 | 2.00 |
| 1.29 | 1.02 | 0.92 | 0.147 | 0.138 | 2.00 |
| 1.31 | 1.02 | 0.91 | 0.154 | 0.142 | 2.00 |
| 2.11 | 1.08 | 0.80 | 0.619 | 0.531 | 2.00 |
| 1.26 | 1.02 | 0.90 | 0.140 | 0.128 | 2.00 |
| 1.23 | 1.02 | 0.90 | 0.130 | 0.119 | 2.00 |
| 1.30 | 1.02 | 0.89 | 0.152 | 0.137 | 2.00 |
| 1.29 | 1.02 | 0.88 | 0.150 | 0.135 | 2.00 |
| 1.42 | 1.03 | 0.86 | 0.186 | 0.164 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 0.0 | 0.000 | 0.00 | 25.34 |
| 4 | 0.0 | 0.000 | 0.00 | 25.34 |
| 6 | 0.0 | 0.000 | 0.00 | 25.34 |
| 8 | 1.0 | 0.027 | 0.33 | 25.34 |
| 10 | 2.0 | 0.045 | 1.08 | 25.02 |
| 12 | 2.0 | 0.040 | 0.97 | 23.94 |
| 14 | 2.0 | 0.028 | 0.67 | 22.97 |
| 16 | 2.0 | 0.053 | 1.28 | 22.30 |
| 18 | 3.8 | 0.056 | 2.51 | 21.02 |
| 23.5 | 5.3 | 0.058 | 3.65 | 18.51 |
| 28.5 | 5.0 | 0.043 | 2.59 | 14.86 |
| 33.5 | 5.0 | 0.045 | 2.69 | 12.27 |
| 38.5 | 5.0 | 0.052 | 3.13 | 9.58 |
| 43.5 | 5.0 | 0.062 | 3.73 | 6.45 |
| 48.5 | 5.0 | 0.045 | 2.72 | 2.72 |
| 53.5 | 3.3 | 0.000 | 0.00 | 0.00 |
| 55 | 2.5 | 0.000 | 0.00 | 0.00 |
| 58.5 | 4.3 | 0.000 | 0.00 | 0.00 |
| 63.5 | 3.3 | 0.000 | 0.00 | 0.00 |
| 65 | 1.5 | 0.000 | 0.00 | 0.00 |
| 66.5 | 1.8 | 0.000 | 0.00 | 0.00 |
| 68.5 | 3.5 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.8 | 0.000 | 0.00 | 0.00 |
| 100 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 4.3 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 126.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:55 PM |
| Boring Designation: | B-2 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | 6 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 82 |
| Distance from sample hammer to ground surface (ft): | 5 |
| Borehole Diameter (in) | 6 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.29 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 20 | SP | 5 | 100 | | Unsaturated |
| 2 | 4.0 | 6 | SP | 5 | 100 | | Unsaturated |
| 3 | 6.0 | 1 | SP | 5 | 100 | | |
| 4 | 8.0 | 11 | SP | 3 | 100 | | |
| 5 | 10.0 | 18 | SP | 3 | 120 | | |
| 6 | 12.0 | 30 | SP | 3 | 120 | | |
| 7 | 14.0 | 38 | SP | 3 | 120 | | |
| 8 | 16.0 | 21 | SP | 3 | 120 | | |
| 9 | 18.0 | 7 | SP-SM | 6 | 100 | | |
| 10 | 23.5 | 0 | SP-SM | 6 | 100 | | |
| 11 | 28.5 | 1 | SM | 14 | 100 | | |
| 12 | 33.5 | 4 | SM | 14 | 100 | | |
| 13 | 38.5 | 4 | SP-SM | 9 | 100 | | |
| 14 | 43.5 | 19 | SP-SM | 9 | 120 | | |
| 15 | 48.5 | 7 | SP-SM | 9 | 100 | | |
| 16 | 53.5 | 11 | SP-SM | 10 | 100 | | |
| 17 | 58.5 | 2 | SP-SM | 10 | 100 | | |
| 18 | 63.5 | 1 | CL | 50 | 100 | | Clay |
| 19 | 68.5 | 7 | SP-SM | 5 | 100 | | |
| 20 | 73.5 | 5 | ML | 50 | 120 | | Clay |
| 21 | 78.5 | 5 | ML | 50 | 120 | | Clay |
| 22 | 83.5 | 4 | ML | 50 | 120 | | Clay |
| 23 | 88.5 | 32 | SM | 15 | 120 | | Clay |
| 24 | 93.5 | 5 | SM | 15 | 120 | | Clay |
| 25 | 98.5 | 6 | SM | 15 | 120 | | Clay |
| 26 | 103.5 | 4 | SM | 15 | 120 | | Clay |
| 27 | 108.5 | 7 | SM | 15 | 120 | | Clay |
| 28 | 113.5 | 10 | SM | 15 | 120 | | Clay |
| 29 | 118.5 | 7 | SM | 15 | 120 | | Clay |
| 30 | 123.5 | 7 | SM | 15 | 120 | | Clay |
| 31 | | | | | | | Clay |
| 32 | | | | | | | Clay |
| 33 | | | | | | | Clay |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 20.0 | SP | 5.0 | 100.0 | Unsaturated | 200 | 200 | 1.37 | 1.15 | 0.75 | 1.00 | 23.58 | 1.70 | 40.08 | 0.00 | 40.08 | 1.002 | 0.189 |
| 2 | 4.0 | 6.0 | SP | 5.0 | 100.0 | Unsaturated | 400 | 400 | 1.37 | 1.15 | 0.75 | 1.00 | 7.07 | 1.70 | 12.02 | 0.00 | 12.03 | 0.997 | 0.188 |
| 3 | 6.0 | 1.0 | SP | 4.9 | 100.0 | | 600 | 600 | 1.37 | 1.15 | 0.80 | 1.00 | 1.26 | 1.70 | 2.14 | 0.00 | 2.14 | 0.991 | 0.187 |
| 4 | 8.0 | 11.0 | SP | 2.5 | 100.0 | | 800 | 675 | 1.37 | 1.15 | 0.80 | 1.00 | 13.83 | 1.62 | 22.37 | 0.00 | 22.37 | 0.985 | 0.220 |
| 5 | 10.0 | 18.0 | SP | 3.0 | 120.0 | | 1040 | 790 | 1.37 | 1.15 | 0.85 | 1.00 | 24.05 | 1.40 | 33.58 | 0.00 | 33.58 | 0.978 | 0.243 |
| 6 | 12.0 | 30.0 | SP | 3.0 | 120.0 | | 1280 | 906 | 1.37 | 1.15 | 0.85 | 1.00 | 40.08 | 1.25 | 50.10 | 0.00 | 50.10 | 0.971 | 0.259 |
| 7 | 14.0 | 38.0 | SP | 3.0 | 120.0 | | 1520 | 1021 | 1.37 | 1.15 | 0.85 | 1.00 | 50.76 | 1.21 | 61.50 | 0.00 | 61.50 | 0.964 | 0.271 |
| 8 | 16.0 | 21.0 | SP | 3.0 | 120.0 | | 1760 | 1136 | 1.37 | 1.15 | 0.95 | 1.00 | 31.35 | 1.21 | 38.03 | 0.00 | 38.03 | 0.957 | 0.279 |
| 9 | 18.0 | 7.0 | SP-SM | 6.3 | 100.0 | | 1960 | 1211 | 1.37 | 1.15 | 0.95 | 1.00 | 10.45 | 1.32 | 13.80 | 0.05 | 13.85 | 0.949 | 0.289 |
| 10 | 23.5 | 0.0 | SP-SM | 6.0 | 100.0 | | 2510 | 1418 | 1.37 | 1.15 | 0.95 | 1.00 | 0.00 | 1.36 | 0.00 | 0.03 | 0.03 | 0.926 | 0.309 |
| 11 | 28.5 | 1.0 | SM | 14.0 | 100.0 | | 3010 | 1606 | 1.37 | 1.15 | 1.00 | 1.00 | 1.57 | 1.19 | 1.86 | 2.91 | 4.77 | 0.903 | 0.319 |
| 12 | 33.5 | 4.0 | SM | 14.0 | 100.0 | | 3510 | 1794 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 1.09 | 6.88 | 2.91 | 9.78 | 0.879 | 0.324 |
| 13 | 38.5 | 4.0 | SP-SM | 8.8 | 100.0 | | 4010 | 1982 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 1.04 | 6.53 | 0.64 | 7.17 | 0.855 | 0.326 |
| 14 | 43.5 | 19.0 | SP-SM | 9.0 | 120.0 | | 4610 | 2270 | 1.37 | 1.15 | 1.00 | 1.00 | 29.86 | 0.97 | 29.11 | 0.72 | 29.83 | 0.830 | 0.318 |
| 15 | 48.5 | 7.0 | SP-SM | 9.0 | 100.0 | | 5110 | 2458 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.92 | 10.16 | 0.72 | 10.88 | 0.805 | 0.316 |
| 16 | 53.5 | 11.0 | SP-SM | 10.0 | 100.0 | | 5610 | 2646 | 1.37 | 1.15 | 1.00 | 1.00 | 17.29 | 0.90 | 15.56 | 1.15 | 16.71 | 0.781 | 0.312 |
| 17 | 58.5 | 2.0 | SP-SM | 10.0 | 100.0 | | 6110 | 2834 | 1.37 | 1.15 | 1.00 | 1.00 | 3.14 | 0.83 | 2.61 | 1.15 | 3.76 | 0.757 | 0.308 |
| 18 | 63.5 | 1.0 | CL | 50.0 | 100.0 | Clay | 6610 | 3022 | 1.37 | 1.15 | 1.00 | 1.00 | 1.57 | 0.81 | 1.28 | 5.61 | 6.89 | 0.734 | 0.303 |
| 19 | 68.5 | 7.0 | SP-SM | 5.0 | 100.0 | | 7110 | 3210 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.79 | 8.72 | 0.00 | 8.72 | 0.712 | 0.297 |
| 20 | 73.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 7710 | 3498 | 1.37 | 1.15 | 1.00 | 1.00 | 7.86 | 0.77 | 6.05 | 5.61 | 11.66 | 0.691 | 0.287 |
| 21 | 78.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 8310 | 3786 | 1.37 | 1.15 | 1.00 | 1.00 | 7.86 | 0.74 | 5.79 | 5.61 | 11.41 | 0.672 | 0.278 |
| 22 | 83.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 8910 | 4074 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 0.70 | 4.41 | 5.61 | 10.03 | 0.654 | 0.270 |
| 23 | 88.5 | 32.0 | SM | 15.0 | 120.0 | Clay | 9510 | 4362 | 1.37 | 1.15 | 1.00 | 1.00 | 50.29 | 0.82 | 41.34 | 3.26 | 44.60 | 0.639 | 0.263 |
| 24 | 93.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 10110 | 4650 | 1.37 | 1.15 | 1.00 | 1.00 | 7.86 | 0.64 | 5.05 | 3.26 | 8.31 | 0.625 | 0.256 |
| 25 | 98.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 10710 | 4938 | 1.37 | 1.15 | 1.00 | 1.00 | 9.43 | 0.63 | 5.91 | 3.26 | 9.17 | 0.613 | 0.251 |
| 26 | 103.5 | 4.0 | SM | 15.0 | 120.0 | Clay | 11310 | 5226 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 0.59 | 3.72 | 3.26 | 6.98 | 0.603 | 0.246 |
| 27 | 108.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 11910 | 5514 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.59 | 6.54 | 3.26 | 9.80 | 0.596 | 0.243 |
| 28 | 113.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 12510 | 5802 | 1.37 | 1.15 | 1.00 | 1.00 | 15.72 | 0.60 | 9.39 | 3.26 | 12.65 | 0.590 | 0.240 |
| 29 | 118.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 13110 | 6090 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.56 | 6.16 | 3.26 | 9.42 | 0.587 | 0.238 |
| 30 | 123.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 13710 | 6378 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.54 | 5.99 | 3.26 | 9.26 | 0.586 | 0.237 |
| 31 | | | | | | | | | | | | | | | | | | | |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.24 | 1.02 | 1.10 | 0.133 | 0.148 | 2.00 |
| 1.09 | 1.01 | 1.08 | 0.071 | 0.077 | 0.41 |
| 1.59 | 1.04 | 1.10 | 0.239 | 0.273 | 1.24 |
| 2.20 | 1.08 | 1.10 | 0.840 | 1.000 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.28 | 1.02 | 1.06 | 0.147 | 0.158 | 0.55 |
| 1.09 | 1.01 | 1.02 | 0.061 | 0.063 | 0.20 |
| 1.11 | 1.01 | 1.02 | 0.085 | 0.087 | 0.27 |
| 1.19 | 1.01 | 1.02 | 0.117 | 0.120 | 0.37 |
| 1.14 | 1.01 | 1.01 | 0.099 | 0.101 | 0.31 |
| 1.99 | 1.07 | 0.99 | 0.474 | 0.499 | 1.57 |
| 1.21 | 1.01 | 0.99 | 0.124 | 0.124 | 0.39 |
| 1.37 | 1.03 | 0.97 | 0.171 | 0.171 | 0.55 |
| 1.10 | 1.01 | 0.98 | 0.079 | 0.078 | 0.25 |
| 1.14 | 1.01 | 0.97 | 0.098 | 0.096 | 2.00 |
| 1.17 | 1.01 | 0.96 | 0.109 | 0.107 | 0.36 |
| 1.23 | 1.02 | 0.95 | 0.130 | 0.125 | 2.00 |
| 1.22 | 1.02 | 0.94 | 0.128 | 0.123 | 2.00 |
| 1.19 | 1.01 | 0.94 | 0.118 | 0.113 | 2.00 |
| 2.20 | 1.08 | 0.79 | 2.000 | 1.701 | 2.00 |
| 1.16 | 1.01 | 0.93 | 0.107 | 0.100 | 2.00 |
| 1.17 | 1.01 | 0.92 | 0.112 | 0.105 | 2.00 |
| 1.14 | 1.01 | 0.93 | 0.098 | 0.092 | 2.00 |
| 1.19 | 1.01 | 0.91 | 0.117 | 0.108 | 2.00 |
| 1.25 | 1.02 | 0.90 | 0.137 | 0.125 | 2.00 |
| 1.18 | 1.01 | 0.90 | 0.114 | 0.104 | 2.00 |
| 1.18 | 1.01 | 0.90 | 0.113 | 0.103 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 0.0 | 0.000 | 0.00 | 27.39 |
| 4 | 0.0 | 0.000 | 0.00 | 27.39 |
| 6 | 1.0 | 0.070 | 0.84 | 27.39 |
| 8 | 2.0 | 0.005 | 0.12 | 26.55 |
| 10 | 2.0 | 0.000 | 0.00 | 26.43 |
| 12 | 2.0 | 0.000 | 0.00 | 26.43 |
| 14 | 2.0 | 0.000 | 0.00 | 26.43 |
| 16 | 2.0 | 0.000 | 0.00 | 26.43 |
| 18 | 3.8 | 0.030 | 1.37 | 26.43 |
| 23.5 | 5.3 | 0.113 | 7.11 | 25.06 |
| 28.5 | 5.0 | 0.054 | 3.22 | 17.95 |
| 33.5 | 5.0 | 0.038 | 2.27 | 14.73 |
| 38.5 | 5.0 | 0.045 | 2.68 | 12.46 |
| 43.5 | 5.0 | 0.002 | 0.12 | 9.78 |
| 48.5 | 5.0 | 0.036 | 2.13 | 9.67 |
| 53.5 | 5.0 | 0.027 | 1.59 | 7.53 |
| 58.5 | 5.0 | 0.059 | 3.52 | 5.94 |
| 63.5 | 5.0 | 0.000 | 0.00 | 2.42 |
| 68.5 | 5.0 | 0.040 | 2.42 | 2.42 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 126.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 6:00 PM |
| **Boring Designation:** | B-3 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 1 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 80 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.26 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 0 | SM | 38 | 100 | | |
| 2 | 4.0 | 0 | SM | 38 | 100 | | |
| 3 | 6.0 | 0 | MH | 99 | 95 | | Clay |
| 4 | 8.0 | 0 | MH | 99 | 95 | | Clay |
| 5 | 13.5 | 16 | SP-SM | 8 | 100 | | |
| 6 | 18.5 | 1 | SP-SM | 8 | 100 | | |
| 7 | 23.5 | 1 | SM | 25 | 100 | | |
| 8 | 28.5 | 0 | MH | 97 | 95 | | Clay |
| 9 | 33.5 | 0 | SP-SM | 10 | 100 | | |
| 10 | 38.5 | 3 | SP-SM | 10 | 100 | | |
| 11 | 43.5 | 4 | SP-SM | 10 | 100 | | |
| 12 | 48.5 | 7 | ML | 50 | 120 | | Clay |
| 13 | 53.5 | 4 | ML | 50 | 120 | | Clay |
| 14 | 58.5 | 7 | ML | 50 | 120 | | Clay |
| 15 | 63.5 | 5 | ML | 50 | 120 | | Clay |
| 16 | 68.5 | 10 | ML | 50 | 120 | | Clay |
| 17 | 73.5 | 8 | ML | 50 | 120 | | Clay |
| 18 | 78.5 | 6 | SM | 15 | 120 | | Clay |
| 19 | | | | | | | |
| 20 | | | | | | | |
| 21 | | | | | | | |
| 22 | | | | | | | |
| 23 | | | | | | | |
| 24 | | | | | | | |
| 25 | | | | | | | |
| 26 | | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | |
| 29 | | | | | | | |
| 30 | | | | | | | |
| 31 | | | | | | | |
| 32 | | | | | | | |
| 33 | | | | | | | |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 0.0 | SM | 37.5 | 100.0 | | 200 | 106 | 1.33 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.55 | 5.55 | 1.002 | 0.318 |
| 2 | 4.0 | 0.0 | SM | 38.0 | 100.0 | | 400 | 182 | 1.33 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.55 | 5.55 | 0.997 | 0.371 |
| 3 | 6.0 | 0.0 | MH | 98.8 | 95.0 | Clay | 590 | 247 | 1.33 | 1.00 | 0.80 | 1.00 | 0.00 | 1.70 | 0.00 | 5.49 | 5.49 | 0.991 | 0.400 |
| 4 | 8.0 | 0.0 | MH | 98.8 | 95.0 | Clay | 780 | 312 | 1.33 | 1.00 | 0.80 | 1.00 | 0.00 | 1.70 | 0.00 | 5.49 | 5.49 | 0.985 | 0.416 |
| 5 | 13.5 | 16.0 | SP-SM | 7.7 | 100.0 | | 1330 | 519 | 1.33 | 1.00 | 0.85 | 1.00 | 18.13 | 1.66 | 30.11 | 0.28 | 30.39 | 0.966 | 0.419 |
| 6 | 18.5 | 1.0 | SP-SM | 7.7 | 100.0 | | 1830 | 707 | 1.33 | 1.00 | 0.95 | 1.00 | 1.27 | 1.70 | 2.15 | 0.28 | 2.44 | 0.947 | 0.414 |
| 7 | 23.5 | 1.0 | SM | 24.5 | 100.0 | | 2330 | 895 | 1.33 | 1.00 | 0.95 | 1.00 | 1.27 | 1.65 | 2.09 | 5.03 | 7.12 | 0.926 | 0.407 |
| 8 | 28.5 | 0.0 | MH | 96.6 | 95.0 | Clay | 2805 | 1058 | 1.33 | 1.00 | 1.00 | 1.00 | 0.00 | 1.52 | 0.00 | 5.50 | 5.50 | 0.903 | 0.405 |
| 9 | 33.5 | 0.0 | SP-SM | 10.4 | 100.0 | | 3305 | 1246 | 1.33 | 1.00 | 1.00 | 1.00 | 0.00 | 1.45 | 0.00 | 1.33 | 1.33 | 0.879 | 0.394 |
| 10 | 38.5 | 3.0 | SP-SM | 10.4 | 100.0 | | 3805 | 1434 | 1.33 | 1.00 | 1.00 | 1.00 | 4.00 | 1.26 | 5.03 | 1.33 | 6.37 | 0.855 | 0.383 |
| 11 | 43.5 | 4.0 | SP-SM | 10.4 | 100.0 | | 4305 | 1622 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 1.16 | 6.21 | 1.33 | 7.54 | 0.830 | 0.372 |
| 12 | 48.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 4905 | 1910 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 1.05 | 9.81 | 5.61 | 15.42 | 0.805 | 0.349 |
| 13 | 53.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 5505 | 2198 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 0.98 | 5.23 | 5.61 | 10.84 | 0.781 | 0.330 |
| 14 | 58.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 6105 | 2486 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 0.92 | 8.62 | 5.61 | 14.23 | 0.757 | 0.314 |
| 15 | 63.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 6705 | 2774 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.87 | 5.78 | 5.61 | 11.40 | 0.734 | 0.300 |
| 16 | 68.5 | 10.0 | ML | 50.0 | 120.0 | Clay | 7305 | 3062 | 1.33 | 1.00 | 1.00 | 1.00 | 13.33 | 0.84 | 11.21 | 5.61 | 16.83 | 0.712 | 0.287 |
| 17 | 73.5 | 8.0 | ML | 50.0 | 120.0 | Clay | 7905 | 3350 | 1.33 | 1.00 | 1.00 | 1.00 | 10.67 | 0.80 | 8.50 | 5.61 | 14.11 | 0.691 | 0.276 |
| 18 | 78.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 8505 | 3638 | 1.33 | 1.00 | 1.00 | 1.00 | 8.00 | 0.74 | 5.93 | 3.26 | 9.20 | 0.672 | 0.266 |
| 19 | | | | | | | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | | | | | | | |
| 31 | | | | | | | | | | | | | | | | | | | |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.099 | 0.31 |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.099 | 0.27 |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.099 | 2.00 |
| 2.02 | 1.07 | 1.10 | 0.510 | 0.600 | 1.43 |
| 1.10 | 1.01 | 1.07 | 0.072 | 0.078 | 0.19 |
| 1.14 | 1.01 | 1.07 | 0.099 | 0.107 | 0.26 |
| 1.12 | 1.01 | 1.05 | 0.089 | 0.095 | 2.00 |
| 1.09 | 1.01 | 1.03 | 0.067 | 0.069 | 0.18 |
| 1.13 | 1.01 | 1.03 | 0.094 | 0.098 | 0.26 |
| 1.15 | 1.01 | 1.02 | 0.102 | 0.105 | 0.28 |
| 1.33 | 1.02 | 1.01 | 0.160 | 0.165 | 2.00 |
| 1.21 | 1.01 | 1.00 | 0.124 | 0.125 | 2.00 |
| 1.29 | 1.02 | 0.98 | 0.150 | 0.150 | 2.00 |
| 1.22 | 1.02 | 0.97 | 0.128 | 0.127 | 2.00 |
| 1.38 | 1.03 | 0.96 | 0.172 | 0.169 | 2.00 |
| 1.29 | 1.02 | 0.95 | 0.149 | 0.144 | 2.00 |
| 1.18 | 1.01 | 0.95 | 0.113 | 0.108 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 2.5 | 0.050 | 1.51 | 19.78 |
| 4 | 2.0 | 0.050 | 1.21 | 18.27 |
| 6 | 2.0 | 0.000 | 0.00 | 17.07 |
| 8 | 3.8 | 0.000 | 0.00 | 17.07 |
| 13.5 | 5.3 | 0.003 | 0.18 | 17.07 |
| 18.5 | 5.0 | 0.067 | 4.05 | 16.89 |
| 23.5 | 5.0 | 0.045 | 2.69 | 12.84 |
| 28.5 | 5.0 | 0.000 | 0.00 | 10.15 |
| 33.5 | 5.0 | 0.078 | 4.70 | 10.15 |
| 38.5 | 5.0 | 0.047 | 2.84 | 5.45 |
| 43.5 | 5.0 | 0.044 | 2.61 | 2.61 |
| 48.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 81.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 6:01 PM |
| **Boring Designation:** | B-4 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 2 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 80 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.26 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 1 | SM | 32 | 100 | | |
| 2 | 4.0 | 0 | SM | 32 | 100 | | |
| 3 | 6.0 | 0 | CL | 50 | 95 | | Clay |
| 4 | 8.0 | 1 | SM | 26 | 100 | | |
| 5 | 13.5 | 2 | SM | 15 | 100 | | |
| 6 | 18.5 | 5 | SM | 15 | 100 | | |
| 7 | 23.5 | 3 | SM | 15 | 100 | | |
| 8 | 28.5 | 3 | SM | 22 | 100 | | |
| 9 | 33.5 | 2 | SM | 22 | 100 | | |
| 10 | 38.5 | 0 | SM | 22 | 100 | | |
| 11 | 43.5 | 4 | SM | 17 | 100 | | |
| 12 | 48.5 | 2 | SM | 17 | 100 | | |
| 13 | 53.5 | 4 | ML | 50 | 120 | | Clay |
| 14 | 58.5 | 7 | MH | 53 | 120 | | Clay |
| 15 | 63.5 | 7 | MH | 53 | 120 | | Clay |
| 16 | 68.5 | 6 | MH | 53 | 120 | | Clay |
| 17 | 73.5 | 100 | SM | 15 | 120 | | Clay |
| 18 | 78.5 | 9 | SM | 15 | 120 | | Clay |
| 19 | | | | | | | |
| 20 | | | | | | | |
| 21 | | | | | | | |
| 22 | | | | | | | |
| 23 | | | | | | | |
| 24 | | | | | | | |
| 25 | | | | | | | |
| 26 | | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | |
| 29 | | | | | | | |
| 30 | | | | | | | |
| 31 | | | | | | | |
| 32 | | | | | | | |
| 33 | | | | | | | |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 1.0 | SM | 31.9 | 100.0 | | 200 | 200 | 1.33 | 1.00 | 0.75 | 1.00 | 1.00 | 1.70 | 1.70 | 5.43 | 7.13 | 1.002 | 0.169 |
| 2 | 4.0 | 0.0 | SM | 31.9 | 100.0 | | 400 | 275 | 1.33 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.43 | 5.43 | 0.997 | 0.245 |
| 3 | 6.0 | 0.0 | CL | 50.0 | 95.0 | Clay | 590 | 340 | 1.33 | 1.00 | 0.80 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 0.991 | 0.290 |
| 4 | 8.0 | 1.0 | SM | 26.0 | 100.0 | | 790 | 416 | 1.33 | 1.00 | 0.80 | 1.00 | 1.07 | 1.70 | 1.81 | 5.15 | 6.96 | 0.985 | 0.316 |
| 5 | 13.5 | 2.0 | SM | 15.1 | 100.0 | | 1340 | 622 | 1.33 | 1.00 | 0.85 | 1.00 | 2.27 | 1.70 | 3.85 | 3.29 | 7.15 | 0.966 | 0.352 |
| 6 | 18.5 | 5.0 | SM | 15.0 | 100.0 | | 1840 | 810 | 1.33 | 1.00 | 0.95 | 1.00 | 6.33 | 1.62 | 10.25 | 3.26 | 13.51 | 0.947 | 0.363 |
| 7 | 23.5 | 3.0 | SM | 15.0 | 100.0 | | 2340 | 998 | 1.33 | 1.00 | 0.95 | 1.00 | 3.80 | 1.52 | 5.76 | 3.26 | 9.02 | 0.926 | 0.367 |
| 8 | 28.5 | 3.0 | SM | 22.0 | 100.0 | | 2840 | 1186 | 1.33 | 1.00 | 1.00 | 1.00 | 4.00 | 1.37 | 5.46 | 4.77 | 10.23 | 0.903 | 0.365 |
| 9 | 33.5 | 2.0 | SM | 21.6 | 100.0 | | 3340 | 1374 | 1.33 | 1.00 | 1.00 | 1.00 | 2.67 | 1.28 | 3.40 | 4.72 | 8.12 | 0.879 | 0.361 |
| 10 | 38.5 | 0.0 | SM | 22.0 | 100.0 | | 3840 | 1562 | 1.33 | 1.00 | 1.00 | 1.00 | 0.00 | 1.21 | 0.00 | 4.77 | 4.77 | 0.855 | 0.355 |
| 11 | 43.5 | 4.0 | SM | 17.0 | 100.0 | | 4340 | 1750 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 1.11 | 5.91 | 3.85 | 9.76 | 0.830 | 0.348 |
| 12 | 48.5 | 2.0 | SM | 17.0 | 100.0 | | 4840 | 1938 | 1.33 | 1.00 | 1.00 | 1.00 | 2.67 | 1.05 | 2.81 | 3.85 | 6.66 | 0.805 | 0.340 |
| 13 | 53.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 5440 | 2226 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 0.97 | 5.19 | 5.61 | 10.81 | 0.781 | 0.322 |
| 14 | 58.5 | 7.0 | MH | 53.1 | 120.0 | Clay | 6040 | 2514 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 0.92 | 8.57 | 5.61 | 14.18 | 0.757 | 0.307 |
| 15 | 63.5 | 7.0 | MH | 53.1 | 120.0 | Clay | 6640 | 2802 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 0.87 | 8.11 | 5.61 | 13.73 | 0.734 | 0.294 |
| 16 | 68.5 | 6.0 | MH | 53.1 | 120.0 | Clay | 7240 | 3090 | 1.33 | 1.00 | 1.00 | 1.00 | 8.00 | 0.82 | 6.58 | 5.61 | 12.19 | 0.712 | 0.282 |
| 17 | 73.5 | 100.0 | SM | 15.0 | 120.0 | Clay | 7840 | 3378 | 1.33 | 1.00 | 1.00 | 1.00 | 133.33 | 0.88 | 117.89 | 3.26 | 121.15 | 0.691 | 0.271 |
| 18 | 78.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 8440 | 3666 | 1.33 | 1.00 | 1.00 | 1.00 | 12.00 | 0.75 | 9.04 | 3.26 | 12.30 | 0.672 | 0.261 |
| 19 | | | | | | | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | | | | | | | |
| 31 | | | | | | | | | | | | | | | | | | | |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.14 | 1.01 | 1.10 | 0.099 | 0.110 | 0.65 |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.098 | 0.40 |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.100 | 2.00 |
| 1.14 | 1.01 | 1.10 | 0.098 | 0.109 | 0.34 |
| 1.14 | 1.01 | 1.10 | 0.099 | 0.110 | 0.31 |
| 1.27 | 1.02 | 1.10 | 0.144 | 0.161 | 0.44 |
| 1.17 | 1.01 | 1.07 | 0.111 | 0.120 | 0.33 |
| 1.20 | 1.01 | 1.05 | 0.120 | 0.128 | 0.35 |
| 1.16 | 1.01 | 1.04 | 0.105 | 0.110 | 0.31 |
| 1.11 | 1.01 | 1.02 | 0.085 | 0.087 | 0.25 |
| 1.19 | 1.01 | 1.02 | 0.116 | 0.120 | 0.34 |
| 1.13 | 1.01 | 1.01 | 0.096 | 0.098 | 0.29 |
| 1.21 | 1.01 | 1.00 | 0.124 | 0.125 | 2.00 |
| 1.29 | 1.02 | 0.98 | 0.149 | 0.150 | 2.00 |
| 1.28 | 1.02 | 0.97 | 0.146 | 0.144 | 2.00 |
| 1.24 | 1.02 | 0.96 | 0.134 | 0.131 | 2.00 |
| 2.20 | 1.08 | 0.86 | 2.000 | 1.864 | 2.00 |
| 1.24 | 1.02 | 0.94 | 0.135 | 0.129 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 1.0 | 0.045 | 0.54 | 23.84 |
| 4 | 2.0 | 0.051 | 1.22 | 23.31 |
| 6 | 2.0 | 0.000 | 0.00 | 22.09 |
| 8 | 3.8 | 0.045 | 2.04 | 22.09 |
| 13.5 | 5.3 | 0.045 | 2.82 | 20.05 |
| 18.5 | 5.0 | 0.031 | 1.85 | 17.23 |
| 23.5 | 5.0 | 0.040 | 2.38 | 15.37 |
| 28.5 | 5.0 | 0.037 | 2.21 | 13.00 |
| 33.5 | 5.0 | 0.042 | 2.52 | 10.78 |
| 38.5 | 5.0 | 0.054 | 3.22 | 8.27 |
| 43.5 | 5.0 | 0.038 | 2.27 | 5.05 |
| 48.5 | 5.0 | 0.046 | 2.78 | 2.78 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 81.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 5:56 PM |
| **Boring Designation:** | B-5 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 0 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 80 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.29 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 4 | SP-SM | 7 | 100 | | |
| 2 | 4.0 | 6 | SP-SM | 7 | 100 | | |
| 3 | 6.0 | 34 | SM | 15 | 120 | | |
| 4 | 8.0 | 15 | SM | 15 | 120 | | |
| 5 | 13.5 | 2 | SM | 20 | 100 | | |
| 6 | 18.5 | 25 | SP-SM | 11 | 120 | | |
| 7 | 23.5 | 5 | SP-SM | 11 | 100 | | |
| 8 | 28.5 | 0 | SM | 33 | 100 | | |
| 9 | 33.5 | 2 | SM | 33 | 100 | | |
| 10 | 38.5 | 2 | SM | 21 | 100 | | |
| 11 | 43.5 | 7 | SM | 21 | 100 | | |
| 12 | 48.5 | 10 | SM | 26 | 100 | | |
| 13 | 53.5 | 6 | SM | 26 | 100 | | |
| 14 | 58.5 | 5 | MH | 50 | 120 | | Clay |
| 15 | 63.5 | 4 | MH | 50 | 120 | | Clay |
| 16 | 68.5 | 5 | MH | 50 | 120 | | Clay |
| 17 | 73.5 | 5 | MH | 50 | 120 | | Clay |
| 18 | 78.5 | 43 | GC | 15 | 120 | | Clay |
| 19 | | | | | | | |
| 20 | | | | | | | |
| 21 | | | | | | | |
| 22 | | | | | | | |
| 23 | | | | | | | |
| 24 | | | | | | | |
| 25 | | | | | | | |
| 26 | | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | |
| 29 | | | | | | | |
| 30 | | | | | | | |
| 31 | | | | | | | |
| 32 | | | | | | | |
| 33 | | | | | | | |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 4.0 | SP-SM | 6.6 | 100.0 | | 200 | 75 | 1.33 | 1.00 | 0.75 | 1.00 | 4.00 | 1.70 | 6.80 | 0.08 | 6.88 | 1.002 | 0.502 |
| 2 | 4.0 | 6.0 | SP-SM | 6.6 | 100.0 | | 400 | 150 | 1.33 | 1.00 | 0.75 | 1.00 | 6.00 | 1.70 | 10.20 | 0.08 | 10.28 | 0.997 | 0.500 |
| 3 | 6.0 | 34.0 | SM | 14.6 | 120.0 | | 640 | 266 | 1.33 | 1.00 | 0.80 | 1.00 | 36.27 | 1.70 | 61.65 | 3.12 | 64.78 | 0.991 | 0.450 |
| 4 | 8.0 | 15.0 | SM | 14.6 | 120.0 | | 880 | 381 | 1.33 | 1.00 | 0.80 | 1.00 | 16.00 | 1.70 | 27.20 | 3.12 | 30.32 | 0.985 | 0.429 |
| 5 | 13.5 | 2.0 | SM | 19.7 | 100.0 | | 1430 | 588 | 1.33 | 1.00 | 0.85 | 1.00 | 2.27 | 1.70 | 3.85 | 4.43 | 8.28 | 0.966 | 0.443 |
| 6 | 18.5 | 25.0 | SP-SM | 10.5 | 120.0 | | 2030 | 876 | 1.33 | 1.00 | 0.95 | 1.00 | 31.67 | 1.29 | 40.74 | 1.38 | 42.12 | 0.947 | 0.414 |
| 7 | 23.5 | 5.0 | SP-SM | 10.5 | 100.0 | | 2530 | 1064 | 1.33 | 1.00 | 0.95 | 1.00 | 6.33 | 1.44 | 9.15 | 1.38 | 10.53 | 0.926 | 0.415 |
| 8 | 28.5 | 0.0 | SM | 32.8 | 100.0 | | 3030 | 1252 | 1.33 | 1.00 | 1.00 | 1.00 | 0.00 | 1.37 | 0.00 | 5.46 | 5.46 | 0.903 | 0.412 |
| 9 | 33.5 | 2.0 | SM | 32.8 | 100.0 | | 3530 | 1440 | 1.33 | 1.00 | 1.00 | 1.00 | 2.67 | 1.24 | 3.30 | 5.46 | 8.76 | 0.879 | 0.406 |
| 10 | 38.5 | 2.0 | SM | 20.9 | 100.0 | | 4030 | 1628 | 1.33 | 1.00 | 1.00 | 1.00 | 2.67 | 1.16 | 3.10 | 4.62 | 7.72 | 0.855 | 0.399 |
| 11 | 43.5 | 7.0 | SM | 20.9 | 100.0 | | 4530 | 1816 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 1.08 | 10.06 | 4.62 | 14.68 | 0.830 | 0.390 |
| 12 | 48.5 | 10.0 | SM | 26.0 | 100.0 | | 5030 | 2004 | 1.33 | 1.00 | 1.00 | 1.00 | 13.33 | 1.02 | 13.67 | 5.15 | 18.81 | 0.805 | 0.381 |
| 13 | 53.5 | 6.0 | SM | 26.0 | 100.0 | | 5530 | 2192 | 1.33 | 1.00 | 1.00 | 1.00 | 8.00 | 0.98 | 7.86 | 5.15 | 13.01 | 0.781 | 0.371 |
| 14 | 58.5 | 5.0 | MH | 50.0 | 120.0 | Clay | 6130 | 2480 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.92 | 6.14 | 5.61 | 11.75 | 0.757 | 0.353 |
| 15 | 63.5 | 4.0 | MH | 50.0 | 120.0 | Clay | 6730 | 2768 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 0.87 | 4.62 | 5.61 | 10.23 | 0.734 | 0.336 |
| 16 | 68.5 | 5.0 | MH | 50.0 | 120.0 | Clay | 7330 | 3056 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.82 | 5.49 | 5.61 | 11.11 | 0.712 | 0.322 |
| 17 | 73.5 | 5.0 | MH | 50.0 | 120.0 | Clay | 7930 | 3344 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.78 | 5.23 | 5.61 | 10.84 | 0.691 | 0.309 |
| 18 | 78.5 | 43.0 | GC | 15.0 | 120.0 | Clay | 8530 | 3632 | 1.33 | 1.00 | 1.00 | 1.00 | 57.33 | 0.87 | 49.74 | 3.26 | 53.00 | 0.672 | 0.298 |
| 19 | | | | | | | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | | | | | | | |
| 31 | | | | | | | | | | | | | | | | | | | |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB | IB |
| 1.14 | 1.01 | 1.10 | 0.097 | 0.108 | 0.22 | |
| 1.20 | 1.01 | 1.10 | 0.120 | 0.134 | 0.27 | |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 | |
| 2.02 | 1.07 | 1.10 | 0.506 | 0.595 | 1.39 | |
| 1.16 | 1.01 | 1.10 | 0.106 | 0.118 | 0.27 | |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 | |
| 1.20 | 1.01 | 1.06 | 0.122 | 0.131 | 0.32 | |
| 1.12 | 1.01 | 1.04 | 0.089 | 0.093 | 0.23 | |
| 1.17 | 1.01 | 1.03 | 0.110 | 0.115 | 0.28 | |
| 1.15 | 1.01 | 1.02 | 0.103 | 0.106 | 0.27 | |
| 1.31 | 1.02 | 1.02 | 0.153 | 0.159 | 0.41 | |
| 1.45 | 1.03 | 1.01 | 0.192 | 0.199 | 0.52 | |
| 1.26 | 1.02 | 1.00 | 0.140 | 0.142 | 0.38 | |
| 1.23 | 1.02 | 0.98 | 0.131 | 0.131 | 2.00 | |
| 1.20 | 1.01 | 0.98 | 0.120 | 0.118 | 2.00 | |
| 1.21 | 1.01 | 0.96 | 0.126 | 0.123 | 2.00 | |
| 1.21 | 1.01 | 0.96 | 0.124 | 0.120 | 2.00 | |
| 2.20 | 1.08 | 0.84 | 2.000 | 1.818 | 2.00 | |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 3.0 | 0.046 | 1.64 | 20.60 |
| 4 | 2.0 | 0.037 | 0.88 | 18.96 |
| 6 | 2.0 | 0.000 | 0.00 | 18.08 |
| 8 | 3.8 | 0.003 | 0.14 | 18.08 |
| 13.5 | 5.3 | 0.042 | 2.61 | 17.94 |
| 18.5 | 5.0 | 0.000 | 0.00 | 15.32 |
| 23.5 | 5.0 | 0.036 | 2.17 | 15.32 |
| 28.5 | 5.0 | 0.051 | 3.04 | 13.15 |
| 33.5 | 5.0 | 0.040 | 2.42 | 10.11 |
| 38.5 | 5.0 | 0.043 | 2.58 | 7.69 |
| 43.5 | 5.0 | 0.029 | 1.75 | 5.11 |
| 48.5 | 5.0 | 0.024 | 1.45 | 3.36 |
| 53.5 | 5.0 | 0.032 | 1.90 | 1.90 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 81.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 5:56 PM |
| **Boring Designation:** | B-6 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 0 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 80 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.29 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 12 | SM | 17 | 100 | | |
| 2 | 4.0 | 9 | SM | 17 | 100 | | |
| 3 | 6.0 | 16 | SM | 16 | 120 | | |
| 4 | 8.0 | 26 | SM | 16 | 120 | | |
| 5 | 13.5 | 0 | SM | 26 | 100 | | |
| 6 | 18.5 | 20 | SM | 14 | 120 | | |
| 7 | 23.5 | 33 | SM | 14 | 120 | | |
| 8 | 28.5 | 0 | SP-SM | 11 | 100 | | |
| 9 | 33.5 | 4 | SM | 18 | 100 | | |
| 10 | 38.5 | 13 | SM | 18 | 100 | | |
| 11 | 43.5 | 25 | SM | 18 | 120 | | |
| 12 | 48.5 | 33 | SM | 18 | 120 | | |
| 13 | 53.5 | 8 | SM | 18 | 100 | | |
| 14 | 58.5 | 5 | MH | 50 | 120 | | Clay |
| 15 | 63.5 | 5 | MH | 50 | 120 | | Clay |
| 16 | 68.5 | 7 | MH | 50 | 120 | | Clay |
| 17 | 73.5 | 6 | MH | 50 | 120 | | Clay |
| 18 | 78.5 | 100 | ML | 50 | 120 | | Clay |
| 19 | | | | | | | |
| 20 | | | | | | | |
| 21 | | | | | | | |
| 22 | | | | | | | |
| 23 | | | | | | | |
| 24 | | | | | | | |
| 25 | | | | | | | |
| 26 | | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | |
| 29 | | | | | | | |
| 30 | | | | | | | |
| 31 | | | | | | | |
| 32 | | | | | | | |
| 33 | | | | | | | |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 12.0 | SM | 17.2 | 100.0 | | 200 | 75 | 1.33 | 1.00 | 0.75 | 1.00 | 12.00 | 1.70 | 20.40 | 3.90 | 24.30 | 1.002 | 0.502 |
| 2 | 4.0 | 9.0 | SM | 17.2 | 100.0 | | 400 | 150 | 1.33 | 1.00 | 0.75 | 1.00 | 9.00 | 1.70 | 15.30 | 3.90 | 19.20 | 0.997 | 0.500 |
| 3 | 6.0 | 16.0 | SM | 15.7 | 120.0 | | 640 | 266 | 1.33 | 1.00 | 0.80 | 1.00 | 17.07 | 1.70 | 29.01 | 3.49 | 32.50 | 0.991 | 0.450 |
| 4 | 8.0 | 26.0 | SM | 15.7 | 120.0 | | 880 | 381 | 1.33 | 1.00 | 0.80 | 1.00 | 27.73 | 1.57 | 43.55 | 3.49 | 47.03 | 0.985 | 0.429 |
| 5 | 13.5 | 0.0 | SM | 26.1 | 100.0 | | 1430 | 588 | 1.33 | 1.00 | 0.85 | 1.00 | 0.00 | 1.70 | 0.00 | 5.15 | 5.15 | 0.966 | 0.443 |
| 6 | 18.5 | 20.0 | SM | 13.7 | 120.0 | | 2030 | 876 | 1.33 | 1.00 | 0.95 | 1.00 | 25.33 | 1.33 | 33.62 | 2.79 | 36.41 | 0.947 | 0.414 |
| 7 | 23.5 | 33.0 | SM | 13.7 | 120.0 | | 2630 | 1164 | 1.33 | 1.00 | 0.95 | 1.00 | 41.80 | 1.17 | 48.92 | 2.79 | 51.71 | 0.926 | 0.394 |
| 8 | 28.5 | 0.0 | SP-SM | 11.0 | 100.0 | | 3130 | 1352 | 1.33 | 1.00 | 1.00 | 1.00 | 0.00 | 1.36 | 0.00 | 1.61 | 1.61 | 0.903 | 0.394 |
| 9 | 33.5 | 4.0 | SM | 18.3 | 100.0 | | 3630 | 1540 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 1.19 | 6.32 | 4.16 | 10.48 | 0.879 | 0.391 |
| 10 | 38.5 | 13.0 | SM | 18.3 | 100.0 | | 4130 | 1728 | 1.33 | 1.00 | 1.00 | 1.00 | 17.33 | 1.09 | 18.86 | 4.16 | 23.01 | 0.855 | 0.385 |
| 11 | 43.5 | 25.0 | SM | 18.3 | 120.0 | | 4730 | 2016 | 1.33 | 1.00 | 1.00 | 1.00 | 33.33 | 1.02 | 33.84 | 4.16 | 38.00 | 0.830 | 0.367 |
| 12 | 48.5 | 33.0 | SM | 18.3 | 120.0 | | 5330 | 2304 | 1.33 | 1.00 | 1.00 | 1.00 | 44.00 | 0.98 | 43.03 | 4.16 | 47.18 | 0.805 | 0.351 |
| 13 | 53.5 | 8.0 | SM | 18.3 | 100.0 | | 5830 | 2492 | 1.33 | 1.00 | 1.00 | 1.00 | 10.67 | 0.92 | 9.84 | 4.16 | 13.99 | 0.781 | 0.344 |
| 14 | 58.5 | 5.0 | MH | 50.0 | 120.0 | Clay | 6430 | 2780 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.87 | 5.78 | 5.61 | 11.39 | 0.757 | 0.330 |
| 15 | 63.5 | 5.0 | MH | 50.0 | 120.0 | Clay | 7030 | 3068 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.82 | 5.48 | 5.61 | 11.09 | 0.734 | 0.317 |
| 16 | 68.5 | 7.0 | MH | 50.0 | 120.0 | Clay | 7630 | 3356 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 0.79 | 7.39 | 5.61 | 13.00 | 0.712 | 0.305 |
| 17 | 73.5 | 6.0 | MH | 50.0 | 120.0 | Clay | 8230 | 3644 | 1.33 | 1.00 | 1.00 | 1.00 | 8.00 | 0.75 | 6.02 | 5.61 | 11.64 | 0.691 | 0.294 |
| 18 | 78.5 | 100.0 | ML | 50.0 | 120.0 | Clay | 8830 | 3932 | 1.33 | 1.00 | 1.00 | 1.00 | 133.33 | 0.85 | 113.28 | 5.61 | 118.89 | 0.672 | 0.284 |
| 19 | | | | | | | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | | | | | | | |
| 31 | | | | | | | | | | | | | | | | | | | |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.69 | 1.05 | 1.10 | 0.274 | 0.316 | 0.63 |
| 1.46 | 1.03 | 1.10 | 0.197 | 0.223 | 0.45 |
| 2.15 | 1.08 | 1.10 | 0.698 | 0.828 | 1.84 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.12 | 1.01 | 1.10 | 0.087 | 0.096 | 0.22 |
| 2.20 | 1.08 | 1.10 | 1.514 | 1.802 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.09 | 1.01 | 1.03 | 0.068 | 0.071 | 0.18 |
| 1.20 | 1.01 | 1.03 | 0.121 | 0.127 | 0.32 |
| 1.62 | 1.04 | 1.03 | 0.250 | 0.268 | 0.70 |
| 2.20 | 1.08 | 1.01 | 2.000 | 2.000 | 2.00 |
| 2.20 | 1.08 | 0.97 | 2.000 | 2.000 | 2.00 |
| 1.29 | 1.02 | 0.98 | 0.148 | 0.148 | 0.43 |
| 1.22 | 1.01 | 0.97 | 0.128 | 0.126 | 2.00 |
| 1.21 | 1.01 | 0.96 | 0.126 | 0.123 | 2.00 |
| 1.26 | 1.02 | 0.95 | 0.140 | 0.136 | 2.00 |
| 1.23 | 1.02 | 0.95 | 0.130 | 0.125 | 2.00 |
| 2.20 | 1.08 | 0.82 | 2.000 | 1.768 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 3.0 | 0.019 | 0.70 | 14.28 |
| 4 | 2.0 | 0.024 | 0.57 | 13.58 |
| 6 | 2.0 | 0.001 | 0.01 | 13.01 |
| 8 | 3.8 | 0.000 | 0.00 | 13.00 |
| 13.5 | 5.3 | 0.052 | 3.27 | 13.00 |
| 18.5 | 5.0 | 0.000 | 0.00 | 9.72 |
| 23.5 | 5.0 | 0.000 | 0.00 | 9.72 |
| 28.5 | 5.0 | 0.075 | 4.51 | 9.72 |
| 33.5 | 5.0 | 0.036 | 2.18 | 5.22 |
| 38.5 | 5.0 | 0.020 | 1.23 | 3.04 |
| 43.5 | 5.0 | 0.000 | 0.00 | 1.81 |
| 48.5 | 5.0 | 0.000 | 0.00 | 1.81 |
| 53.5 | 5.0 | 0.030 | 1.81 | 1.81 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 81.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 6:01 PM |
| **Boring Designation:** | B-7 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 0 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 83.1 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.26 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" | |
|---|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 9 | SM | 13 | 100 | | | |
| 2 | 4.0 | 4 | SM | 13 | 100 | | | |
| 3 | 6.0 | 0 | SM | 18 | 100 | | | |
| 4 | 8.0 | 1 | SM | 18 | 100 | | | |
| 5 | 13.5 | 2 | SM | 31 | 100 | | | |
| 6 | 18.5 | 4 | SP-SM | 11 | 100 | | | |
| 7 | 23.5 | 17 | SP-SM | 11 | 100 | | | |
| 8 | 28.5 | 4 | SP-SM | 11 | 100 | | | |
| 9 | 33.5 | 2 | CL | 50 | 100 | | Clay | |
| 10 | 38.5 | 1 | SM | 18 | 100 | | | |
| 11 | 43.5 | 4 | SM | 18 | 100 | | | |
| 12 | 48.5 | 5 | SM | 18 | 100 | | | |
| 13 | 53.5 | 10 | ML | 50 | 120 | | Clay | *Assumes Marl/Limestone NonLiq |
| 14 | 58.5 | 4 | ML | 50 | 120 | | Clay | |
| 15 | 63.5 | 8 | ML | 50 | 120 | | Clay | |
| 16 | 68.5 | 8 | SM | 15 | 120 | | Clay | |
| 17 | 73.5 | 100 | SM | 15 | 120 | | Clay | |
| 18 | 78.5 | 12 | SM | 15 | 120 | | Clay | |
| 19 | 83.5 | 6 | SM | 15 | 120 | | Clay | |
| 20 | 88.5 | 6 | SM | 15 | 120 | | Clay | |
| 21 | 93.5 | 12 | SM | 15 | 120 | | Clay | |
| 22 | 98.5 | 13 | SM | 15 | 120 | | Clay | |
| 23 | 103.5 | 11 | SM | 15 | 120 | | Clay | |
| 24 | 108.5 | 6 | SM | 15 | 120 | | Clay | |
| 25 | 113.5 | 11 | SM | 15 | 120 | | Clay | |
| 26 | 118.5 | 9 | SM | 15 | 120 | | Clay | |
| 27 | 123.5 | 7 | SM | 15 | 120 | | Clay | |
| 28 | 128.5 | 13 | SM | 15 | 120 | | Clay | |
| 29 | 133.5 | 12 | SM | 15 | 120 | | Clay | |
| 30 | 138.5 | 11 | SM | 15 | 120 | | Clay | |
| 31 | 143.5 | 9 | SM | 15 | 120 | | Clay | |
| 32 | | | | | | | | |
| 33 | | | | | | | | |
| 34 | | | | | | | | |
| 35 | | | | | | | | |
| 36 | | | | | | | | |
| 37 | | | | | | | | |
| 38 | | | | | | | | |
| 39 | | | | | | | | |
| 40 | | | | | | | | |
| 41 | | | | | | | | |
| 42 | | | | | | | | |
| 43 | | | | | | | | |
| 44 | | | | | | | | |
| 45 | | | | | | | | |
| 46 | | | | | | | | |
| 47 | | | | | | | | |
| 48 | | | | | | | | |
| 49 | | | | | | | | |
| 50 | | | | | | | | |

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 9.0 | SM | 12.8 | 100.0 | | 200 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 9.35 | 1.70 | 15.89 | 2.42 | 18.32 | 1.002 | 0.450 |
| 2 | 4.0 | 4.0 | SM | 12.8 | 100.0 | | 400 | 150 | 1.39 | 1.00 | 0.75 | 1.00 | 4.16 | 1.70 | 7.06 | 2.42 | 9.49 | 0.997 | 0.448 |
| 3 | 6.0 | 0.0 | SM | 18.2 | 100.0 | | 600 | 226 | 1.39 | 1.00 | 0.80 | 1.00 | 0.00 | 1.70 | 0.00 | 4.13 | 4.13 | 0.991 | 0.445 |
| 4 | 8.0 | 1.0 | SM | 18.2 | 100.0 | | 800 | 301 | 1.39 | 1.00 | 0.80 | 1.00 | 1.11 | 1.70 | 1.88 | 4.13 | 6.02 | 0.985 | 0.443 |
| 5 | 13.5 | 2.0 | SM | 31.3 | 100.0 | | 1350 | 508 | 1.39 | 1.00 | 0.85 | 1.00 | 2.35 | 1.70 | 4.00 | 5.41 | 9.41 | 0.966 | 0.434 |
| 6 | 18.5 | 4.0 | SP-SM | 10.8 | 100.0 | | 1850 | 696 | 1.39 | 1.00 | 0.95 | 1.00 | 5.26 | 1.70 | 8.95 | 1.52 | 10.47 | 0.947 | 0.426 |
| 7 | 23.5 | 17.0 | SP-SM | 10.8 | 100.0 | | 2350 | 884 | 1.39 | 1.00 | 0.95 | 1.00 | 22.37 | 1.36 | 30.37 | 1.52 | 31.89 | 0.926 | 0.416 |
| 8 | 28.5 | 4.0 | SP-SM | 10.8 | 100.0 | | 2850 | 1072 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.45 | 8.04 | 1.52 | 9.55 | 0.903 | 0.406 |
| 9 | 33.5 | 2.0 | CL | 50.0 | 100.0 | Clay | 3350 | 1260 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.33 | 3.68 | 5.61 | 9.30 | 0.879 | 0.395 |
| 10 | 38.5 | 1.0 | SM | 17.9 | 100.0 | | 3850 | 1448 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.26 | 1.74 | 4.07 | 5.81 | 0.855 | 0.384 |
| 11 | 43.5 | 4.0 | SM | 17.9 | 100.0 | | 4350 | 1636 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.15 | 6.36 | 4.07 | 10.43 | 0.830 | 0.373 |
| 12 | 48.5 | 5.0 | SM | 17.9 | 100.0 | | 4850 | 1824 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 1.08 | 7.49 | 4.07 | 11.55 | 0.805 | 0.362 |
| 13 | 53.5 | 10.0 | ML | 50.0 | 120.0 | Clay | 5450 | 2112 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 1.00 | 13.86 | 5.61 | 19.48 | 0.781 | 0.341 |
| 14 | 58.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 6050 | 2400 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 0.94 | 5.18 | 5.61 | 10.80 | 0.757 | 0.322 |
| 15 | 63.5 | 8.0 | ML | 50.0 | 120.0 | Clay | 6650 | 2688 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.89 | 9.87 | 5.61 | 15.49 | 0.734 | 0.307 |
| 16 | 68.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 7250 | 2976 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.84 | 9.31 | 3.26 | 12.57 | 0.712 | 0.293 |
| 17 | 73.5 | 100.0 | SM | 15.0 | 120.0 | Clay | 7850 | 3264 | 1.39 | 1.00 | 1.00 | 1.00 | 138.50 | 0.89 | 123.58 | 3.26 | 126.84 | 0.691 | 0.281 |
| 18 | 78.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 8450 | 3552 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.78 | 13.00 | 3.26 | 16.26 | 0.672 | 0.270 |
| 19 | 83.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 9050 | 3840 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.72 | 5.99 | 3.26 | 9.25 | 0.654 | 0.261 |
| 20 | 88.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 9650 | 4128 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.69 | 5.74 | 3.26 | 9.00 | 0.639 | 0.252 |
| 21 | 93.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 10250 | 4416 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.70 | 11.61 | 3.26 | 14.87 | 0.625 | 0.245 |
| 22 | 98.5 | 13.0 | SM | 15.0 | 120.0 | Clay | 10850 | 4704 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.68 | 12.26 | 3.26 | 15.52 | 0.613 | 0.239 |
| 23 | 103.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 11450 | 4992 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.65 | 9.87 | 3.26 | 13.13 | 0.603 | 0.234 |
| 24 | 108.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 12050 | 5280 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.60 | 4.96 | 3.26 | 8.22 | 0.596 | 0.230 |
| 25 | 113.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 12650 | 5568 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.61 | 9.28 | 3.26 | 12.55 | 0.590 | 0.227 |
| 26 | 118.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 13250 | 5856 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.58 | 7.23 | 3.26 | 10.49 | 0.587 | 0.224 |
| 27 | 123.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 13850 | 6144 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.55 | 5.34 | 3.26 | 8.61 | 0.586 | 0.223 |
| 28 | 128.5 | 13.0 | SM | 15.0 | 120.0 | Clay | 14450 | 6432 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.57 | 10.32 | 3.26 | 13.58 | 0.588 | 0.223 |
| 29 | 133.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 15050 | 6720 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.55 | 9.19 | 3.26 | 12.45 | 0.592 | 0.224 |
| 30 | 138.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 15650 | 7008 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.53 | 8.13 | 3.26 | 11.39 | 0.598 | 0.226 |
| 31 | 143.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 16250 | 7296 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.51 | 6.34 | 3.26 | 9.60 | 0.607 | 0.228 |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.43 | 1.03 | 1.10 | 0.187 | 0.212 | 0.47 |
| 1.18 | 1.01 | 1.10 | 0.115 | 0.128 | 0.28 |
| 1.11 | 1.01 | 1.10 | 0.081 | 0.090 | 0.20 |
| 1.13 | 1.01 | 1.10 | 0.092 | 0.102 | 0.23 |
| 1.18 | 1.01 | 1.10 | 0.114 | 0.127 | 0.29 |
| 1.20 | 1.01 | 1.10 | 0.121 | 0.135 | 0.32 |
| 2.11 | 1.08 | 1.10 | 0.633 | 0.749 | 1.80 |
| 1.18 | 1.01 | 1.06 | 0.115 | 0.124 | 0.30 |
| 1.18 | 1.01 | 1.05 | 0.113 | 0.120 | 2.00 |
| 1.12 | 1.01 | 1.03 | 0.091 | 0.094 | 0.25 |
| 1.20 | 1.01 | 1.02 | 0.121 | 0.126 | 0.34 |
| 1.22 | 1.02 | 1.01 | 0.129 | 0.133 | 0.37 |
| 1.47 | 1.03 | 1.00 | 0.200 | 0.206 | 2.00 |
| 1.21 | 1.01 | 0.99 | 0.124 | 0.124 | 2.00 |
| 1.33 | 1.02 | 0.97 | 0.160 | 0.159 | 2.00 |
| 1.25 | 1.02 | 0.97 | 0.137 | 0.134 | 2.00 |
| 2.20 | 1.08 | 0.87 | 2.000 | 1.886 | 2.00 |
| 1.36 | 1.02 | 0.94 | 0.167 | 0.161 | 2.00 |
| 1.18 | 1.01 | 0.95 | 0.113 | 0.108 | 2.00 |
| 1.17 | 1.01 | 0.94 | 0.111 | 0.106 | 2.00 |
| 1.31 | 1.02 | 0.92 | 0.155 | 0.145 | 2.00 |
| 1.33 | 1.02 | 0.91 | 0.161 | 0.149 | 2.00 |
| 1.26 | 1.02 | 0.91 | 0.141 | 0.131 | 2.00 |
| 1.16 | 1.01 | 0.92 | 0.106 | 0.099 | 2.00 |
| 1.25 | 1.02 | 0.90 | 0.137 | 0.125 | 2.00 |
| 1.20 | 1.01 | 0.90 | 0.122 | 0.111 | 2.00 |
| 1.16 | 1.01 | 0.91 | 0.109 | 0.100 | 2.00 |
| 1.28 | 1.02 | 0.88 | 0.145 | 0.130 | 2.00 |
| 1.25 | 1.02 | 0.88 | 0.136 | 0.122 | 2.00 |
| 1.22 | 1.01 | 0.88 | 0.128 | 0.115 | 2.00 |
| 1.18 | 1.01 | 0.89 | 0.115 | 0.104 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 3.0 | 0.025 | 0.89 | 19.53 |
| 4 | 2.0 | 0.039 | 0.92 | 18.64 |
| 6 | 2.0 | 0.057 | 1.36 | 17.71 |
| 8 | 3.8 | 0.049 | 2.18 | 16.35 |
| 13.5 | 5.3 | 0.039 | 2.44 | 14.17 |
| 18.5 | 5.0 | 0.036 | 2.18 | 11.73 |
| 23.5 | 5.0 | 0.001 | 0.05 | 9.55 |
| 28.5 | 5.0 | 0.038 | 2.30 | 9.50 |
| 33.5 | 5.0 | 0.000 | 0.00 | 7.20 |
| 38.5 | 5.0 | 0.049 | 2.96 | 7.20 |
| 43.5 | 5.0 | 0.036 | 2.19 | 4.24 |
| 48.5 | 5.0 | 0.034 | 2.05 | 2.05 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 133.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 143.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 146.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 6:02 PM |
| **Boring Designation:** | B-8 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 0 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 83.1 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.26 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 3 | SP-SM | 12 | 100 | | |
| 2 | 4.0 | 5 | SP-SM | 12 | 100 | | |
| 3 | 6.0 | 4 | SP-SM | 12 | 100 | | |
| 4 | 8.0 | 2 | SP-SM | 12 | 100 | | |
| 5 | 10.0 | 2 | SP-SM | 12 | 100 | | |
| 6 | 13.5 | 0 | CL | 68 | 95 | | Clay |
| 7 | 18.5 | 0 | CL | 68 | 95 | | Clay |
| 8 | 23.5 | 0 | SC | 35 | 100 | | |
| 9 | 28.5 | 2 | SM | 22 | 100 | | |
| 10 | 33.5 | 4 | SM | 22 | 100 | | |
| 11 | 38.5 | 2 | CL | 50 | 95 | | Clay |
| 12 | 43.5 | 8 | SP-SM | 7 | 100 | | |
| 13 | 48.5 | 7 | SP-SM | 8 | 100 | | |
| 14 | 53.5 | 5 | SM | 15 | 120 | | Clay |
| 15 | 58.5 | 6 | ML | 50 | 120 | | Clay |
| 16 | 63.5 | 6 | ML | 50 | 120 | | Clay |
| 17 | 68.5 | 5 | ML | 50 | 120 | | Clay |
| 18 | 73.5 | 18 | ML | 50 | 120 | | Clay |
| 19 | 78.5 | 13 | SM | 15 | 120 | | Clay |
| 20 | 83.5 | 5 | SM | 15 | 120 | | Clay |
| 21 | 88.5 | 8 | SM | 15 | 120 | | Clay |
| 22 | 93.5 | 9 | SM | 15 | 120 | | Clay |
| 23 | 98.5 | 8 | SM | 15 | 120 | | Clay |
| 24 | 103.5 | 9 | SM | 15 | 120 | | Clay |
| 25 | 108.5 | 6 | SM | 15 | 120 | | Clay |
| 26 | 113.5 | 12 | SM | 15 | 120 | | Clay |
| 27 | 118.5 | 9 | SM | 15 | 120 | | Clay |
| 28 | 123.5 | 7 | SM | 15 | 120 | | Clay |
| 29 | 128.5 | 19 | SM | 15 | 120 | | Clay |
| 30 | 133.5 | 11 | SM | 15 | 120 | | Clay |
| 31 | 138.5 | | SM | 15 | 120 | | Clay |
| 32 | 143.5 | 10 | SM | 15 | 120 | | Clay |
| 33 | 148.5 | 11 | SM | 15 | 120 | | Clay |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 3.0 | SP-SM | 11.9 | 100.0 | | 200 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 3.12 | 1.70 | 5.30 | 2.03 | 7.32 | 1.002 | 0.450 |
| 2 | 4.0 | 5.0 | SP-SM | 11.9 | 100.0 | | 400 | 150 | 1.39 | 1.00 | 0.75 | 1.00 | 5.19 | 1.70 | 8.83 | 2.03 | 10.86 | 0.997 | 0.448 |
| 3 | 6.0 | 4.0 | SP-SM | 11.9 | 100.0 | | 600 | 226 | 1.39 | 1.00 | 0.80 | 1.00 | 4.43 | 1.70 | 7.53 | 2.03 | 9.56 | 0.991 | 0.445 |
| 4 | 8.0 | 2.0 | SP-SM | 11.9 | 100.0 | | 800 | 301 | 1.39 | 1.00 | 0.80 | 1.00 | 2.22 | 1.70 | 3.77 | 2.03 | 5.79 | 0.985 | 0.443 |
| 5 | 10.0 | 2.0 | SP-SM | 11.9 | 100.0 | | 1000 | 376 | 1.39 | 1.00 | 0.85 | 1.00 | 2.35 | 1.70 | 4.00 | 2.03 | 6.03 | 0.978 | 0.440 |
| 6 | 13.5 | 0.0 | CL | 67.5 | 95.0 | Clay | 1333 | 490 | 1.39 | 1.00 | 0.85 | 1.00 | 0.00 | 1.70 | 0.00 | 5.58 | 5.58 | 0.966 | 0.444 |
| 7 | 18.5 | 0.0 | CL | 67.5 | 95.0 | Clay | 1808 | 653 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.58 | 5.58 | 0.947 | 0.443 |
| 8 | 23.5 | 0.0 | SC | 34.9 | 100.0 | | 2308 | 841 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.50 | 5.50 | 0.926 | 0.429 |
| 9 | 28.5 | 2.0 | SM | 22.0 | 100.0 | | 2808 | 1029 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.49 | 4.13 | 4.77 | 8.90 | 0.903 | 0.416 |
| 10 | 33.5 | 4.0 | SM | 22.0 | 100.0 | | 3308 | 1217 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.33 | 7.37 | 4.77 | 12.14 | 0.879 | 0.404 |
| 11 | 38.5 | 2.0 | CL | 50.0 | 95.0 | Clay | 3783 | 1380 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.27 | 3.51 | 5.61 | 9.12 | 0.855 | 0.396 |
| 12 | 43.5 | 8.0 | SP-SM | 6.5 | 100.0 | | 4283 | 1568 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 1.16 | 12.90 | 0.07 | 12.97 | 0.830 | 0.383 |
| 13 | 48.5 | 7.0 | SP-SM | 8.2 | 100.0 | | 4783 | 1756 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 1.10 | 10.70 | 0.43 | 11.13 | 0.805 | 0.371 |
| 14 | 53.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 5383 | 2044 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 1.02 | 7.05 | 3.26 | 10.32 | 0.781 | 0.347 |
| 15 | 58.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 5983 | 2332 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.95 | 7.91 | 5.61 | 13.53 | 0.757 | 0.328 |
| 16 | 63.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 6583 | 2620 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.90 | 7.46 | 5.61 | 13.07 | 0.734 | 0.312 |
| 17 | 68.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 7183 | 2908 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.85 | 5.86 | 5.61 | 11.48 | 0.712 | 0.297 |
| 18 | 73.5 | 18.0 | ML | 50.0 | 120.0 | Clay | 7783 | 3196 | 1.39 | 1.00 | 1.00 | 1.00 | 24.93 | 0.85 | 21.26 | 5.61 | 26.88 | 0.691 | 0.284 |
| 19 | 78.5 | 13.0 | SM | 15.0 | 120.0 | Clay | 8383 | 3484 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.79 | 14.30 | 3.26 | 17.56 | 0.672 | 0.273 |
| 20 | 83.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 8983 | 3772 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.72 | 5.00 | 3.26 | 8.26 | 0.654 | 0.263 |
| 21 | 88.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 9583 | 4060 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.71 | 7.85 | 3.26 | 11.12 | 0.639 | 0.255 |
| 22 | 93.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 10183 | 4348 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.69 | 8.57 | 3.26 | 11.83 | 0.625 | 0.247 |
| 23 | 98.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 10783 | 4636 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.66 | 7.29 | 3.26 | 10.55 | 0.613 | 0.241 |
| 24 | 103.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 11383 | 4924 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.64 | 7.99 | 3.26 | 11.25 | 0.603 | 0.236 |
| 25 | 108.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 11983 | 5212 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.60 | 5.00 | 3.26 | 8.26 | 0.596 | 0.231 |
| 26 | 113.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 12583 | 5500 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.62 | 10.30 | 3.26 | 13.56 | 0.590 | 0.228 |
| 27 | 118.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 13183 | 5788 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.58 | 7.28 | 3.26 | 10.54 | 0.587 | 0.226 |
| 28 | 123.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 13783 | 6076 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.55 | 5.38 | 3.26 | 8.64 | 0.586 | 0.225 |
| 29 | 128.5 | 19.0 | SM | 15.0 | 120.0 | Clay | 14383 | 6364 | 1.39 | 1.00 | 1.00 | 1.00 | 26.32 | 0.61 | 16.10 | 3.26 | 19.36 | 0.588 | 0.224 |
| 30 | 133.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 14983 | 6652 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.55 | 8.38 | 3.26 | 11.64 | 0.592 | 0.225 |
| 31 | 138.5 | 0.0 | SM | 15.0 | 120.0 | Clay | 15583 | 6940 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 0.46 | 0.00 | 3.26 | 3.26 | 0.598 | 0.227 |
| 32 | 143.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 16183 | 7228 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.52 | 7.17 | 3.26 | 10.43 | 0.607 | 0.230 |
| 33 | 148.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 16783 | 7516 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.51 | 7.80 | 3.26 | 11.06 | 0.618 | 0.233 |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.14 | 1.01 | 1.10 | 0.100 | 0.111 | 0.25 |
| 1.21 | 1.01 | 1.10 | 0.124 | 0.138 | 0.31 |
| 1.18 | 1.01 | 1.10 | 0.115 | 0.128 | 0.29 |
| 1.12 | 1.01 | 1.10 | 0.091 | 0.101 | 0.23 |
| 1.13 | 1.01 | 1.10 | 0.092 | 0.102 | 0.23 |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.09 | 0.090 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.07 | 0.089 | 0.096 | 0.22 |
| 1.17 | 1.01 | 1.06 | 0.111 | 0.119 | 0.29 |
| 1.24 | 1.02 | 1.06 | 0.133 | 0.143 | 0.35 |
| 1.17 | 1.01 | 1.04 | 0.112 | 0.118 | 2.00 |
| 1.26 | 1.02 | 1.03 | 0.140 | 0.147 | 0.38 |
| 1.21 | 1.01 | 1.02 | 0.126 | 0.130 | 0.35 |
| 1.20 | 1.01 | 1.00 | 0.120 | 0.122 | 2.00 |
| 1.27 | 1.02 | 0.99 | 0.144 | 0.145 | 2.00 |
| 1.26 | 1.02 | 0.98 | 0.141 | 0.140 | 2.00 |
| 1.22 | 1.02 | 0.97 | 0.129 | 0.127 | 2.00 |
| 1.82 | 1.06 | 0.93 | 0.342 | 0.335 | 2.00 |
| 1.40 | 1.03 | 0.94 | 0.179 | 0.173 | 2.00 |
| 1.16 | 1.01 | 0.95 | 0.106 | 0.102 | 2.00 |
| 1.21 | 1.01 | 0.94 | 0.126 | 0.120 | 2.00 |
| 1.23 | 1.02 | 0.93 | 0.131 | 0.124 | 2.00 |
| 1.20 | 1.01 | 0.93 | 0.122 | 0.114 | 2.00 |
| 1.22 | 1.01 | 0.92 | 0.127 | 0.118 | 2.00 |
| 1.16 | 1.01 | 0.92 | 0.106 | 0.099 | 2.00 |
| 1.28 | 1.02 | 0.90 | 0.144 | 0.132 | 2.00 |
| 1.20 | 1.01 | 0.91 | 0.122 | 0.112 | 2.00 |
| 1.17 | 1.01 | 0.91 | 0.109 | 0.100 | 2.00 |
| 1.47 | 1.03 | 0.86 | 0.198 | 0.175 | 2.00 |
| 1.23 | 1.02 | 0.89 | 0.130 | 0.117 | 2.00 |
| 1.10 | 1.01 | 0.92 | 0.077 | 0.071 | 2.00 |
| 1.20 | 1.01 | 0.88 | 0.121 | 0.109 | 2.00 |
| 1.21 | 1.01 | 0.88 | 0.126 | 0.112 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 3.0 | 0.044 | 1.59 | 17.57 |
| 4 | 2.0 | 0.036 | 0.85 | 15.98 |
| 6 | 2.0 | 0.038 | 0.92 | 15.13 |
| 8 | 2.0 | 0.049 | 1.18 | 14.21 |
| 10 | 2.8 | 0.048 | 1.60 | 13.02 |
| 13.5 | 4.3 | 0.000 | 0.00 | 11.42 |
| 18.5 | 5.0 | 0.000 | 0.00 | 11.42 |
| 23.5 | 5.0 | 0.050 | 3.03 | 11.42 |
| 28.5 | 5.0 | 0.040 | 2.39 | 8.39 |
| 33.5 | 5.0 | 0.033 | 1.99 | 6.00 |
| 38.5 | 5.0 | 0.000 | 0.00 | 4.01 |
| 43.5 | 5.0 | 0.032 | 1.91 | 4.01 |
| 48.5 | 5.0 | 0.035 | 2.10 | 2.10 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 133.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 143.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 148.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 151.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 6:03 PM |
| **Boring Designation:** | B-9 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 0 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 83.1 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.26 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" | |
|---|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 0 | ML | 50 | 95 | | Clay | |
| 2 | 2.0 | 5 | SP-SM | 8 | 100 | | | |
| 3 | 4.0 | 6 | SP-SM | 7 | 100 | | | |
| 4 | 6.0 | 0 | SP-SM | 7 | 100 | | | |
| 5 | 8.0 | 2 | SP-SM | 10 | 100 | | | |
| 6 | 13.5 | 0 | SP-SM | 10 | 100 | | | |
| 7 | 18.5 | 0 | CL | 79 | 95 | | Clay | |
| 8 | 23.5 | 0 | CL | 79 | 95 | | Clay | |
| 9 | 28.5 | 0 | CL | 79 | 95 | | Clay | |
| 10 | 33.5 | 1 | CL | 79 | 95 | | Clay | |
| 11 | 38.5 | 2 | CL | 79 | 95 | | Clay | |
| 12 | 43.5 | 7 | SP-SM | 8 | 100 | | | |
| 13 | 48.5 | 4 | SP-SM | 8 | 100 | | | |
| 14 | 53.5 | 4 | ML | 50 | 120 | | Clay | *Assumes Marl/Limestone NonLiq |
| 15 | 58.5 | 5 | ML | 50 | 120 | | Clay | |
| 16 | 63.5 | 7 | ML | 50 | 120 | | Clay | |
| 17 | 68.5 | 5 | ML | 50 | 120 | | Clay | |
| 18 | 73.5 | 13 | ML | 50 | 120 | | Clay | |
| 19 | 78.5 | 100 | SM | 15 | 120 | | Clay | |
| 20 | 83.5 | 5 | SM | 15 | 120 | | Clay | |
| 21 | 88.5 | 8 | SM | 15 | 120 | | Clay | |
| 22 | 93.5 | 8 | SM | 15 | 120 | | Clay | |
| 23 | 98.5 | 8 | SM | 15 | 120 | | Clay | |
| 24 | 103.5 | 14 | SM | 15 | 120 | | Clay | |
| 25 | 108.5 | 8 | SM | 15 | 120 | | Clay | |
| 26 | 113.5 | 7 | SM | 15 | 120 | | Clay | |
| 27 | 118.5 | 7 | SM | 15 | 120 | | Clay | |
| 28 | 123.5 | 6 | SM | 15 | 120 | | Clay | |
| 29 | 128.5 | 6 | SM | 15 | 120 | | Clay | |
| 30 | 133.5 | 13 | ML | 50 | 120 | | Clay | |
| 31 | 138.5 | 11 | ML | 50 | 120 | | Clay | |
| 32 | 143.5 | 11 | SM | 15 | 120 | | Clay | |
| 33 | 148.5 | 10 | SM | 15 | 120 | | Clay | |
| 34 | | | | | | | | |
| 35 | | | | | | | | |
| 36 | | | | | | | | |
| 37 | | | | | | | | |
| 38 | | | | | | | | |
| 39 | | | | | | | | |
| 40 | | | | | | | | |
| 41 | | | | | | | | |
| 42 | | | | | | | | |
| 43 | | | | | | | | |
| 44 | | | | | | | | |
| 45 | | | | | | | | |
| 46 | | | | | | | | |
| 47 | | | | | | | | |
| 48 | | | | | | | | |
| 49 | | | | | | | | |
| 50 | | | | | | | | |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 0.0 | ML | 50.0 | 95.0 | Clay | 48 | 16 | 1.39 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 1.005 | 0.495 |
| 2 | 2.0 | 5.0 | SP-SM | 7.7 | 100.0 | | 198 | 73 | 1.39 | 1.00 | 0.75 | 1.00 | 5.19 | 1.70 | 8.83 | 0.28 | 9.11 | 1.002 | 0.460 |
| 3 | 4.0 | 6.0 | SP-SM | 7.2 | 100.0 | | 398 | 148 | 1.39 | 1.00 | 0.75 | 1.00 | 6.23 | 1.70 | 10.60 | 0.17 | 10.77 | 0.997 | 0.453 |
| 4 | 6.0 | 0.0 | SP-SM | 7.0 | 100.0 | | 598 | 223 | 1.39 | 1.00 | 0.80 | 1.00 | 0.00 | 1.70 | 0.00 | 0.14 | 0.14 | 0.991 | 0.448 |
| 5 | 8.0 | 2.0 | SP-SM | 10.3 | 100.0 | | 798 | 298 | 1.39 | 1.00 | 0.80 | 1.00 | 2.22 | 1.70 | 3.77 | 1.29 | 5.05 | 0.985 | 0.445 |
| 6 | 13.5 | 0.0 | SP-SM | 10.0 | 100.0 | | 1348 | 505 | 1.39 | 1.00 | 0.85 | 1.00 | 0.00 | 1.70 | 0.00 | 1.15 | 1.15 | 0.966 | 0.436 |
| 7 | 18.5 | 0.0 | CL | 79.0 | 95.0 | Clay | 1823 | 668 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.55 | 5.55 | 0.947 | 0.436 |
| 8 | 23.5 | 0.0 | CL | 79.0 | 95.0 | Clay | 2298 | 831 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.55 | 5.55 | 0.926 | 0.432 |
| 9 | 28.5 | 0.0 | CL | 79.1 | 95.0 | Clay | 2773 | 994 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.58 | 0.00 | 5.55 | 5.55 | 0.903 | 0.426 |
| 10 | 33.5 | 1.0 | CL | 79.0 | 95.0 | Clay | 3248 | 1157 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.41 | 1.96 | 5.55 | 7.51 | 0.879 | 0.417 |
| 11 | 38.5 | 2.0 | CL | 79.0 | 95.0 | Clay | 3723 | 1320 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.30 | 3.59 | 5.55 | 9.14 | 0.855 | 0.407 |
| 12 | 43.5 | 7.0 | SP-SM | 7.5 | 100.0 | | 4223 | 1508 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 1.19 | 11.56 | 0.23 | 11.80 | 0.830 | 0.393 |
| 13 | 48.5 | 4.0 | SP-SM | 8.0 | 100.0 | | 4723 | 1696 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.14 | 6.31 | 0.37 | 6.67 | 0.805 | 0.379 |
| 14 | 53.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 5323 | 1984 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.03 | 5.73 | 5.61 | 11.35 | 0.781 | 0.354 |
| 15 | 58.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 5923 | 2272 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.96 | 6.68 | 5.61 | 12.29 | 0.757 | 0.333 |
| 16 | 63.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 6523 | 2560 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.91 | 8.83 | 5.61 | 14.44 | 0.734 | 0.316 |
| 17 | 68.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 7123 | 2848 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.86 | 5.93 | 5.61 | 11.54 | 0.712 | 0.301 |
| 18 | 73.5 | 13.0 | ML | 50.0 | 120.0 | Clay | 7723 | 3136 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.84 | 15.18 | 5.61 | 20.79 | 0.691 | 0.288 |
| 19 | 78.5 | 100.0 | SM | 15.0 | 120.0 | Clay | 8323 | 3424 | 1.39 | 1.00 | 1.00 | 1.00 | 138.50 | 0.88 | 122.03 | 3.26 | 125.29 | 0.672 | 0.276 |
| 20 | 83.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 8923 | 3712 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.73 | 5.05 | 3.26 | 8.31 | 0.654 | 0.266 |
| 21 | 88.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 9523 | 4000 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.71 | 7.92 | 3.26 | 11.18 | 0.639 | 0.257 |
| 22 | 93.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 10123 | 4288 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.69 | 7.62 | 3.26 | 10.88 | 0.625 | 0.249 |
| 23 | 98.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 10723 | 4576 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.66 | 7.34 | 3.26 | 10.60 | 0.613 | 0.243 |
| 24 | 103.5 | 14.0 | SM | 15.0 | 120.0 | Clay | 11323 | 4864 | 1.39 | 1.00 | 1.00 | 1.00 | 19.39 | 0.67 | 13.07 | 3.26 | 16.33 | 0.603 | 0.237 |
| 25 | 108.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 11923 | 5152 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.62 | 6.85 | 3.26 | 10.12 | 0.596 | 0.233 |
| 26 | 113.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 12523 | 5440 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.59 | 5.75 | 3.26 | 9.01 | 0.590 | 0.230 |
| 27 | 118.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 13123 | 5728 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.57 | 5.57 | 3.26 | 8.84 | 0.587 | 0.227 |
| 28 | 123.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 13723 | 6016 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.55 | 4.59 | 3.26 | 7.85 | 0.586 | 0.226 |
| 29 | 128.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 14323 | 6304 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.54 | 4.46 | 3.26 | 7.72 | 0.588 | 0.226 |
| 30 | 133.5 | 13.0 | ML | 50.0 | 120.0 | Clay | 14923 | 6592 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.58 | 10.48 | 5.61 | 16.10 | 0.592 | 0.226 |
| 31 | 138.5 | 11.0 | ML | 50.0 | 120.0 | Clay | 15523 | 6880 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.56 | 8.49 | 5.61 | 14.11 | 0.598 | 0.228 |
| 32 | 143.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 16123 | 7168 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.53 | 8.02 | 3.26 | 11.28 | 0.607 | 0.231 |
| 33 | 148.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 16723 | 7456 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.51 | 7.04 | 3.26 | 10.30 | 0.618 | 0.234 |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.100 | 2.00 |
| 1.17 | 1.01 | 1.10 | 0.112 | 0.125 | 0.27 |
| 1.21 | 1.01 | 1.10 | 0.123 | 0.138 | 0.30 |
| 1.09 | 1.01 | 1.10 | 0.061 | 0.068 | 0.15 |
| 1.12 | 1.01 | 1.10 | 0.086 | 0.096 | 0.22 |
| 1.09 | 1.01 | 1.09 | 0.066 | 0.072 | 0.17 |
| 1.12 | 1.01 | 1.09 | 0.089 | 0.098 | 2.00 |
| 1.12 | 1.01 | 1.07 | 0.089 | 0.097 | 2.00 |
| 1.12 | 1.01 | 1.06 | 0.089 | 0.095 | 2.00 |
| 1.15 | 1.01 | 1.05 | 0.101 | 0.108 | 2.00 |
| 1.17 | 1.01 | 1.04 | 0.112 | 0.118 | 2.00 |
| 1.23 | 1.02 | 1.03 | 0.131 | 0.137 | 0.35 |
| 1.13 | 1.01 | 1.02 | 0.096 | 0.099 | 0.26 |
| 1.22 | 1.01 | 1.01 | 0.128 | 0.130 | 2.00 |
| 1.24 | 1.02 | 0.99 | 0.135 | 0.136 | 2.00 |
| 1.30 | 1.02 | 0.98 | 0.151 | 0.151 | 2.00 |
| 1.22 | 1.02 | 0.97 | 0.129 | 0.127 | 2.00 |
| 1.53 | 1.04 | 0.95 | 0.216 | 0.212 | 2.00 |
| 2.20 | 1.08 | 0.86 | 2.000 | 1.856 | 2.00 |
| 1.16 | 1.01 | 0.95 | 0.107 | 0.103 | 2.00 |
| 1.22 | 1.01 | 0.94 | 0.126 | 0.120 | 2.00 |
| 1.21 | 1.01 | 0.93 | 0.124 | 0.118 | 2.00 |
| 1.20 | 1.01 | 0.93 | 0.122 | 0.115 | 2.00 |
| 1.36 | 1.02 | 0.90 | 0.168 | 0.155 | 2.00 |
| 1.19 | 1.01 | 0.92 | 0.119 | 0.110 | 2.00 |
| 1.17 | 1.01 | 0.92 | 0.111 | 0.103 | 2.00 |
| 1.17 | 1.01 | 0.91 | 0.110 | 0.102 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.104 | 0.095 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.103 | 0.094 | 2.00 |
| 1.35 | 1.02 | 0.87 | 0.166 | 0.147 | 2.00 |
| 1.29 | 1.02 | 0.87 | 0.149 | 0.133 | 2.00 |
| 1.22 | 1.01 | 0.88 | 0.127 | 0.114 | 2.00 |
| 1.20 | 1.01 | 0.88 | 0.120 | 0.107 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.000 | 0.00 | 16.45 |
| 2 | 1.8 | 0.039 | 0.83 | 16.45 |
| 4 | 2.0 | 0.036 | 0.86 | 15.62 |
| 6 | 2.0 | 0.105 | 2.51 | 14.76 |
| 8 | 3.8 | 0.052 | 2.36 | 12.25 |
| 13.5 | 5.3 | 0.081 | 5.09 | 9.89 |
| 18.5 | 5.0 | 0.000 | 0.00 | 4.80 |
| 23.5 | 5.0 | 0.000 | 0.00 | 4.80 |
| 28.5 | 5.0 | 0.000 | 0.00 | 4.80 |
| 33.5 | 5.0 | 0.000 | 0.00 | 4.80 |
| 38.5 | 5.0 | 0.000 | 0.00 | 4.80 |
| 43.5 | 5.0 | 0.034 | 2.03 | 4.80 |
| 48.5 | 5.0 | 0.046 | 2.78 | 2.78 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 133.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 143.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 148.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 151.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 6:03 PM |
| Boring Designation: | B-10 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | -2 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 83.1 |
| Distance from sample hammer to ground surface (ft): | 7 |
| Borehole Diameter (in) | 4 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.26 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 0 | SC | 41 | 100 | | |
| 2 | 2.0 | 0 | SC | 41 | 100 | | |
| 3 | 4.0 | 6 | SC | 41 | 100 | | |
| 4 | 6.0 | 2 | SP-SM | 8 | 100 | | |
| 5 | 8.0 | 2 | SP-SM | 8 | 100 | | |
| 6 | 10.0 | 2 | ML | 57 | 95 | | Clay |
| 7 | 13.0 | 0 | ML | 57 | 95 | | Clay |
| 8 | 18.0 | 0 | ML | 57 | 95 | | Clay |
| 9 | 23.0 | 0 | ML | 57 | 95 | | Clay |
| 10 | 28.5 | 0 | ML | 57 | 95 | | Clay |
| 11 | 33.5 | 0 | ML | 57 | 95 | | Clay |
| 12 | 38.5 | 1 | ML | 57 | 95 | | Clay |
| 13 | 44.0 | 6 | SP-SM | 6 | 100 | | |
| 14 | 49.0 | 17 | SP-SM | 6 | 100 | | |
| 15 | 54.5 | 3 | SM | 31 | 120 | | Clay |
| 16 | 59.5 | 6 | SM | 31 | 120 | | Clay |
| 17 | 64.5 | 5 | SM | 31 | 120 | | Clay |
| 18 | 69.5 | 8 | SM | 31 | 120 | | Clay |
| 19 | 74.5 | 7 | SM | 15 | 120 | | Clay |
| 20 | 79.5 | 11 | SM | 15 | 120 | | Clay |
| 21 | 84.5 | 13 | SM | 15 | 120 | | Clay |
| 22 | 89.5 | 16 | SM | 15 | 120 | | Clay |
| 23 | 94.5 | 7 | SM | 15 | 120 | | Clay |
| 24 | 99.5 | 11 | SM | 15 | 120 | | Clay |
| 25 | 104.5 | 7 | SM | 15 | 120 | | Clay |
| 26 | 109.5 | 7 | SM | 15 | 120 | | Clay |
| 27 | 114.5 | 9 | SM | 15 | 120 | | Clay |
| 28 | 119.5 | 6 | SM | 15 | 120 | | Clay |
| 29 | 124.5 | 3 | SM | 15 | 120 | | Clay |
| 30 | 128.0 | 6 | SM | 15 | 120 | | Clay |
| 31 | 133.0 | 5 | SM | 15 | 120 | | Clay |
| 32 | 140.0 | 8 | SM | 15 | 120 | | Clay |
| 33 | 145.0 | 13 | SM | 15 | 120 | | Clay |
| 34 | 150.0 | 10 | SM | 15 | 120 | | Clay |
| 35 | 155.5 | 7 | SM | 15 | 120 | | Clay |
| 36 | 160.0 | 7 | SM | 15 | 120 | | Clay |
| 37 | 165.0 | 16 | SM | 15 | 120 | | Clay |
| 38 | 170.0 | 9 | SM | 15 | 120 | | Clay |
| 39 | 175.0 | 10 | SM | 15 | 120 | | Clay |
| 40 | 180.0 | 18 | SM | 15 | 120 | | Clay |
| 41 | 185.0 | 37 | SM | 15 | 120 | | Clay |
| 42 | 189.5 | 10 | SM | 15 | 120 | | Clay |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 0.0 | SC | 41.0 | 100.0 | | 175 | 19 | 1.39 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.58 | 5.58 | 1.005 | 1.580 |
| 2 | 2.0 | 0.0 | SC | 41.1 | 100.0 | | 325 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.59 | 5.59 | 1.002 | 0.731 |
| 3 | 4.0 | 6.0 | SC | 41.0 | 100.0 | | 525 | 150 | 1.39 | 1.00 | 0.80 | 1.00 | 6.65 | 1.70 | 11.30 | 5.58 | 16.89 | 0.997 | 0.588 |
| 4 | 6.0 | 2.0 | SP-SM | 7.9 | 100.0 | | 725 | 226 | 1.39 | 1.00 | 0.80 | 1.00 | 2.22 | 1.70 | 3.77 | 0.34 | 4.11 | 0.991 | 0.538 |
| 5 | 8.0 | 2.0 | SP-SM | 8.0 | 100.0 | | 925 | 301 | 1.39 | 1.00 | 0.85 | 1.00 | 2.35 | 1.70 | 4.00 | 0.37 | 4.37 | 0.985 | 0.512 |
| 6 | 10.0 | 2.0 | ML | 57.0 | 95.0 | Clay | 1115 | 366 | 1.39 | 1.00 | 0.85 | 1.00 | 2.35 | 1.70 | 4.00 | 5.61 | 9.61 | 0.978 | 0.504 |
| 7 | 13.0 | 0.0 | ML | 57.0 | 95.0 | Clay | 1400 | 464 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 0.968 | 0.494 |
| 8 | 18.0 | 0.0 | ML | 57.2 | 95.0 | Clay | 1875 | 627 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 0.949 | 0.480 |
| 9 | 23.0 | 0.0 | ML | 57.0 | 95.0 | Clay | 2350 | 790 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 0.928 | 0.466 |
| 10 | 28.5 | 0.0 | ML | 57.0 | 95.0 | Clay | 2872 | 969 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.60 | 0.00 | 5.61 | 5.61 | 0.903 | 0.452 |
| 11 | 33.5 | 0.0 | ML | 57.0 | 95.0 | Clay | 3347 | 1132 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.46 | 0.00 | 5.61 | 5.61 | 0.879 | 0.439 |
| 12 | 38.5 | 1.0 | ML | 57.0 | 95.0 | Clay | 3822 | 1295 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.33 | 1.84 | 5.61 | 7.44 | 0.855 | 0.426 |
| 13 | 44.0 | 6.0 | SP-SM | 6.0 | 100.0 | | 4372 | 1502 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 1.20 | 10.00 | 0.03 | 10.03 | 0.827 | 0.407 |
| 14 | 49.0 | 17.0 | SP-SM | 6.0 | 100.0 | | 4872 | 1690 | 1.39 | 1.00 | 1.00 | 1.00 | 23.55 | 1.09 | 25.73 | 0.03 | 25.76 | 0.803 | 0.391 |
| 15 | 54.5 | 3.0 | SM | 31.0 | 120.0 | Clay | 5532 | 2007 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.03 | 4.28 | 5.40 | 9.68 | 0.776 | 0.361 |
| 16 | 59.5 | 6.0 | SM | 31.0 | 120.0 | Clay | 6132 | 2295 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.96 | 7.98 | 5.40 | 13.38 | 0.752 | 0.340 |
| 17 | 64.5 | 5.0 | SM | 31.0 | 120.0 | Clay | 6732 | 2583 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.90 | 6.24 | 5.40 | 11.64 | 0.729 | 0.321 |
| 18 | 69.5 | 8.0 | SM | 31.0 | 120.0 | Clay | 7332 | 2871 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.86 | 9.55 | 5.40 | 14.95 | 0.708 | 0.305 |
| 19 | 74.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 7932 | 3159 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.81 | 7.85 | 3.26 | 11.11 | 0.687 | 0.292 |
| 20 | 79.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 8532 | 3447 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.79 | 12.03 | 3.26 | 15.29 | 0.668 | 0.280 |
| 21 | 84.5 | 13.0 | SM | 15.0 | 120.0 | Clay | 9132 | 3735 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.77 | 13.81 | 3.26 | 17.07 | 0.651 | 0.269 |
| 22 | 89.5 | 16.0 | SM | 15.0 | 120.0 | Clay | 9732 | 4023 | 1.39 | 1.00 | 1.00 | 1.00 | 22.16 | 0.75 | 16.69 | 3.26 | 19.96 | 0.636 | 0.260 |
| 23 | 94.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 10332 | 4311 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.68 | 6.59 | 3.26 | 9.85 | 0.622 | 0.252 |
| 24 | 99.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 10932 | 4599 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.68 | 10.33 | 3.26 | 13.59 | 0.611 | 0.245 |
| 25 | 104.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 11532 | 4887 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.63 | 6.12 | 3.26 | 9.39 | 0.602 | 0.240 |
| 26 | 109.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 12132 | 5175 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.61 | 5.92 | 3.26 | 9.18 | 0.594 | 0.236 |
| 27 | 114.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 12732 | 5463 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.60 | 7.53 | 3.26 | 10.79 | 0.589 | 0.232 |
| 28 | 119.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 13332 | 5751 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.57 | 4.71 | 3.26 | 7.98 | 0.587 | 0.230 |
| 29 | 124.5 | 3.0 | SM | 15.0 | 120.0 | Clay | 13932 | 6039 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 0.53 | 2.20 | 3.26 | 5.47 | 0.586 | 0.229 |
| 30 | 128.0 | 6.0 | SM | 15.0 | 120.0 | Clay | 14352 | 6240 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.54 | 4.48 | 3.26 | 7.75 | 0.587 | 0.228 |
| 31 | 133.0 | 5.0 | SM | 15.0 | 120.0 | Clay | 14952 | 6528 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.52 | 3.59 | 3.26 | 6.85 | 0.591 | 0.229 |
| 32 | 140.0 | 8.0 | SM | 15.0 | 120.0 | Clay | 15792 | 6932 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.52 | 5.75 | 3.26 | 9.01 | 0.600 | 0.231 |
| 33 | 145.0 | 13.0 | SM | 15.0 | 120.0 | Clay | 16392 | 7220 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.54 | 9.65 | 3.26 | 12.91 | 0.610 | 0.234 |
| 34 | 150.0 | 10.0 | SM | 15.0 | 120.0 | Clay | 16992 | 7508 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.51 | 7.01 | 3.26 | 10.27 | 0.622 | 0.238 |
| 35 | 155.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 17652 | 7824 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.48 | 4.61 | 3.26 | 7.87 | 0.639 | 0.244 |
| 36 | 160.0 | 7.0 | SM | 15.0 | 120.0 | Clay | 18192 | 8084 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.47 | 4.52 | 3.26 | 7.78 | 0.655 | 0.249 |
| 37 | 165.0 | 16.0 | SM | 15.0 | 120.0 | Clay | 18792 | 8372 | 1.39 | 1.00 | 1.00 | 1.00 | 22.16 | 0.51 | 11.28 | 3.26 | 14.54 | 0.675 | 0.256 |
| 38 | 170.0 | 9.0 | SM | 15.0 | 120.0 | Clay | 19392 | 8660 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.46 | 5.71 | 3.26 | 8.97 | 0.697 | 0.264 |
| 39 | 175.0 | 10.0 | SM | 15.0 | 120.0 | Clay | 19992 | 8948 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.45 | 6.30 | 3.26 | 9.56 | 0.722 | 0.273 |
| 40 | 180.0 | 18.0 | SM | 15.0 | 120.0 | Clay | 20592 | 9236 | 1.39 | 1.00 | 1.00 | 1.00 | 24.93 | 0.49 | 12.26 | 3.26 | 15.53 | 0.750 | 0.283 |
| 41 | 185.0 | 37.0 | SM | 15.0 | 120.0 | Clay | 21192 | 9524 | 1.39 | 1.00 | 1.00 | 1.00 | 51.25 | 0.60 | 30.98 | 3.26 | 34.24 | 0.780 | 0.293 |
| 42 | 189.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 21732 | 9783 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.43 | 5.96 | 3.26 | 9.22 | 0.808 | 0.303 |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.099 | 0.06 |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.099 | 0.14 |
| 1.38 | 1.03 | 1.10 | 0.173 | 0.195 | 0.33 |
| 1.11 | 1.01 | 1.10 | 0.081 | 0.090 | 0.17 |
| 1.11 | 1.01 | 1.10 | 0.083 | 0.091 | 0.18 |
| 1.18 | 1.01 | 1.10 | 0.115 | 0.128 | 2.00 |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.09 | 0.090 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.08 | 0.090 | 0.097 | 2.00 |
| 1.12 | 1.01 | 1.06 | 0.090 | 0.096 | 2.00 |
| 1.12 | 1.01 | 1.05 | 0.090 | 0.095 | 2.00 |
| 1.15 | 1.01 | 1.04 | 0.101 | 0.106 | 2.00 |
| 1.19 | 1.01 | 1.03 | 0.118 | 0.124 | 0.30 |
| 1.76 | 1.05 | 1.04 | 0.309 | 0.337 | 0.86 |
| 1.18 | 1.01 | 1.00 | 0.116 | 0.118 | 2.00 |
| 1.27 | 1.02 | 0.99 | 0.143 | 0.144 | 2.00 |
| 1.23 | 1.02 | 0.98 | 0.130 | 0.129 | 2.00 |
| 1.32 | 1.02 | 0.97 | 0.156 | 0.154 | 2.00 |
| 1.21 | 1.01 | 0.96 | 0.126 | 0.123 | 2.00 |
| 1.33 | 1.02 | 0.95 | 0.159 | 0.153 | 2.00 |
| 1.38 | 1.03 | 0.93 | 0.175 | 0.167 | 2.00 |
| 1.49 | 1.03 | 0.91 | 0.205 | 0.194 | 2.00 |
| 1.19 | 1.01 | 0.93 | 0.117 | 0.111 | 2.00 |
| 1.28 | 1.02 | 0.92 | 0.145 | 0.135 | 2.00 |
| 1.18 | 1.01 | 0.92 | 0.114 | 0.107 | 2.00 |
| 1.17 | 1.01 | 0.92 | 0.112 | 0.105 | 2.00 |
| 1.21 | 1.01 | 0.91 | 0.124 | 0.114 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.104 | 0.097 | 2.00 |
| 1.12 | 1.01 | 0.92 | 0.089 | 0.082 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.103 | 0.094 | 2.00 |
| 1.14 | 1.01 | 0.91 | 0.097 | 0.089 | 2.00 |
| 1.17 | 1.01 | 0.89 | 0.111 | 0.101 | 2.00 |
| 1.26 | 1.02 | 0.87 | 0.139 | 0.124 | 2.00 |
| 1.20 | 1.01 | 0.88 | 0.120 | 0.107 | 2.00 |
| 1.15 | 1.01 | 0.89 | 0.104 | 0.093 | 2.00 |
| 1.15 | 1.01 | 0.89 | 0.103 | 0.092 | 2.00 |
| 1.30 | 1.02 | 0.85 | 0.152 | 0.132 | 2.00 |
| 1.17 | 1.01 | 0.87 | 0.111 | 0.098 | 2.00 |
| 1.18 | 1.01 | 0.87 | 0.115 | 0.101 | 2.00 |
| 1.33 | 1.02 | 0.83 | 0.161 | 0.137 | 2.00 |
| 2.20 | 1.08 | 0.62 | 0.952 | 0.640 | 2.00 |
| 1.18 | 1.01 | 0.86 | 0.113 | 0.098 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.050 | 0.75 | 8.18 |
| 2 | 1.8 | 0.050 | 1.05 | 7.43 |
| 4 | 2.0 | 0.026 | 0.63 | 6.37 |
| 6 | 2.0 | 0.057 | 1.36 | 5.74 |
| 8 | 2.0 | 0.055 | 1.33 | 4.38 |
| 10 | 2.5 | 0.000 | 0.00 | 3.05 |
| 13 | 4.0 | 0.000 | 0.00 | 3.05 |
| 18 | 5.0 | 0.000 | 0.00 | 3.05 |
| 23 | 5.3 | 0.000 | 0.00 | 3.05 |
| 28.5 | 5.3 | 0.000 | 0.00 | 3.05 |
| 33.5 | 5.0 | 0.000 | 0.00 | 3.05 |
| 38.5 | 5.3 | 0.000 | 0.00 | 3.05 |
| 44 | 5.3 | 0.037 | 2.35 | 3.05 |
| 49 | 5.3 | 0.011 | 0.70 | 0.70 |
| 54.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 59.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 64.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 69.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 74.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 79.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 84.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 89.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 94.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 99.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 104.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 109.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 114.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 119.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 124.5 | 4.3 | 0.000 | 0.00 | 0.00 |
| 128 | 4.3 | 0.000 | 0.00 | 0.00 |
| 133 | 6.0 | 0.000 | 0.00 | 0.00 |
| 140 | 6.0 | 0.000 | 0.00 | 0.00 |
| 145 | 5.0 | 0.000 | 0.00 | 0.00 |
| 150 | 5.3 | 0.000 | 0.00 | 0.00 |
| 155.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 160 | 4.8 | 0.000 | 0.00 | 0.00 |
| 165 | 5.0 | 0.000 | 0.00 | 0.00 |
| 170 | 5.0 | 0.000 | 0.00 | 0.00 |
| 175 | 5.0 | 0.000 | 0.00 | 0.00 |
| 180 | 5.0 | 0.000 | 0.00 | 0.00 |
| 185 | 4.8 | 0.000 | 0.00 | 0.00 |
| 189.5 | 3.8 | 0.000 | 0.00 | 0.00 |
| 192.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 6:04 PM |
| Boring Designation: | B-11 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | -22 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 83.1 |
| Distance from sample hammer to ground surface (ft): | 27 |
| Borehole Diameter (in) | 4 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.26 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 0 | ML | 50 | 95 | | Clay |
| 2 | 2.0 | 1 | ML | 50 | 95 | | Clay |
| 3 | 4.0 | 0 | SM | 18 | 100 | | |
| 4 | 6.0 | 0 | CL | 52 | 95 | | Clay |
| 5 | 8.0 | 0 | SM | 15 | 100 | | |
| 6 | 14.5 | 0 | MH | 94 | 95 | | Clay |
| 7 | 20.0 | 0 | MH | 94 | 95 | | Clay |
| 8 | 25.5 | 2 | SM | 15 | 100 | | |
| 9 | 31.5 | 7 | SM | 15 | 100 | | |
| 10 | 36.0 | 6 | ML | 50 | 120 | | Clay |
| 11 | 41.5 | 5 | ML | 50 | 120 | | Clay |
| 12 | 46.5 | 7 | ML | 50 | 120 | | Clay |
| 13 | 51.5 | 7 | ML | 50 | 120 | | Clay |
| 14 | 56.5 | 23 | SM | 15 | 120 | | Clay |
| 15 | 61.0 | 6 | SM | 45 | 120 | | Clay |
| 16 | 65.5 | 5 | SM | 15 | 120 | | Clay |
| 17 | 70.5 | 5 | SM | 15 | 120 | | Clay |
| 18 | 75.0 | 6 | SM | 15 | 120 | | Clay |
| 19 | 78.0 | 5 | SM | 15 | 120 | | Clay |
| 20 | 82.5 | 27 | SM | 15 | 120 | | Clay |
| 21 | 85.0 | 1 | SM | 15 | 120 | | Clay |
| 22 | 90.0 | 8 | SM | 15 | 120 | | Clay |
| 23 | 98.5 | 9 | SM | 15 | 120 | | Clay |
| 24 | 104.0 | 11 | SM | 15 | 120 | | Clay |
| 25 | 110.0 | 8 | SM | 15 | 120 | | Clay |
| 26 | 115.5 | 10 | SM | 15 | 120 | | Clay |
| 27 | 121.5 | 8 | SM | 15 | 120 | | Clay |
| 28 | 125.5 | 10 | SM | 15 | 120 | | Clay |
| 29 | 132.0 | 9 | SM | 15 | 120 | | Clay |
| 30 | 137.0 | 10 | SM | 15 | 120 | | Clay |
| 31 | 141.5 | 12 | SM | 15 | 120 | | Clay |
| 32 | 146.0 | 10 | SM | 15 | 120 | | Clay |
| 33 | 150.5 | 8 | SM | 15 | 120 | | Clay |
| 34 | 155.0 | 19 | SM | 15 | 120 | | Clay |
| 35 | 159.5 | 10 | SM | 15 | 120 | | Clay |
| 36 | 164.0 | 9 | SM | 15 | 120 | | Clay |
| 37 | 168.5 | 9 | SM | 15 | 120 | | Clay |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 0.0 | ML | 50.0 | 95.0 | Clay | 1420 | 16 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 1.005 | 14.805 |
| 2 | 2.0 | 1.0 | ML | 50.0 | 95.0 | Clay | 1563 | 65 | 1.39 | 1.00 | 0.95 | 1.00 | 1.32 | 1.70 | 2.24 | 5.61 | 7.85 | 1.002 | 4.058 |
| 3 | 4.0 | 0.0 | SM | 18.1 | 100.0 | | 1763 | 140 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 4.11 | 4.11 | 0.997 | 2.115 |
| 4 | 6.0 | 0.0 | CL | 52.1 | 95.0 | Clay | 1953 | 206 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 0.991 | 1.591 |
| 5 | 8.0 | 0.0 | SM | 15.3 | 100.0 | | 2153 | 281 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.70 | 0.00 | 3.36 | 3.36 | 0.985 | 1.276 |
| 6 | 14.5 | 0.0 | MH | 93.7 | 95.0 | Clay | 2770 | 493 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.70 | 0.00 | 5.50 | 5.50 | 0.962 | 0.914 |
| 7 | 20.0 | 0.0 | MH | 94.0 | 95.0 | Clay | 3293 | 672 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.70 | 0.00 | 5.50 | 5.50 | 0.941 | 0.779 |
| 8 | 25.5 | 2.0 | SM | 15.0 | 100.0 | | 3843 | 879 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.65 | 4.57 | 3.26 | 7.83 | 0.917 | 0.677 |
| 9 | 31.5 | 7.0 | SM | 15.0 | 100.0 | | 4443 | 1104 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 1.36 | 13.18 | 3.26 | 16.44 | 0.889 | 0.604 |
| 10 | 36.0 | 6.0 | ML | 50.0 | 120.0 | Clay | 4983 | 1364 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 1.23 | 10.25 | 5.61 | 15.87 | 0.867 | 0.535 |
| 11 | 41.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 5643 | 1680 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 1.12 | 7.78 | 5.61 | 13.39 | 0.840 | 0.477 |
| 12 | 46.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 6243 | 1968 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 1.04 | 10.04 | 5.61 | 15.65 | 0.815 | 0.437 |
| 13 | 51.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 6843 | 2256 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.97 | 9.40 | 5.61 | 15.01 | 0.790 | 0.405 |
| 14 | 56.5 | 23.0 | SM | 15.0 | 120.0 | Clay | 7443 | 2544 | 1.39 | 1.00 | 1.00 | 1.00 | 31.86 | 0.94 | 29.91 | 3.26 | 33.17 | 0.766 | 0.379 |
| 15 | 61.0 | 6.0 | SM | 45.3 | 120.0 | Clay | 7983 | 2804 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.87 | 7.20 | 5.61 | 12.81 | 0.745 | 0.359 |
| 16 | 65.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 8523 | 3063 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.81 | 5.64 | 3.26 | 8.90 | 0.725 | 0.341 |
| 17 | 70.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 9123 | 3351 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.77 | 5.36 | 3.26 | 8.62 | 0.703 | 0.324 |
| 18 | 75.0 | 6.0 | SM | 15.0 | 120.0 | Clay | 9663 | 3610 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.75 | 6.20 | 3.26 | 9.46 | 0.685 | 0.310 |
| 19 | 78.0 | 5.0 | SM | 15.0 | 120.0 | Clay | 10023 | 3783 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.72 | 4.99 | 3.26 | 8.25 | 0.674 | 0.302 |
| 20 | 82.5 | 27.0 | SM | 15.0 | 120.0 | Clay | 10563 | 4042 | 1.39 | 1.00 | 1.00 | 1.00 | 37.40 | 0.80 | 29.99 | 3.26 | 33.25 | 0.658 | 0.291 |
| 21 | 85.0 | 1.0 | SM | 15.0 | 120.0 | Clay | 10863 | 4186 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 0.65 | 0.90 | 3.26 | 4.16 | 0.650 | 0.285 |
| 22 | 90.0 | 8.0 | SM | 15.0 | 120.0 | Clay | 11463 | 4474 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.67 | 7.43 | 3.26 | 10.70 | 0.634 | 0.275 |
| 23 | 98.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 12483 | 4964 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.64 | 7.95 | 3.26 | 11.22 | 0.613 | 0.261 |
| 24 | 104.0 | 11.0 | SM | 15.0 | 120.0 | Clay | 13143 | 5280 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.63 | 9.57 | 3.26 | 12.83 | 0.602 | 0.253 |
| 25 | 110.0 | 8.0 | SM | 15.0 | 120.0 | Clay | 13863 | 5626 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.59 | 6.51 | 3.26 | 9.77 | 0.594 | 0.247 |
| 26 | 115.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 14523 | 5943 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.58 | 8.05 | 3.26 | 11.31 | 0.589 | 0.243 |
| 27 | 121.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 15243 | 6288 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.55 | 6.09 | 3.26 | 9.35 | 0.586 | 0.240 |
| 28 | 125.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 15723 | 6519 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.55 | 7.62 | 3.26 | 10.89 | 0.586 | 0.239 |
| 29 | 132.0 | 9.0 | SM | 15.0 | 120.0 | Clay | 16503 | 6893 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.53 | 6.56 | 3.26 | 9.82 | 0.590 | 0.239 |
| 30 | 137.0 | 10.0 | SM | 15.0 | 120.0 | Clay | 17103 | 7181 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.52 | 7.20 | 3.26 | 10.46 | 0.596 | 0.240 |
| 31 | 141.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 17643 | 7440 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.52 | 8.66 | 3.26 | 11.92 | 0.603 | 0.242 |
| 32 | 146.0 | 10.0 | SM | 15.0 | 120.0 | Clay | 18183 | 7700 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.50 | 6.90 | 3.26 | 10.16 | 0.612 | 0.244 |
| 33 | 150.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 18723 | 7959 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.48 | 5.28 | 3.26 | 8.54 | 0.624 | 0.248 |
| 34 | 155.0 | 19.0 | SM | 15.0 | 120.0 | Clay | 19263 | 8218 | 1.39 | 1.00 | 1.00 | 1.00 | 26.32 | 0.53 | 14.00 | 3.26 | 17.27 | 0.637 | 0.252 |
| 35 | 159.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 19803 | 8477 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.47 | 6.51 | 3.26 | 9.77 | 0.653 | 0.258 |
| 36 | 164.0 | 9.0 | SM | 15.0 | 120.0 | Clay | 20343 | 8736 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.46 | 5.68 | 3.26 | 8.94 | 0.670 | 0.264 |
| 37 | 168.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 20883 | 8996 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.45 | 5.58 | 3.26 | 8.84 | 0.690 | 0.271 |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.100 | 2.00 |
| 1.15 | 1.01 | 1.10 | 0.104 | 0.115 | 2.00 |
| 1.11 | 1.01 | 1.10 | 0.081 | 0.090 | 0.04 |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.100 | 2.00 |
| 1.10 | 1.01 | 1.10 | 0.077 | 0.085 | 0.07 |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.09 | 0.089 | 0.098 | 2.00 |
| 1.15 | 1.01 | 1.07 | 0.103 | 0.112 | 0.17 |
| 1.36 | 1.02 | 1.08 | 0.169 | 0.186 | 0.31 |
| 1.34 | 1.02 | 1.05 | 0.164 | 0.176 | 2.00 |
| 1.27 | 1.02 | 1.02 | 0.143 | 0.149 | 2.00 |
| 1.34 | 1.02 | 1.01 | 0.162 | 0.167 | 2.00 |
| 1.32 | 1.02 | 0.99 | 0.156 | 0.158 | 2.00 |
| 2.20 | 1.08 | 0.96 | 0.782 | 0.809 | 2.00 |
| 1.26 | 1.02 | 0.97 | 0.139 | 0.137 | 2.00 |
| 1.17 | 1.01 | 0.97 | 0.111 | 0.108 | 2.00 |
| 1.16 | 1.01 | 0.96 | 0.109 | 0.105 | 2.00 |
| 1.18 | 1.01 | 0.95 | 0.114 | 0.110 | 2.00 |
| 1.16 | 1.01 | 0.95 | 0.106 | 0.102 | 2.00 |
| 2.20 | 1.08 | 0.85 | 0.792 | 0.725 | 2.00 |
| 1.11 | 1.01 | 0.95 | 0.081 | 0.078 | 2.00 |
| 1.21 | 1.01 | 0.93 | 0.123 | 0.116 | 2.00 |
| 1.22 | 1.01 | 0.92 | 0.127 | 0.118 | 2.00 |
| 1.26 | 1.02 | 0.91 | 0.139 | 0.128 | 2.00 |
| 1.19 | 1.01 | 0.91 | 0.116 | 0.107 | 2.00 |
| 1.22 | 1.01 | 0.90 | 0.127 | 0.116 | 2.00 |
| 1.18 | 1.01 | 0.90 | 0.114 | 0.104 | 2.00 |
| 1.21 | 1.01 | 0.89 | 0.124 | 0.113 | 2.00 |
| 1.19 | 1.01 | 0.89 | 0.117 | 0.106 | 2.00 |
| 1.20 | 1.01 | 0.89 | 0.121 | 0.109 | 2.00 |
| 1.23 | 1.02 | 0.88 | 0.132 | 0.117 | 2.00 |
| 1.19 | 1.01 | 0.88 | 0.119 | 0.106 | 2.00 |
| 1.16 | 1.01 | 0.88 | 0.108 | 0.097 | 2.00 |
| 1.39 | 1.03 | 0.84 | 0.176 | 0.152 | 2.00 |
| 1.19 | 1.01 | 0.87 | 0.116 | 0.103 | 2.00 |
| 1.17 | 1.01 | 0.87 | 0.111 | 0.098 | 2.00 |
| 1.17 | 1.01 | 0.87 | 0.110 | 0.097 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.000 | 0.00 | 9.12 |
| 2 | 1.8 | 0.000 | 0.00 | 9.12 |
| 4 | 2.0 | 0.057 | 1.36 | 9.12 |
| 6 | 2.0 | 0.000 | 0.00 | 7.75 |
| 8 | 4.3 | 0.061 | 3.11 | 7.75 |
| 14.5 | 6.0 | 0.000 | 0.00 | 4.64 |
| 20 | 5.5 | 0.000 | 0.00 | 4.64 |
| 25.5 | 5.8 | 0.043 | 2.95 | 4.64 |
| 31.5 | 5.3 | 0.027 | 1.69 | 1.69 |
| 36 | 5.0 | 0.000 | 0.00 | 0.00 |
| 41.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 46.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 51.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 56.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 61 | 4.5 | 0.000 | 0.00 | 0.00 |
| 65.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 70.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 75 | 3.8 | 0.000 | 0.00 | 0.00 |
| 78 | 3.8 | 0.000 | 0.00 | 0.00 |
| 82.5 | 3.5 | 0.000 | 0.00 | 0.00 |
| 85 | 3.8 | 0.000 | 0.00 | 0.00 |
| 90 | 6.8 | 0.000 | 0.00 | 0.00 |
| 98.5 | 7.0 | 0.000 | 0.00 | 0.00 |
| 104 | 5.8 | 0.000 | 0.00 | 0.00 |
| 110 | 5.8 | 0.000 | 0.00 | 0.00 |
| 115.5 | 5.8 | 0.000 | 0.00 | 0.00 |
| 121.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 125.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 132 | 5.8 | 0.000 | 0.00 | 0.00 |
| 137 | 4.8 | 0.000 | 0.00 | 0.00 |
| 141.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 146 | 4.5 | 0.000 | 0.00 | 0.00 |
| 150.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 155 | 4.5 | 0.000 | 0.00 | 0.00 |
| 159.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 164 | 4.5 | 0.000 | 0.00 | 0.00 |
| 168.5 | 3.8 | 0.000 | 0.00 | 0.00 |
| 171.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:53 PM |
| Boring Designation: | B-12 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | -33 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 83.1 |
| Distance from sample hammer to ground surface (ft): | 38 |
| Borehole Diameter (in) | 4 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.29 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 1 | CL | 50 | 95 | | Clay |
| 2 | 2.0 | 4 | CL | 50 | 95 | | Clay |
| 3 | 4.0 | 3 | SM | 24 | 100 | | |
| 4 | 6.0 | 9 | SC | 15 | 100 | | |
| 5 | 8.0 | 4 | SP | 0 | 100 | | |
| 6 | 12.5 | 5 | SP-SM | 10 | 100 | | |
| 7 | 17.5 | 7 | SM | 48 | 120 | | Clay |
| 8 | 23.0 | 8 | SM | 48 | 120 | | Clay |
| 9 | 28.0 | 4 | SM | 48 | 120 | | Clay |
| 10 | 36.5 | 6 | SM | 48 | 120 | | Clay |
| 11 | 42.0 | 9 | SM | 48 | 120 | | Clay |
| 12 | 47.0 | 6 | SM | 47 | 120 | | Clay |
| 13 | 53.0 | 8 | SM | 47 | 120 | | Clay |
| 14 | 58.0 | 12 | SM | 15 | 120 | | Clay |
| 15 | 63.5 | 11 | SM | 50 | 120 | | Clay |
| 16 | 69.0 | 9 | SM | 15 | 120 | | Clay |
| 17 | 73.5 | 12 | SM | 15 | 120 | | Clay |
| 18 | 77.5 | 8 | SM | 15 | 120 | | Clay |
| 19 | 82.5 | 5 | SM | 15 | 120 | | Clay |
| 20 | 87.5 | | SM | 15 | 120 | | Clay |
| 21 | 92.5 | 14 | SM | 15 | 120 | | Clay |
| 22 | 97.5 | 12 | SM | 15 | 120 | | Clay |
| 23 | 102.5 | 7 | SM | 15 | 120 | | Clay |
| 24 | 108.0 | 12 | SM | 15 | 120 | | Clay |
| 25 | 115.5 | 8 | SM | 15 | 120 | | Clay |
| 26 | 118.5 | 11 | SM | 15 | 120 | | Clay |
| 27 | 122.5 | 9 | SM | 15 | 120 | | Clay |
| 28 | 127.0 | 19 | SM | 15 | 120 | | Clay |
| 29 | 132.0 | 10 | SM | 15 | 120 | | Clay |
| 30 | 137.0 | 8 | SM | 15 | 120 | | Clay |
| 31 | 141.5 | 20 | SM | 15 | 120 | | Clay |
| 32 | 147.0 | | SM | 15 | 120 | | Clay |
| 33 | 152.5 | 12 | SM | 15 | 120 | | Clay |
| 34 | 157.5 | 8 | SM | 15 | 120 | | Clay |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 1.0 | CL | 50.0 | 95.0 | Clay | 2107 | 16 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.70 | 2.35 | 5.61 | 7.97 | 1.005 | 24.495 |
| 2 | 2.0 | 4.0 | CL | 50.0 | 95.0 | Clay | 2249 | 65 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.70 | 9.42 | 5.61 | 15.03 | 1.002 | 6.514 |
| 3 | 4.0 | 3.0 | SM | 23.8 | 100.0 | | 2449 | 140 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.70 | 7.06 | 4.97 | 12.03 | 0.997 | 3.277 |
| 4 | 6.0 | 9.0 | SC | 15.0 | 100.0 | | 2649 | 216 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 1.70 | 21.19 | 3.26 | 24.45 | 0.991 | 2.295 |
| 5 | 8.0 | 4.0 | SP | 0.0 | 100.0 | | 2849 | 291 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.70 | 9.42 | 0.00 | 9.42 | 0.985 | 1.819 |
| 6 | 12.5 | 5.0 | SP-SM | 10.4 | 100.0 | | 3299 | 460 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 1.70 | 11.77 | 1.33 | 13.11 | 0.970 | 1.311 |
| 7 | 17.5 | 7.0 | SM | 48.0 | 120.0 | Clay | 3899 | 748 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 1.57 | 15.22 | 5.61 | 20.83 | 0.951 | 0.934 |
| 8 | 23.0 | 8.0 | SM | 48.0 | 120.0 | Clay | 4559 | 1065 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 1.35 | 14.95 | 5.61 | 20.56 | 0.928 | 0.749 |
| 9 | 28.0 | 4.0 | SM | 48.0 | 120.0 | Clay | 5159 | 1353 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.26 | 6.96 | 5.61 | 12.58 | 0.905 | 0.651 |
| 10 | 36.5 | 6.0 | SM | 48.0 | 120.0 | Clay | 6179 | 1842 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 1.07 | 8.90 | 5.61 | 14.51 | 0.865 | 0.547 |
| 11 | 42.0 | 9.0 | SM | 48.0 | 120.0 | Clay | 6839 | 2159 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.99 | 12.35 | 5.61 | 17.96 | 0.837 | 0.500 |
| 12 | 47.0 | 6.0 | SM | 46.6 | 120.0 | Clay | 7439 | 2447 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.93 | 7.72 | 5.61 | 13.33 | 0.813 | 0.466 |
| 13 | 53.0 | 8.0 | SM | 47.0 | 120.0 | Clay | 8159 | 2793 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.87 | 9.69 | 5.61 | 15.30 | 0.783 | 0.431 |
| 14 | 58.0 | 12.0 | SM | 15.0 | 120.0 | Clay | 8759 | 3081 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.84 | 13.95 | 3.26 | 17.22 | 0.759 | 0.407 |
| 15 | 63.5 | 11.0 | SM | 49.7 | 120.0 | Clay | 9419 | 3398 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.80 | 12.26 | 5.61 | 17.87 | 0.734 | 0.383 |
| 16 | 69.0 | 9.0 | SM | 15.0 | 120.0 | Clay | 10079 | 3714 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.75 | 9.35 | 3.26 | 12.61 | 0.710 | 0.363 |
| 17 | 73.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 10619 | 3974 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.74 | 12.27 | 3.26 | 15.53 | 0.691 | 0.348 |
| 18 | 77.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 11099 | 4204 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.70 | 7.70 | 3.26 | 10.96 | 0.676 | 0.336 |
| 19 | 82.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 11699 | 4492 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.65 | 4.51 | 3.26 | 7.77 | 0.658 | 0.323 |
| 20 | 87.5 | 0.0 | SM | 15.0 | 120.0 | Clay | 12299 | 4780 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 0.59 | 0.00 | 3.26 | 3.26 | 0.642 | 0.311 |
| 21 | 92.5 | 14.0 | SM | 15.0 | 120.0 | Clay | 12899 | 5068 | 1.39 | 1.00 | 1.00 | 1.00 | 19.39 | 0.66 | 12.79 | 3.26 | 16.05 | 0.628 | 0.301 |
| 22 | 97.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 13499 | 5356 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.63 | 10.45 | 3.26 | 13.71 | 0.615 | 0.292 |
| 23 | 102.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 14099 | 5644 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.58 | 5.62 | 3.26 | 8.89 | 0.605 | 0.285 |
| 24 | 108.0 | 12.0 | SM | 15.0 | 120.0 | Clay | 14759 | 5961 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.59 | 9.84 | 3.26 | 13.10 | 0.596 | 0.278 |
| 25 | 115.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 15659 | 6393 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.54 | 6.03 | 3.26 | 9.29 | 0.589 | 0.272 |
| 26 | 118.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 16019 | 6566 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.55 | 8.44 | 3.26 | 11.70 | 0.587 | 0.270 |
| 27 | 122.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 16499 | 6796 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.53 | 6.62 | 3.26 | 9.88 | 0.586 | 0.268 |
| 28 | 127.0 | 19.0 | SM | 15.0 | 120.0 | Clay | 17039 | 7055 | 1.39 | 1.00 | 1.00 | 1.00 | 26.32 | 0.58 | 15.24 | 3.26 | 18.50 | 0.587 | 0.267 |
| 29 | 132.0 | 10.0 | SM | 15.0 | 120.0 | Clay | 17639 | 7343 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.51 | 7.10 | 3.26 | 10.36 | 0.590 | 0.267 |
| 30 | 137.0 | 8.0 | SM | 15.0 | 120.0 | Clay | 18239 | 7631 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.49 | 5.42 | 3.26 | 8.68 | 0.596 | 0.268 |
| 31 | 141.5 | 20.0 | SM | 15.0 | 120.0 | Clay | 18779 | 7890 | 1.39 | 1.00 | 1.00 | 1.00 | 27.70 | 0.55 | 15.25 | 3.26 | 18.51 | 0.603 | 0.270 |
| 32 | 147.0 | 0.0 | SM | 15.0 | 120.0 | Clay | 19439 | 8207 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 0.42 | 0.00 | 3.26 | 3.26 | 0.615 | 0.274 |
| 33 | 152.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 20099 | 8524 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.48 | 7.98 | 3.26 | 11.24 | 0.629 | 0.280 |
| 34 | 157.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 20699 | 8812 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.45 | 4.96 | 3.26 | 8.22 | 0.645 | 0.286 |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.15 | 1.01 | 1.10 | 0.104 | 0.116 | 2.00 |
| 1.32 | 1.02 | 1.10 | 0.156 | 0.176 | 2.00 |
| 1.24 | 1.02 | 1.10 | 0.133 | 0.148 | 0.05 |
| 1.69 | 1.05 | 1.10 | 0.278 | 0.320 | 0.14 |
| 1.18 | 1.01 | 1.10 | 0.114 | 0.127 | 0.07 |
| 1.26 | 1.02 | 1.10 | 0.141 | 0.158 | 0.12 |
| 1.53 | 1.04 | 1.10 | 0.216 | 0.247 | 2.00 |
| 1.52 | 1.04 | 1.09 | 0.213 | 0.241 | 2.00 |
| 1.25 | 1.02 | 1.05 | 0.137 | 0.145 | 2.00 |
| 1.30 | 1.02 | 1.02 | 0.152 | 0.157 | 2.00 |
| 1.42 | 1.03 | 1.00 | 0.183 | 0.188 | 2.00 |
| 1.27 | 1.02 | 0.98 | 0.143 | 0.143 | 2.00 |
| 1.33 | 1.02 | 0.97 | 0.159 | 0.157 | 2.00 |
| 1.39 | 1.03 | 0.95 | 0.176 | 0.172 | 2.00 |
| 1.41 | 1.03 | 0.94 | 0.182 | 0.177 | 2.00 |
| 1.25 | 1.02 | 0.94 | 0.137 | 0.131 | 2.00 |
| 1.33 | 1.02 | 0.93 | 0.161 | 0.153 | 2.00 |
| 1.21 | 1.01 | 0.93 | 0.125 | 0.118 | 2.00 |
| 1.15 | 1.01 | 0.94 | 0.103 | 0.098 | 2.00 |
| 1.10 | 1.01 | 0.94 | 0.077 | 0.073 | 2.00 |
| 1.35 | 1.02 | 0.90 | 0.165 | 0.152 | 2.00 |
| 1.28 | 1.02 | 0.90 | 0.146 | 0.134 | 2.00 |
| 1.17 | 1.01 | 0.91 | 0.110 | 0.102 | 2.00 |
| 1.26 | 1.02 | 0.89 | 0.141 | 0.128 | 2.00 |
| 1.18 | 1.01 | 0.90 | 0.113 | 0.103 | 2.00 |
| 1.23 | 1.02 | 0.89 | 0.130 | 0.118 | 2.00 |
| 1.19 | 1.01 | 0.89 | 0.117 | 0.106 | 2.00 |
| 1.43 | 1.03 | 0.85 | 0.189 | 0.165 | 2.00 |
| 1.20 | 1.01 | 0.88 | 0.121 | 0.108 | 2.00 |
| 1.17 | 1.01 | 0.89 | 0.109 | 0.098 | 2.00 |
| 1.44 | 1.03 | 0.83 | 0.189 | 0.162 | 2.00 |
| 1.10 | 1.01 | 0.91 | 0.077 | 0.070 | 2.00 |
| 1.22 | 1.01 | 0.87 | 0.127 | 0.111 | 2.00 |
| 1.16 | 1.01 | 0.88 | 0.106 | 0.094 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.000 | 0.00 | 4.57 |
| 2 | 1.8 | 0.000 | 0.00 | 4.57 |
| 4 | 2.0 | 0.033 | 0.80 | 4.57 |
| 6 | 2.0 | 0.019 | 0.46 | 3.77 |
| 8 | 3.3 | 0.039 | 1.51 | 3.31 |
| 12.5 | 4.8 | 0.032 | 1.80 | 1.80 |
| 17.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 23 | 5.3 | 0.000 | 0.00 | 0.00 |
| 28 | 6.8 | 0.000 | 0.00 | 0.00 |
| 36.5 | 7.0 | 0.000 | 0.00 | 0.00 |
| 42 | 5.3 | 0.000 | 0.00 | 0.00 |
| 47 | 5.5 | 0.000 | 0.00 | 0.00 |
| 53 | 5.5 | 0.000 | 0.00 | 0.00 |
| 58 | 5.3 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 69 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 4.3 | 0.000 | 0.00 | 0.00 |
| 77.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 82.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 87.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 92.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 97.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 102.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 108 | 6.5 | 0.000 | 0.00 | 0.00 |
| 115.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 118.5 | 3.5 | 0.000 | 0.00 | 0.00 |
| 122.5 | 4.3 | 0.000 | 0.00 | 0.00 |
| 127 | 4.8 | 0.000 | 0.00 | 0.00 |
| 132 | 5.0 | 0.000 | 0.00 | 0.00 |
| 137 | 4.8 | 0.000 | 0.00 | 0.00 |
| 141.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 147 | 5.5 | 0.000 | 0.00 | 0.00 |
| 152.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 157.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 160.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 5:54 PM |
| **Boring Designation:** | B-13 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | -28 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 83.1 |
| **Distance from sample hammer to ground surface (ft):** | 33 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.29 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" | |
|---|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 1 | SM | 23 | 100 | | | |
| 2 | 2.0 | 3 | SM | 23 | 100 | | | |
| 3 | 4.0 | 3 | SM | 23 | 100 | | | |
| 4 | 6.0 | 3 | SM | 23 | 100 | | | |
| 5 | 8.0 | 1 | SC | 15 | 100 | | | |
| 6 | 14.5 | 1 | CL | 64 | 95 | | Clay | |
| 7 | 19.5 | 0 | CL | 64 | 95 | | Clay | |
| 8 | 24.5 | 2 | ML | 65 | 95 | | | |
| 9 | 30.0 | 6 | SC | 44 | 120 | | Clay | *Assumes Marl/Limestone NonLiq |
| 10 | 35.5 | 4 | SC | 44 | 120 | | Clay | |
| 11 | 41.0 | 6 | SC | 44 | 120 | | Clay | |
| 12 | 48.5 | 6 | ML | 50 | 120 | | Clay | |
| 13 | 53.5 | 7 | ML | 50 | 120 | | Clay | |
| 14 | 58.5 | 4 | ML | 50 | 120 | | Clay | |
| 15 | 62.5 | 23 | ML | 50 | 120 | | Clay | |
| 16 | 66.5 | 7 | ML | 50 | 120 | | Clay | |
| 17 | 71.5 | 7 | ML | 50 | 120 | | Clay | |
| 18 | 76.0 | 10 | ML | 50 | 120 | | Clay | |
| 19 | 81.0 | 6 | ML | 50 | 120 | | Clay | |
| 20 | 88.5 | 6 | ML | 50 | 120 | | Clay | |
| 21 | 93.5 | 12 | ML | 50 | 120 | | Clay | |
| 22 | 99.0 | 11 | ML | 50 | 120 | | Clay | |
| 23 | 104.5 | 7 | ML | 50 | 120 | | Clay | |
| 24 | 110.0 | 9 | ML | 50 | 120 | | Clay | |
| 25 | 118.0 | 8 | ML | 50 | 120 | | Clay | |
| 26 | 120.0 | 8 | ML | 50 | 120 | | Clay | |
| 27 | 124.5 | 7 | ML | 50 | 120 | | Clay | |
| 28 | 129.0 | 8 | ML | 50 | 120 | | Clay | |
| 29 | 134.0 | 10 | ML | 50 | 120 | | Clay | |
| 30 | 138.5 | 9 | ML | 50 | 120 | | Clay | |
| 31 | 144.0 | 12 | ML | 50 | 120 | | Clay | |
| 32 | 149.5 | 7 | ML | 50 | 120 | | Clay | |
| 33 | 155.5 | 13 | ML | 50 | 120 | | Clay | |
| 34 | 161.0 | 17 | ML | 50 | 120 | | Clay | |
| 35 | | | | | | | | |
| 36 | | | | | | | | |
| 37 | | | | | | | | |
| 38 | | | | | | | | |
| 39 | | | | | | | | |
| 40 | | | | | | | | |
| 41 | | | | | | | | |
| 42 | | | | | | | | |
| 43 | | | | | | | | |
| 44 | | | | | | | | |
| 45 | | | | | | | | |
| 46 | | | | | | | | |
| 47 | | | | | | | | |
| 48 | | | | | | | | |
| 49 | | | | | | | | |
| 50 | | | | | | | | |

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR | MS |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB (MSFmax) |
| 1 | 0.5 | 1.0 | SM | 23.0 | 100.0 | | 1797 | 19 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.70 | 2.35 | 4.88 | 7.24 | 1.005 | 18.117 | 1.14 |
| 2 | 2.0 | 3.0 | SM | 23.0 | 100.0 | | 1947 | 75 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.70 | 7.06 | 4.88 | 11.95 | 1.002 | 4.890 | 1.23 |
| 3 | 4.0 | 3.0 | SM | 22.8 | 100.0 | | 2147 | 150 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.70 | 7.06 | 4.86 | 11.93 | 0.997 | 2.682 | 1.23 |
| 4 | 6.0 | 3.0 | SM | 23.0 | 100.0 | | 2347 | 226 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.70 | 7.06 | 4.88 | 11.95 | 0.991 | 1.943 | 1.23 |
| 5 | 8.0 | 1.0 | SC | 15.0 | 100.0 | | 2547 | 301 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.70 | 2.35 | 3.26 | 5.62 | 0.985 | 1.572 | 1.12 |
| 6 | 14.5 | 1.0 | CL | 64.2 | 95.0 | Clay | 3165 | 513 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.70 | 2.35 | 5.59 | 7.95 | 0.962 | 1.120 | 1.15 |
| 7 | 19.5 | 0.0 | CL | 64.0 | 95.0 | Clay | 3640 | 676 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.70 | 0.00 | 5.59 | 5.59 | 0.943 | 0.957 | 1.12 |
| 8 | 24.5 | 2.0 | ML | 65.3 | 95.0 | | 4115 | 839 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.65 | 4.56 | 5.59 | 10.15 | 0.921 | 0.852 | 1.19 |
| 9 | 30.0 | 6.0 | SC | 44.0 | 120.0 | Clay | 4775 | 1156 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 1.33 | 11.05 | 5.60 | 16.65 | 0.896 | 0.698 | 1.37 |
| 10 | 35.5 | 4.0 | SC | 43.9 | 120.0 | Clay | 5435 | 1472 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.21 | 6.68 | 5.60 | 12.28 | 0.869 | 0.605 | 1.24 |
| 11 | 41.0 | 6.0 | SC | 44.0 | 120.0 | Clay | 6095 | 1789 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 1.09 | 9.02 | 5.60 | 14.62 | 0.842 | 0.541 | 1.31 |
| 12 | 48.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 6995 | 2221 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.98 | 8.11 | 5.61 | 13.73 | 0.805 | 0.478 | 1.28 |
| 13 | 53.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 7595 | 2509 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.92 | 8.92 | 5.61 | 14.53 | 0.781 | 0.445 | 1.30 |
| 14 | 58.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 8195 | 2797 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 0.86 | 4.77 | 5.61 | 10.38 | 0.757 | 0.418 | 1.20 |
| 15 | 62.5 | 23.0 | ML | 50.0 | 120.0 | Clay | 8675 | 3028 | 1.39 | 1.00 | 1.00 | 1.00 | 31.86 | 0.89 | 28.23 | 5.61 | 33.85 | 0.738 | 0.399 | 2.20 |
| 16 | 66.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 9155 | 3258 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.80 | 7.80 | 5.61 | 13.42 | 0.720 | 0.382 | 1.27 |
| 17 | 71.5 | 7.0 | ML | 50.2 | 120.0 | Clay | 9755 | 3546 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.77 | 7.47 | 5.61 | 13.08 | 0.699 | 0.363 | 1.26 |
| 18 | 76.0 | 10.0 | ML | 50.0 | 120.0 | Clay | 10295 | 3805 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.76 | 10.48 | 5.61 | 16.09 | 0.681 | 0.347 | 1.35 |
| 19 | 81.0 | 6.0 | ML | 50.0 | 120.0 | Clay | 10895 | 4093 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.71 | 5.88 | 5.61 | 11.50 | 0.663 | 0.333 | 1.22 |
| 20 | 88.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 11795 | 4525 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.67 | 5.57 | 5.61 | 11.18 | 0.639 | 0.314 | 1.22 |
| 21 | 93.5 | 12.0 | ML | 50.0 | 120.0 | Clay | 12395 | 4813 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.68 | 11.31 | 5.61 | 16.93 | 0.625 | 0.303 | 1.38 |
| 22 | 99.0 | 11.0 | ML | 50.0 | 120.0 | Clay | 13055 | 5130 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.65 | 9.95 | 5.61 | 15.57 | 0.612 | 0.294 | 1.33 |
| 23 | 104.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 13715 | 5447 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.61 | 5.91 | 5.61 | 11.53 | 0.602 | 0.286 | 1.22 |
| 24 | 110.0 | 9.0 | ML | 50.0 | 120.0 | Clay | 14375 | 5764 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.60 | 7.51 | 5.61 | 13.12 | 0.594 | 0.279 | 1.26 |
| 25 | 118.0 | 8.0 | ML | 50.0 | 120.0 | Clay | 15335 | 6224 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.57 | 6.33 | 5.61 | 11.95 | 0.587 | 0.273 | 1.23 |
| 26 | 120.0 | 8.0 | ML | 50.0 | 120.0 | Clay | 15575 | 6340 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.57 | 6.27 | 5.61 | 11.88 | 0.587 | 0.272 | 1.23 |
| 27 | 124.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 16115 | 6599 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.55 | 5.30 | 5.61 | 10.92 | 0.586 | 0.270 | 1.21 |
| 28 | 129.0 | 8.0 | ML | 50.0 | 120.0 | Clay | 16655 | 6858 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.54 | 6.00 | 5.61 | 11.61 | 0.588 | 0.269 | 1.23 |
| 29 | 134.0 | 10.0 | ML | 50.0 | 120.0 | Clay | 17255 | 7146 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.54 | 7.48 | 5.61 | 13.10 | 0.592 | 0.269 | 1.26 |
| 30 | 138.5 | 9.0 | ML | 50.0 | 120.0 | Clay | 17795 | 7405 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.52 | 6.53 | 5.61 | 12.14 | 0.598 | 0.271 | 1.24 |
| 31 | 144.0 | 12.0 | ML | 50.0 | 120.0 | Clay | 18455 | 7722 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.53 | 8.78 | 5.61 | 14.40 | 0.608 | 0.274 | 1.30 |
| 32 | 149.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 19115 | 8039 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.49 | 4.73 | 5.61 | 10.35 | 0.621 | 0.278 | 1.20 |
| 33 | 155.5 | 13.0 | ML | 50.0 | 120.0 | Clay | 19835 | 8384 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.51 | 9.19 | 5.61 | 14.80 | 0.639 | 0.285 | 1.31 |
| 34 | 161.0 | 17.0 | ML | 50.0 | 120.0 | Clay | 20495 | 8701 | 1.39 | 1.00 | 1.00 | 1.00 | 23.55 | 0.52 | 12.31 | 5.61 | 17.92 | 0.658 | 0.292 | 1.41 |
| 35 | | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | | |

| ıF | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|
| IB | IB | IB | IB | IB |
| 1.01 | 1.10 | 0.100 | 0.111 | 0.01 |
| 1.02 | 1.10 | 0.132 | 0.148 | 0.03 |
| 1.02 | 1.10 | 0.132 | 0.147 | 0.05 |
| 1.02 | 1.10 | 0.132 | 0.148 | 0.08 |
| 1.01 | 1.10 | 0.090 | 0.100 | 0.06 |
| 1.01 | 1.10 | 0.104 | 0.116 | 2.00 |
| 1.01 | 1.09 | 0.090 | 0.098 | 2.00 |
| 1.01 | 1.09 | 0.119 | 0.131 | 0.15 |
| 1.03 | 1.07 | 0.171 | 0.187 | 2.00 |
| 1.02 | 1.04 | 0.135 | 0.142 | 2.00 |
| 1.02 | 1.02 | 0.153 | 0.159 | 2.00 |
| 1.02 | 0.99 | 0.146 | 0.148 | 2.00 |
| 1.02 | 0.98 | 0.152 | 0.152 | 2.00 |
| 1.01 | 0.97 | 0.121 | 0.119 | 2.00 |
| 1.08 | 0.91 | 0.883 | 0.871 | 2.00 |
| 1.02 | 0.95 | 0.143 | 0.139 | 2.00 |
| 1.02 | 0.95 | 0.141 | 0.136 | 2.00 |
| 1.02 | 0.93 | 0.166 | 0.158 | 2.00 |
| 1.02 | 0.94 | 0.129 | 0.122 | 2.00 |
| 1.01 | 0.93 | 0.126 | 0.119 | 2.00 |
| 1.03 | 0.90 | 0.173 | 0.160 | 2.00 |
| 1.02 | 0.90 | 0.161 | 0.148 | 2.00 |
| 1.02 | 0.91 | 0.129 | 0.119 | 2.00 |
| 1.02 | 0.90 | 0.141 | 0.129 | 2.00 |
| 1.02 | 0.89 | 0.132 | 0.120 | 2.00 |
| 1.02 | 0.89 | 0.132 | 0.119 | 2.00 |
| 1.01 | 0.89 | 0.125 | 0.113 | 2.00 |
| 1.02 | 0.88 | 0.130 | 0.116 | 2.00 |
| 1.02 | 0.87 | 0.141 | 0.125 | 2.00 |
| 1.02 | 0.87 | 0.134 | 0.119 | 2.00 |
| 1.02 | 0.86 | 0.151 | 0.133 | 2.00 |
| 1.01 | 0.88 | 0.121 | 0.107 | 2.00 |
| 1.02 | 0.85 | 0.154 | 0.134 | 2.00 |
| 1.03 | 0.83 | 0.183 | 0.155 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.044 | 0.67 | 7.87 |
| 2 | 1.8 | 0.034 | 0.70 | 7.20 |
| 4 | 2.0 | 0.034 | 0.81 | 6.50 |
| 6 | 2.0 | 0.034 | 0.80 | 5.69 |
| 8 | 4.3 | 0.050 | 2.55 | 4.89 |
| 14.5 | 5.8 | 0.000 | 0.00 | 2.33 |
| 19.5 | 5.0 | 0.000 | 0.00 | 2.33 |
| 24.5 | 5.3 | 0.037 | 2.33 | 2.33 |
| 30 | 5.5 | 0.000 | 0.00 | 0.00 |
| 35.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 41 | 6.5 | 0.000 | 0.00 | 0.00 |
| 48.5 | 6.3 | 0.000 | 0.00 | 0.00 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 62.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 66.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 71.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 76 | 4.8 | 0.000 | 0.00 | 0.00 |
| 81 | 6.3 | 0.000 | 0.00 | 0.00 |
| 88.5 | 6.3 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 99 | 5.5 | 0.000 | 0.00 | 0.00 |
| 104.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 110 | 6.8 | 0.000 | 0.00 | 0.00 |
| 118 | 5.0 | 0.000 | 0.00 | 0.00 |
| 120 | 3.3 | 0.000 | 0.00 | 0.00 |
| 124.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 129 | 4.8 | 0.000 | 0.00 | 0.00 |
| 134 | 4.8 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 144 | 5.5 | 0.000 | 0.00 | 0.00 |
| 149.5 | 5.8 | 0.000 | 0.00 | 0.00 |
| 155.5 | 5.8 | 0.000 | 0.00 | 0.00 |
| 161 | 4.3 | 0.000 | 0.00 | 0.00 |
| 164 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:58 PM |
| Boring Designation: | B-14 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | 0 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 83.1 |
| Distance from sample hammer to ground surface (ft): | 5 |
| Borehole Diameter (in) | 4 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.29 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 1 | SM | 14 | 100 | | |
| 2 | 2.0 | 2 | SM | 14 | 100 | | |
| 3 | 4.0 | 4 | SM | 14 | 100 | | |
| 4 | 6.0 | 25 | SM | 14 | 120 | | |
| 5 | 8.0 | 3 | SM | 14 | 100 | | |
| 6 | 13.5 | 16 | SM | 14 | 120 | | |
| 7 | 18.5 | 5 | SM | 14 | 100 | | |
| 8 | 23.5 | 9 | SM | 18 | 100 | | |
| 9 | 28.5 | 2 | SM | 44 | 100 | | |
| 10 | 33.5 | 4 | ML | 52 | 95 | | Clay |
| 11 | 38.5 | 2 | ML | 52 | 95 | | Clay |
| 12 | 43.5 | 2 | ML | 52 | 95 | | Clay |
| 13 | 48.5 | 4 | SM | 30 | 100 | | |
| 14 | 53.5 | 9 | ML | 50 | 120 | | Clay |
| 15 | 58.5 | 4 | ML | 50 | 120 | | Clay |
| 16 | 63.0 | 7 | ML | 50 | 120 | | Clay |
| 17 | 68.0 | 7 | ML | 50 | 120 | | Clay |
| 18 | 72.5 | 7 | ML | 50 | 120 | | Clay |
| 19 | 77.5 | 13 | SC | 15 | 120 | | Clay |
| 20 | 83.5 | 9 | SC | 15 | 120 | | Clay |
| 21 | 88.5 | 5 | SC | 15 | 120 | | Clay |
| 22 | 93.5 | 26 | SC | 15 | 120 | | Clay |
| 23 | 98.5 | 8 | ML | 50 | 120 | | Clay |
| 24 | 104.0 | 4 | ML | 50 | 120 | | Clay |
| 25 | 108.5 | 5 | ML | 50 | 120 | | Clay |
| 26 | 113.5 | 6 | ML | 50 | 120 | | Clay |
| 27 | 118.5 | 9 | ML | 50 | 120 | | Clay |
| 28 | 123.5 | 8 | SM | 15 | 120 | | Clay |
| 29 | 128.5 | 6 | SM | 15 | 120 | | Clay |
| 30 | 133.0 | 5 | SM | 15 | 120 | | Clay |
| 31 | 138.0 | 11 | SM | 15 | 120 | | Clay |
| 32 | 142.5 | 9 | SM | 15 | 120 | | Clay |
| 33 | 148.5 | 8 | SM | 15 | 120 | | Clay |
| 34 | 153.5 | 9 | SM | 15 | 120 | | Clay |
| 35 | 158.5 | 9 | SM | 15 | 120 | | Clay |
| 36 | 163.5 | 7 | SM | 15 | 120 | | Clay |
| 37 | 168.5 | 8 | SM | 15 | 120 | | Clay |
| 38 | 173.5 | 8 | SM | 15 | 120 | | Clay |
| 39 | 178.5 | 6 | SM | 15 | 120 | | Clay |
| 40 | 183.5 | 8 | SM | 15 | 120 | | Clay |
| 41 | 188.5 | 6 | SM | 15 | 120 | | Clay |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 1.0 | SM | 14.0 | 100.0 | | 50 | 19 | 1.39 | 1.00 | 0.75 | 1.00 | 1.04 | 1.70 | 1.77 | 2.91 | 4.67 | 1.005 | 0.504 |
| 2 | 2.0 | 2.0 | SM | 14.0 | 100.0 | | 200 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 2.08 | 1.70 | 3.53 | 2.91 | 6.44 | 1.002 | 0.502 |
| 3 | 4.0 | 4.0 | SM | 14.0 | 100.0 | | 400 | 150 | 1.39 | 1.00 | 0.75 | 1.00 | 4.16 | 1.70 | 7.06 | 2.91 | 9.97 | 0.997 | 0.500 |
| 4 | 6.0 | 25.0 | SM | 14.0 | 120.0 | | 640 | 266 | 1.39 | 1.00 | 0.80 | 1.00 | 27.70 | 1.70 | 47.09 | 2.91 | 50.00 | 0.991 | 0.450 |
| 5 | 8.0 | 3.0 | SM | 13.8 | 100.0 | | 840 | 341 | 1.39 | 1.00 | 0.80 | 1.00 | 3.32 | 1.70 | 5.65 | 2.83 | 8.48 | 0.985 | 0.458 |
| 6 | 13.5 | 16.0 | SM | 14.0 | 120.0 | | 1500 | 658 | 1.39 | 1.00 | 0.85 | 1.00 | 18.84 | 1.51 | 28.48 | 2.91 | 31.39 | 0.966 | 0.415 |
| 7 | 18.5 | 5.0 | SM | 14.0 | 100.0 | | 2000 | 846 | 1.39 | 1.00 | 0.95 | 1.00 | 6.58 | 1.59 | 10.44 | 2.91 | 13.35 | 0.947 | 0.422 |
| 8 | 23.5 | 9.0 | SM | 17.6 | 100.0 | | 2500 | 1034 | 1.39 | 1.00 | 0.95 | 1.00 | 11.84 | 1.37 | 16.22 | 4.00 | 20.21 | 0.926 | 0.422 |
| 9 | 28.5 | 2.0 | SM | 43.7 | 100.0 | | 3000 | 1222 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.35 | 3.75 | 5.60 | 9.35 | 0.903 | 0.418 |
| 10 | 33.5 | 4.0 | ML | 52.0 | 95.0 | Clay | 3475 | 1385 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.24 | 6.88 | 5.61 | 12.50 | 0.879 | 0.416 |
| 11 | 38.5 | 2.0 | ML | 52.0 | 95.0 | Clay | 3950 | 1548 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.19 | 3.29 | 5.61 | 8.91 | 0.855 | 0.411 |
| 12 | 43.5 | 2.0 | ML | 52.0 | 95.0 | Clay | 4425 | 1711 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.13 | 3.12 | 5.61 | 8.73 | 0.830 | 0.405 |
| 13 | 48.5 | 4.0 | SM | 30.1 | 100.0 | | 4925 | 1899 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.06 | 5.87 | 5.37 | 11.23 | 0.805 | 0.394 |
| 14 | 53.5 | 9.0 | ML | 50.0 | 120.0 | Clay | 5525 | 2187 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.99 | 12.28 | 5.61 | 17.89 | 0.781 | 0.372 |
| 15 | 58.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 6125 | 2475 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 0.92 | 5.10 | 5.61 | 10.71 | 0.757 | 0.353 |
| 16 | 63.0 | 7.0 | ML | 50.0 | 120.0 | Clay | 6665 | 2734 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.88 | 8.54 | 5.61 | 14.16 | 0.736 | 0.338 |
| 17 | 68.0 | 7.0 | ML | 50.0 | 120.0 | Clay | 7265 | 3022 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.84 | 8.11 | 5.61 | 13.73 | 0.714 | 0.324 |
| 18 | 72.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 7805 | 3281 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.80 | 7.78 | 5.61 | 13.39 | 0.695 | 0.312 |
| 19 | 77.5 | 13.0 | SC | 15.0 | 120.0 | Clay | 8405 | 3569 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.78 | 14.13 | 3.26 | 17.39 | 0.676 | 0.300 |
| 20 | 83.5 | 9.0 | SC | 15.0 | 120.0 | Clay | 9125 | 3915 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.73 | 9.09 | 3.26 | 12.35 | 0.654 | 0.288 |
| 21 | 88.5 | 5.0 | SC | 15.0 | 120.0 | Clay | 9725 | 4203 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.68 | 4.69 | 3.26 | 7.95 | 0.639 | 0.279 |
| 22 | 93.5 | 26.0 | SC | 15.0 | 120.0 | Clay | 10325 | 4491 | 1.39 | 1.00 | 1.00 | 1.00 | 36.01 | 0.76 | 27.51 | 3.26 | 30.77 | 0.625 | 0.271 |
| 23 | 98.5 | 8.0 | ML | 50.0 | 120.0 | Clay | 10925 | 4779 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.66 | 7.33 | 5.61 | 12.94 | 0.613 | 0.264 |
| 24 | 104.0 | 4.0 | ML | 50.0 | 120.0 | Clay | 11585 | 5095 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 0.61 | 3.41 | 5.61 | 9.02 | 0.602 | 0.258 |
| 25 | 108.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 12125 | 5355 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.60 | 4.18 | 5.61 | 9.80 | 0.596 | 0.254 |
| 26 | 113.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 12725 | 5643 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.59 | 4.92 | 5.61 | 10.53 | 0.590 | 0.251 |
| 27 | 118.5 | 9.0 | ML | 50.0 | 120.0 | Clay | 13325 | 5931 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.59 | 7.39 | 5.61 | 13.01 | 0.587 | 0.249 |
| 28 | 123.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 13925 | 6219 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.55 | 6.13 | 3.26 | 9.39 | 0.586 | 0.247 |
| 29 | 128.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 14525 | 6507 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.53 | 4.37 | 3.26 | 7.63 | 0.588 | 0.247 |
| 30 | 133.0 | 5.0 | SM | 15.0 | 120.0 | Clay | 15065 | 6766 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.51 | 3.51 | 3.26 | 6.77 | 0.591 | 0.248 |
| 31 | 138.0 | 11.0 | SM | 15.0 | 120.0 | Clay | 15665 | 7054 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.53 | 8.10 | 3.26 | 11.36 | 0.597 | 0.250 |
| 32 | 142.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 16205 | 7313 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.51 | 6.33 | 3.26 | 9.59 | 0.605 | 0.253 |
| 33 | 148.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 16925 | 7659 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.49 | 5.41 | 3.26 | 8.67 | 0.618 | 0.258 |
| 34 | 153.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 17525 | 7947 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.48 | 6.02 | 3.26 | 9.28 | 0.632 | 0.263 |
| 35 | 158.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 18125 | 8235 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.47 | 5.89 | 3.26 | 9.15 | 0.649 | 0.269 |
| 36 | 163.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 18725 | 8523 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.45 | 4.37 | 3.26 | 7.63 | 0.668 | 0.277 |
| 37 | 168.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 19325 | 8811 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.45 | 4.96 | 3.26 | 8.22 | 0.690 | 0.285 |
| 38 | 173.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 19925 | 9099 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.44 | 4.86 | 3.26 | 8.12 | 0.715 | 0.295 |
| 39 | 178.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 20525 | 9387 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.42 | 3.48 | 3.26 | 6.74 | 0.741 | 0.306 |
| 40 | 183.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 21125 | 9675 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.42 | 4.68 | 3.26 | 7.94 | 0.771 | 0.317 |
| 41 | 188.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 21725 | 9963 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.40 | 3.35 | 3.26 | 6.61 | 0.802 | 0.330 |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.11 | 1.01 | 1.10 | 0.084 | 0.093 | 0.19 |
| 1.13 | 1.01 | 1.10 | 0.095 | 0.105 | 0.21 |
| 1.19 | 1.01 | 1.10 | 0.118 | 0.131 | 0.26 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.16 | 1.01 | 1.10 | 0.108 | 0.120 | 0.26 |
| 2.08 | 1.07 | 1.10 | 0.587 | 0.693 | 1.67 |
| 1.27 | 1.02 | 1.10 | 0.143 | 0.159 | 0.38 |
| 1.50 | 1.03 | 1.10 | 0.208 | 0.236 | 0.56 |
| 1.18 | 1.01 | 1.05 | 0.114 | 0.121 | 0.29 |
| 1.25 | 1.02 | 1.04 | 0.136 | 0.144 | 2.00 |
| 1.17 | 1.01 | 1.03 | 0.111 | 0.115 | 2.00 |
| 1.17 | 1.01 | 1.02 | 0.109 | 0.113 | 2.00 |
| 1.22 | 1.01 | 1.01 | 0.127 | 0.130 | 0.33 |
| 1.41 | 1.03 | 1.00 | 0.183 | 0.187 | 2.00 |
| 1.21 | 1.01 | 0.99 | 0.123 | 0.123 | 2.00 |
| 1.29 | 1.02 | 0.97 | 0.149 | 0.148 | 2.00 |
| 1.28 | 1.02 | 0.96 | 0.146 | 0.143 | 2.00 |
| 1.27 | 1.02 | 0.95 | 0.143 | 0.139 | 2.00 |
| 1.39 | 1.03 | 0.94 | 0.178 | 0.171 | 2.00 |
| 1.24 | 1.02 | 0.94 | 0.135 | 0.129 | 2.00 |
| 1.15 | 1.01 | 0.94 | 0.104 | 0.099 | 2.00 |
| 2.04 | 1.07 | 0.84 | 0.537 | 0.484 | 2.00 |
| 1.26 | 1.02 | 0.92 | 0.140 | 0.130 | 2.00 |
| 1.17 | 1.01 | 0.92 | 0.111 | 0.104 | 2.00 |
| 1.19 | 1.01 | 0.91 | 0.117 | 0.108 | 2.00 |
| 1.20 | 1.01 | 0.91 | 0.122 | 0.112 | 2.00 |
| 1.26 | 1.02 | 0.89 | 0.140 | 0.127 | 2.00 |
| 1.18 | 1.01 | 0.90 | 0.114 | 0.104 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.102 | 0.093 | 2.00 |
| 1.14 | 1.01 | 0.91 | 0.097 | 0.088 | 2.00 |
| 1.22 | 1.01 | 0.88 | 0.128 | 0.114 | 2.00 |
| 1.18 | 1.01 | 0.89 | 0.115 | 0.104 | 2.00 |
| 1.17 | 1.01 | 0.89 | 0.109 | 0.098 | 2.00 |
| 1.18 | 1.01 | 0.88 | 0.113 | 0.101 | 2.00 |
| 1.17 | 1.01 | 0.88 | 0.112 | 0.100 | 2.00 |
| 1.15 | 1.01 | 0.88 | 0.102 | 0.091 | 2.00 |
| 1.16 | 1.01 | 0.88 | 0.106 | 0.094 | 2.00 |
| 1.16 | 1.01 | 0.87 | 0.105 | 0.093 | 2.00 |
| 1.14 | 1.01 | 0.88 | 0.097 | 0.086 | 2.00 |
| 1.15 | 1.01 | 0.87 | 0.104 | 0.092 | 2.00 |
| 1.13 | 1.01 | 0.87 | 0.096 | 0.085 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.054 | 0.81 | 12.29 |
| 2 | 1.8 | 0.047 | 0.99 | 11.48 |
| 4 | 2.0 | 0.037 | 0.90 | 10.49 |
| 6 | 2.0 | 0.000 | 0.00 | 9.59 |
| 8 | 3.8 | 0.041 | 1.84 | 9.59 |
| 13.5 | 5.3 | 0.001 | 0.09 | 7.75 |
| 18.5 | 5.0 | 0.031 | 1.87 | 7.66 |
| 23.5 | 5.0 | 0.023 | 1.37 | 5.79 |
| 28.5 | 5.0 | 0.039 | 2.33 | 4.42 |
| 33.5 | 5.0 | 0.000 | 0.00 | 2.09 |
| 38.5 | 5.0 | 0.000 | 0.00 | 2.09 |
| 43.5 | 5.0 | 0.000 | 0.00 | 2.09 |
| 48.5 | 5.0 | 0.035 | 2.09 | 2.09 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 63 | 4.8 | 0.000 | 0.00 | 0.00 |
| 68 | 4.8 | 0.000 | 0.00 | 0.00 |
| 72.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 77.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 104 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 133 | 4.8 | 0.000 | 0.00 | 0.00 |
| 138 | 4.8 | 0.000 | 0.00 | 0.00 |
| 142.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 148.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 153.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 158.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 163.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 168.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 173.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 178.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 183.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 188.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 191.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:58 PM |
| Boring Designation: | B-15 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | 0 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 83.1 |
| Distance from sample hammer to ground surface (ft): | 5 |
| Borehole Diameter (in) | 4 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.29 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 0 | SP-SM | 5 | 100 | | |
| 2 | 2.0 | 2 | SP-SM | 5 | 100 | | |
| 3 | 4.0 | 16 | SP-SM | 8 | 120 | | |
| 4 | 6.0 | 17 | SP-SM | 5 | 120 | | |
| 5 | 8.0 | 14 | SP-SM | 5 | 120 | | |
| 6 | 13.5 | 25 | SP-SM | 6 | 120 | | |
| 7 | 18.5 | 7 | SM | 18 | 100 | | |
| 8 | 23.5 | 7 | SM | 18 | 100 | | |
| 9 | 28.5 | 4 | SM | 18 | 100 | | |
| 10 | 33.5 | 4 | SM | 18 | 100 | | |
| 11 | 38.5 | 0 | CL | 50 | 95 | | Clay |
| 12 | 43.5 | 0 | SM | 21 | 100 | | |
| 13 | 48.5 | 9 | SM | 21 | 100 | | |
| 14 | 53.5 | 14 | SM | 21 | 100 | | |
| 15 | 58.5 | 2 | SM | 21 | 100 | | |
| 16 | 63.5 | 6 | SM | 21 | 100 | | |
| 17 | 68.5 | 8 | SM | 15 | 120 | | Clay |
| 18 | 73.5 | 10 | SM | 15 | 120 | | Clay |
| 19 | 78.5 | 23 | SM | 15 | 120 | | Clay |
| 20 | 83.5 | 9 | SM | 15 | 120 | | Clay |
| 21 | 88.5 | 27 | SM | 15 | 120 | | Clay |
| 22 | 93.5 | 17 | SM | 15 | 120 | | Clay |
| 23 | 98.5 | 8 | SM | 15 | 120 | | Clay |
| 24 | 103.5 | 16 | SM | 15 | 120 | | Clay |
| 25 | 108.5 | 10 | SM | 15 | 120 | | Clay |
| 26 | 113.5 | 5 | SM | 15 | 120 | | Clay |
| 27 | 118.5 | 6 | SM | 15 | 120 | | Clay |
| 28 | 123.5 | 5 | SM | 15 | 120 | | Clay |
| 29 | 128.5 | 7 | SM | 15 | 120 | | Clay |
| 30 | 133.5 | 8 | SM | 15 | 120 | | Clay |
| 31 | 138.5 | 8 | SM | 15 | 120 | | Clay |
| 32 | 143.5 | 9 | ML | 50 | 120 | | Clay |
| 33 | 148.5 | 12 | SM | 15 | 120 | | Clay |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 0.0 | SP-SM | 5.0 | 100.0 | | 50 | 19 | 1.39 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 0.00 | 0.00 | 1.005 | 0.504 |
| 2 | 2.0 | 2.0 | SP-SM | 5.0 | 100.0 | | 200 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 2.08 | 1.70 | 3.53 | 0.00 | 3.53 | 1.002 | 0.502 |
| 3 | 4.0 | 16.0 | SP-SM | 8.2 | 120.0 | | 440 | 190 | 1.39 | 1.00 | 0.75 | 1.00 | 16.62 | 1.70 | 28.25 | 0.43 | 28.68 | 0.997 | 0.434 |
| 4 | 6.0 | 17.0 | SP-SM | 5.1 | 120.0 | | 680 | 306 | 1.39 | 1.00 | 0.80 | 1.00 | 18.84 | 1.70 | 32.02 | 0.00 | 32.02 | 0.991 | 0.416 |
| 5 | 8.0 | 14.0 | SP-SM | 5.0 | 120.0 | | 920 | 421 | 1.39 | 1.00 | 0.80 | 1.00 | 15.51 | 1.70 | 26.37 | 0.00 | 26.37 | 0.985 | 0.406 |
| 6 | 13.5 | 25.0 | SP-SM | 5.5 | 120.0 | | 1580 | 738 | 1.39 | 1.00 | 0.85 | 1.00 | 29.43 | 1.37 | 40.24 | 0.01 | 40.25 | 0.966 | 0.390 |
| 7 | 18.5 | 7.0 | SM | 17.5 | 100.0 | | 2080 | 926 | 1.39 | 1.00 | 0.95 | 1.00 | 9.21 | 1.47 | 13.51 | 3.97 | 17.48 | 0.947 | 0.401 |
| 8 | 23.5 | 7.0 | SM | 18.0 | 100.0 | | 2580 | 1114 | 1.39 | 1.00 | 0.95 | 1.00 | 9.21 | 1.35 | 12.47 | 4.09 | 16.56 | 0.926 | 0.404 |
| 9 | 28.5 | 4.0 | SM | 18.0 | 100.0 | | 3080 | 1302 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.29 | 7.16 | 4.09 | 11.25 | 0.903 | 0.403 |
| 10 | 33.5 | 4.0 | SM | 18.0 | 100.0 | | 3580 | 1490 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.21 | 6.68 | 4.09 | 10.77 | 0.879 | 0.398 |
| 11 | 38.5 | 0.0 | CL | 50.0 | 95.0 | Clay | 4055 | 1653 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.16 | 0.00 | 5.61 | 5.61 | 0.855 | 0.395 |
| 12 | 43.5 | 0.0 | SM | 20.7 | 100.0 | | 4555 | 1841 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.09 | 0.00 | 4.59 | 4.59 | 0.830 | 0.387 |
| 13 | 48.5 | 9.0 | SM | 21.0 | 100.0 | | 5055 | 2029 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 1.02 | 12.71 | 4.63 | 17.34 | 0.805 | 0.378 |
| 14 | 53.5 | 14.0 | SM | 21.0 | 100.0 | | 5555 | 2217 | 1.39 | 1.00 | 1.00 | 1.00 | 19.39 | 0.98 | 19.02 | 4.63 | 23.66 | 0.781 | 0.369 |
| 15 | 58.5 | 2.0 | SM | 21.0 | 100.0 | | 6055 | 2405 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 0.93 | 2.57 | 4.63 | 7.21 | 0.757 | 0.359 |
| 16 | 63.5 | 6.0 | SM | 21.0 | 100.0 | | 6555 | 2593 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.90 | 7.48 | 4.63 | 12.12 | 0.734 | 0.350 |
| 17 | 68.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 7155 | 2881 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.85 | 9.47 | 3.26 | 12.73 | 0.712 | 0.333 |
| 18 | 73.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 7755 | 3169 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.82 | 11.36 | 3.26 | 14.62 | 0.691 | 0.319 |
| 19 | 78.5 | 23.0 | SM | 15.0 | 120.0 | Clay | 8355 | 3457 | 1.39 | 1.00 | 1.00 | 1.00 | 31.86 | 0.84 | 26.64 | 3.26 | 29.91 | 0.672 | 0.306 |
| 20 | 83.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 8955 | 3745 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.75 | 9.31 | 3.26 | 12.57 | 0.654 | 0.295 |
| 21 | 88.5 | 27.0 | SM | 15.0 | 120.0 | Clay | 9555 | 4033 | 1.39 | 1.00 | 1.00 | 1.00 | 37.40 | 0.80 | 30.01 | 3.26 | 33.27 | 0.639 | 0.285 |
| 22 | 93.5 | 17.0 | SM | 15.0 | 120.0 | Clay | 10155 | 4321 | 1.39 | 1.00 | 1.00 | 1.00 | 23.55 | 0.73 | 17.24 | 3.26 | 20.51 | 0.625 | 0.277 |
| 23 | 98.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 10755 | 4609 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.66 | 7.31 | 3.26 | 10.57 | 0.613 | 0.270 |
| 24 | 103.5 | 16.0 | SM | 15.0 | 120.0 | Clay | 11355 | 4897 | 1.39 | 1.00 | 1.00 | 1.00 | 22.16 | 0.68 | 15.13 | 3.26 | 18.39 | 0.603 | 0.264 |
| 25 | 108.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 11955 | 5185 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.63 | 8.70 | 3.26 | 11.97 | 0.596 | 0.259 |
| 26 | 113.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 12555 | 5473 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.58 | 4.00 | 3.26 | 7.26 | 0.590 | 0.255 |
| 27 | 118.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 13155 | 5761 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.57 | 4.71 | 3.26 | 7.97 | 0.587 | 0.253 |
| 28 | 123.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 13755 | 6049 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.54 | 3.76 | 3.26 | 7.03 | 0.586 | 0.251 |
| 29 | 128.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 14355 | 6337 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.54 | 5.25 | 3.26 | 8.51 | 0.588 | 0.251 |
| 30 | 133.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 14955 | 6625 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.53 | 5.90 | 3.26 | 9.17 | 0.592 | 0.252 |
| 31 | 138.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 15555 | 6913 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.52 | 5.75 | 3.26 | 9.02 | 0.598 | 0.254 |
| 32 | 143.5 | 9.0 | ML | 50.0 | 120.0 | Clay | 16155 | 7201 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.53 | 6.63 | 5.61 | 12.25 | 0.607 | 0.257 |
| 33 | 148.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 16755 | 7489 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.52 | 8.62 | 3.26 | 11.88 | 0.618 | 0.261 |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.09 | 1.01 | 1.10 | 0.061 | 0.067 | 0.13 |
| 1.10 | 1.01 | 1.10 | 0.078 | 0.086 | 0.17 |
| 1.92 | 1.06 | 1.10 | 0.414 | 0.483 | 1.11 |
| 2.12 | 1.08 | 1.10 | 0.647 | 0.766 | 1.84 |
| 1.79 | 1.05 | 1.10 | 0.327 | 0.379 | 0.93 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.40 | 1.03 | 1.10 | 0.179 | 0.202 | 0.50 |
| 1.37 | 1.02 | 1.08 | 0.170 | 0.187 | 0.46 |
| 1.22 | 1.01 | 1.05 | 0.127 | 0.135 | 0.33 |
| 1.21 | 1.01 | 1.03 | 0.123 | 0.129 | 0.32 |
| 1.12 | 1.01 | 1.02 | 0.090 | 0.092 | 2.00 |
| 1.11 | 1.01 | 1.01 | 0.084 | 0.085 | 0.22 |
| 1.39 | 1.03 | 1.01 | 0.177 | 0.183 | 0.48 |
| 1.65 | 1.04 | 0.99 | 0.261 | 0.271 | 0.74 |
| 1.14 | 1.01 | 0.99 | 0.099 | 0.099 | 0.28 |
| 1.24 | 1.02 | 0.98 | 0.133 | 0.133 | 0.38 |
| 1.25 | 1.02 | 0.97 | 0.138 | 0.136 | 2.00 |
| 1.31 | 1.02 | 0.96 | 0.153 | 0.149 | 2.00 |
| 1.99 | 1.07 | 0.90 | 0.479 | 0.461 | 2.00 |
| 1.25 | 1.02 | 0.94 | 0.137 | 0.131 | 2.00 |
| 2.20 | 1.08 | 0.85 | 0.796 | 0.729 | 2.00 |
| 1.51 | 1.03 | 0.90 | 0.212 | 0.198 | 2.00 |
| 1.20 | 1.01 | 0.93 | 0.122 | 0.115 | 2.00 |
| 1.43 | 1.03 | 0.89 | 0.188 | 0.173 | 2.00 |
| 1.23 | 1.02 | 0.91 | 0.132 | 0.122 | 2.00 |
| 1.14 | 1.01 | 0.92 | 0.100 | 0.093 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.104 | 0.096 | 2.00 |
| 1.14 | 1.01 | 0.91 | 0.098 | 0.091 | 2.00 |
| 1.16 | 1.01 | 0.90 | 0.108 | 0.099 | 2.00 |
| 1.17 | 1.01 | 0.90 | 0.112 | 0.102 | 2.00 |
| 1.17 | 1.01 | 0.89 | 0.111 | 0.101 | 2.00 |
| 1.24 | 1.02 | 0.88 | 0.134 | 0.120 | 2.00 |
| 1.23 | 1.02 | 0.87 | 0.132 | 0.117 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.118 | 1.77 | 21.53 |
| 2 | 1.8 | 0.060 | 1.26 | 19.76 |
| 4 | 2.0 | 0.006 | 0.14 | 18.50 |
| 6 | 2.0 | 0.001 | 0.01 | 18.36 |
| 8 | 3.8 | 0.009 | 0.41 | 18.35 |
| 13.5 | 5.3 | 0.000 | 0.00 | 17.94 |
| 18.5 | 5.0 | 0.026 | 1.54 | 17.94 |
| 23.5 | 5.0 | 0.027 | 1.60 | 16.40 |
| 28.5 | 5.0 | 0.035 | 2.09 | 14.79 |
| 33.5 | 5.0 | 0.036 | 2.15 | 12.70 |
| 38.5 | 5.0 | 0.000 | 0.00 | 10.56 |
| 43.5 | 5.0 | 0.054 | 3.27 | 10.56 |
| 48.5 | 5.0 | 0.026 | 1.55 | 7.29 |
| 53.5 | 5.0 | 0.018 | 1.08 | 5.74 |
| 58.5 | 5.0 | 0.045 | 2.67 | 4.67 |
| 63.5 | 5.0 | 0.033 | 1.99 | 1.99 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 133.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 143.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 148.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 151.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:57 PM |
| Boring Designation: | B-16 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | 0 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 83.1 |
| Distance from sample hammer to ground surface (ft): | 5 |
| Borehole Diameter (in) | 4 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.29 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 0 | SM | 15 | 100 | | |
| 2 | 2.0 | 5 | SM | 15 | 100 | | |
| 3 | 4.0 | 28 | SP | 2 | 120 | | |
| 4 | 6.0 | 22 | SP | 2 | 120 | | |
| 5 | 8.0 | 15 | SP | 2 | 120 | | |
| 6 | 13.5 | 29 | SP | 2 | 120 | | |
| 7 | 18.5 | 8 | SM | 14 | 100 | | |
| 8 | 23.5 | 5 | SM | 14 | 100 | | |
| 9 | 28.5 | 10 | SM | 14 | 100 | | |
| 10 | 33.5 | 4 | SM | 14 | 100 | | |
| 11 | 38.5 | 2 | SC | 47 | 100 | | |
| 12 | 43.5 | 3 | SM | 15 | 100 | | |
| 13 | 48.5 | 1 | MH | 91 | 100 | | Clay |
| 14 | 53.5 | 2 | MH | 91 | 100 | | Clay |
| 15 | 58.5 | 5 | SM | 15 | 100 | | |
| 16 | 63.5 | 8 | SM | 15 | 100 | | |
| 17 | 68.5 | 3 | CL | 50 | 95 | | Clay |
| 18 | 73.5 | 6 | SM | 15 | 120 | | Clay |
| 19 | 78.5 | 27 | SM | 15 | 120 | | Clay |
| 20 | 83.5 | 11 | SM | 15 | 120 | | Clay |
| 21 | 88.5 | 5 | SM | 15 | 120 | | Clay |
| 22 | 93.5 | 28 | SM | 15 | 120 | | Clay |
| 23 | 98.5 | 15 | SM | 15 | 120 | | Clay |
| 24 | 103.5 | 10 | SM | 15 | 120 | | Clay |
| 25 | 108.5 | 6 | SM | 15 | 120 | | Clay |
| 26 | 113.5 | 9 | SM | 15 | 120 | | Clay |
| 27 | 118.5 | 8 | SM | 15 | 120 | | Clay |
| 28 | 123.5 | 9 | SM | 15 | 120 | | Clay |
| 29 | 128.5 | 7 | SM | 15 | 120 | | Clay |
| 30 | 133.5 | 6 | SM | 15 | 120 | | Clay |
| 31 | 138.5 | 7 | SM | 15 | 120 | | Clay |
| 32 | 143.5 | 12 | SM | 15 | 120 | | Clay |
| 33 | 148.5 | 11 | SM | 15 | 120 | | Clay |
| 34 | | | | | | | Clay |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 0.0 | SM | 15.0 | 100.0 | | 50 | 19 | 1.39 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 3.26 | 3.26 | 1.005 | 0.504 |
| 2 | 2.0 | 5.0 | SM | 15.0 | 100.0 | | 200 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 5.19 | 1.70 | 8.83 | 3.26 | 12.09 | 1.002 | 0.502 |
| 3 | 4.0 | 28.0 | SP | 2.0 | 120.0 | | 440 | 190 | 1.39 | 1.00 | 0.75 | 1.00 | 29.09 | 1.70 | 49.44 | 0.00 | 49.44 | 0.997 | 0.434 |
| 4 | 6.0 | 22.0 | SP | 2.1 | 120.0 | | 680 | 306 | 1.39 | 1.00 | 0.80 | 1.00 | 24.38 | 1.70 | 41.44 | 0.00 | 41.44 | 0.991 | 0.416 |
| 5 | 8.0 | 15.0 | SP | 2.0 | 120.0 | | 920 | 421 | 1.39 | 1.00 | 0.80 | 1.00 | 16.62 | 1.70 | 28.25 | 0.00 | 28.25 | 0.985 | 0.406 |
| 6 | 13.5 | 29.0 | SP | 2.1 | 120.0 | | 1580 | 738 | 1.39 | 1.00 | 0.85 | 1.00 | 34.14 | 1.33 | 45.25 | 0.00 | 45.25 | 0.966 | 0.390 |
| 7 | 18.5 | 8.0 | SM | 14.0 | 100.0 | | 2080 | 926 | 1.39 | 1.00 | 0.95 | 1.00 | 10.53 | 1.46 | 15.35 | 2.91 | 18.25 | 0.947 | 0.401 |
| 8 | 23.5 | 5.0 | SM | 13.9 | 100.0 | | 2580 | 1114 | 1.39 | 1.00 | 0.95 | 1.00 | 6.58 | 1.39 | 9.17 | 2.87 | 12.04 | 0.926 | 0.404 |
| 9 | 28.5 | 10.0 | SM | 14.0 | 100.0 | | 3080 | 1302 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 1.24 | 17.15 | 2.91 | 20.06 | 0.903 | 0.403 |
| 10 | 33.5 | 4.0 | SM | 14.0 | 100.0 | | 3580 | 1490 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.21 | 6.71 | 2.91 | 9.62 | 0.879 | 0.398 |
| 11 | 38.5 | 2.0 | SC | 46.6 | 100.0 | | 4080 | 1678 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.14 | 3.15 | 5.61 | 8.76 | 0.855 | 0.392 |
| 12 | 43.5 | 3.0 | SM | 15.0 | 100.0 | | 4580 | 1866 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.07 | 4.46 | 3.26 | 7.73 | 0.830 | 0.384 |
| 13 | 48.5 | 1.0 | MH | 91.0 | 100.0 | Clay | 5080 | 2054 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.02 | 1.41 | 5.51 | 6.92 | 0.805 | 0.375 |
| 14 | 53.5 | 2.0 | MH | 91.0 | 100.0 | Clay | 5580 | 2242 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 0.97 | 2.68 | 5.51 | 8.19 | 0.781 | 0.366 |
| 15 | 58.5 | 5.0 | SM | 15.0 | 100.0 | | 6080 | 2430 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.93 | 6.42 | 3.26 | 9.68 | 0.757 | 0.357 |
| 16 | 63.5 | 8.0 | SM | 15.0 | 100.0 | | 6580 | 2618 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.90 | 9.95 | 3.26 | 13.21 | 0.734 | 0.348 |
| 17 | 68.5 | 3.0 | CL | 50.0 | 95.0 | Clay | 7055 | 2781 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 0.86 | 3.57 | 5.61 | 9.19 | 0.712 | 0.340 |
| 18 | 73.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 7655 | 3069 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.82 | 6.80 | 3.26 | 10.06 | 0.691 | 0.325 |
| 19 | 78.5 | 27.0 | SM | 15.0 | 120.0 | Clay | 8255 | 3357 | 1.39 | 1.00 | 1.00 | 1.00 | 37.40 | 0.86 | 32.16 | 3.26 | 35.42 | 0.672 | 0.312 |
| 20 | 83.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 8855 | 3645 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.77 | 11.69 | 3.26 | 14.95 | 0.654 | 0.300 |
| 21 | 88.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 9455 | 3933 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.70 | 4.88 | 3.26 | 8.14 | 0.639 | 0.289 |
| 22 | 93.5 | 28.0 | SM | 15.0 | 120.0 | Clay | 10055 | 4221 | 1.39 | 1.00 | 1.00 | 1.00 | 38.78 | 0.79 | 30.75 | 3.26 | 34.01 | 0.625 | 0.281 |
| 23 | 98.5 | 15.0 | SM | 15.0 | 120.0 | Clay | 10655 | 4509 | 1.39 | 1.00 | 1.00 | 1.00 | 20.78 | 0.71 | 14.68 | 3.26 | 17.95 | 0.613 | 0.273 |
| 24 | 103.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 11255 | 4797 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.66 | 9.09 | 3.26 | 12.36 | 0.603 | 0.267 |
| 25 | 108.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 11855 | 5085 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.61 | 5.08 | 3.26 | 8.34 | 0.596 | 0.262 |
| 26 | 113.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 12455 | 5373 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.61 | 7.60 | 3.26 | 10.86 | 0.590 | 0.258 |
| 27 | 118.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 13055 | 5661 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.59 | 6.49 | 3.26 | 9.75 | 0.587 | 0.255 |
| 28 | 123.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 13655 | 5949 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.57 | 7.16 | 3.26 | 10.42 | 0.586 | 0.254 |
| 29 | 128.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 14255 | 6237 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.55 | 5.30 | 3.26 | 8.56 | 0.588 | 0.253 |
| 30 | 133.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 14855 | 6525 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.53 | 4.36 | 3.26 | 7.63 | 0.592 | 0.254 |
| 31 | 138.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 15455 | 6813 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.52 | 5.02 | 3.26 | 8.28 | 0.598 | 0.256 |
| 32 | 143.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 16055 | 7101 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.54 | 8.90 | 3.26 | 12.16 | 0.607 | 0.259 |
| 33 | 148.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 16655 | 7389 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.52 | 7.88 | 3.26 | 11.14 | 0.618 | 0.263 |
| 34 | | | | | | Clay | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.10 | 1.01 | 1.10 | 0.077 | 0.085 | 0.17 |
| 1.24 | 1.02 | 1.10 | 0.133 | 0.149 | 0.30 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.89 | 1.06 | 1.10 | 0.394 | 0.460 | 1.13 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.43 | 1.03 | 1.10 | 0.186 | 0.211 | 0.53 |
| 1.24 | 1.02 | 1.06 | 0.133 | 0.143 | 0.35 |
| 1.50 | 1.03 | 1.06 | 0.207 | 0.227 | 0.56 |
| 1.18 | 1.01 | 1.03 | 0.115 | 0.121 | 0.30 |
| 1.17 | 1.01 | 1.02 | 0.110 | 0.113 | 0.29 |
| 1.15 | 1.01 | 1.01 | 0.103 | 0.105 | 0.27 |
| 1.14 | 1.01 | 1.00 | 0.098 | 0.099 | 2.00 |
| 1.16 | 1.01 | 1.00 | 0.106 | 0.106 | 2.00 |
| 1.18 | 1.01 | 0.99 | 0.116 | 0.116 | 0.32 |
| 1.27 | 1.02 | 0.98 | 0.142 | 0.141 | 0.41 |
| 1.18 | 1.01 | 0.98 | 0.112 | 0.111 | 2.00 |
| 1.19 | 1.01 | 0.97 | 0.118 | 0.116 | 2.00 |
| 2.20 | 1.08 | 0.88 | 1.212 | 1.148 | 2.00 |
| 1.32 | 1.02 | 0.94 | 0.156 | 0.149 | 2.00 |
| 1.16 | 1.01 | 0.95 | 0.106 | 0.101 | 2.00 |
| 2.20 | 1.08 | 0.83 | 0.911 | 0.816 | 2.00 |
| 1.41 | 1.03 | 0.91 | 0.183 | 0.171 | 2.00 |
| 1.24 | 1.02 | 0.92 | 0.135 | 0.126 | 2.00 |
| 1.16 | 1.01 | 0.92 | 0.107 | 0.100 | 2.00 |
| 1.21 | 1.01 | 0.91 | 0.124 | 0.115 | 2.00 |
| 1.19 | 1.01 | 0.91 | 0.116 | 0.107 | 2.00 |
| 1.20 | 1.01 | 0.90 | 0.121 | 0.111 | 2.00 |
| 1.16 | 1.01 | 0.91 | 0.108 | 0.099 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.102 | 0.093 | 2.00 |
| 1.16 | 1.01 | 0.90 | 0.106 | 0.097 | 2.00 |
| 1.24 | 1.02 | 0.88 | 0.134 | 0.119 | 2.00 |
| 1.22 | 1.01 | 0.88 | 0.126 | 0.113 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.062 | 0.92 | 18.20 |
| 2 | 1.8 | 0.033 | 0.70 | 17.28 |
| 4 | 2.0 | 0.000 | 0.00 | 16.58 |
| 6 | 2.0 | 0.000 | 0.00 | 16.58 |
| 8 | 3.8 | 0.006 | 0.25 | 16.58 |
| 13.5 | 5.3 | 0.000 | 0.00 | 16.33 |
| 18.5 | 5.0 | 0.025 | 1.49 | 16.33 |
| 23.5 | 5.0 | 0.033 | 2.00 | 14.84 |
| 28.5 | 5.0 | 0.023 | 1.38 | 12.84 |
| 33.5 | 5.0 | 0.038 | 2.29 | 11.46 |
| 38.5 | 5.0 | 0.040 | 2.42 | 9.16 |
| 43.5 | 5.0 | 0.043 | 2.58 | 6.75 |
| 48.5 | 5.0 | 0.000 | 0.00 | 4.17 |
| 53.5 | 5.0 | 0.000 | 0.00 | 4.17 |
| 58.5 | 5.0 | 0.038 | 2.28 | 4.17 |
| 63.5 | 5.0 | 0.031 | 1.88 | 1.88 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 133.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 143.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 148.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 151.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:46 PM |
| Boring Designation: | B-1 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | 8 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 82 |
| Distance from sample hammer to ground surface (ft): | 5 |
| Borehole Diameter (in) | 6 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.14 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 8 | SP-SM | 8 | 100 | | Unsaturated |
| 2 | 4.0 | 7 | SP-SM | 8 | 100 | | Unsaturated |
| 3 | 6.0 | 6 | SP-SM | 8 | 100 | | Unsaturated |
| 4 | 8.0 | 6 | SP-SM | 8 | 100 | | |
| 5 | 10.0 | 3 | SP-SM | 8 | 100 | | |
| 6 | 12.0 | 4 | SP-SM | 8 | 100 | | |
| 7 | 14.0 | 8 | SP-SM | 8 | 100 | | |
| 8 | 16.0 | 2 | SP-SM | 8 | 100 | | |
| 9 | 18.0 | 2 | SP | 3 | 100 | | |
| 10 | 23.5 | 2 | SP | 3 | 100 | | |
| 11 | 28.5 | 4 | SP-SM | 7 | 100 | | |
| 12 | 33.5 | 4 | SP-SM | 7 | 100 | | |
| 13 | 38.5 | 3 | SP-SM | 7 | 100 | | |
| 14 | 43.5 | 1 | SP-SM | 11 | 100 | | |
| 15 | 48.5 | 1 | SM | 33 | 100 | | |
| 16 | 53.5 | 14 | ML | 50 | 120 | | Clay |
| 17 | 55.0 | 34 | ML | 50 | 120 | | Clay |
| 18 | 58.5 | 7 | ML | 50 | 120 | | Clay |
| 19 | 63.5 | 6 | ML | 50 | 120 | | Clay |
| 20 | 65.0 | 7 | ML | 50 | 120 | | Clay |
| 21 | 66.5 | 10 | ML | 50 | 120 | | Clay |
| 22 | 68.5 | 12 | ML | 50 | 120 | | Clay |
| 23 | 73.5 | 11 | ML | 50 | 120 | | Clay |
| 24 | 78.5 | 23 | ML | 50 | 120 | | Clay |
| 25 | 83.5 | 3 | SM | 15 | 120 | | Clay |
| 26 | 88.5 | 10 | SM | 15 | 120 | | Clay |
| 27 | 93.5 | 11 | SM | 15 | 120 | | Clay |
| 28 | 100.0 | 25 | SM | 15 | 120 | | Clay |
| 29 | 103.5 | 10 | SM | 15 | 120 | | Clay |
| 30 | 108.5 | 9 | SM | 15 | 120 | | Clay |
| 31 | 113.5 | 12 | SM | 15 | 120 | | Clay |
| 32 | 118.5 | 12 | SM | 15 | 120 | | Clay |
| 33 | 123.5 | 16 | SM | 15 | 120 | | Clay |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 8.0 | SP-SM | 8.0 | 100.0 | Unsaturated | 200 | 200 | 1.37 | 1.15 | 0.75 | 1.00 | 9.43 | 1.70 | 16.03 | 0.37 | 16.40 | 1.002 | 0.091 |
| 2 | 4.0 | 7.0 | SP-SM | 8.0 | 100.0 | Unsaturated | 400 | 400 | 1.37 | 1.15 | 0.75 | 1.00 | 8.25 | 1.70 | 14.03 | 0.37 | 14.39 | 0.997 | 0.091 |
| 3 | 6.0 | 6.0 | SP-SM | 8.0 | 100.0 | Unsaturated | 600 | 600 | 1.37 | 1.15 | 0.80 | 1.00 | 7.54 | 1.70 | 12.82 | 0.37 | 13.19 | 0.991 | 0.090 |
| 4 | 8.0 | 6.0 | SP-SM | 8.0 | 100.0 | | 800 | 800 | 1.37 | 1.15 | 0.80 | 1.00 | 7.54 | 1.64 | 12.39 | 0.37 | 12.75 | 0.985 | 0.090 |
| 5 | 10.0 | 3.0 | SP-SM | 8.0 | 100.0 | | 1000 | 875 | 1.37 | 1.15 | 0.85 | 1.00 | 4.01 | 1.67 | 6.69 | 0.37 | 7.06 | 0.978 | 0.102 |
| 6 | 12.0 | 4.0 | SP-SM | 8.0 | 100.0 | | 1200 | 950 | 1.37 | 1.15 | 0.85 | 1.00 | 5.34 | 1.56 | 8.35 | 0.37 | 8.72 | 0.971 | 0.112 |
| 7 | 14.0 | 8.0 | SP-SM | 8.0 | 100.0 | | 1400 | 1026 | 1.37 | 1.15 | 0.85 | 1.00 | 10.69 | 1.42 | 15.15 | 0.37 | 15.51 | 0.964 | 0.120 |
| 8 | 16.0 | 2.0 | SP-SM | 8.0 | 100.0 | | 1600 | 1101 | 1.37 | 1.15 | 0.95 | 1.00 | 2.99 | 1.49 | 4.46 | 0.37 | 4.83 | 0.957 | 0.127 |
| 9 | 18.0 | 2.0 | SP | 3.3 | 100.0 | | 1800 | 1176 | 1.37 | 1.15 | 0.95 | 1.00 | 2.99 | 1.44 | 4.31 | 0.00 | 4.31 | 0.949 | 0.132 |
| 10 | 23.5 | 2.0 | SP | 3.3 | 100.0 | | 2350 | 1383 | 1.37 | 1.15 | 0.95 | 1.00 | 2.99 | 1.31 | 3.91 | 0.00 | 3.91 | 0.926 | 0.143 |
| 11 | 28.5 | 4.0 | SP-SM | 7.4 | 100.0 | | 2850 | 1571 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 1.19 | 7.45 | 0.21 | 7.67 | 0.903 | 0.149 |
| 12 | 33.5 | 4.0 | SP-SM | 7.0 | 100.0 | | 3350 | 1759 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 1.11 | 7.00 | 0.14 | 7.13 | 0.879 | 0.152 |
| 13 | 38.5 | 3.0 | SP-SM | 7.0 | 100.0 | | 3850 | 1947 | 1.37 | 1.15 | 1.00 | 1.00 | 4.72 | 1.05 | 4.96 | 0.14 | 5.10 | 0.855 | 0.154 |
| 14 | 43.5 | 1.0 | SP-SM | 11.0 | 100.0 | | 4350 | 2135 | 1.37 | 1.15 | 1.00 | 1.00 | 1.57 | 0.99 | 1.56 | 1.61 | 3.17 | 0.830 | 0.154 |
| 15 | 48.5 | 1.0 | SM | 33.2 | 100.0 | | 4850 | 2323 | 1.37 | 1.15 | 1.00 | 1.00 | 1.57 | 0.95 | 1.49 | 5.47 | 6.95 | 0.805 | 0.153 |
| 16 | 53.5 | 14.0 | ML | 50.0 | 120.0 | Clay | 5450 | 2611 | 1.37 | 1.15 | 1.00 | 1.00 | 22.00 | 0.92 | 20.26 | 5.61 | 25.87 | 0.781 | 0.148 |
| 17 | 55.0 | 34.0 | ML | 50.0 | 120.0 | Clay | 5630 | 2697 | 1.37 | 1.15 | 1.00 | 1.00 | 53.44 | 0.94 | 50.13 | 5.61 | 55.75 | 0.773 | 0.147 |
| 18 | 58.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 6050 | 2899 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.86 | 9.44 | 5.61 | 15.06 | 0.757 | 0.144 |
| 19 | 63.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 6650 | 3187 | 1.37 | 1.15 | 1.00 | 1.00 | 9.43 | 0.81 | 7.67 | 5.61 | 13.29 | 0.734 | 0.139 |
| 20 | 65.0 | 7.0 | ML | 50.0 | 120.0 | Clay | 6830 | 3273 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.81 | 8.88 | 5.61 | 14.49 | 0.727 | 0.138 |
| 21 | 66.5 | 10.0 | ML | 50.0 | 120.0 | Clay | 7010 | 3360 | 1.37 | 1.15 | 1.00 | 1.00 | 15.72 | 0.81 | 12.74 | 5.61 | 18.35 | 0.720 | 0.137 |
| 22 | 68.5 | 12.0 | ML | 50.0 | 120.0 | Clay | 7250 | 3475 | 1.37 | 1.15 | 1.00 | 1.00 | 18.86 | 0.81 | 15.21 | 5.61 | 20.83 | 0.712 | 0.135 |
| 23 | 73.5 | 11.0 | ML | 50.0 | 120.0 | Clay | 7850 | 3763 | 1.37 | 1.15 | 1.00 | 1.00 | 17.29 | 0.77 | 13.35 | 5.61 | 18.96 | 0.691 | 0.131 |
| 24 | 78.5 | 23.0 | ML | 50.0 | 120.0 | Clay | 8450 | 4051 | 1.37 | 1.15 | 1.00 | 1.00 | 36.15 | 0.81 | 29.15 | 5.61 | 34.77 | 0.672 | 0.128 |
| 25 | 83.5 | 3.0 | SM | 15.0 | 120.0 | Clay | 9050 | 4339 | 1.37 | 1.15 | 1.00 | 1.00 | 4.72 | 0.65 | 3.09 | 3.26 | 6.35 | 0.654 | 0.124 |
| 26 | 88.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 9650 | 4627 | 1.37 | 1.15 | 1.00 | 1.00 | 15.72 | 0.68 | 10.65 | 3.26 | 13.91 | 0.639 | 0.121 |
| 27 | 93.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 10250 | 4915 | 1.37 | 1.15 | 1.00 | 1.00 | 17.29 | 0.66 | 11.44 | 3.26 | 14.71 | 0.625 | 0.119 |
| 28 | 100.0 | 25.0 | SM | 15.0 | 120.0 | Clay | 11030 | 5289 | 1.37 | 1.15 | 1.00 | 1.00 | 39.29 | 0.72 | 28.48 | 3.26 | 31.74 | 0.610 | 0.116 |
| 29 | 103.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 11450 | 5491 | 1.37 | 1.15 | 1.00 | 1.00 | 15.72 | 0.62 | 9.69 | 3.26 | 12.95 | 0.603 | 0.114 |
| 30 | 108.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 12050 | 5779 | 1.37 | 1.15 | 1.00 | 1.00 | 14.15 | 0.59 | 8.37 | 3.26 | 11.63 | 0.596 | 0.113 |
| 31 | 113.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 12650 | 6067 | 1.37 | 1.15 | 1.00 | 1.00 | 18.86 | 0.60 | 11.24 | 3.26 | 14.50 | 0.590 | 0.112 |
| 32 | 118.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 13250 | 6355 | 1.37 | 1.15 | 1.00 | 1.00 | 18.86 | 0.58 | 10.95 | 3.26 | 14.21 | 0.587 | 0.111 |
| 33 | 123.5 | 16.0 | SM | 15.0 | 120.0 | Clay | 13850 | 6643 | 1.37 | 1.15 | 1.00 | 1.00 | 25.15 | 0.59 | 14.92 | 3.26 | 18.18 | 0.586 | 0.111 |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.36 | 1.02 | 1.10 | 0.168 | 0.190 | 2.00 |
| 1.30 | 1.02 | 1.10 | 0.151 | 0.170 | 2.00 |
| 1.27 | 1.02 | 1.10 | 0.142 | 0.158 | 2.00 |
| 1.25 | 1.02 | 1.10 | 0.138 | 0.154 | 1.72 |
| 1.14 | 1.01 | 1.07 | 0.099 | 0.107 | 1.05 |
| 1.17 | 1.01 | 1.07 | 0.109 | 0.118 | 1.06 |
| 1.33 | 1.02 | 1.08 | 0.161 | 0.178 | 1.48 |
| 1.11 | 1.01 | 1.05 | 0.085 | 0.090 | 0.71 |
| 1.11 | 1.01 | 1.04 | 0.082 | 0.086 | 0.65 |
| 1.11 | 1.01 | 1.03 | 0.080 | 0.083 | 0.58 |
| 1.15 | 1.01 | 1.03 | 0.102 | 0.106 | 0.71 |
| 1.14 | 1.01 | 1.02 | 0.099 | 0.102 | 0.67 |
| 1.12 | 1.01 | 1.01 | 0.087 | 0.088 | 0.57 |
| 1.10 | 1.01 | 1.00 | 0.076 | 0.077 | 0.50 |
| 1.14 | 1.01 | 0.99 | 0.098 | 0.098 | 0.64 |
| 1.76 | 1.05 | 0.96 | 0.312 | 0.317 | 2.00 |
| 2.20 | 1.08 | 0.93 | 2.000 | 2.000 | 2.00 |
| 1.32 | 1.02 | 0.97 | 0.157 | 0.154 | 2.00 |
| 1.27 | 1.02 | 0.96 | 0.142 | 0.139 | 2.00 |
| 1.30 | 1.02 | 0.95 | 0.152 | 0.148 | 2.00 |
| 1.43 | 1.03 | 0.94 | 0.187 | 0.182 | 2.00 |
| 1.53 | 1.04 | 0.93 | 0.216 | 0.209 | 2.00 |
| 1.45 | 1.03 | 0.93 | 0.194 | 0.185 | 2.00 |
| 2.20 | 1.08 | 0.83 | 1.057 | 0.951 | 2.00 |
| 1.13 | 1.01 | 0.94 | 0.094 | 0.090 | 2.00 |
| 1.29 | 1.02 | 0.92 | 0.147 | 0.138 | 2.00 |
| 1.31 | 1.02 | 0.91 | 0.154 | 0.142 | 2.00 |
| 2.11 | 1.08 | 0.80 | 0.619 | 0.531 | 2.00 |
| 1.26 | 1.02 | 0.90 | 0.140 | 0.128 | 2.00 |
| 1.23 | 1.02 | 0.90 | 0.130 | 0.119 | 2.00 |
| 1.30 | 1.02 | 0.89 | 0.152 | 0.137 | 2.00 |
| 1.29 | 1.02 | 0.88 | 0.150 | 0.135 | 2.00 |
| 1.42 | 1.03 | 0.86 | 0.186 | 0.164 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 0.0 | 0.000 | 0.00 | 22.80 |
| 4 | 0.0 | 0.000 | 0.00 | 22.80 |
| 6 | 0.0 | 0.000 | 0.00 | 22.80 |
| 8 | 1.0 | 0.001 | 0.01 | 22.80 |
| 10 | 2.0 | 0.010 | 0.23 | 22.79 |
| 12 | 2.0 | 0.009 | 0.21 | 22.56 |
| 14 | 2.0 | 0.002 | 0.05 | 22.35 |
| 16 | 2.0 | 0.053 | 1.28 | 22.30 |
| 18 | 3.8 | 0.056 | 2.51 | 21.02 |
| 23.5 | 5.3 | 0.058 | 3.65 | 18.51 |
| 28.5 | 5.0 | 0.043 | 2.59 | 14.86 |
| 33.5 | 5.0 | 0.045 | 2.69 | 12.27 |
| 38.5 | 5.0 | 0.052 | 3.13 | 9.58 |
| 43.5 | 5.0 | 0.062 | 3.73 | 6.45 |
| 48.5 | 5.0 | 0.045 | 2.72 | 2.72 |
| 53.5 | 3.3 | 0.000 | 0.00 | 0.00 |
| 55 | 2.5 | 0.000 | 0.00 | 0.00 |
| 58.5 | 4.3 | 0.000 | 0.00 | 0.00 |
| 63.5 | 3.3 | 0.000 | 0.00 | 0.00 |
| 65 | 1.5 | 0.000 | 0.00 | 0.00 |
| 66.5 | 1.8 | 0.000 | 0.00 | 0.00 |
| 68.5 | 3.5 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.8 | 0.000 | 0.00 | 0.00 |
| 100 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 4.3 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 126.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:40 PM |
| Boring Designation: | B-2 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | 6 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 82 |
| Distance from sample hammer to ground surface (ft): | 5 |
| Borehole Diameter (in) | 6 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.12 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 20 | SP | 5 | 100 | | Unsaturated |
| 2 | 4.0 | 6 | SP | 5 | 100 | | Unsaturated |
| 3 | 6.0 | 1 | SP | 5 | 100 | | |
| 4 | 8.0 | 11 | SP | 3 | 100 | | |
| 5 | 10.0 | 18 | SP | 3 | 120 | | |
| 6 | 12.0 | 30 | SP | 3 | 120 | | |
| 7 | 14.0 | 38 | SP | 3 | 120 | | |
| 8 | 16.0 | 21 | SP | 3 | 120 | | |
| 9 | 18.0 | 7 | SP-SM | 6 | 100 | | |
| 10 | 23.5 | 0 | SP-SM | 6 | 100 | | |
| 11 | 28.5 | 1 | SM | 14 | 100 | | |
| 12 | 33.5 | 4 | SM | 14 | 100 | | |
| 13 | 38.5 | 4 | SP-SM | 9 | 100 | | |
| 14 | 43.5 | 19 | SP-SM | 9 | 120 | | |
| 15 | 48.5 | 7 | SP-SM | 9 | 100 | | |
| 16 | 53.5 | 11 | SP-SM | 10 | 100 | | |
| 17 | 58.5 | 2 | SP-SM | 10 | 100 | | |
| 18 | 63.5 | 1 | CL | 50 | 100 | | Clay |
| 19 | 68.5 | 7 | SP-SM | 5 | 100 | | |
| 20 | 73.5 | 5 | ML | 50 | 120 | | Clay |
| 21 | 78.5 | 5 | ML | 50 | 120 | | Clay |
| 22 | 83.5 | 4 | ML | 50 | 120 | | Clay |
| 23 | 88.5 | 32 | SM | 15 | 120 | | Clay |
| 24 | 93.5 | 5 | SM | 15 | 120 | | Clay |
| 25 | 98.5 | 6 | SM | 15 | 120 | | Clay |
| 26 | 103.5 | 4 | SM | 15 | 120 | | Clay |
| 27 | 108.5 | 7 | SM | 15 | 120 | | Clay |
| 28 | 113.5 | 10 | SM | 15 | 120 | | Clay |
| 29 | 118.5 | 7 | SM | 15 | 120 | | Clay |
| 30 | 123.5 | 7 | SM | 15 | 120 | | Clay |
| 31 | | | | | | | Clay |
| 32 | | | | | | | Clay |
| 33 | | | | | | | Clay |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 20.0 | SP | 5.0 | 100.0 | Unsaturated | 200 | 200 | 1.37 | 1.15 | 0.75 | 1.00 | 23.58 | 1.70 | 40.08 | 0.00 | 40.08 | 1.002 | 0.078 |
| 2 | 4.0 | 6.0 | SP | 5.0 | 100.0 | Unsaturated | 400 | 400 | 1.37 | 1.15 | 0.75 | 1.00 | 7.07 | 1.70 | 12.02 | 0.00 | 12.03 | 0.997 | 0.078 |
| 3 | 6.0 | 1.0 | SP | 4.9 | 100.0 | | 600 | 600 | 1.37 | 1.15 | 0.80 | 1.00 | 1.26 | 1.70 | 2.14 | 0.00 | 2.14 | 0.991 | 0.077 |
| 4 | 8.0 | 11.0 | SP | 2.5 | 100.0 | | 800 | 675 | 1.37 | 1.15 | 0.80 | 1.00 | 13.83 | 1.62 | 22.37 | 0.00 | 22.37 | 0.985 | 0.091 |
| 5 | 10.0 | 18.0 | SP | 3.0 | 120.0 | | 1040 | 790 | 1.37 | 1.15 | 0.85 | 1.00 | 24.05 | 1.40 | 33.58 | 0.00 | 33.58 | 0.978 | 0.100 |
| 6 | 12.0 | 30.0 | SP | 3.0 | 120.0 | | 1280 | 906 | 1.37 | 1.15 | 0.85 | 1.00 | 40.08 | 1.25 | 50.10 | 0.00 | 50.10 | 0.971 | 0.107 |
| 7 | 14.0 | 38.0 | SP | 3.0 | 120.0 | | 1520 | 1021 | 1.37 | 1.15 | 0.85 | 1.00 | 50.76 | 1.21 | 61.50 | 0.00 | 61.50 | 0.964 | 0.112 |
| 8 | 16.0 | 21.0 | SP | 3.0 | 120.0 | | 1760 | 1136 | 1.37 | 1.15 | 0.95 | 1.00 | 31.35 | 1.21 | 38.03 | 0.00 | 38.03 | 0.957 | 0.116 |
| 9 | 18.0 | 7.0 | SP-SM | 6.3 | 100.0 | | 1960 | 1211 | 1.37 | 1.15 | 0.95 | 1.00 | 10.45 | 1.32 | 13.80 | 0.05 | 13.85 | 0.949 | 0.120 |
| 10 | 23.5 | 0.0 | SP-SM | 6.0 | 100.0 | | 2510 | 1418 | 1.37 | 1.15 | 0.95 | 1.00 | 0.00 | 1.36 | 0.00 | 0.03 | 0.03 | 0.926 | 0.128 |
| 11 | 28.5 | 1.0 | SM | 14.0 | 100.0 | | 3010 | 1606 | 1.37 | 1.15 | 1.00 | 1.00 | 1.57 | 1.19 | 1.86 | 2.91 | 4.77 | 0.903 | 0.132 |
| 12 | 33.5 | 4.0 | SM | 14.0 | 100.0 | | 3510 | 1794 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 1.09 | 6.88 | 2.91 | 9.78 | 0.879 | 0.134 |
| 13 | 38.5 | 4.0 | SP-SM | 8.8 | 100.0 | | 4010 | 1982 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 1.04 | 6.53 | 0.64 | 7.17 | 0.855 | 0.135 |
| 14 | 43.5 | 19.0 | SP-SM | 9.0 | 120.0 | | 4610 | 2270 | 1.37 | 1.15 | 1.00 | 1.00 | 29.86 | 0.97 | 29.11 | 0.72 | 29.83 | 0.830 | 0.131 |
| 15 | 48.5 | 7.0 | SP-SM | 9.0 | 100.0 | | 5110 | 2458 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.92 | 10.16 | 0.72 | 10.88 | 0.805 | 0.131 |
| 16 | 53.5 | 11.0 | SP-SM | 10.0 | 100.0 | | 5610 | 2646 | 1.37 | 1.15 | 1.00 | 1.00 | 17.29 | 0.90 | 15.56 | 1.15 | 16.71 | 0.781 | 0.129 |
| 17 | 58.5 | 2.0 | SP-SM | 10.0 | 100.0 | | 6110 | 2834 | 1.37 | 1.15 | 1.00 | 1.00 | 3.14 | 0.83 | 2.61 | 1.15 | 3.76 | 0.757 | 0.127 |
| 18 | 63.5 | 1.0 | CL | 50.0 | 100.0 | Clay | 6610 | 3022 | 1.37 | 1.15 | 1.00 | 1.00 | 1.57 | 0.81 | 1.28 | 5.61 | 6.89 | 0.734 | 0.125 |
| 19 | 68.5 | 7.0 | SP-SM | 5.0 | 100.0 | | 7110 | 3210 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.79 | 8.72 | 0.00 | 8.72 | 0.712 | 0.123 |
| 20 | 73.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 7710 | 3498 | 1.37 | 1.15 | 1.00 | 1.00 | 7.86 | 0.77 | 6.05 | 5.61 | 11.66 | 0.691 | 0.119 |
| 21 | 78.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 8310 | 3786 | 1.37 | 1.15 | 1.00 | 1.00 | 7.86 | 0.74 | 5.79 | 5.61 | 11.41 | 0.672 | 0.115 |
| 22 | 83.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 8910 | 4074 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 0.70 | 4.41 | 5.61 | 10.03 | 0.654 | 0.112 |
| 23 | 88.5 | 32.0 | SM | 15.0 | 120.0 | Clay | 9510 | 4362 | 1.37 | 1.15 | 1.00 | 1.00 | 50.29 | 0.82 | 41.34 | 3.26 | 44.60 | 0.639 | 0.109 |
| 24 | 93.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 10110 | 4650 | 1.37 | 1.15 | 1.00 | 1.00 | 7.86 | 0.64 | 5.05 | 3.26 | 8.31 | 0.625 | 0.106 |
| 25 | 98.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 10710 | 4938 | 1.37 | 1.15 | 1.00 | 1.00 | 9.43 | 0.63 | 5.91 | 3.26 | 9.17 | 0.613 | 0.104 |
| 26 | 103.5 | 4.0 | SM | 15.0 | 120.0 | Clay | 11310 | 5226 | 1.37 | 1.15 | 1.00 | 1.00 | 6.29 | 0.59 | 3.72 | 3.26 | 6.98 | 0.603 | 0.102 |
| 27 | 108.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 11910 | 5514 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.59 | 6.54 | 3.26 | 9.80 | 0.596 | 0.100 |
| 28 | 113.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 12510 | 5802 | 1.37 | 1.15 | 1.00 | 1.00 | 15.72 | 0.60 | 9.39 | 3.26 | 12.65 | 0.590 | 0.099 |
| 29 | 118.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 13110 | 6090 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.56 | 6.16 | 3.26 | 9.42 | 0.587 | 0.099 |
| 30 | 123.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 13710 | 6378 | 1.37 | 1.15 | 1.00 | 1.00 | 11.00 | 0.54 | 5.99 | 3.26 | 9.26 | 0.586 | 0.098 |
| 31 | | | | | | | | | | | | | | | | | | | |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.24 | 1.02 | 1.10 | 0.133 | 0.148 | 2.00 |
| 1.09 | 1.01 | 1.08 | 0.071 | 0.077 | 1.00 |
| 1.59 | 1.04 | 1.10 | 0.239 | 0.273 | 2.00 |
| 2.20 | 1.08 | 1.10 | 0.840 | 1.000 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.28 | 1.02 | 1.06 | 0.147 | 0.158 | 1.32 |
| 1.09 | 1.01 | 1.02 | 0.061 | 0.063 | 0.49 |
| 1.11 | 1.01 | 1.02 | 0.085 | 0.087 | 0.66 |
| 1.19 | 1.01 | 1.02 | 0.117 | 0.120 | 0.89 |
| 1.14 | 1.01 | 1.01 | 0.099 | 0.101 | 0.75 |
| 1.99 | 1.07 | 0.99 | 0.474 | 0.499 | 2.00 |
| 1.21 | 1.01 | 0.99 | 0.124 | 0.124 | 0.95 |
| 1.37 | 1.03 | 0.97 | 0.171 | 0.171 | 1.32 |
| 1.10 | 1.01 | 0.98 | 0.079 | 0.078 | 0.61 |
| 1.14 | 1.01 | 0.97 | 0.098 | 0.096 | 2.00 |
| 1.17 | 1.01 | 0.96 | 0.109 | 0.107 | 0.87 |
| 1.23 | 1.02 | 0.95 | 0.130 | 0.125 | 2.00 |
| 1.22 | 1.02 | 0.94 | 0.128 | 0.123 | 2.00 |
| 1.19 | 1.01 | 0.94 | 0.118 | 0.113 | 2.00 |
| 2.20 | 1.08 | 0.79 | 2.000 | 1.701 | 2.00 |
| 1.16 | 1.01 | 0.93 | 0.107 | 0.100 | 2.00 |
| 1.17 | 1.01 | 0.92 | 0.112 | 0.105 | 2.00 |
| 1.14 | 1.01 | 0.93 | 0.098 | 0.092 | 2.00 |
| 1.19 | 1.01 | 0.91 | 0.117 | 0.108 | 2.00 |
| 1.25 | 1.02 | 0.90 | 0.137 | 0.125 | 2.00 |
| 1.18 | 1.01 | 0.90 | 0.114 | 0.104 | 2.00 |
| 1.18 | 1.01 | 0.90 | 0.113 | 0.103 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 0.0 | 0.000 | 0.00 | 23.78 |
| 4 | 0.0 | 0.000 | 0.00 | 23.78 |
| 6 | 1.0 | 0.032 | 0.39 | 23.78 |
| 8 | 2.0 | 0.000 | 0.00 | 23.40 |
| 10 | 2.0 | 0.000 | 0.00 | 23.40 |
| 12 | 2.0 | 0.000 | 0.00 | 23.40 |
| 14 | 2.0 | 0.000 | 0.00 | 23.40 |
| 16 | 2.0 | 0.000 | 0.00 | 23.40 |
| 18 | 3.8 | 0.003 | 0.16 | 23.40 |
| 23.5 | 5.3 | 0.113 | 7.11 | 23.24 |
| 28.5 | 5.0 | 0.054 | 3.22 | 16.14 |
| 33.5 | 5.0 | 0.038 | 2.27 | 12.92 |
| 38.5 | 5.0 | 0.045 | 2.68 | 10.65 |
| 43.5 | 5.0 | 0.000 | 0.00 | 7.97 |
| 48.5 | 5.0 | 0.030 | 1.79 | 7.97 |
| 53.5 | 5.0 | 0.004 | 0.23 | 6.18 |
| 58.5 | 5.0 | 0.059 | 3.52 | 5.94 |
| 63.5 | 5.0 | 0.000 | 0.00 | 2.42 |
| 68.5 | 5.0 | 0.040 | 2.42 | 2.42 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 126.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 5:47 PM |
| **Boring Designation:** | B-3 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 1 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 80 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.14 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 0 | SM | 38 | 100 | | |
| 2 | 4.0 | 0 | SM | 38 | 100 | | |
| 3 | 6.0 | 0 | MH | 99 | 95 | | Clay |
| 4 | 8.0 | 0 | MH | 99 | 95 | | Clay |
| 5 | 13.5 | 16 | SP-SM | 8 | 100 | | |
| 6 | 18.5 | 1 | SP-SM | 8 | 100 | | |
| 7 | 23.5 | 1 | SM | 25 | 100 | | |
| 8 | 28.5 | 0 | MH | 97 | 95 | | Clay |
| 9 | 33.5 | 0 | SP-SM | 10 | 100 | | |
| 10 | 38.5 | 3 | SP-SM | 10 | 100 | | |
| 11 | 43.5 | 4 | SP-SM | 10 | 100 | | |
| 12 | 48.5 | 7 | ML | 50 | 120 | | Clay |
| 13 | 53.5 | 4 | ML | 50 | 120 | | Clay |
| 14 | 58.5 | 7 | ML | 50 | 120 | | Clay |
| 15 | 63.5 | 5 | ML | 50 | 120 | | Clay |
| 16 | 68.5 | 10 | ML | 50 | 120 | | Clay |
| 17 | 73.5 | 8 | ML | 50 | 120 | | Clay |
| 18 | 78.5 | 6 | SM | 15 | 120 | | Clay |
| 19 | | | | | | | |
| 20 | | | | | | | |
| 21 | | | | | | | |
| 22 | | | | | | | |
| 23 | | | | | | | |
| 24 | | | | | | | |
| 25 | | | | | | | |
| 26 | | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | |
| 29 | | | | | | | |
| 30 | | | | | | | |
| 31 | | | | | | | |
| 32 | | | | | | | |
| 33 | | | | | | | |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 0.0 | SM | 37.5 | 100.0 | | 200 | 106 | 1.33 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.55 | 5.55 | 1.002 | 0.171 |
| 2 | 4.0 | 0.0 | SM | 38.0 | 100.0 | | 400 | 182 | 1.33 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.55 | 5.55 | 0.997 | 0.200 |
| 3 | 6.0 | 0.0 | MH | 98.8 | 95.0 | Clay | 590 | 247 | 1.33 | 1.00 | 0.80 | 1.00 | 0.00 | 1.70 | 0.00 | 5.49 | 5.49 | 0.991 | 0.216 |
| 4 | 8.0 | 0.0 | MH | 98.8 | 95.0 | Clay | 780 | 312 | 1.33 | 1.00 | 0.80 | 1.00 | 0.00 | 1.70 | 0.00 | 5.49 | 5.49 | 0.985 | 0.224 |
| 5 | 13.5 | 16.0 | SP-SM | 7.7 | 100.0 | | 1330 | 519 | 1.33 | 1.00 | 0.85 | 1.00 | 18.13 | 1.66 | 30.11 | 0.28 | 30.39 | 0.966 | 0.225 |
| 6 | 18.5 | 1.0 | SP-SM | 7.7 | 100.0 | | 1830 | 707 | 1.33 | 1.00 | 0.95 | 1.00 | 1.27 | 1.70 | 2.15 | 0.28 | 2.44 | 0.947 | 0.223 |
| 7 | 23.5 | 1.0 | SM | 24.5 | 100.0 | | 2330 | 895 | 1.33 | 1.00 | 0.95 | 1.00 | 1.27 | 1.65 | 2.09 | 5.03 | 7.12 | 0.926 | 0.219 |
| 8 | 28.5 | 0.0 | MH | 96.6 | 95.0 | Clay | 2805 | 1058 | 1.33 | 1.00 | 1.00 | 1.00 | 0.00 | 1.52 | 0.00 | 5.50 | 5.50 | 0.903 | 0.218 |
| 9 | 33.5 | 0.0 | SP-SM | 10.4 | 100.0 | | 3305 | 1246 | 1.33 | 1.00 | 1.00 | 1.00 | 0.00 | 1.45 | 0.00 | 1.33 | 1.33 | 0.879 | 0.212 |
| 10 | 38.5 | 3.0 | SP-SM | 10.4 | 100.0 | | 3805 | 1434 | 1.33 | 1.00 | 1.00 | 1.00 | 4.00 | 1.26 | 5.03 | 1.33 | 6.37 | 0.855 | 0.206 |
| 11 | 43.5 | 4.0 | SP-SM | 10.4 | 100.0 | | 4305 | 1622 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 1.16 | 6.21 | 1.33 | 7.54 | 0.830 | 0.200 |
| 12 | 48.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 4905 | 1910 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 1.05 | 9.81 | 5.61 | 15.42 | 0.805 | 0.188 |
| 13 | 53.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 5505 | 2198 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 0.98 | 5.23 | 5.61 | 10.84 | 0.781 | 0.178 |
| 14 | 58.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 6105 | 2486 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 0.92 | 8.62 | 5.61 | 14.23 | 0.757 | 0.169 |
| 15 | 63.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 6705 | 2774 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.87 | 5.78 | 5.61 | 11.40 | 0.734 | 0.161 |
| 16 | 68.5 | 10.0 | ML | 50.0 | 120.0 | Clay | 7305 | 3062 | 1.33 | 1.00 | 1.00 | 1.00 | 13.33 | 0.84 | 11.21 | 5.61 | 16.83 | 0.712 | 0.155 |
| 17 | 73.5 | 8.0 | ML | 50.0 | 120.0 | Clay | 7905 | 3350 | 1.33 | 1.00 | 1.00 | 1.00 | 10.67 | 0.80 | 8.50 | 5.61 | 14.11 | 0.691 | 0.148 |
| 18 | 78.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 8505 | 3638 | 1.33 | 1.00 | 1.00 | 1.00 | 8.00 | 0.74 | 5.93 | 3.26 | 9.20 | 0.672 | 0.143 |
| 19 | | | | | | | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | | | | | | | |
| 31 | | | | | | | | | | | | | | | | | | | |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.099 | 0.58 |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.099 | 0.50 |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.099 | 2.00 |
| 2.02 | 1.07 | 1.10 | 0.510 | 0.600 | 2.00 |
| 1.10 | 1.01 | 1.07 | 0.072 | 0.078 | 0.35 |
| 1.14 | 1.01 | 1.07 | 0.099 | 0.107 | 0.49 |
| 1.12 | 1.01 | 1.05 | 0.089 | 0.095 | 2.00 |
| 1.09 | 1.01 | 1.03 | 0.067 | 0.069 | 0.33 |
| 1.13 | 1.01 | 1.03 | 0.094 | 0.098 | 0.48 |
| 1.15 | 1.01 | 1.02 | 0.102 | 0.105 | 0.52 |
| 1.33 | 1.02 | 1.01 | 0.160 | 0.165 | 2.00 |
| 1.21 | 1.01 | 1.00 | 0.124 | 0.125 | 2.00 |
| 1.29 | 1.02 | 0.98 | 0.150 | 0.150 | 2.00 |
| 1.22 | 1.02 | 0.97 | 0.128 | 0.127 | 2.00 |
| 1.38 | 1.03 | 0.96 | 0.172 | 0.169 | 2.00 |
| 1.29 | 1.02 | 0.95 | 0.149 | 0.144 | 2.00 |
| 1.18 | 1.01 | 0.95 | 0.113 | 0.108 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 2.5 | 0.050 | 1.51 | 19.61 |
| 4 | 2.0 | 0.050 | 1.21 | 18.10 |
| 6 | 2.0 | 0.000 | 0.00 | 16.89 |
| 8 | 3.8 | 0.000 | 0.00 | 16.89 |
| 13.5 | 5.3 | 0.000 | 0.00 | 16.89 |
| 18.5 | 5.0 | 0.067 | 4.05 | 16.89 |
| 23.5 | 5.0 | 0.045 | 2.69 | 12.84 |
| 28.5 | 5.0 | 0.000 | 0.00 | 10.15 |
| 33.5 | 5.0 | 0.078 | 4.70 | 10.15 |
| 38.5 | 5.0 | 0.047 | 2.84 | 5.45 |
| 43.5 | 5.0 | 0.044 | 2.61 | 2.61 |
| 48.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 81.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 5:47 PM |
| **Boring Designation:** | B-4 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 2 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 80 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.14 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 1 | SM | 32 | 100 | | |
| 2 | 4.0 | 0 | SM | 32 | 100 | | |
| 3 | 6.0 | 0 | CL | 50 | 95 | | Clay |
| 4 | 8.0 | 1 | SM | 26 | 100 | | |
| 5 | 13.5 | 2 | SM | 15 | 100 | | |
| 6 | 18.5 | 5 | SM | 15 | 100 | | |
| 7 | 23.5 | 3 | SM | 15 | 100 | | |
| 8 | 28.5 | 3 | SM | 22 | 100 | | |
| 9 | 33.5 | 2 | SM | 22 | 100 | | |
| 10 | 38.5 | 0 | SM | 22 | 100 | | |
| 11 | 43.5 | 4 | SM | 17 | 100 | | |
| 12 | 48.5 | 2 | SM | 17 | 100 | | |
| 13 | 53.5 | 4 | ML | 50 | 120 | | Clay |
| 14 | 58.5 | 7 | MH | 53 | 120 | | Clay |
| 15 | 63.5 | 7 | MH | 53 | 120 | | Clay |
| 16 | 68.5 | 6 | MH | 53 | 120 | | Clay |
| 17 | 73.5 | 100 | SM | 15 | 120 | | Clay |
| 18 | 78.5 | 9 | SM | 15 | 120 | | Clay |
| 19 | | | | | | | |
| 20 | | | | | | | |
| 21 | | | | | | | |
| 22 | | | | | | | |
| 23 | | | | | | | |
| 24 | | | | | | | |
| 25 | | | | | | | |
| 26 | | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | |
| 29 | | | | | | | |
| 30 | | | | | | | |
| 31 | | | | | | | |
| 32 | | | | | | | |
| 33 | | | | | | | |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 1.0 | SM | 31.9 | 100.0 | | 200 | 200 | 1.33 | 1.00 | 0.75 | 1.00 | 1.00 | 1.70 | 1.70 | 5.43 | 7.13 | 1.002 | 0.091 |
| 2 | 4.0 | 0.0 | SM | 31.9 | 100.0 | | 400 | 275 | 1.33 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.43 | 5.43 | 0.997 | 0.132 |
| 3 | 6.0 | 0.0 | CL | 50.0 | 95.0 | Clay | 590 | 340 | 1.33 | 1.00 | 0.80 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 0.991 | 0.156 |
| 4 | 8.0 | 1.0 | SM | 26.0 | 100.0 | | 790 | 416 | 1.33 | 1.00 | 0.80 | 1.00 | 1.07 | 1.70 | 1.81 | 5.15 | 6.96 | 0.985 | 0.170 |
| 5 | 13.5 | 2.0 | SM | 15.1 | 100.0 | | 1340 | 622 | 1.33 | 1.00 | 0.85 | 1.00 | 2.27 | 1.70 | 3.85 | 3.29 | 7.15 | 0.966 | 0.189 |
| 6 | 18.5 | 5.0 | SM | 15.0 | 100.0 | | 1840 | 810 | 1.33 | 1.00 | 0.95 | 1.00 | 6.33 | 1.62 | 10.25 | 3.26 | 13.51 | 0.947 | 0.196 |
| 7 | 23.5 | 3.0 | SM | 15.0 | 100.0 | | 2340 | 998 | 1.33 | 1.00 | 0.95 | 1.00 | 3.80 | 1.52 | 5.76 | 3.26 | 9.02 | 0.926 | 0.197 |
| 8 | 28.5 | 3.0 | SM | 22.0 | 100.0 | | 2840 | 1186 | 1.33 | 1.00 | 1.00 | 1.00 | 4.00 | 1.37 | 5.46 | 4.77 | 10.23 | 0.903 | 0.197 |
| 9 | 33.5 | 2.0 | SM | 21.6 | 100.0 | | 3340 | 1374 | 1.33 | 1.00 | 1.00 | 1.00 | 2.67 | 1.28 | 3.40 | 4.72 | 8.12 | 0.879 | 0.194 |
| 10 | 38.5 | 0.0 | SM | 22.0 | 100.0 | | 3840 | 1562 | 1.33 | 1.00 | 1.00 | 1.00 | 0.00 | 1.21 | 0.00 | 4.77 | 4.77 | 0.855 | 0.191 |
| 11 | 43.5 | 4.0 | SM | 17.0 | 100.0 | | 4340 | 1750 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 1.11 | 5.91 | 3.85 | 9.76 | 0.830 | 0.187 |
| 12 | 48.5 | 2.0 | SM | 17.0 | 100.0 | | 4840 | 1938 | 1.33 | 1.00 | 1.00 | 1.00 | 2.67 | 1.05 | 2.81 | 3.85 | 6.66 | 0.805 | 0.183 |
| 13 | 53.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 5440 | 2226 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 0.97 | 5.19 | 5.61 | 10.81 | 0.781 | 0.174 |
| 14 | 58.5 | 7.0 | MH | 53.1 | 120.0 | Clay | 6040 | 2514 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 0.92 | 8.57 | 5.61 | 14.18 | 0.757 | 0.165 |
| 15 | 63.5 | 7.0 | MH | 53.1 | 120.0 | Clay | 6640 | 2802 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 0.87 | 8.11 | 5.61 | 13.73 | 0.734 | 0.158 |
| 16 | 68.5 | 6.0 | MH | 53.1 | 120.0 | Clay | 7240 | 3090 | 1.33 | 1.00 | 1.00 | 1.00 | 8.00 | 0.82 | 6.58 | 5.61 | 12.19 | 0.712 | 0.152 |
| 17 | 73.5 | 100.0 | SM | 15.0 | 120.0 | Clay | 7840 | 3378 | 1.33 | 1.00 | 1.00 | 1.00 | 133.33 | 0.88 | 117.89 | 3.26 | 121.15 | 0.691 | 0.146 |
| 18 | 78.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 8440 | 3666 | 1.33 | 1.00 | 1.00 | 1.00 | 12.00 | 0.75 | 9.04 | 3.26 | 12.30 | 0.672 | 0.141 |
| 19 | | | | | | | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | | | | | | | |
| 31 | | | | | | | | | | | | | | | | | | | |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.14 | 1.01 | 1.10 | 0.099 | 0.110 | 1.21 |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.098 | 0.75 |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.100 | 2.00 |
| 1.14 | 1.01 | 1.10 | 0.098 | 0.109 | 0.64 |
| 1.14 | 1.01 | 1.10 | 0.099 | 0.110 | 0.58 |
| 1.27 | 1.02 | 1.10 | 0.144 | 0.161 | 0.82 |
| 1.17 | 1.01 | 1.07 | 0.111 | 0.120 | 0.61 |
| 1.20 | 1.01 | 1.05 | 0.120 | 0.128 | 0.65 |
| 1.16 | 1.01 | 1.04 | 0.105 | 0.110 | 0.57 |
| 1.11 | 1.01 | 1.02 | 0.085 | 0.087 | 0.46 |
| 1.19 | 1.01 | 1.02 | 0.116 | 0.120 | 0.64 |
| 1.13 | 1.01 | 1.01 | 0.096 | 0.098 | 0.53 |
| 1.21 | 1.01 | 1.00 | 0.124 | 0.125 | 2.00 |
| 1.29 | 1.02 | 0.98 | 0.149 | 0.150 | 2.00 |
| 1.28 | 1.02 | 0.97 | 0.146 | 0.144 | 2.00 |
| 1.24 | 1.02 | 0.96 | 0.134 | 0.131 | 2.00 |
| 2.20 | 1.08 | 0.86 | 2.000 | 1.864 | 2.00 |
| 1.24 | 1.02 | 0.94 | 0.135 | 0.129 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 1.0 | 0.003 | 0.04 | 23.34 |
| 4 | 2.0 | 0.051 | 1.22 | 23.31 |
| 6 | 2.0 | 0.000 | 0.00 | 22.09 |
| 8 | 3.8 | 0.045 | 2.04 | 22.09 |
| 13.5 | 5.3 | 0.045 | 2.82 | 20.05 |
| 18.5 | 5.0 | 0.031 | 1.85 | 17.23 |
| 23.5 | 5.0 | 0.040 | 2.38 | 15.37 |
| 28.5 | 5.0 | 0.037 | 2.21 | 13.00 |
| 33.5 | 5.0 | 0.042 | 2.52 | 10.78 |
| 38.5 | 5.0 | 0.054 | 3.22 | 8.27 |
| 43.5 | 5.0 | 0.038 | 2.27 | 5.05 |
| 48.5 | 5.0 | 0.046 | 2.78 | 2.78 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 81.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 5:41 PM |
| **Boring Designation:** | B-5 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 0 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 80 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.12 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 4 | SP-SM | 7 | 100 | | |
| 2 | 4.0 | 6 | SP-SM | 7 | 100 | | |
| 3 | 6.0 | 34 | SM | 15 | 120 | | |
| 4 | 8.0 | 15 | SM | 15 | 120 | | |
| 5 | 13.5 | 2 | SM | 20 | 100 | | |
| 6 | 18.5 | 25 | SP-SM | 11 | 120 | | |
| 7 | 23.5 | 5 | SP-SM | 11 | 100 | | |
| 8 | 28.5 | 0 | SM | 33 | 100 | | |
| 9 | 33.5 | 2 | SM | 33 | 100 | | |
| 10 | 38.5 | 2 | SM | 21 | 100 | | |
| 11 | 43.5 | 7 | SM | 21 | 100 | | |
| 12 | 48.5 | 10 | SM | 26 | 100 | | |
| 13 | 53.5 | 6 | SM | 26 | 100 | | |
| 14 | 58.5 | 5 | MH | 50 | 120 | | Clay |
| 15 | 63.5 | 4 | MH | 50 | 120 | | Clay |
| 16 | 68.5 | 5 | MH | 50 | 120 | | Clay |
| 17 | 73.5 | 5 | MH | 50 | 120 | | Clay |
| 18 | 78.5 | 43 | GC | 15 | 120 | | Clay |
| 19 | | | | | | | |
| 20 | | | | | | | |
| 21 | | | | | | | |
| 22 | | | | | | | |
| 23 | | | | | | | |
| 24 | | | | | | | |
| 25 | | | | | | | |
| 26 | | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | |
| 29 | | | | | | | |
| 30 | | | | | | | |
| 31 | | | | | | | |
| 32 | | | | | | | |
| 33 | | | | | | | |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 4.0 | SP-SM | 6.6 | 100.0 | | 200 | 75 | 1.33 | 1.00 | 0.75 | 1.00 | 4.00 | 1.70 | 6.80 | 0.08 | 6.88 | 1.002 | 0.208 |
| 2 | 4.0 | 6.0 | SP-SM | 6.6 | 100.0 | | 400 | 150 | 1.33 | 1.00 | 0.75 | 1.00 | 6.00 | 1.70 | 10.20 | 0.08 | 10.28 | 0.997 | 0.207 |
| 3 | 6.0 | 34.0 | SM | 14.6 | 120.0 | | 640 | 266 | 1.33 | 1.00 | 0.80 | 1.00 | 36.27 | 1.70 | 61.65 | 3.12 | 64.78 | 0.991 | 0.186 |
| 4 | 8.0 | 15.0 | SM | 14.6 | 120.0 | | 880 | 381 | 1.33 | 1.00 | 0.80 | 1.00 | 16.00 | 1.70 | 27.20 | 3.12 | 30.32 | 0.985 | 0.178 |
| 5 | 13.5 | 2.0 | SM | 19.7 | 100.0 | | 1430 | 588 | 1.33 | 1.00 | 0.85 | 1.00 | 2.27 | 1.70 | 3.85 | 4.43 | 8.28 | 0.966 | 0.183 |
| 6 | 18.5 | 25.0 | SP-SM | 10.5 | 120.0 | | 2030 | 876 | 1.33 | 1.00 | 0.95 | 1.00 | 31.67 | 1.29 | 40.74 | 1.38 | 42.12 | 0.947 | 0.171 |
| 7 | 23.5 | 5.0 | SP-SM | 10.5 | 100.0 | | 2530 | 1064 | 1.33 | 1.00 | 0.95 | 1.00 | 6.33 | 1.44 | 9.15 | 1.38 | 10.53 | 0.926 | 0.172 |
| 8 | 28.5 | 0.0 | SM | 32.8 | 100.0 | | 3030 | 1252 | 1.33 | 1.00 | 1.00 | 1.00 | 0.00 | 1.37 | 0.00 | 5.46 | 5.46 | 0.903 | 0.170 |
| 9 | 33.5 | 2.0 | SM | 32.8 | 100.0 | | 3530 | 1440 | 1.33 | 1.00 | 1.00 | 1.00 | 2.67 | 1.24 | 3.30 | 5.46 | 8.76 | 0.879 | 0.168 |
| 10 | 38.5 | 2.0 | SM | 20.9 | 100.0 | | 4030 | 1628 | 1.33 | 1.00 | 1.00 | 1.00 | 2.67 | 1.16 | 3.10 | 4.62 | 7.72 | 0.855 | 0.165 |
| 11 | 43.5 | 7.0 | SM | 20.9 | 100.0 | | 4530 | 1816 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 1.08 | 10.06 | 4.62 | 14.68 | 0.830 | 0.162 |
| 12 | 48.5 | 10.0 | SM | 26.0 | 100.0 | | 5030 | 2004 | 1.33 | 1.00 | 1.00 | 1.00 | 13.33 | 1.02 | 13.67 | 5.15 | 18.81 | 0.805 | 0.158 |
| 13 | 53.5 | 6.0 | SM | 26.0 | 100.0 | | 5530 | 2192 | 1.33 | 1.00 | 1.00 | 1.00 | 8.00 | 0.98 | 7.86 | 5.15 | 13.01 | 0.781 | 0.154 |
| 14 | 58.5 | 5.0 | MH | 50.0 | 120.0 | Clay | 6130 | 2480 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.92 | 6.14 | 5.61 | 11.75 | 0.757 | 0.146 |
| 15 | 63.5 | 4.0 | MH | 50.0 | 120.0 | Clay | 6730 | 2768 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 0.87 | 4.62 | 5.61 | 10.23 | 0.734 | 0.139 |
| 16 | 68.5 | 5.0 | MH | 50.0 | 120.0 | Clay | 7330 | 3056 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.82 | 5.49 | 5.61 | 11.11 | 0.712 | 0.133 |
| 17 | 73.5 | 5.0 | MH | 50.0 | 120.0 | Clay | 7930 | 3344 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.78 | 5.23 | 5.61 | 10.84 | 0.691 | 0.128 |
| 18 | 78.5 | 43.0 | GC | 15.0 | 120.0 | Clay | 8530 | 3632 | 1.33 | 1.00 | 1.00 | 1.00 | 57.33 | 0.87 | 49.74 | 3.26 | 53.00 | 0.672 | 0.123 |
| 19 | | | | | | | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | | | | | | | |
| 31 | | | | | | | | | | | | | | | | | | | |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.14 | 1.01 | 1.10 | 0.097 | 0.108 | 0.52 |
| 1.20 | 1.01 | 1.10 | 0.120 | 0.134 | 0.65 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 2.02 | 1.07 | 1.10 | 0.506 | 0.595 | 2.00 |
| 1.16 | 1.01 | 1.10 | 0.106 | 0.118 | 0.65 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.20 | 1.01 | 1.06 | 0.122 | 0.131 | 0.77 |
| 1.12 | 1.01 | 1.04 | 0.089 | 0.093 | 0.55 |
| 1.17 | 1.01 | 1.03 | 0.110 | 0.115 | 0.68 |
| 1.15 | 1.01 | 1.02 | 0.103 | 0.106 | 0.64 |
| 1.31 | 1.02 | 1.02 | 0.153 | 0.159 | 0.99 |
| 1.45 | 1.03 | 1.01 | 0.192 | 0.199 | 1.26 |
| 1.26 | 1.02 | 1.00 | 0.140 | 0.142 | 0.92 |
| 1.23 | 1.02 | 0.98 | 0.131 | 0.131 | 2.00 |
| 1.20 | 1.01 | 0.98 | 0.120 | 0.118 | 2.00 |
| 1.21 | 1.01 | 0.96 | 0.126 | 0.123 | 2.00 |
| 1.21 | 1.01 | 0.96 | 0.124 | 0.120 | 2.00 |
| 2.20 | 1.08 | 0.84 | 2.000 | 1.818 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 3.0 | 0.046 | 1.64 | 18.07 |
| 4 | 2.0 | 0.037 | 0.88 | 16.43 |
| 6 | 2.0 | 0.000 | 0.00 | 15.55 |
| 8 | 3.8 | 0.000 | 0.00 | 15.55 |
| 13.5 | 5.3 | 0.042 | 2.61 | 15.55 |
| 18.5 | 5.0 | 0.000 | 0.00 | 12.93 |
| 23.5 | 5.0 | 0.036 | 2.17 | 12.93 |
| 28.5 | 5.0 | 0.051 | 3.04 | 10.76 |
| 33.5 | 5.0 | 0.040 | 2.42 | 7.72 |
| 38.5 | 5.0 | 0.043 | 2.58 | 5.30 |
| 43.5 | 5.0 | 0.014 | 0.83 | 2.72 |
| 48.5 | 5.0 | 0.005 | 0.29 | 1.89 |
| 53.5 | 5.0 | 0.027 | 1.61 | 1.61 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 81.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 5:42 PM |
| **Boring Designation:** | B-6 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 0 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 80 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.12 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 12 | SM | 17 | 100 | | |
| 2 | 4.0 | 9 | SM | 17 | 100 | | |
| 3 | 6.0 | 16 | SM | 16 | 120 | | |
| 4 | 8.0 | 26 | SM | 16 | 120 | | |
| 5 | 13.5 | 0 | SM | 26 | 100 | | |
| 6 | 18.5 | 20 | SM | 14 | 120 | | |
| 7 | 23.5 | 33 | SM | 14 | 120 | | |
| 8 | 28.5 | 0 | SP-SM | 11 | 100 | | |
| 9 | 33.5 | 4 | SM | 18 | 100 | | |
| 10 | 38.5 | 13 | SM | 18 | 100 | | |
| 11 | 43.5 | 25 | SM | 18 | 120 | | |
| 12 | 48.5 | 33 | SM | 18 | 120 | | |
| 13 | 53.5 | 8 | SM | 18 | 100 | | |
| 14 | 58.5 | 5 | MH | 50 | 120 | | Clay |
| 15 | 63.5 | 5 | MH | 50 | 120 | | Clay |
| 16 | 68.5 | 7 | MH | 50 | 120 | | Clay |
| 17 | 73.5 | 6 | MH | 50 | 120 | | Clay |
| 18 | 78.5 | 100 | ML | 50 | 120 | | Clay |
| 19 | | | | | | | |
| 20 | | | | | | | |
| 21 | | | | | | | |
| 22 | | | | | | | |
| 23 | | | | | | | |
| 24 | | | | | | | |
| 25 | | | | | | | |
| 26 | | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | |
| 29 | | | | | | | |
| 30 | | | | | | | |
| 31 | | | | | | | |
| 32 | | | | | | | |
| 33 | | | | | | | |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 12.0 | SM | 17.2 | 100.0 | | 200 | 75 | 1.33 | 1.00 | 0.75 | 1.00 | 12.00 | 1.70 | 20.40 | 3.90 | 24.30 | 1.002 | 0.208 |
| 2 | 4.0 | 9.0 | SM | 17.2 | 100.0 | | 400 | 150 | 1.33 | 1.00 | 0.75 | 1.00 | 9.00 | 1.70 | 15.30 | 3.90 | 19.20 | 0.997 | 0.207 |
| 3 | 6.0 | 16.0 | SM | 15.7 | 120.0 | | 640 | 266 | 1.33 | 1.00 | 0.80 | 1.00 | 17.07 | 1.70 | 29.01 | 3.49 | 32.50 | 0.991 | 0.186 |
| 4 | 8.0 | 26.0 | SM | 15.7 | 120.0 | | 880 | 381 | 1.33 | 1.00 | 0.80 | 1.00 | 27.73 | 1.57 | 43.55 | 3.49 | 47.03 | 0.985 | 0.178 |
| 5 | 13.5 | 0.0 | SM | 26.1 | 100.0 | | 1430 | 588 | 1.33 | 1.00 | 0.85 | 1.00 | 0.00 | 1.70 | 0.00 | 5.15 | 5.15 | 0.966 | 0.183 |
| 6 | 18.5 | 20.0 | SM | 13.7 | 120.0 | | 2030 | 876 | 1.33 | 1.00 | 0.95 | 1.00 | 25.33 | 1.33 | 33.62 | 2.79 | 36.41 | 0.947 | 0.171 |
| 7 | 23.5 | 33.0 | SM | 13.7 | 120.0 | | 2630 | 1164 | 1.33 | 1.00 | 0.95 | 1.00 | 41.80 | 1.17 | 48.92 | 2.79 | 51.71 | 0.926 | 0.163 |
| 8 | 28.5 | 0.0 | SP-SM | 11.0 | 100.0 | | 3130 | 1352 | 1.33 | 1.00 | 1.00 | 1.00 | 0.00 | 1.36 | 0.00 | 1.61 | 1.61 | 0.903 | 0.163 |
| 9 | 33.5 | 4.0 | SM | 18.3 | 100.0 | | 3630 | 1540 | 1.33 | 1.00 | 1.00 | 1.00 | 5.33 | 1.19 | 6.32 | 4.16 | 10.48 | 0.879 | 0.162 |
| 10 | 38.5 | 13.0 | SM | 18.3 | 100.0 | | 4130 | 1728 | 1.33 | 1.00 | 1.00 | 1.00 | 17.33 | 1.09 | 18.86 | 4.16 | 23.01 | 0.855 | 0.159 |
| 11 | 43.5 | 25.0 | SM | 18.3 | 120.0 | | 4730 | 2016 | 1.33 | 1.00 | 1.00 | 1.00 | 33.33 | 1.02 | 33.84 | 4.16 | 38.00 | 0.830 | 0.152 |
| 12 | 48.5 | 33.0 | SM | 18.3 | 120.0 | | 5330 | 2304 | 1.33 | 1.00 | 1.00 | 1.00 | 44.00 | 0.98 | 43.03 | 4.16 | 47.18 | 0.805 | 0.145 |
| 13 | 53.5 | 8.0 | SM | 18.3 | 100.0 | | 5830 | 2492 | 1.33 | 1.00 | 1.00 | 1.00 | 10.67 | 0.92 | 9.84 | 4.16 | 13.99 | 0.781 | 0.142 |
| 14 | 58.5 | 5.0 | MH | 50.0 | 120.0 | Clay | 6430 | 2780 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.87 | 5.78 | 5.61 | 11.39 | 0.757 | 0.137 |
| 15 | 63.5 | 5.0 | MH | 50.0 | 120.0 | Clay | 7030 | 3068 | 1.33 | 1.00 | 1.00 | 1.00 | 6.67 | 0.82 | 5.48 | 5.61 | 11.09 | 0.734 | 0.131 |
| 16 | 68.5 | 7.0 | MH | 50.0 | 120.0 | Clay | 7630 | 3356 | 1.33 | 1.00 | 1.00 | 1.00 | 9.33 | 0.79 | 7.39 | 5.61 | 13.00 | 0.712 | 0.126 |
| 17 | 73.5 | 6.0 | MH | 50.0 | 120.0 | Clay | 8230 | 3644 | 1.33 | 1.00 | 1.00 | 1.00 | 8.00 | 0.75 | 6.02 | 5.61 | 11.64 | 0.691 | 0.122 |
| 18 | 78.5 | 100.0 | ML | 50.0 | 120.0 | Clay | 8830 | 3932 | 1.33 | 1.00 | 1.00 | 1.00 | 133.33 | 0.85 | 113.28 | 5.61 | 118.89 | 0.672 | 0.118 |
| 19 | | | | | | | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | | | | | | | |
| 31 | | | | | | | | | | | | | | | | | | | |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.69 | 1.05 | 1.10 | 0.274 | 0.316 | 1.52 |
| 1.46 | 1.03 | 1.10 | 0.197 | 0.223 | 1.08 |
| 2.15 | 1.08 | 1.10 | 0.698 | 0.828 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.12 | 1.01 | 1.10 | 0.087 | 0.096 | 0.53 |
| 2.20 | 1.08 | 1.10 | 1.514 | 1.802 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.09 | 1.01 | 1.03 | 0.068 | 0.071 | 0.43 |
| 1.20 | 1.01 | 1.03 | 0.121 | 0.127 | 0.78 |
| 1.62 | 1.04 | 1.03 | 0.250 | 0.268 | 1.68 |
| 2.20 | 1.08 | 1.01 | 2.000 | 2.000 | 2.00 |
| 2.20 | 1.08 | 0.97 | 2.000 | 2.000 | 2.00 |
| 1.29 | 1.02 | 0.98 | 0.148 | 0.148 | 1.04 |
| 1.22 | 1.01 | 0.97 | 0.128 | 0.126 | 2.00 |
| 1.21 | 1.01 | 0.96 | 0.126 | 0.123 | 2.00 |
| 1.26 | 1.02 | 0.95 | 0.140 | 0.136 | 2.00 |
| 1.23 | 1.02 | 0.95 | 0.130 | 0.125 | 2.00 |
| 2.20 | 1.08 | 0.82 | 2.000 | 1.768 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 3.0 | 0.002 | 0.09 | 10.96 |
| 4 | 2.0 | 0.008 | 0.20 | 10.88 |
| 6 | 2.0 | 0.000 | 0.00 | 10.68 |
| 8 | 3.8 | 0.000 | 0.00 | 10.68 |
| 13.5 | 5.3 | 0.052 | 3.27 | 10.68 |
| 18.5 | 5.0 | 0.000 | 0.00 | 7.41 |
| 23.5 | 5.0 | 0.000 | 0.00 | 7.41 |
| 28.5 | 5.0 | 0.075 | 4.51 | 7.41 |
| 33.5 | 5.0 | 0.036 | 2.18 | 2.90 |
| 38.5 | 5.0 | 0.001 | 0.08 | 0.72 |
| 43.5 | 5.0 | 0.000 | 0.00 | 0.64 |
| 48.5 | 5.0 | 0.000 | 0.00 | 0.64 |
| 53.5 | 5.0 | 0.011 | 0.64 | 0.64 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 81.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:48 PM |
| Boring Designation: | B-7 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | 0 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 83.1 |
| Distance from sample hammer to ground surface (ft): | 5 |
| Borehole Diameter (in) | 4 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.14 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 9 | SM | 13 | 100 | | |
| 2 | 4.0 | 4 | SM | 13 | 100 | | |
| 3 | 6.0 | 0 | SM | 18 | 100 | | |
| 4 | 8.0 | 1 | SM | 18 | 100 | | |
| 5 | 13.5 | 2 | SM | 31 | 100 | | |
| 6 | 18.5 | 4 | SP-SM | 11 | 100 | | |
| 7 | 23.5 | 17 | SP-SM | 11 | 100 | | |
| 8 | 28.5 | 4 | SP-SM | 11 | 100 | | |
| 9 | 33.5 | 2 | CL | 50 | 100 | | Clay |
| 10 | 38.5 | 1 | SM | 18 | 100 | | |
| 11 | 43.5 | 4 | SM | 18 | 100 | | |
| 12 | 48.5 | 5 | SM | 18 | 100 | | |
| 13 | 53.5 | 10 | ML | 50 | 120 | | Clay |
| 14 | 58.5 | 4 | ML | 50 | 120 | | Clay |
| 15 | 63.5 | 8 | ML | 50 | 120 | | Clay |
| 16 | 68.5 | 8 | SM | 15 | 120 | | Clay |
| 17 | 73.5 | 100 | SM | 15 | 120 | | Clay |
| 18 | 78.5 | 12 | SM | 15 | 120 | | Clay |
| 19 | 83.5 | 6 | SM | 15 | 120 | | Clay |
| 20 | 88.5 | 6 | SM | 15 | 120 | | Clay |
| 21 | 93.5 | 12 | SM | 15 | 120 | | Clay |
| 22 | 98.5 | 13 | SM | 15 | 120 | | Clay |
| 23 | 103.5 | 11 | SM | 15 | 120 | | Clay |
| 24 | 108.5 | 6 | SM | 15 | 120 | | Clay |
| 25 | 113.5 | 11 | SM | 15 | 120 | | Clay |
| 26 | 118.5 | 9 | SM | 15 | 120 | | Clay |
| 27 | 123.5 | 7 | SM | 15 | 120 | | Clay |
| 28 | 128.5 | 13 | SM | 15 | 120 | | Clay |
| 29 | 133.5 | 12 | SM | 15 | 120 | | Clay |
| 30 | 138.5 | 11 | SM | 15 | 120 | | Clay |
| 31 | 143.5 | 9 | SM | 15 | 120 | | Clay |
| 32 | | | | | | | |
| 33 | | | | | | | |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

Liquefaction Calculations B-7 (FEE)

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 9.0 | SM | 12.8 | 100.0 | | 200 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 9.35 | 1.70 | 15.89 | 2.42 | 18.32 | 1.002 | 0.242 |
| 2 | 4.0 | 4.0 | SM | 12.8 | 100.0 | | 400 | 150 | 1.39 | 1.00 | 0.75 | 1.00 | 4.16 | 1.70 | 7.06 | 2.42 | 9.49 | 0.997 | 0.241 |
| 3 | 6.0 | 0.0 | SM | 18.2 | 100.0 | | 600 | 226 | 1.39 | 1.00 | 0.80 | 1.00 | 0.00 | 1.70 | 0.00 | 4.13 | 4.13 | 0.991 | 0.240 |
| 4 | 8.0 | 1.0 | SM | 18.2 | 100.0 | | 800 | 301 | 1.39 | 1.00 | 0.80 | 1.00 | 1.11 | 1.70 | 1.88 | 4.13 | 6.02 | 0.985 | 0.238 |
| 5 | 13.5 | 2.0 | SM | 31.3 | 100.0 | | 1350 | 508 | 1.39 | 1.00 | 0.85 | 1.00 | 2.35 | 1.70 | 4.00 | 5.41 | 9.41 | 0.966 | 0.234 |
| 6 | 18.5 | 4.0 | SP-SM | 10.8 | 100.0 | | 1850 | 696 | 1.39 | 1.00 | 0.95 | 1.00 | 5.26 | 1.70 | 8.95 | 1.52 | 10.47 | 0.947 | 0.229 |
| 7 | 23.5 | 17.0 | SP-SM | 10.8 | 100.0 | | 2350 | 884 | 1.39 | 1.00 | 0.95 | 1.00 | 22.37 | 1.36 | 30.37 | 1.52 | 31.89 | 0.926 | 0.224 |
| 8 | 28.5 | 4.0 | SP-SM | 10.8 | 100.0 | | 2850 | 1072 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.45 | 8.04 | 1.52 | 9.55 | 0.903 | 0.219 |
| 9 | 33.5 | 2.0 | CL | 50.0 | 100.0 | Clay | 3350 | 1260 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.33 | 3.68 | 5.61 | 9.30 | 0.879 | 0.213 |
| 10 | 38.5 | 1.0 | SM | 17.9 | 100.0 | | 3850 | 1448 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.26 | 1.74 | 4.07 | 5.81 | 0.855 | 0.207 |
| 11 | 43.5 | 4.0 | SM | 17.9 | 100.0 | | 4350 | 1636 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.15 | 6.36 | 4.07 | 10.43 | 0.830 | 0.201 |
| 12 | 48.5 | 5.0 | SM | 17.9 | 100.0 | | 4850 | 1824 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 1.08 | 7.49 | 4.07 | 11.55 | 0.805 | 0.195 |
| 13 | 53.5 | 10.0 | ML | 50.0 | 120.0 | Clay | 5450 | 2112 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 1.00 | 13.86 | 5.61 | 19.48 | 0.781 | 0.183 |
| 14 | 58.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 6050 | 2400 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 0.94 | 5.18 | 5.61 | 10.80 | 0.757 | 0.174 |
| 15 | 63.5 | 8.0 | ML | 50.0 | 120.0 | Clay | 6650 | 2688 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.89 | 9.87 | 5.61 | 15.49 | 0.734 | 0.165 |
| 16 | 68.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 7250 | 2976 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.84 | 9.31 | 3.26 | 12.57 | 0.712 | 0.158 |
| 17 | 73.5 | 100.0 | SM | 15.0 | 120.0 | Clay | 7850 | 3264 | 1.39 | 1.00 | 1.00 | 1.00 | 138.50 | 0.89 | 123.58 | 3.26 | 126.84 | 0.691 | 0.151 |
| 18 | 78.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 8450 | 3552 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.78 | 13.00 | 3.26 | 16.26 | 0.672 | 0.145 |
| 19 | 83.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 9050 | 3840 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.72 | 5.99 | 3.26 | 9.25 | 0.654 | 0.140 |
| 20 | 88.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 9650 | 4128 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.69 | 5.74 | 3.26 | 9.00 | 0.639 | 0.136 |
| 21 | 93.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 10250 | 4416 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.70 | 11.61 | 3.26 | 14.87 | 0.625 | 0.132 |
| 22 | 98.5 | 13.0 | SM | 15.0 | 120.0 | Clay | 10850 | 4704 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.68 | 12.26 | 3.26 | 15.52 | 0.613 | 0.129 |
| 23 | 103.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 11450 | 4992 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.65 | 9.87 | 3.26 | 13.13 | 0.603 | 0.126 |
| 24 | 108.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 12050 | 5280 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.60 | 4.96 | 3.26 | 8.22 | 0.596 | 0.124 |
| 25 | 113.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 12650 | 5568 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.61 | 9.28 | 3.26 | 12.55 | 0.590 | 0.122 |
| 26 | 118.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 13250 | 5856 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.58 | 7.23 | 3.26 | 10.49 | 0.587 | 0.121 |
| 27 | 123.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 13850 | 6144 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.55 | 5.34 | 3.26 | 8.61 | 0.586 | 0.120 |
| 28 | 128.5 | 13.0 | SM | 15.0 | 120.0 | Clay | 14450 | 6432 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.57 | 10.32 | 3.26 | 13.58 | 0.588 | 0.120 |
| 29 | 133.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 15050 | 6720 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.55 | 9.19 | 3.26 | 12.45 | 0.592 | 0.121 |
| 30 | 138.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 15650 | 7008 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.53 | 8.13 | 3.26 | 11.39 | 0.598 | 0.122 |
| 31 | 143.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 16250 | 7296 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.51 | 6.34 | 3.26 | 9.60 | 0.607 | 0.123 |
| 32 | | | | | | | | | | | | | | | | | | | |
| 33 | | | | | | | | | | | | | | | | | | | |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.43 | 1.03 | 1.10 | 0.187 | 0.212 | 0.87 |
| 1.18 | 1.01 | 1.10 | 0.115 | 0.128 | 0.53 |
| 1.11 | 1.01 | 1.10 | 0.081 | 0.090 | 0.38 |
| 1.13 | 1.01 | 1.10 | 0.092 | 0.102 | 0.43 |
| 1.18 | 1.01 | 1.10 | 0.114 | 0.127 | 0.54 |
| 1.20 | 1.01 | 1.10 | 0.121 | 0.135 | 0.59 |
| 2.11 | 1.08 | 1.10 | 0.633 | 0.749 | 2.00 |
| 1.18 | 1.01 | 1.06 | 0.115 | 0.124 | 0.57 |
| 1.18 | 1.01 | 1.05 | 0.113 | 0.120 | 2.00 |
| 1.12 | 1.01 | 1.03 | 0.091 | 0.094 | 0.46 |
| 1.20 | 1.01 | 1.02 | 0.121 | 0.126 | 0.63 |
| 1.22 | 1.02 | 1.01 | 0.129 | 0.133 | 0.68 |
| 1.47 | 1.03 | 1.00 | 0.200 | 0.206 | 2.00 |
| 1.21 | 1.01 | 0.99 | 0.124 | 0.124 | 2.00 |
| 1.33 | 1.02 | 0.97 | 0.160 | 0.159 | 2.00 |
| 1.25 | 1.02 | 0.97 | 0.137 | 0.134 | 2.00 |
| 2.20 | 1.08 | 0.87 | 2.000 | 1.886 | 2.00 |
| 1.36 | 1.02 | 0.94 | 0.167 | 0.161 | 2.00 |
| 1.18 | 1.01 | 0.95 | 0.113 | 0.108 | 2.00 |
| 1.17 | 1.01 | 0.94 | 0.111 | 0.106 | 2.00 |
| 1.31 | 1.02 | 0.92 | 0.155 | 0.145 | 2.00 |
| 1.33 | 1.02 | 0.91 | 0.161 | 0.149 | 2.00 |
| 1.26 | 1.02 | 0.91 | 0.141 | 0.131 | 2.00 |
| 1.16 | 1.01 | 0.92 | 0.106 | 0.099 | 2.00 |
| 1.25 | 1.02 | 0.90 | 0.137 | 0.125 | 2.00 |
| 1.20 | 1.01 | 0.90 | 0.122 | 0.111 | 2.00 |
| 1.16 | 1.01 | 0.91 | 0.109 | 0.100 | 2.00 |
| 1.28 | 1.02 | 0.88 | 0.145 | 0.130 | 2.00 |
| 1.25 | 1.02 | 0.88 | 0.136 | 0.122 | 2.00 |
| 1.22 | 1.01 | 0.88 | 0.128 | 0.115 | 2.00 |
| 1.18 | 1.01 | 0.89 | 0.115 | 0.104 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 3.0 | 0.018 | 0.65 | 19.24 |
| 4 | 2.0 | 0.039 | 0.92 | 18.59 |
| 6 | 2.0 | 0.057 | 1.36 | 17.66 |
| 8 | 3.8 | 0.049 | 2.18 | 16.30 |
| 13.5 | 5.3 | 0.039 | 2.44 | 14.12 |
| 18.5 | 5.0 | 0.036 | 2.18 | 11.68 |
| 23.5 | 5.0 | 0.000 | 0.00 | 9.50 |
| 28.5 | 5.0 | 0.038 | 2.30 | 9.50 |
| 33.5 | 5.0 | 0.000 | 0.00 | 7.20 |
| 38.5 | 5.0 | 0.049 | 2.96 | 7.20 |
| 43.5 | 5.0 | 0.036 | 2.19 | 4.24 |
| 48.5 | 5.0 | 0.034 | 2.05 | 2.05 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 133.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 143.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 146.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 5:49 PM |
| **Boring Designation:** | B-8 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 0 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 83.1 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.14 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 3 | SP-SM | 12 | 100 | | |
| 2 | 4.0 | 5 | SP-SM | 12 | 100 | | |
| 3 | 6.0 | 4 | SP-SM | 12 | 100 | | |
| 4 | 8.0 | 2 | SP-SM | 12 | 100 | | |
| 5 | 10.0 | 2 | SP-SM | 12 | 100 | | |
| 6 | 13.5 | 0 | CL | 68 | 95 | | Clay |
| 7 | 18.5 | 0 | CL | 68 | 95 | | Clay |
| 8 | 23.5 | 0 | SC | 35 | 100 | | |
| 9 | 28.5 | 2 | SM | 22 | 100 | | |
| 10 | 33.5 | 4 | SM | 22 | 100 | | |
| 11 | 38.5 | 2 | CL | 50 | 95 | | Clay |
| 12 | 43.5 | 8 | SP-SM | 7 | 100 | | |
| 13 | 48.5 | 7 | SP-SM | 8 | 100 | | |
| 14 | 53.5 | 5 | SM | 15 | 120 | | Clay |
| 15 | 58.5 | 6 | ML | 50 | 120 | | Clay |
| 16 | 63.5 | 6 | ML | 50 | 120 | | Clay |
| 17 | 68.5 | 5 | ML | 50 | 120 | | Clay |
| 18 | 73.5 | 18 | ML | 50 | 120 | | Clay |
| 19 | 78.5 | 13 | SM | 15 | 120 | | Clay |
| 20 | 83.5 | 5 | SM | 15 | 120 | | Clay |
| 21 | 88.5 | 8 | SM | 15 | 120 | | Clay |
| 22 | 93.5 | 9 | SM | 15 | 120 | | Clay |
| 23 | 98.5 | 8 | SM | 15 | 120 | | Clay |
| 24 | 103.5 | 9 | SM | 15 | 120 | | Clay |
| 25 | 108.5 | 6 | SM | 15 | 120 | | Clay |
| 26 | 113.5 | 12 | SM | 15 | 120 | | Clay |
| 27 | 118.5 | 9 | SM | 15 | 120 | | Clay |
| 28 | 123.5 | 7 | SM | 15 | 120 | | Clay |
| 29 | 128.5 | 19 | SM | 15 | 120 | | Clay |
| 30 | 133.5 | 11 | SM | 15 | 120 | | Clay |
| 31 | 138.5 | | SM | 15 | 120 | | Clay |
| 32 | 143.5 | 10 | SM | 15 | 120 | | Clay |
| 33 | 148.5 | 11 | SM | 15 | 120 | | Clay |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

Liquefaction Calculations B-8 (FEE)

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 2.0 | 3.0 | SP-SM | 11.9 | 100.0 | | 200 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 3.12 | 1.70 | 5.30 | 2.03 | 7.32 | 1.002 | 0.242 |
| 2 | 4.0 | 5.0 | SP-SM | 11.9 | 100.0 | | 400 | 150 | 1.39 | 1.00 | 0.75 | 1.00 | 5.19 | 1.70 | 8.83 | 2.03 | 10.86 | 0.997 | 0.241 |
| 3 | 6.0 | 4.0 | SP-SM | 11.9 | 100.0 | | 600 | 226 | 1.39 | 1.00 | 0.80 | 1.00 | 4.43 | 1.70 | 7.53 | 2.03 | 9.56 | 0.991 | 0.240 |
| 4 | 8.0 | 2.0 | SP-SM | 11.9 | 100.0 | | 800 | 301 | 1.39 | 1.00 | 0.80 | 1.00 | 2.22 | 1.70 | 3.77 | 2.03 | 5.79 | 0.985 | 0.238 |
| 5 | 10.0 | 2.0 | SP-SM | 11.9 | 100.0 | | 1000 | 376 | 1.39 | 1.00 | 0.85 | 1.00 | 2.35 | 1.70 | 4.00 | 2.03 | 6.03 | 0.978 | 0.237 |
| 6 | 13.5 | 0.0 | CL | 67.5 | 95.0 | Clay | 1333 | 490 | 1.39 | 1.00 | 0.85 | 1.00 | 0.00 | 1.70 | 0.00 | 5.58 | 5.58 | 0.966 | 0.239 |
| 7 | 18.5 | 0.0 | CL | 67.5 | 95.0 | Clay | 1808 | 653 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.58 | 5.58 | 0.947 | 0.238 |
| 8 | 23.5 | 0.0 | SC | 34.9 | 100.0 | | 2308 | 841 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.50 | 5.50 | 0.926 | 0.231 |
| 9 | 28.5 | 2.0 | SM | 22.0 | 100.0 | | 2808 | 1029 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.49 | 4.13 | 4.77 | 8.90 | 0.903 | 0.224 |
| 10 | 33.5 | 4.0 | SM | 22.0 | 100.0 | | 3308 | 1217 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.33 | 7.37 | 4.77 | 12.14 | 0.879 | 0.217 |
| 11 | 38.5 | 2.0 | CL | 50.0 | 95.0 | Clay | 3783 | 1380 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.27 | 3.51 | 5.61 | 9.12 | 0.855 | 0.213 |
| 12 | 43.5 | 8.0 | SP-SM | 6.5 | 100.0 | | 4283 | 1568 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 1.16 | 12.90 | 0.07 | 12.97 | 0.830 | 0.206 |
| 13 | 48.5 | 7.0 | SP-SM | 8.2 | 100.0 | | 4783 | 1756 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 1.10 | 10.70 | 0.43 | 11.13 | 0.805 | 0.200 |
| 14 | 53.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 5383 | 2044 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 1.02 | 7.05 | 3.26 | 10.32 | 0.781 | 0.187 |
| 15 | 58.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 5983 | 2332 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.95 | 7.91 | 5.61 | 13.53 | 0.757 | 0.177 |
| 16 | 63.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 6583 | 2620 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.90 | 7.46 | 5.61 | 13.07 | 0.734 | 0.168 |
| 17 | 68.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 7183 | 2908 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.85 | 5.86 | 5.61 | 11.48 | 0.712 | 0.160 |
| 18 | 73.5 | 18.0 | ML | 50.0 | 120.0 | Clay | 7783 | 3196 | 1.39 | 1.00 | 1.00 | 1.00 | 24.93 | 0.85 | 21.26 | 5.61 | 26.88 | 0.691 | 0.153 |
| 19 | 78.5 | 13.0 | SM | 15.0 | 120.0 | Clay | 8383 | 3484 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.79 | 14.30 | 3.26 | 17.56 | 0.672 | 0.147 |
| 20 | 83.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 8983 | 3772 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.72 | 5.00 | 3.26 | 8.26 | 0.654 | 0.142 |
| 21 | 88.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 9583 | 4060 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.71 | 7.85 | 3.26 | 11.12 | 0.639 | 0.137 |
| 22 | 93.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 10183 | 4348 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.69 | 8.57 | 3.26 | 11.83 | 0.625 | 0.133 |
| 23 | 98.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 10783 | 4636 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.66 | 7.29 | 3.26 | 10.55 | 0.613 | 0.130 |
| 24 | 103.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 11383 | 4924 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.64 | 7.99 | 3.26 | 11.25 | 0.603 | 0.127 |
| 25 | 108.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 11983 | 5212 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.60 | 5.00 | 3.26 | 8.26 | 0.596 | 0.125 |
| 26 | 113.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 12583 | 5500 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.62 | 10.30 | 3.26 | 13.56 | 0.590 | 0.123 |
| 27 | 118.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 13183 | 5788 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.58 | 7.28 | 3.26 | 10.54 | 0.587 | 0.122 |
| 28 | 123.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 13783 | 6076 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.55 | 5.38 | 3.26 | 8.64 | 0.586 | 0.121 |
| 29 | 128.5 | 19.0 | SM | 15.0 | 120.0 | Clay | 14383 | 6364 | 1.39 | 1.00 | 1.00 | 1.00 | 26.32 | 0.61 | 16.10 | 3.26 | 19.36 | 0.588 | 0.121 |
| 30 | 133.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 14983 | 6652 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.55 | 8.38 | 3.26 | 11.64 | 0.592 | 0.121 |
| 31 | 138.5 | 0.0 | SM | 15.0 | 120.0 | Clay | 15583 | 6940 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 0.46 | 0.00 | 3.26 | 3.26 | 0.598 | 0.122 |
| 32 | 143.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 16183 | 7228 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.52 | 7.17 | 3.26 | 10.43 | 0.607 | 0.124 |
| 33 | 148.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 16783 | 7516 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.51 | 7.80 | 3.26 | 11.06 | 0.618 | 0.126 |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.14 | 1.01 | 1.10 | 0.100 | 0.111 | 0.46 |
| 1.21 | 1.01 | 1.10 | 0.124 | 0.138 | 0.57 |
| 1.18 | 1.01 | 1.10 | 0.115 | 0.128 | 0.53 |
| 1.12 | 1.01 | 1.10 | 0.091 | 0.101 | 0.42 |
| 1.13 | 1.01 | 1.10 | 0.092 | 0.102 | 0.43 |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.09 | 0.090 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.07 | 0.089 | 0.096 | 0.42 |
| 1.17 | 1.01 | 1.06 | 0.111 | 0.119 | 0.53 |
| 1.24 | 1.02 | 1.06 | 0.133 | 0.143 | 0.66 |
| 1.17 | 1.01 | 1.04 | 0.112 | 0.118 | 2.00 |
| 1.26 | 1.02 | 1.03 | 0.140 | 0.147 | 0.71 |
| 1.21 | 1.01 | 1.02 | 0.126 | 0.130 | 0.65 |
| 1.20 | 1.01 | 1.00 | 0.120 | 0.122 | 2.00 |
| 1.27 | 1.02 | 0.99 | 0.144 | 0.145 | 2.00 |
| 1.26 | 1.02 | 0.98 | 0.141 | 0.140 | 2.00 |
| 1.22 | 1.02 | 0.97 | 0.129 | 0.127 | 2.00 |
| 1.82 | 1.06 | 0.93 | 0.342 | 0.335 | 2.00 |
| 1.40 | 1.03 | 0.94 | 0.179 | 0.173 | 2.00 |
| 1.16 | 1.01 | 0.95 | 0.106 | 0.102 | 2.00 |
| 1.21 | 1.01 | 0.94 | 0.126 | 0.120 | 2.00 |
| 1.23 | 1.02 | 0.93 | 0.131 | 0.124 | 2.00 |
| 1.20 | 1.01 | 0.93 | 0.122 | 0.114 | 2.00 |
| 1.22 | 1.01 | 0.92 | 0.127 | 0.118 | 2.00 |
| 1.16 | 1.01 | 0.92 | 0.106 | 0.099 | 2.00 |
| 1.28 | 1.02 | 0.90 | 0.144 | 0.132 | 2.00 |
| 1.20 | 1.01 | 0.91 | 0.122 | 0.112 | 2.00 |
| 1.17 | 1.01 | 0.91 | 0.109 | 0.100 | 2.00 |
| 1.47 | 1.03 | 0.86 | 0.198 | 0.175 | 2.00 |
| 1.23 | 1.02 | 0.89 | 0.130 | 0.117 | 2.00 |
| 1.10 | 1.01 | 0.92 | 0.077 | 0.071 | 2.00 |
| 1.20 | 1.01 | 0.88 | 0.121 | 0.109 | 2.00 |
| 1.21 | 1.01 | 0.88 | 0.126 | 0.112 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 2 | 3.0 | 0.044 | 1.59 | 17.57 |
| 4 | 2.0 | 0.036 | 0.85 | 15.98 |
| 6 | 2.0 | 0.038 | 0.92 | 15.13 |
| 8 | 2.0 | 0.049 | 1.18 | 14.21 |
| 10 | 2.8 | 0.048 | 1.60 | 13.02 |
| 13.5 | 4.3 | 0.000 | 0.00 | 11.42 |
| 18.5 | 5.0 | 0.000 | 0.00 | 11.42 |
| 23.5 | 5.0 | 0.050 | 3.03 | 11.42 |
| 28.5 | 5.0 | 0.040 | 2.39 | 8.39 |
| 33.5 | 5.0 | 0.033 | 1.99 | 6.00 |
| 38.5 | 5.0 | 0.000 | 0.00 | 4.01 |
| 43.5 | 5.0 | 0.032 | 1.91 | 4.01 |
| 48.5 | 5.0 | 0.035 | 2.10 | 2.10 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 133.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 143.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 148.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 151.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 6:08 PM |
| **Boring Designation:** | B-9 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 0 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 83.1 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.14 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 0 | ML | 50 | 95 | | Clay |
| 2 | 2.0 | 5 | SP-SM | 8 | 100 | | |
| 3 | 4.0 | 6 | SP-SM | 7 | 100 | | |
| 4 | 6.0 | 0 | SP-SM | 7 | 100 | | |
| 5 | 8.0 | 2 | SP-SM | 10 | 100 | | |
| 6 | 13.5 | 0 | SP-SM | 10 | 100 | | |
| 7 | 18.5 | 0 | CL | 79 | 95 | | Clay |
| 8 | 23.5 | 0 | CL | 79 | 95 | | Clay |
| 9 | 28.5 | 0 | CL | 79 | 95 | | Clay |
| 10 | 33.5 | 1 | CL | 79 | 95 | | Clay |
| 11 | 38.5 | 2 | CL | 79 | 95 | | Clay |
| 12 | 43.5 | 7 | SP-SM | 8 | 100 | | |
| 13 | 48.5 | 4 | SP-SM | 8 | 100 | | |
| 14 | 53.5 | 4 | ML | 50 | 120 | | Clay |
| 15 | 58.5 | 5 | ML | 50 | 120 | | Clay |
| 16 | 63.5 | 7 | ML | 50 | 120 | | Clay |
| 17 | 68.5 | 5 | ML | 50 | 120 | | Clay |
| 18 | 73.5 | 13 | ML | 50 | 120 | | Clay |
| 19 | 78.5 | 100 | SM | 15 | 120 | | Clay |
| 20 | 83.5 | 5 | SM | 15 | 120 | | Clay |
| 21 | 88.5 | 8 | SM | 15 | 120 | | Clay |
| 22 | 93.5 | 8 | SM | 15 | 120 | | Clay |
| 23 | 98.5 | 8 | SM | 15 | 120 | | Clay |
| 24 | 103.5 | 14 | SM | 15 | 120 | | Clay |
| 25 | 108.5 | 8 | SM | 15 | 120 | | Clay |
| 26 | 113.5 | 7 | SM | 15 | 120 | | Clay |
| 27 | 118.5 | 7 | SM | 15 | 120 | | Clay |
| 28 | 123.5 | 6 | SM | 15 | 120 | | Clay |
| 29 | 128.5 | 6 | SM | 15 | 120 | | Clay |
| 30 | 133.5 | 13 | ML | 50 | 120 | | Clay |
| 31 | 138.5 | 11 | ML | 50 | 120 | | Clay |
| 32 | 143.5 | 11 | SM | 15 | 120 | | Clay |
| 33 | 148.5 | 10 | SM | 15 | 120 | | Clay |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 0.0 | ML | 50.0 | 95.0 | Clay | 48 | 16 | 1.39 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 1.005 | 0.267 |
| 2 | 2.0 | 5.0 | SP-SM | 7.7 | 100.0 | | 198 | 73 | 1.39 | 1.00 | 0.75 | 1.00 | 5.19 | 1.70 | 8.83 | 0.28 | 9.11 | 1.002 | 0.248 |
| 3 | 4.0 | 6.0 | SP-SM | 7.2 | 100.0 | | 398 | 148 | 1.39 | 1.00 | 0.75 | 1.00 | 6.23 | 1.70 | 10.60 | 0.17 | 10.77 | 0.997 | 0.244 |
| 4 | 6.0 | 0.0 | SP-SM | 7.0 | 100.0 | | 598 | 223 | 1.39 | 1.00 | 0.80 | 1.00 | 0.00 | 1.70 | 0.00 | 0.14 | 0.14 | 0.991 | 0.241 |
| 5 | 8.0 | 2.0 | SP-SM | 10.3 | 100.0 | | 798 | 298 | 1.39 | 1.00 | 0.80 | 1.00 | 2.22 | 1.70 | 3.77 | 1.29 | 5.05 | 0.985 | 0.240 |
| 6 | 13.5 | 0.0 | SP-SM | 10.0 | 100.0 | | 1348 | 505 | 1.39 | 1.00 | 0.85 | 1.00 | 0.00 | 1.70 | 0.00 | 1.15 | 1.15 | 0.966 | 0.235 |
| 7 | 18.5 | 0.0 | CL | 79.0 | 95.0 | Clay | 1823 | 668 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.55 | 5.55 | 0.947 | 0.235 |
| 8 | 23.5 | 0.0 | CL | 79.0 | 95.0 | Clay | 2298 | 831 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.55 | 5.55 | 0.926 | 0.233 |
| 9 | 28.5 | 0.0 | CL | 79.1 | 95.0 | Clay | 2773 | 994 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.58 | 0.00 | 5.55 | 5.55 | 0.903 | 0.229 |
| 10 | 33.5 | 1.0 | CL | 79.0 | 95.0 | Clay | 3248 | 1157 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.41 | 1.96 | 5.55 | 7.51 | 0.879 | 0.225 |
| 11 | 38.5 | 2.0 | CL | 79.0 | 95.0 | Clay | 3723 | 1320 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.30 | 3.59 | 5.55 | 9.14 | 0.855 | 0.219 |
| 12 | 43.5 | 7.0 | SP-SM | 7.5 | 100.0 | | 4223 | 1508 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 1.19 | 11.56 | 0.23 | 11.80 | 0.830 | 0.211 |
| 13 | 48.5 | 4.0 | SP-SM | 8.0 | 100.0 | | 4723 | 1696 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.14 | 6.31 | 0.37 | 6.67 | 0.805 | 0.204 |
| 14 | 53.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 5323 | 1984 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.03 | 5.73 | 5.61 | 11.35 | 0.781 | 0.191 |
| 15 | 58.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 5923 | 2272 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.96 | 6.68 | 5.61 | 12.29 | 0.757 | 0.180 |
| 16 | 63.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 6523 | 2560 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.91 | 8.83 | 5.61 | 14.44 | 0.734 | 0.170 |
| 17 | 68.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 7123 | 2848 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.86 | 5.93 | 5.61 | 11.54 | 0.712 | 0.162 |
| 18 | 73.5 | 13.0 | ML | 50.0 | 120.0 | Clay | 7723 | 3136 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.84 | 15.18 | 5.61 | 20.79 | 0.691 | 0.155 |
| 19 | 78.5 | 100.0 | SM | 15.0 | 120.0 | Clay | 8323 | 3424 | 1.39 | 1.00 | 1.00 | 1.00 | 138.50 | 0.88 | 122.03 | 3.26 | 125.29 | 0.672 | 0.149 |
| 20 | 83.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 8923 | 3712 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.73 | 5.05 | 3.26 | 8.31 | 0.654 | 0.143 |
| 21 | 88.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 9523 | 4000 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.71 | 7.92 | 3.26 | 11.18 | 0.639 | 0.138 |
| 22 | 93.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 10123 | 4288 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.69 | 7.62 | 3.26 | 10.88 | 0.625 | 0.134 |
| 23 | 98.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 10723 | 4576 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.66 | 7.34 | 3.26 | 10.60 | 0.613 | 0.131 |
| 24 | 103.5 | 14.0 | SM | 15.0 | 120.0 | Clay | 11323 | 4864 | 1.39 | 1.00 | 1.00 | 1.00 | 19.39 | 0.67 | 13.07 | 3.26 | 16.33 | 0.603 | 0.128 |
| 25 | 108.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 11923 | 5152 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.62 | 6.85 | 3.26 | 10.12 | 0.596 | 0.125 |
| 26 | 113.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 12523 | 5440 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.59 | 5.75 | 3.26 | 9.01 | 0.590 | 0.124 |
| 27 | 118.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 13123 | 5728 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.57 | 5.57 | 3.26 | 8.84 | 0.587 | 0.122 |
| 28 | 123.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 13723 | 6016 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.55 | 4.59 | 3.26 | 7.85 | 0.586 | 0.122 |
| 29 | 128.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 14323 | 6304 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.54 | 4.46 | 3.26 | 7.72 | 0.588 | 0.121 |
| 30 | 133.5 | 13.0 | ML | 50.0 | 120.0 | Clay | 14923 | 6592 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.58 | 10.48 | 5.61 | 16.10 | 0.592 | 0.122 |
| 31 | 138.5 | 11.0 | ML | 50.0 | 120.0 | Clay | 15523 | 6880 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.56 | 8.49 | 5.61 | 14.11 | 0.598 | 0.123 |
| 32 | 143.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 16123 | 7168 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.53 | 8.02 | 3.26 | 11.28 | 0.607 | 0.124 |
| 33 | 148.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 16723 | 7456 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.51 | 7.04 | 3.26 | 10.30 | 0.618 | 0.126 |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.100 | 2.00 |
| 1.17 | 1.01 | 1.10 | 0.112 | 0.125 | 0.50 |
| 1.21 | 1.01 | 1.10 | 0.123 | 0.138 | 0.57 |
| 1.09 | 1.01 | 1.10 | 0.061 | 0.068 | 0.28 |
| 1.12 | 1.01 | 1.10 | 0.086 | 0.096 | 0.40 |
| 1.09 | 1.01 | 1.09 | 0.066 | 0.072 | 0.31 |
| 1.12 | 1.01 | 1.09 | 0.089 | 0.098 | 2.00 |
| 1.12 | 1.01 | 1.07 | 0.089 | 0.097 | 2.00 |
| 1.12 | 1.01 | 1.06 | 0.089 | 0.095 | 2.00 |
| 1.15 | 1.01 | 1.05 | 0.101 | 0.108 | 2.00 |
| 1.17 | 1.01 | 1.04 | 0.112 | 0.118 | 2.00 |
| 1.23 | 1.02 | 1.03 | 0.131 | 0.137 | 0.65 |
| 1.13 | 1.01 | 1.02 | 0.096 | 0.099 | 0.48 |
| 1.22 | 1.01 | 1.01 | 0.128 | 0.130 | 2.00 |
| 1.24 | 1.02 | 0.99 | 0.135 | 0.136 | 2.00 |
| 1.30 | 1.02 | 0.98 | 0.151 | 0.151 | 2.00 |
| 1.22 | 1.02 | 0.97 | 0.129 | 0.127 | 2.00 |
| 1.53 | 1.04 | 0.95 | 0.216 | 0.212 | 2.00 |
| 2.20 | 1.08 | 0.86 | 2.000 | 1.856 | 2.00 |
| 1.16 | 1.01 | 0.95 | 0.107 | 0.103 | 2.00 |
| 1.22 | 1.01 | 0.94 | 0.126 | 0.120 | 2.00 |
| 1.21 | 1.01 | 0.93 | 0.124 | 0.118 | 2.00 |
| 1.20 | 1.01 | 0.93 | 0.122 | 0.115 | 2.00 |
| 1.36 | 1.02 | 0.90 | 0.168 | 0.155 | 2.00 |
| 1.19 | 1.01 | 0.92 | 0.119 | 0.110 | 2.00 |
| 1.17 | 1.01 | 0.92 | 0.111 | 0.103 | 2.00 |
| 1.17 | 1.01 | 0.91 | 0.110 | 0.102 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.104 | 0.095 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.103 | 0.094 | 2.00 |
| 1.35 | 1.02 | 0.87 | 0.166 | 0.147 | 2.00 |
| 1.29 | 1.02 | 0.87 | 0.149 | 0.133 | 2.00 |
| 1.22 | 1.01 | 0.88 | 0.127 | 0.114 | 2.00 |
| 1.20 | 1.01 | 0.88 | 0.120 | 0.107 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.000 | 0.00 | 16.45 |
| 2 | 1.8 | 0.039 | 0.83 | 16.45 |
| 4 | 2.0 | 0.036 | 0.86 | 15.62 |
| 6 | 2.0 | 0.105 | 2.51 | 14.76 |
| 8 | 3.8 | 0.052 | 2.36 | 12.25 |
| 13.5 | 5.3 | 0.081 | 5.09 | 9.89 |
| 18.5 | 5.0 | 0.000 | 0.00 | 4.80 |
| 23.5 | 5.0 | 0.000 | 0.00 | 4.80 |
| 28.5 | 5.0 | 0.000 | 0.00 | 4.80 |
| 33.5 | 5.0 | 0.000 | 0.00 | 4.80 |
| 38.5 | 5.0 | 0.000 | 0.00 | 4.80 |
| 43.5 | 5.0 | 0.034 | 2.03 | 4.80 |
| 48.5 | 5.0 | 0.046 | 2.78 | 2.78 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 133.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 143.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 148.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 151.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:51 PM |
| Boring Designation: | B-10 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | -2 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 83.1 |
| Distance from sample hammer to ground surface (ft): | 7 |
| Borehole Diameter (in) | 4 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.14 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 0 | SC | 41 | 100 | | |
| 2 | 2.0 | 0 | SC | 41 | 100 | | |
| 3 | 4.0 | 6 | SC | 41 | 100 | | |
| 4 | 6.0 | 2 | SP-SM | 8 | 100 | | |
| 5 | 8.0 | 2 | SP-SM | 8 | 100 | | |
| 6 | 10.0 | 2 | ML | 57 | 95 | | Clay |
| 7 | 13.0 | 0 | ML | 57 | 95 | | Clay |
| 8 | 18.0 | 0 | ML | 57 | 95 | | Clay |
| 9 | 23.0 | 0 | ML | 57 | 95 | | Clay |
| 10 | 28.5 | 0 | ML | 57 | 95 | | Clay |
| 11 | 33.5 | 0 | ML | 57 | 95 | | Clay |
| 12 | 38.5 | 1 | ML | 57 | 95 | | Clay |
| 13 | 44.0 | 6 | SP-SM | 6 | 100 | | |
| 14 | 49.0 | 17 | SP-SM | 6 | 100 | | |
| 15 | 54.5 | 3 | SM | 31 | 120 | | Clay |
| 16 | 59.5 | 6 | SM | 31 | 120 | | Clay |
| 17 | 64.5 | 5 | SM | 31 | 120 | | Clay |
| 18 | 69.5 | 8 | SM | 31 | 120 | | Clay |
| 19 | 74.5 | 7 | SM | 15 | 120 | | Clay |
| 20 | 79.5 | 11 | SM | 15 | 120 | | Clay |
| 21 | 84.5 | 13 | SM | 15 | 120 | | Clay |
| 22 | 89.5 | 16 | SM | 15 | 120 | | Clay |
| 23 | 94.5 | 7 | SM | 15 | 120 | | Clay |
| 24 | 99.5 | 11 | SM | 15 | 120 | | Clay |
| 25 | 104.5 | 7 | SM | 15 | 120 | | Clay |
| 26 | 109.5 | 7 | SM | 15 | 120 | | Clay |
| 27 | 114.5 | 9 | SM | 15 | 120 | | Clay |
| 28 | 119.5 | 6 | SM | 15 | 120 | | Clay |
| 29 | 124.5 | 3 | SM | 15 | 120 | | Clay |
| 30 | 128.0 | 6 | SM | 15 | 120 | | Clay |
| 31 | 133.0 | 5 | SM | 15 | 120 | | Clay |
| 32 | 140.0 | 8 | SM | 15 | 120 | | Clay |
| 33 | 145.0 | 13 | SM | 15 | 120 | | Clay |
| 34 | 150.0 | 10 | SM | 15 | 120 | | Clay |
| 35 | 155.5 | 7 | SM | 15 | 120 | | Clay |
| 36 | 160.0 | 7 | SM | 15 | 120 | | Clay |
| 37 | 165.0 | 16 | SM | 15 | 120 | | Clay |
| 38 | 170.0 | 9 | SM | 15 | 120 | | Clay |
| 39 | 175.0 | 10 | SM | 15 | 120 | | Clay |
| 40 | 180.0 | 18 | SM | 15 | 120 | | Clay |
| 41 | 185.0 | 37 | SM | 15 | 120 | | Clay |
| 42 | 189.5 | 10 | SM | 15 | 120 | | Clay |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 0.0 | SC | 41.0 | 100.0 | | 175 | 19 | 1.39 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.58 | 5.58 | 1.005 | 0.851 |
| 2 | 2.0 | 0.0 | SC | 41.1 | 100.0 | | 325 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 5.59 | 5.59 | 1.002 | 0.394 |
| 3 | 4.0 | 6.0 | SC | 41.0 | 100.0 | | 525 | 150 | 1.39 | 1.00 | 0.80 | 1.00 | 6.65 | 1.70 | 11.30 | 5.58 | 16.89 | 0.997 | 0.316 |
| 4 | 6.0 | 2.0 | SP-SM | 7.9 | 100.0 | | 725 | 226 | 1.39 | 1.00 | 0.80 | 1.00 | 2.22 | 1.70 | 3.77 | 0.34 | 4.11 | 0.991 | 0.290 |
| 5 | 8.0 | 2.0 | SP-SM | 8.0 | 100.0 | | 925 | 301 | 1.39 | 1.00 | 0.85 | 1.00 | 2.35 | 1.70 | 4.00 | 0.37 | 4.37 | 0.985 | 0.276 |
| 6 | 10.0 | 2.0 | ML | 57.0 | 95.0 | Clay | 1115 | 366 | 1.39 | 1.00 | 0.85 | 1.00 | 2.35 | 1.70 | 4.00 | 5.61 | 9.61 | 0.978 | 0.271 |
| 7 | 13.0 | 0.0 | ML | 57.0 | 95.0 | Clay | 1400 | 464 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 0.968 | 0.266 |
| 8 | 18.0 | 0.0 | ML | 57.2 | 95.0 | Clay | 1875 | 627 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 0.949 | 0.258 |
| 9 | 23.0 | 0.0 | ML | 57.0 | 95.0 | Clay | 2350 | 790 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 0.928 | 0.251 |
| 10 | 28.5 | 0.0 | ML | 57.0 | 95.0 | Clay | 2872 | 969 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.60 | 0.00 | 5.61 | 5.61 | 0.903 | 0.244 |
| 11 | 33.5 | 0.0 | ML | 57.0 | 95.0 | Clay | 3347 | 1132 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.46 | 0.00 | 5.61 | 5.61 | 0.879 | 0.237 |
| 12 | 38.5 | 1.0 | ML | 57.0 | 95.0 | Clay | 3822 | 1295 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.33 | 1.84 | 5.61 | 7.44 | 0.855 | 0.230 |
| 13 | 44.0 | 6.0 | SP-SM | 6.0 | 100.0 | | 4372 | 1502 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 1.20 | 10.00 | 0.03 | 10.03 | 0.827 | 0.219 |
| 14 | 49.0 | 17.0 | SP-SM | 6.0 | 100.0 | | 4872 | 1690 | 1.39 | 1.00 | 1.00 | 1.00 | 23.55 | 1.09 | 25.73 | 0.03 | 25.76 | 0.803 | 0.211 |
| 15 | 54.5 | 3.0 | SM | 31.0 | 120.0 | Clay | 5532 | 2007 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.03 | 4.28 | 5.40 | 9.68 | 0.776 | 0.195 |
| 16 | 59.5 | 6.0 | SM | 31.0 | 120.0 | Clay | 6132 | 2295 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.96 | 7.98 | 5.40 | 13.38 | 0.752 | 0.183 |
| 17 | 64.5 | 5.0 | SM | 31.0 | 120.0 | Clay | 6732 | 2583 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.90 | 6.24 | 5.40 | 11.64 | 0.729 | 0.173 |
| 18 | 69.5 | 8.0 | SM | 31.0 | 120.0 | Clay | 7332 | 2871 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.86 | 9.55 | 5.40 | 14.95 | 0.708 | 0.164 |
| 19 | 74.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 7932 | 3159 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.81 | 7.85 | 3.26 | 11.11 | 0.687 | 0.157 |
| 20 | 79.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 8532 | 3447 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.79 | 12.03 | 3.26 | 15.29 | 0.668 | 0.151 |
| 21 | 84.5 | 13.0 | SM | 15.0 | 120.0 | Clay | 9132 | 3735 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.77 | 13.81 | 3.26 | 17.07 | 0.651 | 0.145 |
| 22 | 89.5 | 16.0 | SM | 15.0 | 120.0 | Clay | 9732 | 4023 | 1.39 | 1.00 | 1.00 | 1.00 | 22.16 | 0.75 | 16.69 | 3.26 | 19.96 | 0.636 | 0.140 |
| 23 | 94.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 10332 | 4311 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.68 | 6.59 | 3.26 | 9.85 | 0.622 | 0.136 |
| 24 | 99.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 10932 | 4599 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.68 | 10.33 | 3.26 | 13.59 | 0.611 | 0.132 |
| 25 | 104.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 11532 | 4887 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.63 | 6.12 | 3.26 | 9.39 | 0.602 | 0.129 |
| 26 | 109.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 12132 | 5175 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.61 | 5.92 | 3.26 | 9.18 | 0.594 | 0.127 |
| 27 | 114.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 12732 | 5463 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.60 | 7.53 | 3.26 | 10.79 | 0.589 | 0.125 |
| 28 | 119.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 13332 | 5751 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.57 | 4.71 | 3.26 | 7.98 | 0.587 | 0.124 |
| 29 | 124.5 | 3.0 | SM | 15.0 | 120.0 | Clay | 13932 | 6039 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 0.53 | 2.20 | 3.26 | 5.47 | 0.586 | 0.123 |
| 30 | 128.0 | 6.0 | SM | 15.0 | 120.0 | Clay | 14352 | 6240 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.54 | 4.48 | 3.26 | 7.75 | 0.587 | 0.123 |
| 31 | 133.0 | 5.0 | SM | 15.0 | 120.0 | Clay | 14952 | 6528 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.52 | 3.59 | 3.26 | 6.85 | 0.591 | 0.123 |
| 32 | 140.0 | 8.0 | SM | 15.0 | 120.0 | Clay | 15792 | 6932 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.52 | 5.75 | 3.26 | 9.01 | 0.600 | 0.124 |
| 33 | 145.0 | 13.0 | SM | 15.0 | 120.0 | Clay | 16392 | 7220 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.54 | 9.65 | 3.26 | 12.91 | 0.610 | 0.126 |
| 34 | 150.0 | 10.0 | SM | 15.0 | 120.0 | Clay | 16992 | 7508 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.51 | 7.01 | 3.26 | 10.27 | 0.622 | 0.128 |
| 35 | 155.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 17652 | 7824 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.48 | 4.61 | 3.26 | 7.87 | 0.639 | 0.131 |
| 36 | 160.0 | 7.0 | SM | 15.0 | 120.0 | Clay | 18192 | 8084 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.47 | 4.52 | 3.26 | 7.78 | 0.655 | 0.134 |
| 37 | 165.0 | 16.0 | SM | 15.0 | 120.0 | Clay | 18792 | 8372 | 1.39 | 1.00 | 1.00 | 1.00 | 22.16 | 0.51 | 11.28 | 3.26 | 14.54 | 0.675 | 0.138 |
| 38 | 170.0 | 9.0 | SM | 15.0 | 120.0 | Clay | 19392 | 8660 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.46 | 5.71 | 3.26 | 8.97 | 0.697 | 0.142 |
| 39 | 175.0 | 10.0 | SM | 15.0 | 120.0 | Clay | 19992 | 8948 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.45 | 6.30 | 3.26 | 9.56 | 0.722 | 0.147 |
| 40 | 180.0 | 18.0 | SM | 15.0 | 120.0 | Clay | 20592 | 9236 | 1.39 | 1.00 | 1.00 | 1.00 | 24.93 | 0.49 | 12.26 | 3.26 | 15.53 | 0.750 | 0.152 |
| 41 | 185.0 | 37.0 | SM | 15.0 | 120.0 | Clay | 21192 | 9524 | 1.39 | 1.00 | 1.00 | 1.00 | 51.25 | 0.60 | 30.98 | 3.26 | 34.24 | 0.780 | 0.158 |
| 42 | 189.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 21732 | 9783 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.43 | 5.96 | 3.26 | 9.22 | 0.808 | 0.163 |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.099 | 0.12 |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.099 | 0.25 |
| 1.38 | 1.03 | 1.10 | 0.173 | 0.195 | 0.62 |
| 1.11 | 1.01 | 1.10 | 0.081 | 0.090 | 0.31 |
| 1.11 | 1.01 | 1.10 | 0.083 | 0.091 | 0.33 |
| 1.18 | 1.01 | 1.10 | 0.115 | 0.128 | 2.00 |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.09 | 0.090 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.08 | 0.090 | 0.097 | 2.00 |
| 1.12 | 1.01 | 1.06 | 0.090 | 0.096 | 2.00 |
| 1.12 | 1.01 | 1.05 | 0.090 | 0.095 | 2.00 |
| 1.15 | 1.01 | 1.04 | 0.101 | 0.106 | 2.00 |
| 1.19 | 1.01 | 1.03 | 0.118 | 0.124 | 0.56 |
| 1.76 | 1.05 | 1.04 | 0.309 | 0.337 | 1.60 |
| 1.18 | 1.01 | 1.00 | 0.116 | 0.118 | 2.00 |
| 1.27 | 1.02 | 0.99 | 0.143 | 0.144 | 2.00 |
| 1.23 | 1.02 | 0.98 | 0.130 | 0.129 | 2.00 |
| 1.32 | 1.02 | 0.97 | 0.156 | 0.154 | 2.00 |
| 1.21 | 1.01 | 0.96 | 0.126 | 0.123 | 2.00 |
| 1.33 | 1.02 | 0.95 | 0.159 | 0.153 | 2.00 |
| 1.38 | 1.03 | 0.93 | 0.175 | 0.167 | 2.00 |
| 1.49 | 1.03 | 0.91 | 0.205 | 0.194 | 2.00 |
| 1.19 | 1.01 | 0.93 | 0.117 | 0.111 | 2.00 |
| 1.28 | 1.02 | 0.92 | 0.145 | 0.135 | 2.00 |
| 1.18 | 1.01 | 0.92 | 0.114 | 0.107 | 2.00 |
| 1.17 | 1.01 | 0.92 | 0.112 | 0.105 | 2.00 |
| 1.21 | 1.01 | 0.91 | 0.124 | 0.114 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.104 | 0.097 | 2.00 |
| 1.12 | 1.01 | 0.92 | 0.089 | 0.082 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.103 | 0.094 | 2.00 |
| 1.14 | 1.01 | 0.91 | 0.097 | 0.089 | 2.00 |
| 1.17 | 1.01 | 0.89 | 0.111 | 0.101 | 2.00 |
| 1.26 | 1.02 | 0.87 | 0.139 | 0.124 | 2.00 |
| 1.20 | 1.01 | 0.88 | 0.120 | 0.107 | 2.00 |
| 1.15 | 1.01 | 0.89 | 0.104 | 0.093 | 2.00 |
| 1.15 | 1.01 | 0.89 | 0.103 | 0.092 | 2.00 |
| 1.30 | 1.02 | 0.85 | 0.152 | 0.132 | 2.00 |
| 1.17 | 1.01 | 0.87 | 0.111 | 0.098 | 2.00 |
| 1.18 | 1.01 | 0.87 | 0.115 | 0.101 | 2.00 |
| 1.33 | 1.02 | 0.83 | 0.161 | 0.137 | 2.00 |
| 2.20 | 1.08 | 0.62 | 0.952 | 0.640 | 2.00 |
| 1.18 | 1.01 | 0.86 | 0.113 | 0.098 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.050 | 0.75 | 7.60 |
| 2 | 1.8 | 0.050 | 1.05 | 6.85 |
| 4 | 2.0 | 0.026 | 0.63 | 5.79 |
| 6 | 2.0 | 0.057 | 1.36 | 5.16 |
| 8 | 2.0 | 0.055 | 1.33 | 3.80 |
| 10 | 2.5 | 0.000 | 0.00 | 2.47 |
| 13 | 4.0 | 0.000 | 0.00 | 2.47 |
| 18 | 5.0 | 0.000 | 0.00 | 2.47 |
| 23 | 5.3 | 0.000 | 0.00 | 2.47 |
| 28.5 | 5.3 | 0.000 | 0.00 | 2.47 |
| 33.5 | 5.0 | 0.000 | 0.00 | 2.47 |
| 38.5 | 5.3 | 0.000 | 0.00 | 2.47 |
| 44 | 5.3 | 0.037 | 2.35 | 2.47 |
| 49 | 5.3 | 0.002 | 0.12 | 0.12 |
| 54.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 59.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 64.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 69.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 74.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 79.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 84.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 89.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 94.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 99.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 104.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 109.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 114.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 119.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 124.5 | 4.3 | 0.000 | 0.00 | 0.00 |
| 128 | 4.3 | 0.000 | 0.00 | 0.00 |
| 133 | 6.0 | 0.000 | 0.00 | 0.00 |
| 140 | 6.0 | 0.000 | 0.00 | 0.00 |
| 145 | 5.0 | 0.000 | 0.00 | 0.00 |
| 150 | 5.3 | 0.000 | 0.00 | 0.00 |
| 155.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 160 | 4.8 | 0.000 | 0.00 | 0.00 |
| 165 | 5.0 | 0.000 | 0.00 | 0.00 |
| 170 | 5.0 | 0.000 | 0.00 | 0.00 |
| 175 | 5.0 | 0.000 | 0.00 | 0.00 |
| 180 | 5.0 | 0.000 | 0.00 | 0.00 |
| 185 | 4.8 | 0.000 | 0.00 | 0.00 |
| 189.5 | 3.8 | 0.000 | 0.00 | 0.00 |
| 192.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:52 PM |
| Boring Designation: | B-11 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | -22 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 83.1 |
| Distance from sample hammer to ground surface (ft): | 27 |
| Borehole Diameter (in) | 4 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.14 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 0 | ML | 50 | 95 | | Clay |
| 2 | 2.0 | 1 | ML | 50 | 95 | | Clay |
| 3 | 4.0 | 0 | SM | 18 | 100 | | |
| 4 | 6.0 | 0 | CL | 52 | 95 | | Clay |
| 5 | 8.0 | 0 | SM | 15 | 100 | | |
| 6 | 14.5 | 0 | MH | 94 | 95 | | Clay |
| 7 | 20.0 | 0 | MH | 94 | 95 | | Clay |
| 8 | 25.5 | 2 | SM | 15 | 100 | | |
| 9 | 31.5 | 7 | SM | 15 | 100 | | |
| 10 | 36.0 | 6 | ML | 50 | 120 | | Clay |
| 11 | 41.5 | 5 | ML | 50 | 120 | | Clay |
| 12 | 46.5 | 7 | ML | 50 | 120 | | Clay |
| 13 | 51.5 | 7 | ML | 50 | 120 | | Clay |
| 14 | 56.5 | 23 | SM | 15 | 120 | | Clay |
| 15 | 61.0 | 6 | SM | 45 | 120 | | Clay |
| 16 | 65.5 | 5 | SM | 15 | 120 | | Clay |
| 17 | 70.5 | 5 | SM | 15 | 120 | | Clay |
| 18 | 75.0 | 6 | SM | 15 | 120 | | Clay |
| 19 | 78.0 | 5 | SM | 15 | 120 | | Clay |
| 20 | 82.5 | 27 | SM | 15 | 120 | | Clay |
| 21 | 85.0 | 1 | SM | 15 | 120 | | Clay |
| 22 | 90.0 | 8 | SM | 15 | 120 | | Clay |
| 23 | 98.5 | 9 | SM | 15 | 120 | | Clay |
| 24 | 104.0 | 11 | SM | 15 | 120 | | Clay |
| 25 | 110.0 | 8 | SM | 15 | 120 | | Clay |
| 26 | 115.5 | 10 | SM | 15 | 120 | | Clay |
| 27 | 121.5 | 8 | SM | 15 | 120 | | Clay |
| 28 | 125.5 | 10 | SM | 15 | 120 | | Clay |
| 29 | 132.0 | 9 | SM | 15 | 120 | | Clay |
| 30 | 137.0 | 10 | SM | 15 | 120 | | Clay |
| 31 | 141.5 | 12 | SM | 15 | 120 | | Clay |
| 32 | 146.0 | 10 | SM | 15 | 120 | | Clay |
| 33 | 150.5 | 8 | SM | 15 | 120 | | Clay |
| 34 | 155.0 | 19 | SM | 15 | 120 | | Clay |
| 35 | 159.5 | 10 | SM | 15 | 120 | | Clay |
| 36 | 164.0 | 9 | SM | 15 | 120 | | Clay |
| 37 | 168.5 | 9 | SM | 15 | 120 | | Clay |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 0.0 | ML | 50.0 | 95.0 | Clay | 1420 | 16 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 1.005 | 7.972 |
| 2 | 2.0 | 1.0 | ML | 50.0 | 95.0 | Clay | 1563 | 65 | 1.39 | 1.00 | 0.95 | 1.00 | 1.32 | 1.70 | 2.24 | 5.61 | 7.85 | 1.002 | 2.185 |
| 3 | 4.0 | 0.0 | SM | 18.1 | 100.0 | | 1763 | 140 | 1.39 | 1.00 | 0.95 | 1.00 | 0.00 | 1.70 | 0.00 | 4.11 | 4.11 | 0.997 | 1.139 |
| 4 | 6.0 | 0.0 | CL | 52.1 | 95.0 | Clay | 1953 | 206 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.70 | 0.00 | 5.61 | 5.61 | 0.991 | 0.856 |
| 5 | 8.0 | 0.0 | SM | 15.3 | 100.0 | | 2153 | 281 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.70 | 0.00 | 3.36 | 3.36 | 0.985 | 0.687 |
| 6 | 14.5 | 0.0 | MH | 93.7 | 95.0 | Clay | 2770 | 493 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.70 | 0.00 | 5.50 | 5.50 | 0.962 | 0.492 |
| 7 | 20.0 | 0.0 | MH | 94.0 | 95.0 | Clay | 3293 | 672 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.70 | 0.00 | 5.50 | 5.50 | 0.941 | 0.419 |
| 8 | 25.5 | 2.0 | SM | 15.0 | 100.0 | | 3843 | 879 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.65 | 4.57 | 3.26 | 7.83 | 0.917 | 0.365 |
| 9 | 31.5 | 7.0 | SM | 15.0 | 100.0 | | 4443 | 1104 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 1.36 | 13.18 | 3.26 | 16.44 | 0.889 | 0.325 |
| 10 | 36.0 | 6.0 | ML | 50.0 | 120.0 | Clay | 4983 | 1364 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 1.23 | 10.25 | 5.61 | 15.87 | 0.867 | 0.288 |
| 11 | 41.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 5643 | 1680 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 1.12 | 7.78 | 5.61 | 13.39 | 0.840 | 0.257 |
| 12 | 46.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 6243 | 1968 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 1.04 | 10.04 | 5.61 | 15.65 | 0.815 | 0.235 |
| 13 | 51.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 6843 | 2256 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.97 | 9.40 | 5.61 | 15.01 | 0.790 | 0.218 |
| 14 | 56.5 | 23.0 | SM | 15.0 | 120.0 | Clay | 7443 | 2544 | 1.39 | 1.00 | 1.00 | 1.00 | 31.86 | 0.94 | 29.91 | 3.26 | 33.17 | 0.766 | 0.204 |
| 15 | 61.0 | 6.0 | SM | 45.3 | 120.0 | Clay | 7983 | 2804 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.87 | 7.20 | 5.61 | 12.81 | 0.745 | 0.193 |
| 16 | 65.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 8523 | 3063 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.81 | 5.64 | 3.26 | 8.90 | 0.725 | 0.184 |
| 17 | 70.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 9123 | 3351 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.77 | 5.36 | 3.26 | 8.62 | 0.703 | 0.174 |
| 18 | 75.0 | 6.0 | SM | 15.0 | 120.0 | Clay | 9663 | 3610 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.75 | 6.20 | 3.26 | 9.46 | 0.685 | 0.167 |
| 19 | 78.0 | 5.0 | SM | 15.0 | 120.0 | Clay | 10023 | 3783 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.72 | 4.99 | 3.26 | 8.25 | 0.674 | 0.162 |
| 20 | 82.5 | 27.0 | SM | 15.0 | 120.0 | Clay | 10563 | 4042 | 1.39 | 1.00 | 1.00 | 1.00 | 37.40 | 0.80 | 29.99 | 3.26 | 33.25 | 0.658 | 0.156 |
| 21 | 85.0 | 1.0 | SM | 15.0 | 120.0 | Clay | 10863 | 4186 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 0.65 | 0.90 | 3.26 | 4.16 | 0.650 | 0.153 |
| 22 | 90.0 | 8.0 | SM | 15.0 | 120.0 | Clay | 11463 | 4474 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.67 | 7.43 | 3.26 | 10.70 | 0.634 | 0.148 |
| 23 | 98.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 12483 | 4964 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.64 | 7.95 | 3.26 | 11.22 | 0.613 | 0.140 |
| 24 | 104.0 | 11.0 | SM | 15.0 | 120.0 | Clay | 13143 | 5280 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.63 | 9.57 | 3.26 | 12.83 | 0.602 | 0.136 |
| 25 | 110.0 | 8.0 | SM | 15.0 | 120.0 | Clay | 13863 | 5626 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.59 | 6.51 | 3.26 | 9.77 | 0.594 | 0.133 |
| 26 | 115.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 14523 | 5943 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.58 | 8.05 | 3.26 | 11.31 | 0.589 | 0.131 |
| 27 | 121.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 15243 | 6288 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.55 | 6.09 | 3.26 | 9.35 | 0.586 | 0.129 |
| 28 | 125.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 15723 | 6519 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.55 | 7.62 | 3.26 | 10.89 | 0.586 | 0.129 |
| 29 | 132.0 | 9.0 | SM | 15.0 | 120.0 | Clay | 16503 | 6893 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.53 | 6.56 | 3.26 | 9.82 | 0.590 | 0.129 |
| 30 | 137.0 | 10.0 | SM | 15.0 | 120.0 | Clay | 17103 | 7181 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.52 | 7.20 | 3.26 | 10.46 | 0.596 | 0.129 |
| 31 | 141.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 17643 | 7440 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.52 | 8.66 | 3.26 | 11.92 | 0.603 | 0.130 |
| 32 | 146.0 | 10.0 | SM | 15.0 | 120.0 | Clay | 18183 | 7700 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.50 | 6.90 | 3.26 | 10.16 | 0.612 | 0.132 |
| 33 | 150.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 18723 | 7959 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.48 | 5.28 | 3.26 | 8.54 | 0.624 | 0.133 |
| 34 | 155.0 | 19.0 | SM | 15.0 | 120.0 | Clay | 19263 | 8218 | 1.39 | 1.00 | 1.00 | 1.00 | 26.32 | 0.53 | 14.00 | 3.26 | 17.27 | 0.637 | 0.136 |
| 35 | 159.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 19803 | 8477 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.47 | 6.51 | 3.26 | 9.77 | 0.653 | 0.139 |
| 36 | 164.0 | 9.0 | SM | 15.0 | 120.0 | Clay | 20343 | 8736 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.46 | 5.68 | 3.26 | 8.94 | 0.670 | 0.142 |
| 37 | 168.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 20883 | 8996 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.45 | 5.58 | 3.26 | 8.84 | 0.690 | 0.146 |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.100 | 2.00 |
| 1.15 | 1.01 | 1.10 | 0.104 | 0.115 | 2.00 |
| 1.11 | 1.01 | 1.10 | 0.081 | 0.090 | 0.08 |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.100 | 2.00 |
| 1.10 | 1.01 | 1.10 | 0.077 | 0.085 | 0.12 |
| 1.12 | 1.01 | 1.10 | 0.089 | 0.099 | 2.00 |
| 1.12 | 1.01 | 1.09 | 0.089 | 0.098 | 2.00 |
| 1.15 | 1.01 | 1.07 | 0.103 | 0.112 | 0.31 |
| 1.36 | 1.02 | 1.08 | 0.169 | 0.186 | 0.57 |
| 1.34 | 1.02 | 1.05 | 0.164 | 0.176 | 2.00 |
| 1.27 | 1.02 | 1.02 | 0.143 | 0.149 | 2.00 |
| 1.34 | 1.02 | 1.01 | 0.162 | 0.167 | 2.00 |
| 1.32 | 1.02 | 0.99 | 0.156 | 0.158 | 2.00 |
| 2.20 | 1.08 | 0.96 | 0.782 | 0.809 | 2.00 |
| 1.26 | 1.02 | 0.97 | 0.139 | 0.137 | 2.00 |
| 1.17 | 1.01 | 0.97 | 0.111 | 0.108 | 2.00 |
| 1.16 | 1.01 | 0.96 | 0.109 | 0.105 | 2.00 |
| 1.18 | 1.01 | 0.95 | 0.114 | 0.110 | 2.00 |
| 1.16 | 1.01 | 0.95 | 0.106 | 0.102 | 2.00 |
| 2.20 | 1.08 | 0.85 | 0.792 | 0.725 | 2.00 |
| 1.11 | 1.01 | 0.95 | 0.081 | 0.078 | 2.00 |
| 1.21 | 1.01 | 0.93 | 0.123 | 0.116 | 2.00 |
| 1.22 | 1.01 | 0.92 | 0.127 | 0.118 | 2.00 |
| 1.26 | 1.02 | 0.91 | 0.139 | 0.128 | 2.00 |
| 1.19 | 1.01 | 0.91 | 0.116 | 0.107 | 2.00 |
| 1.22 | 1.01 | 0.90 | 0.127 | 0.116 | 2.00 |
| 1.18 | 1.01 | 0.90 | 0.114 | 0.104 | 2.00 |
| 1.21 | 1.01 | 0.89 | 0.124 | 0.113 | 2.00 |
| 1.19 | 1.01 | 0.89 | 0.117 | 0.106 | 2.00 |
| 1.20 | 1.01 | 0.89 | 0.121 | 0.109 | 2.00 |
| 1.23 | 1.02 | 0.88 | 0.132 | 0.117 | 2.00 |
| 1.19 | 1.01 | 0.88 | 0.119 | 0.106 | 2.00 |
| 1.16 | 1.01 | 0.88 | 0.108 | 0.097 | 2.00 |
| 1.39 | 1.03 | 0.84 | 0.176 | 0.152 | 2.00 |
| 1.19 | 1.01 | 0.87 | 0.116 | 0.103 | 2.00 |
| 1.17 | 1.01 | 0.87 | 0.111 | 0.098 | 2.00 |
| 1.17 | 1.01 | 0.87 | 0.110 | 0.097 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.000 | 0.00 | 9.12 |
| 2 | 1.8 | 0.000 | 0.00 | 9.12 |
| 4 | 2.0 | 0.057 | 1.36 | 9.12 |
| 6 | 2.0 | 0.000 | 0.00 | 7.75 |
| 8 | 4.3 | 0.061 | 3.11 | 7.75 |
| 14.5 | 6.0 | 0.000 | 0.00 | 4.64 |
| 20 | 5.5 | 0.000 | 0.00 | 4.64 |
| 25.5 | 5.8 | 0.043 | 2.95 | 4.64 |
| 31.5 | 5.3 | 0.027 | 1.69 | 1.69 |
| 36 | 5.0 | 0.000 | 0.00 | 0.00 |
| 41.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 46.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 51.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 56.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 61 | 4.5 | 0.000 | 0.00 | 0.00 |
| 65.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 70.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 75 | 3.8 | 0.000 | 0.00 | 0.00 |
| 78 | 3.8 | 0.000 | 0.00 | 0.00 |
| 82.5 | 3.5 | 0.000 | 0.00 | 0.00 |
| 85 | 3.8 | 0.000 | 0.00 | 0.00 |
| 90 | 6.8 | 0.000 | 0.00 | 0.00 |
| 98.5 | 7.0 | 0.000 | 0.00 | 0.00 |
| 104 | 5.8 | 0.000 | 0.00 | 0.00 |
| 110 | 5.8 | 0.000 | 0.00 | 0.00 |
| 115.5 | 5.8 | 0.000 | 0.00 | 0.00 |
| 121.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 125.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 132 | 5.8 | 0.000 | 0.00 | 0.00 |
| 137 | 4.8 | 0.000 | 0.00 | 0.00 |
| 141.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 146 | 4.5 | 0.000 | 0.00 | 0.00 |
| 150.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 155 | 4.5 | 0.000 | 0.00 | 0.00 |
| 159.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 164 | 4.5 | 0.000 | 0.00 | 0.00 |
| 168.5 | 3.8 | 0.000 | 0.00 | 0.00 |
| 171.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 5:38 PM |
| **Boring Designation:** | B-12 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | -33 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 83.1 |
| **Distance from sample hammer to ground surface (ft):** | 38 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.12 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 1 | CL | 50 | 95 | | Clay |
| 2 | 2.0 | 4 | CL | 50 | 95 | | Clay |
| 3 | 4.0 | 3 | SM | 24 | 100 | | |
| 4 | 6.0 | 9 | SC | 15 | 100 | | |
| 5 | 8.0 | 4 | SP | 0 | 100 | | |
| 6 | 12.5 | 5 | SP-SM | 10 | 100 | | |
| 7 | 17.5 | 7 | SM | 48 | 120 | | Clay |
| 8 | 23.0 | 8 | SM | 48 | 120 | | Clay |
| 9 | 28.0 | 4 | SM | 48 | 120 | | Clay |
| 10 | 36.5 | 6 | SM | 48 | 120 | | Clay |
| 11 | 42.0 | 9 | SM | 48 | 120 | | Clay |
| 12 | 47.0 | 6 | SM | 47 | 120 | | Clay |
| 13 | 53.0 | 8 | SM | 47 | 120 | | Clay |
| 14 | 58.0 | 12 | SM | 15 | 120 | | Clay |
| 15 | 63.5 | 11 | SM | 50 | 120 | | Clay |
| 16 | 69.0 | 9 | SM | 15 | 120 | | Clay |
| 17 | 73.5 | 12 | SM | 15 | 120 | | Clay |
| 18 | 77.5 | 8 | SM | 15 | 120 | | Clay |
| 19 | 82.5 | 5 | SM | 15 | 120 | | Clay |
| 20 | 87.5 | | SM | 15 | 120 | | Clay |
| 21 | 92.5 | 14 | SM | 15 | 120 | | Clay |
| 22 | 97.5 | 12 | SM | 15 | 120 | | Clay |
| 23 | 102.5 | 7 | SM | 15 | 120 | | Clay |
| 24 | 108.0 | 12 | SM | 15 | 120 | | Clay |
| 25 | 115.5 | 8 | SM | 15 | 120 | | Clay |
| 26 | 118.5 | 11 | SM | 15 | 120 | | Clay |
| 27 | 122.5 | 9 | SM | 15 | 120 | | Clay |
| 28 | 127.0 | 19 | SM | 15 | 120 | | Clay |
| 29 | 132.0 | 10 | SM | 15 | 120 | | Clay |
| 30 | 137.0 | 8 | SM | 15 | 120 | | Clay |
| 31 | 141.5 | 20 | SM | 15 | 120 | | Clay |
| 32 | 147.0 | | SM | 15 | 120 | | Clay |
| 33 | 152.5 | 12 | SM | 15 | 120 | | Clay |
| 34 | 157.5 | 8 | SM | 15 | 120 | | Clay |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 1.0 | CL | 50.0 | 95.0 | Clay | 2107 | 16 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.70 | 2.35 | 5.61 | 7.97 | 1.005 | 10.136 |
| 2 | 2.0 | 4.0 | CL | 50.0 | 95.0 | Clay | 2249 | 65 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.70 | 9.42 | 5.61 | 15.03 | 1.002 | 2.696 |
| 3 | 4.0 | 3.0 | SM | 23.8 | 100.0 | | 2449 | 140 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.70 | 7.06 | 4.97 | 12.03 | 0.997 | 1.356 |
| 4 | 6.0 | 9.0 | SC | 15.0 | 100.0 | | 2649 | 216 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 1.70 | 21.19 | 3.26 | 24.45 | 0.991 | 0.950 |
| 5 | 8.0 | 4.0 | SP | 0.0 | 100.0 | | 2849 | 291 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.70 | 9.42 | 0.00 | 9.42 | 0.985 | 0.753 |
| 6 | 12.5 | 5.0 | SP-SM | 10.4 | 100.0 | | 3299 | 460 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 1.70 | 11.77 | 1.33 | 13.11 | 0.970 | 0.542 |
| 7 | 17.5 | 7.0 | SM | 48.0 | 120.0 | Clay | 3899 | 748 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 1.57 | 15.22 | 5.61 | 20.83 | 0.951 | 0.387 |
| 8 | 23.0 | 8.0 | SM | 48.0 | 120.0 | Clay | 4559 | 1065 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 1.35 | 14.95 | 5.61 | 20.56 | 0.928 | 0.310 |
| 9 | 28.0 | 4.0 | SM | 48.0 | 120.0 | Clay | 5159 | 1353 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.26 | 6.96 | 5.61 | 12.58 | 0.905 | 0.269 |
| 10 | 36.5 | 6.0 | SM | 48.0 | 120.0 | Clay | 6179 | 1842 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 1.07 | 8.90 | 5.61 | 14.51 | 0.865 | 0.226 |
| 11 | 42.0 | 9.0 | SM | 48.0 | 120.0 | Clay | 6839 | 2159 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.99 | 12.35 | 5.61 | 17.96 | 0.837 | 0.207 |
| 12 | 47.0 | 6.0 | SM | 46.6 | 120.0 | Clay | 7439 | 2447 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.93 | 7.72 | 5.61 | 13.33 | 0.813 | 0.193 |
| 13 | 53.0 | 8.0 | SM | 47.0 | 120.0 | Clay | 8159 | 2793 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.87 | 9.69 | 5.61 | 15.30 | 0.783 | 0.178 |
| 14 | 58.0 | 12.0 | SM | 15.0 | 120.0 | Clay | 8759 | 3081 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.84 | 13.95 | 3.26 | 17.22 | 0.759 | 0.168 |
| 15 | 63.5 | 11.0 | SM | 49.7 | 120.0 | Clay | 9419 | 3398 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.80 | 12.26 | 5.61 | 17.87 | 0.734 | 0.159 |
| 16 | 69.0 | 9.0 | SM | 15.0 | 120.0 | Clay | 10079 | 3714 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.75 | 9.35 | 3.26 | 12.61 | 0.710 | 0.150 |
| 17 | 73.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 10619 | 3974 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.74 | 12.27 | 3.26 | 15.53 | 0.691 | 0.144 |
| 18 | 77.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 11099 | 4204 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.70 | 7.70 | 3.26 | 10.96 | 0.676 | 0.139 |
| 19 | 82.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 11699 | 4492 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.65 | 4.51 | 3.26 | 7.77 | 0.658 | 0.134 |
| 20 | 87.5 | 0.0 | SM | 15.0 | 120.0 | Clay | 12299 | 4780 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 0.59 | 0.00 | 3.26 | 3.26 | 0.642 | 0.129 |
| 21 | 92.5 | 14.0 | SM | 15.0 | 120.0 | Clay | 12899 | 5068 | 1.39 | 1.00 | 1.00 | 1.00 | 19.39 | 0.66 | 12.79 | 3.26 | 16.05 | 0.628 | 0.125 |
| 22 | 97.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 13499 | 5356 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.63 | 10.45 | 3.26 | 13.71 | 0.615 | 0.121 |
| 23 | 102.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 14099 | 5644 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.58 | 5.62 | 3.26 | 8.89 | 0.605 | 0.118 |
| 24 | 108.0 | 12.0 | SM | 15.0 | 120.0 | Clay | 14759 | 5961 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.59 | 9.84 | 3.26 | 13.10 | 0.596 | 0.115 |
| 25 | 115.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 15659 | 6393 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.54 | 6.03 | 3.26 | 9.29 | 0.589 | 0.112 |
| 26 | 118.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 16019 | 6566 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.55 | 8.44 | 3.26 | 11.70 | 0.587 | 0.112 |
| 27 | 122.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 16499 | 6796 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.53 | 6.62 | 3.26 | 9.88 | 0.586 | 0.111 |
| 28 | 127.0 | 19.0 | SM | 15.0 | 120.0 | Clay | 17039 | 7055 | 1.39 | 1.00 | 1.00 | 1.00 | 26.32 | 0.58 | 15.24 | 3.26 | 18.50 | 0.587 | 0.111 |
| 29 | 132.0 | 10.0 | SM | 15.0 | 120.0 | Clay | 17639 | 7343 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.51 | 7.10 | 3.26 | 10.36 | 0.590 | 0.111 |
| 30 | 137.0 | 8.0 | SM | 15.0 | 120.0 | Clay | 18239 | 7631 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.49 | 5.42 | 3.26 | 8.68 | 0.596 | 0.111 |
| 31 | 141.5 | 20.0 | SM | 15.0 | 120.0 | Clay | 18779 | 7890 | 1.39 | 1.00 | 1.00 | 1.00 | 27.70 | 0.55 | 15.25 | 3.26 | 18.51 | 0.603 | 0.112 |
| 32 | 147.0 | 0.0 | SM | 15.0 | 120.0 | Clay | 19439 | 8207 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 0.42 | 0.00 | 3.26 | 3.26 | 0.615 | 0.114 |
| 33 | 152.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 20099 | 8524 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.48 | 7.98 | 3.26 | 11.24 | 0.629 | 0.116 |
| 34 | 157.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 20699 | 8812 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.45 | 4.96 | 3.26 | 8.22 | 0.645 | 0.118 |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.15 | 1.01 | 1.10 | 0.104 | 0.116 | 2.00 |
| 1.32 | 1.02 | 1.10 | 0.156 | 0.176 | 2.00 |
| 1.24 | 1.02 | 1.10 | 0.133 | 0.148 | 0.11 |
| 1.69 | 1.05 | 1.10 | 0.278 | 0.320 | 0.34 |
| 1.18 | 1.01 | 1.10 | 0.114 | 0.127 | 0.17 |
| 1.26 | 1.02 | 1.10 | 0.141 | 0.158 | 0.29 |
| 1.53 | 1.04 | 1.10 | 0.216 | 0.247 | 2.00 |
| 1.52 | 1.04 | 1.09 | 0.213 | 0.241 | 2.00 |
| 1.25 | 1.02 | 1.05 | 0.137 | 0.145 | 2.00 |
| 1.30 | 1.02 | 1.02 | 0.152 | 0.157 | 2.00 |
| 1.42 | 1.03 | 1.00 | 0.183 | 0.188 | 2.00 |
| 1.27 | 1.02 | 0.98 | 0.143 | 0.143 | 2.00 |
| 1.33 | 1.02 | 0.97 | 0.159 | 0.157 | 2.00 |
| 1.39 | 1.03 | 0.95 | 0.176 | 0.172 | 2.00 |
| 1.41 | 1.03 | 0.94 | 0.182 | 0.177 | 2.00 |
| 1.25 | 1.02 | 0.94 | 0.137 | 0.131 | 2.00 |
| 1.33 | 1.02 | 0.93 | 0.161 | 0.153 | 2.00 |
| 1.21 | 1.01 | 0.93 | 0.125 | 0.118 | 2.00 |
| 1.15 | 1.01 | 0.94 | 0.103 | 0.098 | 2.00 |
| 1.10 | 1.01 | 0.94 | 0.077 | 0.073 | 2.00 |
| 1.35 | 1.02 | 0.90 | 0.165 | 0.152 | 2.00 |
| 1.28 | 1.02 | 0.90 | 0.146 | 0.134 | 2.00 |
| 1.17 | 1.01 | 0.91 | 0.110 | 0.102 | 2.00 |
| 1.26 | 1.02 | 0.89 | 0.141 | 0.128 | 2.00 |
| 1.18 | 1.01 | 0.90 | 0.113 | 0.103 | 2.00 |
| 1.23 | 1.02 | 0.89 | 0.130 | 0.118 | 2.00 |
| 1.19 | 1.01 | 0.89 | 0.117 | 0.106 | 2.00 |
| 1.43 | 1.03 | 0.85 | 0.189 | 0.165 | 2.00 |
| 1.20 | 1.01 | 0.88 | 0.121 | 0.108 | 2.00 |
| 1.17 | 1.01 | 0.89 | 0.109 | 0.098 | 2.00 |
| 1.44 | 1.03 | 0.83 | 0.189 | 0.162 | 2.00 |
| 1.10 | 1.01 | 0.91 | 0.077 | 0.070 | 2.00 |
| 1.22 | 1.01 | 0.87 | 0.127 | 0.111 | 2.00 |
| 1.16 | 1.01 | 0.88 | 0.106 | 0.094 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.000 | 0.00 | 4.57 |
| 2 | 1.8 | 0.000 | 0.00 | 4.57 |
| 4 | 2.0 | 0.033 | 0.80 | 4.57 |
| 6 | 2.0 | 0.019 | 0.46 | 3.77 |
| 8 | 3.3 | 0.039 | 1.51 | 3.31 |
| 12.5 | 4.8 | 0.032 | 1.80 | 1.80 |
| 17.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 23 | 5.3 | 0.000 | 0.00 | 0.00 |
| 28 | 6.8 | 0.000 | 0.00 | 0.00 |
| 36.5 | 7.0 | 0.000 | 0.00 | 0.00 |
| 42 | 5.3 | 0.000 | 0.00 | 0.00 |
| 47 | 5.5 | 0.000 | 0.00 | 0.00 |
| 53 | 5.5 | 0.000 | 0.00 | 0.00 |
| 58 | 5.3 | 0.000 | 0.00 | 0.00 |
| 63.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 69 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 4.3 | 0.000 | 0.00 | 0.00 |
| 77.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 82.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 87.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 92.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 97.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 102.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 108 | 6.5 | 0.000 | 0.00 | 0.00 |
| 115.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 118.5 | 3.5 | 0.000 | 0.00 | 0.00 |
| 122.5 | 4.3 | 0.000 | 0.00 | 0.00 |
| 127 | 4.8 | 0.000 | 0.00 | 0.00 |
| 132 | 5.0 | 0.000 | 0.00 | 0.00 |
| 137 | 4.8 | 0.000 | 0.00 | 0.00 |
| 141.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 147 | 5.5 | 0.000 | 0.00 | 0.00 |
| 152.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 157.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 160.5 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 5:39 PM |
| **Boring Designation:** | B-13 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | -28 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 83.1 |
| **Distance from sample hammer to ground surface (ft):** | 33 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.12 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" | |
|---|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 1 | SM | 23 | 100 | | | |
| 2 | 2.0 | 3 | SM | 23 | 100 | | | |
| 3 | 4.0 | 3 | SM | 23 | 100 | | | |
| 4 | 6.0 | 3 | SM | 23 | 100 | | | |
| 5 | 8.0 | 1 | SC | 15 | 100 | | | |
| 6 | 14.5 | 1 | CL | 64 | 95 | | Clay | |
| 7 | 19.5 | 0 | CL | 64 | 95 | | Clay | |
| 8 | 24.5 | 2 | ML | 65 | 95 | | | |
| 9 | 30.0 | 6 | SC | 44 | 120 | | Clay | *Assumes Marl/Limestone NonLiq |
| 10 | 35.5 | 4 | SC | 44 | 120 | | Clay | |
| 11 | 41.0 | 6 | SC | 44 | 120 | | Clay | |
| 12 | 48.5 | 6 | ML | 50 | 120 | | Clay | |
| 13 | 53.5 | 7 | ML | 50 | 120 | | Clay | |
| 14 | 58.5 | 4 | ML | 50 | 120 | | Clay | |
| 15 | 62.5 | 23 | ML | 50 | 120 | | Clay | |
| 16 | 66.5 | 7 | ML | 50 | 120 | | Clay | |
| 17 | 71.5 | 7 | ML | 50 | 120 | | Clay | |
| 18 | 76.0 | 10 | ML | 50 | 120 | | Clay | |
| 19 | 81.0 | 6 | ML | 50 | 120 | | Clay | |
| 20 | 88.5 | 6 | ML | 50 | 120 | | Clay | |
| 21 | 93.5 | 12 | ML | 50 | 120 | | Clay | |
| 22 | 99.0 | 11 | ML | 50 | 120 | | Clay | |
| 23 | 104.5 | 7 | ML | 50 | 120 | | Clay | |
| 24 | 110.0 | 9 | ML | 50 | 120 | | Clay | |
| 25 | 118.0 | 8 | ML | 50 | 120 | | Clay | |
| 26 | 120.0 | 8 | ML | 50 | 120 | | Clay | |
| 27 | 124.5 | 7 | ML | 50 | 120 | | Clay | |
| 28 | 129.0 | 8 | ML | 50 | 120 | | Clay | |
| 29 | 134.0 | 10 | ML | 50 | 120 | | Clay | |
| 30 | 138.5 | 9 | ML | 50 | 120 | | Clay | |
| 31 | 144.0 | 12 | ML | 50 | 120 | | Clay | |
| 32 | 149.5 | 7 | ML | 50 | 120 | | Clay | |
| 33 | 155.5 | 13 | ML | 50 | 120 | | Clay | |
| 34 | 161.0 | 17 | ML | 50 | 120 | | Clay | |
| 35 | | | | | | | | |
| 36 | | | | | | | | |
| 37 | | | | | | | | |
| 38 | | | | | | | | |
| 39 | | | | | | | | |
| 40 | | | | | | | | |
| 41 | | | | | | | | |
| 42 | | | | | | | | |
| 43 | | | | | | | | |
| 44 | | | | | | | | |
| 45 | | | | | | | | |
| 46 | | | | | | | | |
| 47 | | | | | | | | |
| 48 | | | | | | | | |
| 49 | | | | | | | | |
| 50 | | | | | | | | |

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 1.0 | SM | 23.0 | 100.0 | | 1797 | 19 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.70 | 2.35 | 4.88 | 7.24 | 1.005 | 7.497 |
| 2 | 2.0 | 3.0 | SM | 23.0 | 100.0 | | 1947 | 75 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.70 | 7.06 | 4.88 | 11.95 | 1.002 | 2.023 |
| 3 | 4.0 | 3.0 | SM | 22.8 | 100.0 | | 2147 | 150 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.70 | 7.06 | 4.86 | 11.93 | 0.997 | 1.110 |
| 4 | 6.0 | 3.0 | SM | 23.0 | 100.0 | | 2347 | 226 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.70 | 7.06 | 4.88 | 11.95 | 0.991 | 0.804 |
| 5 | 8.0 | 1.0 | SC | 15.0 | 100.0 | | 2547 | 301 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.70 | 2.35 | 3.26 | 5.62 | 0.985 | 0.650 |
| 6 | 14.5 | 1.0 | CL | 64.2 | 95.0 | Clay | 3165 | 513 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.70 | 2.35 | 5.59 | 7.95 | 0.962 | 0.463 |
| 7 | 19.5 | 0.0 | CL | 64.0 | 95.0 | Clay | 3640 | 676 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.70 | 0.00 | 5.59 | 5.59 | 0.943 | 0.396 |
| 8 | 24.5 | 2.0 | ML | 65.3 | 95.0 | | 4115 | 839 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.65 | 4.56 | 5.59 | 10.15 | 0.921 | 0.352 |
| 9 | 30.0 | 6.0 | SC | 44.0 | 120.0 | Clay | 4775 | 1156 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 1.33 | 11.05 | 5.60 | 16.65 | 0.896 | 0.289 |
| 10 | 35.5 | 4.0 | SC | 43.9 | 120.0 | Clay | 5435 | 1472 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.21 | 6.68 | 5.60 | 12.28 | 0.869 | 0.250 |
| 11 | 41.0 | 6.0 | SC | 44.0 | 120.0 | Clay | 6095 | 1789 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 1.09 | 9.02 | 5.60 | 14.62 | 0.842 | 0.224 |
| 12 | 48.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 6995 | 2221 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.98 | 8.11 | 5.61 | 13.73 | 0.805 | 0.198 |
| 13 | 53.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 7595 | 2509 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.92 | 8.92 | 5.61 | 14.53 | 0.781 | 0.184 |
| 14 | 58.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 8195 | 2797 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 0.86 | 4.77 | 5.61 | 10.38 | 0.757 | 0.173 |
| 15 | 62.5 | 23.0 | ML | 50.0 | 120.0 | Clay | 8675 | 3028 | 1.39 | 1.00 | 1.00 | 1.00 | 31.86 | 0.89 | 28.23 | 5.61 | 33.85 | 0.738 | 0.165 |
| 16 | 66.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 9155 | 3258 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.80 | 7.80 | 5.61 | 13.42 | 0.720 | 0.158 |
| 17 | 71.5 | 7.0 | ML | 50.2 | 120.0 | Clay | 9755 | 3546 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.77 | 7.47 | 5.61 | 13.08 | 0.699 | 0.150 |
| 18 | 76.0 | 10.0 | ML | 50.0 | 120.0 | Clay | 10295 | 3805 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.76 | 10.48 | 5.61 | 16.09 | 0.681 | 0.144 |
| 19 | 81.0 | 6.0 | ML | 50.0 | 120.0 | Clay | 10895 | 4093 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.71 | 5.88 | 5.61 | 11.50 | 0.663 | 0.138 |
| 20 | 88.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 11795 | 4525 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.67 | 5.57 | 5.61 | 11.18 | 0.639 | 0.130 |
| 21 | 93.5 | 12.0 | ML | 50.0 | 120.0 | Clay | 12395 | 4813 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.68 | 11.31 | 5.61 | 16.93 | 0.625 | 0.126 |
| 22 | 99.0 | 11.0 | ML | 50.0 | 120.0 | Clay | 13055 | 5130 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.65 | 9.95 | 5.61 | 15.57 | 0.612 | 0.121 |
| 23 | 104.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 13715 | 5447 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.61 | 5.91 | 5.61 | 11.53 | 0.602 | 0.118 |
| 24 | 110.0 | 9.0 | ML | 50.0 | 120.0 | Clay | 14375 | 5764 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.60 | 7.51 | 5.61 | 13.12 | 0.594 | 0.116 |
| 25 | 118.0 | 8.0 | ML | 50.0 | 120.0 | Clay | 15335 | 6224 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.57 | 6.33 | 5.61 | 11.95 | 0.587 | 0.113 |
| 26 | 120.0 | 8.0 | ML | 50.0 | 120.0 | Clay | 15575 | 6340 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.57 | 6.27 | 5.61 | 11.88 | 0.587 | 0.112 |
| 27 | 124.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 16115 | 6599 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.55 | 5.30 | 5.61 | 10.92 | 0.586 | 0.112 |
| 28 | 129.0 | 8.0 | ML | 50.0 | 120.0 | Clay | 16655 | 6858 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.54 | 6.00 | 5.61 | 11.61 | 0.588 | 0.111 |
| 29 | 134.0 | 10.0 | ML | 50.0 | 120.0 | Clay | 17255 | 7146 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.54 | 7.48 | 5.61 | 13.10 | 0.592 | 0.112 |
| 30 | 138.5 | 9.0 | ML | 50.0 | 120.0 | Clay | 17795 | 7405 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.52 | 6.53 | 5.61 | 12.14 | 0.598 | 0.112 |
| 31 | 144.0 | 12.0 | ML | 50.0 | 120.0 | Clay | 18455 | 7722 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.53 | 8.78 | 5.61 | 14.40 | 0.608 | 0.113 |
| 32 | 149.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 19115 | 8039 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.49 | 4.73 | 5.61 | 10.35 | 0.621 | 0.115 |
| 33 | 155.5 | 13.0 | ML | 50.0 | 120.0 | Clay | 19835 | 8384 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.51 | 9.19 | 5.61 | 14.80 | 0.639 | 0.118 |
| 34 | 161.0 | 17.0 | ML | 50.0 | 120.0 | Clay | 20495 | 8701 | 1.39 | 1.00 | 1.00 | 1.00 | 23.55 | 0.52 | 12.31 | 5.61 | 17.92 | 0.658 | 0.121 |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.14 | 1.01 | 1.10 | 0.100 | 0.111 | 0.01 |
| 1.23 | 1.02 | 1.10 | 0.132 | 0.148 | 0.07 |
| 1.23 | 1.02 | 1.10 | 0.132 | 0.147 | 0.13 |
| 1.23 | 1.02 | 1.10 | 0.132 | 0.148 | 0.18 |
| 1.12 | 1.01 | 1.10 | 0.090 | 0.100 | 0.15 |
| 1.15 | 1.01 | 1.10 | 0.104 | 0.116 | 2.00 |
| 1.12 | 1.01 | 1.09 | 0.090 | 0.098 | 2.00 |
| 1.19 | 1.01 | 1.09 | 0.119 | 0.131 | 0.37 |
| 1.37 | 1.03 | 1.07 | 0.171 | 0.187 | 2.00 |
| 1.24 | 1.02 | 1.04 | 0.135 | 0.142 | 2.00 |
| 1.31 | 1.02 | 1.02 | 0.153 | 0.159 | 2.00 |
| 1.28 | 1.02 | 0.99 | 0.146 | 0.148 | 2.00 |
| 1.30 | 1.02 | 0.98 | 0.152 | 0.152 | 2.00 |
| 1.20 | 1.01 | 0.97 | 0.121 | 0.119 | 2.00 |
| 2.20 | 1.08 | 0.91 | 0.883 | 0.871 | 2.00 |
| 1.27 | 1.02 | 0.95 | 0.143 | 0.139 | 2.00 |
| 1.26 | 1.02 | 0.95 | 0.141 | 0.136 | 2.00 |
| 1.35 | 1.02 | 0.93 | 0.166 | 0.158 | 2.00 |
| 1.22 | 1.02 | 0.94 | 0.129 | 0.122 | 2.00 |
| 1.22 | 1.01 | 0.93 | 0.126 | 0.119 | 2.00 |
| 1.38 | 1.03 | 0.90 | 0.173 | 0.160 | 2.00 |
| 1.33 | 1.02 | 0.90 | 0.161 | 0.148 | 2.00 |
| 1.22 | 1.02 | 0.91 | 0.129 | 0.119 | 2.00 |
| 1.26 | 1.02 | 0.90 | 0.141 | 0.129 | 2.00 |
| 1.23 | 1.02 | 0.89 | 0.132 | 0.120 | 2.00 |
| 1.23 | 1.02 | 0.89 | 0.132 | 0.119 | 2.00 |
| 1.21 | 1.01 | 0.89 | 0.125 | 0.113 | 2.00 |
| 1.23 | 1.02 | 0.88 | 0.130 | 0.116 | 2.00 |
| 1.26 | 1.02 | 0.87 | 0.141 | 0.125 | 2.00 |
| 1.24 | 1.02 | 0.87 | 0.134 | 0.119 | 2.00 |
| 1.30 | 1.02 | 0.86 | 0.151 | 0.133 | 2.00 |
| 1.20 | 1.01 | 0.88 | 0.121 | 0.107 | 2.00 |
| 1.31 | 1.02 | 0.85 | 0.154 | 0.134 | 2.00 |
| 1.41 | 1.03 | 0.83 | 0.183 | 0.155 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.044 | 0.67 | 7.87 |
| 2 | 1.8 | 0.034 | 0.70 | 7.20 |
| 4 | 2.0 | 0.034 | 0.81 | 6.50 |
| 6 | 2.0 | 0.034 | 0.80 | 5.69 |
| 8 | 4.3 | 0.050 | 2.55 | 4.89 |
| 14.5 | 5.8 | 0.000 | 0.00 | 2.33 |
| 19.5 | 5.0 | 0.000 | 0.00 | 2.33 |
| 24.5 | 5.3 | 0.037 | 2.33 | 2.33 |
| 30 | 5.5 | 0.000 | 0.00 | 0.00 |
| 35.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 41 | 6.5 | 0.000 | 0.00 | 0.00 |
| 48.5 | 6.3 | 0.000 | 0.00 | 0.00 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 62.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 66.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 71.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 76 | 4.8 | 0.000 | 0.00 | 0.00 |
| 81 | 6.3 | 0.000 | 0.00 | 0.00 |
| 88.5 | 6.3 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 99 | 5.5 | 0.000 | 0.00 | 0.00 |
| 104.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 110 | 6.8 | 0.000 | 0.00 | 0.00 |
| 118 | 5.0 | 0.000 | 0.00 | 0.00 |
| 120 | 3.3 | 0.000 | 0.00 | 0.00 |
| 124.5 | 4.5 | 0.000 | 0.00 | 0.00 |
| 129 | 4.8 | 0.000 | 0.00 | 0.00 |
| 134 | 4.8 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 144 | 5.5 | 0.000 | 0.00 | 0.00 |
| 149.5 | 5.8 | 0.000 | 0.00 | 0.00 |
| 155.5 | 5.8 | 0.000 | 0.00 | 0.00 |
| 161 | 4.3 | 0.000 | 0.00 | 0.00 |
| 164 | | | | |

| | |
|---|---|
| **Project:** | Harbor River Bridge |
| **Owner:** | SC DOT |
| **Job Number:** | 18461-007-00 |
| **Analysis by:** | ZAS |
| **Date/Time:** | 9/29/17 5:44 PM |
| **Boring Designation:** | B-14 |
| **Checked by:** | CDL |

**Sampling Information**

| | |
|---|---|
| **Depth to Groundwater (ft):** | 0 |
| **SPT Liner (Yes/No):** | No |
| **Hammer Energy, %:** | 83.1 |
| **Distance from sample hammer to ground surface (ft):** | 5 |
| **Borehole Diameter (in)** | 4 |

**Earthquake Information**

| | |
|---|---|
| **Max Acceleration (g) :** | 0.12 |
| **Earthquake Magnitude:** | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 1 | SM | 14 | 100 | | |
| 2 | 2.0 | 2 | SM | 14 | 100 | | |
| 3 | 4.0 | 4 | SM | 14 | 100 | | |
| 4 | 6.0 | 25 | SM | 14 | 120 | | |
| 5 | 8.0 | 3 | SM | 14 | 100 | | |
| 6 | 13.5 | 16 | SM | 14 | 120 | | |
| 7 | 18.5 | 5 | SM | 14 | 100 | | |
| 8 | 23.5 | 9 | SM | 18 | 100 | | |
| 9 | 28.5 | 2 | SM | 44 | 100 | | |
| 10 | 33.5 | 4 | ML | 52 | 95 | | Clay |
| 11 | 38.5 | 2 | ML | 52 | 95 | | Clay |
| 12 | 43.5 | 2 | ML | 52 | 95 | | Clay |
| 13 | 48.5 | 4 | SM | 30 | 100 | | |
| 14 | 53.5 | 9 | ML | 50 | 120 | | Clay |
| 15 | 58.5 | 4 | ML | 50 | 120 | | Clay |
| 16 | 63.0 | 7 | ML | 50 | 120 | | Clay |
| 17 | 68.0 | 7 | ML | 50 | 120 | | Clay |
| 18 | 72.5 | 7 | ML | 50 | 120 | | Clay |
| 19 | 77.5 | 13 | SC | 15 | 120 | | Clay |
| 20 | 83.5 | 9 | SC | 15 | 120 | | Clay |
| 21 | 88.5 | 5 | SC | 15 | 120 | | Clay |
| 22 | 93.5 | 26 | SC | 15 | 120 | | Clay |
| 23 | 98.5 | 8 | ML | 50 | 120 | | Clay |
| 24 | 104.0 | 4 | ML | 50 | 120 | | Clay |
| 25 | 108.5 | 5 | ML | 50 | 120 | | Clay |
| 26 | 113.5 | 6 | ML | 50 | 120 | | Clay |
| 27 | 118.5 | 9 | ML | 50 | 120 | | Clay |
| 28 | 123.5 | 8 | SM | 15 | 120 | | Clay |
| 29 | 128.5 | 6 | SM | 15 | 120 | | Clay |
| 30 | 133.0 | 5 | SM | 15 | 120 | | Clay |
| 31 | 138.0 | 11 | SM | 15 | 120 | | Clay |
| 32 | 142.5 | 9 | SM | 15 | 120 | | Clay |
| 33 | 148.5 | 8 | SM | 15 | 120 | | Clay |
| 34 | 153.5 | 9 | SM | 15 | 120 | | Clay |
| 35 | 158.5 | 9 | SM | 15 | 120 | | Clay |
| 36 | 163.5 | 7 | SM | 15 | 120 | | Clay |
| 37 | 168.5 | 8 | SM | 15 | 120 | | Clay |
| 38 | 173.5 | 8 | SM | 15 | 120 | | Clay |
| 39 | 178.5 | 6 | SM | 15 | 120 | | Clay |
| 40 | 183.5 | 8 | SM | 15 | 120 | | Clay |
| 41 | 188.5 | 6 | SM | 15 | 120 | | Clay |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 1.0 | SM | 14.0 | 100.0 | | 50 | 19 | 1.39 | 1.00 | 0.75 | 1.00 | 1.04 | 1.70 | 1.77 | 2.91 | 4.67 | 1.005 | 0.209 |
| 2 | 2.0 | 2.0 | SM | 14.0 | 100.0 | | 200 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 2.08 | 1.70 | 3.53 | 2.91 | 6.44 | 1.002 | 0.208 |
| 3 | 4.0 | 4.0 | SM | 14.0 | 100.0 | | 400 | 150 | 1.39 | 1.00 | 0.75 | 1.00 | 4.16 | 1.70 | 7.06 | 2.91 | 9.97 | 0.997 | 0.207 |
| 4 | 6.0 | 25.0 | SM | 14.0 | 120.0 | | 640 | 266 | 1.39 | 1.00 | 0.80 | 1.00 | 27.70 | 1.70 | 47.09 | 2.91 | 50.00 | 0.991 | 0.186 |
| 5 | 8.0 | 3.0 | SM | 13.8 | 100.0 | | 840 | 341 | 1.39 | 1.00 | 0.80 | 1.00 | 3.32 | 1.70 | 5.65 | 2.83 | 8.48 | 0.985 | 0.189 |
| 6 | 13.5 | 16.0 | SM | 14.0 | 120.0 | | 1500 | 658 | 1.39 | 1.00 | 0.85 | 1.00 | 18.84 | 1.51 | 28.48 | 2.91 | 31.39 | 0.966 | 0.172 |
| 7 | 18.5 | 5.0 | SM | 14.0 | 100.0 | | 2000 | 846 | 1.39 | 1.00 | 0.95 | 1.00 | 6.58 | 1.59 | 10.44 | 2.91 | 13.35 | 0.947 | 0.175 |
| 8 | 23.5 | 9.0 | SM | 17.6 | 100.0 | | 2500 | 1034 | 1.39 | 1.00 | 0.95 | 1.00 | 11.84 | 1.37 | 16.22 | 4.00 | 20.21 | 0.926 | 0.175 |
| 9 | 28.5 | 2.0 | SM | 43.7 | 100.0 | | 3000 | 1222 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.35 | 3.75 | 5.60 | 9.35 | 0.903 | 0.173 |
| 10 | 33.5 | 4.0 | ML | 52.0 | 95.0 | Clay | 3475 | 1385 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.24 | 6.88 | 5.61 | 12.50 | 0.879 | 0.172 |
| 11 | 38.5 | 2.0 | ML | 52.0 | 95.0 | Clay | 3950 | 1548 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.19 | 3.29 | 5.61 | 8.91 | 0.855 | 0.170 |
| 12 | 43.5 | 2.0 | ML | 52.0 | 95.0 | Clay | 4425 | 1711 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.13 | 3.12 | 5.61 | 8.73 | 0.830 | 0.167 |
| 13 | 48.5 | 4.0 | SM | 30.1 | 100.0 | | 4925 | 1899 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.06 | 5.87 | 5.37 | 11.23 | 0.805 | 0.163 |
| 14 | 53.5 | 9.0 | ML | 50.0 | 120.0 | Clay | 5525 | 2187 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.99 | 12.28 | 5.61 | 17.89 | 0.781 | 0.154 |
| 15 | 58.5 | 4.0 | ML | 50.0 | 120.0 | Clay | 6125 | 2475 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 0.92 | 5.10 | 5.61 | 10.71 | 0.757 | 0.146 |
| 16 | 63.0 | 7.0 | ML | 50.0 | 120.0 | Clay | 6665 | 2734 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.88 | 8.54 | 5.61 | 14.16 | 0.736 | 0.140 |
| 17 | 68.0 | 7.0 | ML | 50.0 | 120.0 | Clay | 7265 | 3022 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.84 | 8.11 | 5.61 | 13.73 | 0.714 | 0.134 |
| 18 | 72.5 | 7.0 | ML | 50.0 | 120.0 | Clay | 7805 | 3281 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.80 | 7.78 | 5.61 | 13.39 | 0.695 | 0.129 |
| 19 | 77.5 | 13.0 | SC | 15.0 | 120.0 | Clay | 8405 | 3569 | 1.39 | 1.00 | 1.00 | 1.00 | 18.01 | 0.78 | 14.13 | 3.26 | 17.39 | 0.676 | 0.124 |
| 20 | 83.5 | 9.0 | SC | 15.0 | 120.0 | Clay | 9125 | 3915 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.73 | 9.09 | 3.26 | 12.35 | 0.654 | 0.119 |
| 21 | 88.5 | 5.0 | SC | 15.0 | 120.0 | Clay | 9725 | 4203 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.68 | 4.69 | 3.26 | 7.95 | 0.639 | 0.115 |
| 22 | 93.5 | 26.0 | SC | 15.0 | 120.0 | Clay | 10325 | 4491 | 1.39 | 1.00 | 1.00 | 1.00 | 36.01 | 0.76 | 27.51 | 3.26 | 30.77 | 0.625 | 0.112 |
| 23 | 98.5 | 8.0 | ML | 50.0 | 120.0 | Clay | 10925 | 4779 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.66 | 7.33 | 5.61 | 12.94 | 0.613 | 0.109 |
| 24 | 104.0 | 4.0 | ML | 50.0 | 120.0 | Clay | 11585 | 5095 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 0.61 | 3.41 | 5.61 | 9.02 | 0.602 | 0.107 |
| 25 | 108.5 | 5.0 | ML | 50.0 | 120.0 | Clay | 12125 | 5355 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.60 | 4.18 | 5.61 | 9.80 | 0.596 | 0.105 |
| 26 | 113.5 | 6.0 | ML | 50.0 | 120.0 | Clay | 12725 | 5643 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.59 | 4.92 | 5.61 | 10.53 | 0.590 | 0.104 |
| 27 | 118.5 | 9.0 | ML | 50.0 | 120.0 | Clay | 13325 | 5931 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.59 | 7.39 | 5.61 | 13.01 | 0.587 | 0.103 |
| 28 | 123.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 13925 | 6219 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.55 | 6.13 | 3.26 | 9.39 | 0.586 | 0.102 |
| 29 | 128.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 14525 | 6507 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.53 | 4.37 | 3.26 | 7.63 | 0.588 | 0.102 |
| 30 | 133.0 | 5.0 | SM | 15.0 | 120.0 | Clay | 15065 | 6766 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.51 | 3.51 | 3.26 | 6.77 | 0.591 | 0.103 |
| 31 | 138.0 | 11.0 | SM | 15.0 | 120.0 | Clay | 15665 | 7054 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.53 | 8.10 | 3.26 | 11.36 | 0.597 | 0.103 |
| 32 | 142.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 16205 | 7313 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.51 | 6.33 | 3.26 | 9.59 | 0.605 | 0.105 |
| 33 | 148.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 16925 | 7659 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.49 | 5.41 | 3.26 | 8.67 | 0.618 | 0.107 |
| 34 | 153.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 17525 | 7947 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.48 | 6.02 | 3.26 | 9.28 | 0.632 | 0.109 |
| 35 | 158.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 18125 | 8235 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.47 | 5.89 | 3.26 | 9.15 | 0.649 | 0.111 |
| 36 | 163.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 18725 | 8523 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.45 | 4.37 | 3.26 | 7.63 | 0.668 | 0.115 |
| 37 | 168.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 19325 | 8811 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.45 | 4.96 | 3.26 | 8.22 | 0.690 | 0.118 |
| 38 | 173.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 19925 | 9099 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.44 | 4.86 | 3.26 | 8.12 | 0.715 | 0.122 |
| 39 | 178.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 20525 | 9387 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.42 | 3.48 | 3.26 | 6.74 | 0.741 | 0.126 |
| 40 | 183.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 21125 | 9675 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.42 | 4.68 | 3.26 | 7.94 | 0.771 | 0.131 |
| 41 | 188.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 21725 | 9963 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.40 | 3.35 | 3.26 | 6.61 | 0.802 | 0.136 |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.11 | 1.01 | 1.10 | 0.084 | 0.093 | 0.45 |
| 1.13 | 1.01 | 1.10 | 0.095 | 0.105 | 0.51 |
| 1.19 | 1.01 | 1.10 | 0.118 | 0.131 | 0.64 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.16 | 1.01 | 1.10 | 0.108 | 0.120 | 0.63 |
| 2.08 | 1.07 | 1.10 | 0.587 | 0.693 | 2.00 |
| 1.27 | 1.02 | 1.10 | 0.143 | 0.159 | 0.91 |
| 1.50 | 1.03 | 1.10 | 0.208 | 0.236 | 1.35 |
| 1.18 | 1.01 | 1.05 | 0.114 | 0.121 | 0.70 |
| 1.25 | 1.02 | 1.04 | 0.136 | 0.144 | 2.00 |
| 1.17 | 1.01 | 1.03 | 0.111 | 0.115 | 2.00 |
| 1.17 | 1.01 | 1.02 | 0.109 | 0.113 | 2.00 |
| 1.22 | 1.01 | 1.01 | 0.127 | 0.130 | 0.80 |
| 1.41 | 1.03 | 1.00 | 0.183 | 0.187 | 2.00 |
| 1.21 | 1.01 | 0.99 | 0.123 | 0.123 | 2.00 |
| 1.29 | 1.02 | 0.97 | 0.149 | 0.148 | 2.00 |
| 1.28 | 1.02 | 0.96 | 0.146 | 0.143 | 2.00 |
| 1.27 | 1.02 | 0.95 | 0.143 | 0.139 | 2.00 |
| 1.39 | 1.03 | 0.94 | 0.178 | 0.171 | 2.00 |
| 1.24 | 1.02 | 0.94 | 0.135 | 0.129 | 2.00 |
| 1.15 | 1.01 | 0.94 | 0.104 | 0.099 | 2.00 |
| 2.04 | 1.07 | 0.84 | 0.537 | 0.484 | 2.00 |
| 1.26 | 1.02 | 0.92 | 0.140 | 0.130 | 2.00 |
| 1.17 | 1.01 | 0.92 | 0.111 | 0.104 | 2.00 |
| 1.19 | 1.01 | 0.91 | 0.117 | 0.108 | 2.00 |
| 1.20 | 1.01 | 0.91 | 0.122 | 0.112 | 2.00 |
| 1.26 | 1.02 | 0.89 | 0.140 | 0.127 | 2.00 |
| 1.18 | 1.01 | 0.90 | 0.114 | 0.104 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.102 | 0.093 | 2.00 |
| 1.14 | 1.01 | 0.91 | 0.097 | 0.088 | 2.00 |
| 1.22 | 1.01 | 0.88 | 0.128 | 0.114 | 2.00 |
| 1.18 | 1.01 | 0.89 | 0.115 | 0.104 | 2.00 |
| 1.17 | 1.01 | 0.89 | 0.109 | 0.098 | 2.00 |
| 1.18 | 1.01 | 0.88 | 0.113 | 0.101 | 2.00 |
| 1.17 | 1.01 | 0.88 | 0.112 | 0.100 | 2.00 |
| 1.15 | 1.01 | 0.88 | 0.102 | 0.091 | 2.00 |
| 1.16 | 1.01 | 0.88 | 0.106 | 0.094 | 2.00 |
| 1.16 | 1.01 | 0.87 | 0.105 | 0.093 | 2.00 |
| 1.14 | 1.01 | 0.88 | 0.097 | 0.086 | 2.00 |
| 1.15 | 1.01 | 0.87 | 0.104 | 0.092 | 2.00 |
| 1.13 | 1.01 | 0.87 | 0.096 | 0.085 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.054 | 0.81 | 10.92 |
| 2 | 1.8 | 0.047 | 0.99 | 10.10 |
| 4 | 2.0 | 0.037 | 0.90 | 9.12 |
| 6 | 2.0 | 0.000 | 0.00 | 8.22 |
| 8 | 3.8 | 0.041 | 1.84 | 8.22 |
| 13.5 | 5.3 | 0.000 | 0.00 | 6.37 |
| 18.5 | 5.0 | 0.029 | 1.73 | 6.37 |
| 23.5 | 5.0 | 0.004 | 0.23 | 4.65 |
| 28.5 | 5.0 | 0.039 | 2.33 | 4.42 |
| 33.5 | 5.0 | 0.000 | 0.00 | 2.09 |
| 38.5 | 5.0 | 0.000 | 0.00 | 2.09 |
| 43.5 | 5.0 | 0.000 | 0.00 | 2.09 |
| 48.5 | 5.0 | 0.035 | 2.09 | 2.09 |
| 53.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 58.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 63 | 4.8 | 0.000 | 0.00 | 0.00 |
| 68 | 4.8 | 0.000 | 0.00 | 0.00 |
| 72.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 77.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 104 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 4.8 | 0.000 | 0.00 | 0.00 |
| 133 | 4.8 | 0.000 | 0.00 | 0.00 |
| 138 | 4.8 | 0.000 | 0.00 | 0.00 |
| 142.5 | 5.3 | 0.000 | 0.00 | 0.00 |
| 148.5 | 5.5 | 0.000 | 0.00 | 0.00 |
| 153.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 158.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 163.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 168.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 173.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 178.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 183.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 188.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 191.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:45 PM |
| Boring Designation: | B-15 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | 0 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 83.1 |
| Distance from sample hammer to ground surface (ft): | 5 |
| Borehole Diameter (in) | 4 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.12 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 0 | SP-SM | 5 | 100 | | |
| 2 | 2.0 | 2 | SP-SM | 5 | 100 | | |
| 3 | 4.0 | 16 | SP-SM | 8 | 120 | | |
| 4 | 6.0 | 17 | SP-SM | 5 | 120 | | |
| 5 | 8.0 | 14 | SP-SM | 5 | 120 | | |
| 6 | 13.5 | 25 | SP-SM | 6 | 120 | | |
| 7 | 18.5 | 7 | SM | 18 | 100 | | |
| 8 | 23.5 | 7 | SM | 18 | 100 | | |
| 9 | 28.5 | 4 | SM | 18 | 100 | | |
| 10 | 33.5 | 4 | SM | 18 | 100 | | |
| 11 | 38.5 | 0 | CL | 50 | 95 | | Clay |
| 12 | 43.5 | 0 | SM | 21 | 100 | | |
| 13 | 48.5 | 9 | SM | 21 | 100 | | |
| 14 | 53.5 | 14 | SM | 21 | 100 | | |
| 15 | 58.5 | 2 | SM | 21 | 100 | | |
| 16 | 63.5 | 6 | SM | 21 | 100 | | |
| 17 | 68.5 | 8 | SM | 15 | 120 | | Clay |
| 18 | 73.5 | 10 | SM | 15 | 120 | | Clay |
| 19 | 78.5 | 23 | SM | 15 | 120 | | Clay |
| 20 | 83.5 | 9 | SM | 15 | 120 | | Clay |
| 21 | 88.5 | 27 | SM | 15 | 120 | | Clay |
| 22 | 93.5 | 17 | SM | 15 | 120 | | Clay |
| 23 | 98.5 | 8 | SM | 15 | 120 | | Clay |
| 24 | 103.5 | 16 | SM | 15 | 120 | | Clay |
| 25 | 108.5 | 10 | SM | 15 | 120 | | Clay |
| 26 | 113.5 | 5 | SM | 15 | 120 | | Clay |
| 27 | 118.5 | 6 | SM | 15 | 120 | | Clay |
| 28 | 123.5 | 5 | SM | 15 | 120 | | Clay |
| 29 | 128.5 | 7 | SM | 15 | 120 | | Clay |
| 30 | 133.5 | 8 | SM | 15 | 120 | | Clay |
| 31 | 138.5 | 8 | SM | 15 | 120 | | Clay |
| 32 | 143.5 | 9 | ML | 50 | 120 | | Clay |
| 33 | 148.5 | 12 | SM | 15 | 120 | | Clay |
| 34 | | | | | | | |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 0.0 | SP-SM | 5.0 | 100.0 | | 50 | 19 | 1.39 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 0.00 | 0.00 | 1.005 | 0.209 |
| 2 | 2.0 | 2.0 | SP-SM | 5.0 | 100.0 | | 200 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 2.08 | 1.70 | 3.53 | 0.00 | 3.53 | 1.002 | 0.208 |
| 3 | 4.0 | 16.0 | SP-SM | 8.2 | 120.0 | | 440 | 190 | 1.39 | 1.00 | 0.75 | 1.00 | 16.62 | 1.70 | 28.25 | 0.43 | 28.68 | 0.997 | 0.180 |
| 4 | 6.0 | 17.0 | SP-SM | 5.1 | 120.0 | | 680 | 306 | 1.39 | 1.00 | 0.80 | 1.00 | 18.84 | 1.70 | 32.02 | 0.00 | 32.02 | 0.991 | 0.172 |
| 5 | 8.0 | 14.0 | SP-SM | 5.0 | 120.0 | | 920 | 421 | 1.39 | 1.00 | 0.80 | 1.00 | 15.51 | 1.70 | 26.37 | 0.00 | 26.37 | 0.985 | 0.168 |
| 6 | 13.5 | 25.0 | SP-SM | 5.5 | 120.0 | | 1580 | 738 | 1.39 | 1.00 | 0.85 | 1.00 | 29.43 | 1.37 | 40.24 | 0.01 | 40.25 | 0.966 | 0.161 |
| 7 | 18.5 | 7.0 | SM | 17.5 | 100.0 | | 2080 | 926 | 1.39 | 1.00 | 0.95 | 1.00 | 9.21 | 1.47 | 13.51 | 3.97 | 17.48 | 0.947 | 0.166 |
| 8 | 23.5 | 7.0 | SM | 18.0 | 100.0 | | 2580 | 1114 | 1.39 | 1.00 | 0.95 | 1.00 | 9.21 | 1.35 | 12.47 | 4.09 | 16.56 | 0.926 | 0.167 |
| 9 | 28.5 | 4.0 | SM | 18.0 | 100.0 | | 3080 | 1302 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.29 | 7.16 | 4.09 | 11.25 | 0.903 | 0.167 |
| 10 | 33.5 | 4.0 | SM | 18.0 | 100.0 | | 3580 | 1490 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.21 | 6.68 | 4.09 | 10.77 | 0.879 | 0.165 |
| 11 | 38.5 | 0.0 | CL | 50.0 | 95.0 | Clay | 4055 | 1653 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.16 | 0.00 | 5.61 | 5.61 | 0.855 | 0.164 |
| 12 | 43.5 | 0.0 | SM | 20.7 | 100.0 | | 4555 | 1841 | 1.39 | 1.00 | 1.00 | 1.00 | 0.00 | 1.09 | 0.00 | 4.59 | 4.59 | 0.830 | 0.160 |
| 13 | 48.5 | 9.0 | SM | 21.0 | 100.0 | | 5055 | 2029 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 1.02 | 12.71 | 4.63 | 17.34 | 0.805 | 0.156 |
| 14 | 53.5 | 14.0 | SM | 21.0 | 100.0 | | 5555 | 2217 | 1.39 | 1.00 | 1.00 | 1.00 | 19.39 | 0.98 | 19.02 | 4.63 | 23.66 | 0.781 | 0.153 |
| 15 | 58.5 | 2.0 | SM | 21.0 | 100.0 | | 6055 | 2405 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 0.93 | 2.57 | 4.63 | 7.21 | 0.757 | 0.149 |
| 16 | 63.5 | 6.0 | SM | 21.0 | 100.0 | | 6555 | 2593 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.90 | 7.48 | 4.63 | 12.12 | 0.734 | 0.145 |
| 17 | 68.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 7155 | 2881 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.85 | 9.47 | 3.26 | 12.73 | 0.712 | 0.138 |
| 18 | 73.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 7755 | 3169 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.82 | 11.36 | 3.26 | 14.62 | 0.691 | 0.132 |
| 19 | 78.5 | 23.0 | SM | 15.0 | 120.0 | Clay | 8355 | 3457 | 1.39 | 1.00 | 1.00 | 1.00 | 31.86 | 0.84 | 26.64 | 3.26 | 29.91 | 0.672 | 0.127 |
| 20 | 83.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 8955 | 3745 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.75 | 9.31 | 3.26 | 12.57 | 0.654 | 0.122 |
| 21 | 88.5 | 27.0 | SM | 15.0 | 120.0 | Clay | 9555 | 4033 | 1.39 | 1.00 | 1.00 | 1.00 | 37.40 | 0.80 | 30.01 | 3.26 | 33.27 | 0.639 | 0.118 |
| 22 | 93.5 | 17.0 | SM | 15.0 | 120.0 | Clay | 10155 | 4321 | 1.39 | 1.00 | 1.00 | 1.00 | 23.55 | 0.73 | 17.24 | 3.26 | 20.51 | 0.625 | 0.115 |
| 23 | 98.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 10755 | 4609 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.66 | 7.31 | 3.26 | 10.57 | 0.613 | 0.112 |
| 24 | 103.5 | 16.0 | SM | 15.0 | 120.0 | Clay | 11355 | 4897 | 1.39 | 1.00 | 1.00 | 1.00 | 22.16 | 0.68 | 15.13 | 3.26 | 18.39 | 0.603 | 0.109 |
| 25 | 108.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 11955 | 5185 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.63 | 8.70 | 3.26 | 11.97 | 0.596 | 0.107 |
| 26 | 113.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 12555 | 5473 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.58 | 4.00 | 3.26 | 7.26 | 0.590 | 0.106 |
| 27 | 118.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 13155 | 5761 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.57 | 4.71 | 3.26 | 7.97 | 0.587 | 0.105 |
| 28 | 123.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 13755 | 6049 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.54 | 3.76 | 3.26 | 7.03 | 0.586 | 0.104 |
| 29 | 128.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 14355 | 6337 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.54 | 5.25 | 3.26 | 8.51 | 0.588 | 0.104 |
| 30 | 133.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 14955 | 6625 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.53 | 5.90 | 3.26 | 9.17 | 0.592 | 0.104 |
| 31 | 138.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 15555 | 6913 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.52 | 5.75 | 3.26 | 9.02 | 0.598 | 0.105 |
| 32 | 143.5 | 9.0 | ML | 50.0 | 120.0 | Clay | 16155 | 7201 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.53 | 6.63 | 5.61 | 12.25 | 0.607 | 0.106 |
| 33 | 148.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 16755 | 7489 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.52 | 8.62 | 3.26 | 11.88 | 0.618 | 0.108 |
| 34 | | | | | | | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.09 | 1.01 | 1.10 | 0.061 | 0.067 | 0.32 |
| 1.10 | 1.01 | 1.10 | 0.078 | 0.086 | 0.42 |
| 1.92 | 1.06 | 1.10 | 0.414 | 0.483 | 2.00 |
| 2.12 | 1.08 | 1.10 | 0.647 | 0.766 | 2.00 |
| 1.79 | 1.05 | 1.10 | 0.327 | 0.379 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.40 | 1.03 | 1.10 | 0.179 | 0.202 | 1.22 |
| 1.37 | 1.02 | 1.08 | 0.170 | 0.187 | 1.12 |
| 1.22 | 1.01 | 1.05 | 0.127 | 0.135 | 0.81 |
| 1.21 | 1.01 | 1.03 | 0.123 | 0.129 | 0.79 |
| 1.12 | 1.01 | 1.02 | 0.090 | 0.092 | 2.00 |
| 1.11 | 1.01 | 1.01 | 0.084 | 0.085 | 0.53 |
| 1.39 | 1.03 | 1.01 | 0.177 | 0.183 | 1.17 |
| 1.65 | 1.04 | 0.99 | 0.261 | 0.271 | 1.78 |
| 1.14 | 1.01 | 0.99 | 0.099 | 0.099 | 0.67 |
| 1.24 | 1.02 | 0.98 | 0.133 | 0.133 | 0.92 |
| 1.25 | 1.02 | 0.97 | 0.138 | 0.136 | 2.00 |
| 1.31 | 1.02 | 0.96 | 0.153 | 0.149 | 2.00 |
| 1.99 | 1.07 | 0.90 | 0.479 | 0.461 | 2.00 |
| 1.25 | 1.02 | 0.94 | 0.137 | 0.131 | 2.00 |
| 2.20 | 1.08 | 0.85 | 0.796 | 0.729 | 2.00 |
| 1.51 | 1.03 | 0.90 | 0.212 | 0.198 | 2.00 |
| 1.20 | 1.01 | 0.93 | 0.122 | 0.115 | 2.00 |
| 1.43 | 1.03 | 0.89 | 0.188 | 0.173 | 2.00 |
| 1.23 | 1.02 | 0.91 | 0.132 | 0.122 | 2.00 |
| 1.14 | 1.01 | 0.92 | 0.100 | 0.093 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.104 | 0.096 | 2.00 |
| 1.14 | 1.01 | 0.91 | 0.098 | 0.091 | 2.00 |
| 1.16 | 1.01 | 0.90 | 0.108 | 0.099 | 2.00 |
| 1.17 | 1.01 | 0.90 | 0.112 | 0.102 | 2.00 |
| 1.17 | 1.01 | 0.89 | 0.111 | 0.101 | 2.00 |
| 1.24 | 1.02 | 0.88 | 0.134 | 0.120 | 2.00 |
| 1.23 | 1.02 | 0.87 | 0.132 | 0.117 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.118 | 1.77 | 16.41 |
| 2 | 1.8 | 0.060 | 1.26 | 14.64 |
| 4 | 2.0 | 0.000 | 0.00 | 13.38 |
| 6 | 2.0 | 0.000 | 0.00 | 13.38 |
| 8 | 3.8 | 0.000 | 0.00 | 13.38 |
| 13.5 | 5.3 | 0.000 | 0.00 | 13.38 |
| 18.5 | 5.0 | 0.005 | 0.33 | 13.38 |
| 23.5 | 5.0 | 0.007 | 0.45 | 13.05 |
| 28.5 | 5.0 | 0.035 | 2.09 | 12.60 |
| 33.5 | 5.0 | 0.036 | 2.15 | 10.51 |
| 38.5 | 5.0 | 0.000 | 0.00 | 8.37 |
| 43.5 | 5.0 | 0.054 | 3.27 | 8.37 |
| 48.5 | 5.0 | 0.006 | 0.38 | 5.10 |
| 53.5 | 5.0 | 0.001 | 0.05 | 4.72 |
| 58.5 | 5.0 | 0.045 | 2.67 | 4.67 |
| 63.5 | 5.0 | 0.033 | 1.99 | 1.99 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 133.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 143.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 148.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 151.5 | | | | |

| | |
|---|---|
| Project: | Harbor River Bridge |
| Owner: | SC DOT |
| Job Number: | 18461-007-00 |
| Analysis by: | ZAS |
| Date/Time: | 9/29/17 5:43 PM |
| Boring Designation: | B-16 |
| Checked by: | CDL |

**Sampling Information**

| | |
|---|---|
| Depth to Groundwater (ft): | 0 |
| SPT Liner (Yes/No): | No |
| Hammer Energy, %: | 83.1 |
| Distance from sample hammer to ground surface (ft): | 5 |
| Borehole Diameter (in) | 4 |

**Earthquake Information**

| | |
|---|---|
| Max Acceleration (g) : | 0.12 |
| Earthquake Magnitude: | 7.30 |

| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Thickness of Liquefiable Unit (ft) | Flag "Clay" "Unsaturated" "Unreliable" |
|---|---|---|---|---|---|---|---|
| 1 | 0.5 | 0 | SM | 15 | 100 | | |
| 2 | 2.0 | 5 | SM | 15 | 100 | | |
| 3 | 4.0 | 28 | SP | 2 | 120 | | |
| 4 | 6.0 | 22 | SP | 2 | 120 | | |
| 5 | 8.0 | 15 | SP | 2 | 120 | | |
| 6 | 13.5 | 29 | SP | 2 | 120 | | |
| 7 | 18.5 | 8 | SM | 14 | 100 | | |
| 8 | 23.5 | 5 | SM | 14 | 100 | | |
| 9 | 28.5 | 10 | SM | 14 | 100 | | |
| 10 | 33.5 | 4 | SM | 14 | 100 | | |
| 11 | 38.5 | 2 | SC | 47 | 100 | | |
| 12 | 43.5 | 3 | SM | 15 | 100 | | |
| 13 | 48.5 | 1 | MH | 91 | 100 | | Clay |
| 14 | 53.5 | 2 | MH | 91 | 100 | | Clay |
| 15 | 58.5 | 5 | SM | 15 | 100 | | |
| 16 | 63.5 | 8 | SM | 15 | 100 | | |
| 17 | 68.5 | 3 | CL | 50 | 95 | | Clay |
| 18 | 73.5 | 6 | SM | 15 | 120 | | Clay |
| 19 | 78.5 | 27 | SM | 15 | 120 | | Clay |
| 20 | 83.5 | 11 | SM | 15 | 120 | | Clay |
| 21 | 88.5 | 5 | SM | 15 | 120 | | Clay |
| 22 | 93.5 | 28 | SM | 15 | 120 | | Clay |
| 23 | 98.5 | 15 | SM | 15 | 120 | | Clay |
| 24 | 103.5 | 10 | SM | 15 | 120 | | Clay |
| 25 | 108.5 | 6 | SM | 15 | 120 | | Clay |
| 26 | 113.5 | 9 | SM | 15 | 120 | | Clay |
| 27 | 118.5 | 8 | SM | 15 | 120 | | Clay |
| 28 | 123.5 | 9 | SM | 15 | 120 | | Clay |
| 29 | 128.5 | 7 | SM | 15 | 120 | | Clay |
| 30 | 133.5 | 6 | SM | 15 | 120 | | Clay |
| 31 | 138.5 | 7 | SM | 15 | 120 | | Clay |
| 32 | 143.5 | 12 | SM | 15 | 120 | | Clay |
| 33 | 148.5 | 11 | SM | 15 | 120 | | Clay |
| 34 | | | | | | | Clay |
| 35 | | | | | | | |
| 36 | | | | | | | |
| 37 | | | | | | | |
| 38 | | | | | | | |
| 39 | | | | | | | |
| 40 | | | | | | | |
| 41 | | | | | | | |
| 42 | | | | | | | |
| 43 | | | | | | | |
| 44 | | | | | | | |
| 45 | | | | | | | |
| 46 | | | | | | | |
| 47 | | | | | | | |
| 48 | | | | | | | |
| 49 | | | | | | | |
| 50 | | | | | | | |

*Assumes Marl/Limestone NonLiq

| | | | | | | | | | $C_E$ | $C_B$ | $C_R$ | $C_S$ | $N_{60}$ | $C_N$ | $N_{1,60}$ | Fines Correction | N1,60cs | $r_d$ | CSR |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPT Sample Number | Depth (ft) | Measured N | Soil Type | Fines Content (%) | Unit Weight (pcf) | Flag "Clay" "Unsaturated" "Unreliable" | $\sigma_v$ (psf) | $\sigma_v'$ (psf) | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB | IB |
| 1 | 0.5 | 0.0 | SM | 15.0 | 100.0 | | 50 | 19 | 1.39 | 1.00 | 0.75 | 1.00 | 0.00 | 1.70 | 0.00 | 3.26 | 3.26 | 1.005 | 0.209 |
| 2 | 2.0 | 5.0 | SM | 15.0 | 100.0 | | 200 | 75 | 1.39 | 1.00 | 0.75 | 1.00 | 5.19 | 1.70 | 8.83 | 3.26 | 12.09 | 1.002 | 0.208 |
| 3 | 4.0 | 28.0 | SP | 2.0 | 120.0 | | 440 | 190 | 1.39 | 1.00 | 0.75 | 1.00 | 29.09 | 1.70 | 49.44 | 0.00 | 49.44 | 0.997 | 0.180 |
| 4 | 6.0 | 22.0 | SP | 2.1 | 120.0 | | 680 | 306 | 1.39 | 1.00 | 0.80 | 1.00 | 24.38 | 1.70 | 41.44 | 0.00 | 41.44 | 0.991 | 0.172 |
| 5 | 8.0 | 15.0 | SP | 2.0 | 120.0 | | 920 | 421 | 1.39 | 1.00 | 0.80 | 1.00 | 16.62 | 1.70 | 28.25 | 0.00 | 28.25 | 0.985 | 0.168 |
| 6 | 13.5 | 29.0 | SP | 2.1 | 120.0 | | 1580 | 738 | 1.39 | 1.00 | 0.85 | 1.00 | 34.14 | 1.33 | 45.25 | 0.00 | 45.25 | 0.966 | 0.161 |
| 7 | 18.5 | 8.0 | SM | 14.0 | 100.0 | | 2080 | 926 | 1.39 | 1.00 | 0.95 | 1.00 | 10.53 | 1.46 | 15.35 | 2.91 | 18.25 | 0.947 | 0.166 |
| 8 | 23.5 | 5.0 | SM | 13.9 | 100.0 | | 2580 | 1114 | 1.39 | 1.00 | 0.95 | 1.00 | 6.58 | 1.39 | 9.17 | 2.87 | 12.04 | 0.926 | 0.167 |
| 9 | 28.5 | 10.0 | SM | 14.0 | 100.0 | | 3080 | 1302 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 1.24 | 17.15 | 2.91 | 20.06 | 0.903 | 0.167 |
| 10 | 33.5 | 4.0 | SM | 14.0 | 100.0 | | 3580 | 1490 | 1.39 | 1.00 | 1.00 | 1.00 | 5.54 | 1.21 | 6.71 | 2.91 | 9.62 | 0.879 | 0.165 |
| 11 | 38.5 | 2.0 | SC | 46.6 | 100.0 | | 4080 | 1678 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 1.14 | 3.15 | 5.61 | 8.76 | 0.855 | 0.162 |
| 12 | 43.5 | 3.0 | SM | 15.0 | 100.0 | | 4580 | 1866 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 1.07 | 4.46 | 3.26 | 7.73 | 0.830 | 0.159 |
| 13 | 48.5 | 1.0 | MH | 91.0 | 100.0 | Clay | 5080 | 2054 | 1.39 | 1.00 | 1.00 | 1.00 | 1.39 | 1.02 | 1.41 | 5.51 | 6.92 | 0.805 | 0.155 |
| 14 | 53.5 | 2.0 | MH | 91.0 | 100.0 | Clay | 5580 | 2242 | 1.39 | 1.00 | 1.00 | 1.00 | 2.77 | 0.97 | 2.68 | 5.51 | 8.19 | 0.781 | 0.152 |
| 15 | 58.5 | 5.0 | SM | 15.0 | 100.0 | | 6080 | 2430 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.93 | 6.42 | 3.26 | 9.68 | 0.757 | 0.148 |
| 16 | 63.5 | 8.0 | SM | 15.0 | 100.0 | | 6580 | 2618 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.90 | 9.95 | 3.26 | 13.21 | 0.734 | 0.144 |
| 17 | 68.5 | 3.0 | CL | 50.0 | 95.0 | Clay | 7055 | 2781 | 1.39 | 1.00 | 1.00 | 1.00 | 4.16 | 0.86 | 3.57 | 5.61 | 9.19 | 0.712 | 0.141 |
| 18 | 73.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 7655 | 3069 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.82 | 6.80 | 3.26 | 10.06 | 0.691 | 0.134 |
| 19 | 78.5 | 27.0 | SM | 15.0 | 120.0 | Clay | 8255 | 3357 | 1.39 | 1.00 | 1.00 | 1.00 | 37.40 | 0.86 | 32.16 | 3.26 | 35.42 | 0.672 | 0.129 |
| 20 | 83.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 8855 | 3645 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.77 | 11.69 | 3.26 | 14.95 | 0.654 | 0.124 |
| 21 | 88.5 | 5.0 | SM | 15.0 | 120.0 | Clay | 9455 | 3933 | 1.39 | 1.00 | 1.00 | 1.00 | 6.93 | 0.70 | 4.88 | 3.26 | 8.14 | 0.639 | 0.120 |
| 22 | 93.5 | 28.0 | SM | 15.0 | 120.0 | Clay | 10055 | 4221 | 1.39 | 1.00 | 1.00 | 1.00 | 38.78 | 0.79 | 30.75 | 3.26 | 34.01 | 0.625 | 0.116 |
| 23 | 98.5 | 15.0 | SM | 15.0 | 120.0 | Clay | 10655 | 4509 | 1.39 | 1.00 | 1.00 | 1.00 | 20.78 | 0.71 | 14.68 | 3.26 | 17.95 | 0.613 | 0.113 |
| 24 | 103.5 | 10.0 | SM | 15.0 | 120.0 | Clay | 11255 | 4797 | 1.39 | 1.00 | 1.00 | 1.00 | 13.85 | 0.66 | 9.09 | 3.26 | 12.36 | 0.603 | 0.110 |
| 25 | 108.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 11855 | 5085 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.61 | 5.08 | 3.26 | 8.34 | 0.596 | 0.108 |
| 26 | 113.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 12455 | 5373 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.61 | 7.60 | 3.26 | 10.86 | 0.590 | 0.107 |
| 27 | 118.5 | 8.0 | SM | 15.0 | 120.0 | Clay | 13055 | 5661 | 1.39 | 1.00 | 1.00 | 1.00 | 11.08 | 0.59 | 6.49 | 3.26 | 9.75 | 0.587 | 0.106 |
| 28 | 123.5 | 9.0 | SM | 15.0 | 120.0 | Clay | 13655 | 5949 | 1.39 | 1.00 | 1.00 | 1.00 | 12.47 | 0.57 | 7.16 | 3.26 | 10.42 | 0.586 | 0.105 |
| 29 | 128.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 14255 | 6237 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.55 | 5.30 | 3.26 | 8.56 | 0.588 | 0.105 |
| 30 | 133.5 | 6.0 | SM | 15.0 | 120.0 | Clay | 14855 | 6525 | 1.39 | 1.00 | 1.00 | 1.00 | 8.31 | 0.53 | 4.36 | 3.26 | 7.63 | 0.592 | 0.105 |
| 31 | 138.5 | 7.0 | SM | 15.0 | 120.0 | Clay | 15455 | 6813 | 1.39 | 1.00 | 1.00 | 1.00 | 9.70 | 0.52 | 5.02 | 3.26 | 8.28 | 0.598 | 0.106 |
| 32 | 143.5 | 12.0 | SM | 15.0 | 120.0 | Clay | 16055 | 7101 | 1.39 | 1.00 | 1.00 | 1.00 | 16.62 | 0.54 | 8.90 | 3.26 | 12.16 | 0.607 | 0.107 |
| 33 | 148.5 | 11.0 | SM | 15.0 | 120.0 | Clay | 16655 | 7389 | 1.39 | 1.00 | 1.00 | 1.00 | 15.24 | 0.52 | 7.88 | 3.26 | 11.14 | 0.618 | 0.109 |
| 34 | | | | | | Clay | | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | | | | | | | | |
| 36 | | | | | | | | | | | | | | | | | | | |
| 37 | | | | | | | | | | | | | | | | | | | |
| 38 | | | | | | | | | | | | | | | | | | | |
| 39 | | | | | | | | | | | | | | | | | | | |
| 40 | | | | | | | | | | | | | | | | | | | |
| 41 | | | | | | | | | | | | | | | | | | | |
| 42 | | | | | | | | | | | | | | | | | | | |
| 43 | | | | | | | | | | | | | | | | | | | |
| 44 | | | | | | | | | | | | | | | | | | | |
| 45 | | | | | | | | | | | | | | | | | | | |
| 46 | | | | | | | | | | | | | | | | | | | |
| 47 | | | | | | | | | | | | | | | | | | | |
| 48 | | | | | | | | | | | | | | | | | | | |
| 49 | | | | | | | | | | | | | | | | | | | |
| 50 | | | | | | | | | | | | | | | | | | | |

| MSF | | Ksig | CRR | Corrected CRR | Factor of Safety |
|---|---|---|---|---|---|
| IB (MSFmax) | IB | IB | IB | IB | IB |
| 1.10 | 1.01 | 1.10 | 0.077 | 0.085 | 0.41 |
| 1.24 | 1.02 | 1.10 | 0.133 | 0.149 | 0.72 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.89 | 1.06 | 1.10 | 0.394 | 0.460 | 2.00 |
| 2.20 | 1.08 | 1.10 | 2.000 | 2.000 | 2.00 |
| 1.43 | 1.03 | 1.10 | 0.186 | 0.211 | 1.27 |
| 1.24 | 1.02 | 1.06 | 0.133 | 0.143 | 0.86 |
| 1.50 | 1.03 | 1.06 | 0.207 | 0.227 | 1.36 |
| 1.18 | 1.01 | 1.03 | 0.115 | 0.121 | 0.73 |
| 1.17 | 1.01 | 1.02 | 0.110 | 0.113 | 0.70 |
| 1.15 | 1.01 | 1.01 | 0.103 | 0.105 | 0.66 |
| 1.14 | 1.01 | 1.00 | 0.098 | 0.099 | 2.00 |
| 1.16 | 1.01 | 1.00 | 0.106 | 0.106 | 2.00 |
| 1.18 | 1.01 | 0.99 | 0.116 | 0.116 | 0.78 |
| 1.27 | 1.02 | 0.98 | 0.142 | 0.141 | 0.98 |
| 1.18 | 1.01 | 0.98 | 0.112 | 0.111 | 2.00 |
| 1.19 | 1.01 | 0.97 | 0.118 | 0.116 | 2.00 |
| 2.20 | 1.08 | 0.88 | 1.212 | 1.148 | 2.00 |
| 1.32 | 1.02 | 0.94 | 0.156 | 0.149 | 2.00 |
| 1.16 | 1.01 | 0.95 | 0.106 | 0.101 | 2.00 |
| 2.20 | 1.08 | 0.83 | 0.911 | 0.816 | 2.00 |
| 1.41 | 1.03 | 0.91 | 0.183 | 0.171 | 2.00 |
| 1.24 | 1.02 | 0.92 | 0.135 | 0.126 | 2.00 |
| 1.16 | 1.01 | 0.92 | 0.107 | 0.100 | 2.00 |
| 1.21 | 1.01 | 0.91 | 0.124 | 0.115 | 2.00 |
| 1.19 | 1.01 | 0.91 | 0.116 | 0.107 | 2.00 |
| 1.20 | 1.01 | 0.90 | 0.121 | 0.111 | 2.00 |
| 1.16 | 1.01 | 0.91 | 0.108 | 0.099 | 2.00 |
| 1.15 | 1.01 | 0.91 | 0.102 | 0.093 | 2.00 |
| 1.16 | 1.01 | 0.90 | 0.106 | 0.097 | 2.00 |
| 1.24 | 1.02 | 0.88 | 0.134 | 0.119 | 2.00 |
| 1.22 | 1.01 | 0.88 | 0.126 | 0.113 | 2.00 |

| Temporary Depth Number | $\Delta H_i$ | $\varepsilon_v$ | $\Delta S_i$ (in) | Cummulative Settlement (in) |
|---|---|---|---|---|
| 0.5 | 1.3 | 0.062 | 0.92 | 14.64 |
| 2 | 1.8 | 0.033 | 0.70 | 13.72 |
| 4 | 2.0 | 0.000 | 0.00 | 13.02 |
| 6 | 2.0 | 0.000 | 0.00 | 13.02 |
| 8 | 3.8 | 0.000 | 0.00 | 13.02 |
| 13.5 | 5.3 | 0.000 | 0.00 | 13.02 |
| 18.5 | 5.0 | 0.005 | 0.28 | 13.02 |
| 23.5 | 5.0 | 0.033 | 2.00 | 12.74 |
| 28.5 | 5.0 | 0.004 | 0.22 | 10.74 |
| 33.5 | 5.0 | 0.038 | 2.29 | 10.52 |
| 38.5 | 5.0 | 0.040 | 2.42 | 8.22 |
| 43.5 | 5.0 | 0.043 | 2.58 | 5.81 |
| 48.5 | 5.0 | 0.000 | 0.00 | 3.23 |
| 53.5 | 5.0 | 0.000 | 0.00 | 3.23 |
| 58.5 | 5.0 | 0.038 | 2.28 | 3.23 |
| 63.5 | 5.0 | 0.016 | 0.94 | 0.94 |
| 68.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 73.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 78.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 83.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 88.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 93.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 98.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 103.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 108.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 113.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 118.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 123.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 128.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 133.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 138.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 143.5 | 5.0 | 0.000 | 0.00 | 0.00 |
| 148.5 | 4.0 | 0.000 | 0.00 | 0.00 |
| 151.5 | | | | |

# APPENDIX G
## Ground Improvement Analyses

**LTP Catenary Design**

| | W3 | | W4 | | E1 | |
|---|---|---|---|---|---|---|
| Embankment Height (ft) = | 14 | | 18 | | 17 | |
| Embankment Fill Friction Angle (deg) = | 38 | | 38 | | 38 | |
| Embankment Fill Unit Weight (pcf) = | 125 | | 125 | | 125 | |
| Spacing (ft) = | 7 | | 5 | | 5 | |
| Diameter (in) = | 10 | | 10 | | 10 | |
| **Tensile Force for Lateral Spreading** | | | | | | |
| Ka = | 0.24 | | 0.24 | | 0.24 | |
| q (psf) = | 400 | | 400 | | 400 | |
| Tls (lb/ft) = | 3580 | | 5674 | | 5106 | |
| **Catenary Method (British Standard)** | | | | | | |
| frs = | 1.30 | | 1.30 | | 1.30 | |
| fq = | 1.30 | | 1.30 | | 1.30 | |
| $\sigma_c$' (psf) = | 2795 | | 3445 | | 3283 | |
| End-Bearing Columns Cc = | 32.58 | | 41.94 | | 39.60 | |
| Frictional Columns Cc = | 25.13 | | 32.33 | | 30.53 | |
| Pc'/$\sigma_c$' = | 3.76 | | 3.77 | | 3.77 | |
| Pc' (psf) = | 10512 | | 12988 | | 12369 | |
| Fc' (kips) = | 6 | | 7 | | 7 | |
| Wt (Equation 19-34) = | 18788 | | 15862 | | 15114 | |
| Wt (Equation 19-35) = | 9431 | | 4364 | | 4365 | |
| Wt (lb/ft) = | 9431 | | 4364 | | 4365 | |
| | | Strain | | Strain | | Strain |
| Trp (lb/ft) = | 89340 | 0.03 | 45862 | 0.01 | 45864 | 0.01 |
| | 79314 | 0.04 | 33334 | 0.02 | 33336 | 0.02 |
| | 72636 | 0.05 | 27937 | 0.03 | 27938 | 0.03 |
| | 67821 | 0.06 | 24801 | 0.04 | 24803 | 0.04 |
| | 64160 | 0.07 | 22713 | 0.05 | 22715 | 0.05 |
| **Maximum Design Tensile Force** | | Strain | | Strain | | Strain |
| Longitudinal Tmax = | 89340 | 0.03 | 45862 | 0.01 | 45864 | 0.01 |
| | 79314 | 0.04 | 33334 | 0.02 | 33336 | 0.02 |
| | 72636 | 0.05 | 27937 | 0.03 | 27938 | 0.03 |
| | 67821 | 0.06 | 24801 | 0.04 | 24803 | 0.04 |
| | 64160 | 0.07 | 22713 | 0.05 | 22715 | 0.05 |
| | | Strain | | Strain | | Strain |
| Transverse Tmax = | 92921 | 0.03 | 51535 | 0.01 | 50970 | 0.01 |
| | 82894 | 0.04 | 39008 | 0.02 | 38442 | 0.02 |
| | 76217 | 0.05 | 33610 | 0.03 | 33044 | 0.03 |
| | 71401 | 0.06 | 30475 | 0.04 | 29908 | 0.04 |
| | 67740 | 0.07 | 28387 | 0.05 | 27820 | 0.05 |

**GeoTextile Deformation Calculation**

| | | |
|---|---|---|
| Strain | 7 | % |
| Pile Diameter | 10 | inches |

| Spacing (ft) | Unsupported Length (in) | Strained Length (in) | Deformed Angle (rad) | Settlement (in) |
|---|---|---|---|---|
| 3 | 26 | 27.8 | 0.36 | 4.9 |
| 4 | 38 | 40.7 | 0.36 | 7.2 |
| 5 | 50 | 53.5 | 0.36 | 9.5 |
| 6 | 62 | 66.3 | 0.36 | 11.8 |
| 7 | 74 | 79.2 | 0.36 | 14.1 |
| 8 | 86 | 92.0 | 0.36 | 16.4 |
| 9 | 98 | 104.9 | 0.36 | 18.7 |
| 10 | 110 | 117.7 | 0.36 | 20.9 |

| | | |
|---|---|---|
| Strain | 3 | % |
| Pile Diameter | 10 | inches |

| Spacing (ft) | Unsupported Length (in) | Strained Length (in) | Deformed Angle (rad) | Settlement (in) |
|---|---|---|---|---|
| 3 | 26 | 26.8 | 0.24 | 3.2 |
| 4 | 38 | 39.1 | 0.24 | 4.7 |
| 5 | 50 | 51.5 | 0.24 | 6.2 |
| 6 | 62 | 63.9 | 0.24 | 7.7 |
| 7 | 74 | 76.2 | 0.24 | 9.1 |
| 8 | 86 | 88.6 | 0.24 | 10.6 |
| 9 | 98 | 100.9 | 0.24 | 12.1 |
| 10 | 110 | 113.3 | 0.24 | 13.6 |

# APPENDIX H
## Report Limitations and Guidelines for Use

# APPENDIX H
# REPORT LIMITATIONS AND GUIDELINES FOR USE

## Geotechnical Services Are Performed For Specific Purposes, Persons And Projects

This report is for the use by UIG-ICE Design Build Team and the SCDOT for design and construction of the US 21 over Harbor River Bridge Replacement project in Beaufort County, South Carolina. This report is not intended for use by others, and the information contained herein is not applicable to other sites.

GeoEngineers structures our services to meet the specific needs of our clients. For example, a geotechnical or geologic study conducted for a civil engineer or architect may not fulfill the needs of a construction contractor or even another civil engineer or architect that are involved in the same project. Because each geotechnical or geologic study is unique, each geotechnical engineering or geologic report is unique, prepared solely for the specific client and project site. This report should not be applied for any purpose or project except the one originally contemplated.

## A Geotechnical Engineering Or Geologic Report Is Based On A Unique Set Of Project-Specific Factors

This data report has been prepared for UIG-ICE Design Build Team and the SCDOT for design and construction of the US 21 over Harbor River Bridge Replacement project in Beaufort County, South Carolina. GeoEngineers considered a number of unique, project-specific factors when establishing the scope of services for this project and report. Unless GeoEngineers specifically indicates otherwise, do not rely on this report if it was:

- not prepared for you,
- not prepared for your project,
- not prepared for the specific site explored, or
- completed before important project changes were made.

For example, changes that can affect the applicability of this report include those that affect:

- the function of the proposed structure;
- elevation, configuration, location, orientation or weight of the proposed structure;
- composition of the design team; or
- project ownership.

If important changes are made after the date of this report, GeoEngineers should be given the opportunity to review our interpretations and recommendations and provide written modifications or confirmation, as appropriate.

## Subsurface Conditions Can Change

This geotechnical or geologic report is based on conditions that existed at the time the study was performed. The findings and conclusions of this report may be affected by the passage of time, by manmade events such as construction on or adjacent to the site, or by natural events such as floods, earthquakes, and slope

instability or groundwater fluctuations. Always contact GeoEngineers before applying a report to determine if it remains applicable.

### Most Geotechnical And Geologic Findings Are Professional Opinions

Our interpretations of subsurface conditions are based on field observations from widely spaced sampling locations at the site. Site exploration identifies subsurface conditions only at those points where subsurface tests are conducted or samples are taken. GeoEngineers reviewed field and laboratory data and then applied our professional judgment to render an opinion about subsurface conditions throughout the site. Actual subsurface conditions may differ, sometimes significantly, from those indicated in this report. Our report, conclusions and interpretations should not be construed as a warranty of the subsurface conditions.

### Geotechnical Engineering Report Recommendations Are Not Final

Do not over-rely on the preliminary construction recommendations included in this report. These recommendations are not final, because they were developed principally from GeoEngineers' professional judgment and opinion. GeoEngineers' recommendations can be finalized only by observing actual subsurface conditions revealed during construction. GeoEngineers cannot assume responsibility or liability for this report's recommendations if we do not perform construction observation.

Sufficient monitoring, testing and consultation by GeoEngineers should be provided during construction to confirm that the conditions encountered are consistent with those indicated by the explorations, to provide recommendations for design changes should the conditions revealed during the work differ from those anticipated, and to evaluate whether or not earthwork activities are completed in accordance with our recommendations. Retaining GeoEngineers for construction observation for this project is the most effective method of managing the risks associated with unanticipated conditions.

### A Geotechnical Engineering Report Or Geologic Report Could Be Subject To Misinterpretation

Misinterpretation of this report by other design team members can result in costly problems. You could lower that risk by having GeoEngineers confer with appropriate members of the design team after submitting the report. Also retain GeoEngineers to review pertinent elements of the design team's plans and specifications. Contractors can also misinterpret a geotechnical engineering or geologic report. Reduce that risk by having GeoEngineers participate in pre-bid and preconstruction conferences, and by providing construction observation.

### Do Not Redraw The Exploration Logs

Geotechnical engineers and geologists prepare final boring and testing logs based upon their interpretation of field logs and laboratory data. To prevent errors or omissions, the logs included in a geotechnical engineering or geologic report should never be redrawn for inclusion in architectural or other design drawings. Only photographic or electronic reproduction is acceptable, but recognize that separating logs from the report can elevate risk.

### Give Contractors A Complete Report And Guidance

Some owners and design professionals believe they can make contractors liable for unanticipated subsurface conditions by limiting what they provide for bid preparation. To help prevent costly problems, give contractors the complete geotechnical engineering or geologic report, but preface it with a clearly written letter of transmittal. In that letter, advise contractors that the report was not prepared for purposes

of bid development and that the report's accuracy is limited; encourage them to confer with GeoEngineers and/or to conduct additional study to obtain the specific types of information they need or prefer. A pre-bid conference can also be valuable. Be sure contractors have sufficient time to perform additional study. Only then might an owner be in a position to give contractors the best information available, while requiring them to at least share the financial responsibilities stemming from unanticipated conditions. Further, a contingency for unanticipated conditions should be included in your project budget and schedule.

### Contractors Are Responsible For Site Safety On Their Own Construction Projects

Our geotechnical recommendations are not intended to direct the contractor's procedures, methods, schedule or management of the work site. The contractor is solely responsible for job site safety and for managing construction operations to minimize risks to on-site personnel and to adjacent properties.

### Read These Provisions Closely

Some clients, design professionals and contractors may not recognize that the geoscience practices (geotechnical engineering or geology) are far less exact than other engineering and natural science disciplines. This lack of understanding can create unrealistic expectations that could lead to disappointments, claims and disputes. GeoEngineers includes these explanatory "limitations" provisions in our reports to help reduce such risks. Please confer with GeoEngineers if you are unclear how these "Report Limitations and Guidelines for Use" apply to your project or site.

### Geotechnical, Geologic And Environmental Reports Should Not Be Interchanged

The equipment, techniques and personnel used to perform an environmental study differ significantly from those used to perform a geotechnical or geologic study and vice versa. For that reason, a geotechnical engineering or geologic report does not usually relate any environmental findings, conclusions or recommendations; e.g., about the likelihood of encountering underground storage tanks or regulated contaminants. Similarly, environmental reports are not used to address geotechnical or geologic concerns regarding a specific project.

Have we delivered World Class Client Service?

Please let us know by visiting **www.geoengineers.com/feedback**.

GeoEngineers